



# NORTH WEST

# Contents

HERITAGE AT RISK	3
Reducing the risks	7
Publications and guidance	10
THE REGISTER	12
Content and assessment criteria	12
Key to the entries	15
Heritage at risk entries by local planning authority	17
Blackburn with Darwen (UA) Blackpool (UA) Cheshire East (UA) Cheshire West and Chester (UA) Cumbria Greater Manchester Halton (UA) Lancashire Merseyside Warrington (UA)	19 19 23 29 52 66 67 75 83



# HERITAGE AT

# NORTH WEST



Despite the challenges of recession, the number of sites on the Heritage at Risk Register continues to fall. Excluding listed places of worship, for which the survey is still incomplete, 1,150 assets have been removed for positive reasons since the Register was launched in 2008. The sites that remain at risk tend to be the more intractable ones where solutions are taking longer to implement.

While the overall number of buildings at risk has fallen, the average conservation deficit for each property has increased from £260k (1999)

to  $\pounds$ 370k (2012). We are also seeing a steady increase in the proportion of buildings that are capable of beneficial re-use – those that have become redundant not because of any fundamental lack of potential, but simply as the temporary victims of the current economic climate.

Almost 100 years ago, the British War Department requisitioned land at Hooton Park near Ellesmere Port. By 1917 the park was the home of Royal Flying Corps squadrons where pilots trained for action in France. Planes were housed in three double hangars where no single piece of timber in the roof structure was more than 6 foot long. The 'Belfast trusses', developed in the shipyards of Northern Ireland, were strong and cheap to build, but no one thought the hangars would be there 95 years later, after vital service in the assembly of military aircraft during the Second World War and subsequent use by the Vauxhall motor company.

One hangar has collapsed, but with a grant from English Heritage and an endowment from Vauxhall, the Hooton Park Trust has saved a second and plans to secure the third remaining one. The Trust intends to open the hangars, so that their remarkable role in modern history is available to all.

There have been other successes. Flood damage at the shieling (agricultural settlement) at Scale Beck in Cumbria had caused the nearby stream to change course, eroding the medieval remains. The Lake District National Park Authority, with support from volunteers, returned the stream to its original channel and is eradicating bracken, the roots of which destroy underlying archaeology.

Over the next three years, the Park and its volunteers will remove bracken from other scheduled monuments with the assistance of petrol strimmers funded by English Heritage. Critical to the success of these ventures is Natural England's Higher Level Stewardship (HLS) scheme. With our financial support, the National Park dedicates staff time to working with Natural England in targeting HLS resources to save monuments at risk. Altogether 4 buildings, I2 monuments and 3 conservation areas in the North West have been removed from the Register this year for entirely good reasons. But it is not all good news. Other priority sites such as the London Road Fire and Police Station in Manchester remain at risk, despite a commitment from the owner to start remedial work last year.

And as we improve our evidence, so 7 more secular buildings, 48 places of worship and 26 conservation areas have had to be added to this year's Register. Nevertheless, we are on course to achieve the target agreed with the Department for Culture Media and Sport to remove for positive reasons 25% (75) of the 301 entries on the 2010 Register by 2015. Thus far 37 sites have been successfully taken out of risk.

There are challenges ahead: the lack of resources in a recession and the loss of Conservation Officers as councils make savings. The latter are critical to achieving success on the ground. But, with the reshaping of English Heritage's local teams to provide a sharper focus on Heritage at Risk, and continued attention to priority places, progress can be sustained and priceless parts of our heritage will be saved.

Henry Owen. D.1\_

Henry Owen-John Planning and Conservation Director, North West

### HOOTON HANGARS, ELLESMERE PORT, CHESHIRE

Constructed in 1917, this rare grade II\* Belfast aircraft hangar had fallen into a state of severe disrepair. Prefabricated buildings of this kind were never intended to last 100 years and their roofs are now unable to cope with the volumes of rainwater they receive. However, the local Hooton Park Trust is determined to bring this and a second surving hangar back into beneficial use. © English Heritage

### **BUILDINGS AT RISK**

- Nationally, 3.0% of grade I and II\* listed buildings are at risk. In the North West this rises to 5.4% (109 buildings).
- 4 buildings at risk were removed from the 2011 North West Register, but 7 have been added.

### PLACES OF WORSHIP AT RISK

• Of the 297 listed places of worship surveyed in the North West, 75 are at risk. 48 have been added this year.

### SCHEDULED MONUMENTS

- 3,286 (16.6%) of England's 19,759 scheduled monuments are at risk, of which 187 are in the North West.
- In the North West, I2 scheduled monuments have been removed from the 2011 Register for positive reasons, and 6 have been added.
- 20.8% of scheduled monuments (35) on the North West's baseline 2009 Register have been removed for positive reasons, compared to the national figure of 15.8%.
- Nationally, damage from arable cultivation is the greatest risk factor for scheduled monuments, accounting for 44% of those at risk. In the North West the proportion is only 18%. The greatest threat for over half (55%) of scheduled monuments in the North West is from unrestricted plant, scrub and tree growth.

### REGISTERED PARKS AND GARDENS

- 99 (6.1%) of England's 1,617 registered parks and gardens are at risk, a decrease from 103 (6.4%) in 2011. In the North West, 7 (5.3%) of our 133 sites are at risk.
- Nationally, 5 sites were removed from the 2011 Register and 1 has been added. There has been no change in the North West.

### **REGISTERED BATTLEFIELDS**

- Of the 43 registered battlefields in England, 6 are at risk, 2 fewer than the 2008 baseline. None of the 3 registered battlefields in the North West are at risk.
- None of our 3 registered battlefields are at risk.

## the 2011 sites off the coast of the North West.

### CONSERVATION AREAS


**PROTECTED WRECK SITES** 

• We now have information on the condition of 7,976 of England's 9,770 conservation areas; 524 (6.6%) are at risk. Of the 760 conservation areas surveyed in the North West, 84 (11.1%) are at risk.

• Of the 46 protected wreck sites off England's coast,

4 are at risk. Of the 10 sites on the 2008 baseline,9 have been removed. There are no protected wreck.

• 3 conservation areas were removed from the 2011 North West Register for positive reasons, but 26 have been added.



### FLAYBRICK MEMORIAL GARDENS, WIRRAL

First opened in 1864 and now listed grade II\*, the former Birkenhead Cemetery is today used mainly as a public garden. Some of its listed buildings as well as the grounds are in a poor condition; a Friends Group is working with the council to improve the area.

© English Heritage









### PRIORITY HAR SITES

- Castle Hill motte and ditch system, Oldcastle, Cheshire
- Central General Service Hangar, South Road, Hooton, Ellesmere Port, Cheshire
- Church of St James, St James's Place, Liverpool, Merseyside
- Flaybrick Memorial Gardens, Wirral, Merseyside
- Police and Fire Station, London Road, Manchester
- Ribchester Roman fort (Bremetennacum), Ribchester, Ribble Valley, Lancashire
- Shieling settlement close to the mouth of Scale Beck, Loweswater, Allerdale, Cumbria
- The Winter Gardens, Adelaide Street, Blackpool
- Whitesyke and Bentyfield Lead Mines, Alston Moor, Eden, Cumbria
- Wycliffe Congregational Chapel, Wellington Road North, Heaton Norris, Stockport

### GRADE II PILOT PROJECTS

English Heritage is looking for people to take part in pilot projects that will explore options for expanding the Heritage at Risk programme to include all grade II listed buildings.


A maximum of I 5 pilot projects are required to explore, cost and test various options for undertaking surveys of grade II listed buildings.

For more information and details on how to apply visit:

www.english-heritage. org.uk/risk

### FOR MORE INFORMATION CONTACT:

Principal Heritage at Risk Adviser, English Heritage North West, 3rd floor Canada House, 3 Chepstow Street, Manchester, M1 5FW. Telephone: 0161 242 1400 Email: northwest@english-heritage.org.uk



Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

# Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. This will be challenging given the number of assets on the Register and the different kinds of risk they face.

To help address this challenge we have published our National Heritage at Risk Strategy which will be supported by nine local strategies. Key objectives of the strategy are to understand why assets are at risk and what most influences their removal from the Register and to find solutions for heritage at risk through partnership, stimulating economic regeneration and growth and maximising the benefit of our expertise and resources.

Whilst each asset type and individual site will require its own approach and solution, there are some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential to prevent them becoming at risk, and those that are already at risk from decaying further and the cost of their repair and consolidation from escalating. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website, **www.helm.org.uk** 

### LISTED BUILDINGS Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (Stopping the Rot) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society, The Twentieth Century Society, the Council for British Archaeology and the Ancient Monuments Society. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk officers to help not-for-profit organisations take building at risk projects forward.

### Places of worship at risk

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. It also means volunteers do not take unnecessary risks balancing on ladders.

The Repair Grants for Places of Worship scheme helped under-resourced congregations do urgent works to make buildings wind and watertight. From 2013 the Heritage Lottery Fund will fund a new scheme for places of worship. The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports the congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. *New Work in Historic Places of Worship* (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

### SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Continuing partnership with Defra and Natural England over the last year has seen the introduction of much more effective information sharing so that resources whether Environmental Stewardship or English Heritage – can be more closely targeted where they will have the greatest impact. Over the next year we will also work more closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Continued progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage for the period 2011 to 2015 – the Conservation of Scheduled Monuments in Cultivation project has begun across England. The project, which started with a questionnaire to all farmers and landowners with a scheduled monument that is being cultivated, will look at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk still shows that unmanaged tree, scrub and bracken growth is one of the most widespread causes of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers will remain the key to making further progress in ever more challenging circumstances.

### REGISTERED PARKS AND GARDENS

Inclusion on the Register of Historic Parks and Gardens of Special Historic Interest confers no additional statutory controls but the Government's new National Planning Policy Framework stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. Registered parks and gardens carry the same weight as listed buildings in the National Planning Policy Framework and substantial harm or loss can only be justified in exceptional cases. English Heritage's landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We encourage the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/ advice-by-topic/parks-and-gardens

### **REGISTERED BATTLEFIELDS**

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in the *National Planning Policy Framework*.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

### PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

### CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after them is a responsibility shared by those of us who own homes and businesses in them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. However, this is extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/getinvolved/improving-your-neighbourhood

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) - a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010 - report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2012 – national report and summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2012 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk

### CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities on conservation area management

Heritage Works: the use of Historic Buildings in Regeneration (2006)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the Transfer of Local Heritage Assets (2011)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

# THE REGISTER Content and criteria

### DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,617 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

### LISTED BUILDINGS Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I and II\* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

### Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

### Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international, importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed a proportion of the 14,500 listed places of worship. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence which will help us build upon our understanding of the challenges.

### Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

### Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

# SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,759 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

### Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

# REGISTERED PARKS AND GARDENS Definition

There are 1,617 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest.* These registered landscapes are graded I, II\* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades.

### Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

### REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

### Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

# PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

### Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

# CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,700 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

### Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Key to the entries

# This Register includes the following heritage assets at risk:

- grade I and II\* listed buildings and structural scheduled monuments
- grade I, II\* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields (if applicable)
- protected wreck sites (if applicable)
- conservation areas

### ORDER

Entries are grouped and ordered alphabetically first by County or Unitary Authority, and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

Sites that straddle more than one local planning authority are included under the lead authority.

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- registered parks and gardens
- conservation areas

Within each asset type, sites are ordered alphabetically by district for sites in National Parks, otherwise by parish and street/site name. Conservation areas are ordered by site name only.

### DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) Grade I, II\* or II
- Listed Place of Worship Grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) Grade I, II\* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

### CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

### OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

### VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

### PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

### TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

### OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

### CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

### ABBREVIATIONS

CA Conservation Area EH English Heritage HLF Heritage Lottery Fund LPA Local Planning Authority LB Listed Building NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

# Heritage at risk entries by local planning authority

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
BLACKBURN WITH D	ARWEN (UA)						
Blackburn with Darwen (UA)	I	0	0	0	0	0	I
BLACKPOOL (UA)							
Blackpool (UA)	2	0	0	0	0	0	0
CHESHIRE EAST (UA)							
Cheshire East (UA)	6		4		0	0	7
PEAK DISTRICT (NP)							
Peak District (NP)	0	0	0	0	0	0	0
CHESHIRE WEST AND	CHESTER (UA	.)					
Cheshire West and Chester (UA)	11	4	20	0	0	0	5
CUMBRIA							
Allerdale	3	4	5	0	0	0	0
Barrow-in-Furness	0	0	0	0	0	0	0
Carlisle	7		13	0	0	0	
Copeland	2	3	3	0	0	0	0
Eden		4	11	0	0	0	
Lake Distict (NP)	12	2	67	0	0	0	0
South Lakeland	6	2	5	0	0	0	0
Yorkshire Dales (NP)	0	0	0	0	0	0	0
GREATER MANCHEST	ER						
Bolton			0	0	0	0	12
Bury		4	0	0	0	0	4
Manchester	7	7	0	0	0	0	0
Oldham	2	4	0	0	0	0	0
Peak District (NP)	0	0	0	0	0	0	0
Rochdale	5	0	0	0	0	0	3
Salford	I	9	0	0	0	0	5
Stockport	2		0	0	0	0	
Tameside	5	3	0	0	0	0	2
Trafford	0		0	0	0	0	5
Wigan	6	0	0	0	0	0	2
HALTON (UA)							
Halton (UA)		3	1	0	0	0	0

### HERITAGE AT RISK 2012 / NORTH WEST

LANCASHIRE							
Burnley	5	0	0	0	0	0	4
Chorley	3	0	2	0	0	0	0
Fylde	1	0	0	0	0	0	0
Hyndburn	I	2	1	0	0	0	0
Lancaster	5	1	3		0	0	0
Pendle	0	0	0	0	0	0	2
Preston	1	I	0	0	0	0	1
Ribble Valley	2	0	3	0	0	0	0
Ribble Valley / South Ribble / Blackburn with Darwen (UA)*	0	0	0		0	0	0
Rossendale	2	2	0	0	0	0	
South Ribble	0	0	0	0	0	0	0
West Lancashire	6	0	2	U	0	0	2
Wyre	0	0	0	0	0	0	0
MERSEYSIDE	1	0	0	0	0	0	0
	0	0	0	0	0	0	2
Knowsley	0	0	0	0	0	0	2
Liverpool	8	2	0		0	0	/
Sefton		0		0	0	0	
St Helens	3	4	2	0	0	0	8
Wirral	2	3	2	2	0	0	3
WARRINGTON (UA)							
Warrington (UA)	4	0	2	0	0	0	4
TOTAL	137	75	157	7	0	0	84

\*Sites that cross local planning authority boundaries

HERITAGE AT RISK 2012 / NORTH WEST / BLACKBURN WITH DARWEN (UA) / BLACKPOOL (UA) / CHESHIRE EAST (UA)

	DARWEN	(UA)			
	Chapeltown Road (off), North Turton		Summerhouse associated with Turton Tower: Turton Tower is managed by the Local Authority as a museum; the Summerhouse is in separate, private, ownership. It has no internal floor structure		
	DESIGNATION:	Listed Building Grade II*	and requires	s some stabilising works to prevent	
	CONDITION:	Poor	further decl	ine.	
	OCCUPANCY:	Vacant			
	PRIORITY:	C (C)			
	OWNER TYPE:	Private	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Corporati	on Park Blackburn			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	Medium		TREND:	Deteriorating	
CONTACT:	Jackie Whe	elan (LPA) 01254 585846	NEW ENTRY?:	No	
BLACKPOOL (UA)					
WHER CA	SITE NAME: The Winter Gardens, Adelaide Street, Blackpool		Seaside entertainment complex built 1875-8 with later additions. Changing social/economic conditions have rendered the complex financially vulnerable and it is suffering from widespread management issues.		
	DESIGNATION:	Listed Building Grade II*	Acquired by	the Local Authority in 2010. A major	
Contraction of the second second	CONDITION:	Poor	and works a	efurbishment programme is underway are progressing well.	
	OCCUPANCY:	Part occupied		- F 6 6	
THE REAL PROPERTY OF	PRIORITY:	F (E)			
	OWNER TYPE:	Local authority	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Thanksgiving Shrine of Our Lady of Lourdes, Whinney Heys Road, Blackpool	magnificent appearance	C20 war memorial thanksgiving chapel with interior. Vacant since 1998. The chapel's extern belies the extent of severe damage to interna	
	DESIGNATION:	Listed Building Grade II*, CA	historic fabr	ic. Now in the hands of the Historic Chapels has implemented a scheme of urgent repairs	
	CONDITION:	Good	and refurbis	hment with the help of English Heritage.	
	OCCUPANCY:	Vacant			
	PRIORITY:	F (F)			
	PRIORITY: OWNER TYPE:	.,	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400	
CHESHIRE EAST (UA)	OWNER TYPE:	.,	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400	
CHESHIRE EAST (UA)	OWNER TYPE:	.,	CI6 timber-	ncipal Heritage at Risk Adviser 0161 242 1400 framed house. Some repair work o the timber frame and infill panels.	
CHESHIRE EAST (UA)	OWNER TYPE:	Trust Big Fenton, Peover Lane, Buglawton, Congleton	CI6 timber-	framed house. Some repair work	
CHESHIRE EAST (UA)	OWNER TYPE:	Trust Big Fenton, Peover Lane, Buglawton, Congleton	CI6 timber-	framed house. Some repair work	
CHESHIRE EAST (UA)	OWNER TYPE: SITE NAME: DESIGNATION:	Trust Big Fenton, Peover Lane, Buglawton, Congleton Listed Building Grade II*	CI6 timber-	framed house. Some repair work	
CHESHIRE EAST (UA)	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Trust Big Fenton, Peover Lane, Buglawton, Congleton Listed Building Grade II* Fair	CI6 timber-	framed house. Some repair work	
CHESHIRE EAST (UA)	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Trust Big Fenton, Peover Lane, Buglawton, Congleton Listed Building Grade II* Fair Occupied C (C)	CI6 timber- is needed to	framed house. Some repair work the timber frame and infill panels.	
CHESHIRE EAST (UA)	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Trust Big Fenton, Peover Lane, Buglawton, Congleton Listed Building Grade II* Fair Occupied C (C)	CI6 timber- is needed to Contact: Prin Cistercian A after the Dis Part of the I	framed house. Some repair work to the timber frame and infill panels. ncipal Heritage at Risk Adviser 0161 242 140 bbey foundation, converted to a country hou ssolution and beautifully situated within a park house is occupied and recent repairs to the	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Trust Big Fenton, Peover Lane, Buglawton, Congleton Listed Building Grade II* Fair Occupied C (C) Private Combermere Abbey – North Wing, Combermere Park, Dodcott cum Wilkesley	CI6 timber- is needed to Contact: Prin Cistercian A after the Dis Part of the I library have	framed house. Some repair work to the timber frame and infill panels. ncipal Heritage at Risk Adviser 0161 242 1400 bbey foundation, converted to a country hou ssolution and beautifully situated within a park house is occupied and recent repairs to the been carried out. No solution is however	
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Trust Big Fenton, Peover Lane, Buglawton, Congleton Listed Building Grade II* Fair Occupied C (C) Private Combermere Abbey – North Wing, Combermere Park, Dodcott cum Wilkesley	CI6 timber- is needed to Contact: Prin Cistercian A after the Dis Part of the I library have	framed house. Some repair work to the timber frame and infill panels. ncipal Heritage at Risk Adviser 0161 242 1400 bbey foundation, converted to a country hou ssolution and beautifully situated within a park house is occupied and recent repairs to the	
CHESHIRE EAST (UA)	OWNER TYPE:       Image: Designation:       CONDITION:       OCCUPANCY:       PRIORITY:       OWNER TYPE:       Image: Designation:       Image: Designation:       Image: Designation:       Image: Designation:       Image: Designation:       Image: Designation:       Image: Designation:	Trust Trust Big Fenton, Peover Lane, Buglawton, Congleton Listed Building Grade II* Fair Occupied C (C) Private Combermere Abbey – North Wing, Combermere Park, Dodcott cum Wilkesley Listed Building Grade I, RPG II	CI6 timber- is needed to Contact: Prin Cistercian A after the Dis Part of the I library have	framed house. Some repair work b the timber frame and infill panels. ncipal Heritage at Risk Adviser 0161 242 140 bbey foundation, converted to a country hou ssolution and beautifully situated within a park house is occupied and recent repairs to the been carried out. No solution is however	
CHESHIRE EAST (UA)	OWNER TYPE:           J           SITE NAME:           DESIGNATION:           CONDITION:           OCCUPANCY:           PRIORITY:           OWNER TYPE:           SITE NAME:           DESIGNATION:           CONDITION:           OWNER TYPE:	Trust	CI6 timber- is needed to Contact: Prin Cistercian A after the Dis Part of the I library have	framed house. Some repair work to the timber frame and infill panels. ncipal Heritage at Risk Adviser 0161 242 1400 bbey foundation, converted to a country hou ssolution and beautifully situated within a park house is occupied and recent repairs to the been carried out. No solution is however	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expediate functions and fabrics and
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

		( ),		
	SITE NAME:	Barn and farm buildings at Demesne Farm, Doddington Park, Doddington	by Samuel of Dodding	rm buildings built between 1771-1790 Wyatt, located 750 metres north west ton Hall. Suffering from long term neglect.
	DESIGNATION:	Listed Building Grade II*		nt stabilization works have been carried barn and discussions with the owner to
	CONDITION:	Very bad		use have been initialised.
	OCCUPANCY:	Part occupied		
and the second second	PRIORITY:	A (A)		
	OWNER TYPE:	Private	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
For Ford	SITE NAME:	Delves Hall (otherwise known as Doddington Castle), Doddington Park, Doddington	Roofed. Lo parkland la	with late CI6/early CI7 external stair. cated 500 metres north of Doddington Hall in ndscaped by Lancelot 'Capability' Brown in the now used as arable farmland. Building suffering
the state of the s	DESIGNATION:	_	from erosic	on and cracks. Urgent repairs are needed.
A A	CONDITION:	Poor N/A		
	OCCUPANCY:	A (A)		
	PRIORITY: OWNER TYPE:	Private	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	OWNER TIPE	Thivate	Contact. I I	
	SITE NAME:	Doddington Hall, Doddington Park, Doddington	Park landsc has few rer	buse built between 1777-1790 by Samuel Wyat aped by Lancelot Brown in 1770s, which now maining trees, due to intensive arable agriculture rom English Heritage has enabled a major
	DESIGNATION:	0	programme	e of repairs to make the basic fabric of the
	CONDITION:	Poor	end use an	nd and watertight. Negotiations to find an drepair programme initialised with owner.
	OCCUPANCY:			
	PRIORITY: OWNER TYPE:	E (E) Private	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	OWNER I TPE:	TTVALE	Contact. II	incipal heritage at tisk Adviser 0101 242 1400
TERCE	SITE NAME:	Tabley Old Hall, Chester Road, Tabley Inferior	in perilous island on w	use of c1670 with timber frame of c1380 condition. Located in woodland on moated restern edge of landscaped park approximately n west of Tabley House and derelict since
	DESIGNATION:	0	abandonme	ent in the 1920s. Some of the original garden
	CONDITION:	Very bad	scheme ma	y still be recognisable. English Heritage is in
	OCCUPANCY:		of ownersh	with the new land agents, following a change
	PRIORITY:	A (A)		
and the second	OWNER TYPE:	Crown	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Mary, Red Lane, Disley	The church has a magnificent CI6 ceiling to the Water ingress has caused extensive loss of fabric early CI9 aisle. There is one of the largest collec of CI6 German stained glass under threat from unstable and varying internal environmental con-	
	DESIGNATION:	Listed Place of Worship Grade II*	Work is ne	eded to prevent water ingress and to
	CONDITION:	Very bad	conserve th	ne glass.
	PRIORITY:	C (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Bowl barr	ow 140m east of Long Lane, Bickertor	1	
DESIGNATION:		Monument (No.1011143)	CONDITION:	Generally satisfactory
				but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable plc	bugning	TREND:	Declining Decimal Llouitage at Bigly Advisor
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	World Wa	ur II defences of the former airfield of I	RAF Cranage	Cranage
DESIGNATION:		Monument (No.1020762)	CONDITION:	Generally satisfactory
		· · · ·		but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree	growth	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
RIORITY (FOR BUILDINGS)				ABBREVIATIONS
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	but not ye	y; solution agreed F Repair scheme in progr and (where applicable) end use or user identifi functionally working of the solution of the soluti	2011	

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site LA LPA NP RPG SM UA WHS

DESIGNATION: Scheduled Monument (No.1011119) PRINCIPAL VULNERABILITY: Digging OWNER TYPE: Local authority SITE NAME: Brine pumps at Brooks Lane, Middlew DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton N DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	CONDITION: Extensive significant problems TREND: Declining CONTACT: Principal Heritage at Risk Adviser 0161 242 1400	
DWINER TYPE       Private         STE NAME:       Two bowl barrows 390m and 320m SS         DESIGNATION:       Scheduled Monument (No.1007387)         PRINCIPAL VULNERABILITY:       Arable ploughing         DWINER TYPE:       Private         STE NAME:       Bowl barrow in Lavenham Close, Tythe         DESIGNATION:       Scheduled Monument (No.1011119)         PRINCIPAL VULNERABILITY:       Digging         DWINER TYPE:       Local authority         STE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         DOWNER TYPE:       Local authority         STE NAME:       Promontory fort east of Peckforton N         STE NAME:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Arable ploughing	TREND:       Declining         CONTACT:       Principal Heritage at Risk Adviser         0161 242 1400       0161 242 1400         SW of Home Farm, Lower Withington         CONDITION:         Extensive significant problems         TREND:       Declining         CONTACT:       Principal Heritage at Risk Adviser         0161 242 1400       0161 242 1400	
DWINER TYPE       Private         STE NAME:       Two bowl barrows 390m and 320m SS         DESIGNATION:       Scheduled Monument (No.1007387)         PRINCIPAL VULNERABILITY:       Arable ploughing         DWINER TYPE:       Private         STE NAME:       Bowl barrow in Lavenham Close, Tythe         DESIGNATION:       Scheduled Monument (No.1011119)         PRINCIPAL VULNERABILITY:       Digging         DWINER TYPE:       Local authority         STE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         DOWNER TYPE:       Local authority         STE NAME:       Promontory fort east of Peckforton N         STE NAME:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Arable ploughing	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400 SW of Home Farm, Lower Withington CONDITION: Extensive significant problems TREND: Declining CONTACT: Principal Heritage at Risk Adviser 0161 242 1400 erington, Macclesfield	
STE NAME:       Two bowl barrows 390m and 320m SS         DESIGNATION:       Scheduled Monument (No.1007387)         Arable ploughing       Arable ploughing         DWNERTYPE:       Private         STE NAME:       Bowl barrow in Lavenham Close, Tythe         DESIGNATION:       Scheduled Monument (No.1011119)         RINCIPAL VULNERABILITY:       Digging         DWNERTYPE:       Local authority         STE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         RINCIPAL VULNERABILITY:       Rain entry         DWNER TYPE:       Local authority         STE NAME:       Promontory fort east of Peckforton N         Scheduled Monument (No.1013481)       Arable ploughing	0161 242 1400         SW of Home Farm, Lower Withington         CONDITION:         Extensive significant problems         TREND:       Declining         CONTACT:       Principal Heritage at Risk Adviser         0161 242 1400       0161 242 1400	
Designation:       Scheduled Monument (No.1007387)         RINCIPAL VULNERABILITY:       Arable ploughing         DWNER TYPE:       Private         Atte NAME:       Bowl barrow in Lavenham Close, Tythe         Designation:       Scheduled Monument (No.1011119)         RINCIPAL VULNERABILITY:       Digging         DWNER TYPE:       Local authority         Atte NAME:       Brine pumps at Brooks Lane, Middlew         Designation:       Scheduled Monument (No.1020122)         RINCIPAL VULNERABILITY:       Rain entry         Dywner TYPE:       Local authority         Atte NAME:       Promontory fort east of Peckforton N         Designation:       Scheduled Monument (No.1013481)         Arable ploughing       Arable ploughing	SW of Home Farm, Lower Withington CONDITION: Extensive significant problems TREND: Declining CONTACT: Principal Heritage at Risk Adviser 0161 242 1400 erington, Macclesfield	
Designation:       Scheduled Monument (No.1007387)         PRINCIPAL VULNERABILITY:       Arable ploughing         DWNER TYPE:       Private         SITE NAME:       Bowl barrow in Lavenham Close, Tythe         Designation:       Scheduled Monument (No.1011119)         PRINCIPAL VULNERABILITY:       Digging         DOWNER TYPE:       Local authority         SITE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         DESIGNATION:       Scheduled Monument (No.1020122)         SITE NAME:       Promontory fort east of Peckforton N         SITE NAME:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Arable ploughing	condition: Extensive significant problems TREND: Declining contact: Principal Heritage at Risk Adviser 0161 242 1400 erington, Macclesfield	
PRINCIPAL VULNERABILITY:       Arable ploughing         Private       Private         Bowl barrow in Lavenham Close, Tythe         DESIGNATION:       Scheduled Monument (No.1011119)         PRINCIPAL VULNERABILITY:       Digging         DOWNER TYPE:       Local authority         STE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         Local authority       Local authority         STE NAME:       Promontory fort east of Peckforton M         DESIGNATION:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Arable ploughing	TREND: Declining CONTACT: Principal Heritage at Risk Adviser 0161 242 1400 erington, Macclesfield	
OWNER TYPE:       Private         Bowl barrow in Lavenham Close, Tythe         DESIGNATION:       Scheduled Monument (No.1011119)         PRINCIPAL VULNERABILITY:       Digging         OWNER TYPE:       Local authority         SITE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         SITE NAME:       Rain entry         DESIGNATION:       Local authority         SITE NAME:       Promontory fort east of Peckforton N         DESIGNATION:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Rain entry         DOWNER TYPE:       Local authority	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400 erington, Macclesfield	
SITE NAME:       Bowl barrow in Lavenham Close, Tythe         DESIGNATION:       Scheduled Monument (No.1011119)         PRINCIPAL VULNERABILITY:       Digging         OWNER TYPE:       Local authority         SITE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         DOWNER TYPE:       Local authority         SITE NAME:       Promontory fort east of Peckforton N         DESIGNATION:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Rain entry         DESIGNATION:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Scheduled Monument (No.1013481)	0161 242 1400 erington, Macclesfield	
DESIGNATION: Scheduled Monument (No.1011119) PRINCIPAL VULNERABILITY: Digging OWNER TYPE: Local authority SITE NAME: Brine pumps at Brooks Lane, Middlew DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton N DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	erington, Macclesfield	
DESIGNATION: Scheduled Monument (No.1011119) PRINCIPAL VULNERABILITY: Digging OWNER TYPE: Local authority SITE NAME: Brine pumps at Brooks Lane, Middlew DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry OWNER TYPE: Local authority SITE NAME: Promontory fort east of Peckforton N DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	-	
PRINCIPAL VULNERABILITY: Digging DOWNER TYPE: Local authority SITE NAME: Brine pumps at Brooks Lane, Middlew DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing DISTINCIPAL VULNERABILITY: Arable ploughing	CONDITION: Generally satisfactory	
PRINCIPAL VULNERABILITY: Digging OWNER TYPE: Local authority SITE NAME: Brine pumps at Brooks Lane, Middlew DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing Distriction		
OWNER TYPE: Local authority SITE NAME: Brine pumps at Brooks Lane, Middlew DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	but with significant localised proble	ms
DOWNER TYPE:       Local authority         SITE NAME:       Brine pumps at Brooks Lane, Middlew         DESIGNATION:       Scheduled Monument (No.1020122)         PRINCIPAL VULNERABILITY:       Rain entry         DOWNER TYPE:       Local authority         SITE NAME:       Promontory fort east of Peckforton N         DESIGNATION:       Scheduled Monument (No.1013481)         PRINCIPAL VULNERABILITY:       Arable ploughing	TREND: Declining	
DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	CONTACT: Principal Heritage at Risk Adviser	
DESIGNATION: Scheduled Monument (No.1020122) PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	0161 242 1400	
PRINCIPAL VULNERABILITY: Rain entry Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	/ich	
PRINCIPAL VULNERABILITY: Rain entry OWNER TYPE: Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	CONDITION: Generally satisfactory	
OWNER TYPE: Local authority SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing District Market Monument (No.1013481)	but with minor localised problems	
DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining	
SITE NAME: Promontory fort east of Peckforton M DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	CONTACT: Principal Heritage at Risk Adviser	
DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	0161 242 1400	
DESIGNATION: Scheduled Monument (No.1013481) PRINCIPAL VULNERABILITY: Arable ploughing	1ere, Peckforton	
PRINCIPAL VULNERABILITY: Arable ploughing		
	CONDITION: Extensive significant problems TREND: Declining	
	CONTACT: Principal Heritage at Risk Adviser	
	0161 242 1400	
SITE NAME: Foxtwist moated site, two fishponds a	and connecting channels, Prestbury	
DESIGNATION: Scheduled Monument (No.1011864)	CONDITION: Extensive significant problems	
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining	
owner type: Private	CONTACT: Principal Heritage at Risk Adviser	
	0161 242 1400	
SITE NAME: Round cairn 200m south west of Sutta	on Hall, Sutton	
DESIGNATION: Scheduled Monument (No.1007397)	CONDITION: Generally unsatisfactory	
	with major localised problems	
PRINCIPAL VULNERABILITY: Moderate stock erosion	TREND: Declining	
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME: Bowl barrow 450m ENE of Swettenha	am Hall. Swettenham	
	,	
Designation: Scheduled Monument (No.1011165)	condition: Unknown trend: Unknown	
PRINCIPAL VULNERABILITY: Arable ploughing OWNER TYPE: Private		
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400	
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed, E Under repair or in fair to good enduced by the solution agreed but not yet implemented. E Under repair or in fair to good function	ABBREVIATIONS	

deterioration or loss of tabric; no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# LPA NP RPG SM UA WHS

Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME: Bowl barrow 550m south east of Jodrell Bank Farm, Twemlow					
			0161 242 1400		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
			with major localised problems		
DESIGNATION:	Scheduled Monument (No.1007625)	CONDITION:	Generally unsatisfactory		
SITE NAME:	Bowl barrow 800m south east of Jodrell Bank Farm, Swettenham				

DESIGNATION:	Scheduled Monument (No.1007640)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400

SITE NAME:	Bowl barrow 700m south east of Jodrell Ba	ank Farm, Twemlov	v
DESIGNATION:	Scheduled Monument (No.1007624)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Moated site and fishpond north east of Wo	ood Farm, Woolsta	nwood

SITE NAME:	Moated site and fishpond north east of Wood Farm, Woolstanwood			
DESIGNATION:	Scheduled Monument (No.1017838)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			0161 242 1400	

DESIGNATION: Registered Park and Garden Grade II, associated with a country house, with remains of a landscaped park on which Capability Brown, William		
also 8 LBs Eames and Humphry Repton are said to have worked	e said to have worked.	
CONDITION: Generally unsatisfactory with main langlight and enclosed and here there and spa with associated car parking dominating	e	
with major localised problems the former pleasure grounds.	5	
VULNERABILITY: High		
TREND: Declining		
OWNER TYPE: Mixed, multiple owners Contact: Principal Heritage at Risk Adviser 0161 242	1400	

SITE NAME:	Alderley Edge		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Andrew Ramshall (LPA) 01625 383734	NEW ENTRY?:	No
SITE NAME:	Christ Church Macclesfield		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Andrew Ramshall (LPA) 01625 383734	NEW ENTRY?:	Yes
SITE NAME:	Congleton, Lawton Street Moody Street		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Andrew Ramshall (LPA) 01625 383734	NEW ENTRY?:	No

### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expediate functions and fabrics and

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

HERITAGE AT RISK 2012 / NORTH WEST / CHESHIRE EAST (UA) / CHESHIRE WEST AND CHESTER (UA)

SITE NAME:	Crewe Green, Crewe		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Andrew Ramshall (LPA) 01625 383734	NEW ENTRY?:	No
SITE NAME:	Knutsford Legh Road, Knutsford		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Andrew Ramshall (LPA) 01625 383734	NEW ENTRY?:	No
SITE NAME:	Macclesfield High Street		
SITE NAME: DESIGNATION:	Macclesfield High Street Conservation Area	CONDITION:	Poor
	-	CONDITION: TREND:	Poor Deteriorating
designation:	Conservation Area		
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	Deteriorating
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	Deteriorating
DESIGNATION: VULNERABILITY: CONTACT:	Conservation Area Medium Andrew Ramshall (LPA) 01625 383734	TREND:	Deteriorating
DESIGNATION: VULNERABILITY: CONTACT: SITE NAME:	Conservation Area Medium Andrew Ramshall (LPA) 01625 383734 Middlewich Town Centre	TREND: NEW ENTRY?:	Deteriorating Yes
DESIGNATION: VULNERABILITY: CONTACT: SITE NAME: DESIGNATION:	Conservation Area Medium Andrew Ramshall (LPA) 01625 383734 Middlewich Town Centre Conservation Area	TREND: NEW ENTRY?: CONDITION:	Deteriorating Yes Very bad


### CHESHIRE WEST AND CHESTER (UA)



10 01120		
SITE NAME:	Hulme Hall and bridge over moat, Hulme Hall Lane, Allostock	C16 hall house surrounded by moat and reached by a stone bridge, situated within active brine fields. Urgent repairs to stabilise the building have been carried out, but last year's repair scheme have halted. A renewed application
DESIGNATIO	№ Listed Building Grade II*, SM	has been approved and works are expected to restart.
CONDITION	Poor	
OCCUPANC	r: Vacant	
PRIORITY:	D (F)	
OWNER TYP	e Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400
1	A . I .	



SITE NAME:	Aston dovecote, Aston	Dovecote, 1691, of Flemish bond brown brick. Roofless, with deterioration to the walls of the building. Ownership of the dovecote has now been
DESIGNATION:	Listed Building Grade II, SM	established and discussions are under way regarding stabilisation and repair.
CONDITION:	Very bad	
OCCUPANCY:	Vacant	
PRIORITY:	A (A)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400





7	SITE NAME:	Northern General Service Hangar, South Road, Hooton, Ellesmere Port	One of a group of three former World War I aircraft hangars. Now vacant with significant roof collapse. Owned by a Trust dedicated to its restoration.
14	DESIGNATION:	Listed Building Grade II*	
-	CONDITION:	Very bad	
18.1	OCCUPANCY:	Vacant	
-	PRIORITY:	A (A)	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Eventset of the research of

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE-2011 priority categories are given in brackets.

ABBREVIATIONS			
CA	Conservation Area		
LB	Listed Building		
LPA	Local Planning Authority		
NP	National Park		
RPG	Registered Park and Garden		
SM	Scheduled Monument		
UA	Unitary Authority		
WHS	World Heritage Site		

	SITE NAME:	Southern General Service Hangar, South Road, Hooton, Ellesmere Port	One of a group of three former World War I aircraft hangars. Partially used for storage, but roof deteriorating and requiring additional structural support. Owned by
	DESIGNATION:	Listed Building Grade II*	a trust dedicated to its restoration. Emergency roof repairs have been implemented with grant aid from
	CONDITION:	Very bad	English Heritage.
Burnama secondario	OCCUPANCY:	Part occupied	
The second second	PRIORITY:	A (A)	
A REPORT OF	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Calveley Old Hall, Chapel Lane, Handley	House built 1684 for Lady Mary Calveley. Remodelled in 1818 for Sir Thomas Legh of Lyme. Some C20 alterations. Major causes for concern include the roof, brickwork and external joinery. No solution agreed with owner
	DESIGNATION:	Listed Building Grade II*	external joinery. No solution agreed with owner.
are in the second	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Stanlow Abbey Cistercian Monastery and Monastic Grange, Ince	Late CI2 monastery with a cell and grange from the late CI3 incorporated in CI8 buildings. Overgrown and collapsing. Access difficult. English Heritage has carried out a desk-based assessment to improve understanding
	DESIGNATION:	Scheduled Monument	of the site. English Heritage and the Council continue
State of the state	CONDITION:	Very bad	to seek a sustainable solution with the owners to
	OCCUPANCY:		stabilise the upstanding remains and secure the below-ground archaeology.
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400
EAL Pr	SITE NAME:	Lion Salt Works, Ollershaw Lane, Marston	The rare remains of an open-pan salt works. The Local Authority has now started the main phase of the project to convert the remains of the open-pan salt works and related buildings and structures to a building museum
	DESIGNATION:	Listed Building Grade II, SM, CA	related buildings and structures to a living museum. Funding is provided by the Local Authority, the Heritage
	CONDITION:	Very bad	Lottery Fund and English Heritage. The project timetable
and the second	OCCUPANCY:	Part occupied	is for completion in 2014.
The second secon			
THE THE	PRIORITY:	F (D)	
FR. MAR		F (D) Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
			C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of
	OWNER TYPE:	Local authority Rode Street House,	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council
	OWNER TYPE:	Local authority Rode Street House, Tarporley	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss
	OWNER TYPE: SITE NAME: DESIGNATION:	Local authority Rode Street House, Tarporley Listed Building Grade II*	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Local authority Rode Street House, Tarporley Listed Building Grade II* Fair Vacant E (C)	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Local authority Rode Street House, Tarporley Listed Building Grade II* Fair Vacant E (C)	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Local authority Rode Street House, Tarporley Listed Building Grade II* Fair Vacant E (C)	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss of fabric and features. Contact: Principal Heritage at Risk Adviser 0161 242 1400 C18 former manor house, most recently used as a nursing nome, now vacant. Building condition deteriorated following interior and external damage
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Local authority  Rode Street House, Tarporley  Listed Building Grade II* Fair Vacant E (C) Private  Tarvin Hall, High Street,	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss of fabric and features. Contact: Principal Heritage at Risk Adviser 0161 242 1400 C18 former manor house, most recently used as a nursing nome, now vacant. Building condition deteriorated following interior and external damage from lead theft. Ownership change has resulted in
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Local authority  Rode Street House, Tarporley  Listed Building Grade II* Fair Vacant E (C) Private  Tarvin Hall, High Street, Tarvin	C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss of fabric and features. Contact: Principal Heritage at Risk Adviser 0161 242 1400 C18 former manor house, most recently used as a nursing nome, now vacant. Building condition deteriorated following interior and external damage
	OWNER TYPE: SITE NAME: DESIGNATION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Local authority Rode Street House, Tarporley Listed Building Grade II* Fair Vacant E (C) Private Tarvin Hall, High Street, Tarvin Listed Building Grade II*, CA Poor	<ul> <li>C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss of fabric and features.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>C18 former manor house, most recently used as a nursing nome, now vacant. Building condition deteriorated following interior and external damage from lead theft. Ownership change has resulted in emergency repairs and plans to restore to a family</li> </ul>
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Local authority Rode Street House, Tarporley Listed Building Grade II* Fair Vacant E (C) Private Tarvin Hall, High Street, Tarvin Listed Building Grade II*, CA Poor	<ul> <li>C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss of fabric and features.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>C18 former manor house, most recently used as a nursing nome, now vacant. Building condition deteriorated following interior and external damage from lead theft. Ownership change has resulted in emergency repairs and plans to restore to a family</li> </ul>
	OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	Local authority  Rode Street House, Tarporley  Listed Building Grade II* Fair Vacant E (C) Private  Tarvin Hall, High Street, Tarvin Listed Building Grade II*, CA Poor Vacant D (C)	<ul> <li>C18 farmhouse, with fluted pilasters to centre bay, a pediment and hooded porch. The building was purchased in 2008 by the current owner but still suffers from lack of maintenance. Discussions have taken place with the council and some urgent repairs have been implemented, but a long term solution is required to arrest any further loss of fabric and features.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>C18 former manor house, most recently used as a nursing nome, now vacant. Building condition deteriorated following interior and external damage from lead theft. Ownership change has resulted in emergency repairs and plans to restore to a family</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

-	SITE NAME:	Utkinton Hall, Utkinton Lane, Utkinton	used as a fa and window maintenanc	Irmhouse. Roof flas vs in poor condition e. Minor repairs to	gn and evolution now hings, rainwater goods n with a general lack of roof and guttering have
	DESIGNATION:	Listed Building Grade I	been carrie	d out. Discussions \	with the owner have
	CONDITION:	Poor			ong-term solution has
	OCCUPANCY:	Part occupied	been identi	fied.	
	PRIORITY:	С (С)			
	OWNER TYPE:	Private	Contact: Pr	incipal Heritage at I	Risk Adviser 0161 242 1400
	SITE NAME:	Church of St John the Baptist, Vicars Lane, Chester	important p red sandsto amphitheat	place of worship in one, and close to the re, it has the schedu	otist in Chester is a very the city. Built of local e remains of the Roman uled ancient ruins of the into fabric of the church.
	DESIGNATION:	Listed Place of Worship Grade I, CA	The most r	ecent repair work h	has concentrated on the
	CONDITION:	Poor	high level st	onework and repo	inting.
	PRIORITY:	F (F)			
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at f	Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Chad, Church Road, Farndon	spiral stairca I 660. Furthe south transe War Royalis	ise. Five bay nave an er additions are a ru ept.The Barnston Cf	border tower with defendabl d chancel were added aroun sticated C18 porch and C19 hapel has C17 glass of Civil ous trophies. Church is of
	DESIGNATION:	Listed Place of Worship Grade II*, C	A huge local s	ignificance, especially	in its relationship to the
	CONDITION:	Poor	nearby VVels	sh river border cross	sing. A grant of £30,000 has tower and C17 glasswork.
	PRIORITY:	B (B)	Deen Onere	u towarus repair or	LOWEI AITU CT7 glasswork.
and the second	OWNER TYPE:	Religious organisation	Contact: Pri	ncipal Heritage at R	isk Adviser 0161 242 1400
	SITE NAME:	Church of St Lawrence, Church Lane, Stoak	a considera This carper	ble amount of CI6 try is now under a	ilt church of 1827 contains original timber framing. cute threat of loss from videspread ingress of water
		Listed Place of Worship Grade II*			
	CONDITION:	Very bad			
	PRIORITY:	C (New entry)			
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at i	Risk Adviser 0161 242 1400
A	SITE NAME:	Church of St Helen, High Street, Tarporley	C15 church with extensive C19 additions by Manc architect Crowther, and 1930s Worthington repairs local red sandstone. Large tower and slate roof. Int combines features and memorials from the C15, C C19.The church building is locally very prominent		Worthington repairs, all in er and slate roof. Interior rials from the C15, C17 and
ana maria	DESIGNATION:	Listed Place of Worship Grade II*, C	A as strong fo	cus of the commur	nity. The most urgent focus
ALT TURE AND	CONDITION:	Poor			of, high level stonework,
	PRIORITY:	F (F)	parapet and	the gutters.	
In the second	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at I	Risk Adviser 0161 242 1400
SITE NAME:	The Maide	en's Cross, wayside cross 520m SSW	of Four Lane E	nds. Alvanley	
DESIGNATION:		Monument (No.1013785)	CONDITION:	Generally unsatis	factory
	Scheduled		CONDITION:	with major locali	'
PRINCIPAL VULNERABILITY:	Limited/lo	calised vehicle damage/erosion	TREND:	Declining	
OWNER TYPE:	Local auth		CONTACT:	Principal Heritage	e at Risk Adviser
				0161 242 1400	
SITE NAME:	Bruera mo	pated site and adjacent field system, I	Buerton		
				Concrelly active	tony
DESIGNATION:	Scheduled	Monument (No.1012110)	CONDITION:	Generally satisfac	ctory nt localised problems
PRINCIPAL VULNERABILITY:	Arable plc	pughing	TREND:	Declining	ne localised provients
	Private	ω <sup>2</sup> β		Principal Heritage	e at Risk Adviser
OWNER TYPE:	Trivate		CONTACT:	0161 242 1400	
				0.0.2121100	
NORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	but not ye	y; solution agreed F Repair scheme in pro and (where applicable end use or user ident sair or in fair to good	2011	E: priority categories ven in brackets.	ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site LA LPA NP RPG SM UA WHS

SITE NAME:	Shocklach Castle motte and moated enclos	sure, Caldecott		
DESIGNATION:	Scheduled Monument (No.1012620)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Roman camp at Stamford Lodge, 350m nor	th west of Stamfo	ord Hollows Farm, Christleton	
DESIGNATION:	Scheduled Monument (No.1014380)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Bowl barrow I20m north east of Rose Far	n, Coddington		
DESIGNATION:	Scheduled Monument (No.1007389)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Bowl barrow 120m south east of Fishpool Lane Farm, Delamere			
DESIGNATION:	Scheduled Monument (No.1007637)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Bowl barrow 140m south east of Fishpool I	Lane Farm, Delam	ere	
DESIGNATION:	Scheduled Monument (No.1007638)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Bowl barrow 300m WSW of Fishpool Lane	Farm, Delamere		
DESIGNATION:	Scheduled Monument (No.1007632)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Bowl barrow 30m south west of Fishpool I	_ane Farm, Delam	ere	
DESIGNATION:	Scheduled Monument (No.1007631)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

SITE NAME:	Bowl barrow 70m east of Fishpool Lane Fa	rm, Delamere	
DESIGNATION:	Scheduled Monument (No.1007634)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Eddisbury hillfort east of Old Pale Farm, D	elamere	
DESIGNATION:	Scheduled Monument (No.1013295)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Promontory fort on Helsby Hill 250m nor	h west of Harme	rs Lake Farm, Helsby
DESIGNATION:	Scheduled Monument (No.1013292)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Huntington Hall moated site, Huntington		
DESIGNATION:	Scheduled Monument (No.1012112)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Castle Cob motte, Kingsley		
DESIGNATION:	Scheduled Monument (No.1011122)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Glassworking remains in Glazier's Hollow,	330m south of Kir	ngswood Cottage, Manley
DESIGNATION:	Scheduled Monument (No.1020705)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Bowl barrow 160m north east of Moultonb	ank Farm, Moulto	n
DESIGNATION:	Scheduled Monument (No.1011123)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expediate functions and fabrics and
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Motte and bailey 360m north of Harthill Ba	nk, Oakmere	
DESIGNATION:	Scheduled Monument (No.1011792)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Castle Hill motte and ditch system, Oldcast	le	
DESIGNATION:	Scheduled Monument (No.1012124)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Roman camp 50m south of Elm Bank, Wave	rton	
DESIGNATION:	Scheduled Monument (No.1014115)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Bowl barrow I20m east of Village Lane, Wh	itley	
designation:	Scheduled Monument (No.1011166)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Ince		
designation:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Nick Grimshaw (LPA) 01244 973160	NEW ENTRY?:	No
SITE NAME:	Marston (Lion Salt Works) Revised		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Nick Grimshaw (LPA) 01244 973160	NEW ENTRY?:	No
SITE NAME:	Northwich Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Nick Grimshaw (LPA) 01244 973160	NEW ENTRY?:	No
SITE NAME:	Picton		
designation:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Nick Grimshaw (LPA) 01244 973160	NEW ENTRY?:	No
	Saughall		
SITE NAME:			
	Concernation Arres		Vanuebad
DESIGNATION:	Conservation Area	CONDITION:	Very bad
SITE NAME: DESIGNATION: VULNERABILITY: CONTACT:	Conservation Area Low Nick Grimshaw (LPA) 01244 973160	CONDITION: TREND: NEW ENTRY?:	Very bad Deteriorating No

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / ALLERDALE

CUMBRIA			
ALLERDALE			
	SITE NAME:	Hadrian's Wall between Port Carlisle and Bowness on Solway, Port Carlisle, Bowness	Section of Hadrian's Wall, wall miles 78 and 79, surviving as a modern field boundary. In places the wall facing is exposed up to four courses high. It appears likely that the future of the monument could be secured by limited works
	DESIGNATION:	Scheduled Monument, WHS	to control tree and scrub growth, some consolidation and
	CONDITION:	Poor	fencing. English Heritage and Natural England continue to discuss the best way of securing appropriate management
	OCCUPANCY:		of the site.
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Cockermouth Castle bell tower and kitchen tower, Cockermouth	Castle dates from CI3 with major rebuilding occurring in the CI4 and CI9 plus C20 additions. The majority of the Castle is in good repair although the CI3 bell tower is badly leaning and potentially dangerous. The CI4 kitchen
	DESIGNATION:	Listed Building Grade I, SM, CA	tower is suffering from water ingress.
	CONDITION:	Very bad	5 5
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
97 	SITE NAME:	Workington Hall tower house and later medieval fortified house, Workington	Medieval tower house, expanded and enlarged, most recently in the C18. A decision to de-roof the building and consolidate it as a ruin was taken in the 1970s.
1.1.1.1	DESIGNATION:	Listed Building Grade I, SM, RPG II	In the past decade it has seldom been accessible to the public, and maintenance has declined. The owners have
	CONDITION:	Poor	commissioned a condition survey but no further work
	OCCUPANCY:	Vacant	has been undertaken.
Contra V	PRIORITY:	C (New entry)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of All Hallows, Fletchertown, All Hallows	All Hallows is a late C19 church designed by CJ Ferguson in an inventive version of the traditional style of the C11 and C12. Though solidly built and generally well cared for, some blocked and damaged rainwater goods, together with slipped coping stones are causing significant areas
	DESIGNATION:	Listed Place of Worship Grade II	of saturation to wall surfaces, especially to the vestry,
	CONDITION:	Poor	north transept and north face of the tower.
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Mungo, Church Street, Dearham	St Mungo's is a medieval church of the late C12 with C13 and C19 extensions, including work by CJ Ferguson. It is famed for the incorporation into the fabric of much earlier sculpture, predating its Norman foundation. There are considerable
	DESIGNATION:	Listed Place of Worship Grade I	patches of stone erosion caused by repointing in hard cement, and the chancel in general, and its east wall in particular, suffers
EALER ARTEN	CONDITION:	Poor	from damp caused by blocked gutters. It has stonework with
	PRIORITY:	A (New entry)	large open joints, and is subject to movement.
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Mary, Churchtown, Sebergham	St Mary's is a medieval parish church predominantly designed in the Early English phase of Gothic architecture of the C13. Later repairs and alterations have given it an enjoyably Edwardian flavour. The fabric is showing signs of considerable stone decay, loss of mortar and minor movement to the
	DESIGNATION:	Listed Place of Worship Grade II*	south west aisle, the west end, and the north face of the
20 AL	CONDITION:	Poor	tower. Elsewhere damaged stonework is causing shattering
	PRIORITY:	A (New entry)	of window openings from rusting window restraints.
- Contraction of the second	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

	SITE NAME:       Church of St Hilda, Church Hill, Westward         DESIGNATION:       Listed Place of Worship Grade II         CONDITION:       Poor	and probab located abo with a block wall and cau the north e wall, a west growth to t	ratic church of I 785-86, minimally Gothicised later, y on the site of an earlier church and picturesquely ve the River Wiza. The church is in a poor condition ted gutter to the south elevation discharging onto the using cracking to the window mullions; no gutter to levation, slipped tiles allowing water ingress to the wall in need of repointing and stone repair, plant he tower, and a power cable slung from the church pulling stone out of the north east corner, allowing
	PRIORITY: C (New entry)	further wate	
	OWNER TYPE: Religious organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Brownrigg North tower 21b, 830m north we part of the Roman frontier defences along th		
DESIGNATION:	Scheduled Monument (No.1014811)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Settlement west of Birkby, Crosscanonby		
DESIGNATION:	Scheduled Monument (No.1007069)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Beckfoot Roman fort, Holme St Cuthbert		
DESIGNATION:	Scheduled Monument (No.1007170)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Roman fortlet 40m SSW of Castle Fields, Ho	olme St Cuthber	t
DESIGNATION:	Scheduled Monument (No.1007171)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Wolsty South tower 13b, 200m WNW of Ne part of the Roman frontier defences along th		ast, Holme St Cuthbert
DESIGNATION:	Scheduled Monument (No.1014807)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
CARLISLE			
	SITE NAME: Naworth Castle gatehouse, Naworth Castle, Brampton	Castle, circ need of re	y gatehouse to outer courtyard at Naworth a 1520. Altered in C16 and 1840s. Roof in placement. Archway has flattened and requires and pinning.
	designation: Listed Building Grade I	monitoring	
AND INCOME.	CONDITION: Poor		
TIN STATE	occupancy: Vacant		
The second se			

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

OWNERTYPE: Private

C (C)

PRIORITY:

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE: 2011 priority categories are given in brackets.

Contact: Principal Heritage at Risk Adviser 0161 242 1400

ABBREVIATIONS				
CA	Conservation Area			
LB	Listed Building			
LPA	Local Planning Authority			
NP	National Park			
RPG	Registered Park and Garden			
SM	Scheduled Monument			
UA	Unitary Authority			
WHS	World Heritage Site			

### HERITAGE AT RISK 2012 / NORTH WEST / CARLISLE

	SITE NAME:	Hadrian's Wall at Burtholme Beck, Burtholme	Section of Hadrian's Wall and vallum in wall miles 52, 53 and 54. Includes herringbone masonry standing up to seven feet tall.The monument is under threat from the growth
	DESIGNATION:	Scheduled Monument, WHS	of trees and scrub. Discussions with Natural England are
	CONDITION:	Poor	ongoing, but a final solution, properly taking account of all the interests on the site, has yet to be agreed.
经限 沉淀 入 等能	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Roachburn Colliery, Farlam	Colliery built in 1895. The stone-built generating house and pumping house are both roofless. The walls are affected by substantial cracks, rotting of timber lintels and imminent partial collapse. The pumping house is
the state of the s	DESIGNATION:	Scheduled Monument	infested with vegetation which is causing bulging,
	CONDITION:	Very bad	particularly in the exposed wall tops.
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	The Stonehouse (north of Denton Foot), Naworth Park, Nether Denton	A late CI6 bastle which has been roofless and in a bad condition for some years. There is now damaging vegetation growth in the walls. Initial discussions with
	DESIGNATION:	Listed Building Grade II, SM	the owner regarding possible reuse have taken place.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant	
The Self of Self and Self	PRIORITY:	A (A)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
Phase Para	SITE NAME:	Stonehouse Tower remains, Nicholforest	Medieval pele tower. Only two walls stand to any height (approximately 4.5 metres). The east wall is used as part of a cattle shed, but the remainder of the structure is subject to slow docay.
	DESIGNATION:	Scheduled Monument	subject to slow decay.
the second state of the second s			
	CONDITION:	Very bad	
	CONDITION: OCCUPANCY:	,	
		,	
	OCCUPANCY:	N/A C (C)	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	OCCUPANCY: PRIORITY:	N/A C (C)	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	OCCUPANCY: PRIORITY:	N/A C (C)	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	N/A C (C) Private Enclosure castle known as Triermain Castle,	Fragment of CI2 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad N/A A (A)	Fragment of CI2 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad N/A A (A)	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation work discussed with owner.
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad N/A A (A) Private Cornmill at Warwick Bridge, Warwick Bridge, Wetheral	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation work discussed with owner. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Early C19 water powered corn mill. Significant for its intact machinery and waterwheel (dated 1843). The owner has undertaken roof repairs. Options for a
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad N/A A (A) Private Cornmill at Warwick Bridge, Warwick Bridge,	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation work discussed with owner. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Early C19 water powered corn mill. Significant for its intact machinery and waterwheel (dated 1843). The owner has undertaken roof repairs. Options for a more comprehensive restoration to secure a sustainable
	OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad N/A A (A) Private Cornmill at Warwick Bridge, Warwick Bridge, Wetheral	Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation work discussed with owner. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Early C19 water powered corn mill. Significant for its intact machinery and waterwheel (dated 1843). The owner has undertaken roof repairs. Options for a
	OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad N/A A (A) Private Cornmill at Warwick Bridge, Warwick Bridge,	<ul> <li>Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation work discussed with owner.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Early C19 water powered corn mill. Significant for its intact machinery and waterwheel (dated 1843). The owner has undertaken roof repairs. Options for a more comprehensive restoration to secure a sustainable use are to be developed in conjunction with the owner,</li> </ul>
	OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE SITE NAME: DESIGNATION: CONDITION:	N/A C (C) Private Enclosure castle known as Triermain Castle, Waterhead Scheduled Monument Very bad N/A A (A) Private Cornmill at Warwick Bridge, Warwick Bridge,	<ul> <li>Fragment of C12 castle. Now in perilous condition. No consolidation work has ever been undertaken as far as is known. A rectified photographic survey has now been completed, and scope of consolidation work discussed with owner.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Early C19 water powered corn mill. Significant for its intact machinery and waterwheel (dated 1843). The owner has undertaken roof repairs. Options for a more comprehensive restoration to secure a sustainable use are to be developed in conjunction with the owner,</li> </ul>



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME: Church of St Andrew, Bridge Street, Longtown, Arthuret DESIGNATION: Listed Place of Worship Gr CONDITION: POOR PRIORITY: A (New entry) OWNERTYPE: Religious organisation	rade II Constructed red sandsto clad in boar serious risin and further Annandale a in 2016. Acc	ngular church set back behind street frontage. d as a United Succession Church from hammer-dresse ne with ashlar dressings and slate roof. The interior is d sheeting which in a number of places has signs of g and penetrating damp. Removal of the cladding detailed inspection is required. The Presbytery of and Eskdale has decided that the church should close sess difficulties may limit potential reuse. ncipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Dollerline medieval dispersed settlem	nent 250m north of Bus	h Farm, Askerton
DESIGNATION:	Scheduled Monument (No.1015869)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn in Mollen Wood, 640m e	east of Parkgate Bridge,	Askerton
DESIGNATION:	Scheduled Monument (No.1015766)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Two round cairns in Mollen Wood, 66	60m east of Parkgate Br	ridge, Askerton
DESIGNATION:	Scheduled Monument (No.1015767)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Prehistoric enclosure, field system an and field systems 600m SSVV of Black	d cairnfield, medieval an Iyne House, Bewcastle	d early post-medieval settlements
DESIGNATION:	Scheduled Monument (No.1016089)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400

DESIGNATION:	Scheduled Monument (No.1016404)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400

SITE NAME:	The Loan medieval bastle and post-medieval cottage, Bewcastle		
DESIGNATION:	Scheduled Monument (No.1016085)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400

SITE NAME:	Brampton Old Church Roman fort and the medieval Church of St Martin, Brampton		
DESIGNATION:	Scheduled Monument (No.1014586)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400

### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / CARLISLE

SITE NAME:	Tower Tye ringwork, Brampton		
DESIGNATION:	Scheduled Monument (No.1013969)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Written Rock of Gelt: Roman quarry inscr	iptions, Brampton	
DESIGNATION:	Scheduled Monument (No.1014582)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	No known threat	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Grey Yauds stone circle, Cumwhitton		
DESIGNATION:	Scheduled Monument (No.1007233)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Shieling I 50m south of Tinkler Crags, King	water	
DESIGNATION:	Scheduled Monument (No.1017731)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Medieval fishponds and moat at Denton Ha	all, Nether Dentor	1
DESIGNATION:	Scheduled Monument (No.1007090)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Nether Denton Roman fort, associated vic	us and length of S	tanegate Roman road, Nether Denton
DESIGNATION:	Scheduled Monument (No.1018501)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Cumrew		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expedience of the record of th

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

COPELAND				
	SITE NAME:	Millom Castle, A5093, Millom	the present in the later	stle or moated manor house incorporating t farmhouse. Built in early CI4 and much altered CI4 and again in the CI6 and CI7. Gate piers
	DESIGNATION:	Listed Building Grade I, SM	is the heav	I north east are listed grade II. A major problem y sapling growth on upstanding ruins which the
	CONDITION:	Poor	owner has	agreed to clear. Discussions about a scheme
	OCCUPANCY:	Vacant	of consolid	ation continue.
The states	PRIORITY:	С (С)		
	OWNER TYPE:	Unknown	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Old College Hall, B5345, St Bees	to a music The roof h	ancel of St Bees Priory Church, converted school in C19, subsequently used as a hall. as deteriorated to the point at which the
	DESIGNATION:	Listed Building Grade I, CA	been agree	unusable. A scheme to repair the roof has Id, and is being grant-aided by English Heritage.
JA AA	CONDITION:	Poor	The work i	s planned to begin in the summer of 2012.
	OCCUPANCY:	Part occupied		
	PRIORITY:	F(C)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Michael, Stygate, Lamplugh	vestry on so with some v building. Hig Evidence of	h of 1870 by Butterfield. Aisleless nave, chancel with both side; bellcote at west end. In Perpendicular style windows and other features reused from an earlier h quality C19 glass, with four windows by Kempe. structural movement – fracturing of tracery in t window on the north side, porch, buttress at north
		Listed Place of Worship Grade II*	corner. Som	e suggestion that the roof is detaching from the wes
	CONDITION:	Poor	wall. Also da	imp in the south and north walls. Must be regarded
	PRIORITY:	C (New entry)	as at high ris	sk until the extent of the movement is clarified.
	OWNER TYPE:	D III	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400
H	SITE NAME:	Church of St Bridget, Parton	exposed po replaced ar classical des	e site of a Roman fort and in an exceedingly osition, St Bridget's was built in 1822 and n earlier medieval church. A stout and elegant sign, some of the stonework to the west front
	DESIGNATION:	Listed Place of Worship Grade II	(that faces	the prevailing winds coming off the Irish Sea) eroded and a cause for concern, along with
Laplo a stall	CONDITION:	Poor		ce to the north parapet.
	PRIORITY:	C (New entry)		
		Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
1 mont	SITE NAME:	Church of St Bridget, Middlebank Farm, Beckermet, St Bridget Beckermet	some Č17 a slate roof with fixed b	Church in Beckermet is medieval in origin, with alterations. It is built of rough-cast stone with f. The interior has panelling and wainscoting benches. The church roof has widespread slate to have field. The reinworks goode have field
	DESIGNATION:	Listed Place of Worship Grade II*		h have failed. The rainwater goods have failed of places, the render is showing evidence of
	CONDITION:	Very bad	failing and t	there is also evidence of stone decay. Water is
	PRIORITY:	A (A)	penetrating	g in many places.
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Settlemen	t 25m south east of Gatra, Lamplugh		
DESIGNATION:	Scheduled	Monument (No.1007139)	CONDITION:	Generally unsatisfactory
	Cardoning		TRENE	with major localised problems Declining
PRINCIPAL VULNERABILITY:	Gardening Private		TREND:	5
OWNER TYPE:	invate		CONTACT:	Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.


0161 242 1400


# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / COPELAND / EDEN

SITE NAME:	Barrowmc	outh gypsum and alabaster mine at Salt	om Bay, Whit	rehaven
DESIGNATION:	Scheduled	Monument (No.1021106)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree	growth	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Saltom co	al pit,Whitehaven		
DESIGNATION:	Scheduled	Monument (No.1017558)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion		TREND:	Declining
OWNER TYPE:	Local authority		CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
EDEN				
5-4	SITE NAME:	Whitesyke and Bentyfield Lead Mines, Alston Moor	and Bentyfield Lead Mines, Complex set of mid C19 lead mining struction or including bouse teams. Deteriorating with etimbers. A Conservation Management Plan produced with a grant from English Heritag	
	DESIGNATION:	Scheduled Monument	to consolida	ate and present the remains is under way.
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY:	F (B)		
<b>医子宫的</b> 是一种	OWNER TYPE:	Private	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400







	SITE NAME:	Augill Lead Mine Smelting Mill, Stainmore, Brough	C19 lead smelting building, containing remains of furnaces. Roof removed in mid C20. Emergency repairs were carried out to the lintel over the door in 2005.
	DESIGNATION:	Scheduled Monument	Proposals to remove trees and undergrowth from around the monument are under discussion, but no
	CONDITION:	Very bad	solution to the structural problems has yet been agreed.
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400



1			
-	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400
100	SITE NAME:	Ruins of Brougham Hall, Brougham	Surviving walls, gates and associated buildings of a C15, C16, and early C19 hall, which was substantially demolished in the 1930s. A conservation plan has been
	DESIGNATION:	Listed Building Grade II*	adopted and an ambitious programme of restoration is making progress. The reconstruction of the corner
-	CONDITION:	Poor	tower as a publicly accessible archive building has
the second	OCCUPANCY:	Part occupied	recently received planning consent.
1	PRIORITY:	F (F)	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. Under repair or in fair to good Е repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE:	
2011 priority catego	ries
are given in brackets	

ABBREV	'IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / EDEN

	SITE NAME:	Smardale Gill Lime Kilns, Smardale, Crosby Garrett	Remains of a major mid C19 lime-production centre, with two kilns and related engine house and railway structures. The right hand wall of the furnace is bulging,
	DESIGNATION:	Scheduled Monument	and there are problems with the stability of the retaining walls of the railway embankments.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
A CARLEND AND A CARLEND	PRIORITY:	С (С)	
A second s	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400
1.1	SITE NAME:	Crake Trees Tower House, Crosby Ravensworth	C14 tower house with C16 and C17 additions, in ruins with further collapse possible. A management agreement has ensured removal of tipped material and of trees which grew from walls. A scheme for repair using Higher Level
the sale	DESIGNATION:	Scheduled Monument	Stewardship funding has been agreed in principle.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY:	D (C)	
Contraction of the	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Kirkoswald Castle, Kirkoswald	Heavily overgrown late C15 ruin with stone bridge over the moat. North tower 20 metres high with staircase. Vaulted cellars. West tower collapsed in 1993.
	DESIGNATION:	Listed Building Grade II, SM	Large saplings grow from the walls at all levels and roots are dislodging the facing stones. Mature hawthorns growing
	CONDITION:	Very bad	on the bridge have also dislodged many stones.
	OCCUPANCY:	N/A	
	PRIORITY:	A (A)	
Contraction of the second second	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Two Lions Public House and integral stables, Great Dockray, Penrith	C16 house in a Conservation Area, significantly modified from mid-C18 and last used as an inn/pub.Vacant since 2005, but now subject to a planning obligation related to the adjacent manificance transformation of the accurate
		and integral stables, Great Dockray, Penrith	from mid-C18 and last used as an inn7pub.Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure
		and integral stables, Great Dockray, Penrith	from mid-C18 and last used as an inn7pub.Vacant since 2005, but now subject to a planning obligation related to
	DESIGNATION:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor	from mid-C18 and last used as an inn7pub.Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure
	DESIGNATION: CONDITION:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor	from mid-C18 and last used as an inn7pub.Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure
	DESIGNATION: CONDITION: OCCUPANCY:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C)	from mid-C18 and last used as an inn7pub.Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C)	from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C)	from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton	from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton	from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad	from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad	from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINERTYPE: SITE NAME: DESIGNATION: CONDITION: CONDITION:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A)	from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A)	from mid-C18 and last used as an inn/pub.Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation work has been approved.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A)	<ul> <li>from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation work has been approved.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>C14 ruined castle of two storeys and with vaulted cellars. Collapse of facing stone and rubble core owing to frost action, root action and cattle. Mature trees grow on the</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A) Private Lammerside Castle,	<ul> <li>from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation work has been approved.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A) Private Lammerside Castle, Wharton	<ul> <li>from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation work has been approved.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>C14 ruined castle of two storeys and with vaulted cellars. Collapse of facing stone and rubble core owing to frost action, root action and cattle. Mature trees grow on the</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A) Private Lammerside Castle, Wharton	<ul> <li>from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation work has been approved.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: SITE NAME:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A) Private Lammerside Castle, Wharton Listed Building Grade II, SM Very bad	<ul> <li>from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation work has been approved.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: COCUPANCY: SITE NAME: SITE NAME: CONDITION: CONDITION:	and integral stables, Great Dockray, Penrith Listed Building Grade II*, CA Poor Vacant C (C) Company High Head Castle, High Head, Skelton Listed Building Grade II* Very bad Part occupied A (A) Private Listed Building Grade II, Wharton Listed Building Grade II, SM Very bad	<ul> <li>from mid-C18 and last used as an inn/pub. Vacant since 2005, but now subject to a planning obligation related to the adjacent retail development. Implementation to secure its deteriorating condition expected to start in 2012.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Elegant Georgian house, incorporating part of medieval castle, now a structurally unsound shell. English Heritage has part-funded preparation of a Conservation Management Plan and the recently implemented emergency stabilisation works. An options appraisal is being developed with the owner to identify a viable new use, and further stabilisation work has been approved.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

	SITE NAME: DESIGNATION:	Parish Church of St Andrew, St Andrew's Churchyard, Penrith Listed Place of Worship Grade I	west tower the church It has been when worr almost flat, the parapet	built in the C12 an was rebuilt in 1720 restored several tin n-infested roof timb and efflorescence an gutters are failing.	as a red sandstone rubble id C13.The remainder of in red sandstone ashlar. nes, most recently in 1972 pers were removed.The roof is round the parapets indicates Failing downpipes have led to
A A LA	CONDITION:	Poor			there are many patches of
	PRIORITY:	C (New entry)	uarrip, wiur	peeling plaster, som	e of which have been repaired
	OWNER TYPE:		Contact: Pr	incipal Heritage at F	Risk Adviser 0161 242 1400
	SITE NAME:	Christchurch, Stricklandgate, Penrith	The style is rubble, with has a new stonework	s early Perpendicula n slate roofs and a porch roof, and so and replacement c	50 by Travis and Magnell. ar, of coursed red sandstone large east window.The church me repointing of high level of ridge tiles has taken place.
	DESIGNATION:	Listed Place of Worship Grade II	The gutter	s and downpipes n	eed attention, with gutters
	CONDITION:	Poor	missing on	the south side of t	he chancel and nave.
	PRIORITY:	C (New entry)			
	OWNER TYPE:	Religious organisation	Contact: Pr	rincipal Heritage at	Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Cuthbert, Church Lane, Great Salkeld	originally fr with a forti a stone-bui	om the early Middl fied pele tower add It church and an im	an fortified church, dating e Ages – it was rebuilt in 1080 ded in 1380. St Cuthbert's is aportant feature in the local were to re-slate the nave roof,
	DESIGNATION:	Listed Place of Worship Grade II*, CA			d fixing the gutters. This initial
	CONDITION:	Poor			d is almost complete.
	PRIORITY:	F (F)			
	OWNER TYPE:	Religious organisation	Contact: Pr	rincipal Heritage at	Risk Adviser 0161 242 1400
and the	SITE NAME:	Church of St Stephen, Market Square, Kirkby Stephen	Church of 1230 with later additions and alterations, on ar earlier site. C16 west tower, aisled seven bay nave of C12 transept to the north and chancel. Fine C15 and C16 tombs and an important pre-Conquest fragment – the "Loki Stone". Generally appears in good condition and w cared for, but water dripping from the roof just inside the		
WIGHT HOM	DESIGNATION: CONDITION:	Listed Place of Worship Grade II* Poor	main south	west door suggest use of the parapet	ts that the nave roof, not , is in poor condition, placing
Station of the second	PRIORITY:	A (New entry)	<b>C</b> D		
	OWNER TYPE:	Religious organisation	Contact: Pr	rincipal Heritage at	Risk Adviser 0161 242 1400
SITE NAME:	Broomrigg	g I: standing stone in Broomrigg Planta	tion, 920m so	outh east of Street	House, Ainstable
DESIGNATION:	Scheduled	Monument (No.1015277)	CONDITION:	Extensive signific	cant problems
PRINCIPAL VULNERABILITY:	Plant grow	/th	TREND:	Declining	
OWNER TYPE:	Governme	ent or Agency	CONTACT:	Principal Heritag 0161 242 1400	ge at Risk Adviser
SITE NAME:	Broomrigg	g P: shieling in Broomrigg Plantation, 7	75m south ea	ast of Street House	e, Ainstable
DESIGNATION:	Scheduled	Monument (No.1015278)	CONDITION:	Extensive signific	cant problems
PRINCIPAL VULNERABILITY:	Plant grow	· · · · · · · · · · · · · · · · · · ·	TREND:	Declining	
OWNER TYPE:	-	ent or Agency	CONTACT:	0	ge at Risk Adviser
Gunder III E	Sovernine		CONIACI.	0161 242 1400	
SITE NAME:	Brough Ca	astle and Brough (Verterae) Roman fo	rt and civil se	ettlement, Brough	
designation:	Scheduled	Monument (No.1007148)	CONDITION:	Generally satisfa	,
					ant localised problems
PRINCIPAL VULNERABILITY:		natural erosion	TREND:	Declining	
OWNER TYPE:	Governme	ent or Agency	CONTACT:	Principal Heritag 0161 242 1400	ge at Risk Adviser
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	but not ye	y; solution agreed t implemented. pair or in fair to good F Repair scheme in progra and (where applicable) end use or user identifi functionally redundant i	ed; are g	E: priority categories iven in brackets.	ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Endemand the solution of the solut

C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / FDEN

ITE NAME:	The Old Kiln, Wetheriggs Pottery, Clifton			
DESIGNATION:	Scheduled Monument (No.1007120)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Bowl barrow 20m east of Ravens' Gill, Crosh	y Ravensworth		
DESIGNATION:	Scheduled Monument (No.1007603)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Medieval shieling south of Cow Green, Cros	by Ravensworth		
DESIGNATION:	Scheduled Monument (No.1007596)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Maiden Way Roman road, Culgaith			
DESIGNATION:	Scheduled Monument (No.1003053)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Road construction	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Roman camp 200m west of Galleygill Bridge,	Hesket		
DESIGNATION:	Scheduled Monument (No.1007869)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Slight univallate hillfort on Barrock Fell, Hesk	æt		
DESIGNATION:	Scheduled Monument (No.1007874)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
	Haresceugh Fell medieval dispersed settlement 100m south west of Busk lime kiln, Kirkoswald			
SITE NAME:	Haresceugh Fell medieval dispersed settleme	nt 100m south w	vest of Busk lime kiln, Kirkoswald	
	Haresceugh Fell medieval dispersed settleme Scheduled Monument (No.1021185)	ent 100m south w	vest of Busk lime kiln, Kirkoswald Extensive significant problems	
DESIGNATION:			Extensive significant problems Declining	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1021185)	CONDITION:	Extensive significant problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1021185) Plant growth	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 0161 242 1400	
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME:	Scheduled Monument (No.1021185) Plant growth Private	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 0161 242 1400	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1021185) Plant growth Private Village settlement and circular enclosure on	CONDITION: TREND: CONTACT: Lazonby Fell, Laz	Extensive significant problems Declining Principal Heritage at Risk Adviser 0161 242 1400	

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

but not yet implemented. E Under repair or in fair to good repair but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB NP RPG SM UA WHS

38

SITE NAME:	Alston		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Gwyn Clark (LPA) 01768 212158	NEW ENTRY?:	No

LAKE DISTRICT (NP)				
	SITE NAME:	Calder Abbey, St Bridget Beckermet, Copeland	Abbey which originated in the late C12. Emerg of consolidation to chapter house and adjacent undertaken with help of English Heritage and L National Park Authority. A further phase of cor	areas ake District
	DESIGNATION:	Scheduled Monument	to the nave arcade and the high masonry of the	e Crossing
Annetares	CONDITION:	Poor	is required.	0
Constant and states and	OCCUPANCY:	N/A		
	PRIORITY:	С (С)		
	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 016	242   400
	SITE NAME:	and courtyard buildings adjoining to	An extension to Calder Abbey following the Dissolution of the Abbey, the house dates from the early C18 but contains elements of the ear	lier
	DESIGNATION:	Listed Building Grade I	monastic building. Further extension and alterat were designed by G Faulkner Armitage in the e	
	CONDITION:	Poor	C20 creating an impressive Arts and Crafts inte	erior.
A REAL AND A REAL	OCCUPANCY:	Part occupied	Flashings and rainwater goods are in poor conc	lition.
	PRIORITY:	C (New entry)	The condition of the building is slowly deterior	ating.
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 016	242   400
	SITE NAME:	The Monks Oven, Calder Abbey, St Bridget Beckermet, Copeland	Large detached oven associated with Calder Al Roof, wall structure and pointing are in poor co Widespread and serious defects with the loss o	ondítion.
	DESIGNATION:	Listed Building Grade II*, SM	building possible in the short to medium term.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
A TRACE PERSON	PRIORITY:	C (New entry)		
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 016	242   400
<u><u><u>R</u></u></u>	SITE NAME:	Inner terrace wall, ramps and steps, north of Lowther Castle, Near Penrith, Lowther, Eden	Sandstone terrace and turreted retaining wall, b 1806-19 by Smirke. The structure faces the nor in front of Lowther Castle, and is enclosed by t	th garden he outer
Man Man	DESIGNATION:	Listed Building Grade II*, RPG II	terrace. The structure's consolidation is a comp initiative, led by the Lowther Castle and Garder	
B AL BOARD	CONDITION:	Poor	create a major visitor attraction. This has secure	
	OCCUPANCY:	N/A	from the NWDA to implement an extensive p	rogramme
	PRIORITY:	F (F)	of restoration.	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 016	242   400
	SITE NAME:	Lowther Castle, Near Penrith, Lowther, Eden	Gothic house designed by Smirke 1806-1814. C 1935 and removal of the roof in 1957 led to ru the main building's fabric. EH has grant-aided re	ination of pairs to the
	DESIGNATION:	Listed Building Grade II*, RPG II	staircase tower. An ambitious programme of re-	storation
	CONDITION:	Very bad	and conversion of the surviving buildings and gr commenced in February 2011, with funding fro	rounas m the
A DC	OCCUPANCY:	Vacant	Northwest Regional Development Agency. Ope	ened as
三十二 四十二	PRIORITY:	F (F)	a visitor attraction in May 2012.	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 016	242   400
Mitchel.	SITE NAME:	Outer terrace wall, north of Lowther Castle, Near Penrith, Lowther, Eden	Battlemented, sandstone ashlar garden-wall, buil 1806-19 by Smirke. It encloses the north terrac Lowther Castle, at the centre of the 100 acre d landscape.The wall's repair is a component of t	e of lesigned
	DESIGNATION:	Listed Building Grade II*, RPG II	led by the Lowther Castle and Gardens Trust, to	
	CONDITION:	Poor	major visitor attraction. This has secured funding	g from the
	OCCUPANCY:	N/A	NWDA to implement an extensive programme	e of building
	PRIORITY:	F (F)	and landscape restoration.	
and the same of the	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 016	242   400
PRIORITY (FOR BUILDINGS)			ABBREVIATIONS	
A Immediate risk of further rapid deterioration or loss of fabric;		y; solution agreed F Repair scheme in progres and (where applicable)	s NOTE: CA Conservation 2011 priority categories LB Listed Build	on Area ling

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

ABBREV	IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

Contraction of the second	SITE NAME:	Greenside Lead Mine, Glenridding, Patterdale, Eden	Extensive remains of lead mine. Some consolidation of minor features has been carried out by the Lake District National Park Authority, and exploratory work on safety
The states	DESIGNATION:	Scheduled Monument	is in progress. The site has been surveyed by the English Heritage Survey Team. A programme of stabilisation works
SPACE SE	CONDITION:	Very bad	to spoil heaps has been completed, though consolidation
	OCCUPANCY:	N/A	of historic fabric is still required.
and a sound i	PRIORITY:	F (F)	
Aspert	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Winster Potash Kiln, Cartmel Fell, South Lakeland	CI8 potash kiln. Cracking of lintel over entrance to kiln is giving cause for concern – a scheme to pin and secure the lintel is required.
AT ALL AND	DESIGNATION:	Scheduled Monument	
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY:	С (С)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
Star	SITE NAME:	Coniston Copper Mines, Coniston, South Lakeland	Remains of extensive copper mine which operated from C16 to C20. The site was surveyed by the Royal Commission on the Historical Monuments of England and limited consolidation has been carried out by the
	DESIGNATION:	Scheduled Monument	Lake District National Park Authority and English Heritage.
	CONDITION:	Very bad	Flooding has caused damage in recent years, and further
	OCCUPANCY:	Part occupied	repairs are required.
	PRIORITY:	C (C)	
The second second	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
and the second se			
	SITE NAME:	Backbarrow Ironworks, Haverthwaite, South Lakeland	Derelict ironworks. Redevelopment of site currently stalled, but negotiations are continuing between the developer and the National Park Authority over a revised scheme which
		Haverthwaite,	but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and
		Haverthwaite, South Lakeland Scheduled Monument	but negotiations are continuing between the developer and the National Park Authority over a revised scheme which
	DESIGNATION:	Haverthwaite, South Lakeland Scheduled Monument Poor	but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and
	DESIGNATION:	Haverthwaite, South Lakeland Scheduled Monument Poor	but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A	but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F)	but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F)	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite,	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Part occupied A (A)	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Part occupied A (A)	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the remains are underway.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: CONDITION: PRIORITY:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Part occupied A (A)	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the remains are underway.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Timber-framed farm cottage dating from late medieval period, with a single surviving cruck. Extended C17 and altered C19; now slobbered rubble walls with slate roof.</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Part occupied A (A) Company Far Orrest Old Farm Cottage, Holehierd Estate, Troutbeck,	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the remains are underway.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Timber-framed farm cottage dating from late medieval period, with a single surviving cruck. Extended C17 and altered C19; now slobbered rubble walls with slate roof. Partially used for storage by the agricultural estate, but in a</li> </ul>
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Part occupied A (A) Company Ear Orrest Old Farm Cottage, Holehierd Estate, Troutbeck, Windermere, South Lakeland	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the remains are underway.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Timber-framed farm cottage dating from late medieval period, with a single surviving cruck. Extended C17 and altered C19; now slobbered rubble walls with slate roof. Partially used for storage by the agricultural estate, but in a deteriorating condition. Proposals to address further fabric decline and to bring the building back into full use are to</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: CONDITION: OCCUPANCY: PRIORITY: OWINER TYPE: SITE NAME: SITE NAME:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Part occupied A (A) Company Far Orrest Old Farm Cottage, Holehierd Estate, Troutbeck, Windermere, South Lakeland Listed Building Grade II* Poor	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the remains are underway.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Timber-framed farm cottage dating from late medieval period, with a single surviving cruck. Extended C17 and altered C19; now slobbered rubble walls with slate roof. Partially used for storage by the agricultural estate, but in a deteriorating condition. Proposals to address further fabric</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: SITE NAME:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Scheduled Monument Very bad Part occupied A (A) Company Far Orrest Old Farm Cottage, Holehierd Estate, Troutbeck, Windermere, South Lakeland Listed Building Grade II* Poor	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the remains are underway.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Timber-framed farm cottage dating from late medieval period, with a single surviving cruck. Extended C17 and altered C19; now slobbered rubble walls with slate roof. Partially used for storage by the agricultural estate, but in a deteriorating condition. Proposals to address further fabric decline and to bring the building back into full use are to</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: SITE NAME: SITE NAME: CONDITION: CONDITION:	Haverthwaite, South Lakeland Scheduled Monument Poor N/A D (F) Company Lowwood Gunpowder Works, Haverthwaite, South Lakeland Scheduled Monument Very bad Scheduled Monument Very bad Part occupied A (A) Company Far Orrest Old Farm Cottage, Holehierd Estate, Troutbeck, Windermere, South Lakeland Listed Building Grade II* Poor Vacant C (C)	<ul> <li>but negotiations are continuing between the developer and the National Park Authority over a revised scheme which would secure the conservation of the historic features and public access to them.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Remains of gunpowder works, in operation from 1799 to 1935. A detailed survey of the remains by English Heritage Archaeological Survey Branch has been completed. Discussions on the proposals for consolidation of the remains are underway.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Timber-framed farm cottage dating from late medieval period, with a single surviving cruck. Extended C17 and altered C19; now slobbered rubble walls with slate roof. Partially used for storage by the agricultural estate, but in a deteriorating condition. Proposals to address further fabric decline and to bring the building back into full use are to</li> </ul>

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ADDREV	IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

40

	SITE NAME: Church of St Mary, Thornthwaite, Above Derwent, Allerdale	Church of 1831, extended in 1853. Nave, chancel, nort and south transepts all in early English style, with bellc at west end and west porch. Generally appears well c for but there are signs of damp in the south and west wells. Boofs have slipped states and becken ridge tiles.
ARTEN BUILD	DESIGNATION: Listed Place of Worship Grade II	walls. Roofs have slipped slates and broken ridge tiles.
	condition: Poor	
	PRIORITY: C (New entry)	
and and the second	OWNERTYPE: Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242
	SITE NAME: Church of St Anne, Meadowcroft, Ings, Hugill, South Lakeland	Parish church of 1743, north transept added in 1877. West tower, nave and chancel. Venetian window at ease end; remaining windows round headed. Built of rough coursed stonework with stone slate roofs. Attractive interior with late C19/early C20 pews and a mixture
	DESIGNATION: Listed Place of Worship Grade II*	of C18 and Victorian fittings. Generally well maintained but signs of damp in north west corner.
	condition: Poor	but signs of damp in nor th west corner.
ALLALLES BOTH	PRIORITY: C (New entry) OWNERTYPE: Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242
ITE NAME:	Askham Fell stone alignment, Askham, Eden	
DESIGNATION:	Scheduled Monument (No.1007376)	CONDITION: Extensive significant problems
RINCIPAL VULNERABILITY:	Plant growth	TREND: Improving
DWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400
ITE NAME:	Linear stone bank on Askham Fell, Askham, I	den
DESIGNATION:	Scheduled Monument (No.1007363)	CONDITION: Extensive significant problems
RINCIPAL VULNERABILITY:	Plant growth	TREND: Declining
DWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser
		0161 242 1400
SITE NAME:	Round cairn 285m south east of White Rais	round cairn, Askham Fell, Askham, Eden
DESIGNATION:	Scheduled Monument (No.1007375)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND: Improving
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn 475m south east of White Rais	round cairn, Askham Fell, Askham, Eden
DESIGNATION:	Scheduled Monument (No.1007377)	CONDITION: Extensive significant problems
RINCIPAL VULNERABILITY:	Plant growth	TREND: Improving
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn 490m south east of White Rais	round cairn, Askham Fell, Askham, Eden
DESIGNATION:	Scheduled Monument (No.1007378)	CONDITION: Extensive significant problems
RINCIPAL VULNERABILITY:	Plant growth	TREND: Improving
DWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400
ITE NAME:	Round cairn 50m north east of White Raise	round cairn, Askham Fell, Askham, Eden
DESIGNATION:	Scheduled Monument (No.1007373)	CONDITION: Extensive significant problems
RINCIPAL VULNERABILITY:	Plant growth	TREND: Improving
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 0161 242 1400
NORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric;	D Slow decay; solution agreed F Repair scheme in but not yet implemented. and (where applic	
no solution agreed.	E Under repair or in fair to good end use or user is functionally redun	entified; are given in brackets. LPA Local Planning Author

no solution agreed. B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. C Slow decay; no solution agreed.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

LPA NP RPG SM UA WHS

Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Round cairn 515m south east of White Rai	ise round cairn, As	kham Fell, Askham, Eden
DESIGNATION:	Scheduled Monument (No.1007358)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn 520m north east of The Cock	xpit, Askham Fell, A	skham, Eden
DESIGNATION:	Scheduled Monument (No.1007370)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn 580m north east of The Cock	pit, Askham Fell, A	skham, Eden
DESIGNATION:	Scheduled Monument (No.1007369)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn 660m north east of The Cock	pit, Askham Fell, A	skham, Eden
DESIGNATION:	Scheduled Monument (No.1007371)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn on Askham Fell, 270m north c	of The Cop Stone,	Askham, Eden
DESIGNATION:	Scheduled Monument (No.1007361)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
	Davind salam on Haushaara Hill Aalihana Ea		
SITE NAME:	Round cairn on Heughscar Hill, Askham, Ec	len	
	Scheduled Monument (No.1011589)	den condition:	Extensive significant problems
DESIGNATION:	•		Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1011589)	CONDITION:	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1011589) Plant growth	CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 0161 242 1400
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No.1011589) Plant growth Private	CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 0161 242 1400
DESIGNATION: PRINCIPAL VULNERABILITY: OWINER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No.1011589) Plant growth Private Round cairn west of Riddingleys Top, Askha	CONDITION: TREND: CONTACT: am Fell, Askham, Ec	Declining Principal Heritage at Risk Adviser 0161 242 1400 den
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1011589) Plant growth Private Round cairn west of Riddingleys Top, Askha Scheduled Monument (No.1007368)	CONDITION: TREND: CONTACT: am Fell, Askham, Econdition:	Declining Principal Heritage at Risk Adviser 0161 242 1400 <b>Jen</b> Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1011589) Plant growth Private Round cairn west of Riddingleys Top, Askha Scheduled Monument (No.1007368) Plant growth	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 0161 242 1400 den Extensive significant problems Improving Principal Heritage at Risk Adviser
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No.1011589) Plant growth Private Round cairn west of Riddingleys Top, Askhar Scheduled Monument (No.1007368) Plant growth Private White Raise round cairn, Askham Fell, Askh	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 0161 242 1400 Jen Extensive significant problems Improving Principal Heritage at Risk Adviser 0161 242 1400
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: OWNER TYPE: SITE NAME: SITE NAME:	Scheduled Monument (No.1011589) Plant growth Private Round cairn west of Riddingleys Top, Askha Scheduled Monument (No.1007368) Plant growth Private	CONDITION: TREND: CONTACT: CONTACT: CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 0161 242 1400 den Extensive significant problems Improving Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site CA LB LPA NP RPG SM UA WHS

SITE NAME:	Ring cairn on Knipescar Common	, Bampton, Eden			
DESIGNATION:	Scheduled Monument (No.100740)	7) cc	ONDITION:	Generally unsat with major loca	,
RINCIPAL VULNERABILITY:	Plant growth	TR	END:	Declining	
WNER TYPE:	Private	CC	DNTACT:	Principal Herita 0161 242 1400	ge at Risk Adviser
ITE NAME:	Romano-British farmstead at Haw	eswater, Bampton,	Eden		
DESIGNATION:	Scheduled Monument (No.1011158	8) cc	ONDITION:	Extensive signifi	cant problems
RINCIPAL VULNERABILITY:	Plant growth	TR	END:	Improving	
OWNER TYPE:	Government or Agency	CC	ONTACT:	Principal Herita 0161 242 1400	ge at Risk Adviser
ITE NAME:	Two round cairns 415m and 420m	NNE of The Coo	:kpit, Moo	r Divock, Barton	, Eden
DESIGNATION:	Scheduled Monument (No.1007372	2) cc	ONDITION:	Extensive signific	cant problems
RINCIPAL VULNERABILITY:	Plant growth		END:	Improving	
DWNER TYPE:	Private	cc	DNTACT:	1 0	ge at Risk Adviser
ITE NAME:	Prehistoric hut circle settlements, field system and kilns on Heathwa				
DESIGNATION:	Scheduled Monument (No.1020802	2) cc	ONDITION:	Generally unsat	isfactory
				with major loca	lised problems
RINCIPAL VULNERABILITY:	Plant growth	TR	END:	Improving	
WNER TYPE:	Private	CC	DNTACT:	Principal Herita 0161 242 1400	ge at Risk Adviser
ITE NAME:	Great Grassoms prehistoric cairnf and associated field systems on Bo	ootle Fell, Bootle, (			
DESIGNATION:	Scheduled Monument (No.101706	5) сс	ONDITION:	Extensive signifie	cant problems
RINCIPAL VULNERABILITY:	Plant growth		END:	Improving	+ Diele Arthinen
DWNER TYPE:	Private	CC	ONTACT:	0161 242 1400	ge at Risk Adviser
SITE NAME:	Little Grassoms prehistoric field sy Bootle, Copeland	ystem, two cairnfie	elds and si	x funerary cairns	s on Bootle Fell,
DESIGNATION:	Scheduled Monument (No.101907	7) cc	DNDITION:	Extensive signific	cant problems
RINCIPAL VULNERABILITY:	Plant growth	TR	END:	Improving	
DWNER TYPE:	Private	cc	DNTACT:	Principal Herita 0161 242 1400	ge at Risk Adviser
ITE NAME:	Prehistoric cairnfields, funerary cai field systems and a medieval enclo			Fell, Bootle, Cope	eland
DESIGNATION:	Scheduled Monument (No.101706	6) cc	ONDITION:	Generally satisfa but with signific	actory ant localised problems
RINCIPAL VULNERABILITY:	Plant growth	TR	END:	Declining	
WWNER TYPE:	Private	cc	DNTACT:	Principal Herita 0161 242 1400	ge at Risk Adviser
ITE NAME:	Bowl barrow on Brund Fell, Borro	wdale, Allerdale			
esignation:	Scheduled Monument (No.1013389	9) cc	DNDITION:	Extensive signific	cant problems
RINCIPAL VULNERABILITY:	Plant growth	TR	END:	Declining	
DWNER TYPE:	Private	СС	DNTACT:	Principal Herita 0161 242 1400	ge at Risk Adviser
RIORITY (FOR BUILDINGS)					ABBREVIATIONS
Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.	but not yet implemented. er E Under repair or in fair to good fu repair, but no user identified; or fu under theret of varance with po	epair scheme in progress nd (where applicable) nd use or user identified; nrctionally redundant building <i>i</i> th new use agreed but not et implemented.	are give	riority categories en in brackets.	CA Conservation Area LB Listed Building LPA Local Planning Authorit NP National Park RPG Registered Park and Ga SM Scheduled Monument UA Unitary Authority

agreed but not yet implemented. C Slow decay; no solution agreed.

obvious new user (applicable only to buildings capable of beneficial use).

Scheduled Monument Unitary Authority World Heritage Site ument UA WHS

SITE NAME:	Reecastle Crag hillfort, Borrowdale, Allerd	ale	
DESIGNATION:	Scheduled Monument (No.1012941)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn 250m south east of High Wat	h Ford, Caldbeck, /	Allerdale
DESIGNATION:	Scheduled Monument (No.1020046)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn 275m south east of High Wat	h Ford, Caldbeck, /	Allerdale
DESIGNATION:	Scheduled Monument (No.1020047)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Weasel Hills prehistoric cairnfield, associat immediately north and north west of High		
DESIGNATION:	Scheduled Monument (No.1020044)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Nibthwaite furnace, Colton, South Lakeland	d	
DESIGNATION:	Scheduled Monument (No.1007072)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Cairns and enclosure on The Rigg, Banishe	ad, Coniston, Soutl	h Lakeland
DESIGNATION:	Scheduled Monument (No.1007246)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Cairns on Foul Scrow, Coniston, South Lak	eland	
DESIGNATION:	Scheduled Monument (No.1007247)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Cairns on Kiln Bank I/6 to I/2 mile (270m- Dunnerdale-with-Seathwaite, South Lakelar		Kiln Bank Farmhouse,
DESIGNATION:	Scheduled Monument (No.1007234)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site CA LB LPA NP RPG SM UA WHS

SITE NAME:	Tongue How prehistoric stone hut circle so cemetery and cairnfield, Romano-British fa		
DESIGNATION:	Scheduled Monument (No.1018500)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Cairnfield including a funerary cairn, standi Burnmoor, Eskdale, Copeland	ng stone and three	e stone banks south of Eller How,
DESIGNATION:	Scheduled Monument (No.1008538)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
ITE NAME:	Cairnfield including a prehistoric enclosure 2 stone walls, a lynchet and a trackway on		
DESIGNATION:	Scheduled Monument (No.1008539)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Green How West unenclosed prehistoric h 540m NNE of Birkerthwaite, Eskdale, Cope		nt
	-		Extensive significant problems
DESIGNATION:	Scheduled Monument (No.1019618)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND: CONTACT:	Declining Principal Heritage at Risk Adviser
JUVINER TITE.	Thvate	CONTACT.	0161 242 1400
SITE NAME:	Hare Gill prehistoric cairnfield, hut circle so 715m SSE of Fisher Gate, Eskdale, Copelan		ociated field system
DESIGNATION:	Scheduled Monument (No.1019556)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Prehistoric cairnfield and associated field sy	ystem 730m ENE o	of Birkerthwaite, Eskdale, Copeland
DESIGNATION:	Scheduled Monument (No.1019616)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Prehistoric cairnfield and associated field s 650m west of High Ground, Eskdale, Cope		e How,
DESIGNATION:	Scheduled Monument (No.1019555)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
· · · · · · · · · · · · · · · · · · ·			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

SITE NAME:	Prehistoric cairnfield south west o 290m north west of the confluence	f Water Crag, e of Linbeck Gill	and Devo	oke Water, Eskdale,	Copelan	d
DESIGNATION:	Scheduled Monument (No.1019552	2) c	ONDITION:	Generally satisfac	tory	
				but with significa	nt localis	ed problems
PRINCIPAL VULNERABILITY:	Plant growth	Т	REND:	Declining		
OWNER TYPE:	Private	C	ONTACT:	Principal Heritage	e at Risk	Adviser
				0161 242 1400		
SITE NAME:	Prehistoric cairnfield, associated fie	eld system and hu	ıt circle e	ast of Water Crag,	Eskdale,	Copeland
DESIGNATION:	Scheduled Monument (No.101998	D) c	ONDITION:	Generally satisfac	'	ed problems
PRINCIPAL VULNERABILITY:	Plant growth	Т	REND:	Declining		I
OWNER TYPE:	Private	C	ONTACT:	Principal Heritage	e at Risk	Adviser
				0161 242 1400		
SITE NAME:	Prehistoric cairnfield, field system, field system and a post-medieval h					
DESIGNATION:	Scheduled Monument (No.101999	C) (C	ONDITION:	Extensive significa	ant probl	ems
PRINCIPAL VULNERABILITY:	Plant growth	,	REND:	Declining		
OWNER TYPE:	Private	C	ONTACT:	Principal Heritage	e at Risk	Adviser
				0161 242 1400		
SITE NAME:	Prehistoric cairnfield, hut circle se 290m south east of Low Birker Ta			ld system		
DESIGNATION:	Scheduled Monument (No.101961	<b>7)</b> c	ONDITION:	Generally satisfac but with significa	,	ed problems
PRINCIPAL VULNERABILITY:	Plant growth	т	REND:	Declining		
OWNER TYPE:	Private	C	ONTACT:	Principal Heritage	e at Risk	Adviser
				0161 242 1400		
site name:	Prehistoric enclosure containing te	en clearance cairr	ns south v	vest of Boat How, I	Burnmoo	or, Eskdale, Cope
DESIGNATION:	Scheduled Monument (No.100853	7) c	ONDITION:	Extensive significa	ant probl	ems
PRINCIPAL VULNERABILITY:	Plant growth	Τ	REND:	Improving		
OWNER TYPE:	Private	С	ONTACT:	Principal Heritage 0161 242 1400	e at Risk	Adviser
SITE NAME:	Prehistoric enclosure containing th				l an adja	cent hut circle
	and cairnfield north east of Boat H		skdale, C	•		
DESIGNATION:	Scheduled Monument (No.100853)	6) c	ONDITION:	Extensive significa	ant probl	ems
PRINCIPAL VULNERABILITY:	Plant growth	Т	REND:	Improving		
OWNER TYPE:	Private	C	ONTACT:	Principal Heritage 0161 242 1400	e at Risk	Adviser
CITE NIANAE.	Prehistoric enclosure north of Litt	le Pie Burnmoor	Eskdala	Copeland		
SITE NAME:			, Londaie,	•		
DESIGNATION:	Scheduled Monument (No.100853)	З) с	ONDITION:	Extensive significa	ant probl	ems
PRINCIPAL VULNERABILITY:	Plant growth	Т	REND:	Improving		
OWNER TYPE:	Private	C	ONTACT:	Principal Heritage 0161 242 1400	e at Risk	Adviser
SITE NAME:	Prehistoric enclosure, hut circle ar	d adjacent cairof	ield east d	of Whillon Beck Bu	rnmoor	Eskdala Copala
			case (			
DESIGNATION:	Scheduled Monument (No.100853	,	ONDITION:	Extensive significa	ant probl	ems
PRINCIPAL VULNERABILITY:	Plant growth	Т	REND:	Improving		
OWNER TYPE:	Private	C	ONTACT:	Principal Heritage 0161 242 1400	e at Risk	Adviser
RIORITY (FOR BUILDINGS)  Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. Slow decay; no solution agreed.	but not yet implemented.     ar       E     Under repair or in fair to good     fu       repair, but no user identified; or     with po	epair scheme in progress nd (where applicable) nd use or user identified; nctionally redundant buildir ith new use agreed but not t implemented.	are g	E: priority categories iven in brackets.	LB LPA NP RPG SM	TIONS Conservation Area Listed Building Local Planning Authori National Park Registered Park and G Scheduled Monument Unitary Authority

C Slow decay; no solution agreed.

obvious new user (applicable only to buildings capable of beneficial use).

UA Unitary Authority WHS World Heritage Site

SITE NAME:	Romano-British enclosed stone hut circle s north west of Tongue House Barn, Kentme		
DESIGNATION:	Scheduled Monument (No.1008899)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
ITE NAME:	Medieval shieling 100m west of Trout Beck,	Lakes, South Lake	land
DESIGNATION:	Scheduled Monument (No.1011135)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
ITE NAME:	Medieval shieling I50m west of Trout Beck,	Lakes, South Lake	land
DESIGNATION:	Scheduled Monument (No.1011136)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Medieval shieling 640m north of Troutbeck	Park Farm, Lakes,	South Lakeland
DESIGNATION:	Scheduled Monument (No.1011677)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Medieval shieling 70m west of Trout Beck, I	Lakes, South Lakel	and
DESIGNATION:	Scheduled Monument (No.1011137)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Round cairn I5m east of Hagg Gill, Lakes, S	outh Lakeland	
DESIGNATION:	Scheduled Monument (No.1011358)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Settlement on west slope of The Tongue, Tr	outbeck Park, Lak	es, South Lakeland
DESIGNATION:	Scheduled Monument (No.1007201)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
	Private	CONTACT:	Principal Heritage at Risk Adviser
DWNER TYPE:			
OWNER TYPE:			0161 242 1400
	Three round cairns 70m east of Rydal Beck	r, Lakes, South Lak	
SITE NAME:	Three round cairns 70m east of Rydal Beck Scheduled Monument (No.1011351)	x, Lakes, South Lak	
OWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:			eland

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site CA LB LPA NP RPG SM UA WHS

Percent values exercise         Plant growth         meson         Improving           Severative:         Private         connect         Principal Heritage at Risk Adviser           Severative:         Colom NNW of Thwate Year, Millom Without, Copeland         Generally satisfactory           Severative:         Scheduled Monument (No.1021141)         continue         Generally satisfactory           Severative:         Plant growth         make         Declining           Private         carrier         Private         Declining           Severative:         Barnscar prehistoric caimfield, two hut circle settlements, field system, funcary caims, and a Romano-British farmstead, trackway and field system, Muncaster, Copeland           Severative:         Barnscar prehistoric caimfield, two hut circle settlements, field systems, funcary caims, and a Romano-British farmstead, trackway and field system, Muncaster, Copeland           Severative:         Black Beck North prehistoric caimfield on Birkby Fell, 950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland           Severative:         Black Beck North prehistoric caimfield on Birkby Fell, 950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland           Severative:         Principal Heritage at Risk Adviser           O161.242.1400         Travare           Scheduled Monument (No.1019425)         connerse           Scheduled Monument (No.1019425)<	SITE NAME:	Shieling settlement close to the mouth of S	Scale Beck, Lowes	water, Allerdale
Development         Private         Contract:         Principal Heritage at Risk Adviser 0161 242 1400           are swet:         Lath Rigg prehistoric caimfield, hut circle and field system on Thwaites Fell 600m NNW of Thwaite Year, Hilliom Without, Copeland         Generally satisfactory but with significant localised problems mercesus.us.newseum           Decisional         Scheduled Monument (No.1021141)         controls         Generally satisfactory but with significant localised problems mercesus.us.newseum           Plant growth         merces         controls         Generally satisfactory but with significant localised problems mercesus.us.newseum           Barnscar prehistoric caimfield, two hut circle settlements, field system, funerary caims, and a Romano-British famistead, trackway and field system, funerary caims, and a Romano-British famistead, trackway and field system, funerary caims, and a Romano-British famistead, trackway and field system. funerary caims, and a Romano-British famistead, trackway and field system. funerary caims, and a Romano-British famistead, trackway and field system. funerary caims, and a Romano-British famistead, trackway and field system. funerary caims, and a Romano-British famistead, trackway and field system. funcaster, Copeland           Decisions         Principal Heritage at Risk Adviser 0161 242 1400           Streamset         Private         Controcs         Extensive significant problems           Brit growth         merces         Controcs         Extensive significant problems           Brit growth         merces         Controcs         Extens	DESIGNATION:	Scheduled Monument (No.1014735)	CONDITION:	Extensive significant problems
U1612421400       Note:     Lath Rigg prehistoric caimfield, hut circle and field system on Thwaites Fell 600m NNW of Thwaite Yeat, Millom Without, Copeland     Generally satisfactory but with significant localised problems       Prescuence:     Plant growth     massa     Declining       Declining     coxumes:     Principal Heritage at Risk Adviser 01612421400       Data growth     massa     Declining       Data growth     massa     Declining       Data growth     massa     Declining       Data growth     massa     Declining       Data growth     massa     Coxumes       Barnscar prehistoric caimfield, two hut circle settlements, field system, funcary cains, and a Romane-British farmstead, trackway and field system, funcary cains, and a Romane-British farmstead, trackway and field system, funcary cains, and a Romane-British farmstead, trackway and field system, funcary cains, and a Romane-British farmstead, trackway and field system, funcary cains, and a Romane-British farmstead, trackway and field system, funcary cains, and a Romane-British farmstead, trackway and field system, funcary cains, and a Romane-British farmstead, trackway and field system, funcaster, Copeland       Data growth     massa     Improving       Data growth     massa     Improving       Devineux United Monument (No.1019423)     coxumes     Extensive significant problems       Devineux United Monument (No.1019425)     coxumes     Generally satisfactory but with significant localised problems       Den	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
600m NIXW of Thwaite Year, Millom Withour, Copeland         Generally satisfactory           Descramon:         Scheduled Monument (No.1021141)         concore         Generally satisfactory           Dut with significant localised problems         Barnscar prehistoric caimfield, two hut circle settlements, field system funcaster, Copeland           Ownerstring:         Private         concore         Principal Heritage at Risk Adviser           One Name:         Barnscar prehistoric caimfield, two hut circle settlements, field system funcaster, Copeland         Declining           Description:         Scheduled Monument (No.1019427)         concore         Extensive significant problems           Description:         Scheduled Monument (No.1019427)         concore         Extensive significant problems           Description:         Private         concore         Extensive significant problems           Description:         Private         concore         Description           Description:         Scheduled Monument (No.1019423)         concore         Description           Description:         Scheduled Monument (No.1019425)         concore         Extensive significant problems           Description:         Private         control:         Generally satisfactory           Description:         Scheduled Monument (No.1019425)         concore         Generally satisfactory	OWNER TYPE:	Private	CONTACT:	-
but with significant localised problems principal Heritage at Risk Adviser O161 242 1400 are Name: Barnscar prehistoric caimfield, two hut circle settlements, field system, funerary caims, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a Romano-British farmstead, trackway and field system, funerary cairns, and a goowth of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland beconverted Private Priva	SITE NAME:			Thwaites Fell
Prescrew VULNERWARTY:     Plant growth     THEN:     Declining       Development     Private     Contract:     Principal Heritage at Risk Adviser 0161 242 1400       Stre NAME:     Barnscar prehistoric cairnfield, two hut circle settlements, field systems, funcarry cairns, and a Romano-British farmstead, trackway and field system, funcaster, Copeland       Desconstrowt     Scheduled Monument (No.1019427)     Constrowt       Witchew VULNEWARTY:     Plant growth     reno       Private     Constrowt:     Principal Heritage at Risk Adviser 0161 242 1400       Scheduled Monument (No.1019427)     Constrowt:     Principal Heritage at Risk Adviser 0161 242 1400       Scheduled Monument (No.1019423)     Constrowt:     Principal Heritage at Risk Adviser 0161 242 1400       Scheduled Monument (No.1019423)     Constrowt:     Extensive significant problems       Private     Constrowt:     Principal Heritage at Risk Adviser 0161 242 1400       Scheduled Monument (No.1019423)     Constrowt:     Benerally satisfactory but with significant localised problems       Previstoric cairnfield S70m south west of Barnscar settlement, Muncaster, Copeland     Desconnowt       Scheduled Monument (No.1019425)     Constrowt:     Principal Heritage at Risk Adviser 0161 242 1400       Strenster Market     Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       Desconnowt     Scheduled Monument (No.1019910)     Constrowt:	DESIGNATION:	Scheduled Monument (No.1021141)	CONDITION:	Generally satisfactory
Switzerme     Private     Contract:     Principal Heritage at Risk Adviser (161 242 1400       International Science     Barnscar prehistoric cairnfield, two hut circle settlements, field system, funerary cairns, and a Romano-British farmstead, trackway and field system, Muncaster, Copeland     Improving       Science     Scheduled Monument (No.1019427)     cosannow     Extensive significant problems       Winderwork     Private     Private     Contract     Principal Heritage at Risk Adviser (161 242 1400       Winderwork     Plant growth     resis     Improving     Principal Heritage at Risk Adviser (161 242 1400       Winderwork     Black Beck North prehistoric cairnfield on Birkby Fell, 950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland     Improving       Winderwork     Scheduled Monument (No.1019423)     cosannow     Extensive significant problems       Winderwork     Plant growth     Private     Connow     Generally satisfactory but with significant localised problems       Winderwork     Scheduled Monument (No.1019425)     cosannow     Generally satisfactory but with significant localised problems       Winderwork     Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland     Improving       Winderwork     Scheduled Monument (No.1019910)     cosannow     Extensive significant problems       Winderwork     Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland				but with significant localised problems
Adviser     Original State State     Original State     Original State     Original State     Original State     Original     Orig	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
and a Romano-British farmstead, trackway and field system, Muncaster, Copeland Scheduled Monument (No.1019427) coxumox Extensive significant problems maxume Private Private Private Private Private Black Beck North prehistoric cairnfield on Birkby Fell, 950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland Scheduled Monument (No.1019423) coxumox Extensive significant problems maxume Private Private Private Private Private Private Private Private Private Private Private Private Private Private Private Prehistoric cairnfield 570m south west of Barnscar Prevent Vulnervalume Private Pr	OWNER TYPE:	Private	CONTACT:	
Designation         Scheduled Monument (No.1019427)         constrain         Extensive significant problems           PRINCIPAL VULNERABULTY:         Plant growth         THEND:         Improving           OWNERTITY:         Private         constraint         Principal Heritage at Risk Adviser           OTIGIT 242 1400         OTIGIT 242 1400         OTIGIT 242 1400           State NAME:         Black Beck North prehistoric cairinfield on Birkby Fell, 950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland           Designation:         Scheduled Monument (No.1019423)         constrome           Scheduled Monument (No.1019423)         constrome         Extensive significant problems           Private         constrome         Extensive significant problems           Rescent VLUMERABUTY:         Plant growth         THEND:         Improving           Streetwet:         Prehistoric cairifield 570m south west of Barnscar settlement, Muncaster, Copeland         Scheduled Monument (No.1019425)         Constrome           Scheduled Monument (No.1019425)         constrome:         Principal Heritage at Risk Adviser         OTIGIT 242 1400           Streetwet:         Prehistoric cairifield 660m north east of Barnscar settlement, Muncaster, Copeland         Extensive significant problems           Rescent VULNERABUTY:         Plant growth         THEND:         Improving <td>SITE NAME:</td> <td></td> <td></td> <td></td>	SITE NAME:			
<ul> <li>Prencipal Volumervaeum:</li> <li>Plant growth</li> <li>Private</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Black Beck North prehistoric cairnfield on Birkby Fell,</li> <li>950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland</li> <li>Designations</li> <li>Scheduled Monument (No.1019423)</li> <li>CONTRCT:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant localised problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant localised problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant localised problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant problems</li> <li>Improving</li> <li>Private</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 1400</li> <li>Extensive significant problems</li> <li>Improving</li> <li>Contract:</li> <li>Principal Heritage at Risk Adviser</li> <li>O161 242 140</li></ul>	DESIGNATION:			
DWNERTYPE:         Private         CONTRCE:         Principal Heritage at Risk Adviser 0161 242 1400           STEE NAME:         Black Beck North prehistoric cairmfield on Birkby Fell, 950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland         Extensive significant problems           Designations:         Scheduled Monument (No.1019423)         CONTRCE:         Principal Heritage at Risk Adviser 0161 242 1400           Designations:         Scheduled Monument (No.1019423)         CONTRCE:         Principal Heritage at Risk Adviser 0161 242 1400           Stre NAME:         Prehistoric cairnfield 570m south west of Barnscar settlement, Muncaster, Copeland         Scheduled Monument (No.1019425)         Controne:           Scheduled Monument (No.1019425)         Controne:         Generally satisfactory but with significant localised problems           RENCERL VULNERABUTY:         Plant growth         TREND:         Improving           Scheduled Monument (No.1019910)         Controne:         Extensive significant problems           Scheduled Monument (No.1019431)         Controne:         Extensive significant problems				6 1
OIG1 242 1400         Stack Beck North prehistoric cairnfield on Birkby Fell, 950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland         Designatione       Scheduled Monument (No.1019423)       CONDITIONE       Extensive significant problems         PRINCIPAL VLINERABLITY:       Plant growth       THENO:       Improving         Scheduled Monument (No.1019423)       CONDITIONE       Extensive significant problems         Principal Heritage at Risk Adviser 0161 242 1400       OIG1 242 1400         Streame:         Prehistoric cairnfield 570m south west of Barnscar settlement, Muncaster, Copeland         Designation       Scheduled Monument (No.1019425)       Contonone:       Generally satisfactory but with significant localised problems         Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       Improving       OIG1 242 1400         Streame:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       OIG1 242 1400         Streame:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       OIG1 242 1400         Streame:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       OIG1 242 1400         Scheduled Monument (No.1019910)       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         Scheduled Monument (N	OWNER TYPE:	-	CONTACT:	- 0
950m SSW of the confluence of Linbeck Gill and Black Beck, Muncaster, Copeland         Designation       Scheduled Monument (No.1019423)       CONDITION       Extensive significant problems         RINCIPAL VLINERABUTY:       Plant growth       TRINC:       Improving         OWNER TYPE       Private       CONDITION:       Extensive significant problems         STRE NAME:       Private       CONTACT:       Principal Heritage at Risk Adviser         OBSIGNATION:       Scheduled Monument (No.1019425)       CONDITION:       Generally satisfactory but with significant localised problems         RINCIPAL VLINERABUTY:       Plant growth       TREND:       Improving         OWNER TYPE       Private       CONDITION:       Generally satisfactory but with significant localised problems         Stre NAME:       Plant growth       TREND:       Improving         OWNER TYPE       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         Stre NAME:       Prehistoric cairnfield 660m north east of Barnscar       settement:       Principal Heritage at Risk Adviser 0161 242 1400         Designation       Scheduled Monument (No.1019910)       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         Designation       Scheduled Monument (No.1019910)       CONTACT:       Principal Heritage at Risk Adviser 0161 242				
PRINCIPAL VOLNERABLITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser         OUNDERTYPE:       Prehistoric cairnfield 570m south west of Barnscar settlement, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019425)       CONDITION:       Generally satisfactory but with significant localised problems         RRINCIPAL VOLNERABLITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser         OUIS 1242 1400       CONTACT:       Principal Heritage at Risk Adviser       OI 61 242 1400         Stre NAME:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       OI 61 242 1400         Stre NAME:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       Designation:         Stre NAME:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         RRINCIPAL VOLNERABLITY:       Plant growth       TREND:       Improving         Stre NAME:       Prehistoric cairnfield and associated field system       Stom west of The Knott, Muncaster, Copeland         Designation: </td <td>SITE NAME:</td> <td>Black Beck North prehistoric cairnfield on 950m SSW of the confluence of Linbeck G</td> <td>Birkby Fell, ill and Black Beck,</td> <td>Muncaster, Copeland</td>	SITE NAME:	Black Beck North prehistoric cairnfield on 950m SSW of the confluence of Linbeck G	Birkby Fell, ill and Black Beck,	Muncaster, Copeland
OWNER TYPE     Private     CONTACT:     Principal Heritage at Risk Adviser 0161 242 1400       STEE NAME     Prehistoric cairnfield 570m south west of Barnscar settlement, Muncaster, Copeland       DESIGNATION:     Scheduled Monument (No.1019425)     CONDITION:     Generally satisfactory but with significant localised problems       RRINGPAL VOLUERABUTY:     Plant growth     TREND:     Improving       OWNER TYPE     Private     CONTACT:     Principal Heritage at Risk Adviser 0161 242 1400       Stre NAME:     Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       DESIGNATION:     Scheduled Monument (No.1019910)     CONDITION:       Extensive significant problems     Improving       RRINGPAL VOLUERABUTY:     Plant growth     TREND:       Instrement:     Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland       DESIGNATION:     Scheduled Monument (No.1019910)     CONDITION:       Extensive significant problems     Improving       OWNER TYPE     Private     CONTACT:       Prehistoric cairnfield and associated field system     350m west of The Knott, Muncaster, Copeland       DESIGNATION:     Scheduled Monument (No.1019431)     CONDITION:       Stre NAME:     Prehistoric cairnfield and associated field system     350m west of The Knott, Muncaster, Copeland       DESIGNATION:     Scheduled Monument (No.1019431)	DESIGNATION:	Scheduled Monument (No.1019423)	CONDITION:	Extensive significant problems
ANTE NAME:       Prehistoric cairnfield 570m south west of Barnscar settlement, Muncaster, Copeland         Designation:       Scheduled Monument (No.1019425)       CONDITION:       Generally satisfactory but with significant localised problems but with significant localised problems         RRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         ONIGE 1242 1400       TREND:       Improving         DWINER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         DEVENDE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         DESIGNATION:       Sch	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
Designation:       Scheduled Monument (No.1019425)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         RRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNER TYPE:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         RRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         Ster NAME:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         Ster NAME:       Prehistoric cairnfield and associated field system       Stom west of The Knott, Muncaster, Copeland         Designation:       Scheduled Monument (No.1019431)       ConDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser <td>OWNER TYPE:</td> <td>Private</td> <td>CONTACT:</td> <td></td>	OWNER TYPE:	Private	CONTACT:	
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser         OUTOENTRYPE:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONDITION:       Extensive significant problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser         OUTOENT       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory         DUT with significant localised problems       Dut with significant localised problems         PRINCIPA	SITE NAME:	Prehistoric cairnfield 570m south west of I	Barnscar settlemer	nt, Muncaster, Copeland
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         SITE NAME:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONDITION:       Extensive significant problems         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         OWNERTYPE:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         DESIGNATION:       Scheduled Monument (No.1019431)       CONTACT:       Principal teritage at Risk Adviser 0161 242 1400         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1019425)	CONDITION:	Generally satisfactory
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         SITE NAME:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONDITION:       Extensive significant problems         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         OWNERTYPE:       Plant growth       TREND:       Improving         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         DESIGNATION:       Scheduled Monument (No.1019431)       CONTACT:       Principal teritage at Risk Adviser 0161 242 1400         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNERTYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser				but with significant localised problems
STE NAME:       Prehistoric cairnfield 660m north east of Barnscar settlement, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         DOWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         STE NAME:       Prehistoric cairnfield and associated field system 350m west of The Knott, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         DESIGNATION:       Plant growth       TREND:       Declining         Deventor       Private       CONTACT:       Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
Designation:       Scheduled Monument (No.1019910)       CONDITION:       Extensive significant problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser 0161 242 1400         SITE NAME:       Prehistoric cairnfield and associated field system       SOM west of The Knott, Muncaster, Copeland         Designation:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser         SITE NAME:       Prehistoric cairnfield and associated field system 350m west of The Knott, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser	SITE NAME:	Prehistoric cairnfield 660m north east of B	arnscar settlemen	t, Muncaster, Copeland
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Improving         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser         SITE NAME:       Prehistoric cairnfield and associated field system 350m west of The Knott, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1019910)	CONDITION:	Extensive significant problems
OIGI 242 1400         STE NAME:       Prehistoric cairnfield and associated field system 350m west of The Knott, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         DWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:	
SITE NAME:       Prehistoric cairnfield and associated field system 350m west of The Knott, Muncaster, Copeland         DESIGNATION:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser	OWNER TYPE:	-	CONTACT:	
Designation:       Scheduled Monument (No.1019431)       CONDITION:       Generally satisfactory but with significant localised problems         PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser				
PRINCIPAL VULNERABILITY:       Plant growth       TREND:       Declining         OWNER TYPE:       Private       CONTACT:       Principal Heritage at Risk Adviser	SITE NAME:	Prehistoric cairnfield and associated field sy	ystem 350m west	of The Knott, Muncaster, Copeland
PRINCIPAL VULNERABILITY:     Plant growth     TREND:     Declining       owner type:     Private     contact:     Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1019431)	CONDITION:	
OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser				-
	PRINCIPAL VULNERABILITY:	-	TREND:	0
	OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

48

SITE NAME:	Prehistoric cairnfield and associated field sys 750m north east of The Knott, Muncaster, C		of Birkby Fell,
DESIGNATION:	Scheduled Monument (No.1019432)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Prehistoric cairnfield and enclosure 750m w	est of Barnscar s	ettlement, Muncaster, Copeland
DESIGNATION:	Scheduled Monument (No.1019424)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Prehistoric cairnfield on Birkby Fell, 360m so	outh east of Rave	n Crag, Muncaster, Copeland
DESIGNATION:	Scheduled Monument (No.1019433)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Prehistoric cairnfield, hut circle settlement, f	ield system, funer	rary cairn,
	and a medieval shieling on Birkby Fell west o	of Devoke Water,	Muncaster, Copeland
DESIGNATION:	Scheduled Monument (No.1019551)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth Private	TREND:	Declining Principal Heritage at Risk Adviser
OWNER TYPE:	TTIVALE	CONTACT:	0161 242 1400
SITE NAME:	Carrock Fell tungsten, lead, copper, and arse of an early 20th century tungsten mill, Mung		e remains
DESIGNATION:	Scheduled Monument (No.1019958)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Cairns on Throng Moss 700ft (210m) south	west of the rese	rvoir, Torver, South Lakeland
DESIGNATION:	Scheduled Monument (No.1007213)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Dike, circles and cairns on Bleaberry Haws,	Torver, South Lak	eland
DESIGNATION:	Scheduled Monument (No.1007212)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

49

#### SOUTH LAKELAND Early CI4 to late CI5 castle, now part of a working SITE NAME: Gleaston Castle, farm. Its condition is deteriorating, two corner towers Gleaston, are standing, the other two have collapsed. A feasibility Aldingham study was completed in 1998 but agreement has yet Listed Building Grade I, SM to be reached regarding a scheme of consolidation. DESIGNATION: Very bad CONDITION OCCUPANCY: Vacant B(B)Unknown Contact: Principal Heritage at Risk Adviser 0161 242 1400 OWNER TYPE: Fortified tower house, probably C15. Burnt 1602, repaired probably mid C17. One wall has completely Arnside Tower, SITE NAME: Arnside collapsed and there are cracks in some lintels. No work has been undertaken but urgent works are required. DESIGNATION: Listed Building Grade II\*, SM A conservation plan has been produced and its CONDITION: Very bad recommendations are under consideration. N/A OCCUPANCY: C (C) Private Contact: Principal Heritage at Risk Adviser 0161 242 1400 OWNER TYPE: SITE NAME: Beetham Hall Fortified manor house, mid C14. Hall block and cross wings, with an extensive courtyard enclosed by defensive curtain (curtain wall and uninhabited portion), wall. A conservation plan was produced in 2004. New Beetham tenant has carried out some repairs with assistance from Listed Building Grade II\*, SM DESIGNATION: English Heritage. However further repairs are Poor CONDITION: still needed. Vacant OCCUPANCY: PRIORITY: F (F) Private Contact: Principal Heritage at Risk Adviser 0161 242 1400 OWNER TYPE: Hazelslack Tower, C14 pele tower, probably in ruins since C17. SITE NAME: Recent stone collapse within the interior and Beetham cracks on the outside. Saplings growing through the walls. Only limited maintenance carried out. DESIGNATION: Listed Building Grade II, SM A conservation plan has been produced and Very bad CONDITION: its recommendations are under consideration. OCCUPANCY: Vacant C (C) Private OWNER TYPE: Contact: Principal Heritage at Risk Adviser 0161 242 1400 Devil's Bridge, CI5 or early CI6 bridge over the River Lune. SITE NAME: Rubble and ashlar triple span structure. Water penetration Kirkby Lonsdale through the deck is affecting the structure and causing decay. Investigative works have been carried out to identify DESIGNATION: Listed Building Grade I, SM the extent of the problem, and a first phase of repair is Poor CONDITION due to be carried out this year. N/A OCCUPANCY: PRIORITY: D (D) OWNERTYPE: Local authority Contact: Principal Heritage at Risk Adviser 0161 242 1400 Tower at Burneside Hall, CI4 hall house. Part of a tenanted farm. Although SITE NAME: consolidation work was undertaken some years ago, Hall Road, Burneside, Strickland Roger an updated survey is required. DESIGNATION: Listed Building Grade II\*, SM CONDITION: Fair OCCUPANCY: Vacant C (C) OWNER TYPE: Private Contact: Principal Heritage at Risk Adviser 0161 242 1400

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Peter, Woodhouse Lane, Heversham	fire in early West towe south porc	s with C14, C15, C16 additions. Rebuilt after C17, restored by Paley and Austin 1868. If, nave, north and south aisles, chancel and h.A major church but suffering from water he clerestory wall and wall of the north aisle.
Malal T T T Internet	DESIGNATION:	Listed Place of Worship Grade II*		The electrony wait and wait of the nor that asie.
	CONDITION:	Poor		
	PRIORITY:	C (New entry)		
12	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	New Road, Kendal	Nave/chano western or at eastern	1835 in Gothic style by George Webster: cel all in one, with enclosed porch under gan loft. Interior shows signs of water ingress corners, causing loss of plaster and damage ive scheme.
	DESIGNATION:	Listed Place of Worship Grade II*		
	CONDITION:	Poor		
	PRIORITY:	C (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Pr	rincipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Concentri	c stone circle on Birkrigg Common, Al	dingham	
DESIGNATION:	Scheduled	Monument (No.1013501)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Vandalism		TREND:	
OWNER TYPE:		ent or Agency	CONTACT:	Principal Heritage at Risk Adviser
OWNERTIFE.	Governme	int of Agency	CONTACT.	0161 242 1400
SITE NAME:	Round cai	rn on Appleby Hill, Aldingham		
DESIGNATION:	Scheduled	Monument (No.1013963)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant grow	rth	TREND:	Declining
OWNER TYPE:	Governme	ent or Agency	CONTACT:	Principal Heritage at Risk Adviser
				0161 242 1400
SITE NAME:	Frith Hall,	Lower Allithwaite		
DESIGNATION:	Scheduled	Monument (No.1007098)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse		TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser
			contracti	0161 242 1400
SITE NAME:	Castle Hil	l, Pennington		
DESIGNATION:	Scheduled	Monument (No.1007127)	CONDITION:	Generally unsatisfactory
DEJIGINATION:	Jenequied		CONDITION:	with major localised problems
PRINCIPAL VULNERABILITY:	Extensive	stock erosion	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser
	invate		CONTACT.	0161 242 1400
SITE NAME:		c enclosed hut circle settlement, an ass 1 barrow NNE of Appleby Slack, Urswi		osure,
DESIGNATION:	Scheduled	Monument (No.1013818)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant grow	. ,	TREND:	Declining
OWNER TYPE:	-	ent or Agency	CONTACT:	Principal Heritage at Risk Adviser
				0161 242 1400

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

GREATER MANCHEST	ΓER				
BOLTON					
	SITE NAME: Swan Lane Mill No. 3, Higher Swan Lane, Bolton		Cotton spinning mill, 1914. Building partly occupied (in multiple occupancy) and not fully maintained.		
	DESIGNATION:	Listed Building Grade II*			
Tentinatentias	CONDITION:	Poor			
	OCCUPANCY:	Part occupied			
1A	PRIORITY:	C (C)			
	OWNER TYPE:	Company	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Bolton Methodist Mission, Knowsley Street, Bolton	by Bradshaw auditorium.T makes an im	odist Mission was built between 1898 and 1900 and Gass. The interior is centred around a large he tower over the Knowsley Street entrance portant contribution to the streetscape. The roof n poor condition and further work is needed to	
The number of the second	DESIGNATION:	Listed Place of Worship Grade II, CA	the gutters a	and downpipes. Grants totalling £186,000 have	
	CONDITION:	Poor		I towards repairs to the roof and gutters, rk has not started yet.	
	PRIORITY:	D (D)			
	OWNER TYPE:	Religious organisation	Contact: Prir	ncipal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Bank Top,	Bolton			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	High		TREND:	No significant change	
CONTACT:	Jon Berry	(LPA) 01204 336042	NEW ENTRY?:	Yes	
site name:	Birley Stre	eet, Bolton			
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad	
VULNERABILITY:	High		TREND:	Deteriorating	
CONTACT:	Jon Berry	(LPA) 01204 336042	NEW ENTRY?:	Yes	
SITE NAME:	Chorley N	lew Road, Bolton			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	High		TREND:	Deteriorating	
CONTACT:	Jon Berry	(LPA) 01204 336042	NEW ENTRY?:	No	
SITE NAME:	Deansgate	, Bolton			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	High		TREND:	No significant change	
CONTACT:	Jon Berry	(LPA) 01204 336042	NEW ENTRY?:	Yes	
SITE NAME:	Firwood F	old, Bolton			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	High		TREND:	No significant change	
CONTACT:	Jon Berry	(LPA) 01204 336042	NEW ENTRY?:	Yes	
SITE NAME:	Hill Top, B	olton			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	High		TREND:	No significant change	
CONTACT:	Jon Berry	(LPA) 01204 336042	NEW ENTRY?:	Yes	

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the research of the research

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / BOLTON / BURY

SITE NAME:	Horwich Locomotive Works		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Jon Berry (LPA) 01204 336042	NEW ENTRY?:	No
SITE NAME:	Horwich, Bolton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Jon Berry (LPA) 01204 336042	NEW ENTRY?:	Yes
SITE NAME:	Queens Park, Bolton		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Deteriorating significantly
CONTACT:	Jon Berry (LPA) 01204 336042	NEW ENTRY?:	Yes
SITE NAME:	Riding Gate, Bolton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Jon Berry (LPA) 01204 336042	NEW ENTRY?:	Yes
SITE NAME:	Ringley, Kearsley		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Jon Berry (LPA) 01204 336042	NEW ENTRY?:	Yes
SITE NAME:	Wethoughton, Bolton		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Jon Berry (LPA) 01204 336042	NEW ENTRY?:	Yes

### BURY



SITE NAME:	Lower Chesham Hall, Bell Lane, Bury	House of 1713. Some repairs have been carried out, although general upgrading is still required. The Local Planning Authority and English Heritage have had a number of discussions with the owner about cross-funding			
DESIGNATION:	Listed Building Grade II*	the repair through the development of adjacent land,			
CONDITION:	Fair	though there has been no positive outcome as yet.			
OCCUPANCY:	Occupied				
PRIORITY:	C (F)				
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400			



	SITE NAME:	Church of St Gabriel, Bishops Road, Prestwich	Built in 1932-33 and designed by Isaac Taylor and W Cecil Young. Built using brown Blockley brick, with Westmorland slate roofs. The north side of the roof is in poor condition and requires significant repair works to prevent further deterioration. The south roof and gutters have already
	DESIGNATION:	Listed Place of Worship Grade II	been replaced.
	CONDITION:	Poor	
	PRIORITY:	C (New entry)	
-	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site CA LB LPA NP RPG SM UA WHS

	site name:	Church of St Hilda, Whittaker Lane, Prestwich	in the Perpe dressings ar Long-term	It in 1903-4 and designed by FP Oakley, endicular style. Red brick with terracotta d parapetted slate roof and terracotta gables. water ingress is a continuing problem with agreed. Severe rot and fungal problems
	DESIGNATION:	Listed Place of Worship Grade II		g the timbers of the east corridor.
	CONDITION:	Poor		
	PRIORITY:	C (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Mary and St Bartholomew, Bury Street, Radcliffe	cell nave, to dominated north trans	building has developed from a CI4, single the predominantly Gothic church of today – by its CI5 tower. Some medieval masonry in ept. Church of huge local significance with an
	DESIGNATION:	Listed Place of Worship Grade I		elationship to the Manor Tower located 50m of the church. Parts of the church are in poor
	CONDITION:	Poor		in particular the roof and high level stonework
	PRIORITY:	B (B)		rants totalling £183,000 have been offered.
		Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
	OWNER TYPE:	Religious of galfisation	Contact. Fr	incipal mentage at Nisk Adviser 0101 242 1400
All AL	SITE NAME:	Christ Church, High Street, Walshaw	for local bu modificatior and creation	orial church of 1892 by Lawrence Booth siness man Jesse Haworth. Minor late C20 ns included a toilet in the north east corner n of a thrust platform to the crossing, but appearance of interior and exterior is of the
A THE FILM	DESIGNATION:	Listed Place of Worship Grade II*		epair surveys have identified work required
IT IT AND AND	CONDITION:	Poor	to the high	level stonework, gutters and downpipes.
	PRIORITY:	В (В)		
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Ainsworth	n, Radcliffe		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
VULNERABILITY:	Low		TREND:	Deteriorating
CONTACT:	Mick Nigh	tingale (LPA) 0161 253 5317	NEW ENTRY?:	No
SITE NAME:	Bury Towr	n Centre		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
VULNERABILITY:	High		TREND:	Deteriorating
CONTACT:	0	tingale (LPA) 0161 253 5317	NEW ENTRY?:	No
			INEVV EINTIKT:	
SITE NAME:	Rowlands/	Brookbottoms, Ramsbottom		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
VULNERABILITY:	High		TREND:	No significant change
CONTACT:		tingale (LPA) 0161 253 5317	NEW ENTRY?:	No
SITE NAME:	Walmersle	ey		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	High		TREND:	Improving
CONTACT:		tingale (LPA) 0161 253 5317	NEW ENTRY?:	No
MANCHESTER				
LA	SITE NAME:	Police and Fire Station, London Road, Manchester	1906 as the Increasing s rainwater g	ice and Fire Station, built between 1901 and fire headquarters. Partly used as storage. igns of poor maintenance, including defective oods, and extensive water ingress. Planning and
APPENDING	DESIGNATION:	Listed Building Grade II*, CA		ng approvals were granted in September 2010
	CONDITION:	Poor		ion to a hotel and the implementation of such is being actively pursued following a public
	OCCUPANCY:	Part occupied	enquiry in 2	
	PRIORITY:	D (D)	. /	



PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Events and the sound of the s
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

OWNER TYPE: Company

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE-2011 priority categories are given in brackets.

Contact: Principal Heritage at Risk Adviser 0161 242 1400

ABBREV	(IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site
	0

### HERITAGE AT RISK 2012 / NORTH WEST / MANCHESTER

	SITE NAME:	Paragon Mill, Royal Mill Complex, Jersey Street, Ancoats, Manchester	Cotton mill of 1912. Complex also includes Royal Mill and Sedgewick Mill. Limited repairs have been undertaken, and are ongoing. A comprehensive repairs and conversion scheme has stalled due to the economic circumstances.
	DESIGNATION:	Listed Building Grade II*, CA	scheme has stalled due to the economic circumstances.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
	PRIORITY:	F (F)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Baguley Hall, Hall Lane, Baguley, Manchester	Medieval hall in the guardianship of English Heritage. English Heritage is committed to finding an appropriate new owner. A development brief has been agreed with
	DESIGNATION:	Listed Building Grade I, SM	Manchester City Council and a negotiations are ongoing with a prospective partner.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant	
La Sala Maile Manager State	PRIORITY:	E (E)	
	OWNER TYPE:	English Heritage	Contact: Principal Heritage at Risk Adviser 0161 242 1400
		0 0	1 0
	SITE NAME:	Mrs Gaskell's House, 84 Plymouth Grove, Chorlton on Medlock, Manchester	Regency villa where Elizabeth Gaskell wrote many of her novels. Owned by a trust. The first phase of repair was completed in autumn 2010 with grant support
	DESIGNATION:	Listed Building Grade II*	from English Heritage. Proposals are being developed to complete the restoration and bring the building back
Finn T	CONDITION:	Fair	into a new use by the trust, securing its future.
	OCCUPANCY:	Part occupied	,
	PRIORITY:	F (F)	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Former Welsh Baptist Chapel, Upper Brook Street, Chorlton on Medlock, Manchester	Former Unitarian Chapel and Baptist Chapel designed by Charles Barry. Deterioration continues despite emergency works designed to make the structure safe, including removal of the roof and limited demolition of
	DESIGNATION:	Listed Building Grade II*	unsafe masonry. Further works are required to protect
THE PART	CONDITION:	Very bad	the surviving fábric. The LPA are working to deliver a
	OCCUPANCY:		preferred development option to partially restore the building and bring it into new use.
	PRIORITY:	A (A)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Heaton Hall, West Wing, Heaton Park, Crumpsall, Manchester	Neo-classical country house, 1772 by James Wyatt. Partially open to the public. However, the fabric is vulnerable and the west wing is an empty shell. An initial
		Listed Building Grade I, RPG II	phase of urgent works has been implemented, informed
The Party of the P	DESIGNATION.		by a conservation plan. Further repair works are required
	CONDITION:	Poor	
	CONDITION:		by a conservation plan. Further repair works are required, with funding necessary for a major restoration scheme.
	CONDITION:	Poor Part occupied	
	CONDITION: OCCUPANCY: PRIORITY:	Poor	with funding necessary for a major restoration scheme.
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Part occupied C (C) Local authority Victoria Baths with attached forecourt walls, Hathersage Road, Longsight, Manchester	With funding necessary for a major restoration scheme. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Public baths complex, 1906. A major programme of repairs continues, led by the trust, with repairs to the front block completed in July 2008. The steering group of Manchester
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Part occupied C (C) Local authority Victoria Baths with attached forecourt walls, Hathersage Road,	With funding necessary for a major restoration scheme. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Public baths complex, 1906. A major programme of repairs continues, led by the trust, with repairs to the front block completed in July 2008. The steering group of Manchester City Council, Heritage Lottery Fund, English Heritage
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Poor Part occupied C (C) Local authority Victoria Baths with attached forecourt walls, Hathersage Road, Longsight, Manchester	<ul> <li>With funding necessary for a major restoration scheme.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Public baths complex, 1906. A major programme of repairs continues, led by the trust, with repairs to the front block completed in July 2008. The steering group of Manchester City Council, Heritage Lottery Fund, English Heritage and the Victoria Baths Preservation Trust are working to complete the restoration project which is designed</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Poor Part occupied C (C) Local authority Victoria Baths with attached forecourt walls, Hathersage Road, Longsight, Manchester Listed Building Grade II* Poor	with funding necessary for a major restoration scheme. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Public baths complex, 1906. A major programme of repairs continues, led by the trust, with repairs to the front block completed in July 2008. The steering group of Manchester City Council, Heritage Lottery Fund, English Heritage and the Victoria Baths Preservation Trust are working
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Poor Part occupied C (C) Local authority Victoria Baths with attached forecourt walls, Hathersage Road, Longsight, Manchester Listed Building Grade II* Poor	Contact: Principal Heritage at Risk Adviser 0161 242 1400 Public baths complex, 1906. A major programme of repairs continues, led by the trust, with repairs to the front block completed in July 2008. The steering group of Manchester City Council, Heritage Lottery Fund, English Heritage and the Victoria Baths Preservation Trust are working to complete the restoration project which is designed



- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

		Church of St Ann.	Classical at la church 1709 12 with three Anti-large its
and and a second s	SITE NAME:	St Ann Street	Classical style church, I 709-12, with strong Anti-Jacobite connections, influenced by principal funder Lady Ann Bland. Restored 1886 by Alfred Waterhouse. Large round-headed
			windows and internal aisle arcade of Tuscan columns supporting upper balconies and upper arcade of original slender Tuscan
DA R TAT			columns. Plays key role in defining character of St Ann's Square. Work on tower is underway; work to parapet and roof
		Listed Place of Worship Grade I, CA	supported by a further grant is expected to start after
	CONDITION: PRIORITY:	Very bad F (B)	completion of the first phase.
Human	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of Emmanuel,	Victorian church built in 1858 by Starkey and Cuffley.
AA		Barlow Moor Road, Didsbury	Reordered interior and used for BBC Radio 4 Daily Service recordings. William Morris window in south window of
10 A			transept. Water ingress is apparent in the north aisle below
	DESIGNATION:	Listed Place of Worship Grade II	the inaccessible valley gutter and some slipped slates on the roof. SmartWater protected but some evidence of
	CONDITION:	Poor	localised theft.
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
1 million	SITE NAME:	Synagogue of Withington	Red brick synagogue of 1925-6 by Delissa Joseph
The state of the		Congregation of Spanish and Portuguese Jews,	under the supervision of Joseph Sunlight in the art deco/neoclassical style of the time. The building is
		Old Lansdowne Road,	suffering from some water ingress from concealed
		Didsbury	parapet gutters and failing downpipes. It has flat roofs which were not visible to inspect. Otherwise in generally good
	DESIGNATION:	Listed Place of Worship Grade II	condition throughout.
	CONDITION:	Poor	
	PRIORITY:	A (New entry)	
AND DESCRIPTION OF THE OWNER.	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
6	SITE NAME:	St Aidan United Reform Church,	Red brick church building from 1901 with stunning art
		Palatine Road,	nouveau stained glass windows. Well maintained and in
		Didsbury	generally good condition but suffering some problems from water ingress from concealed gutters. The main church
	DECIONATION I	Listed Place of Worship Grade II	building is also used by the Manchester Korean Church.
	CONDITION:	Poor	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
			·
A.	SITE NAME:	Christ Church,	Victorian church of 1881-2 built in sandstone.
		Princess Road, Didsbury	The west end tower is now missing its pinnacles. There is widespread water ingress due to failing,
			concealed parapet gutters. A grant has been offered
	DESIGNATION:	Listed Place of Worship Grade II	under the Repair Grants for Places of Worship scheme and a repair project is in preparation.
	CONDITION:	Poor	
	PRIORITY:	B (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
<b>§</b>		Church of St lawson	CI7 church requilt and enlarged in CI0 with a district
indu a	SITE NAME:	Church of St James, Stenner Lane,	C17 church rebuilt and enlarged in C19, with a distinctive tower of I 620, with a parapet of large openwork hoops
hour		Didsbury	with crocketed corner pinnacles. There are severe issues
			of water ingress caused by repair needs to the wall head gutters and failing downpipes. At the time of visiting, plaster
	DESIGNATION:	Listed Place of Worship Grade II*	had been removed from the interior to one problem area
STOR .	CONDITION:	Very bad	to allow the wall to dry out, and a new drainpipe had been
		,	erected. Plans were in place to improve drainage.
	PRIORITY: OWNER TYPE:	B (New entry) Religious organisation	erected. Plans were in place to improve drainage. Contact: Principal Heritage at Risk Adviser 0161 242 1400

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Hyde Road, Gorton	Imposing sandstone church in a churchyard surrounded by woodland. Designed by Thomas Worthington in 1869-71, it has a six bay nave with north and south aisles. Arcade columns are of polished granite, wall faces are plaster lined with a large painting over chancel arch. The main issues have	
	DESIGNATION: CONDITION:	Listed Place of Worship Grade II*, CA Very bad	been the roof, gutters and high level stonework, all of which were in need of repair to prevent further water ingress. These repairs were grant-aided and are underway.	
	PRIORITY: OWNER TYPE:	F (F) Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400	
OLDHAM				
1.1.	SITE NAME:	Foxdenton Hall, Foxdenton Lane, Chadderton	Early C18 two storey house, built on a basement which reuses features and stonework from a building of 1620. It has a u-shaped plan with two-bay wings projecting either side. Original features remain, including some glazing	
	DESIGNATION:	Listed Building Grade II*, CA	wall panelling and a fire surround. The house is vacant and	
	CONDITION:	Poor	its condition is deteriorating with further damage from	
	OCCUPANCY:	Vacant	water ingress.	
Contraction of the second s	PRIORITY:	C (New entry)		
and the second	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Independent Methodist Chapel, George Street, Oldham	Former Methodist Chapel, built 1815, brick with Welsh slate roof. Internally it has galleries to three sides and panelled box pews. The basement contained dwellings	
	DESIGNATION:	Listed Building Grade II*	and has been altered. It is currently used for storage and has suffered from water ingress and unauthorised	
	CONDITION:	Poor	alterations. The charity who own the building have been	
	OCCUPANCY:	Vacant	awarded a grant from the Heritage Lottery Fund.	
	PRIORITY:	D (C)		
	OWNER TYPE:	Charity	Contact: Principal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Church of St Mark with Christchurch, Glodwick Road, Glodwick	Church built in 1875 in a Gothic style of rusticated coursed and squared rubble with Welsh slate roofs containing scalloped cut grey banding. The tower and spire are landmarks in the area. Inside, the nave arcade is on polished granite columns. The building is generally	
	DESIGNATION:	Listed Place of Worship Grade II	in very bad condition with the roof and high level	
E TIM			stonework of particular concern.	
	CONDITION:	Very bad	stonework of particular concern.	
ALA ST	CONDITION: PRIORITY:	Very bad A (A)	stonework of particular concern.	
		,	Contact: Principal Heritage at Risk Adviser 0161 242 1400	
	PRIORITY:	A (A)	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address	
	PRIORITY: OWNER TYPE:	A (Å) Religious organisation Church of St Margaret, Chapel Road,	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received	
	PRIORITY: OWNER TYPE: SITE NAME:	A (Å) Religious organisation Church of St Margaret, Chapel Road, Hollins	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address the failings of the tower, but the whole slate roof needs	
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	A (A) Religious organisation Church of St Margaret, Chapel Road, Hollins Listed Place of Worship Grade II	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address the failings of the tower, but the whole slate roof needs replacing and problems associated with rot need to	
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	A (A) Religious organisation Church of St Margaret, Chapel Road, Hollins Listed Place of Worship Grade II Very bad	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address the failings of the tower, but the whole slate roof needs replacing and problems associated with rot need to be resolved.	
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY:	A (A) Religious organisation Church of St Margaret, Chapel Road, Hollins Listed Place of Worship Grade II Very bad B (B)	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address the failings of the tower, but the whole slate roof needs replacing and problems associated with rot need to be resolved. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Parish church of 1847 with tower and spire added later. Has its own grave yard, now closed and adopted by the local council, with many fine monuments. Original design of roof has meant water ingress compromising the whole	
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	A (A) Religious organisation Church of St Margaret, Chapel Road, Hollins Listed Place of Worship Grade II Very bad B (B) Religious organisation Church of the Holy Trinity, Church Street, Oldham	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address the failings of the tower, but the whole slate roof needs replacing and problems associated with rot need to be resolved. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Parish church of 1847 with tower and spire added later. Has its own grave yard, now closed and adopted by the local council, with many fine monuments. Original design of roof has meant water ingress compromising the whole building. Current number of proactive people acknowledge	
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	A (A) Religious organisation Church of St Margaret, Chapel Road, Hollins Listed Place of Worship Grade II Very bad B (B) Religious organisation Church of the Holy Trinity, Church Street,	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address the failings of the tower, but the whole slate roof needs replacing and problems associated with rot need to be resolved. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Parish church of 1847 with tower and spire added later. Has its own grave yard, now closed and adopted by the local council, with many fine monuments. Original design of roof has meant water ingress compromising the whole building. Current number of proactive people acknowledge the difficulties and are trying to seek remedies. There is a strong desire to cultivate the critical role of the church as	
	PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	A (A) Religious organisation Church of St Margaret, Chapel Road, Hollins Listed Place of Worship Grade II Very bad B (B) Religious organisation Church of the Holy Trinity, Church Street, Oldham Listed Place of Worship Grade II	Contact: Principal Heritage at Risk Adviser 0161 242 1400 The Church of St Margaret in Hollins, Oldham was built in 1877 in a decorated Gothic style of squared rubble with giltstone tracery and ashlars. The church has received a large Repair Grant for Places of Worship to address the failings of the tower, but the whole slate roof needs replacing and problems associated with rot need to be resolved. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Parish church of 1847 with tower and spire added later. Has its own grave yard, now closed and adopted by the local council, with many fine monuments. Original design of roof has meant water ingress compromising the whole building. Current number of proactive people acknowledge the difficulties and are trying to seek remedies. There is a	

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

57

TH WEST / <b>OL</b>		
SITE NAME: DESIGNATION: CONDITION: PRIORITY:	Poor C (C)	This 1870 church has a landmark crossing tower with slate roofs on the nave, chancel and vestry transepts. The external masonry is rock-faced stone above projecting plinth and weathered buttresses. Inside the nave arcades are circular columns, arch-braced and scissor roof trusses and decorated tracery. Repairs are still needed for the chancel roof.
OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Crimble Mill, Crimble Lane, Heywood	Early C19 cotton mill, subsequently modified and enlarged. Retains rare water wheel housing. Roof and gutters are leaking and windows missing. Brickwork is decaying at upper levels.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	A (A)	
		Contact: Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Hopwood Hall, Rochdale Road, Middleton	House, dating from C17 and C18, incorporating parts of an early C16 open hall timber-framed structure with some C19 and C20 additions. Now vacant; last used by Hopwood Hall College. Emergency repairs have been
DESIGNATION:	Listed Building Grade II*	undertaken by the Local Authority to make the building
CONDITION:	Poor	wind and weathertight. Discussions are ongoing with a
OCCUPANCY:	Vacant	potential development partner.
PRIORITY:	С (С)	
OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Tonge Hall, William Street, Middleton	House dating from 1580s with C18 and C19 alterations. Ravaged by fire in 2007. English Heritage-funded urgent works are partly completed to stabilise the structure.
DESIGNATION:	Listed Building Grade II*	
	Very bad	
CONDITION:	very bad	
OCCUPANCY:	Vacant	
	Vacant D (E)	Contact: Principal Heritage at Risk Adviser 0161 242 1400
OCCUPANCY: PRIORITY:	Vacant D (E) Private	
OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant D (E)	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up
OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C)	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated boundary wall, railings and gates, Edmund Street, Falinge, Rochdale	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been deconsecrated and passed to the Churches Conservation
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated boundary wall, railings and gates, Edmund Street, Falinge, Rochdale	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated boundary wall, railings and gates, Edmund Street, Falinge, Rochdale Listed Building Grade I, CA Fair	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been deconsecrated and passed to the Churches Conservation
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: CONDITION:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated boundary wall, railings and gates, Edmund Street, Falinge, Rochdale Listed Building Grade I, CA Fair Vacant Vacant	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been deconsecrated and passed to the Churches Conservation
OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated boundary wall, railings and gates, Edmund Street, Falinge, Rochdale Listed Building Grade I, CA Fair	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been deconsecrated and passed to the Churches Conservation
OCCUPANCY:         PRIORITY:         OWNER TYPE:         SITE NAME:         DESIGNATION:         OCCUPANCY:         PRIORITY:         OWNER TYPE:         SITE NAME:         DESIGNATION:         OCCUPANCY:         PRIORITY:         OWNER TYPE:         PRIORITY:         OCONDITION:         CONDITION:         OCCUPANCY:         PRIORITY:         OWNER TYPE:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated boundary wall, railings and gates, Edmund Street, Falinge, Rochdale Listed Building Grade I, CA Fair Vacant C (A) Trust	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been deconsecrated and passed to the Churches Conservation Trust for its preservation.
OCCUPANCY:         PRIORITY:         OWNER TYPE:         SITE NAME:         DESIGNATION:         OCCUPANCY:         PRIORITY:         OWNER TYPE:         SITE NAME:         DESIGNATION:         OCCUPANCY:         PRIORITY:         OWNER TYPE:         PRIORITY:         OCONDITION:         CONDITION:         OCCUPANCY:         PRIORITY:         OWNER TYPE:	Vacant D (E) Private Birchinley Manor Farmhouse, Wild House Lane, Milnrow Listed Building Grade II* Poor Vacant C (C) Private Church of St Edmund and associated boundary wall, railings and gates, Edmund Street, Falinge, Rochdale Listed Building Grade I, CA Fair Vacant C (A) Trust chdale Borough	Early C17 farmhouse, 1631 on door lintel but with modern rebuilt wing. Hammer dressed stone with diminishing coursed stone slate roof. Boarded up and vacant for a long time. Derelict grade II barns are adjacent. Contact: Principal Heritage at Risk Adviser 0161 242 1400 St Edmund's Church, 1870-73, was designed by Manchester architects Medland and Taylor. It is of Gothic revival design, merged with Masonic symbolism. The church has been deconsecrated and passed to the Churches Conservation Trust for its preservation.
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: CONDITION: CONDITION: CONDITION: CONDITION: CONDITION: SITE NAME:	Church Road, Shaw, Shaw and Crompton         DESIGNATION:       Listed Place of Worship Grade II         CONDITION:       POOR         PRIORITY:       C (C)         OWNERTYPE:       Religious organisation         SITE NAME:       Crimble Mill, Crimble Lane, Heywood         DESIGNATION:       Listed Building Grade II*         CONDITION:       POOR         OCCUPANCY:       Vacant         PRIORITY:       A (A)         OWNERTYPE:       Company         SITE NAME:       Hopwood Hall, Rochdale Road, Middleton         DESIGNATION:       Listed Building Grade II*         CONDITION:       POOR         OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNERTYPE:       Listed Building Grade II*         CONDITION:       POOR         SITE NAME:       Hopwood Hall, Rochdale Road, Middleton         DESIGNATION:       Listed Building Grade II*         CONDITION:       POOR         OCCUPANCY:       Vacant         PRIORITY:       C (C)         OWNERTYPE:       Local authority         SITE NAME:       Tonge Hall, William Street, Middleton

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving significantly
CONTACT:	David Morris (LPA) 01706 924 352	NEW ENTRY?:	No

PRIORITY (FOR BUILDINGS)

- PRIORITY (FOR BUILDINGS)
  A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
  C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREVIATIONS			
CA	Conservation Area		
LB	Listed Building		
LPA	Local Planning Authority		
NP	National Park		
RPG	Registered Park and Garden		
SM	Scheduled Monument		
UA	Unitary Authority		
WHS	World Heritage Site		
	-		

### HERITAGE AT RISK 2012 / NORTH WEST / ROCHDALE / SALFORD

SITE NAME:	Castleton (South)		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	David Morris (LPA) 01706 924 352	NEW ENTRY?:	No
SITE NAME:	Middleton Town Centre		
SITE NAME: DESIGNATION:	Middleton Town Centre Conservation Area	CONDITION:	Very bad
		CONDITION: TREND:	Very bad Improving significantly

SALFORD			
	SITE NAME:	Former public baths, Collier Street, Salford	Former baths of I 855. Later used as a warehouse. Repairs undertaken several years ago. Discussions are continuing between local authority and potential developers on new uses.
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	С (С)	
Contraction of the second s	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Higher Crumpsall Synagogue, Bury Old Road, Broughton Park	Higher Crumpsall Synagogue has had several repair grants in recent years for phases of work to the building. There is still work to be done on the higher level stonework.
	DESIGNATION:	Listed Place of Worship Grade II, CA	
	CONDITION:	Poor	
The second se	PRIORITY:	C (C)	
NINGER STREET	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Mary Magdalene, Vaughan Street, Eccles	Church of 1913 of central crossing plan with chancel, north vestry and transept. Central crossing tower and nave with aisles. Poor rainwater goods put this church at risk, with vegetation on the roof and walls. General external condition is poor.
	DESIGNATION:	Listed Place of Worship Grade II	
	CONDITION:	Poor	
	PRIORITY:	A (New entry)	
States and	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Mary the Virgin, Bridgewater Road, Ellenbrook	1725 church, with five bay nave and Norman style gabled porch; small chancel with three lancet east window. Extremely poor condition of rainwater goods and extensive vegetation growing between the roof slates. There are several areas with structural fractures down the
	DESIGNATION:	Listed Place of Worship Grade II	length of the west walls. Window frames have cracked and
	CONDITION:	Poor	are deteriorating.
	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Philip, St Philips Place, New Windsor	This church has not altered much from the original 1825 neoclassical design of Sir Robert Smirke. One of the first Commissioners' Churches following the 1818 Act. Design is a reproduction of Smirke's St Mary the Virgin, Wyndham Place, London. The church has been specifically laid out within an urban
a late	DESIGNATION:	Listed Place of Worship Grade II*, CA	designed landscape. Church is of strong local significance but
Contraction of Contraction	CONDITION:	Poor	requires work on its masonry, particularly around the windows. A grant has recently been secured for this work.
Ulas Grand as	PRIORITY:	B (B)	A grant has recently been seconed for this work.
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expedience of the record of th

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREV	'IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

Place of Worship Grade II, CA bus organisation h of St John the Baptist, non Road, on Place of Worship Grade II	Contact: Pri	ave been offered and work to repair the start soon. ncipal Heritage at Risk Adviser 0161 242 1400
h of St John the Baptist, non Road, on	Church of I chamber an	ncipal Heritage at Risk Adviser 0161 242 1400
h of St John the Baptist, non Road, on	Church of I chamber an	ncipal Heritage at Risk Adviser 0161 242 1400
h of St John the Baptist, non Road, on	Church of I chamber an	ncipal Heritage at Risk Adviser 0161 242 1400
non Road, on	chamber an	
Place of Worship Grade II	with water :	876 with transeptal vestry and organ d crossing tower in the Gothic Revival style. ater goods are creating excessive overflow streaming down the exterior walls. There are of damp and fracturing at the base of several
	buttresses. T	The roof is mostly intact, although vegetation
	is visible in s	
w entry)		
ous organisation	Contact: Pri	incipal Heritage at Risk Adviser 0161 242 1400
h of St Peter, ey Road, on	single project base, and in both arcade	869 George Street church executed as a ct. Unfortunately suffering failure of the gutter efficient water discharge. Ingress of water alon es of the north and south aisles. Two phases of new the roof have just begun.
Place of Worship Grade II*		
w entry)		
ous organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400
h of St Paul, len, lester Road, on	with south v Structural c cracking at t	848 with nave, clerestory, aisles and chancel west tower, built in the Gothic Revival style. racking is evident on the north side, with the base of some buttresses. The ground church is saturated, which could contribute
Place of Worship Grade II	to the struc	tural issues. Apart from this, the building is
	in reasonab	le condition and is well maintained.
ew entry)		
ous organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400
h of St Mark, len Road, on	comprising tower, chance The high lev	a grade I listed church built in 1844-6, a nave with clerestory, aisles and west cel, side chapel, vestry and organ chamber. vel masonry is showing signs of deterioration, the spire. Structural cracks are visible internall
Place of Worship Grade I	at the rear of	of the building. Water ingress is evident on
	the high lev	el windows.
w entry)		
ous organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 140
a	CONDITION:	Very bad
	TREND:	Improving significantly
(LPA) 0161 793 3780	NEW ENTRY?:	No
ghton	CONDITION:	Very bad
-	TREND:	Deteriorating
-		No
_	ughton ea (1 PA) 0161 793 3780	ea condition:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the research of the research
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / SALFORD / STOCKPORT

SITE NAME:	Crescent		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Alison Partington (LPA) 0161 793 3780	NEW ENTRY?:	No
SITE NAME:	Irlams o' th' Height		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Alison Partington (LPA) 0161 793 3780	NEW ENTRY?:	No
SITE NAME:	St Augustine's, Pendlebury		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Alison Partington (LPA) 0161 793 3780	NEW ENTRY?:	No

		2	
	SITE NAME:	Gateway, wall and fountain at St Mary's Church, Churchgate, Stockport	Gateway (1312) to the parish church of St Mary's and wall and fountain (1853) to side. The structure has been partially dismantled for health and safety reasons.
	DESIGNATION:	Listed Building Grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY:	C (C)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Houldsworth Mill Engine House, Houldsworth Street, Reddish, Stockport	1860s central engine to rear of massive double cotton mill, which is now converted to offices and housing. No repairs yet agreed for engine house which suffers from water
		Houldsworth Street,	which is now converted to offices and housing. No repairs yet agreed for engine house which suffers from water ingress. Discussions are on-going with the owner regarding
		Houldsworth Street, Reddish, Stockport	which is now converted to offices and housing. No repairs yet agreed for engine house which suffers from water
	DESIGNATION:	Houldsworth Street, Reddish, Stockport Listed Building Grade II* Poor	which is now converted to offices and housing. No repairs yet agreed for engine house which suffers from water ingress. Discussions are on-going with the owner regarding phasing repairs in conjunction with conversion of the mill
	DESIGNATION: CONDITION:	Houldsworth Street, Reddish, Stockport Listed Building Grade II* Poor	which is now converted to offices and housing. No repairs yet agreed for engine house which suffers from water ingress. Discussions are on-going with the owner regarding phasing repairs in conjunction with conversion of the mill for which listed building consent and planning permission
	DESIGNATION: CONDITION: OCCUPANCY:	Houldsworth Street, Reddish, Stockport Listed Building Grade II* Poor Vacant C (C)	which is now converted to offices and housing. No repairs yet agreed for engine house which suffers from water ingress. Discussions are on-going with the owner regarding phasing repairs in conjunction with conversion of the mill for which listed building consent and planning permission
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY:	Houldsworth Street, Reddish, Stockport Listed Building Grade II* Poor Vacant C (C)	which is now converted to offices and housing. No repairs yet agreed for engine house which suffers from water ingress. Discussions are on-going with the owner regarding phasing repairs in conjunction with conversion of the mill for which listed building consent and planning permission have been approved.

E TIAN	SITE NAME:	Christ Church, Woodford, Wilmslow Road, Cheadle and Bramhall	Brick church with beautiful Victorian inspired interior with intricate woodcarvings and decoration. Well maintained church, but there are structural distortions in the tower and central truss to the nave.
	DESIGNATION:	Listed Place of Worship Grade II	
	CONDITION:	Poor	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400



STOCKPORT

	OWNER TYPE:	Religious organisation	Contact: Frincipal Hentage at Nisk Adviser 0161 242 1400
	SITE NAME:	Wycliffe Congregational Chapel, Wellington Road North, Heaton Norris	Medium sized, Gothic style chapel, once surrounded by terraced houses, north of Stockport town centre. Designed by architect Edward Walters, and built in 1849 of small coursed stone with ashlar dressings. The nave and side aisle support balconies carried on a cast iron frame. The church is in poor condition with water coming in
1 Tal	DESIGNATION:	Listed Place of Worship Grade II The chu	
E A	CONDITION:	Poor	through the roof. Further work is needed on the gutters and high level stonework.
	PRIORITY:	A (A)	and high level stonework.
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Event Event of the source of t

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

	SITE NAME:	Church of St Mark, Redhouse Lane, Romiley	Large Gothic Revival inspired stone church with open aspect to all elevations and clearly visible from the main Stockport East Road. High level stonework on the spire is suffering from woody growth; coping stones have been dislodged and the majority of the finials have been lost
		Listed Place of Worship Grade II	due to iron cramp damage.
	CONDITION:	Poor C (New entry)	
A A A A A A A A A A A A A A A A A A A	PRIORITY:	C (New entry) Religious organisation	Contact: Principal Henitage at Pick Advisor 0161 242 1400
	OWNER TYPE:	Ivengious of gamsation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	St Mary's in the Marketplace, Churchgate, Stockport	St Mary's is a large parish church in a conservation area. The east end chancel is medieval in origin, with much of the rest rebuilt in the C19 in sandstone in a mostly Gothic style. There have been several phases of repair work, concentrating on the urgent masonry repairs, the roof,
	DESIGNATION:	Listed Place of Worship Grade I, CA	and in particular, recently, to chancel arch. The church
	CONDITION:	Poor	plays a significant role in the centre of the historic part
	PRIORITY:	F (F)	of the town.
A TATA	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Parish Church of St Peter, St Peters Square, Stockport	Well used church, open five days a week, with a café. The church is suffering due to problems at high level. The copper bell tower is in need of repair and louvre windows are blocked up. There is some cracking of the
		Listed Place of Worship Grade II	stonework at eaves level and at ground floor level, and weathering of keystones. There is vegetation growth at
	CONDITION:	Poor	high level. The roof appears sound from the exterior
	PRIORITY:	C (New entry)	but there are problems inside with water ingress.
	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 0161 242 1400
	OWNER TIPE:	Trengious of gamsation	
	SITE NAME:	Parish Church of St Thomas, St Thomas's Place, Stockport	Highly significant Waterloo Church of the I 820s; a fine example of a Commissioners' Church. Graffiti and smashed windows suggest problems with vandalism. Vegetation growth and pigeon infestation at eaves level, and falling masonry indicate problems with high level stonework. Inside, damp
		Listed Place of Worship Grade I	patches indicate water ingress. Repair has been carried out on the roof in 1998 and the tower early in 2000s. The upper
		Poor	level windows are currently replaced with corrugated plastic,
		C (New entry)	not in keeping with such an important church, and certainly
	PRIORITY: OWNER TYPE:	Religious organisation	detracting from its significance. Contact: Principal Heritage at Risk Adviser 0161 242 1400
	OWNER I TPE:	Trengious of gamsation	Contact. I fincipal i lentage at tisk Adviser 0101 242 1400
	SITE NAME:	St Joseph's Church, Tatton Street, Stockport	Church of I 861-2 by Matthew Ellison Hadfield of Sheffield; built of hammer-dressed Yorkshire grit stone, Hollington stone dressings and slate roofs. Particularly of concern is evidence of damp and water ingress at high level, and
	DESIGNATION:	Listed Place of Worship Grade II	missing hood moulding to high level stonework.
A	CONDITION:	Poor	
	PRIORITY:	C (New entry)	
		Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
		0 0	
SITE NAME:	Hillgate, St	tockport Town Centre	
	-		

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Unknown
CONTACT:	Fiona Albarracin (LPA) 0161 474 4561	NEW ENTRY?:	No

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site

#### HERITAGE AT RISK 2012 / NORTH WEST / TAMESIDE TAMESIDE Municipal swimming baths built 1870-1, by Paul and Robinson. SITE NAME: Hugh Mason House (Former Municipal Baths), Derelict, but purchased by a developer for commercial use. Temporary works undertaken by Local Planning Authority in Henry Square, Ashton-under-Lyne 1990's and in 2003 by owner. Further discussions on potential DESIGNATION: Listed Building Grade II\* for re-use as part of wider regeneration have taken place. Enveloping works have been completed to weatherproof Poor CONDITION: 10.100 the building. OCCUPANCY: Vacant F (F) Contact: Principal Heritage at Risk Adviser 0161 242 1400 OWNER TYPE: Company Hyde Hall, Late CI6 farmhouse with later additions and part of SITE NAME: good farm group (outbuildings are Grade II listed). Town Lane. The roof covering is failing with water ingress now Denton threatening the interior. Discussions regarding urgent Listed Building Grade II\* DESIGNATION: works to the Hall and outbuildings are under way with CONDITION: Very bad the owners but no long-term solution has been identified for the site. The building is in need of a temporary Vacant OCCUPANCY: cover/urgent roof repairs. A(A)Private Contact: Principal Heritage at Risk Adviser 0161 242 1400 OWNER TYPE: SITE NAME: Old Hall Chapel, Former chapel. Once the domestic chapel of Dukinfield Old Hall Street, Hall and later a transept of the Congregational Chapel (neither of which is extant). Applications for consolidation Dukinfield and presentation of the chapel as a managed ruin have Listed Building Grade II\* DESIGNATION: been approved by the local authority but progress with Very bad CONDITION: the scheme has stalled due to economic conditions. A Friends Organisation has been set up. Vacant OCCUPANCY: PRIORITY: B (B) Contact: Principal Heritage at Risk Adviser 0161 242 1400 Company OWNER TYPE: Apethorn Farmhouse, C15 cruck-framed farmhouse and shippon. Planning and SITE NAME: listed building consents granted for residential conversion, Apethorn Lane, Hyde but difficulties relating to ownership have not been resolved and the scheme has not been implemented. Listed Building Grade II\* DESIGNATION: Poor CONDITION: OCCUPANCY: Vacant D (D) Private OWNER TYPE: Contact: Principal Heritage at Risk Adviser 0161 242 1400 Staley Hall and adjoining west wing, CI6 and CI7 manor house. Derelict and in very bad SITE NAME: condition. Revised proposals for residential conversion Millbrook, gained approval in 2010 and work has started on site. It is hoped that this work will be completed in 2012 and Stalybridge DESIGNATION: Listed Building Grade II\*, CA the hall can be removed from the Register next year. Very bad CONDITION Vacant OCCUPANCY PRIORITY F (D) OWNER TYPE: Company Contact: Principal Heritage at Risk Adviser 0161 242 1400 Church of St Michael and All Angels, Church. C10 Gothic rebuilding includes substantial C15 SITE NAME: elements. The crocketed pinnacles of the tower and the Stamford Street, pierced balustrade are suffering movement and fracturing Ashton-under-Lyne caused by widespread use of ferrous cramps and dowels. There is awareness of the need for repairs but the fundraising Listed Place of Worship Grade I DESIGNATION: capacity of the church is recovering from an earlier phase of grant-aided repair to the chancel and clerestory. Very bad CONDITION: PRIORITY B (New entry) OWNER TYPE: Religious organisation Contact: Principal Heritage at Risk Adviser 0161 242 1400

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid в deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE 2011 priority categories are given in brackets.

### ABBREVIATIONS CA LB LPA NP RPG SM Conservation Area

UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

63

	SITE NAME: DESIGNATION:	Church of St Mary, Haughton Green Road, Denton Listed Place of Worship Grade II	a brick towe need some slipped slate	ch by JM and H Taylor. Timber-framed with er and slate roof. Guttering and downpipes maintenance, and although there are no visible s, the roofs have some vegetation growing on pows to the rear have been smashed.
	CONDITION:	Poor		
	PRIORITY:	C (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400
				· · ·
010	SITE NAME:	Church of St Lawrence, Town Lane, Denton	with chance frame which is stone slate broken wind	, cruciform planned church dating from 1530 I and transepts added in 1872. It has a timber was rendered to the north in 1862. The roof e. The church is in a poor condition with dow panes, moss on the roof and ad hoc
	DESIGNATION:	Listed Place of Worship Grade II*	patching to	the high level elevations. Repair work has
	CONDITION:	Poor	concentrate	d so far on the timber frame and roof.
	PRIORITY:	F (F)		
	OWNER TYPE:	Religious organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Ashton To	wn Centre, Ashton-under-Lyne		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Medium		TREND:	No significant change
CONTACT:	Catherine	Jones (LPA) 0161 342 3118	NEW ENTRY?:	No
SITE NAME:	Stalybridge	e Town Centre		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	Medium		TREND:	Deteriorating
CONTACT:	Catherine	Jones (LPA) 0161 342 3118	NEW ENTRY?:	No
TRAFFORD				
	SITE NAME:	Church of St Martin, Church Lane, Sale	added in 18 G Truefitt. Se window is tl	n building dating to 1714 with baptistry 74 by WH Brakespear, and tower in 1887 by ettlement of lean-to baptistry and leaking west ne main cause for concern. The remainder of s now in good condition, as the tower has
	DESIGNATION:	Listed Place of Worship Grade II*		ed with grant aid from English Heritage.
Am	CONDITION:	Poor	I	0 0 0
LITTLE AND AND A	PRIORITY:	C (New entry)		
	OWNER TYPE:	Religious organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Barton-up	on-Irwell		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	High		TREND:	Deteriorating significantly
CONTACT:	-	Read (LPA) 0161 912 3149	NEW ENTRY?:	Yes
SITE NAME:	Empress, O	Old Trafford		
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad
VULNERABILITY:	High		TREND:	Deteriorating
CONTACT:	Elisabeth F	Read (LPA) 0161 912 3149	NEW ENTRY?:	Yes
SITE NAME:	George St	reet, Altrincham		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
VULNERABILITY:	Medium		TREND:	Deteriorating
CONTACT:	Elisabeth F	Read (LPA) 0161 912 3149	NEW ENTRY?:	Yes

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expedience of the record of th

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / TRAFFORD / WIGAN

SITE NAME:	Old Market Place		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Elisabeth Read (LPA) 0161 912 3149	NEW ENTRY?:	Yes
SITE NAME:	Stamford New Road, Altrincham		
SITE NAME: DESIGNATION:	Stamford New Road, Altrincham Conservation Area	CONDITION:	Poor
	,	CONDITION: TREND:	Poor Deteriorating
DESIGNATION:	Conservation Area		

WIGAN			
	SITE NAME:	Haigh Hall, School Lane, Wigan	House, I 827-40, set within the remains of early C19 gardens and pleasure grounds, now overlaid with late C20 visitor facilities and playgrounds. Ground and first floor used for commercial offices and functions. Top floor
	DESIGNATION:	Listed Building Grade II*, RPG II	is vacant. An options appraisal for the wider estate has
	CONDITION:	Poor	been completed.
	OCCUPANCY:	Part occupied	
i la	PRIORITY:	С (С)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Wigan Lane, Wigan	Neo-classical gateway with attached lodges of 1840 forming the approach to Haigh Hall from the south-west. Slates and lead hips are missing, temporary roof covering provided. Lack of permanent repair and an end use
	DESIGNATION:	Listed Building Grade II*, CA, RPG II	continues to threaten buildings. An options appraisal
	CONDITION:	Very bad	for the wider estate has been completed.
	OCCUPANCY:	Vacant	
and the second second	PRIORITY:	C (C)	
The second se	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Leigh Spinners Mill, Park Lane, Leigh	Double cotton mill, 1923, in partial use. Large steam engine in situ. The roof of the mill is in need of repair with some internal settlement evident. English Heritage
	DESIGNATION:	Listed Building Grade II*, CA	have undertaken a re-assessment of the building's significance and have offered support to the mill's owner
TITEL A PART	CONDITION:	Poor	in finding a long-term solution for the mill and its site.
THE REPORT OF	OCCUPANCY:	Part occupied	
A REAL PROPERTY OF ANY	PRIORITY:	С (С)	
ete e	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Headgear at Astley Green Colliery, Higher Green Lane, Astley Green,Tyldesley	Pit head gear dating from 1912. The site is operated as a museum, but repairing and maintaining the gear requires significant investment. English Heritage has grant aided a condition survey of the headgear, which will be used as
	DESIGNATION:	Listed Building Grade II, SM	the basis for specifying repairs.
	CONDITION:	Poor	
A REAL OF	OCCUPANCY:	Occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Barn and stable to east of Winstanley Hall and two attached gateways, Pemberton Road, Winstanley, Wigan	C17 barn with stable of 1830s and gates of 1859. A previous development proposal has stalled. Part of the parapet recently collapsed. Options for reuse are being developed by Save Britain's Heritage.
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:	Very bad	
Constant of the second se	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expediate functions and fabrics and

C Slow decay; no solution agreed.


D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREV	'IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Leigh, Leigh Bridge		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Jenny Tunney (LPA) 01942 489234	NEW ENTRY?:	Yes
SITE NAME:	Tyldesley Town Centre		
SITE NAME: DESIGNATION:	<b>Tyldesley Town Centre</b> Conservation Area	CONDITION:	Poor
		CONDITION: TREND:	Poor Deteriorating

### HALTON (UA)

	SITE NAME:	Daresbury Hall, Daresbury Lane, Daresbury	Mansion of 1759. Leaking roofs have led to widespread dry rot exacerbated by lead theft. The permission for an enabling development scheme for conversion to apartments with housing development within the grounds has lapsed
自自自自自自自		Listed Building Grade II*, CA	and a renewed application for the same scheme is currently under consultation.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	A (B)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400

Church of the Holy Trinity,

Trinity Street,

Poor

Higher Runcorn

DESIGNATION: Listed Place of Worship Grade II

SITE NAME:

CONDITION:



C (C) PRIORITY: OWNER TYPE: Religious organisation Contact: Principal Heritage at Risk Adviser 0161 242 1400 Church of St Mary, This single phase built church of 1908 by Austin and Paley SITE NAME: is a landmark of the lower Mersey. The tower has received Victoria Promenade, grant aid for repair and two phases of roof tile and gutter West Bank repair will secure this church. At present the failed parapet gutters have resulted in widespread wet rot to the DESIGNATION: Listed Place of Worship Grade II\* associated timbers, including the lower rafters and the wall plates. The internal ceilings have collapsed in places. Very bad CONDITION B (New entry) 242 | 400 iderable lier C20

OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 14
SITE NAME:	Church of St Luke, Pit Lane, Widnes	The late C15 chancel timberwork is under considerable and extensive deathwatch beetle attack and earlier C20 strengthening repairs are failing due to their reliance on timbers affected by wet rot. Due to extensive failure of the roof and instability of the parapets this church will
DESIGNATION:	Listed Place of Worship Grade II*	require several phases of repair.
CONDITION:	Very bad	
PRIORITY:	C (New entry)	
OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 14

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

Under repair or in fair to good Е repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress F and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE 2011 priority categories are given in brackets.

Large, Gothic Revival style Commissioners' Church dating

from 1838 with a chancel dating from 1867, by local

architect J Hartley. The parapet conceals a moderately

and a crenellated parapet. Inside there is a balcony on cast iron columns. Repairs are needed to the roof.

pitched roof and there are some minor flower carvings as exterior decoration. The tower has pyramid pinnacles

### ABBREVIATIONS CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site

242 1400

SITE NAME:	Augustinia	an Abbey known as Norton Prior	y, Halton		
DESIGNATION:	Schedulec	Monument (No.1015603)	CONDITION:	Generally unsatisfactory	
				with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub/tree	e growth	TREND:	Declining	
OWNER TYPE:	Local auth	nority	CONTACT:	Principal Heritage at Risk Adviser	
				0161 242 1400	
LANCASHIRE					
BURNLEY					
	SITE NAME:	Extwistle Hall and attached garden wall, Briercliffe	in later CIS refurbishme	C16 and C17 gentry hall house. Altered and remodellec in later C19. No progress has been made on repairs or refurbishment and the building continues to deteriorate. Following a change in ownership in January 2012, English Heritage and the Local Planning Authority are advising	
Third arrow the Third	DESIGNATION	<ul> <li>Listed Building Grade II*</li> </ul>	Heritage ar		
	CONDITION:	Very bad		wner on an emerging enabling development o secure the future of the building.	
	OCCUPANCY:	Vacant	proposal to	secure the latare of the building.	
The second second	PRIORITY:	A (A)			
	OWNER TYPE:	Company	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	The Holme, Burnley Boad		es from C17, with C18 and C19 alterations.	

AND AND	SITE NAME:	The Holme, Burnley Road, Cliviger	House dates from C17, with C18 and C19 alterations. Use as a nursing home ceased in 2001/02 and a serious fire in 2003 destroyed the internal structure and roof of the
	DESIGNATION:	Listed Building Grade II*	C17 hall range. English Heritage and the Local Planning Authority are in discussions with the owner regarding
	CONDITION:	Very bad	future plans.
	OCCUPANCY:	Vacant	
	PRIORITY:	A (A)	
© Richard E Gruise	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Arched gateway and garden wall attached to south front of	C17 gate and garden wall. Survey carried out in August 1991 and has continued to deteriorate since then.

Shuttleworth Hall, Hapton

DESIGNATION: Listed Building Grade II\* Poor

N/A

C (C)

CONDITION:

OCCUPANCY:


OWNERTYPE: Private

PRIORITY:





AA	SITE NAME:	Shuttleworth Hall, Hapton	Early to mid C17 manor house. Now two dwellings. Requires a full condition survey and schedule of works which English Heritage will endeavour to negotiate.
-	DESIGNATION:	Listed Building Grade I	
-	CONDITION:	Fair	
Ħ	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
. seve	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400



PR	IORIT	Y (F	OR	BUI	LDI	√GS)

- А
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

Е Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE-2011 priority categories are given in brackets.

Contact: Principal Heritage at Risk Adviser 0161 242 1400

### ABBREVIATIONS CA LB LPA NP RPG SM UA WHS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / BURNLEY / CHORLEY

SITE NAME:	Burnley Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Erika Eden-Porter (LPA) 01282 425011	NEW ENTRY?:	No
SITE NAME:	Burnley Wood, Burnley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Erika Eden-Porter (LPA) 01282 425011	NEW ENTRY?:	No
SITE NAME:	Canalside, Burnley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Erika Eden-Porter (LPA) 01282 425011	NEW ENTRY?:	No
SITE NAME:	Palatine, Burnley		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating significantly
CONTACT:	Erika Eden-Porter (LPA) 01282 425011	NEW ENTRY?:	No

### CHORLEY

CHORLET					
	SITE NAME:	Bank Hall, Liverpool Road, Bretherton	Country house first built in I 608, and extensively added to between 1832-3. Derelict since 1985. English Heritage funded emergency repairs to stabilise the stair tower in 2002. Permission has recently been granted for a scheme		
	DESIGNATION:	Listed Building Grade II*	being carried out by the Heritage Trust for the North West		
	CONDITION:	Very bad	and Urban Splash for the renovation of the hall for residential use with enabling development for further		
	OCCUPANCY:	Vacant	residential units.		
(V - 34) (S.S.	PRIORITY:	D (D)			
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400		
	SITE NAME:	Lower Burgh Hall, Coppull New Road, Chorley	Early C17 timber-framed farmhouse, with C19 additions. English Heritage funded a condition survey and structural repairs were completed in 2009. Restoration works		
	DESIGNATION:	Listed Building Grade II*	to the exterior are complete and works to the interior are continuing.		
	CONDITION:	Good			
	OCCUPANCY:	Part occupied			
	PRIORITY:	F (F)			
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400		
ETTES	SITE NAME:	Buckshaw Hall, Euxton Lane (off), Euxton	Timber-framed former manor house dating from early CI7 and restored in 1885. Unoccupied since WWII. Building forms part of the former Royal Ordnance site,		
AND THE REAL	DESIGNATION:	Listed Building Grade II*	now being developed for housing. Structural repairs are completed and internal works are ongoing. Sold in 2009		
Co Presson	CONDITION:	Good	to a private individual.		
The statement	OCCUPANCY:	Vacant			
	PRIORITY:	E (F)			
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400		

SITE NAME:	Ingrave Farm moated site, moated site 100m wes	st of Ingrave I	arm and connecting channel, Eccleston
DESIGNATION:	Scheduled Monument (No.1012502)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400

### PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expediate functions and fabrics and

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site

SITE NAME:	Bretters Farm moated site and two fishponds, Heath Charnock			
DESIGNATION:	Scheduled Monument (No.1009350)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	

FYLDE				
	SITE NAME:	Lytham Hall, Ballam Road, Lytham, Lytham St Annes	Built in 1756 on the site of an earlier C17 manor house and monastic settlement. Acquired by a Trust in 1997 who have undertaken a condition report which highlights the required urgent repair works. Plans have subsequently	
	DESIGNATION:	Listed Building Grade I, CA, RPG II	been drawn up for a multi-use scheme for the hall and	
	CONDITION:	Fair	are awaiting implementation.	
	OCCUPANCY:	Part occupied		
	PRIORITY:	D (D)		
The Real Property in the second	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400	
HYNDBURN				
	SITE NAME:	Parkers Farmhouse, Cow Hill Lane, Rishton	Farmhouse circa I 600. End bay used for farm storage, but remainder disused. In need of masonry repairs, roof and rainwater disposal maintenance. Despite discussions with the Local Planning Authority there is no progress on	
The second se	DESIGNATION:	Listed Building Grade II*	temporary or full refurbishment, or on an appropriate use.	
TI II - III	CONDITION:	Poor		
	OCCUPANCY:	Vacant		
Martin La	PRIORITY:	С (С)		
THE STREET	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Church of St Augustine of Hippo, Bolton Avenue, Accrington	Arts and Crafts Perpendicular style church built 1908-9. Some stonework and mortar is badly weathered due to hillside position. Internally the church has damp patches caused by leaking concealed gutter. There is also water ingress to the tower following repairs to the weather vane.	
	DESIGNATION:	Listed Place of Worship Grade II		
	CONDITION:	Poor		

	PRIORITY: OWNER TYPE:	C (New entry) Religious organisation	Contact: Prir	ncipal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Church of St James, St James Street, Accrington	C20. West to chancel exte east corner.	763 enlarged in C19 and altered in the early ower of 1804, with large two storey nave and ended in 1820s with the vestry in the north Late Victorian pews and choir area due to be reordering. North east corner of the chancel	
HILLAR A A DO ALLA	DESIGNATION:	Listed Place of Worship Grade II	has serious problems with water ingress and the bu		
	CONDITION:	Poor	must be reg	arded as at high risk until this is resolved.	
	PRIORITY:	C (New entry)			
	OWNER TYPE:	Religious organisation	Contact: Prir	ncipal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Remains c	f Aspen Colliery, associated beehive co	oking ovens ar	nd canal basin, Hyndburn	
DESIGNATION:	Scheduled	Monument (No.1016943)	CONDITION:	Generally unsatisfactory	
				with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub/tree	growth	TREND:	Declining	
OWNER TYPE:	Local auth	ority	CONTACT:	Principal Heritage at Risk Adviser	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expediate functions and fabrics and
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

0161 242 1400

## ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / LANCASTER

### LANCASTER

	SITE NAME:	Queen Victoria Memorial, Dalton Square, Lancaster	1906 monument to Queen Victoria. Executed by Herbert Hampton, presented by Lord Ashton. Portland stone ashlar with bronze reliefs and statuary. Topped with a statue
	DESIGNATION:	Listed Building Grade II*, CA	of Queen Victoria, with side bas-relief panels portraying groups of eminent Victorians. The bronze is corroding
	CONDITION:	Poor	(green patina). The stonework suffers from staining and
	OCCUPANCY:	N/A	the monument is often subject to graffiti.
I BOLL	PRIORITY:	C (New entry)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Former Chapel of St Mary in the grounds of Ellel Grange, Ellel	Former chapel built on the Ellel Grange estate in 1873 and designed by W and G Audsley. A striking building in the high Victorian style with ceiling paintings and high quality internal fittings, some stolen. Building has been
and the	DESIGNATION:	Listed Building Grade II*	vacant for at least 17 years. In 2006-7, planning permission
the second second	CONDITION:	Poor	and listed building consent were granted for repair and
	OCCUPANCY:	Vacant	extension. Work has not commenced and permissions
	PRIORITY:	A (B)	have now expired.
Contraction of the second second	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Stables west of Over Hall, Ireby	Stables built I 690 belonging to Over Hall. Currently used for storage. Large two storey stone block with stone slate roof in very poor condition. Structural roof members and
The second secon	DESIGNATION:	Listed Building Grade II*	stone slate coverings are deteriorating, permitting water ingress. The Local Planning Authority and English Heritage
11-11-11-11-11-11-11-11-11-11-11-11-11-	CONDITION:	Poor	continue discussions with the owner to bring the building
	OCCUPANCY:	Part occupied	back into use.
100 ATHE BOAT	PRIORITY:	С (С)	
and the second se	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	The Winter Gardens, 207-214 Marine Road Central, Morecambe	Theatre built in 1896. Had fallen into disuse and disrepair before undergoing major repair and refurbishment completed in 1998 with English Heritage grant support.
	DESIGNATION:	Listed Building Grade II*	The Friends of the Winter Gardens purchased the building and continue in their efforts to make the theatre suitable
# 0000 2 0 0000 f	CONDITION:	Fair	for public performances. Discussions with the local planning
Construction of the second sec	OCCUPANCY:	Part occupied	authority and English Heritage are ongoing.
	PRIORITY:	E (E)	
and the second second	OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Slackwood Farmhouse,	Late C17 house with deep double-pile plan of unusually
Real All		New Road, Silverdale	early date. A scheme is being implemented to bring the farmhouse and adjacent barn into beneficial use.
	DESIGNATION:	Silverdale	early date. A scheme is being implemented to bring the
-	DESIGNATION:	Silverdale	early date. A scheme is being implemented to bring the
		Silverdale Listed Building Grade II*	early date. A scheme is being implemented to bring the
	CONDITION:	Silverdale Listed Building Grade II* Fair	early date. A scheme is being implemented to bring the
	CONDITION: OCCUPANCY:	Silverdale Listed Building Grade II* Fair Vacant F (F)	early date. A scheme is being implemented to bring the
	CONDITION: OCCUPANCY: PRIORITY:	Silverdale Listed Building Grade II* Fair Vacant F (F)	early date. A scheme is being implemented to bring the farmhouse and adjacent barn into beneficial use.
	CONDITION: OCCUPANCY: PRIORITY:	Silverdale Listed Building Grade II* Fair Vacant F (F)	early date. A scheme is being implemented to bring the farmhouse and adjacent barn into beneficial use. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Church with C12 origins, altered in 1771 and 1830; restored 1902. Nave and chancel under one roof with western bellcote. North aisle or transept at right angles. Interior has galleries at west end of nave and north end
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Silverdale Listed Building Grade II* Fair Vacant F (F) Private Church of St Helen, Church Grove, Overton	<ul> <li>early date. A scheme is being implemented to bring the farmhouse and adjacent barn into beneficial use.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church with C12 origins, altered in 1771 and 1830; restored 1902. Nave and chancel under one roof with western bellcote. North aisle or transept at right angles. Interior has galleries at west end of nave and north end of transept. C18 pulpit and earlier font. The west wall of</li> </ul>
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME:	Silverdale Listed Building Grade II* Fair Vacant F (F) Private Church of St Helen, Church Grove, Overton	early date. A scheme is being implemented to bring the farmhouse and adjacent barn into beneficial use. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Church with C12 origins, altered in 1771 and 1830; restored 1902. Nave and chancel under one roof with western bellcote. North aisle or transept at right angles. Interior has galleries at west end of nave and north end of transept. C18 pulpit and earlier font. The west wall of the nave shows signs of the hard mortar cracking and water ingress. The roof is in very poor condition with
	CONDITION: OCCUPANCY: PRIORITY: OWNER TYPE: SITE NAME: DESIGNATION:	Silverdale Listed Building Grade II* Fair Vacant F (F) Private Church of St Helen, Church Grove, Overton	early date. A scheme is being implemented to bring the farmhouse and adjacent barn into beneficial use. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Church with C12 origins, altered in 1771 and 1830; restored 1902. Nave and chancel under one roof with western bellcote. North aisle or transept at right angles. Interior has galleries at west end of nave and north end of transept. C18 pulpit and earlier font. The west wall of the nave shows signs of the hard mortar cracking and
	CONDITION: OCCUPANCY: PRIORITY: OWNERTYPE: SITE NAME: DESIGNATION: CONDITION:	Silverdale Listed Building Grade II* Fair Vacant F (F) Private Church of St Helen, Church Grove, Overton	early date. A scheme is being implemented to bring the farmhouse and adjacent barn into beneficial use. Contact: Principal Heritage at Risk Adviser 0161 242 1400 Church with C12 origins, altered in 1771 and 1830; restored 1902. Nave and chancel under one roof with western bellcote. North aisle or transept at right angles. Interior has galleries at west end of nave and north end of transept. C18 pulpit and earlier font. The west wall of the nave shows signs of the hard mortar cracking and water ingress. The roof is in very poor condition with

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / LANCASTER / PENDLE / PRESTON

SITE NAME:	Castle Stede motte and bailey, Hornby, Hornby-	with-Farleton	1
DESIGNATION:	Scheduled Monument (No.1017689)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate natural erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Cockersand Premonstratensian Abbey, Thurnhar	n	
DESIGNATION:	Scheduled Monument (No.1018919)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Warton Crag small multivallate hillfort, Warton		
DESIGNATION:	Scheduled Monument (No.1007633)	CONDITION:	Generally unsatisfactory

			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400

K.	SITE NAME:	Capernwray Hall, Over Kellet/Borwick	Formal gardens of mid to late C19, a rose garden of 1901 by Thomas Mawson and parkland of early C19. Capernwray Hall (listed grade II*) is owned by a religious
	DESIGNATION:	Registered Park and Garden Grade II, also 3 LBs	Capernwray Hall (listed grade II*) is owned by a religious organisation. New development immediately to south of the Hall and close to the drive has significantly impacted
	CONDITION:	Generally satisfactory but with significant localised problems	upon southern approach to the Hall. Additional new build is planned. Parkland to north of Hall largely retains its historic character, with fine views to the Hall.
	VULNERABILITY	Medium	
	TREND:	Declining	
and the same set of the same	OWNER TYPE:	Mixed, multiple owners	Contact: Principal Heritage at Risk Adviser 0161 242 1400

### PENDLE

SITE NAME:	Brierfield Mills, Brierfield		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Rosemary Lyons (LPA) 01282 661 788	NEW ENTRY?:	No
SITE NAME:	Whitefield, Nelson		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving significantly
CONTACT:	Rosemary Lyons (LPA) 01282 661 788	NEW ENTRY?:	No

### PRESTON



SITE NAME:	Harris Institute, Avenham Lane, Preston
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Built in 1846-9 as 'Preston Institution for the diffusion of useful knowledge'. Extended in 1883. Sandstone ashlar with slate roof. Sold at auction in December 2009 to a private individual. The new owner proposes to retain the building in educational use.

Contact: Principal Heritage at Risk Adviser 0161 242 1400

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Event Event of the source of t
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE-2011 priority categories are given in brackets.

## ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

	SITE NAME:	Preston 7th Day Adventist Church, Grimshaw Street, Avenham	and 1859 by this building in particular stonework	Congregational chapel, built between 1857 y Bellamy and Hardy. The major issue facing is over the material used in its construction; r corroding iron cramps are damaging spire and corroding bars are destabilising west ullions. The main roof has spread (this may	
	DESIGNATION:	Listed Place of Worship Grade II	be historic)	and abutment gutter to the spire has failed. Iling £188,000 have been offered towards	
	CONDITION:	Poor	the spire, hi	igh level masonry and west window.	
	PRIORITY:	D (D)		-	
	OWNER TYPE:	Religious organisation	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Fishergate	Hill, Preston			
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor	
VULNERABILITY:	Low		TREND:	Deteriorating	
CONTACT:	Diane Vau;	ghton (LPA) 01772 906 598	NEW ENTRY?:	No	
RIBBLE VALLEY					
	SITE NAME:	Townhead, Slaidburn	acquired by discussions	country house. The property was recently ' a new owner who entered into extensive with English Heritage regarding the sympatheti re-use of the building. A scheme for the	
	DESIGNATION:	Listed Building Grade II*	renovation	of Townhead is almost complete.	
	CONDITION:	Fair			
		Part occupied			
	PRIORITY: OWNER TYPE:	F (F)	Contorte De	incipal Llavitage at Rick Advisor 01(1,242,140)	
	OWNER I TPE:	TTIVALE	Contact. II	incipal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Whalley Abbey (west range), Whalley	The remains of this medieval Cistercian Monastery are jointly owned by the C of E and the Roman Catholic Church. The west range survives as a standing building, which is at risk. Emergency repairs to the roof have been		
	DESIGNATION:	Listed Building Grade I, SM, CA	undertaken and consolidation work to some of the ruins are currently underway. No further use for the site has yet been identified.		
	CONDITION:	Very bad			
A	OCCUPANCY: PRIORITY:	A (A)	yet been id	entilled.	
	-	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 140		
SITE NAME:	The Old I	ower Hodder Bridge, Aighton, Bailey.	and Chaigley		
DESIGNATION:		Monument (No.1003563)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:		natural erosion	TREND:	Declining	
OWNER TYPE:	Local auth	ority	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Ashnott le	ead mine and lime kiln, 90m south of	Ashnott, Newt	con	
DESIGNATION:	Scheduled	Monument (No.1016550)	CONDITION:	Generally satisfactory	
				but with minor localised problems	
PRINCIPAL VULNERABILITY:	Dumping		TREND:	Declining Bringing L Louitage at Bigly Advisor	
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
	Ribcheste	r Roman fort (Bremetennacum), Ribc	hester		
SITE NAME:		Monument (No.1005110)	CONDITION:	Generally satisfactory	
	Scheduled		CONDITION:		
SITE NAME: DESIGNATION:	Scheduled			but with significant localised problems	
			TREND:	but with significant localised problems Stable	
DESIGNATION:		ent requiring planning permission	TREND: CONTACT:		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

RIBBLE VALLEY / SOU	TH RIBB	LE / BLACKBURN WITH DARW	(UA)
	SITE NAME:	Woodfold Park, Mellor Pleasington, Pleasington/Samlesbury/Mellor	Park laid out in the 1790s providing the setting for a country house. The house is now subdivided for multiple ownership and the various estate buildings
	DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs	have been converted as private dwellings. This progressive redevelopment has impacted significantly upon the historic
	CONDITION:		character of this designed landscape. Part of the park is in Blackburn with Darwen and South Ribble.
	VULNERABILITY	-	
	TREND:	Declining	
	OWNER TYPE:	Private, multiple owners	Contact: Principal Heritage at Risk Adviser 0161 242 1400
LANCASHIRE			
ROSSENDALE			
	SITE NAME:	Grane Mill	Engine house, boiler house and chimney forming part of
- and and the	SHE MAME:	early C20 weaving mill power unit, Lane Side Road, Haslingden	mill complex opened in 1907 and operated until 1979. The site is now affiliated to the Heritage Trust for the North West. Urgent repairs to the chimney are under
and the state of the second	DESIGNATION:	Scheduled Monument	way. A grant-aid application has been submitted for
The second se	CONDITION:	Poor	asbestos removal and to enable survey work and urgent
A STATE OF		Part occupied	repairs to other parts of the complex A Heritage Lottery
	PRIORITY:	A (B)	Fund bid is in preparation.
	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 0161 242 1400
	Owner Tipe:	TTIVALE	Contact, Thincipal Fieldage at thisk Adviser 0101 212 1100
	SITE NAME:	Church of St John the Evangelist, Burnley Road, Crawshawbooth, Rawtenstall	Built in 1890-92 by important north-west architects Austin and Paley. Large sandstone church building, an important feature of the local area. Lofty interior with
	DESIGNATION:	Listed Building Grade II*	fine original fittings. Suffered from water ingress and issues with maintenance. Closed for worship, January
and have a	CONDITION:	Poor	2012. Discussions about the future use of the building
	OCCUPANCY:	Vacant	are on-going.
THE PARTY OF A STATE	PRIORITY:	A (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St James, Church Street, Haslingden	Church of 1780, enlarged and tower added in 1872, and later altered in the C19. Watershot coursed sandstone with rusticated quoins and slate roof. At risk because the tower is saturated. The interior remains very fine.
	DESIGNATION:	Listed Place of Worship Grade II	
	CONDITION:	Poor	
	PRIORITY:	C (New entry)	
	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 0161 242 1400
<b>(</b>	SITE NAME:	Church of St Thomas,	Church of 1850-57 by EH Shellard. Rock-faced sandstone,
		Helmshore Road, Haslingden	two span slate roof, decorated style with reticulated tracery. Commissioners' Church. Concerns over the tower, which is saturated. The wooden flooring is rotten and the interior plaster is wet in places.
	DESIGNATION:	Listed Place of Worship Grade II	interior plaster is wet in places.
	CONDITION:	Poor	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
SITE NAME:	Bacup Tov	vn Centre	
DESIGNATION:	Conservat	ion Area	CONDITION: Very bad
VULNERABILITY:	Low		TREND: Deteriorating
		tabar (LDA) 0170/ 220 / 42	

CONTACT:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expediate functions and fabrics and
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Rachel Fletcher (LPA) 01706 238 642

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

No

NEW ENTRY?:

# ABBREVIATIONS CA LB LPA NP RPG SM UA WHS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

73

WEST LANCASHIRE			
FIT	SITE NAME:	Barn approximately 100 metres south west of Martin Hall Farm, New Lane, Burscough	Barn, late C16. Planning permission and listed building consent granted for conversion for residential use, but work has not yet started on site.
	DESIGNATION:	Listed Building Grade II*	
	CONDITION:		
L L Part	OCCUPANCY:	Part occupied	
the second second	PRIORITY:	D (D)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Ruins of Halsall Rectory 230 metres north north east of St Cuthberts Church, Halsall Road, Halsall	Ruins of rectory, CI4. Suffering from structural movement, poor pointing and vegetation growth. The wider site is subject to unmanaged tree regeneration and growth which is damaging the archaeological remains. A scheme to bring
	DESIGNATION:	Listed Building Grade II, SM, CA	the site into good condition via a grant-aided Management
	CONDITION:		Agreement is being developed with the agents for the
	OCCUPANCY:		owners. The LPA Arboriculture and Conservation officers have been consulted.
	PRIORITY:	A (A)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Water Tower, Tower Hill, Ormskirk	Water tower built between 1853-4. An application for planning permission and listed building consent for seven apartments was refused at appeal by the government inspector on grounds of privacy. At recent appeal the
	DESIGNATION:	Listed Building Grade II*	inspector upheld the refusal.
	CONDITION:		
	OCCUPANCY:		
	PRIORITY:	C (C)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Scarisbrick Hall, Southport Road, Scarisbrick, Ormskirk	Important country house by Pugin dated 1836-45 and of high architectural importance. In need of extensive repair. English Heritage are in negotiations with the owners and
· · · · ·	DESIGNATION:	Listed Building Grade I, CA, RPG II	the local planning authority regarding proposed enabling development on the site
ALL AND	CONDITION:		
THURSDAY TOULS	OCCUPANCY:	Part occupied	
The second second	PRIORITY:	С (В)	
KIR	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Remains of Up Holland Benedictine Priory, Church Street, Up Holland	Remains of priory, CI4. The boundary wall between the Conservative Club car park and The Priory House is suffering from crumbling stone, defective pointing and
TT	DESIGNATION:	Listed Building Grade II, SM, CA	extensive vegetation growth on the Priory House side.
	CONDITION:	Poor	
AND DE BORA TO ANT	OCCUPANCY:		
and the state of the	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Old Grammar School, School Lane, Up Holland	School built early C17 and extended in the early C18. Became workshops in the early C19 and C20. Local authority is in discussion with the owner regarding new use but problems occur due to lack of curtilage and
	DESIGNATION:	Listed Building Grade II*, CA	poor access.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
A MARK	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / WEST LANCASHIRE / WYRE / KNOWSLEY

SITE NAME:	Rufford moated site, Rufford			
DESIGNATION:	Scheduled Monument (No.1012316)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			0161 242 1400	
SITE NAME:	Moated site of Scarisbrick Hall, Scarisbrick			
DESIGNATION:	Scheduled Monument (No.1011997)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			0161 242 1400	
	SITE NAME: Scarisbrick Hall, Scarisbrick	A landscape	e park possibly altered following Humphry	
	DESIGNATION: Registered Park and Garden Grade II, also CA, 7 LBs, 3 SMs	II. Repton's Red Book proposals of 1803, associated with a country house extensively remodelled and extended by the Pugins in the mid C19. Hall (listed grade I) now occupied by a school, pleasure grounds occupied by pugeness asciellancy building. Multiple occupied by		
	CONDITION: Generally satisfactory but with significant localised problems			
	VULNERABILITY: Medium			
NAME AND ADDRESS OF TAXABLE PARTY.	TREND: Declining			
	OWNER TYPE: Mixed, multiple owners	Contact: Principal Heritage at Risk Adviser 0161 242 140		
SITE NAME:	Ruff Lane			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	Low	TREND:	Deteriorating	
CONTACT:	lan Bond (LPA) 01695 585167	NEW ENTRY?:	No	
SITE NAME:	Scarisbrick Park			
DESIGNATION:	Conservation Area	CONDITION:	Very bad	
VULNERABILITY:	Low	TREND:	Improving	

### **WYRE**

	SITE NAME:	Marsh Mill, Fleetwood Road North, Thornton-Cleveleys	Tower windmill, 1794. Tapering brick tower, rendered, on circular plan. Most original internal wooden machinery remains in-situ. Open to the public. Cracked render coating is allowing water ingress affecting external			
a contraction	DESIGNATION:	Listed Building Grade II*	timbers. Damp penetration is affecting interior wall			
	CONDITION:	Fair	surfaces. Repairs needed to the external walkway and sails. A full building survey is being carried out to			
	OCCUPANCY:	Part occupied	prioritise the most urgent works.			
	PRIORITY:	C (New entry)				
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400			

### MERSEYSIDE

I							
I	К	N 1	0	<b>\</b>	10		
I	ĸ	NI	()	$\mathbf{X}$	15	- Y	

SITE NAME:	Prescot Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Christine Anders (LPA) 0151 443 2397	NEW ENTRY?:	No

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

### HERITAGE AT RISK 2012 / NORTH WEST / KNOWSLEY / LIVERPOOL

SITE NAME:	South Park Road, Kirkby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Christine Anders (LPA) 0151 443 2397	NEW ENTRY?:	No

LIVERPOOL			
1 And	SITE NAME:	St Luke's Church, gateposts and railings, Berry Street, Liverpool	Former Anglican Church built 1811-1832 in the Perpendicular Gothic style by John Foster, completed by his son John Foster junior. Damaged by bombing in May 1941, now largely regarded as a War Memorial but
	DESIGNATION:	Listed Building Grade II*, CA	not officially designated as such. A study recommended a
A for the state of the state of the state	CONDITION:	Fair	cultural venue option but no funding has been identified.
A 10-0100 0 0 0 0 0 0	OCCUPANCY:	N/A	
	PRIORITY:	C (D)	
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Wellington Rooms, Mount Pleasant, Liverpool	Built as a private assembly room for the Wellington Club in 1815. Severe dry rot continues to be monitored. An options appraisal has been undertaken and the lease
N manufacture and the	DESIGNATION:	Listed Building Grade II*, CA	now rests with the Duchy of Lancaster. Emergency roof repairs were grant aided by English Heritage during 2011
	CONDITION:	Very bad	and the Heritage Open Day proved very successful,
	OCCUPANCY:	Vacant	generating interest from a community group with
	PRIORITY:	A (A)	whom discussions are at an early stage.
	OWNER TYPE:	Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400
*			
æ	SITE NAME:	Royal Insurance Building, North John Street, Liverpool	A grand Neo-Baroque office building of 1903. Urgent works have previously been undertaken and amended proposals for a hotel conversion
E. F.	DESIGNATION:	Listed Building Grade II*, WHS, CA	have been approved.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant	
	PRIORITY:	D (D)	
	OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0161 242 1400

Î	SITE NAME:	Church of Saint Andrew, Rodney Street, Liverpool	Former Presbyterian Church of 1823. Fire damaged during the 1980s with no roof and only the external walls surviving. Following acquisition by the Local Planning
	DESIGNATION: CONDITION:	Listed Building Grade II*, CA Very bad	Authority and emergency repairs grant aided by English Heritage a developer has acquired a long lease and is currently on site with a scheme to convert the building
	OCCUPANCY:	Vacant	into student apartments.
		F (C) Local authority	Contact: Principal Heritage at Risk Adviser 0161 242 1400



PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Events and the sound of the s
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. Under repair or in fair to good Е

OWNER TYPE: Private

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). with new use agreed but not yet implemented.

F

NOTE 2011 priority categories are given in brackets.

Contact: Principal Heritage at Risk Adviser 0161 242 1400

ABBREV	(IATIONS
CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

HERITAGE AT RISK 2012 / NORTH WEST / LIVERPOOL

MAN TO	SITE NAME:	Greenbank Drive Synagogue, Greenbank Drive, Sefton Park, Liverpool	local congre	tyle synagogue, built 1936.Vacated by the gation.The building is in need of substantial tiations with a prospective purchaser have
	DESIGNATION:	Listed Building Grade II*, CA, RPG II*	recently star	iled.
一种花花 同学 / 論	CONDITION:	Poor		
	OCCUPANCY:			
Constraint and	PRIORITY:	A (C)		
	OWNER TYPE:	Religious organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 140
	SITE NAME: Warehouse on north side of de Stanley Dock, Liverpool		Dock warehouse, 1852-4 by Jesse Hartley. In very poor condition and deteriorating further due to long term vacancy. An application has recently been approved for	
	DESIGNATION:	Listed Building Grade II*, WHS	use hotel de	d scheme to convert the building as a mixed evelopment.
	CONDITION:	Poor		
A ALL	OCCUPANCY:			
	PRIORITY:	B (B)		
MARKE	OWNER TYPE:	Company	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 140
	SITE NAME:	Welsh Presbyterian Church, Princes Road, Liverpool	It is in high tower and s currently no	mist chapel built 1865-7 by W and G Audsley Victorian Gothic style with a very prominent spire. It has sustained fire damage and is t in use. There is a partial felt roof but much
	DESIGNATION:	,	best conditi	he elements.The tower and spire are in the on.
and I He work they want	CONDITION: PRIORITY:	Very bad A (A)		
	OWNER TYPE:	Religious organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 140
	SITE NAME:	Holy Trinity Church, Breck Road, Walton Breck	Holy Trinity Church on Breck Road, Liverpool has roof gutters and downpipes and high level stonework all in poor state of repair. It has received funds for conversic of undercroft for use by social organisations, which will help in keeping the building in continual use.	
	DESIGNATION:	Listed Place of Worship Grade II, CA		
	CONDITION:	Poor		
	PRIORITY:	D (D)		
	OWNER TYPE:	Religious organisation	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 140
	SITE NAME:	Anfield Cemetery, Anfield	A municipal	cemetery designed by Edward Kemp with
	DESIGNATION:	,	Of three or	Lucy & Littler which was laid out 1856-63. iginal chapels only one (listed grade II and
A Panana		also 12 LBs		d) remains and two catacombs (also listed rvive, roofless and in very poor condition.
	CONDITION:	Generally unsatisfactory	grade il) sui	wive, rooness and in very poor condition.
	VULNERABILITY	with major localised problems		
	TREND:	Declining		
		Local authority, single owner	Contact: Pri	ncipal Heritage at Risk Adviser 0161 242 140
	Castle Stro	eet, Liverpool		Poor
DESIGNATION: VULNERABILITY:	Low	ion Area	CONDITION: TREND:	Deteriorating significantly
CONTACT:		bett (LPA) 0151 233 5623	NEW ENTRY?:	No
			INEVV EINTITT.	
SITE NAME:	Derwent	Square, Liverpool		
DESIGNATION:	Conservat	ion Area	CONDITION:	Poor
	Low		TREND:	Deteriorating
/ULNERABILITY:	LOW		1110211021	2 otor lor at 16

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS ATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / LIVERPOOL / SEFTON

SITE NAME:	Duke Street, Liverpool		
			De eu
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Steve Corbett (LPA) 0151 233 5623	NEW ENTRY?:	No
SITE NAME:	Newsham Park, Liverpool		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Steve Corbett (LPA) 0151 233 5623	NEW ENTRY?:	No
SITE NAME:	Ogden Close, Liverpool		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Steve Corbett (LPA) 0151 233 5623	NEW ENTRY?:	No
SITE NAME:	Princes Road, Liverpool		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Steve Corbett (LPA) 0151 233 5623	NEW ENTRY?:	No
SITE NAME:	Stanley Dock, Liverpool		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating significantly
CONTACT:	Steve Corbett (LPA) 0151 233 5623	NEW ENTRY?:	No
SEFTON			
The second	SITE NAME: Ince Blundell Old Hall, Park Wall Road.	House circa south west	a 1590-1620 located approximately 150 metres of the new hall. In the C19 used as a malt

ALL AND	SITE NAME:	Ince Blundell Old Hall, Park Wall Road, Ince Blundell	House circa 1590-1620 located approximately 150 metres south west of the new hall. In the C19 used as a malt house. A restoration scheme had been considered, but no further progress made.
	DESIGNATION:	Listed Building Grade II*, CA, RPG II*	1 0
m mm mm 1	CONDITION:	Poor	
the statistic statistics of the	OCCUPANCY:	Vacant	
	PRIORITY:	C (C)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400

SITE NAME:	Sefton Old Hall moated site and fishponds, S	Sefton	
DESIGNATION:	Scheduled Monument (No.1013629)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
site name:	West Birkdale		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Daniel Byron (LPA) 0151 934 3584	NEW ENTRY?:	No

1

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expedience of the record of th

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / ST HELENS

ST HELENS			
	SITE NAME:	Rainhill Hall Farmhouse, Blundell's Lane, Rainhill	Former hall house dating from C14. Most recently a farmhouse, now derelict. Parts of the upper floor are unsafe and the sandstone roof is putting undue strain on the main beams. A feasibility study has been funded
	DESIGNATION:	Listed Building Grade II*, SM	by the Local Planning Authority and English Heritage;
	CONDITION:	Very bad	urgent works are required.
	OCCUPANCY:	,	
	PRIORITY:	A (A)	
	OWNER TYPE:		Contact: Principal Heritage at Risk Adviser 0161 242 1400
			• • • • • • • • • • • • • • • • • • •
	SITE NAME:	Cannington Shaw Bottle Shop, Site of Sherdley Works, St Helens	Late C19 tank furnace glass shop, with oval 'chimney' and remains of furnace heating system. Derelict since closure of the works in the late 1980s; it is now badly overgrown, with structural deterioration. The owner has drawn up a
	DESIGNATION:	Listed Building Grade II, SM	management plan for consolidation and is discussing
	CONDITION:	Very bad	implementation with the Council and English Heritage.
	OCCUPANCY:	Vacant	
A start and a start and a start a star	PRIORITY:	A (A)	
the second se	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Ruins of Chapel of St Thomas of Canterbury, Windlehurst Roman Catholic Cemetery, St Helens	Ruins of a small chantry chapel founded C15 abolished 1548. Both the chapel and the surrounding graveyard are in ruinous condition. English Heritage and St Helens Borough Council have funded an options appraisal, which
	DESIGNATION:	Listed Building Grade II*, SM	was carried out by Heritage Trust for the North West.
	CONDITION:	Poor	Arising from that work, the Local Authority is seeking
	OCCUPANCY:	N/A	lottery funding.
	PRIORITY:	D (D)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Mary, North Road	This church is a local landmark of cathedral-like proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof
		North Road	proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof
		North Road Listed Place of Worship Grade II	proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled
	DESIGNATION:	North Road Listed Place of Worship Grade II Poor	proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the
	DESIGNATION: CONDITION: PRIORITY:	North Road Listed Place of Worship Grade II Poor C (C)	proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.
	DESIGNATION: CONDITION: PRIORITY:	North Road Listed Place of Worship Grade II Poor	proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the
	DESIGNATION: CONDITION: PRIORITY:	North Road Listed Place of Worship Grade II Poor C (C)	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street,	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design.</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens Listed Place of Worship Grade II	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens Listed Place of Worship Grade II Poor	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: SITE NAME: DESIGNATION: CONDITION: PRIORITY:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens Listed Place of Worship Grade II Poor C (C)	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to this church.</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: PRIORITY: OWNER TYPE:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens Listed Place of Worship Grade II Poor C (C) Religious organisation Church of All Saints, Ellamsbridge Road, Sutton	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to this church.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built by regional architects Austin and Paley in 1891-3 of red sandstone in Gothic Revival style. Cruciform in plan with a five bay nave and two bay chancel. The intended crossing tower was never built. Church houses organ from 1900 and memorial window to local glass producers 'Pilkington'. C20 concrete tile replacement roof has some cracked and displaced tiles. Without intervention it is likely that water will penetrate the building, accelerating deterioration. The building has been a</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: PRIORITY: OWNER TYPE:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens Listed Place of Worship Grade II Poor C (C) Religious organisation Church of All Saints, Ellamsbridge Road,	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to this church.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built by regional architects Austin and Paley in 1891-3 of red sandstone in Gothic Revival style. Cruciform in plan with a five bay nave and two bay chancel. The intended crossing tower was never built. Church houses organ from 1900 and memorial window to local glass producers 'Pilkington'. C20 concrete tile replacement roof has some cracked and displaced tiles. Without intervention it is likely that water will penetrate the building, accelerating deterioration. The building has been a victim of heritage crime. Several windows damaged and some</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWNER TYPE: SITE NAME: CONDITION: PRIORITY: OWNER TYPE:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens Listed Place of Worship Grade II Poor C (C) Religious organisation Church of All Saints, Ellamsbridge Road, Sutton	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to this church.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built by regional architects Austin and Paley in 1891-3 of red sandstone in Gothic Revival style. Cruciform in plan with a five bay nave and two bay chancel. The intended crossing tower was never built. Church houses organ from 1900 and memorial window to local glass producers 'Pilkington'. C20 concrete tile replacement roof has some cracked and displaced tiles. Without intervention it is likely that water will penetrate the building, accelerating deterioration. The building has been a</li> </ul>
	DESIGNATION: CONDITION: PRIORITY: OWINER TYPE: SITE NAME: CONDITION: PRIORITY: OWINER TYPE: SITE NAME: SITE NAME:	North Road Listed Place of Worship Grade II Poor C (C) Religious organisation Church of St Helen, Church Street, St Helens Listed Place of Worship Grade II Poor C (C) Religious organisation Church of All Saints, Ellamsbridge Road, Sutton	<ul> <li>proportions, designed by CB Powell and built between 1924-30 in Byzantine style, surmounted with copper dome on octagonal drum. It has an impressive, gabled west entrance, flying buttresses and complicated roof junctions and detailing. Repair work is needed to the roof and also the gutters and downpipes.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built between 1916-26 of Caroe brick with stone dressing and a slate roof. Experiencing considerable damage due to blocked rainwater outlets and a convoluted design. A nominal redesign of the gutters with an overflow facility should correct the design defects and reduce the risk to this church.</li> <li>Contact: Principal Heritage at Risk Adviser 0161 242 1400</li> <li>Church built by regional architects Austin and Paley in 1891-3 of red sandstone in Gothic Revival style. Cruciform in plan with a five bay nave and two bay chancel. The intended crossing tower was never built. Church houses organ from 1900 and memorial window to local glass producers 'Pilkington'. C20 concrete tile replacement roof has some cracked and displaced tiles. Without intervention it is likely that water will penetrate the building, accelerating deterioration. The building has been a victim of heritage crime. Several windows damaged and some</li> </ul>

PRIORITY (FOR BUILDINGS)

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Expedience of the record of th

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREVIATIONS				
CA	Conservation Area			
LB	Listed Building			
LPA	Local Planning Authority			
NP	National Park			
RPG	Registered Park and Garden			
SM	Scheduled Monument			
UA	Unitary Authority			
WHS	World Heritage Site			

### HERITAGE AT RISK 2012 / NORTH WEST / ST HEI ENS

	SITE NAME: Christ Church, Church Road, Eccleston DESIGNATION: Listed Place of Worship Grade II CONDITION: POOr	Church, I 838, designed in an eclectic Gothic style by the then Lord of the Manor. The three stage tower is surrounded by a needle spire from behind a battlemented tower parapet. This church is suffering from the use of iron in its construction, which has now corroded, damaging the surrounding stonework. Until the final phase of iron cramp removal is completed, the church will remain at risk.		
	PRIORITY: F (F)	C + + D		
	OWNERTYPE: Religious organisation	Contact: Pri	incipal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	Old Moat House Medieval Moat, Bold			
DESIGNATION:	Scheduled Monument (No.1017582)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	St Anne's Well, St Helens			
DESIGNATION:	Scheduled Monument (No.1019449)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0161 242 1400	
SITE NAME:	George Street, St Helens			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	High	TREND:	Deteriorating	
CONTACT:	Emily Hrycan (LPA) 01744 676 185	NEW ENTRY?:	Yes	
SITE NAME:	High Street, St Helens			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	Emily Hrycan (LPA) 01744 676 185	NEW ENTRY?:	Yes	
SITE NAME:	Rainford Conservation Area I			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	High	TREND:	Deteriorating	
CONTACT:	Emily Hrycan (LPA) 01744 676 185	NEW ENTRY?:	Yes	
SITE NAME:	Rainford Conservation Area 2			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	High	TREND:	Deteriorating	
CONTACT:	Emily Hrycan (LPA) 01744 676 185	NEW ENTRY?:	Yes	
SITE NAME:	Rainhill Conservation Area I			
DESIGNATION:	Conservation Area	CONDITION:	Poor	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	Emily Hrycan (LPA) 01744 676 185	NEW ENTRY?:	Yes	
SITE NAME:	Rainhill Conservation Area 2			
DESIGNATION:	Conservation Area	CONDITION:	Fair	
VULNERABILITY:	Medium	TREND:	Deteriorating	
CONTACT:	Emily Hrycan (LPA) 01744 676 185	NEW ENTRY?:	Yes	
RIORITY (FOR BUILDINGS) Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.	D Slow decay; solution agreed but not yet implemented. F Repair scheme in pr and (where applicab end use or user ider	le) 2011	ABBREVIATIONS E: CA Conservation Area priority categories LB Listed Building wen in brackers LPA Local Planning Authority	

A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / ST HELENS / WIRRAL

SITE NAME:	Rainhill Conservation Area 3		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Emily Hrycan (LPA) 01744 676 185	NEW ENTRY?:	Yes
SITE NAME:	Willow Park		
SITE NAME: DESIGNATION:	<b>Willow Park</b> Conservation Area	CONDITION:	Fair
		CONDITION: TREND:	Fair Deteriorating

VALIB B A I

WIRRAL			
	SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Fair Part occupied	C17 house with C14 architectural details (H-plan). North wing and east wall of Great Hall incorporated into farm buildings. North wing is deteriorating. Emergency work and archaeological assessment have been carried out. A proposal for enabling development is in preparation.
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Fort Perch Rock, Marine Promenade, New Brighton, Wallasey	Coastal fort 1826-9 with later additions. Built to defend the approach to Liverpool, now used as a museum and in need of general repair. Brief has been drafted for a Conservation Management Plan and feasibility study for
The second se	DESIGNATION:	Listed Building Grade II*	additional uses. An application for an English Heritage
	CONDITION:	Poor	grant has been encouraged.
	OCCUPANCY:	Part occupied	
	PRIORITY:	C (C)	
	OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St Andrew, Church Lane, Bebington	Grade I listed multi-phase medieval church, stone with slate roofs. Interior with arcades, columns, capitals and roof structure which are all significant. Evidence of recent heritage crime and historic weathering.
	DESIGNATION:	Listed Place of Worship Grade I	
	CONDITION:	Very bad	
	PRIORITY:	C (New entry)	
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Church of St James, Victoria Road, New Brighton	Sir GG Scott 1854 Gothic Revival church, elaborately painted cantered chancel, five bay north and south arcade. Soaring landmark five stage tower. Complicated integration of iron cramps and dowels, heavily corroded
	DESIGNATION:	Listed Place of Worship Grade II	and jacking/fracturing of masonry. Complicated rainwater discharge prone to blockage. Soft external sandstone,
	CONDITION:	Very bad	excessively weathered to point of failure with hard
	PRIORITY:	C (New entry)	cement patches and pointing.
	OWNER TYPE:	Religious organisation	Contact: Principal Heritage at Risk Adviser 0161 242 1400
	SITE NAME:	Christ Church, Church Drive, Port Sunlight Listed Place of Worship Grade II*	Large early C20 sandstone church, built as part of the Port Sunlight model village built under the philanthropy of Lord and Lady Lever. The founders are buried at the church, in a small mausoleum attached to the west end of the church. The cast iron rainwater goods are severely corroded. The west side of the north porch is heavily
I OT CALLER DO	CONDITION:	Poor	saturated. There are detached rainwater goods on the
	PRIORITY:	A (New entry)	east side of the north porch and dislodged downpipes.
	OWNER TYPE:	D II I	Contact: Principal Heritage at Risk Adviser 0161 242 1400

PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

## ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site CA LB LPA NP RPG SM UA WHS

### HERITAGE AT RISK 2012 / NORTH WEST / WIRRAL

SITE NAME:	Birkenhead Priory, Wirral		
DESIGNATION:	Scheduled Monument (No.1019159)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			0161 242 1400
SITE NAME:	Bromborough Court House moated site and	fishponds, Wirr	al
Site name: Designation:	Bromborough Court House moated site and Scheduled Monument (No.1012503)	fishponds, Wirra	al Generally satisfactory
	5	•	
	5	•	Generally satisfactory

Salar In	SITE NAME:	Flaybrick Memorial Gardens	A public cer	metery opened in 1864 and extended in		
AND A REAL PROPERTY	DESIGNATION:	Registered Park and Garden Grade II*,	Edward Ker	9 and early C20.The layout was designed by np and the buildings by Lucy & Littler. Edward		
		also CA, 7 LBs	Kemp is bur	ried within the cemetery. Cemetery Chapels		
monimum ( marting and the	CONDITION:	Generally satisfactory	now roofless and some walls supported by scaffolding. Boundary walls and lodges generally in poor condition.			
		but with significant localised problems	Landscape r	management and maintenance under resourced.		
	VULNERABILITY	r: Medium	I	0		
INTRA STATE	TREND:	Declining				
	OWNER TYPE:	Local authority, single owner	Contact: Principal Heritage at Risk Adviser 0161 242			
	SITE NAME:	Thornton Manor, Bebington	Park and ga	rdens designed by Thomas Hayton Mawson		
WARA	DESIGNATION:	Registered Park and Garden Grade II*,	in collaboration with the industrialist and philanthropis William Hesketh Lever, later first Viscount Leverhulme			
		also I LB		This privately owned property, which is used for exclusive		
and a second second second second	CONDITION:	Generally unsatisfactory	events, inherited a large backlog of conservation and work both in house and grounds. Gardens around t			
		with major localised problems	house well maintained but pergola in advanced state of			
and the second se	VULNERABILITY: High		decay and lake and woodland in poor condition.			
the second second	TREND:	Declining	Contact: Principal Heritage at Risk Adviser 0161 242 1400			
	OWNER TYPE:	Corporate, single owner				
SITE NAME:	Flavbrick (	Cemetery, Bidston, Birkenhead				
SHE NAHE.	,					
DESIGNATION:	Conservat	ion Area	CONDITION:	Very bad		
VULNERABILITY:	Low		TREND:	Deteriorating		
CONTACT:	Matthew (	Crook (LPA) 0151 6062485	NEW ENTRY?:	No		
SITE NAME:	Hamilton	Square, Birkenhead				

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Matthew Crook (LPA) 0151 6062485	NEW ENTRY?:	No

site name:	Rock Park, Rock Ferry, Birkenhead				
designation:	Conservation Area	CONDITION:	Poor		
VULNERABILITY:	Medium	TREND:	Deteriorating		
CONTACT:	Matthew Crook (LPA) 0151 6062485	NEW ENTRY?:	No		

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

CA LB	Conservation Area Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

WARRINGTON (UA)	SITE NAME:	Gatehouse to Bradlegh Old Hall,	Gatebours	circa 1460 Heavily weathered canditana which	
	SITE NAME:	Bradley Lane, Burtonwood	Gatehouse circa 1460. Heavily weathered sandstone, whic is in urgent need of repair. The site has recently changed ownership and the hall (grade II) is being repaired.		
	DESIGNATION:	Listed Building Grade II*			
	CONDITION:	Poor			
	OCCUPANCY:	N/A			
	PRIORITY:	A (A)			
	OWNER TYPE:	Private	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Bewsey Old Hall, Lodge Lane (off), Bewsey, Burtonwood	Hall house. Late C16, C17 and C19 restored in late C20.The hall has changed ownership and the approved enabling scheme is being implemented.The grade II listed		
	DESIGNATION:	Listed Building Grade II*, SM		irmhouse was severely damaged in a fire last summer ut is now being repaired and converted in line with the	
1 1 1	CONDITION:	Fair	approved so		
	OCCUPANCY:	Vacant			
	PRIORITY:	D (D)			
The second second second	OWNER TYPE:	Company	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 140	
	SITE NAME:	Hurst Hall North Barn, Hurst Lane, Glazebury, Culcheth and Glazebury	Part of a late C15 hall but now a barn. Exposed pair of posts with arch braces but mainly clad in thin early red bricks with stone slate roof. The building has missing ridge tiles and guttering. Maintenance has been lacking		
MARK COLOR	DESIGNATION:	0	for many ye		
	CONDITION:	Poor			
	OCCUPANCY:	I. I			
	PRIORITY:	C (C)	<b>C A A D</b>		
	OWNER TYPE:	Private	Contact: Pr	incipal Heritage at Risk Adviser 0161 242 1400	
	SITE NAME:	Bank Quay transporter bridge, Warrington	Transporter bridge circa 1904 with deteriorating ironwork. Not easily accessible. There are problems with funding the necessary maintenance programme. No longer usable, but gondola intact. Discussions are on-going with Warrington Council about joint funding for a management plan and options appraisal.		
KI	DESIGNATION:	Listed Building Grade II*, SM			
A AND A AND A	CONDITION:	Poor			
and the state	OCCUPANCY:		The Council is investigating funding sources.		
	PRIORITY:	C (C)	Contact: Principal Heritage at Risk Adviser 0161 242 1400		
	OWNER TYPE:	Local authority			
SITE NAME:	Bradlegh (	Old Hall moated site and fishpond, Bu	rtonwood		
DESIGNATION:	Scheduled	Monument (No.1011885)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Drainage/c	lewatering	TREND:	Declining	
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser	
				0161 242 1400	
ITE NAME:	Bowl barr	ow west of Highfield Lane, Winwick			
DESIGNATION:		Monument (No.1011124)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:			TREND:		
OWNER TYPE:	Private	Arable ploughing Private		Principal Heritage at Risk Adviser	
			CONTACT:	0161 242 1400	
ITE NAME:	Bewsey St	reet, Bewsey			
DESIGNATION:	Conservat	Conservation Area		Fair	
VULNERABILITY:	High		TREND:	Deteriorating	

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Expedience of the record of th
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented. E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREVIATIONS					
CA	Conservation Area				
LB	Listed Building				
LPA	Local Planning Authority				
NP	National Park				
RPG	Registered Park and Garden				
SM	Scheduled Monument				
UA	Unitary Authority				
WHS	World Heritage Site				
	0				

### HERITAGE AT RISK 2012 / NORTH WEST / WARRINGTON (UA)

SITE NAME:	Bridge Street, Warrington Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Deteriorating significantly
CONTACT:	John Groves (LPA) 01925 442819	NEW ENTRY ?:	No
SITE NAME:	Church Street, Warrington Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	John Groves (LPA) 01925 442819	NEW ENTRY?:	No
SITE NAME:	Town Hall, Warrington Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating significantly
CONTACT:	John Groves (LPA) 01925 442819	NEW ENTRY?:	No

### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
   C Exploremented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority. World Heritage Site CA LB LPA NP RPG SM UA WHS

84



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at **www.english-heritage.org.uk/risk** 

HERITAGE AT RISK

Published September 2012 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST

© Copyright English Heritage 2012