


VORKSHIRE AND THE HUMBER

# Contents

HERITAGE AT RISK	3
Reducing the risks	7
Publications and guidance	10
THE REGISTER	12
Content and assessment criteria	12
Key to the entries	15
Heritage at risk entries by local planning authority	17
Cumbria East Riding of Yorkshire (UA) Kingston upon Hull, City of (UA) North East Lincolnshire (UA) North Lincolnshire (UA) North Yorkshire South Yorkshire West Yorkshire York (UA)	18 18 44 45 46 49 108 121





It is heartening to see that the number of sites on the national Heritage at Risk Register continues to fall, despite the challenges of recession. I,150 assets have been removed for positive reasons since the Register was launched in 2008. The sites that remain at risk tend to be the more intractable ones where solutions are taking longer to implement.

Overall, the number of buildings at risk has fallen, although we are seeing a steady increase in the proportion of buildings on the Register that are capable of beneficial re-use. These have become vacant not because of

any fundamental lack of potential, but as the temporary victims of the current economic climate. The average conservation deficit for buildings has increased as end-values have stagnated or fallen.

We are now into the third year of our thematic approach, which focuses on the most distinctive aspects of Yorkshire's heritage at risk. We have had another strong year, removing 56 sites from the Register and offering £800,000 in grants to 20 others. Very few major repair schemes are coming forward, because financial margins are tight. We will therefore be investing in surveys and viability studies for selected sites, in the hope that this will reduce uncertainty and identify deliverable projects for the future.

The story of the Industrial Remains of the Dales has been enriched this year by the re-commissioning of Linton Falls Hydroelectric Power Station. An options appraisal has been completed for the lead-mining complex at Keld Heads and we are working with the owner to develop a project. Elsewhere, at Grassington Moor work to the flue and chimney is almost complete. Works will soon start at Beever and Cockburn mines with support from Natural England and a management plan for the whole Moor is underway.

We are delighted that the Heritage Lottery Fund has agreed to fund a scheme which should enable the First White Cloth Hall in Leeds to be restored. In Huddersfield a commercial solution has converted the merchants' warehouse at St George's Square to provide student flats. But otherwise there is little development of sites from the **Textile Industry of the West Riding**. We will therefore be working with owners to support urgent repairs wherever we can to reduce the conservation deficit and ensure reuse schemes can progress once the market recovers.

Our Chair, Baroness Andrews, recently visited Joel's Yard in Sheffield to celebrate the completion of repairs and to announce a further grant of £300,000 for the adjacent North Yard. But more needs to be done for the buildings of the **South Yorkshire Metal Trades**. Leah's Yard remains a priority, while the metal-trade conservation area of Kelham Island has been added to the Register.

We continue to support the restoration of one of the finest of **South Yorkshire's Designed Landscapes**, Wentworth Castle. Repair of the pillared barn is complete and we are providing £200,000 towards restoration of the conservatory. It is great to see that work has now begun on this impressive structure, which has been on the Register since 1999 and featured on the Restoration television series.

#### Ancient Landscapes of the Wolds and Moors.

Our productive partnership with the North York Moors National Park continues, with a further 25 scheduled sites removed from the Register. We hope to increase our support to maximise the benefits of this work. Arable cultivation is the greatest source of risk to scheduled monuments and a particular issue on the Wolds. We will be re-doubling our efforts to work with landowners, Natural England and other partners to understand the impact and to secure action. This will become the largest strand of our Heritage at Risk work.

Trevor Mitchell

Trevor Mitchell
Planning and Conservation Director,
Yorkshire and the Humber

#### BIRDSALL ESTATE, MALTON, NORTH YORKSHIRE

The rolling chalklands of the Yorkshire Wolds contain some of England's least appreciated prehistoric, Roman and medieval remains. The greatest risk to these sites comes from arable cultivation cutting into their buried layers and eroding irreplaceable evidence of Yorkshire's past. Sites of this kind were once part of extensive systems stretching for many miles. They can therefore only be properly understood and protected at a landscape scale, which is why English Heritage is helping the Birdsall Estate to develop a Conservation Management Plan for the 65 scheduled monuments in its stewardship, I 6 of which are at risk. Peter Horne © English Heritage

#### **BUILDINGS AT RISK**

- Nationally, 3.0% of grade I and II\* listed buildings are at risk. In Yorkshire and the Humber this rises to 4.1% (91 buildings).
- 8 buildings at risk were removed from the 2011 Yorkshire and the Humber Register, and 4 have been added.

#### PLACES OF WORSHIP AT RISK

 Of the 339 listed places of worship surveyed in Yorkshire and the Humber, 63 are at risk.
 22 have been added this year.

#### SCHEDULED MONUMENTS

- 3,286 (16.6%) of England's 19,759 scheduled monuments are at risk, of which 676 are in Yorkshire and the Humber.
- In Yorkshire and the Humber, 33 scheduled monuments have been removed from the 2011 Register for positive reasons, and 12 have been added.
- 12.8% of scheduled monuments (93) on Yorkshire and the Humber's baseline 2009 Register have been removed for positive reasons, compared to the national figure of 15.8%.
- Nationally, damage from arable cultivation is the greatest risk factor for scheduled monuments, accounting for 44% of those at risk. In Yorkshire and the Humber the proportion is 57%.

#### REGISTERED PARKS AND GARDENS

- 99 (6.1%) of England's 1,617 registered parks and gardens are at risk, a decrease from 103 (6.4%) in 2011. In Yorkshire and the Humber, 13 (11%) of our 118 sites are at risk.
- Nationally, 5 registered parks and gardens were removed from the 2011 Register and I, in Yorkshire and the Humber, has been added.

#### **REGISTERED BATTLEFIELDS**

• Of the 43 registered battlefields in England, 6 are at risk, 2 fewer than the 2008 baseline. Of the 7 registered battlefields in Yorkshire and the Humber, 4 are at risk.

#### PROTECTED WRECK SITES

 Of the 46 protected wreck sites off England's coast, 4 are at risk. Of the 10 sites on the 2008 baseline, 9 have been removed. Yorkshire and the Humber's single protected wreck site is not at risk.

#### **CONSERVATION AREAS**

- We now have information on the condition of 7,976 of England's 9,770 conservation areas; 524 (6.6%) are at risk. Of the 848 conservation areas surveyed in Yorkshire and the Humber, 53 (6.3%) are at risk.
- 2 conservation areas were removed from the 2011 Yorkshire and the Humber Register for positive reasons, but 3 have been added.



#### **HAWORTH**

Poor maintenance and cumulative changes are threatening Haworth's reputation as a high-quality tourist destination. In partnership with Bradford Council, local groups and business owners, English Heritage is working to restore the character of the village and create a more authentic atmosphere for visitors.

© Trevor Mitchell, English Heritage





25.0% SCHEDULED MONUMENTS ARE AT RISK



#### PRIORITY HAR SITES

- Barden Church, Barden, Yorkshire Dales National Park
- Battle of Towton, Lead / Saxton with Scarthingwell / Towton, Selby, North Yorkshire
- Birdsall Estate (incl.16 scheduled monuments at risk), Birdsall Wold, Ryedale, North Yorkshire
- First Leeds White Cloth Hall,
   98-101 (consec.) Kirkgate, Leeds,
   West Yorkshire
- Haworth Conservation Area, Bradford West Yorkshire
- Keld Heads lead smeltmill and mine complex, Wensley, Richmondshire, North Yorkshire

- Kirklees Park Farm buildings (incl. Double aisled barn to north west of Kirklees Priory Gatehouse, Home Farm (Building No. 6), Kirklees Priory Gatehouse, L-shaped Aisled Barn, and the Malthouse) Brighouse, Calderdale, West Yorkshire
- Leah's Yard, 20-22 Cambridge Street, Sheffield, South Yorkshire
- Grassington Moor (multi-period lead mines and processing works and 20th century barytes mill), Grassington, Yorkshire Dales National Park
- Whortlon Castle (gatehouse and ruins of undercroft), Castle Bank, Whorlton, North York Moors National Park

#### **GRADE II PILOT PROJECTS**

English Heritage is looking for people to take part in pilot projects that will explore options for expanding the Heritage at Risk programme to include all grade II listed buildings.


A maximum of I5 pilot projects are required to explore, cost and test various options for undertaking surveys of grade II listed buildings.

For more information and details on how to apply visit:

www.english-heritage. org.uk/risk

#### FOR MORE INFORMATION CONTACT:

Principal Heritage at Risk Adviser, English Heritage Yorkshire and the Humber, 37 Tanner Row, York, YO I 6WP. Telephone: 01904 601 901 Email: yorkshire@english-heritage.org.uk



Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

# Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. This will be challenging given the number of assets on the Register and the different kinds of risk they face.

To help address this challenge we have published our National Heritage at Risk Strategy which will be supported by nine local strategies. Key objectives of the strategy are to understand why assets are at risk and what most influences their removal from the Register and to find solutions for heritage at risk through partnership, stimulating economic regeneration and growth and maximising the benefit of our expertise and resources.

Whilst each asset type and individual site will require its own approach and solution, there are some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential to prevent them becoming at risk, and those that are already at risk from decaying further and the cost of their repair and consolidation from escalating. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website, www.helm.org.uk

## LISTED BUILDINGS Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (Stopping the Rot) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society, The Twentieth Century Society, the Council for British Archaeology and the Ancient Monuments Society. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk officers to help not-for-profit organisations take building at risk projects forward.

### Places of worship at risk

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. It also means volunteers do not take unnecessary risks balancing on ladders.

The Repair Grants for Places of Worship scheme helped under-resourced congregations do urgent works to make buildings wind and watertight. From 2013 the Heritage Lottery Fund will fund a new scheme for places of worship. The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports the congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. New Work in Historic Places of Worship (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

#### SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Continuing partnership with Defra and Natural England over the last year has seen the introduction of much more effective information sharing so that resources whether Environmental Stewardship or English Heritage - can be more closely targeted where they will have the greatest impact. Over the next year we will also work more closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Continued progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage for the period 2011 to 2015 – the Conservation of Scheduled Monuments in Cultivation project has begun across England. The project, which started with a questionnaire to all farmers and landowners with a scheduled monument that is being cultivated, will look at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk still shows that unmanaged tree, scrub and bracken growth is one of the most widespread causes of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

In all cases, however — whether for rural or urban monuments — close co-operation with owners and land managers will remain the key to making further progress in ever more challenging circumstances.

#### REGISTERED PARKS AND GARDENS

Inclusion on the Register of Historic Parks and Gardens of Special Historic Interest confers no additional statutory controls but the Government's new National Planning Policy Framework stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. Registered parks and gardens carry the same weight as listed buildings in the National Planning Policy Framework and substantial harm or loss can only be justified in exceptional cases.

English Heritage's landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We encourage the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens

#### REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in the *National Planning Policy Framework*.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

### PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory

power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

#### **CONSERVATION AREAS**

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after them is a responsibility shared by those of us who own homes and businesses in them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. However, this is extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/get-involved/improving-your-neighbourhood

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) — a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010 - report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2012 – national report and summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

Heritage at Risk Register 2012 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

#### HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk

# CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) — a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance on the Management of Conservation Areas (2006)

Guidance on Conservation Area Appraisals (2006)

Guidance Notes and Application Forms for Grants to Local Authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage at Risk: Conservation Areas (2009) — guidance for local authorities on conservation area management

Heritage Works: the use of Historic Buildings in Regeneration (2006)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the Transfer of Local Heritage Assets (2011)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 | 181

Fax: 01793 414926

Email: customers@english-heritage.org.uk

# THE REGISTER Content and criteria

**DESIGNATION** 

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since I 882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz I 940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some I,617 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations — but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

### LISTED BUILDINGS Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I and II\* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential

terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

### Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

### Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international, importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed a proportion of the I4,500 listed places of worship. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence which will help us build upon our understanding of the challenges.

### Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

### Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

# SCHEDULED MONUMENTS Definition

Scheduled monuments include archaeological sites and landscapes, and 19,759 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and — often most seriously of all — wholly natural processes such as scrub growth, animal burrowing and erosion.

### Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

# REGISTERED PARKS AND GARDENS Definition

There are 1,617 designed landscapes on the current English Heritage Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage Register of Historic Parks and Gardens brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades.

### Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

# REGISTERED BATTLEFIELDS Definition

English Heritage's Register of Historic Battlefields has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

### Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

# PROTECTED WRECK SITES Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

### Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

# CONSERVATION AREAS Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,700 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

## Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Key to the entries

# This Register includes the following heritage assets at risk:

- grade I and II\* listed buildings and structural scheduled monuments
- grade I, II\* and II listed places of worship
- scheduled monuments
- · registered parks and gardens
- registered battlefields
- protected wreck sites (if applicable)
- · conservation areas

#### **ORDER**

Entries are grouped and ordered alphabetically first by County\* or Unitary Authority, and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

Sites that straddle more than one local planning authority are included under the lead authority.

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- · registered parks and gardens
- registered battlefields
- conservation areas

Within each asset type, sites are ordered alphabetically by district for sites in National Parks, otherwise by parish and street/site name. Conservation areas are ordered by site name only.

\*The metropolitan counties of South Yorkshire and West Yorkshire are used to group the data. North Yorkshire is the only two tier planning authority in the region.

#### **DESIGNATION**

The principal designation is noted for each entry and includes:

- Listed Building (LB) Grade I, II\* or II
- Listed Place of Worship Grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) Grade I, II\* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

#### CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

#### OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

#### **VULNERABILITY**

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- · animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- · visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

#### **PRIORITY**

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- **B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- **D** Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

#### **TREND**

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- · improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- · deteriorating significantly
- · no significant change
- improving
- · improving significantly
- unknown

#### **OWNERSHIP**

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

#### **CONTACT**

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

#### **ABBREVIATIONS**

NP

CA	Conservation Area
EH	English Heritage
HLF	Heritage Lottery Fund
LPA	Local Planning Authority
LB	Listed Building

National Park

RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

# Heritage at risk entries by local planning authority

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
CUMBRIA							
Yorkshire Dales (NP)	I	0	0	0	0	0	0
EAST RIDING OF YORK	SHIRE (UA)						
East Riding of	10	4	LOF	2	1		2
Yorkshire (UA)	10	4	185	2		0	2
KINGSTON UPON HUL Kingston upon Hull,	L, CITT OF (C	JA)					
City of (UA)	0	2	0	0	0	0	2
NORTH EAST LINCOLN	ISHIRE (UA)						
North East	( )						
Lincolnshire (UA)	2	0	2	0	0	0	6
NORTH LINCOLNSHIRE	,						
North Lincolnshire (UA)	2	3	14	0	0	0	2
NORTH YORKSHIRE				0			
Craven	-	0	1	0	0	0	0
Hambleton	5	I	28	0	0	0	0
Harrogate	9	0	15	3	I	0	0
North York Moors (NP)	5	0	120	0	0	0	0
Richmondshire	6	0	15	0	0	0	0
Ryedale	11	I	133	2	0	0	0
Scarborough	1	2	24	0	0	0	I
Selby	4	I	22	0	I	0	0
Yorkshire Dales (NP)	4	2	П	0	0	0	2
SOUTH YORKSHIRE	Г.	2	0	0	0	0	1
Barnsley	5	3	9	0	0	0	
Doncaster Doncaster	2	5	16	0	0	0	7
Peak District (NP)	0	0	3	0	0	0	0
Rotherham Sheffield	4	3	13	0	0	0	4
	5	2	8	2	0	0	3
WEST YORKSHIRE Bradford	4	7	17		0	0	10
Bradford / Kirklees /	4	/	17	I	U	U	10
Leeds*	0	0	0	0	1	0	0
Calderdale	10	3	5	0	0	0	3
Kirklees	3	14	5	0	0	0	4
Leeds	Ш	4	9	2	0	0	4
Peak District (NP)	0	0	0	0	0	0	0
Wakefield	3	6	6	0	0	0	0
Wakefield / Barnsley /							
Kirklees*	0	0	0	1	0	0	0
YORK (UA)							
York (UA)	0	0	0	0	0	0	2
TOTAL	108	63	661	13	4	0	53

#### **CUMBRIA**

#### YORKSHIRE DALES (NP)



High Hall Farmhouse including cartshed, Dent, South Lakeland

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: Part occupied OCCUPANCY: A (New entry) PRIORITY:

C17 farmhouse once owned by Richard Trotter who led the Dent "statesmen" to purchase the manor of Dent from the crown in 1670. Partially derelict and collapsing.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### EAST RIDING OF YORKSHIRE (UA)



Easington Tithe Barn, SITE NAME: High Street, Easington

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION: OCCUPANCY: Vacant C (C) PRIORITY Private OWNER TYPE:

OWNER TYPE:

Medieval and post medieval thatched timber-framed aisled barn associated with historic rectory farm. A unique survival for this part of the region. Fallen into disuse and disrepair.

Contact: Principal Heritage at Risk Adviser 01904 601901



Flamborough Castle, SITE NAME: Tower Street, Flamborough

DESIGNATION: Listed Building Grade II, SM, CA

Poor CONDITION: N/A OCCUPANCY: C(C)OWNERTYPE: Private Mid C14 castle comprised of earthworks and upstanding remains within a pasture field in the centre of the village. The upstanding elements consist of an unconsolidated former undercroft which is made of decaying chalk blocks.

Contact: Principal Heritage at Risk Adviser 01904 601901



Elmswell Old Hall, SITE NAME: Elmswell Lane,

Garton

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: OCCUPANCY: Vacant A (A) PRIORITY: Private OWNER TYPE:

House, 1634 with later alterations. Once the home of Henry Best, important C17 agricultural diarist. Isolated and abandoned. Urgent works have been carried out but these have not arrested decay. The whole building is roofless. An application to restore the house to a dwelling has been made by the Spitalfield Trust.

Contact: Principal Heritage at Risk Adviser 01904 601901



Gates, gate piers, SITE NAME

flanking walls and abutments, Londesborough

DESIGNATION: Listed Building Grade I, CA, RPG II\*

Poor CONDITION: N/A OCCUPANCY: C (C) PRIORITY: OWNERTYPE: Private Gateway, I 660-70, probably by Robert Hooke, forming the principal entrance to Londesborough Park. The caps of the gate piers are deteriorating and trees are growing from the joints. The ball finials have fallen.

Contact: Principal Heritage at Risk Adviser 01904 601901



Paull Holme Tower, SITE NAME:

Thorngumbald Road,

DESIGNATION: Listed Building Grade I, SM, CA

Very bad Vacant OCCUPANCY: A(A)PRIORITY: OWNERTYPE: Private

Mid C15 three storey brick tower house in a scheduled moated site, originally part of a larger manorial complex. A unique survival for this region. Restored and re-roofed in 1871; roofless since the early C20 and suffering from long-term neglect.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

# **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site



The Old Farmhouse, SITE NAME: Glebe Farm, Thwing

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY:

A (New entry)

Private OWNER TYPE:

C17 former farmhouse with timber framing encased in chalk and brick walling. Retains timber frame with cruck trusses and rare original internal features such as a box-bed and staircase. A unique survival on the Yorkshire Wolds of a once common type of building.

Contact: Principal Heritage at Risk Adviser 01904 601901



Adlingfleet Medieval Rectory, SITE NAME: Church Lane, Adlingfleet, Twin Rivers

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant OCCUPANCY: A(A)PRIORITY: Private OWNER TYPE:

Part of a C13 dwelling of the wealthy rector and King's councillor, John le Franceys. Re-used as farm buildings in the C18. A unique survival of a stone-built medieval dwelling in this area.

Contact: Principal Heritage at Risk Adviser 01904 601901



Outbuildings to Watton Abbey, SITE NAME: Church Lane.

Watton DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant OCCUPANCY: C(C)PRIORITY: Private

OWNER TYPE:

Gilbertine priory buildings, now outbuildings. C16 with later additions and alterations. The structure is derelict and mainly ruinous. Urgent repairs have been undertaken with the help of an English Heritage grant to stabilise the leaning gable.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Haltemprice Priory Farmhouse, Abbey Lane,

Willerby

DESIGNATION: Listed Building Grade II\*, SM

Very bad CONDITION: Vacant A(A)PRIORITY Private OWNER TYPE:

Fragmentary remains of a farmhouse dating largely from the C17-C19, incorporating sections of re-used medieval and CI6 fabric. In a very advanced state of decay. Proposals for repair and residential re-use are in preparation.

Contact: Principal Heritage at Risk Adviser 01904 601901



Wressle Castle, SITE NAME: Breighton Road, Wressle

DESIGNATION: Listed Building Grade I, SM

CONDITION: Vacant OCCUPANCY: A (A) PRIORITY-OWNERTYPE: Private Very impressive and important surviving range of a major late C14 castle built for the Percy family and occupied by them during the period when they were at the height of their power as the leading family in northern England. Repaired and consolidated as a roofless ruin in the C19; some repairs in 1970-80s.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Andrew, Main Street, Bainton

DESIGNATION: Listed Place of Worship Grade I

CONDITION:

D (New entry) PRIORITY:

OWNERTYPE: Religious organisation

Fine medieval church, C12-C14, restored by Fowler of Louth. Roof and stonework in poor repair, structural movement in east wall. Grant offered.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

**ABBREVIATIONS** CA LB LPA NP RPG SM

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Church of All Saints, SITE NAME: Low Catton, Catton

Medieval church with prominent Victorian chancel set back from the road in the small village of Low Catton. The chancel roof is tiled and there were a large number of slipped tiles particularly to the north.

DESIGNATION: Listed Place of Worship Grade I

Poor CONDITION: PRIORITY: C(C)

SITE NAME:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Mary, Church Lane. Watton

C16 church, largely brick. The roofs have recently been recovered and the parapets repaired. Extensive repair is needed to the windows and brickwork.

DESIGNATION: Listed Place of Worship Grade I

Poor F(D) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Mary Magdalene, SITE NAME: Whitgift

Medieval village church. Body of church recently under-pinned, but extensive repairs are needed to tower stonework. Grant offered for tower and roof work.

DESIGNATION: Listed Place of Worship Grade I

Poor CONDITION:

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Bewick Hall moated site, Aldbrough		
DESIGNATION:	Scheduled Monument (No.1007848)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Rectilinear enclosures, Barmby Moor		
DESIGNATION:	Scheduled Monument (No.1005209)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Barf Hill moated site, Beswick		
DESIGNATION:	Scheduled Monument (No.1007717)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Beverley sanctuary limit stone, Bishop Burton cross, Bishop Burton		
DESIGNATION:	Scheduled Monument (No.1012589)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTF: 2011 priority categories are given in brackets. **ABBREVIATIONS** 

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument CA LB LPA NP RPG SM UA WHS Unitary Authority World Heritage Site

ITE NAME:	Five round barrows 700m north east of Lit	ttlewood Lodge, Bi	ishop Burton
DESIGNATION:	Scheduled Monument (No.1007401)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Four round barrows 780m north east of Li	ittlewood Lodge, B	Bishop Burton
DESIGNATION:	Scheduled Monument (No.1007563)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Round barrow 1000m north east of Littlew	vood Lodge, Bishop	p Burton
DESIGNATION:	Scheduled Monument (No.1007572)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Round barrow 900m north east of Littlewo	ood Lodge, Bishop	Burton
DESIGNATION:	Scheduled Monument (No.1007440)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	CONTACT:	Principal Heritage at Risk Adviser
OWNER TYPE:	TTVate	0011111011	1 0
OWNER TYPE:	Tivace	66.1	01904 601901
DWNER TYPE: IITE NAME:	Three round barrows 800m north east of		01904 601901
ITE NAME:			01904 601901
	Three round barrows 800m north east of	Littlewood Lodge,	01904 601901 Bishop Burton
ITE NAME: DESIGNATION:	Three round barrows 800m north east of Scheduled Monument (No.1007573)	Littlewood Lodge,	Bishop Burton  Extensive significant problems Declining
ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing	Littlewood Lodge,  CONDITION:  TREND:  CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
ITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private	Littlewood Lodge,  CONDITION:  TREND:  CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
ITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B	Littlewood Lodge,  CONDITION:  TREND:  CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton
DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B	Littlewood Lodge,  CONDITION:  TREND:  CONTACT:  Sishop Wilton Wold  CONDITION:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining
DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing	Littlewood Lodge,  CONDITION:  TREND:  CONTACT:  Sishop Wilton Wold  CONDITION:  TREND:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining
DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing	Littlewood Lodge,  CONDITION: TREND: CONTACT:  Sishop Wilton Wold  CONDITION: TREND: CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing Private	Littlewood Lodge,  CONDITION: TREND: CONTACT:  Sishop Wilton Wold  CONDITION: TREND: CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  DESIGNATION:  DEVINCIPAL VULNERABILITY:  DEVINER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing Private  Round barrow 250m south of Callis Wold	Littlewood Lodge,  CONDITION: TREND: CONTACT:  Sishop Wilton Wold  CONDITION: TREND: CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing Private  Round barrow 250m south of Callis Wold Scheduled Monument (No.1008366)	Littlewood Lodge,  CONDITION: TREND: CONTACT:  Sishop Wilton Wold  CONDITION: TREND: CONTACT:  Farm, Bishop Wilton  CONDITION:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  on Extensive significant problems Declining
DESIGNATION:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing Private  Round barrow 250m south of Callis Wold Scheduled Monument (No.1008366) Arable ploughing	Littlewood Lodge,  CONDITION: TREND: CONTACT:  ishop Wilton Wold  CONDITION: TREND: CONTACT:  Farm, Bishop Wilton  CONDITION: TREND: TREND:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  on Extensive significant problems Declining
DESIGNATION:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing Private  Round barrow 250m south of Callis Wold Scheduled Monument (No.1008366) Arable ploughing	Littlewood Lodge,  CONDITION: TREND: CONTACT:  Sishop Wilton Wold  CONDITION: TREND: CONTACT:  Farm, Bishop Wilto  CONDITION: TREND: CONDITION: TREND: CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing Private  Round barrow 250m south of Callis Wold Scheduled Monument (No.1008366) Arable ploughing Private	Littlewood Lodge,  CONDITION: TREND: CONTACT:  Sishop Wilton Wold  CONDITION: TREND: CONTACT:  Farm, Bishop Wilto  CONDITION: TREND: CONDITION: TREND: CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Three round barrows 800m north east of Instrument (No.1007573)  Arable ploughing Private  Round barrow 250m east of Wold Farm, Bound barrow 250m east of Wold Farm, Bound barrow 250m east of Wold Farm, Bound barrow 250m south of Callis Wold Scheduled Monument (No.1008366)  Arable ploughing Private  Round barrow 300m south west of Callis Wold Scheduled Monument (No.1008366)  Arable ploughing Private	Littlewood Lodge,  CONDITION: TREND: CONTACT:  Sishop Wilton Wold  CONDITION: TREND: CONTACT:  Farm, Bishop Wilton TREND: CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Wilton
DESIGNATION:	Three round barrows 800m north east of Scheduled Monument (No.1007573) Arable ploughing Private  Round barrow 250m east of Wold Farm, B Scheduled Monument (No.1008320) Arable ploughing Private  Round barrow 250m south of Callis Wold Scheduled Monument (No.1008366) Arable ploughing Private  Round barrow 300m south west of Callis V Scheduled Monument (No.1008368)	Littlewood Lodge,  CONDITION: TREND: CONTACT:  ishop Wilton Wold  CONDITION: TREND: CONTACT:  Farm, Bishop Wilton TREND: CONDITION: TREND: CONTACT:	Bishop Burton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  d, Bishop Wilton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Wilton Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

Rescuence Authorized Private Control Principal Heritage at Risk Adviser 01904 601901  Scheduled Monument (No.1008314) control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Extensive significant problems Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Extensive significant problems Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Extensive significant problems Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Extensive significant problems Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Extensive significant problems Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Extensive significant problems Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk Adviser 01904 601901  Arable ploughing make Control Principal Heritage at Risk	SITE NAME:	Round barrow 300m south west of Cot No	ab Farm, Bishop W	/ilton
Round barrow 350m west of Cot Nab Farm, Bishop Wilton  Scheduled Monument (No.1008314)  Brindball Hentage at Risk Adviser 01904 601901  Brindball Hentage at Risk Adviser 0190	DESIGNATION:	Scheduled Monument (No.1008319)	CONDITION:	Extensive significant problems
STEINAME  Round barrow 350m west of Cot Nab Farm, Bishop Wilton  PROCREMENTATION  ROUND BARROWS	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
Round barrow 350m west of Cot Nab Farm, Bishop Wilton  Scheduled Monument (No. 1008314) consument  Arable ploughing TRAND  Declining  Private CONSUMENTY:  Round barrow 400m north east of Wold Farm, Bishop Wilton Wold, Bishop Wilton  Scheduled Monument (No. 1008344) consument  Arable ploughing TRAND  Scheduled Monument (No. 1008344) consument  Arable ploughing TRAND  Declining  Private CONSUMENTY:  Private CONSUMENTY:  Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton  Scheduled Monument (No. 1008345) consument  Fatersive significant problems  Declining  Private CONSUMENTY:  Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton  Scheduled Monument (No. 1008345) consument  Fatersive significant problems  Declining  Private CONSUMENTY:  Private CONSUMENTY:  Round barrow south east of Cot Nab Farm, Bishop Wilton  Scheduled Monument (No. 1009386) consument  Extensive significant problems  Declining  Private CONSUMENTY:  Round barrow south east of Cot Nab Farm, Bishop Wilton  Scheduled Monument (No. 1009386) consument  Extensive significant problems  Declining  Private CONSUMENTY:  Private CONSUMENTY:  Round Barrow south east of Cot Nab Farm, Bishop Wilton  Scheduled Monument (No. 1009386) consument  Extensive significant problems  Declining  Declining  Declining  Private CONSUMENTY:  Private CONSUMENTY:  Private CONSUMENTY:  Ste of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  Drainage/dewatering INEND  Declining  TRAND  CONSUMENTY:  Private CONSUMENTY:  Declining  Declining  Declining  Finance  Declining  Decli	OWNER TYPE:	Private	CONTACT:	
Scheduled Monument (No.1008314) condition. Extensive significant problems provided Monument (No.1008314) condition. Extensive significant problems private Private Control Principal Heritage at Risk Adviser 01904 601901  Round barrow 400m north east of Wold Farm, Bishop Wilton Wold, Bishop Wilton Scheduled Monument (No.1008344) condition. Extensive significant problems Private Control Principal Heritage at Risk Adviser 01904 601901  Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton Private Control Principal Heritage at Risk Adviser 01904 601901  Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton Private Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton Private Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow south east of Cot Nab Farm, Bishop Wilton Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow south east of Cot Nab Farm, Bishop Wilton Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow south east of Cot Nab Farm, Bishop Wilton Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow south east of Cot Nab Farm, Bishop Wilton Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow south east of Cot Nab Farm, Bishop Wilton Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow Scheduled Monument (No.1009383) Control Generally satisfactory but with significant localised problems of the Private Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow Scheduled Monument (No.1009383) Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow Scheduled Monument (No.1005207) Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow Scheduled Monument (No.1005207) Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow Scheduled Monument (No.1005207) Control Principal Heritage at Risk Adviser 01904 601901  Round Barrow Scheduled Monument (No.1005207				01904 601901
Arable ploughing Treads Declining Private Convents Principal Heritage at Risk Adviser 01904 601901  Round barrow 400m north east of Wold Farm, Bishop Wilton Wold, Bishop Wilton Scheduled Monument (No.1008344) convents Scheduled Monument (No.1008344) convents Private Convents Private Pr	SITE NAME:	Round barrow 350m west of Cot Nab Fari	m, Bishop Wilton	
CONTROL Private Private Private Round barrow 400m north east of Wold Farm, Bishop Wilton Wold, Bishop Wilton DESONATION Scheduled Monument (No.1008344) CONDITION PRIVATE Private CONTROL CONTROL Private CONTROL CONTROL Private CONTROL Priv	DESIGNATION:	Scheduled Monument (No.1008314)	CONDITION:	Extensive significant problems
Round barrow 400m north east of Wold Farm, Bishop Wilton Wold, Bishop Wilton  Scheduled Monument (No.1008344)  CONDITION  Arable ploughing  Private  Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton  Scheduled Monument (No.1008345)  CONDITION  Scheduled Monument (No.1008345)  CONDITION  Scheduled Monument (No.1008345)  CONDITION  Scheduled Monument (No.1008345)  CONTRICE  Private  CONTRICE  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  CONTRICE  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  CONTRICE  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  CONTRICE  CONTRICE  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  CONTRICE  CONTRICE  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  CONTRICE  CONTRICE  Private  Private  CONTRICE  Private  CONTRICE  Private  Private  CONTRICE  Private  Private  Private  CONTRICE  Private  Private  Private  CONTRICE  Private  Private  Private  Private  CONTRICE  Private	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
ESCHAMION: Scheduled Monument (No.1008344) COMBINION: Extensive significant problems provided with provided ploughing TREND: Declining Principal Heritage at Risk Adviser 01904 601901  STEINAME: Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton	OWNER TYPE:	Private	CONTACT:	, ,
PRESIDENTALIZATION PRIVATE  Private  Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton  Scheduled Monument (No.1008345)  Scheduled Monument (No.1009386)  Site of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  Scheduled Monument (No.1009383)  Scheduled M	SITE NAME:	Round barrow 400m north east of Wold F	arm, Bishop Wilto	n Wold, Bishop Wilton
PRINCIPLY AUTORITION.  Arable ploughing Private Privat	DESIGNATION:	Scheduled Monument (No.1008344)	CONDITION:	Extensive significant problems
Round barrow 850m north of Wold Farm, Bishop Wilton Wold, Bishop Wilton  Designation  Scheduled Monument (No.1008345)  CONDITION  Arable ploughing  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  Designation  Scheduled Monument (No.1009386)  Scheduled Monument (No.1009386)  Scheduled Monument (No.1009386)  Designation  Scheduled Monument (No.1009386)  Designation  Scheduled Monument (No.1009386)  Designation  Scheduled Monument (No.1009386)  Scheduled Monument (No.1009387)  Scheduled Monument (No.1009388)	PRINCIPAL VULNERABILITY:		TREND:	Declining
Scheduled Monument (No.1008345)  Scheduled Monument (No.1008345)  Arable ploughing  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  DESIGNATION  Scheduled Monument (No.1009386)  Scheduled Monument (No.1009386)  Scheduled Monument (No.1009386)  Scheduled Monument (No.1009386)  Strename  Private  Site of Arable ploughing  Strename  Scheduled Monument (No.1009386)  Strename  Strename  Scheduled Monument (No.1009386)  Strename  Strename  Scheduled Monument (No.1009383)  Strename  Scheduled Monument (No.1009383)  Strename  Scheduled Monument (No.1009383)  Strename  Scheduled Monument (No.1009383)  Scheduled	OWNER TYPE:	Private	CONTACT:	, ,
Arable ploughing  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  Designation  Scheduled Monument (No.1009386)  Strename  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  Designation  Scheduled Monument (No.1009386)  Strename  Private  Private  Private  Declining  Contract  Principal Heritage at Risk Adviser 01904 601901  Strename  Strename  Ste of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  Designation  Scheduled Monument (No.1009383)  Condition  Generally satisfactory but with significant localised problems  Private  Drainage/dewatering  TREND: Declining  CONTRACT  Principal Heritage at Risk Adviser 01904 601901  Strename  Strename  Strename  Scheduled Monument (No.1005207)  Condition  Extensive significant problems  Designation  Scheduled Monument (No.1005207)  Condition  Extensive significant problems  Private  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  Strename  Remon-British villa at Cockle Pits, near Brantingham  Designation  Scheduled Monument (No.1014736)  Condition  Extensive significant problems  Principal Heritage at Risk Adviser 01904 601901  Strename  Remon-British villa at Cockle Pits, near Brantingham  Designation  Scheduled Monument (No.1014736)  Condition  Extensive significant problems  Principal Heritage at Risk Adviser 01904 601901	SITE NAME:	Round barrow 850m north of Wold Farm,	Bishop Wilton Wo	old, Bishop Wilton
Arable ploughing  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  Designation  Scheduled Monument (No.1009386)  Strename  Private  Round barrow south east of Cot Nab Farm, Bishop Wilton  Designation  Scheduled Monument (No.1009386)  Strename  Private  Private  Private  Declining  Contract  Principal Heritage at Risk Adviser 01904 601901  Strename  Strename  Ste of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  Designation  Scheduled Monument (No.1009383)  Condition  Generally satisfactory but with significant localised problems  Private  Drainage/dewatering  TREND: Declining  CONTRACT  Principal Heritage at Risk Adviser 01904 601901  Strename  Strename  Strename  Scheduled Monument (No.1005207)  Condition  Extensive significant problems  Designation  Scheduled Monument (No.1005207)  Condition  Extensive significant problems  Private  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  Strename  Remon-British villa at Cockle Pits, near Brantingham  Designation  Scheduled Monument (No.1014736)  Condition  Extensive significant problems  Principal Heritage at Risk Adviser 01904 601901  Strename  Remon-British villa at Cockle Pits, near Brantingham  Designation  Scheduled Monument (No.1014736)  Condition  Extensive significant problems  Principal Heritage at Risk Adviser 01904 601901	DESIGNATION:	Scheduled Monument (No.1008345)	CONDITION:	Extensive significant problems
Round barrow south east of Cot Nab Farm, Bishop Wilton  DESIGNATION: Scheduled Monument (No.1009386) CONDITION: Extensive significant problems  Declining OWNERTYPE Private  Site of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  DESIGNATION: Scheduled Monument (No.1009383) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VALNERABILITY: Drainage/dewatering TERND: Declining OWNERTYPE Private  CONTACT: Principal Heritage at Risk Adviser  19904 601901  STIE NAME: Settlement site at Boynton Hall, Boynton  DESIGNATION: Scheduled Monument (No.1005207) CONDITION: Extensive significant problems  PRINCIPAL VALNERABILITY: DESIGNATION: Scheduled Monument (No.1005207) CONDITION: Extensive significant problems  PRINCIPAL VALNERABILITY: OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems  PRINCIPAL VALNERABILITY: O1904 601901  STIE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems  PRINCIPAL VALNERABILITY: O1904 601901  STIE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems  PRINCIPAL VALNERABILITY: O1904 601901  TREND: DESIGNATION: PRINCIPAL VALNERABILITY: O1904 601901  PRINCIPAL VALNERABILITY: O1904 6019	PRINCIPAL VULNERABILITY:		TREND:	
DESIGNATION: Scheduled Monument (No.1009386) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TERND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Site of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  SITE NAME: Scheduled Monument (No.1009383) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Settlement site at Boynton Hall, Boynton  Scheduled Monument (No.1005207) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  Designation: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Dumping TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901	OWNER TYPE:	Private	CONTACT:	, ,
PRINCIPAL VULNERABILITY: Arable ploughing Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Site of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  DESIGNATION: Scheduled Monument (No.1009383) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Settlement site at Boynton Hall, Boynton  DESIGNATION: Scheduled Monument (No.1005207) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow south east of Cot Nab Farn	n, Bishop Wilton	
OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Site of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  DESIGNATION: Scheduled Monument (No.1009383) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Settlement site at Boynton Hall, Boynton  DESIGNATION: Scheduled Monument (No.1005207) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems PINCIPAL VULNERABILITY: Dumping TREND: Declining  OWNERTYPE: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems PINCIPAL VULNERABILITY: Dumping TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1009386)	CONDITION:	Extensive significant problems
SITE NAME:  Site of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton  DESIGNATION:  Scheduled Monument (No.1009383)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Drainage/dewatering  TREND:  Declining  OWNER TYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Settlement site at Boynton Hall, Boynton  DESIGNATION:  Scheduled Monument (No.1005207)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  OWNER TYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION:  Scheduled Monument (No.1014736)  CONDITION:  Extensive significant problems 01904 601901  SITE NAME:  Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION:  Declining  OWNER TYPE:  Private	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DESIGNATION:  Scheduled Monument (No.1009383)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Drainage/dewatering  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Settlement site at Boynton Hall, Boynton  DESIGNATION:  Scheduled Monument (No.1005207)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  OWNERTYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION:  Scheduled Monument (No.1014736)  CONDITION:  Extensive significant problems  POSTE NAME:  DESIGNATION:  Scheduled Monument (No.1014736)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Dumping  TREND:  Declining  OWNERTYPE:  Principal Heritage at Risk Adviser  Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
but with significant localised problems PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Declining OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Settlement site at Boynton Hall, Boynton  DESIGNATION: Scheduled Monument (No.1005207) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Site of Archbishop's moated palace and fish	ponds, Hall Garth	, Bishop Wilton
PRINCIPAL VULNERABILITY:  Drainage/dewatering  Private  Private  Private  Private  Private  Settlement site at Boynton Hall, Boynton  DESIGNATION:  DESIGNATION:  Private  Scheduled Monument (No.1005207)  Arable ploughing  TREND:  Declining  Declining  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Declining  OWNERTYPE  Private  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  SITE NAME:  Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION:  Scheduled Monument (No.1014736)  CONDITION:  Extensive significant problems  01904 601901  Declining  TREND:  Declining  TREND:  Declining  OWNERTYPE:  Private  Principal Heritage at Risk Adviser  Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1009383)	CONDITION:	
OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Settlement site at Boynton Hall, Boynton  DESIGNATION: Scheduled Monument (No.1005207) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Dumping  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser				but with significant localised problems
SITE NAME:  Settlement site at Boynton Hall, Boynton  DESIGNATION:  Scheduled Monument (No.1005207)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  OWNER TYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  SITE NAME:  Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION:  Scheduled Monument (No.1014736)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Dumping  TREND:  Declining  OWNER TYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:	9
Designation: Scheduled Monument (No.1005207) condition: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) condition: Extensive significant problems  PRINCIPAL VULNERABILITY: Dumping TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	, ,
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Settlement site at Boynton Hall, Boynton		
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1005207)	CONDITION:	Extensive significant problems
Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Dumping TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:	
Romano-British villa at Cockle Pits, near Brantingham  DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Dumping TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	, ,
DESIGNATION: Scheduled Monument (No.1014736) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Dumping TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser				01904 601901
PRINCIPAL VULNERABILITY: Dumping trend: Declining OWNERTYPE: Private contact: Principal Heritage at Risk Adviser	SITE NAME:	Romano-British villa at Cockle Pits, near B	rantingham	
OWNERTYPE: Private contact: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1014736)	CONDITION:	Extensive significant problems
· · · · · · · · · · · · · · · · · · ·	PRINCIPAL VULNERABILITY:		TREND:	9
01904 601901	OWNER TYPE:	Private	CONTACT:	,
				01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Bowl barrow, 500m south of Buckton Barn	, Bridlington	
DESIGNATION:	Scheduled Monument (No.1013624)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow, 500m SSW of Buckton Barn,	Bridlington	
DESIGNATION:	Scheduled Monument (No.1013623)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site at North Park Farm, Burstwick	<	
DESIGNATION:	Scheduled Monument (No.1008047)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Iron Age square barrow cemetery on Haist	chorpe Moor, 750n	n WNW of Demming Farm, Burton Agnes
DESIGNATION:	Scheduled Monument (No.1013706)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Wharram Hill embankment cross, Burton A	Agnes	
DESIGNATION:	Scheduled Monument (No.1005199)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Site revealed by aerial photography north v	west of Argam Co	ttages, Burton Fleming
DESIGNATION:	Scheduled Monument (No.1005211)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Willy Howe round barrow, Burton Fleming		
DESIGNATION:	Scheduled Monument (No.1008040)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
	Bowl barrow 200m west of Crest Cottage:	s, Carnaby	
SITE NAME:	Bowl ballow 200111 west of elest cottage.		
SITE NAME:  DESIGNATION:	Scheduled Monument (No.1007733)	CONDITION:	Extensive significant problems
	•	CONDITION: TREND:	Extensive significant problems Declining Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB LPA NP RPG SM UA WHS

SITE NAME:	Moated site and two fishponds 80m south west of Parkhouse Farm, Cherry Burton			
DESIGNATION:	Scheduled Monument (No.1007842)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 300m south west of High G	ardham Farm, Ch	erry Burton	
DESIGNATION:	Scheduled Monument (No.1007726)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 430m north west of High G	Sardham Farm, Ch	erry Burton	
DESIGNATION:	Scheduled Monument (No.1012121)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 430m north west of High G	ardham Farm, Ch	erry Burton	
DESIGNATION:	Scheduled Monument (No.1007727)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 700m west of High Gardhai	m Farm, Cherry B	urton	
DESIGNATION:	Scheduled Monument (No.1007728)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Seven round barrows 530m west of High C	Gardham Farm, Ch	erry Burton	
DESIGNATION:	Scheduled Monument (No.1012187)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two round barrows 600m north west of H	ligh Gardham Farr	n, Cherry Burton	
DESIGNATION:	Scheduled Monument (No.1008785)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Linear earthwork north east of Collingwoo	od Farm, Cottam		
DESIGNATION:	Scheduled Monument (No.1007862)	CONDITION:	Extensive significant problems	
	Arable ploughing	TREND:	Declining	
PRINCIPAL VULNERABILITY:	1 0 0		0	
PRINCIPAL VULNERABILITY: OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
		CONTACT:	0	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Round barrow 700m north east of Colling	wood Farm, Cotta	m
DESIGNATION:	Scheduled Monument (No.1007861)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Baynard Castle, Cottingham		
DESIGNATION:	Scheduled Monument (No.1019823)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Money Hill round barrow, Dalton Holme		
DESIGNATION:	Scheduled Monument (No.1007923)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moot Hill motte and bailey castle, and site	of a medieval moa	ated manor, Driffield
designation:	Scheduled Monument (No.1015612)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	World War I acoustic mirror 335m north	east of Kilnsea Gra	ange, Easington
DESIGNATION:	Scheduled Monument (No.1020989)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Site of deserted village of Grimston, East G	iarton	
DESIGNATION:	Scheduled Monument (No.1021241)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site at Newland Farm, Eastrington		
DESIGNATION:	Scheduled Monument (No.1015925)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
	Private		Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Heavy Anti-aircraft gunsite at Old Ellerby, 6	00m south of Elle	rby Grange, Ellerby
DESIGNATION:	Scheduled Monument (No.1019185)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Motte and bailey castle, fishpond and moate	ed site north and	east of Aughton church, Ellerton
DESIGNATION:	Scheduled Monument (No.1007973)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bolton Old Hall moated site, Fangfoss		
designation:	Scheduled Monument (No.1008045)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow I50m NNE of Towthorpe Hig	h Barn, Fimber	
DESIGNATION:	Scheduled Monument (No.1013702)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow,150m south east of Towthorp	e Reservoir, Fimb	er
DESIGNATION:	Scheduled Monument (No.1013703)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Settlement at Blealands Nook, Fimber		
DESIGNATION:	Scheduled Monument (No.1005205)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Garton Slack settlement site, Garton		
DESIGNATION:	Scheduled Monument (No.1005235)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
	Linear earthwork running from the head of	Warren Dale	6
SITE NAME:	towards Sledmere Field Farm and associate	d settlement site.	Garton
	towards Sledmere Field Farm and associate	ed settlement site,	
SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:	towards Sledmere Field Farm and associate  Scheduled Monument (No.1007736)  Arable ploughing		Extensive significant problems  Declining

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

SITE NAME:	Round barrow 350m south east of Low Fa	rm, Garton	
DESIGNATION:	Scheduled Monument (No.1007852)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Round barrow 400m south west of Low Fa	ırm, Garton	
DESIGNATION:	Scheduled Monument (No.1007856)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 420m south west of Low Fa	arm, Garton	
DESIGNATION:	Scheduled Monument (No.1007857)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 440m south west of Low Fa	ırm, Garton	
DESIGNATION:	Scheduled Monument (No.1007854)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 450m south west of Low Fa	arm Garton	
SITE INALIE.		irm, Garton	
	Scheduled Monument (No.1007853)	CONDITION:	Extensive significant problems
DESIGNATION:	Scheduled Monument (No.1007853)  Arable ploughing		Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007853)	CONDITION:	Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007853)  Arable ploughing	CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No.1007853) Arable ploughing Private	CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Fall	CONDITION: TREND: CONTACT:  rm, Garton	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Fall Scheduled Monument (No.1008810)	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Fare Scheduled Monument (No.1008810) Arable ploughing	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL YULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL YULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Fall Scheduled Monument (No.1008810) Arable ploughing Private	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL YULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION: DWNER TYPE:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Factorial Scheduled Monument (No.1008810) Arable ploughing Private  Round barrow 500m south of Low Farm, Comment (No.1008810)	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  OWNER TYPE:	Scheduled Monument (No.1007853)  Arable ploughing Private  Round barrow 500m south east of Low Farman Scheduled Monument (No.1008810)  Arable ploughing Private  Round barrow 500m south of Low Farm, Construction of Low Farm, Co	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Factorial Scheduled Monument (No.1008810) Arable ploughing Private  Round barrow 500m south of Low Farm, Common Scheduled Monument (No.1009394) Arable ploughing	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION: TREND: CONTACT:  Garton  CONDITION: TREND: CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Fall Scheduled Monument (No.1008810) Arable ploughing Private  Round barrow 500m south of Low Farm, Company Scheduled Monument (No.1009394) Arable ploughing Private	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION: TREND: CONTACT:  Garton  CONDITION: TREND: CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007853) Arable ploughing Private  Round barrow 500m south east of Low Fart Scheduled Monument (No.1008810) Arable ploughing Private  Round barrow 500m south of Low Farm, Company Scheduled Monument (No.1009394) Arable ploughing Private  Round barrow 700m south of Low Farm, Company Scheduled Monument (No.1009394) Arable ploughing Private	CONDITION: TREND: CONTACT:  rm, Garton  CONDITION: TREND: CONTACT:  Garton  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 700m south of Low Farm, C	Garton	
DESIGNATION:	Scheduled Monument (No.1007855)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
ITE NAME:	Round barrow 750m south of Low Farm, C	Garton	
DESIGNATION:	Scheduled Monument (No.1007851)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 1000m north east of Goodma	anham Wold Farm	, Goodmanham
DESIGNATION:	Scheduled Monument (No.1008934)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 230m south west of Enthorp	e House, Goodma	nham
DESIGNATION:	Scheduled Monument (No.1012835)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Bowl barrow 550m north east of Goodma	nham Wold Farm,	
	Bowl barrow 550m north east of Goodma  Scheduled Monument (No.1008933)	nham Wold Farm,	
DESIGNATION:		,	Goodmanham
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1008933)	CONDITION:	Goodmanham  Extensive significant problems  Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1008933)  Arable ploughing	CONDITION: TREND: CONTACT:	Goodmanham  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No.1008933) Arable ploughing Private	CONDITION: TREND: CONTACT:	Goodmanham  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No.1008933)  Arable ploughing  Private  Bowl barrow 550m south west of Enthorp	CONDITION: TREND: CONTACT:  e House, Goodma	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1008933) Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923)	CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1008933) Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923) Arable ploughing	condition:  TREND:  CONTACT:  e House, Goodma  CONDITION:  TREND:  CONTACT:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1008933) Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923) Arable ploughing Private	condition:  TREND:  CONTACT:  e House, Goodma  CONDITION:  TREND:  CONTACT:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL YULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL YULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No.1008933) Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923) Arable ploughing Private  Bowl barrow 700m south west of Enthorp	condition: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1008933) Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923) Arable ploughing Private  Bowl barrow 700m south west of Enthorp Scheduled Monument (No.1008922)	CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1008933)  Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923) Arable ploughing Private  Bowl barrow 700m south west of Enthorp Scheduled Monument (No.1008922) Arable ploughing	CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1008933) Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923) Arable ploughing Private  Bowl barrow 700m south west of Enthorp Scheduled Monument (No.1008922) Arable ploughing Private  Round barrow 730m NNW of Goodmanha	CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: OWNER TYPE:	Scheduled Monument (No.1008933) Arable ploughing Private  Bowl barrow 550m south west of Enthorp Scheduled Monument (No.1008923) Arable ploughing Private  Bowl barrow 700m south west of Enthorp Scheduled Monument (No.1008922) Arable ploughing Private	CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:  e House, Goodma  CONDITION: TREND: CONTACT:	Goodmanham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  nham  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA LB LPA NP RPG SM UA WHS

SITE NAME:	Twelve bowl barrows 800m north of Good	dmanham Wold Fai	rm, Goodmanham
DESIGNATION:	Scheduled Monument (No.1007642)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Romano-British villa east of Sandy Lane, 80	00m north west of	Harpham Grange, Harpham
DESIGNATION:	Scheduled Monument (No.1013628)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Park Closes moated lodge, I 30m south we	st of Park Farm, H	olme upon Spalding Moor
DESIGNATION:	Scheduled Monument (No.1015311)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hall Garths moated site, immediately south	n of St Mary's Chu	rch, Hook
DESIGNATION:	Scheduled Monument (No.1017823)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 230m south west of High Ba	rn Farm, Huggate	
DESIGNATION:	Scheduled Monument (No.1013464)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 400m NNW of East Greenw	ick Farm, Huggate	
DESIGNATION:	Scheduled Monument (No.1014727)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 780m north east of Waterma	anhole Reservoir, I	Huggate
DESIGNATION:	Scheduled Monument (No.1013864)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow on Huggate Pasture, 350m no	orth east of Pastur	e Dale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No.1013868)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Bowl barrow on Huggate Pasture, 450m N	NE of Pasture Dal	e Plantation, Huggate
DESIGNATION:	Scheduled Monument (No.1013867)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Bowl barrow on Huggate Pasture, 500m no	orth of Pasture Da	le Plantation, Huggate
DESIGNATION:	Scheduled Monument (No.1013866)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow on Huggate Wold, 400m NN	W of Watermanho	le Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No.1013861)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Bowl barrow on Huggate Wold, 460m WN	W of western cor	ner of Horsedale Plantation, Huggat
DESIGNATION:	Scheduled Monument (No.1013858)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	COLUTICE	Principal Heritage at Risk Adviser
OWNER TYPE:	rrivate	CONTACT:	,
OWNER TYPE:	rrivate	CONTACT:	01904 601901
OWNER TYPE: SITE NAME:	Bowl barrow on Huggate Wold, 480m nort		01904 601901
			01904 601901
SITE NAME:	Bowl barrow on Huggate Wold, 480m nort	h of Watermanho	01904 601901 le Reservoir, Huggate
SITE NAME: DESIGNATION:	Bowl barrow on Huggate Wold, 480m nort Scheduled Monument (No.1013862)	ch of Watermanho	le Reservoir, Huggate  Extensive significant problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 480m nort Scheduled Monument (No.1013862) Arable ploughing	ch of Watermanho  CONDITION:  TREND:  CONTACT:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Bowl barrow on Huggate Wold, 480m nort Scheduled Monument (No.1013862) Arable ploughing Private	ch of Watermanho  CONDITION:  TREND:  CONTACT:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Bowl barrow on Huggate Wold, 480m nort Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNV	ch of Watermanho  CONDITION:  TREND:  CONTACT:  W of Horsedale Pl	le Reservoir, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Bowl barrow on Huggate Wold, 480m nort Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNV Scheduled Monument (No.1013854)	ch of Watermanho  CONDITION:  TREND:  CONTACT:  W of Horsedale Pl  CONDITION:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl.  CONDITION: TREND:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl  CONDITION: TREND: CONTACT:	le Reservoir, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl  CONDITION: TREND: CONTACT:	le Reservoir, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private  Bowl barrow on Huggate Wold, 580m north	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl  CONDITION: TREND: CONTACT:	le Reservoir, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  OWNER TYPE:  SITE NAME:  DESIGNATION:  DESIGNATION:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private  Bowl barrow on Huggate Wold, 580m north Scheduled Monument (No.1013857)	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl  CONDITION: TREND: CONTACT:	le Reservoir, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  ale Plantation, Huggate Extensive significant problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private  Bowl barrow on Huggate Wold, 580m north Scheduled Monument (No.1013857) Arable ploughing	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl. CONDITION: TREND: CONTACT:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  alle Plantation, Huggate  Extensive significant problems Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private  Bowl barrow on Huggate Wold, 580m north Scheduled Monument (No.1013857) Arable ploughing	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl. CONDITION: TREND: CONTACT:  ch west of Horsedal CONDITION: TREND: CONTACT:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  ale Plantation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private  Bowl barrow on Huggate Wold, 580m north Scheduled Monument (No.1013857) Arable ploughing Private	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl. CONDITION: TREND: CONTACT:  ch west of Horsedal CONDITION: TREND: CONTACT:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  ale Plantation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private  Bowl barrow on Huggate Wold, 580m north Scheduled Monument (No.1013857) Arable ploughing Private  Bowl barrow on Huggate Wold, 600m NNN Bowl barrow on Huggate Wold, 600m NNN	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl. CONDITION: TREND: CONTACT:  ch west of Horsedale CONDITION: TREND: CONTACT:  W of Horsedale Pl.	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  ale Plantation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  antation, Huggate
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  DESIGNATION:  DESIGNATION:	Bowl barrow on Huggate Wold, 480m north Scheduled Monument (No.1013862) Arable ploughing Private  Bowl barrow on Huggate Wold, 500m NNN Scheduled Monument (No.1013854) Arable ploughing Private  Bowl barrow on Huggate Wold, 580m north Scheduled Monument (No.1013857) Arable ploughing Private  Bowl barrow on Huggate Wold, 600m NNN Scheduled Monument (No.1013853)	ch of Watermanho  CONDITION: TREND: CONTACT:  W of Horsedale Pl. CONDITION: TREND: CONTACT:  CONDITION: TREND: CONTACT:  W of Horsedale Pl. CONDITION:	le Reservoir, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  ale Plantation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  antation, Huggate  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

ITE NAME:	Bowl barrow on Huggate Wold, 600m west	t of Horsedale Pla	ntation, Huggate
DESIGNATION:	Scheduled Monument (No.1013859)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow on Huggate Wold, 700m NN	W of Watermanho	ole Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No.1013863)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
ITE NAME:	Bowl barrow on Huggate Wold, 700m nort	th west of Horsed	ale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No.1013856)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow on Huggate Wold, 840m ENE	of Watermanhole	: Reservoir, Huggate
DESIGNATION:	Scheduled Monument (No.1013860)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
ITE NAME:	Round barrow 240m south west of High B		
DESIGNATION:	Scheduled Monument (No.1012491)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1012491) Arable ploughing	CONDITION: TREND:	Extensive significant problems  Declining
DESIGNATION:	Scheduled Monument (No.1012491)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1012491) Arable ploughing	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1012491) Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  SITE NAME:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B	condition: trend: contact: arn Farm, Huggate	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479)	condition: trend: contact:  arn Farm, Huggate  condition:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing	condition: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  JITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private	condition: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  ITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private  Round barrow 360m south west of High B	condition: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  JITE NAME:  DESIGNATION:  DWNER TYPE:  JITE NAME:  DWNER TYPE:  JITE NAME:  DESIGNATION:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private  Round barrow 360m south west of High B Scheduled Monument (No.1012493)	condition: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:  arn Farm, Huggate  CONDITION:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private  Round barrow 360m south west of High B Scheduled Monument (No.1012493) Arable ploughing	CONDITION: TREND: CONTACT:  arn Farm, Huggate CONDITION: TREND: CONTACT:  arn Farm, Huggate CONDITION: TREND:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private  Round barrow 360m south west of High B Scheduled Monument (No.1012493) Arable ploughing	CONDITION: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private  Round barrow 360m south west of High B Scheduled Monument (No.1012493) Arable ploughing Private	CONDITION: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  JETE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  JETE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private  Round barrow 360m south west of High B Scheduled Monument (No.1012493) Arable ploughing Private  Round barrow 380m south west of High B	condition: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:  arn Farm, Huggate  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1012491) Arable ploughing Private  Round barrow 320m south west of High B Scheduled Monument (No.1012479) Arable ploughing Private  Round barrow 360m south west of High B Scheduled Monument (No.1012493) Arable ploughing Private  Round barrow 380m south west of High B Scheduled Monument (No.1012505)	CONDITION: TREND: CONTACT:  arn Farm, Huggate CONTACT:  arn Farm, Huggate CONDITION: TREND: CONTACT:  arn Farm, Huggate CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 390m south west of High B	arn Farm, Huggate	<b>:</b>
DESIGNATION:	Scheduled Monument (No.1012489)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Section of a single and double linear bound and the junctions of Holm Dale and Harpe		
DESIGNATION:	Scheduled Monument (No.1015566)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Section of linear boundary dyke south of N	1iddleham Plantatio	on and Harper Dale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No.1015569)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Sections of linear boundary dyke in Cow D	Dale Plantation, Ral	bbit Dale and Oxland Plantation, Huggate
DESIGNATION:	Scheduled Monument (No.1015570)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two bowl barrows on Huggate Wold, 600m	n north west of H	orsedale Plantation, Huggate
DESIGNATION:	Scheduled Monument (No.1013855)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Shaw Fosse moated site, Humbleton		
DESIGNATION:	Scheduled Monument (No.1007847)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Nunnery Hill and adjacent earthworks, Litt	le Kelk, Kelk	
DESIGNATION:	Scheduled Monument (No.1005202)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Gallows Hill round barrow, Kilham		
SITE NAME: DESIGNATION:	Gallows Hill round barrow, Kilham Scheduled Monument (No.1016737)	CONDITION:	Extensive significant problems
		CONDITION: TREND:	Extensive significant problems Declining Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Iron Age barrow cemetery, Kilham		
DESIGNATION:	Scheduled Monument (No.1005208)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 250m north east of Painsth	orpe Wold Cottag	es, Kirby Underdale
DESIGNATION:	Scheduled Monument (No.1008417)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 350m south east of Fordham	m Farm, Kirby Und	lerdale
DESIGNATION:	Scheduled Monument (No.1013165)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 500m south east of Painsthe	orpe Wold Cottag	es, Kirby Underdale
DESIGNATION:	Scheduled Monument (No.1008347)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 600m north east of Painsth	orpe Wold Cottag	es, Kirby Underdale
DESIGNATION:	Scheduled Monument (No.1008408)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 850m north east of Wayrha	ım Farm, Kirby Un	derdale
DESIGNATION:	Scheduled Monument (No.1008351)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 900m north east of Wayrha	ım Farm, Kirby Un	derdale
DESIGNATION:	Scheduled Monument (No.1008362)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow south east of South Wold F	arm, Kirby Underd	lale
DESIGNATION:	Scheduled Monument (No.1009384)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Eastern bowl barrow of a pair at crossroads Ikm NNW of Eastburn Warren Farm, Kirkb		till,
DESIGNATION:	Scheduled Monument (No.1014873)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
ITE NAME:	Western bowl barrow of a pair east of Crai	ke Hill, Ikm NNV	V of Eastburn Warren Farm, Kirkburn
DESIGNATION:	Scheduled Monument (No.1013709)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site at Metham Hall Farm, Laxton		
designation:	Scheduled Monument (No.1007972)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site 100m north of Parkhouse Farm	, Leconfield	
DESIGNATION:	Scheduled Monument (No.1008292)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site 310m north east of Scorborous	gh church, Leconf	îeld
DESIGNATION:	Scheduled Monument (No.1015818)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site 550m south east of Scorboroug	gh Hall, Leconfield	i
DESIGNATION:	Scheduled Monument (No.1016250)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site of Leconfield Castle, Leconfield		
			Conorally satisfactory
designation:	Scheduled Monument (No.1007949)	CONDITION:	Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007949)  Drainage/dewatering	CONDITION: TREND:	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Hayholme moated site, Leven		
DESIGNATION:	Scheduled Monument (No.1008043)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hall Garth motte and bailey, Lockington		
DESIGNATION:	Scheduled Monument (No.1021289)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Cleaving Hall moated site, Londesborough		
DESIGNATION:	Scheduled Monument (No.1007817)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 100m north east of High Wold	Farm, Market W	eighton
DESIGNATION:	Scheduled Monument (No.1013672)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow I I0m east of High Wold Farm,	Market Weighto	n
DESIGNATION:	Scheduled Monument (No.1012091)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 200m south east of High Wold	Farm, Market W	/eighton
DESIGNATION:	Scheduled Monument (No.1012092)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 320m north east of High Wold	Farm, Market W	/eighton
DESIGNATION:	Scheduled Monument (No.1012090)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 400m south of High Wold Farm	n, Market Weight	con
DESIGNATION:	Scheduled Monument (No.1012100)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA LB LPA NP RPG SM UA WHS

SITE NAME:	Bowl barrow 450m north east of High Wo	ld Farm, Market W	/eighton
DESIGNATION:	Scheduled Monument (No.1014256)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow 450m north of High Wold Fa	rm, Market Weight	con
DESIGNATION:	Scheduled Monument (No.1012089)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow 550m north of High Wold Fa	rm, Market Weight	con
DESIGNATION:	Scheduled Monument (No.1012088)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Four bowl barrows 450m south east of Hig	gh Wold Farm, Mai	rket Weighton
DESIGNATION:	Scheduled Monument (No.1012103)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01004 (01001
			01904 601901
SITE NAME:	Nine round barrows south east of Arras C	ottages, Market W	
	Nine round barrows south east of Arras C Scheduled Monument (No.1005228)	ottages, Market W	
DESIGNATION:			eighton eighton
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1005228)	CONDITION:	<b>'eighton</b> Extensive significant problems  Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1005228) Metal detecting	CONDITION: TREND: CONTACT:	Yeighton  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No.1005228)  Metal detecting  Private  Six bowl barrows 300m north east of High	CONDITION: TREND: CONTACT:  Wold Farm, Mark	leighton  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901  et Weighton
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No.1005228)  Metal detecting  Private  Six bowl barrows 300m north east of High  Scheduled Monument (No.1007501)	CONDITION: TREND: CONTACT:  Wold Farm, Mark CONDITION:	Teighton  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901  et Weighton  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1005228)  Metal detecting  Private  Six bowl barrows 300m north east of High	CONDITION: TREND: CONTACT:  Wold Farm, Mark	leighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No.1005228)  Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing	CONDITION: TREND: CONTACT:  Wold Farm, Mark CONDITION: TREND:	leighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1005228)  Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing	CONDITION: TREND: CONTACT:  Wold Farm, Mark CONDITION: TREND: CONTACT:	leighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1005228)  Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private	CONDITION: TREND: CONTACT:  Wold Farm, Mark CONDITION: TREND: CONTACT:	leighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  ITE NAME:  DWNER TYPE:  ITE NAME:  DESIGNATION:	Scheduled Monument (No.1005228)  Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private  Iron Age barrow group north east of Middle	CONDITION: TREND: CONTACT:  Wold Farm, Mark CONDITION: TREND: CONTACT:	feighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  s, Middleton
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1005228)  Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private  Iron Age barrow group north east of Middle Scheduled Monument (No.1003597)	CONDITION: TREND: CONTACT:  NWOLD Farm, Mark CONDITION: TREND: CONTACT:  Leton on the Wold CONDITION:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  s, Middleton Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1005228)  Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private  Iron Age barrow group north east of Middle Scheduled Monument (No.1003597) Arable ploughing	CONDITION: TREND: CONTACT:  NOOL Farm, Mark CONDITION: TREND: CONTACT:  Leton on the Wold CONDITION: TREND:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  s, Middleton Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1005228)  Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private  Iron Age barrow group north east of Middle Scheduled Monument (No.1003597) Arable ploughing	CONDITION: TREND: CONTACT:  Wold Farm, Mark CONDITION: TREND: CONTACT:  Jeton on the Wold CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  s, Middleton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1005228) Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private  Iron Age barrow group north east of Middle Scheduled Monument (No.1003597) Arable ploughing Private	CONDITION: TREND: CONTACT:  Wold Farm, Mark CONDITION: TREND: CONTACT:  Jeton on the Wold CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  s, Middleton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1005228) Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private  Iron Age barrow group north east of Middle Scheduled Monument (No.1003597) Arable ploughing Private  Bowl barrow 340m south east of Waterman	CONDITION: TREND: CONTACT:  NOOL Farm, Mark CONDITION: TREND: CONTACT:  JUNE 100 CONDITION: TREND: CONTACT: CONTACT:  CONTACT:	feighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  s, Middleton Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  fillington
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  DESIGNATION:  DWNER TYPE:	Scheduled Monument (No.1005228) Metal detecting Private  Six bowl barrows 300m north east of High Scheduled Monument (No.1007501) Arable ploughing Private  Iron Age barrow group north east of Middle Scheduled Monument (No.1003597) Arable ploughing Private  Bowl barrow 340m south east of Waterman Scheduled Monument (No.1013865)	CONDITION: TREND: CONTACT:  NOOID Farm, Mark CONDITION: TREND: CONTACT:  Leton on the Wold CONDITION: TREND: CONTACT:  CONTACT:  CONTACT:	leighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  et Weighton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  s, Middleton  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  fillington  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

Dumping TRADE Declaring Private CONNECT Principal Heritage at Risk Adviser 01904-601901  TRADE Private Private CONNECT Principal Heritage at Risk Adviser 01904-601901  TRADE Private CONNECT Principal Heritage at Risk Adviser 01904-601901  TRADE Scheduled Monument (No.1007325) CONNECT Principal Heritage at Risk Adviser 01904-601901  TRADE ROUND BARROWS PRIVATE PRIVATE PRIVATE PRINCIPAL AND ASSESSMENT PRIVATE PRI	SITE NAME:	Dane's Graves, Nafferton					
Dumping construers Private converse principal lentage at Risk Adviser 01901 601901  Five round barrows 750m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01901 601901  Five round barrows 400m south west of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01901 601901  Fire Name  Round barrow 400m south west of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01901 601901  Fire Name  Round barrow 400m south west of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01901 601901  Fire Name  Round barrow 550m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 550m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 550m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire Name  Round barrow 600m south east of Newbald Lodge, Newbald Converse principal lentage at Risk Adviser 01904 601901  Fire	DESIGNATION:	Scheduled Monument (No.1005230)	CONDITION:	Generally satisfactory but with significant localised problems			
Five round barrows 750m south east of Newbald Lodge, Newbald  Scheduled Monument (No.1007325)  CONTROL  Private  Round barrow 400m south west of Newbald Lodge, Newbald  Scheduled Monument (No.1011654)  CONTROL  CONTROL  Private  Round barrow 400m south west of Newbald Lodge, Newbald  CONTROL  CONTROL  CONTROL  CONTROL  CONTROL  Private  CONTROL  Private  Round barrow 550m south east of Newbald Lodge, Newbald  CONTROL  CONTROL  Private  CONTROL  CONTROL  Private  CONTROL  Private  Round barrow 550m south east of Newbald Lodge, Newbald  CONTROL  CONTROL  Private  Round barrow 550m south east of Newbald Lodge, Newbald  CONTROL  CONTROL  Private  CONTROL  CONTROL  CONTROL  Private  CONTROL  CONTROL  CONTROL  CONTROL  Private  CONTROL  CONTROL  CONTROL  CONTROL  CONTROL  Private  CONTROL	PRINCIPAL VULNERABILITY:	Dumping	TREND:	-			
Scheduled Monument (No.1007325) constitues Scheduled Monument (No.1007325) Constitues Scheduled Monument (No.1007325) Constitues Scheduled Monument (No.1011654) Constitues Scheduled Monument (No.1011654) Constitues Scheduled Monument (No.1011654) Constitues Scheduled Monument (No.1011654) Constitues Scheduled Monument (No.1007326) Constitues Scheduled Monument (No.1007320) Constitues Scheduled Monument (No.1007321) Constitues Scheduled Monument (No.1007321) Constitues Scheduled Monument (No.1007323) Constitues Scheduled Monument (No.10	OWNER TYPE:	Private	CONTACT:				
Private Declining Private Declining Declining Private Declining Declining Declining Declining Private Declining Declining Declining Private Declining Declining Declining Private Declining Declining Declining Declining Declining Declining Declining Private Declining Decl	SITE NAME:	Five round barrows 750m south east of Ne	ewbald Lodge, Nev	wbald			
Round barrow 400m south west of Newbald Lodge, Newbald DESCRIPTION SCHEDULE PRIVATE  ROUND BARROW VALERABULTY DATE NAME  ROUND BARROW SOUTH WAS A CONDITION SCHEDULE PRIVATE  ROUND BARROW VALERABULTY DATE NAME  ROUND BARROW SOUTH EAST OF Newbald Lodge, Newbald DESCRIPTION SCHEDULE PRIVATE  ROUND BARROW SOUTH EAST OF Newbald Lodge, Newbald DESCRIPTION SCHEDULE PRIVATE DEVINE PRIVATE  ROUND BARROW SOUTH EAST OF Newbald Lodge, Newbald DESCRIPTION DEVINE PRIVATE DEVINE PRIVATE DEVINE PRIVATE  ROUND BARROW SOUTH EAST OF Newbald Lodge, Newbald DESCRIPTION DEVINE PRIVATE DEVINE PRIVATE  ROUND BARROW SOUTH EAST OF Newbald Lodge, Newbald DESCRIPTION DEVINE SIGNIFICANT PROBLEMS DEVELOPED TO THE PRIVATE DEVELOPMENT PRIVATE DEVEL	DESIGNATION:	Scheduled Monument (No.1007325)	CONDITION:	Extensive significant problems			
ROUND BATTON 400m SOUTH WEST OF Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 400m SOUTH WEST OF Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 550m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 550m SOUTH east of Newbald Lodge, Newbald  SESENATION.  SCHEDUL VULNEARABUTY:  Arable ploughing  FINAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Newbald Lodge, Newbald  SETENAME:  ROUND BATTON 600m SOUTH east of Littlewood Lodge, Newbald  SETENAME:  ROUND BATTON 600m FEE OF Blanch Farm, North Dalton  SETENAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  SETENAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  SETENAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  SETENAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  SETENAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  SETENAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  FINAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  FINAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  FINAME:  ROUND BATTON 600m ESE OF Blanch Farm, North Dalton  FINAME:  ROUND BATTON 600m ESE OF Blan	PRINCIPAL VULNERABILITY:		TREND:	9			
Scheduled Monument (No.1011654)  CONDITION:  Arable ploughing  Private  Round barrow 550m south east of Newbald Lodge, Newbald  SEGONATION:  Scheduled Monument (No.1007320)  CONDITION:  Extensive significant problems  Declining  Private  Round barrow 550m south east of Newbald Lodge, Newbald  SEGONATION:  Scheduled Monument (No.1007320)  CONDITION:  Extensive significant problems  Declining  Private  Round barrow 600m south east of Newbald Lodge, Newbald  SEGONATION:  Round barrow 600m south east of Newbald Lodge, Newbald  SEGONATION:  Scheduled Monument (No.1007321)  SEGONATION:  Scheduled Monument (No.1007321)  SEGONATION:  SCHEDURA (NO.1007323)  SEGONATION:  SCHEDURA (NO.1007323)  SCHEDURA (NO.	OWNER TYPE:	Private	CONTACT:				
Arable ploughing TREND: Declining Private CONTACT Principal Heritage at Risk Adviser 01904 601901  Arable ploughing TREND: CONTACT Principal Heritage at Risk Adviser 01904 601901  Arable ploughing TREND: Declining Extensive significant problems Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Arable ploughing TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Arable ploughing TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Arable ploughing TREND: Declining Declining Declining TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Arable ploughing TREND: Declining Declining Declining Declining TREND: Declining Declining TREND: Declining Declining TREND: Declining Declining Declining TREND: Declining TREND: Declining TREND: Declining Declining TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  ARE NAME: Round barrow 700m north east of Littlewood Lodge, Newbald Lodge, Newb	SITE NAME:	Round barrow 400m south west of Newba	ıld Lodge, Newbal	i			
Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007320) CONDITION: Extensive significant problems  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007320) TRRDD Declining  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007321) CONDITION: Extensive significant problems  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007321) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007323) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007323) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007323) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007333) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007353) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007353) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007353) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1007353) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems  Representation: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems  Representation: Scheduled Monument (No.1013463) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Representation: Scheduled Monument (No.1013463) CONDITION: Principal Heritage at Risk Adviser 01904 601901	DESIGNATION:		CONDITION:				
Round barrow 550m south east of Newbald Lodge, Newbald  BESIGNAPHONE Scheduled Monument (No.1007320)  CONDITION: Principal Heritage at Risk Adviser O1904 601901  BY TREND.  Private  Round barrow 600m south east of Newbald Lodge, Newbald  CONTROLL  Frincipal Heritage at Risk Adviser O1904 601901  CONTROLL  FREND.  Declining  Round barrow 600m south east of Newbald Lodge, Newbald  CESCHARDINE Scheduled Monument (No.1007321)  CONDITION: Principal Heritage at Risk Adviser O1904 601901  CONTROLL  FREND.  Private  Round barrow 620m south east of Newbald Lodge, Newbald  CONTROLL  FREND.  Private  Round barrow 620m south east of Newbald Lodge, Newbald  CESCHARDINE  Round barrow 620m south east of Newbald Lodge, Newbald  CESCHARDINE  Round barrow 620m south east of Newbald Lodge, Newbald  CESCHARDINE  FREND.  Declining  Private  CONTROLL  Principal Heritage at Risk Adviser O1904 601901  CONTROLL  FREND.  Declining  Private  Round barrow 700m north east of Littlewood Lodge, Newbald  CONTROLL  FREND.  Declining  Private  Round barrow 700m north east of Littlewood Lodge, Newbald  CONTROLL  FREND.  Declining  Private  Round barrow 700m north east of Littlewood Lodge, Newbald  CONTROLL  FREND.  Declining  Private  Round barrow 700m north east of Littlewood Lodge, Newbald  CONTROLL  FREND.  Declining  Private  Round barrow 600m ESE of Blanch Farm, North Dalton  SECHANDER  Bowl barrow 600m ESE of Blanch Farm, North Dalton  Extensive significant problems  Private  Bowl barrow 600m ESE of Blanch Farm, North Dalton  Extensive significant problems  Extensive significant problems  Extensive significant problems  Declining  Private  Private  Declining  Private  Round barrow 600m ESE of Blanch Farm, North Dalton  Declining  Private  Private  Private  Round barrow 600m ESE of Blanch Farm, North Dalton  Declining  Private  Private  Private  Round barrow 600m ESE of Blanch Farm, North Dalton  Declining  Private  Private  Private  Round barrow 600m ESE of Blanch Farm, North Dalton  Declining  Private  Private  Private  Round barrow 600m	PRINCIPAL VULNERABILITY:	, 5	TREND:	9			
Scheduled Monument (No.1007320)  CONDITION  Arable ploughing  TREND: Declining  Private  Round barrow 600m south east of Newbald Lodge, Newbald  SESIGNATION: Arable ploughing  TREND: Declining  Private  Round barrow 600m south east of Newbald Lodge, Newbald  SESIGNATION: Arable ploughing  TREND: Declining  TREND: Dec	OWNER TYPE:	Private	CONTACT:				
Arable ploughing TIRIND: Declining Private Pri	SITE NAME:	Round barrow 550m south east of Newbal	d Lodge, Newbald				
Round barrow 600m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 600m south east of Newbald Lodge, Newbald  SESTENAME:  Scheduled Monument (No.1007321)  CONDITION:  Scheduled Monument (No.1007321)  CONDITION:  Declining  Principal Heritage at Risk Adviser  O1904 601901  STENAME:  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME:  Round barrow 620m north east of Littlewood Lodge, Newbald  SESTENAME:  Round barrow 700m north east of Littlewood Lodge, Newbald  SESTENAME:  Round barrow 700m north east of Littlewood Lodge, Newbald  SESTENAME:  Round barrow 700m north east of Littlewood Lodge, Newbald  SESTENAME:  Round barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Bowl barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Bowl barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Bowl barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Bowl barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch Farm, North Dalton  SESTENAME:  Round Barrow 600m ESE of Blanch F	DESIGNATION:	Scheduled Monument (No.1007320)	CONDITION:	Extensive significant problems			
Round barrow 600m south east of Newbald Lodge, Newbald  SESTENAME  Round barrow 600m south east of Newbald Lodge, Newbald  SESTENAME  Arable ploughing  TREND: Declining  Devinicipal Heritage at Risk Adviser 01904 601901  STEND: Declining  Private  Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME: Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME: Round barrow 620m south east of Newbald Lodge, Newbald  SESTENAME: ROUNDERTYPE  ROUNDERTYPE  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STENAME: ROUNDERTYPE	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	8			
Scheduled Monument (No.1007321)  Arable ploughing  Private  Round barrow 620m south east of Newbald Lodge, Newbald  Scheduled Monument (No.1007323)  Scheduled Monument (No.1007353)  Scheduled Monume	OWNER TYPE:	Private	CONTACT:				
Arable ploughing TREND: Declining  Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  RETE NAME: Round barrow 620m south east of Newbald Lodge, Newbald  DESIGNATION: Scheduled Monument (No.1007323) CONDITION: Extensive significant problems  Declining  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  RETE NAME: Round barrow 700m north east of Littlewood Lodge, Newbald  RETE NAME: Round barrow 700m north east of Littlewood Lodge, Newbald  RETE NAME: Round barrow 700m north east of Littlewood Lodge, Newbald  RETE NAME: Scheduled Monument (No.1007353) CONDITION: Extensive significant problems  DESIGNATION: Scheduled Monument (No.1007353) CONDITION: Declining  DEVINENTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  RETE NAME: Bowl barrow 600m ESE of Blanch Farm, North Dalton  DESIGNATION: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems  DESIGNATION: Principal Heritage at Risk Adviser  DESIGNATION: Principal Heritage at Risk Adviser  DESIGNATION: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow 600m south east of Newbal	d Lodge, Newbald				
Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Round barrow 620m south east of Newbald Lodge, Newbald Condition: Extensive significant problems Designation: Arable ploughing TREND: Declining Principal Heritage at Risk Adviser 01904 601901  Retensive Scheduled Monument (No.1007323) CONDITION: Extensive significant problems Development (No.1007323) CONDITION: Principal Heritage at Risk Adviser 01904 601901  Retensive Round barrow 700m north east of Littlewood Lodge, Newbald Designation: Scheduled Monument (No.1007353) CONDITION: Extensive significant problems Declining Downer type Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Retensive Scheduled Monument (No.1013463) CONTACT: Principal Heritage at Risk Adviser 01904 601901  Retensive Scheduled Monument (No.1013463) CONDITION: Extensive significant problems Designation: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems Designation: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems Declining Downer type Private Private Principal Heritage at Risk Adviser Declining Declin	DESIGNATION:	Scheduled Monument (No.1007321)	CONDITION:	Extensive significant problems			
Round barrow 620m south east of Newbald Lodge, Newbald  SCHENAME: Round barrow 620m south east of Newbald Lodge, Newbald  SCHENCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SCHENAME: Round barrow 700m north east of Littlewood Lodge, Newbald  DESIGNATION: Scheduled Monument (No.1007353) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SCHENAME: Bowl barrow 600m ESE of Blanch Farm, North Dalton  DESIGNATION: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems  DESIGNATION: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:	8			
Scheduled Monument (No.1007323)  CONDITION: Extensive significant problems  Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Round barrow 700m north east of Littlewood Lodge, Newbald  Designation: Scheduled Monument (No.1007353)  CONDITION: Extensive significant problems  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Round barrow 700m north east of Littlewood Lodge, Newbald  Designation: Scheduled Monument (No.1007353)  CONDITION: Extensive significant problems  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Bowl barrow 600m ESE of Blanch Farm, North Dalton  Scheduled Monument (No.1013463)  CONDITION: Extensive significant problems 01904 601901  Extensive significant problems 01904 601901  Designation: Scheduled Monument (No.1013463)  CONDITION: Extensive significant problems  Private CONTACT: Principal Heritage at Risk Adviser  Declining  Devine Type: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:				
Arable ploughing TREND: Declining DWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Round barrow 700m north east of Littlewood Lodge, Newbald  DESIGNATION: Scheduled Monument (No.1007353) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining DWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Bowl barrow 600m ESE of Blanch Farm, North Dalton  DESIGNATION: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems 01904 601901  Brite NAME: Bowl barrow 600m ESE of Blanch Farm, North Dalton  DESIGNATION: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow 620m south east of Newbal	d Lodge, Newbald				
Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Round barrow 700m north east of Littlewood Lodge, Newbald  DESIGNATION: Scheduled Monument (No.1007353) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  BOWNER TYPE: Bowl barrow 600m ESE of Blanch Farm, North Dalton  DESIGNATION: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1007323)	CONDITION:	Extensive significant problems			
Round barrow 700m north east of Littlewood Lodge, Newbald  DESIGNATION: Scheduled Monument (No.1007353) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DEVINER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  BOWNER TYPE: Bowl barrow 600m ESE of Blanch Farm, North Dalton  DESIGNATION: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:	8			
Designation: Scheduled Monument (No.1007353) condition: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining Downer Type: Private Contact: Principal Heritage at Risk Adviser 01904 601901  Bowl barrow 600m ESE of Blanch Farm, North Dalton  Designation: Scheduled Monument (No.1013463) condition: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Downer Type: Private Contact: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	, -			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  Bowl barrow 600m ESE of Blanch Farm, North Dalton  Designation:  Scheduled Monument (No.1013463)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  Declining  CONTACT:  Principal Heritage at Risk Adviser  Designation:  Private  Private	SITE NAME:	Round barrow 700m north east of Littlewo	ood Lodge, Newba	ld			
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  Bowl barrow 600m ESE of Blanch Farm, North Dalton  Designation:  Scheduled Monument (No.1013463)  CONDITION:  Extensive significant problems  PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  Declining  CONTACT:  Principal Heritage at Risk Adviser  Designation:  Private  Private	DESIGNATION:	Scheduled Monument (No.1007353)	CONDITION:	Extensive significant problems			
Bowl barrow 600m ESE of Blanch Farm, North Dalton  Scheduled Monument (No.1013463) condition: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing trend: Declining  Downer type: Private contact: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:				
DESIGNATION: Scheduled Monument (No.1013463) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining DOWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	, -			
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Bowl barrow 600m ESE of Blanch Farm, No	orth Dalton				
OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1013463)	CONDITION:	Extensive significant problems			
	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	8			
01904 601901	OWNER TYPE:	Private	CONTACT:	, -			
				01904 601901			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Bowl barrow 610m east of Blanch Farm, N	orth Dalton	
DESIGNATION:	Scheduled Monument (No.1013460)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 620m ESE of Blanch Farm, No	orth Dalton	
DESIGNATION:	Scheduled Monument (No.1013461)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Paull Holme moated site and tower, Paull		
DESIGNATION:	Scheduled Monument (No.1007875)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Paull Point Battery, coastal artillery battery	and Submarine M	ining Establishment, Paull
DESIGNATION:	Scheduled Monument (No.1020425)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Argam dykes, Rudston		
DESIGNATION:	Scheduled Monument (No.1005234)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Earthwork on the Sheepwalk stretching no	rth from Wold Ga	te for 530yds (480m), Rudston
DESIGNATION:	Scheduled Monument (No.1005223)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman villa site, Rudston		
DESIGNATION:	Scheduled Monument (No.1005222)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
OWNER TYPE:			
	Rudston Beacon and round barrows to eas	t, Rudston	
OWNER TYPE:  SITE NAME:  DESIGNATION:	Rudston Beacon and round barrows to eas Scheduled Monument (No.1005231)	t, Rudston	Extensive significant problems
SITE NAME:		,	Extensive significant problems Declining Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

ITE NAME:	Bowl barrow 550m south of High Wold Fa	rm, Sancton	
DESIGNATION:	Scheduled Monument (No.1012102)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated monastic grange 300m south west	of Winsetts Farm	, Skeffling
DESIGNATION:	Scheduled Monument (No.1015309)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hallgarth medieval hall and moat, Skipsea		
DESIGNATION:	Scheduled Monument (No.1013705)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Royal Observer Corps underground monit 200m north of Southfield House, Skipsea	coring post and Wo	orld War II visual spotting post,
DESIGNATION:	Scheduled Monument (No.1021192)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
			01701 001701
SITE NAME:	Skipsea Castle:11th century motte and bail	ley castle and inlan	
SITE NAME: DESIGNATION:	Skipsea Castle: 11th century motte and bail Scheduled Monument (No.1011212)	ley castle and inlan	
		•	d harbour, Skipsea  Generally satisfactory
DESIGNATION:	Scheduled Monument (No.1011212)	CONDITION:	d harbour, Skipsea  Generally satisfactory but with significant localised problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1011212)  Drainage/dewatering	CONDITION: TREND: CONTACT:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1011212)  Drainage/dewatering  Private	CONDITION: TREND: CONTACT:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)	CONDITION:  TREND:  CONTACT:  nworks at Manor I	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth	CONDITION:  TREND: CONTACT:  nworks at Manor I	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)  Drainage/dewatering	CONDITION:  TREND: CONTACT:  nworks at Manor I  CONDITION:  TREND: CONTACT:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)  Drainage/dewatering Private	CONDITION:  TREND: CONTACT:  nworks at Manor I  CONDITION:  TREND: CONTACT:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)  Drainage/dewatering Private  Round barrow 1300m east of Life Hill, Sled	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)  Drainage/dewatering Private  Round barrow I 300m east of Life Hill, Sled Scheduled Monument (No.1007858)	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONTACT:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)  Drainage/dewatering Private  Round barrow I 300m east of Life Hill, Sled Scheduled Monument (No.1007858) Arable ploughing	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)  Drainage/dewatering Private  Round barrow I 300m east of Life Hill, Sled Scheduled Monument (No.1007858) Arable ploughing Private	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  TREND: CONDITION: TREND: CONDITION: TREND: CONDITION:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1011212)  Drainage/dewatering Private  Moated site, fishponds and associated earth Scheduled Monument (No.1015614)  Drainage/dewatering Private  Round barrow I 300m east of Life Hill, Sled Scheduled Monument (No.1007858) Arable ploughing Private  Round barrow I 400m east of Life Hill, Sled	CONDITION:  TREND: CONTACT:  CONDITION:  TREND: CONTACT:  TREND: CONTACT:  TREND: CONTACT:  TREND: CONTACT:	d harbour, Skipsea  Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  House, Skirpenbeck Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

SITE NAME:	Round barrow 1650m east of Life Hill, Sled	mere	
DESIGNATION:	Scheduled Monument (No.1007860)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Kings Manor moated site, 450m south of L	ittle London, Snait	h and Cowick
DESIGNATION:	Scheduled Monument (No.1015307)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Stone Creek Heavy Anti-aircraft gunsite, at	Sunk Island Cloug	gh, Sunk Island
DESIGNATION:	Scheduled Monument (No.1020187)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site at St Lois Farm, Sutton upon D	Derwent	
DESIGNATION:	Scheduled Monument (No.1007818)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hall Garth moated site, associated drainage	e channels and fish	pond, Twin Rivers
DESIGNATION:	Scheduled Monument (No.1013190)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE:	Drainage/dewatering Private	TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Ling Howe long barrow, Walkington		
DESIGNATION:	Scheduled Monument (No.1015306)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 170m north west of Farberry	Garth Farm, War	ter
DESIGNATION:	Scheduled Monument (No.1013471)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 210m south east of Blanch Fa	ırm,Warter	
	C	CONDITION:	Extensive significant problems
DESIGNATION:	Scheduled Monument (No.1013456)	CONDITION.	8 1
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing  Private	TREND:	Declining Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA LB LPA NP RPG SM UA WHS

SITE NAME:	Bowl barrow 290m south east of Blanch Fa	arm,Warter	
DESIGNATION:	Scheduled Monument (No.1013457)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow 500m east of Blanch Farm, W	arter	
DESIGNATION:	Scheduled Monument (No.1013459)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow 560m NNW of Farberry Gar	th Farm,Warter	
DESIGNATION:	Scheduled Monument (No.1013467)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow 720m NNW of Farberry Gar	th Farm,Warter	
DESIGNATION:	Scheduled Monument (No.1013466)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
ITE NAME:	Bowl barrow 760m NNE of Farberry Gart	h Farm,Warter	
	C	CONDITION	Extensive significant problems
DESIGNATION:	Scheduled Monument (No.1013465)	CONDITION:	Exterisive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
			Declining Principal Heritage at Risk Adviser
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: CONTACT:	Declining Principal Heritage at Risk Adviser
RINCIPAL VULNERABILITY: DWNER TYPE:	Arable ploughing Private	TREND: CONTACT:	Declining Principal Heritage at Risk Adviser
RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing	TREND: CONTACT: e Farm, Warter	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895)	TREND: CONTACT:  e Farm, Warter CONDITION:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
RINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
RINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private  Round barrow 400m north west of Cobdal	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private  Round barrow 400m north west of Cobdal Scheduled Monument (No.1012508)	TREND: CONTACT:  e Farm, Warter CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  JETE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  JETE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private  Round barrow 400m north west of Cobdal Scheduled Monument (No.1012508) Arable ploughing	TREND: CONTACT:  e Farm, Warter CONDITION: TREND: CONTACT:  le Farm, Warter CONDITION: TREND:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private  Round barrow 400m north west of Cobdal Scheduled Monument (No.1012508) Arable ploughing	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND: CONTACT:  le Farm, Warter  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  JETE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  JETE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Arable ploughing Private  Round barrow I 00m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private  Round barrow 400m north west of Cobdal Scheduled Monument (No.1012508) Arable ploughing Private	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND: CONTACT:  le Farm, Warter  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser
RINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DWNER TYPE:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private  Round barrow 400m north west of Cobdal Scheduled Monument (No.1012508) Arable ploughing Private  Round barrow 450m north east of Blanch	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND: CONTACT:  le Farm, Warter  CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
PRINCIPAL VULNERABILITY:  DOWNER TYPE:  JUSTIC NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  JUSTIC NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:  JUSTIC NAME:  DESIGNATION:  JUSTIC NAME:  DESIGNATION:	Arable ploughing Private  Round barrow 100m south west of Cobdal Scheduled Monument (No.1011895) Arable ploughing Private  Round barrow 400m north west of Cobdal Scheduled Monument (No.1012508) Arable ploughing Private  Round barrow 450m north east of Blanch Scheduled Monument (No.1011906)	TREND: CONTACT:  e Farm, Warter  CONDITION: TREND: CONTACT:  le Farm, Warter  CONDITION: TREND: CONTACT:  Farm, Warter  CONDITION:	Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME: Round barrow 520m south of Warren Farm, Warter				
DESIGNATION:	Scheduled Monument (No.1011890)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 915m north east of Dalton	Gates Farm, Wart	er	
DESIGNATION:	Scheduled Monument (No.1011911)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 930m north east of Dalton	Gates Farm, Wart	er	
DESIGNATION:	Scheduled Monument (No.1011910)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow on Thirty Acres, Warter			
DESIGNATION:	Scheduled Monument (No.1011908)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Section of linear boundary dyke between S north west of Coldwold Farm, Warter	ylvan Dale and Wa	arren Farm,	
DESIGNATION:	Scheduled Monument (No.1016191)	CONDITION:	Generally satisfactory	
	` ,		but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two bowl barrows 300m south east of Bla	nch Farm, Warter		
DESIGNATION:	Scheduled Monument (No.1013458)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two bowl barrows 500m north west of Fa	rberry Garth Farm	n,Warter	
DESIGNATION:	Scheduled Monument (No.1013470)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two round barrows 820m north east of Da	alton Gates Farm,	Warter	
DESIGNATION:	Scheduled Monument (No.1011912)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Site of Watton Gilbertine priory, two possible	e medieval arche	ry butts and Civil War earthworks,Watto		
DESIGNATION:	Scheduled Monument (No.1007751)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901		
SITE NAME:	Medieval moated tile kiln 250m north east of	North Grange F	- Farm, Wawne		
DESIGNATION:	Scheduled Monument (No.1008039)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901		
SITE NAME:	Moated monastic grange site and fishponds in 630m north west of Carlam Hill Farm, Wawn				
DESIGNATION:	Scheduled Monument (No.1016068)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901		
SITE NAME:	Haltemprice Augustinian priory, Willerby				
DESIGNATION:	Scheduled Monument (No.1019825)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901		
SITE NAME:	Bowl barrow 580m west of High Fordon Farm	m,Wold Newton			
DESIGNATION:	Scheduled Monument (No.1007743)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901		
SITE NAME:	Bowl barrow 600m west of High Fordon Farm, Wold Newton				
DESIGNATION:	Scheduled Monument (No.1007742)	CONDITION:	Extensive significant problems		
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901		
SITE NAME:	Hall Garth moated site south of Beverley Min	nster, Woodmans	еу		
DESIGNATION:	Scheduled Monument (No.1008122)	CONDITION:	Generally satisfactory but with significant localised problems		
PRINCIPAL VULNERABILITY:	Drainage/dewatering Private	TREND:	Declining Principal Heritage at Risk Adviser		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



SITE NAME: Th	waite Hall	, Cottingham
---------------	------------	--------------

DESIGNATION: Registered Park and Garden Grade II,

also CA

Generally satisfactory

but with significant localised problems

VULNERABILITY: High

Declining

OWNERTYPE: Private, single owner

Grounds of a villa developed mainly in the 1870s/80s, but modified in the mid C20 to provide accommodation for the University College of Hull. Grounds partly developed as a botanical garden. Problems with flood damage in 2007 and drainage problems are affecting mature planting and lawns around the lake.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Londesborough Park, Londesborough

DESIGNATION: Registered Park and Garden Grade II\*,

also part in CA, 5 LBs

Generally satisfactory CONDITION:

but with significant localised problems

VULNERABILITY: High

Declining TRENID:

Private, multiple owners

Gardens laid out in the late C17 wholly or partly by Robert Hooke for the first Lord Burlington, with alterations and additions by the third Lord Burlington in the early to mid C18. Park with avenues of early C18 date with earlier origins. Kitchen garden of 1730-5 with cascades and entrances aligned with parkland avenues. Extensive parkland requiring more detailed study of historic development of the planting design, key avenues and vistas. Structures in walled garden in state of deterioration.

Contact: Principal Heritage at Risk Adviser 01904 601901

			4		Ų
M		11	1	1	IF

#### Bridlington Quay, Bridlington

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Malte Klockner (LPA) 01482 393725	NEW ENTRY?:	Yes

SITE NAME:

SITE NAME:

#### Goole

Conservation Area DESIGNATION: CONDITION:

VULNERABILITY:

Malte Klockner (LPA) 01482 393725 CONTACT:

CONDITION:

Very bad

Deteriorating significantly TREND

NEW ENTRY?:



SITE NAME: Battle of Stamford Bridge, Stamford Bridge

DESIGNATION: Registered Battlefield

Generally satisfactory but with minor localised problems

VULNERABILITY: High

Declining

Private OWNER TYPE:

Three weeks before the Battle of Hastings (1066) King Harold defeated a Norwegian army at this crossing point on the River Derwent. The modern settlement of Stamford Bridge grew markedly in the later C20 and little of the battlefield remains undeveloped.

Contact: Principal Heritage at Risk Adviser 01904 601901



#### KINGSTON UPON HULL, CITY OF (UA)



St Albans Church, SITE NAME:


Hall Road

DESIGNATION: Listed Place of Worship Grade II

Poor CONDITION: D (C) PRIORITY:

OWNER TYPE: Religious organisation

Parish church dating to 1938, completed 1954. Constructed from orange brick under a pantile roof. Interior has flat concrete arches. Tower recently repaired, but aisle roofs are in need of recovering. Grant offered for roof work.



SITE NAME:

Church of St Matthew and boundary wall, Anlaby Road, Kingston Upon Hull

DESIGNATION: Listed Place of Worship Grade II

Poor CONDITION:

C (New entry)

Religious organisation OWNER TYPE:

Church of 1870 by Adams & Kelly in the Early English style. Yellow brick, with red brick and ashlar dressings and slate roofs. The spire and tower require repair. The church made a successful application for a grant to undertake this, but were unable to take it forward.

Contact: Principal Heritage at Risk Adviser 01904 601901

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Renair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTF: 2011 priority categories are given in brackets

CA LB LPA NP RPG SM

UA WHS

**ABBREVIATIONS** 

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Beverley Road, Hull		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Philip Hampel (LPA) 01482 612343	NEW ENTRY?:	No
SITE NAME:	St Andrew's Dock, Hull		
SITE NAME:  DESIGNATION:	St Andrew's Dock, Hull  Conservation Area	CONDITION:	Very bad
	·	CONDITION: TREND:	Very bad Deteriorating

#### NORTH EAST LINCOLNSHIRE (UA)




SITE NAME: The Grimsby Ice Factory, Gorton Street, Grimsby

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad OCCUPANCY: Vacant PRIORITY: A (A)
OWNER TYPE: Company

1900 ice works with extension factory of 1907-8 and later alterations. Closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. Window damage. Roof is now deteriorating rapidly.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME:

SITE NAME: Church of Saint Margaret,
Barton Street,

Hawerby cum Beesby
DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad OCCUPANCY: Vacant PRIORITY: A (A)
OWNER TYPE: Private

Former parish church. C12, C13 and C17 with mid C19 restorations. Empty and disused since closed in 1978. Longstanding proposals for conversion to studio/gallery have not been implemented. Suffering from neglect, with localised collapses of walling.

Contact: Principal Heritage at Risk Adviser 01904 601901

Civil W	ir earthwork for	t 350m north	east of Walk	Farm Irby

DESIGNATION:	Scheduled Monument (No.1007735)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Premonstratensian priory chapel 170m sour	Premonstratensian priory chapel 170m south west of Priory Farm, West Ravendale			
DESIGNATION:	Scheduled Monument (No.1019867)	CONDITION:	Generally unsatisfactory		
			with major localised problems		
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining		
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser		
			01904 601901		

SITE NAME:	Central Area, Grimsby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Tony Sargent (LPA) 01472 324 252	NEW ENTRY?:	No

	, I		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Tony Sargent (LPA) 01472 324 252	NEW ENTRY?:	No

#### PRIORITY (FOR BUILDINGS)

SITE NAME:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Central Sea Front, Cleethorpes

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Great Coates, Grimsby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Tony Sargent (LPA) 01472 324 252	NEW ENTRY?:	No
SITE NAME:	Holme Hill, Grimsby		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Tony Sargent (LPA) 01472 324 252	NEW ENTRY?:	No
SITE NAME:	Laceby		
SITE NAME:  DESIGNATION:	Laceby  Conservation Area	CONDITION:	Poor
	•	CONDITION: TREND:	Poor Deteriorating
DESIGNATION:	Conservation Area		,
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	Deteriorating
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	Deteriorating
DESIGNATION: VULNERABILITY: CONTACT:	Conservation Area  Medium  Tony Sargent (LPA) 01472 324 252	TREND:	Deteriorating
DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:	Conservation Area Medium Tony Sargent (LPA) 01472 324 252  Waltham	TREND: NEW ENTRY?:	Deteriorating No
DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:	Conservation Area Medium Tony Sargent (LPA) 01472 324 252  Waltham Conservation Area	TREND: NEW ENTRY?:  CONDITION:	Deteriorating No  Very bad

#### NORTH LINCOLNSHIRE (UA)



Hibaldstow Mill and walls SITE NAME:

Combined wind and watermill, I 802, by James Middleton of Hibaldstow. Some repairs undertaken, but further work to mill pond and wheel race, required to both exterior and interior. Ings Lane, Hibaldstow

DESIGNATION: Listed Building Grade II\*, SM Fair CONDITION: Part occupied OCCUPANCY: C(C)PRIORITY: Private OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Manor Farmhouse, East Halton Road, North Killingholme

DESIGNATION: Listed Building Grade II\* CONDITION: Very bad Vacant OCCUPANCY: B (B) PRIORITY: Private OWNER TYPE:

Medieval, C17-C19 manor house on a scheduled moated site. Exceptional multi-period survival for this region. The roof was repaired in 1980, but little has been done since and the interior is propped with scaffolding. A feasibility study has been completed.

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Martin, SITE NAME: Church Street, Owston Ferry

Medieval church with early C19 north aisle. Roofs and drainage in poor condition. Grant offered.

DESIGNATION: Listed Place of Worship Grade I Poor CONDITION: PRIORITY: D (D)

> Religious organisation Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Lawrence, SITE NAME: Main Street, Thornton Curtis

Very fine medieval church with outstanding font. Roofs repaired with grant. Grant offered for repairs to tower.

DESIGNATION: Listed Place of Worship Grade I Poor CONDITION: PRIORITY: D (D) Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

OWNER TYPE:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

## **ABBREVIATIONS** CA LB LPA NP RPG SM

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Church of St Andrew, SITE NAME: High Street,

Wootton

DESIGNATION: Listed Place of Worship Grade I

Very bad CONDITION: D (D) PRIORITY:

OWNER TYPE: Religious organisation

The church dates to the C13; although both in the early English style, the north arcade is thought to be later in date than the south. The west tower is late Perpendicular, the top rebuilt in 1877. The chancel was rebuilt in 1851 when the whole building underwent a restoration and was re-roofed. A grant has been offered for repairs to the tower roof, north and south aisle masonry and stained glass.

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Heavy Anti-aircraft gunsite 220m east of We	est Marsh Cottag	e, Barrow upon Humber
DESIGNATION:	Scheduled Monument (No.1020024)	CONDITION:	Generally satisfactory but with minor localised problem
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site 285m east of Castlethorpe Hou	ıse, Broughton	
DESIGNATION:	Scheduled Monument (No.1016429)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Yarborough Camp large univallate hillfort, Ci	roxton	
DESIGNATION:	Scheduled Monument (No.1016427)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Romano-British settlement near Staniwells F	arm, Hibaldstow	
DESIGNATION:	Scheduled Monument (No.1005221)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman settlement, Kirmington		
DESIGNATION:	Scheduled Monument (No.1005206)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Romano-British villa at Mount Pleasant Farm	n, Kirton in Linds	ey
DESIGNATION:	Scheduled Monument (No.1013627)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA LB LPA NP RPG SM UA WHS Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site

SITE NAME:	Moated site and fishpond 200m south east	t of Melton Hall, M	elton Ross
DESIGNATION:	Scheduled Monument (No.1007747)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	North Garth moated site and associated e	enclosures, North I	Killingholme
DESIGNATION:	Scheduled Monument (No.1007815)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Money Field Roman site, Dragonby, North	Lincolnshire	
DESIGNATION:	Scheduled Monument (No.1005224)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Kinaird motte and bailey castle, Owston Fe	erry	
DESIGNATION:	Scheduled Monument (No.1017556)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Thornton Abbey Augustinian monastery: ga moat, fishponds, post-Dissolution college a		
DESIGNATION:	Scheduled Monument (No.1011198)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Old Winteringham Roman settlement, Win	nteringham	
DESIGNATION:	Scheduled Monument (No.1005243)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Howe Hill bowl barrow, Wootton		
DESIGNATION:	Scheduled Monument (No.1009346)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman site 400yds (370m) north east of V	Worlaby Church,W	/orlaby
DESIGNATION:	Scheduled Monument (No.1005233)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
PRIORITY (FOR BUILDINGS)  A Immediate risk of further rapid	D Slow decay; solution agreed F Repair scheme	in progress NOT	ABBREVIATIONS E: CA Conservation Area

- PRIORITY (FOR BUILDINGS)

  A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.


  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

SITE NAME:	Crowle		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	lan Goldthorpe (LPA) 01724 297 396	NEW ENTRY?:	No
SITE NAME:	Winterton		
SITE NAME: DESIGNATION:	Winterton Conservation Area	CONDITION:	Poor
		CONDITION: TREND:	Poor Deteriorating

#### **NORTH YORKSHIRE**

#### **CRAVEN**



Dale End Mills, SITE NAME: Dale End. Lothersdale

DESIGNATION: Listed Building Grade II, SM, CA Poor CONDITION: Part occupied OCCUPANCY: C(C)OWNERTYPE: Private

C19 mill, including disused waterwheel (1861), pit and enclosing building. The mill-wheel is the largest in England and is in poor condition. The mill roofs are deteriorating. The base of the stack is also in need of remedial work. Discussions are underway with the owner to find a solution to the building repair.

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Moated site west of Paget Hall, Gargrave		
DESIGNATION:	Scheduled Monument (No.1004126)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

#### HAMBLETON



SITE NAME: The Coach House, Rounton Grange, East Rounton

Listed Building Grade II\* DESIGNATION: Very bad CONDITION: OCCUPANCY: Part occupied A(A)Private OWNER TYPE:

Coach house, built in 1875. Now used as a combined home and workshop. One range is in a fair condition, the rest is in state of collapse.

Contact: Principal Heritage at Risk Adviser 01904 601901



Landmoth Hall, SITE NAME: Landmoth cum Catto

Part of the east wing of a medieval manor house. Now in an unstable condition.

**DESIGNATION: Scheduled Monument** CONDITION: Very bad N/A OCCUPANCY: B (B) PRIORITY: OWNERTYPE: Private

Contact: Principal Heritage at Risk Adviser 01904 601901



West Lodge, SITE NAME:

Thornton Stud, Newsham Road, Newsham with Breckenbrough

DESIGNATION: Listed Building Grade II\* Poor CONDITION: Vacant OCCUPANCY:

C(C)OWNERTYPE: Private Late C18 lodge and entrance gateway. Some roof repairs have been undertaken.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site



Snape Castle, SITE NAME: Snape with Thorp

DESIGNATION: Listed Building Grade I, SM, CA, RPG II Very bad CONDITION:

Part occupied OCCUPANCY: PRIORITY B (B) Private OWNER TYPE:

Castle dated to circa 1430, with additions and alterations in the C16 and C18. It is comprised of extensive ruins, including some vaulted rooms and two towers. The rear ranges are in a poor condition. The upper parts of the towers are particularly unstable. Much repointing is required elsewhere. The front ranges are divided into two dwellings.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: West Harlsey

Stables at Harlsey Castle Farmhouse, Remains of medieval castle keep; in use as farm buildings.

DESIGNATION: Listed Building Grade II\*, SM Poor CONDITION: Occupied D (D) PRIORITY: OWNERTYPE: Private

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Mary, SITE NAME: Bolton on Swale

DESIGNATION: Listed Place of Worship Grade II\*, CA Poor CONDITION: PRIORITY: OWNER TYPE: Religious organisation

A large complex church, the earliest parts probably early C14, but heavily restored in C19. The tower is thought to be mid C16, perhaps a rare product of the reign of Mary Tudor or Elizabeth. The wall paintings of angels, in the style of the Florentine Quattrocento, were carried out in 1902. They were copied from paintings by Filippino Lippi, Matteo di Giovanni and Botticelli, all in the National Gallery. Urgent, high level repairs are being grant-aided for the south aisle and chancel roofs, internal decoration and restoration of the wall paintings.

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Medieval moated grange 160m south east of The Grange, Balk			
DESIGNATION:	Scheduled Monument (No.1015920)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			01904 601901	
SITE NAME:	Birkby medieval settlement and associated	field system, moat	ed site and fishponds, Birkby	
	Birkby medieval settlement and associated  Scheduled Monument (No.1016944)	field system, moat	ed site and fishponds, Birkby  Unknown	
DESIGNATION:	,	•	, ,	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1016944)	CONDITION:	Unknown	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1016944) Localised/limited stock erosion	CONDITION: TREND:	Unknown Unknown	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1016944) Localised/limited stock erosion	CONDITION: TREND:	Unknown Unknown Principal Heritage at Risk Adviser	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1016944) Localised/limited stock erosion	CONDITION: TREND: CONTACT:	Unknown Unknown Principal Heritage at Risk Adviser	

SITE NAME:	Lime kiins 400m south west of Furlands, Bo	Lime Klins 400m south west of Furlands, Borrowby		
DESIGNATION:	Scheduled Monument (No.1021190)	CONDITION:	Unknown	
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			01904 601901	

SITE NAME:	Round barrow I50m south of Warren House, Brandsby cum Stearsby		
DESIGNATION:	Scheduled Monument (No.1013601)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site UA WHS

SITE NAME:	Round barrow 300m east of Warren Hous	e, Brandsby cum S	tearsby
DESIGNATION:	Scheduled Monument (No.1013600)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 300m west of Quarry Hous	e, Brandsby cum S	Stearsby
DESIGNATION:	Scheduled Monument (No.1013602)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 330yds (300m) south of Bar	house Farm, Bran	dsby cum Stearsby
DESIGNATION:	Scheduled Monument (No.1003659)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 450m north east of Hagg Farm, Brandsby cum Stearsby		
DESIGNATION:	Scheduled Monument (No.1013592)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Healam Bridge Roman fort and vicus, Burne	eston	
DESIGNATION:	Scheduled Monument (No.1021211)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Road construction	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site immediately south of Danby W	iske church, Dant	y Wiske with Lazenby
DESIGNATION:	Scheduled Monument (No.1020346)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Gardening	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Deighton moated site, Deighton		
DESIGNATION:	Scheduled Monument (No.1004099)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Earth circles, cursus, pit alignments and bur including Centre Hill round barrow, East Ta		erfield and Thornborough,
DESIGNATION:	Scheduled Monument (No.1004912)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Round barrow 425m north west of Rushw	ood Hall, East Tanf	ìeld
DESIGNATION:	Scheduled Monument (No.1016262)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Medieval moated site, fishponds and associ 125m south of Eldmire Cottage, Eldmire w		
DESIGNATION:	Scheduled Monument (No.1015419)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Medieval settlement of Little Broughton, associated field system and site of medieval chapel, Great and Little Broughton		
DESIGNATION:	Scheduled Monument (No.1018921)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 180m NNE of St Wilfred's C	Church, Kirby Knov	wle
DESIGNATION:	Scheduled Monument (No.1010527)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 250m north east of Comer	Lodge, Kirklingtor	n cum Upsland
DESIGNATION:	Scheduled Monument (No.1016265)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site known as The Rush, Marton co	um Moxby	
DESIGNATION:	Scheduled Monument (No.1003661)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Section of cross ridge dyke and earthwork	s in Roman Planta	tion, Oulston Moor, Oulston
DESIGNATION:	Scheduled Monument (No.1013438)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	A moated site 100m east of St Mary Magda	lene's Church,Thi	rsk
DESIGNATION:	Scheduled Monument (No.1008179)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow known as Gospel Hill, 80m	south west of Pas	ture House, Thornton Watlass
DESIGNATION:	Scheduled Monument (No.1018922)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Maiden Bower and Cock Lodge: a motte ar windmill mound and associated linear outw		pated site,
DESIGNATION:	Scheduled Monument (No.1011612)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Medieval Park Pale, Upsall Estate, Thirsk, U	osall	
DESIGNATION:	Scheduled Monument (No.1010804)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Three round barrows at Three Hills 500m	north east of Cam	np House, West Tanfield
DESIGNATION:	Scheduled Monument (No.1015764)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Four round barrows on Yearsley Moor 200	m south west of H	High Lions' Lodge,Yearsley
SITE NAME: DESIGNATION:	Four round barrows on Yearsley Moor 200 Scheduled Monument (No.1013446)	m south west of F	Generally satisfactory
	·		· ·

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Round barrow on Yearsley Moor 330m SSW of High Lions' Lodge, Yearsley		
DESIGNATION:	Scheduled Monument (No.1013448)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Round barrow on Yearsley Moor 400m south west of High Lions' Lodge, Yearsley		
DESIGNATION:	Scheduled Monument (No.1013447)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Two round barrows on Yearsley Moor 550m south west of High Lions' Lodge, Yearsley		
DESIGNATION:	Scheduled Monument (No.1013449)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

#### **HARROGATE**



Chapel of St Mary attached SITE NAME: to the mansion, Allerton Park, Allerton Mauleverer with Hopperton

DESIGNATION:	Listed Building Grade II*, RPG II
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (D)
OWNER TYPE:	Trust

Former Roman Catholic chapel, circa 1807, attached to the grade I house. The house stands on a promontory in the eastern section of the C18 park, with mid C19 terraces to the north. Much of the interior of the chapel has been stripped out for dry rot treatment. English Heritage has received an application for grant towards repair.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Coach house and bee hives approx 10 metres to north of Nutwith Cote, Grewelthorpe Road, Burton on Yore

DESIGNATION: Listed Building Grade II\* Poor CONDITION: OCCUPANCY: Part occupied A(A)Private OWNER TYPE:

Coach house with bee hives. Mid C18 and C16. The rear hall of the coach house is settling and the end return of the bee hives is failing. There are structural cracks to the right hand return and rear, and some of the copings are missing from the rear gable. Pointing is failing to cut stone on facades leaving some stone loose.

Contact: Principal Heritage at Risk Adviser 01904 601901



Outbuilding approx 20m to north SITE NAME: of Nutwith Cote, Grewelthorpe Road, Burton on Yore

DESIGNATION: Listed Building Grade II\* Fair CONDITION: Vacant OCCUPANCY: C(C)PRIORITY: OWNERTYPE: Private

Early C18 outbuilding/store. The building has been vacant for some time. Emergency re-roofing in corrugated asbestos was carried out many years ago. Building is slowly decaying, with open joints and defective rainwater goods. The corrugated asbestos roof appears to be failing at the ridge and at one of the gables.

Contact: Principal Heritage at Risk Adviser 01904 601901



Temple of Victory SITE NAME: with railed enclosure, Allerton Park, Flaxby

DESIGNATION: Listed Building Grade II\*, RPG II Fair CONDITION: Vacant OCCUPANCY: C(D)OWNERTYPE: Trust

Summerhouse or view point, I 790, situated on a knoll in the park, to NW of the house. Re-roofed, cornice repaired and building made secure over 15 years ago with grant aid from English Heritage and Harrogate Borough Council. Repairs needed to stonework below cornice level and to steps and railings, and interior needs re-instating. Extensive views from the Temple over the park and surrounding landscape.


Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

### **ABBREVIATIONS** CA LB LPA NP RPG SM Conservation Area



SITE NAME:	Church of St Mary,
	Harlow Terrace,
	Harrogate

DESIGNATION: Listed Building Grade II\*, CA

Poor CONDITION: Vacant OCCUPANCY:

F (F) Company OWNER TYPE:

Former church built circa 1916 by Sir Walter Tapper. Deterioration of the stone has occurred from an early date. There is evidence that the mineral felt to the aisle roofs is leaking. It is now proposed to convert the church into a luxury day spa, with minimal internal subdivision. English Heritage have offered grant towards project development.

Contact: Principal Heritage at Risk Adviser 01904 601901



The Old Hall, SITE NAME: Middleton Ouernhow

Gable wall and part of the south wall of an early C17 house. Many open joints are visible and part of chimney stack appears to be unstable.

DESIGNATION: Listed Building Grade II, SM Poor CONDITION: N/A C(C)PRIORITY:

Contact: Principal Heritage at Risk Adviser 01904 601901



Orangery with flanking walls, SITE NAME: botheys and pavilion (Ripley Castle), Ripley

Listed Building Grade II\*, CA, RPG II DESIGNATION: CONDITION: Poor

Part occupied OCCUPANCY: PRIORITY: C(C)

Private OWNER TYPE:

OWNERTYPE: Private

Classical Orangery in walled garden with flanking pavilions, circa 1785 by William Belwood. One surviving glasshouse circa 1840, now repaired. Botheys, in poor condition, to rear. East Pavilion recently repaired and some emergency repairs to Orangery. The balustrade has been dismantled and the cornice has been temporarily supported to prevent collapse.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Butterton Bridge, Sawley

Scheduled Monument DESIGNATION: CONDITION: Poor

C(C)PRIORITY-Company OWNER TYPE:

Medieval bridge, now crossed by a public footpath. The structure is overgrown and decaying and there is danger of structural collapse. English Heritage grant offered but not accepted by owner.

Contact: Principal Heritage at Risk Adviser 01904 601901



Dob Park Lodge, SITE NAME: Dob Park Lane,

N/A

Weston

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad N/A OCCUPANCY: D (D) PRIORITY-

OWNERTYPE: Private

Ruins of a C17 park lodge, now roofless structure three storeys high. Scheduled as an Ancient Monument in 1997. English Heritage grant has been offered for consolidation.

Contact: Principal Heritage at Risk Adviser 01904 601901



Cairnfield, enclosures, boulder walling, hollow way and carved rocks

towards edge of Snowden Carr centred at 370m south east of Crag House, Askwith

Scheduled Monument (No.1014304) Generally satisfactory CONDITION: but with significant localised problems

Plant growth TREND:

PRINCIPAL VULNERABILITY: Private Principal Heritage at Risk Adviser OWNER TYPE: CONTACT:

01904 601901

CITE	N.I	٨	М	-

SITE NAME:

DESIGNATION

#### Rock with complex carving south west of a wall junction, 265m SSW of Far High Westcliff, Bewerley

DESIGNATION:	Scheduled Monument (No.1014969)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets

**ABBREVIATIONS** CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Stone alignment west of Boroughbridge known as the Devil's Arrows, including three standing stones and the setting for a fourth, Boroughbridge			
DESIGNATION:	Scheduled Monument (No.1014705)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Henge monument 300m north of Nunwick	, Hutton Conyers		
DESIGNATION:	Scheduled Monument (No.1012724)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Hutton Hall (site of), Hutton Conyers			
DESIGNATION:	Scheduled Monument (No.1004074)	CONDITION:	Generally satisfactory	
			but with minor localised problems	
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow I50m east of Burtree Hill, Hutton Conyers			
DESIGNATION:	Scheduled Monument (No.1013396)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 300m WNW of Low Barn, I	Hutton Conyers		
DESIGNATION:	Scheduled Monument (No.1013395)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow at Moor House, Hutton Co	nyers		
DESIGNATION:	Scheduled Monument (No.1009784)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow in Harland's Plantation, Hut	ton Conyers		
DESIGNATION:	Scheduled Monument (No.1009785)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Motte and bailey castle, known as Mowbra	y Castle, east of K	irkby Malzeard, Kirkby Malzeard	
DESIGNATION:	Scheduled Monument (No.1012994)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			01904 601901	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

SITE NAME:	Rougemont Castle ringwork and bailey and	d associated fishpo	nds and outwork, Kirkby Overblow	
DESIGNATION:	Scheduled Monument (No.1010026)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Medieval monastic fishponds immediately e	Medieval monastic fishponds immediately east of Park House, Markington with Wallerthwaite		
DESIGNATION:	Scheduled Monument (No.1018691)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Moated site 50m north west of Red House, Moor Monkton			
DESIGNATION:	Scheduled Monument (No.1020887)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Moated site 50m north east of North Rigt	on School, North	Rigton	
DESIGNATION:	Scheduled Monument (No.1017716)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Cairn 7m in diameter north of track east of 450m WNW of Weston Moor Cottage, W		eston Moor	
DESIGNATION:	Scheduled Monument (No.1014314)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	



	with Hopperton/Flaxby
DESIGNATION:	Registered Park and Garden Grade II,
	also 19 LBs
CONDITION:	Generally unsatisfactory
	with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
OWNER TYPE:	Private, multiple owners

Allerton Park, Allerton Mauleverer

Mid C19 terraced gardens which provide the setting for a country house, surrounded by parkland which was enlarged in the I720s and reworked in the I770s. C20 woodland planting has significantly changed the character of the historic landscape and a number of listed structures are in poor condition.





SITE NAME: Plumpton Rocks, Plompton

DESIGNATION: Registered Park and Garden Grade II\*, also CA, I3 LBs

CONDITION: Generally satisfactory but with significant localised problems

VULNERABILITY: Medium

TREND: Declining

OWNERTYPE: Private, single owner

Mid C18 pleasure grounds laid out with advice from John Carr as the grounds for a country house built within a pre-existing park of C16 origin. Painted by JMW Turner in 1798. Landscape designed around an artificial lake contained by dam, probably designed by John Carr. Lake surrounded by picturesque sandstone outcrops frequently surmounted by trees. Progressive silting of lake and regeneration of trees and shrubs is severely compromising the historic views within the site and the relationships of planting, rocks and lake.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA Conser LB Listed E LPA Local P NP Nationa RPG Registe SM Schedu



SITE NAME:	Swinton	Castle,
	Swinton	with Warthermarske

DESIGNATION: Registered Park and Garden Grade II\*, also 7 LBs

Generally satisfactory CONDITION:

but with significant localised problems

VULNERABILITY: Medium Declining TREND:

Private, single owner OWNER TYPE:

Gardens and extensive pleasure grounds with grottos, rustic bridges and rockwork laid out from 1796 to c1820 under the direction of Adam Mickle the second and others for Sir William Danby, incorporating lakes and landscaping of c1760. The park probably has C17 or earlier origins. Significant proportion of the tree cover has reached maturity and beyond, some structures in poor condition and water bodies in Quarry Gill woods heavily silted.

Contact: Principal Heritage at Risk Adviser 01904 601901



Battle of Boroughbridge, SITE NAME: Boroughbridge/Langthorpe/Milby

DESIGNATION: Registered Battlefield Generally satisfactory


but with significant localised problems

VULNERABILITY: Medium Declining OWNER TYPE: Private

Thomas Earl of Lancaster's I 322 revolt against Edward II ended with defeat as his army attempted to retreat north and cross the River Ure. Much of the battlefield lies under modern Boroughbridge; further expansion is possible north

Contact: Principal Heritage at Risk Adviser 01904 601901

#### NORTH YORK MOORS (NP)



SITE NAME: Castle Bank, Whorlton,

Hambleton

DESIGNATION: Listed Building Grade II\*, SM, CA CONDITION: Poor

N/A OCCUPANCY: PRIORITY: D (D) OWNERTYPE: Private

Ruins of Whorlton Castle Undercroft, C14 castle. Parts of two vaulted chambers remain. Conservation plan complete. Options appraisal in progress.

Contact: Principal Heritage at Risk Adviser 01904 601901



Whorlton Castle Gatehouse, SITE NAME: Castle Bank, Whorlton,

Hambleton

DESIGNATION: Listed Building Grade I, SM, CA

Fair CONDITION: N/A OCCUPANCY: D (D) PRIORITY:

OWNERTYPE: Private

Shell remains of a late C14 gatehouse, which was altered in the C16. Conservation plan complete. Possible conversion to holiday accommodation being considered and English Heritage grant has been offered towards project development.

Contact: Principal Heritage at Risk Adviser 01904 601901



Ionic Temple, SITE NAME:

> Duncombe Park Estate, Helmsley, Ryedale

Listed Building Grade I, RPG DESIGNATION:

N/A OCCUPANCY: D(D)PRIORITY-Private OWNER TYPE:

Decorative temple, circa 1730, attributed to Vanbrugh, situated at the north end of the approximately 800m long, grass East Terrace, approximately 120m east of the house. The column shafts are badly decayed. The trial repair of one column is complete. The possibility of full repair is under discussion.

Contact: Principal Heritage at Risk Adviser 01904 601901



Tuscan Temple, SITE NAME:

Duncombe Park Estate, Helmsley, Ryedale

DESIGNATION: Listed Building Grade I, RPG

CONDITION: Poor N/A D(D)PRIORITY Private OWNER TYPE:

Decorative temple circa 1730 in the Palladian style situated at the south end of the East Terrace. The column shafts are badly decayed and internal plasterwork falling.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

NOTE: 2011 priority categories are given in brackets

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Ayton Castle, SITE NAME: Castle Rise, West Ayton, Scarborough

DESIGNATION: Listed Building Grade I, SM

Poor CONDITION: OCCUPANCY: N/A C (C) PRIORITY:

OWNERTYPE: Local authority

Pele tower, late C14. The upper storeys are ruinous, but the undercroft still has a vaulted roof. Subject to weathering. The site has been the subject of a detailed condition survey. Conservation plan completed but no further progress.

Contact: Principal Heritage at Risk Adviser 01904 601901

	owner type: Local authority	Contact: Pr	incipal Heritage at Risk Adviser 01904 6019
SITE NAME:	Oxmoor and Givendale Dikes: prehistoric	linear boundaries	and associated features, Allerston, Ryedale
DESIGNATION:	Scheduled Monument (No.1020834)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows on Low Common, Appleton-le-Moors, Ryedale		
DESIGNATION:	Scheduled Monument (No.1003660)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Beadlam Rigg, 490m wes	st of Stone Ruckle	s round barrow, Beadlam, Ryedale
DESIGNATION:	Scheduled Monument (No.1019516)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Group of round barrows on Bilsdale Moor Bilsdale Midcable, Hambleton	· 1/2 mile (800m) r	orth west of Fangdale Beck,
DESIGNATION:	Scheduled Monument (No.1004148)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 550m east of Cam House, I	Bilsdale Midcable, I	Hambleton
DESIGNATION:	Scheduled Monument (No.1012488)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Pit alignment forming part of the Cleave D 1000m north west of Dialstone Farm, Boltl		
DESIGNATION:	Scheduled Monument (No.1010345)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Pit alignment, part of the Cleave Dyke preb 450m south east of High Paradise, Boltby, F		system and round barrow
DESIGNATION:	Scheduled Monument (No.1015576)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
TE NAME:	Ravensthorpe manor house (site of), Boltby	, Hambleton	
DESIGNATION:	Scheduled Monument (No.1004083)	CONDITION:	Generally satisfactory
			but with minor localised problems
RINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Stable
WNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
TE NAME:	Round barrow 400m south east of Hill For	t Windypit, Boltby	, Hambleton
ESIGNIATION!	Scheduled Monument (No.1010341)	CONDITION:	Extensive significant problems
ESIGNATION: RINCIPAL VULNERABILITY:	Arable ploughing	CONDITION: TREND:	Declining
WNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
VVINER TIPE.	Tivate	CONTACT.	01904 601901
ITE NAME:	Round barrow 500m south east of Hill For	t Windypit, Boltby	, Hambleton
DESIGNATION:	Scheduled Monument (No.1010342)	CONDITION:	Generally satisfactory
	Amble clipping	TOTALD	but with significant localised problems  Declining
RINCIPAL VULNERABILITY:	Arable clipping Private	TREND:	Principal Heritage at Risk Adviser
wner type:	Hivate	CONTACT:	01904 601901
SITE NAME:	Round barrow 600m north east of South V	Voods, Boltby, Har	nbleton
DESIGNATION:	Scheduled Monument (No.1013085)	CONDITION:	Generally satisfactory but with significant localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
	····ace	00.1.7.6.1	01904 601901
ITE NAME:	Round barrow 650m east of South Woods,	Boltby, Hambleto	n
ESIGNATION:	Scheduled Monument (No.1010343)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNERTYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
ITE NAME:	Section of Cleave Dyke, I.4km long from Sr		
	including two pit alignments and round bar	•	
esignation:	Scheduled Monument (No.1012746)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
ITE NAME:	Section of the Cleave Dyke system known	as Hesketh Dike a	and Silver Hill round barrow, Boltby, Hambl
DESIGNATION:	Scheduled Monument (No.1015575)	CONDITION:	Generally satisfactory
			but with significant localised problems
RINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
WNERTYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
IORITY (FOR BUILDINGS)			ABBREVIATIONS

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

SITE NAME:	Section of the Cleave Dyke system on Ard including the Steeple Cross boundary ston		
DESIGNATION:	Scheduled Monument (No.1010533)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows at Seta Pike, Boltby, Ha	ambleton	
DESIGNATION:	Scheduled Monument (No.1008580)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Late prehistoric enclosed settlement and fi 360m south of Moor House Farm, Borrow		rowby Moor,
DESIGNATION:	Scheduled Monument (No.1016957)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow at Crook Staff Hill, Bransda	le, Ryedale	
DESIGNATION:	Scheduled Monument (No.1009360)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow in Wykeham Forest, 440m e	east of Jenny Thrus	h Spring, Brompton, Scarborough
DESIGNATION:	Scheduled Monument (No.1019356)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 350m west of Green Bank,	Carlton, Hambleto	on
DESIGNATION:	Scheduled Monument (No.1008856)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 150m south of Thirley Beck	Farm, Cloughton,	Scarborough
DESIGNATION:	Scheduled Monument (No.1019774)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow known as Hunter Howe, Cl	oughton, Scarbord	ough
DESIGNATION:	Scheduled Monument (No.1019770)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 410m south of Keldy Banks	, Cropton, Ryedale	2
DESIGNATION:	Scheduled Monument (No.1017832)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Maw Rigg, I.6km south v Darncombe cum Langdale End, Scarboroug		dale End,
DESIGNATION:	Scheduled Monument (No.1019970)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 520m north west of Keeper	rs Cottage, East A	yton, Scarborough
designation:	Scheduled Monument (No.1008482)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow in Raincliffe Woods, 420m n	orth of Osborne	Lodge, East Ayton, Scarborough
designation:	Scheduled Monument (No.1021235)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Skell Dikes: a prehistoric linear boundary w and an adjoining pit alignment, East Ayton, S		d round barrows
DESIGNATION:	Scheduled Monument (No.1021238)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow at Blanket Head, 350m nort	th west of Broad I	Head Farm, Ebberston and Yedingham, Ryed
DESIGNATION:	Scheduled Monument (No.1020698)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Scamridge Dikes: prehistoric linear bounda	ries and associated	d features, Ebberston and Yedingham, Ryed
DESIGNATION:	Scheduled Monument (No.1020835)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows east of Coopers Quar	ries, Egton, Scarbo	rough
DESIGNATION:	Scheduled Monument (No.1004158)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow in Newton Mulgrave Woods	s, 740m south of N	Newton Brow, Ellerby, Scarborough
DESIGNATION:	Scheduled Monument (No.1016571)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	'Greenlands Howe' round barrow, Sleights	Moor, Eskdaleside	cum Ugglebarnby, Scarborough
DESIGNATION:	Scheduled Monument (No.1004890)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Group of seventeen tumuli to the north of Greenlands Howe, on the east side of Sleights Moor, Eskdaleside cum Ugglebarnby, Scarborough		
DESIGNATION:	Scheduled Monument (No.1004891)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	High Bride Stones, Eskdaleside cum Uggleb	arnby, Scarboroug	h
DESIGNATION:	Scheduled Monument (No.1004892)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 300m south east of Faceby	Plantation, Faceby,	Hambleton
DESIGNATION:	Scheduled Monument (No.1012731)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Blakey Howe round barrow, Farndale East,	Ryedale	
DESIGNATION:	Scheduled Monument (No.1018983)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Pike Howe round cairn, Farndale East, Ryec	dale	
DESIGNATION:	Scheduled Monument (No.1018986)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow in north corner of a field 205 Fylingdales, Scarborough	om south of the St	anding Stones on Standing Stones Rigg,
DESIGNATION:	Scheduled Monument (No.1011965)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Fyling medieval deer park wall section, Fylin	ngdales, Scarborou	gh
DESIGNATION:	Scheduled Monument (No.1015542)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Linear earthwork south east of the junctio Fylingdales, Scarborough	n of the A171 and	the road leading to Fylingthorpe,
DESIGNATION:	Scheduled Monument (No.1011971)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Linear earthwork to the north west of the Fylingdales, Scarborough	junction of the A	171 and the road leading to Fylingthorpe,
DESIGNATION:	Scheduled Monument (No.1011961)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Medieval dyke known as Green Dike, Fyling	gdales, Scarboroug	h
DESIGNATION:	Scheduled Monument (No.1020116)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Round barrow 510m north east of Cook F	louse, Fylingdales,	Scarborough
DESIGNATION:	Scheduled Monument (No.1019698)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 580m north east of Howda	le Farm, Fylingdale	s, Scarborough
DESIGNATION:	Scheduled Monument (No.1019705)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 720m north east of Cook F	House, Fylingdales,	Scarborough
DESIGNATION:	Scheduled Monument (No.1019699)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Site of Stoupe Brow alum works, 210m sou	ıth east of Stoupe	Bank Farm, Fylingdales, Scarborough
DESIGNATION:	Scheduled Monument (No.1018145)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	The Latter Gate Hills tumuli; the northern 200m ESE from the junction of the A171 a		g to Fylingthorpe, Fylingdales, Scarborougl
DESIGNATION:	Scheduled Monument (No.1011973)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Allan Tofts cairnfield, field system, burial cai immediately south of Morton Close, Goath		
DESIGNATION:	Scheduled Monument (No.1021301)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 200m south of Green Bank,	, Great Busby, Han	nbleton
DESIGNATION:	Scheduled Monument (No.1008854)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow in Springwood Heights Plan 220m north west of Springwood Cottage, I		ough
DESIGNATION:	Scheduled Monument (No.1019620)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Shunner Howe round barrow, Hartoft, Rye	dale	
DESIGNATION:	Scheduled Monument (No.1018763)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow in Harwood Dale Forest kn	own as Penny Ho	we, Harwood Dale, Scarborough
DESIGNATION:	Scheduled Monument (No.1019678)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round cairn on Cowgate Rigg, 790m south	west of Teydale F	arm, Harwood Dale, Scarborough
DESIGNATION:	Scheduled Monument (No.1020226)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round cairn on Cowgate Rigg, 870m north	of Brooklands Fa	rm, Harwood Dale, Scarborough
DESIGNATION:	Scheduled Monument (No.1019769)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Cairnfield 200m east of Hazelshaw House,	Hawnby, Ryedale	
DESIGNATION:	Scheduled Monument (No.1008860)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Cairnfield 500m north east of Bumper Cas	tle, Hawnby, Ryed	ale
DESIGNATION:	Scheduled Monument (No.1009358)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA LB LPA NP RPG SM UA WHS

SITE NAME:	Round barrow IIm east of Hazel Head Wo	ood, Hawnby, Ryed	ale
DESIGNATION:	Scheduled Monument (No.1008585)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow I50m north east of Silver H	ill Farm, Hawnby,	Ryedale
DESIGNATION:	Scheduled Monument (No.1016052)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 500m east of Silver Hill Fari	m, Hawnby, Ryedal	e
DESIGNATION:	Scheduled Monument (No.1016066)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 500m north west of Lower	Locker Farm, Hav	vnby, Ryedale
DESIGNATION:	Scheduled Monument (No.1009371)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 550m south east of High Co	ote Farm, Hawnby	, Ryedale
DESIGNATION:	Scheduled Monument (No.1013223)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows at Sour Milk Hills, Haw	vnby, Ryedale	
DESIGNATION:	Scheduled Monument (No.1008442)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site at Low Laithes Farm, Whitby L	aithes, Hawsker c	um Stainsacre, Scarborough
DESIGNATION:	Scheduled Monument (No.1020402)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
			01701 001701

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	Saltwick Nab alum quarries, Hawsker cum	Stainsacre, Scarbo	rough
designation:	Scheduled Monument (No.1017779)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow and 20th century Royal Obs		
DESIGNATION:	Scheduled Monument (No.1016956)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow immediately south of Californ	rnia Belt, I 90m eas	st of Fox Head, Hutton Buscel, Scarborou
DESIGNATION:	Scheduled Monument (No.1017158)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow in School Belt, 1050m north	west of Jenny Spr	ring, Hutton Buscel, Scarborough
DESIGNATION:	Scheduled Monument (No.1017167)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	The Moor Dikes and Craddlegrip Dike prel		
DESIGNATION:	Scheduled Monument (No.1017164)	CONDITION:	Generally unsatisfactory with major localised problems
	Scheduled Monument (No.1017164)  Plant growth	CONDITION: TREND:	· · · · · · · · · · · · · · · · · · ·
PRINCIPAL VULNERABILITY:	, ,		with major localised problems
PRINCIPAL VULNERABILITY: OWNER TYPE:	Plant growth	trend: Contact:	with major localised problems Stable Principal Heritage at Risk Adviser 01904 601901
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Plant growth Private	trend: Contact:	with major localised problems Stable Principal Heritage at Risk Adviser 01904 601901
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Plant growth Private  Round barrow at Lady Cross, 730m south v	TREND: CONTACT: west of Dun Bogs	with major localised problems Stable Principal Heritage at Risk Adviser 01904 601901  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Plant growth Private  Round barrow at Lady Cross, 730m south of Scheduled Monument (No.1019076)	TREND: CONTACT:  west of Dun Bogs  CONDITION:	with major localised problems Stable Principal Heritage at Risk Adviser 01904 601901  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Plant growth Private  Round barrow at Lady Cross, 730m south of Scheduled Monument (No.1019076)  Arable clipping	TREND: CONTACT:  west of Dun Bogs CONDITION:  TREND: CONTACT:	with major localised problems Stable Principal Heritage at Risk Adviser 01904 601901  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Plant growth Private  Round barrow at Lady Cross, 730m south of Scheduled Monument (No.1019076)  Arable clipping Private	TREND: CONTACT:  west of Dun Bogs CONDITION:  TREND: CONTACT:	with major localised problems Stable Principal Heritage at Risk Adviser 01904 601901  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser
PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Plant growth Private  Round barrow at Lady Cross, 730m south of Scheduled Monument (No.1019076)  Arable clipping Private  Douthwaite pillow mounds, Hutton-le-Hole	TREND: CONTACT:  west of Dun Bogs CONDITION:  TREND: CONTACT:	with major localised problems Stable Principal Heritage at Risk Adviser 01904 601901  Hutton Mulgrave, Scarborough Generally satisfactory but with significant localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Generally unsatisfactory

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Four round barrows one 400m and three !	one 400m and three 540m east of Grouse Hall, Hutton-le-Hole, Ryedale		
DESIGNATION:	Scheduled Monument (No.1016023)	CONDITION:	Generally unsatisfactory with major localised problems	
RINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two round barrows, 245m and 340m north	n west of Barmooi	r Lodge, Hutton-le-Hole, Ryedale	
DESIGNATION:	Scheduled Monument (No.1016022)	CONDITION:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow I 200m north west of Beaco	on Farm, Irton, Sca	rborough	
DESIGNATION:	Scheduled Monument (No.1008501)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown	
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 1350m north west of Beaco	on Farm, Irton, Sca	rborough	
DESIGNATION:	Scheduled Monument (No.1008499)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 480m east of Yorkshire Glic	ling Club, Kilburn I	High and Low, Hambleton	
DESIGNATION:	Scheduled Monument (No.1014564)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Three medieval pillow mounds 900m north	n of Grove House,	Levisham, Ryedale	
DESIGNATION:	Scheduled Monument (No.1020685)	CONDITION:	Generally satisfactory but with minor localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Ayton Banks alum works, Little Ayton, Han	nbleton		
DESIGNATION:	Scheduled Monument (No.1020347)	CONDITION:	Generally unsatisfactory	
			with major localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Cross dyke centred 480m south of Fox an	d Rabbit Farm, Loc	ckton, Ryedale	
DESIGNATION:	Scheduled Monument (No.1021170)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

Plant growth Local authority contract  Prehistoric dyke known as Horcum Dike, Lockton, Ryedale  Presonation  Scheduled Monument (No. 1020117) common  Generally satisfactory but with significant localised problem  presonation  Extensive visitor erosion  Local authority contract  Round barrow 400m north east of Low Pasture Farm, Lockton, Ryedale  Declining  Declining  Declining  Declining  Declining  Declining  Declining  Private  Round barrow 400m north east of Low Pasture Farm, Lockton, Ryedale  Declining  Declining  Private  Declining  TRINGD  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  Declining  Private  Round barrow 01001098)  CONDITION  Generally unstatisfactory but with significant problem  Declining  Private  CONDITION  Round Barrow 01001018149  CONDITION  Round 1001018149  CONDI	SITE NAME:	Field system and cairnfield on Lockton High	h Moor, Ikm NNE	of Needle Point, Lockton, Ryedale
Plant growth Local authority  Prehistoric dyke known as Horcum Dike, Lockton, Ryedale DESONATION  Scheduled Monument (No.1020117)  CONTRACT  Principal Heritage at Risk Adviser 01904-601901  Scheduled Monument (No.1020117)  CONTRACT  CONTRACT  CONTRACT  Principal Heritage at Risk Adviser 01904-601901  TINNA  Declining  Declining  CONTRACT  Principal Heritage at Risk Adviser 01904-601901  DESONATION  Scheduled Monument (No.1021097)  CONTRACT  Principal Heritage at Risk Adviser 01904-601901  DECLINING  CONTRACT  Principal Heritage at Risk Adviser 01904-601901  DECLINING  DECLINING  DECLINING  TREAD  Declining  Private  CONTRACT  Principal Heritage at Risk Adviser 01904-601901  DECLINING  DECLINING  DECLINING  DECLINING  DECLINING  CONTRACT  Principal Heritage at Risk Adviser 01904-601901  DECLINING  DECLIN	DESIGNATION:	Scheduled Monument (No.1021234)	CONDITION:	Generally satisfactory but with significant localised problems
Prehistoric dyke known as Horcum Dike, Lockton, Ryedale  DESCRIPTION  Scheduled Monument (No.1020117)  CONTROL  DESCRIPTION  Extensive visitor erosion  Declining  Declining  THEND  Declining  Private  Round barrow 400m north east of Low Pasture Farm, Lockton, Ryedale  DESCRIPTION  Scheduled Monument (No.1021097)  CONTROL  THEND  THEND  Declining  THEND  Declining  Private  THEND  Declining  Private  Declining  Private  Declining  THEND  Declining  THEND  Declining  THEND  Declining  Private  Declining  THEND  Declining  Private  Declining  Private  Declining  THEND  Declining  Private  Declining  Private  Declining  Private  Declining  THEND  Declining  Private  Declining  Private  Declining  Private  Declining  Declining  Declining  Private  Declining  Decli	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	·
Scheduled Monument (No.1020117)  Scheduled Monument (No.1020117)  Scheduled Monument (No.1020117)  Scheduled Monument (No.1020117)  Scheduled Monument (No.1021097)  Scheduled Monument (No.1021098)  Scheduled Monument (No.1018144)  Scheduled Monument (No.1018144)  Scheduled Monument (No.1018149)  Scheduled Monument (No.1018539)  CONTRACT  Principal Heritage at Risk Adviser (1904 601901)  Scheduled Monument (No.1016539)  CONTRACT  Principal Heritage at Risk Adviser (1904 601901)  Scheduled Monument (No.1016538)  Scheduled Mo	OWNER TYPE:	Local authority	CONTACT:	
but with significant localised problem mencemulations and process of the process	SITE NAME:	Prehistoric dyke known as Horcum Dike, L	ockton, Ryedale	
OWNER TYPE  Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow 400m north east of Low Pasture Farm, Lockton, Ryedale  DESCRAPTION: Scheduled Monument (No.1021097)  CONTACT: Principal Heritage at Risk Adviser 01904 601901  RINCIPAL VALUERMARLITY: ON 140 601901  RINCIPAL VALUERMARLITY: A rable ploughing TRAND  CONTACT: Principal Heritage at Risk Adviser 01904 601901  RINCIPAL VALUERMARLITY: A rable ploughing TRAND  CONTACT: Principal Heritage at Risk Adviser 01904 601901  CONTACT: Principal Heritage at Risk Adviser 01904 601901  RINCIPAL VALUERMARLITY: Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Alum works at Kettleness, Lythe, Scarborough  Scheduled Monument (No.1018144)  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: CONTACT: Private  CONTACT: Private  CONTACT: Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  CONTACT: Private CONTACT: Private Private Private CONTACT: Private Private Stream Adviser 01904 601901  STENAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough CONNERTYRE Private	DESIGNATION:	Scheduled Monument (No.1020117)	CONDITION:	Generally satisfactory but with significant localised problems
Round barrow 400m north east of Low Pasture Farm, Lockton, Ryedale  BESCHARION: Scheduled Monument (No.1021097) CONDITION: Extensive significant problems  PRINCIPLE Private CONTACT: Principal Heritage at Risk Adviser 01904-601901  STEINAME: Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  DESCHARION: Scheduled Monument (No.1021098) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPLE Private CONTACT: Principal Heritage at Risk Adviser 01904-601901  STEINAME: Alum works at Kettleness, Lythe, Scarborough  DESCHARION: Scheduled Monument (No.1018144) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPLE UNIVERSABILITY: Coastal erosion TREND: Declining  Develoning  Develonin	PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
Scheduled Monument (No.1021097)  Scheduled Monument (No.1021097)  Arable ploughing  THEND: Declining  OWNERTIYE  Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  DESCHARGE  Scheduled Monument (No.1021098)  Scheduled Monument (No.1021098)  Scheduled Monument (No.1021098)  CONDITION: Generally unsatisfactory with major localised problems  PRINCEPA VALINERABILITY: OWNERTIYE  Arable ploughing  THEND: Declining  THEND: Declining  THEND: Declining  OWNERTIYE  Alum works at Kettleness, Lythe, Scarborough  DESCHARGE  Scheduled Monument (No.1018144)  CONDITION: Generally satisfactory but with significant localised problems  PRINCEPA VALINERABILITY: OWNERTIYE  Arable ploughing  THEND: Declining  OWNERTIYE  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEINAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESCHARGE: DESCHARGE: Arable ploughing  THEND: DEClining  OWNERTIYE  Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESCHARGE: Principal Heritage at Risk Adviser 01904 601901  THEND: DESCHARGE: Principal Heritage at Risk Adviser 01904 601901  STEINAME: ROUND BARROW: Arable ploughing  THEND: DEClining  THEND: DEClining  CONTACT: Principal Heritage at Risk Adviser 01904 601901  THEND: DESCHARGE: Principal Heritage at Risk Adviser 01904 601901  STEINAME: ROUND BARROW:	OWNER TYPE:	Local authority	CONTACT:	
Arable ploughing TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  ROUNDERFORM: Scheduled Monument (No.1021098) CONDITION: Generally unsatisfactory with major localised problems Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Arable ploughing TREND: Declining Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Alum works at Kettleness, Lythe, Scarborough  DESGNATION: Scheduled Monument (No.1018144) CONDITION: Generally satisfactory but with significant localised problems on the private CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  REND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901	SITE NAME:	Round barrow 400m north east of Low Pas	sture Farm, Lockto	on, Ryedale
Private Contract: Principal Heritage at Risk Adviser 01904 601901  SITE NAME Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  DESIGNATION: Scheduled Monument (No.1021098) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTHYPE: Private CONTRACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Alum works at Kettleness, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1018144) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion TREND: Declining  OWNERTHYPE: Private CONTRACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTHYPE: Private CONTRACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONTRACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  Declining OWNERTHYPE: Private CONTRACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  Declining OWNERTHYPE: Private CONTRACT: Principal Heritage at Risk Adviser 01904 601901	DESIGNATION:	Scheduled Monument (No.1021097)	CONDITION:	Extensive significant problems
Round barrow 430m north west of Crossdale Head, Lockton, Ryedale  DESIGNATION:  Scheduled Monument (No.1021098)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABLITY:  Arable ploughing  TREND  DECIlining  OWNERTYPE:  Private  Alum works at Kettleness, Lythe, Scarborough  DESIGNATION:  Scheduled Monument (No.1018144)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABLITY:  COastal erosion  TREND  Declining  OWNERTYPE:  Private  Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION:  Scheduled Monument (No.1016539)  CONDITION:  Generally satisfactory but with significant localised problems  Principal Heritage at Risk Adviser  01904 601901  STERNAME:  Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION:  Scheduled Monument (No.1016539)  CONDITION:  Generally satisfactory but with significant localised problems  DESIGNATION:  Scheduled Monument (No.1016539)  CONDITION:  Generally satisfactory but with significant localised problems  DESIGNATION:  Scheduled Monument (No.1016539)  TREND:  Declining  OWNERTYPE:  Private  Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION:  Scheduled Monument (No.1016538)  CONDITION:  Extensive significant problems  DESIGNATION:  Private  Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION:  Private  Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION:  Private  Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION:  Private  Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION:  Private CONTROCT:	PRINCIPAL VULNERABILITY:		TREND:	
DESIGNATION: Scheduled Monument (No.1021098)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABLITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Alum works at Kettleness, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1018144) CONDITION: Generally satisfactory but with significant localised problem: PRINCIPAL VULNERABLITY: Coastal erosion TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problem: PRINCIPAL VULNERABLITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABLITY: Arable clipping TREND: Declining  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABLITY: Arable clipping TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	, ,
With major localised problems  PRINCIPAL VULNERABLITY: Arable ploughing  OWNERTYPE  Private  Private  Alum works at Kettleness, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1018144)  CONTACT: Principal Heritage at Risk Adviser 01904 601901  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABLITY: Coastal erosion  TREND: Declining  OWNERTYPE  Private  Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016539)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABLITY: ORDER TO BE CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538)  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABLITY: Arable clipping  TREND: Declining  OWNERTYPE: Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VULNERABLITY: Arable clipping  TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow 430m north west of Crossd	ale Head, Locktor	ı, Ryedale
OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Alum works at Kettleness, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1018144) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Coastal erosion TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1021098)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Alum works at Kettleness, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1018144) CONDITION: Generally satisfactory but with significant localised problems.  PRINCIPAL VULNERABILITY: Coastal erosion TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problems.  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	8
DESIGNATION:  Scheduled Monument (No.1018144)  CONDITION:  Generally satisfactory but with significant localised problems Declining  OWNERTYPE:  Private  Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION:  Scheduled Monument (No.1016539)  CONDITION:  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY:  Arable ploughing  TREND:  Declining  OWNERTYPE:  Private  Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION:  Scheduled Monument (No.1016538)  DESIGNATION:  Scheduled Monument (No.1016538)  DESIGNATION:  Scheduled Monument (No.1016538)  CONDITION:  Extensive significant problems PRINCIPAL VULNERABILITY:  Arable clipping  TREND:  Declining  OWNERTYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser  Declining  OWNERTYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	, ,
Declining OWNERTYPE Private Private Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough DESIGNATION: Scheduled Monument (No.1016539) CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problem: PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough DESIGNATION: SCHEduled Monument (No.1016538) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining OWNERTYPE Private	SITE NAME:	Alum works at Kettleness, Lythe, Scarborou	ıgh	
OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problem: PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1018144)	CONDITION:	Generally satisfactory but with significant localised problems
Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problems:  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	9
DESIGNATION: Scheduled Monument (No.1016539) CONDITION: Generally satisfactory but with significant localised problems.  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	,
but with significant localised problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow on Brockrigg, 400m east of	Brockrigg Farm, Ly	rthe, Scarborough
OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1016539)	CONDITION:	Generally satisfactory but with significant localised problems
Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough  DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	9
DESIGNATION: Scheduled Monument (No.1016538) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable clipping TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
PRINCIPAL VULNERABILITY: Arable clipping trend: Declining  OWNER TYPE: CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough		
PRINCIPAL VULNERABILITY: Arable clipping trend: Declining  OWNER TYPE: CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1016538)	CONDITION:	Extensive significant problems
	PRINCIPAL VULNERABILITY:		TREND:	
	OWNER TYPE:	Private	CONTACT:	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Potato Nab round barrow 1020m south we	est of Penny Holm	e, Nawton, Ryedale
DESIGNATION:	Scheduled Monument (No.1019592)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Dunsley Moor, 160m wes	st of Skelder Cott	age, Newholm cum Dunsley, Scarborough
DESIGNATION:	Scheduled Monument (No.1016534)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Rawcliffe Howe round barrow, Newton, Ry	edale	
DESIGNATION:	Scheduled Monument (No.1019776)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Newton Mulgrave medieval settlement, Newton Mulgrave, Scarborough		
DESIGNATION:	Scheduled Monument (No.1016958)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 330m south west of Newto	n Brow, Newton I	Mulgrave, Scarborough
DESIGNATION:	Scheduled Monument (No.1016961)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 350m south of Long Plain Farm, Old Byland and Scawton, Ryedale		
DESIGNATION:	Scheduled Monument (No.1009793)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Scawton Moor, 620m north west of High Lodge, Old Byland and Scawton, Ryedale		
DESIGNATION:	Scheduled Monument (No.1019824)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	Private	CONTACT:	Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Four round barrows 875m north west of High Blansby, Pickering, Ryedale			
DESIGNATION:	Scheduled Monument (No.1020818)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 440m north of Blansby Park	r Farm, Pickering, F	Ryedale	
DESIGNATION:	Scheduled Monument (No.1020817)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two sections of Roman road on Flamboro	ugh Rigg, Pickering	Ryedale	
DESIGNATION:	Scheduled Monument (No.1004104)	CONDITION:	Unknown	
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Cairn cemetery north east of Birk Nab Far	m, Pockley, Ryedal	e	
DESIGNATION:	Scheduled Monument (No.1004088)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Linear boundary earthwork 370m east of 0	Oscar Park Farm, F	Rievaulx, Ryedale	
DESIGNATION:	Scheduled Monument (No.1019340)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 920m south west of Silpho	Brow Farm, Silpho	, Scarborough	
DESIGNATION:	Scheduled Monument (No.1019626)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	The Thieves' Dikes: prehistoric linear bound	daries and associa	ted features, Silpho, Scarborough	
DESIGNATION:	Scheduled Monument (No.1019627)	CONDITION:	Generally satisfactory but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Prehistoric linear boundary and associated north, east and south east of Moorsome Fa		
DESIGNATION:	Scheduled Monument (No.1020836)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Linear dyke known as Double Dikes, in Wa	terloo Plantation,	Sproxton, Ryedale
DESIGNATION:	Scheduled Monument (No.1019346)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Pry Rigg round barrows, Sproxton, Ryedale		
DESIGNATION:	Scheduled Monument (No.1004086)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 100m north of Church Road	d Farm, Stainton D	Dale, Scarborough
DESIGNATION:	Scheduled Monument (No.1020110)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 370m south east of Rudda	Cottages, Stainton	Dale, Scarborough
DESIGNATION:	Scheduled Monument (No.1020106)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 450m north west of Garbur	tt Farm, Sutton-un	der-Whitestonecliffe, Hambleton
DESIGNATION:	Scheduled Monument (No.1010344)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 600m north west of Garbu	tt Farm, Sutton-un	der-Whitestonecliffe, Hambleton
DESIGNATION:	Scheduled Monument (No.1018550)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
	1 0 0		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Rabbit type 570m south east of Pexton Mo	oor Farm,Thornto	n le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No.1020675)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 460m north west of the Ad	der Stone,Thornt	on le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No.1020434)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 520m north west of St Hild	a's Church, Ellerbu	urn,Thornton le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No.1020693)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 650m north west of St Hild	a's Church, Ellerbu	urn,Thornton le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No.1020694)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Warrening enclosure 975m north east of H	High Paper Mill Far	rm,Thornton le Dale, Ryedale
DESIGNATION:	Scheduled Monument (No.1020680)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Ugthorpe Moor known 130m south west of Day Well House, Ugth		ı
DESIGNATION:	Scheduled Monument (No.1016543)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Prehistoric linear boundary in Craddlegrip 900m north west of High Yedmandale, Wes		ugh
DESIGNATION:	Scheduled Monument (No.1017165)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow on Coverdale Moor, 530m s	south of North Sti	le Cottage, West Ayton, Scarborough
DESIGNATION:	Scheduled Monument (No.1017156)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 200m north west of Scarth	Nick,Whorlton, F	lambleton
DESIGNATION:	Scheduled Monument (No.1008862)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 500m west of Red Way Hea	ad,Whorlton, Ham	bleton
DESIGNATION:	Scheduled Monument (No.1012728)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow at northern edge of Snotter	rdale Plantation,W	/horlton, Hambleton
DESIGNATION:	Scheduled Monument (No.1012736)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows 275m south of Scarth	Wood,Whorlton,	Hambleton
DESIGNATION:	Scheduled Monument (No.1011917)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow at North Moor, I20m south	east of Forest Lo	dge, Wykeham, Scarborough
DESIGNATION:	Scheduled Monument (No.1017021)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on East Moor, 640m north	of East Moor Farm	n, Wykeham, Scarborough
DESIGNATION:	Scheduled Monument (No.1019371)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### **RICHMONDSHIRE**



The Old Gatehouse, SITE NAME: Jervaulx Park,

East Witton Out Parish

DESIGNATION: Listed Building Grade I, SM

Very bad CONDITION: OCCUPANCY: Part occupied

C(C)PRIORITY-Private OWNER TYPE:

The house, known as the Old Gatehouse, was probably constructed from re-used medieval masonry in the C19, on medieval foundations. Part of the building is occupied and being repaired but the western end is ruinous and in need of repair.

Contact: Principal Heritage at Risk Adviser 01904 601901



Ravensworth Castle and park wall, SITE NAME: The Green. Ravensworth

Listed Building Grade I, SM, CA DESIGNATION: CONDITION: N/A OCCUPANCY:

A(A)PRIORITY: OWNERTYPE: Private Late C14, small roofless keep/gate tower and ruins of ancillary buildings together with impressive water defences later adapted to form water gardens. Much repointing and consolidation needed to all parts of the building. Significant parts of the standing remains, including the gate tower, are now at risk. A detailed record of the standing fabric has been completed.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Cobscar lead smeltmill, Redmire

Scheduled Monument DESIGNATION: Poor

CONDITION: N/A D (D) PRIORITY: Private OWNER TYPE:

The monument includes the standing, earthwork and buried remains of an ore hearth lead smelt mill, fuel store, and associated buildings, with the remains of a flue system leading to an intact chimney. Natural England will be taking forward repair programme.

Contact: Principal Heritage at Risk Adviser 01904 601901



Old Grandstand, SITE NAME: Richmond

DESIGNATION: Listed Building Grade II\*, CA Poor CONDITION: OCCUPANCY: N/A C (C) PRIORITY-OWNERTYPE: Company

A rare example of an C18 racecourse grandstand. The racecourse was closed in the late Č19 and the Grandstand became derelict. It was partially demolished c1960. Ruins cleared and stonework sorted c1995. A conservation plan for the building has been completed with the support of English Heritage. The Racecourse is now a conservation area.

Contact: Principal Heritage at Risk Adviser 01904 601901



St Martins Priory Ruins, SITE NAME: A6136,

St Martins

DESIGNATION: Listed Building Grade I, SM, CA

Poor CONDITION: N/A OCCUPANCY: A(A)OWNERTYPE: Private

The ruins of a small medieval monastic house, of C12 (possibly earlier) and C15. Part of a church, small gate tower and the ruined walls of other buildings also remain. Extensive consolidation and repointing work is required.



Keld Heads lead smeltmill SITE NAME and mine complex,

Preston-under-Scar, Wensley

**DESIGNATION: Scheduled Monument** CONDITION: Poor

N/A OCCUPANCY: PRIORITY: D(D)OWNER TYPE: Private The mine complex displays a wide range of features associated with lead exploitation and processing. The site has been mined since the C12 but the present complex dates from C18 and C19. Scrub clearance was undertaken by North Yorkshire County Council volunteers in 2005 to assist with the preparation of survey documents. Options appraisal complete.

Contact: Principal Heritage at Risk Adviser 01904 601901

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

## **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site

SITE NAME:	Section of Scots Dyke linear boundary 600	m south east of P	ark House, Aldbrough
DESIGNATION:	Scheduled Monument (No.1013305)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Stanwick Late Iron Age oppidum, Iron Age early Christian church and sculpture and po		
DESIGNATION:	Scheduled Monument (No.1016199)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Section of Scots Dyke linear boundary I50m ENE of Olliver, Aske		
DESIGNATION:	Scheduled Monument (No.1013780)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Cataractonium Roman forts and town, Bro	mpton-on-Swale	
DESIGNATION:	Scheduled Monument (No.1021181)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	St Giles medieval hospital, post-medieval fa immediately north of St Giles Farm, Brough		Age occupation site
DESIGNATION:	Scheduled Monument (No.1021210)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Medieval settlement of Dalton upon Tees a	nd associated field	l system, Dalton-on-Tees
DESIGNATION:	Scheduled Monument (No.1019724)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Section of Scots Dyke linear boundary and	portion of field s	ystem 100m east of Whitefields Farm, Eas
DESIGNATION:	Scheduled Monument (No.1013777)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


#### ABBREVIATIONS

TO COLUMN	Schodulad Manuscant (No. 1015410)		Extensive significant and blass
DESIGNATION:	Scheduled Monument (No.1015418)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two moated sites, the site of a dovecote as 120m north west and 180m north of The C		
DESIGNATION:	Scheduled Monument (No.1021039)	CONDITION:	Generally satisfactory
DESIGNATION:	Scheduled Floridine it (140.1021037)	CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Medieval village of Hunton and field system	n, Hunton	
DESIGNIATIONI	Scheduled Monument (No.1018380)	CONDITION:	Generally satisfactory
DESIGNATION:	Scheduled Floridificht (140.1010300)	CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
SWINER LIFE.	Tivacc	CONTACT.	01904 601901
SITE NAME:	Section of Scots Dike linear boundary nort	th west of High Me	errybent, Melsonby
DESIGNATION:	Scheduled Monument (No.1014799)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
SWINER III E.	Tivaco	CONTROL.	01904 601901
SITE NAME:	Section of Scots Dyke linear boundary east	of Langdale Rush	, Melsonby
DESIGNATION:	Scheduled Monument (No.1014240)	CONDITION:	Generally satisfactory
SESIGIV (1101).	Scheduled Floridine in (1961) 12 (0)	CONDITION.	but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	William's Hill, Middleham		
DESIGNATION:	Scheduled Monument (No.1004907)	CONDITION:	Generally satisfactory
	,		but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Section of the Scots Dyke linear boundary	225m south of St	Martin's Priory, St Martin's
DESIGNATION:	Scheduled Monument (No.1018143)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
		Common	01904 601901
SITE NAME:	Roman fort at Wensley, Wensley		
DESIGNATION:	Scheduled Monument (No.1012004)	CONDITION:	Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
OVVINER LIFE.	TITVALC	CONTACT:	i i i icipai i ici itage at i isk Auvisci

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
   B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

# 2011 priority categories are given in brackets.

#### RYFDAI F



SITE NAME: Lime Kilns. A170,

Allerston

DESIGNATION: Listed Building Grade II, SM, CA

Poor CONDITION: N/A OCCUPANCY: D (D) PRIORITY-Private

OWNER TYPE:

Bank of four lime kilns circa 1800. For Sir George Osbaldeston. Situated in woodland. These are in a poor state of repair. Some parts are starting to collapse. Section I7 Management Agreement works to remove damaging trees completed.

Contact: Principal Heritage at Risk Adviser 01904 601901



Yedingham Priory, SITE NAME: Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, SM

CONDITION:

Part occupied OCCUPANCY:

C(C)PRIORITY: Private OWNER TYPE:

Former priory, C12-C13. Little standing structure survives except for part of the precinct wall and part of the refectory, which has been incorporated into a cottage and barn. The masonry is cracking and bulging

Contact: Principal Heritage at Risk Adviser 01904 601901

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale approximately



SITE NAME: Wall of cascade approximately 100 metres north of Ebberston Hall, A 170, Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, RPG II\*

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY

OWNER TYPE:

Private

50m to the north of the Hall by Colen Campbell. Forms the lowest cascade of the two in the water garden.

Contact: Principal Heritage at Risk Adviser 01904 601901



Wall of cascade approximately SITE NAME: 50 metres north of Ebberston Hall, A170, Ebberston and Yedingham

DESIGNATION: Listed Building Grade II\*, RPG II\*

Poor OCCUPANCY: N/A C (C) PRIORITY Private OWNER TYPE:

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale circa 50m to the north of the Hall by Colen Campbell. Forms the upper cascade of the two in the water garden. In need of consolidation and restoration.

Contact: Principal Heritage at Risk Adviser 01904 601901

Castellated walls, 4 metres high, with square and round



SITE NAME: The Stray, Castle Howard, Henderskelfe

DESIGNATION: Listed Building Grade I, RPG

Poor CONDITION: N/A OCCUPANCY: D (D) OWNERTYPE: Private

OWNER TYPE:

interval towers stretching for one mile to either side of the main drive, immediately south of the pyramid gate. Built to the designs of Sir John Vanbrugh c1723 as a landscape feature. With EH support the Estate has secured Natural England grant of £1 million to help fund repairs. Eastern half repaired but repairs are still required to the western half.

Contact: Principal Heritage at Risk Adviser 01904 601901



The Mausoleum and bastion wall SITE NAME: with gates and railings, Kirk Hill, Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I, RPG I Poor CONDITION: N/A OCCUPANCY: PRIORITY C(C)

Mausoleum by Hawksmoor, 1729-42, modelled on the tomb of Metella, Situated on a bluff c1.2km E of the mansion and visible from the Temple Terrace and the Temple of the Four Winds (1724-28 by Vanbrugh), both SE of the mansion. The columns were repaired with a grant in the 1980s. The entablature and bastions continue to decay. Much of the damage is due to rusting cramps. The staircase balustrade is collapsing.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Private

Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: 2011 priority categories are given in brackets

## **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site



SITE NAME:	The Pyramid, St Annes Hill,
	Castle Howard Estate,
	Henderskelfe

DESIGNATION: Listed Building Grade I, RPG I

Poor CONDITION: N/A OCCUPANCY: C(C)

OWNERTYPE: Private

situated on a knoll and dominating views to the south from the Broad Walk and South Parterre. Decaying stone pyramid suffering from cramp damage. Five of the eight piers at the corners have been repaired with the support of a grant. Set in late C17/early C18 park, one of the most historically significant landscapes in the country.

Commemorative monument of 1728 by Hawksmoor,

Contact: Principal Heritage at Risk Adviser 01904 601901



Walls to walled garden SITE NAME: with gates and corner piers, Castle Howard Estate, Henderskelfe

DESIGNATION: Listed Building Grade I, RPG I

Very bad CONDITION: N/A OCCUPANCY: C(C)PRIORITY: Private OWNER TYPE:

Walls to the walled garden, early C18 by Sir John Vanburgh. The brick walls are in fair condition but the limestone piers are decaying and destabilising, partly collapsed due to lack of maintenance and repair.

Contact: Principal Heritage at Risk Adviser 01904 601901



Screen wall, SITE NAME:

north west of Malton Lodge, Old Maltongate, Malton

DESIGNATION: Listed Building Grade II\*, CA

Very bad CONDITION: N/A OCCUPANCY: PRIORITY: A(A)OWNERTYPE: Private

Courtyard wall circa I 604 of 'An extraordinary relic of a great Prodigy house of considerable national importance' (list description). Very heavily decayed and potentially unstable.

Contact: Principal Heritage at Risk Adviser 01904 601901



Sheriff Hutton Castle, SITE NAME:

Main Street, Sheriff Hutton

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY: Private OWNER TYPE:

Ruinous castle begun in 1382 by John, Lord Neville, with CI5 gatehouse inserted. Vulnerable to weathering. A condition survey was funded by English Heritage and Phase I repairs, also funded by English Heritage are complete. Emergency works to south west tower are complete.

Contact: Principal Heritage at Risk Adviser 01904 601901



Slingsby Castle, SITE NAME:

Slingsby

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad N/A OCCUPANCY: C (C) PRIORITY-OWNERTYPE: Private

C16 Great House built on the site of a medieval castle. Ruinous but surviving up to the eaves in height. In need of urgent consolidation; site is deteriorating as a result of natural erosion and some vandalism.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME:

Church of St Nicholas, Main Street, Ganton

DESIGNATION: Listed Place of Worship Grade II\*

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

C14 church incorporating C13 chancel and transept arches. C15 tower and south porch. Chancel partly rebuilt during restoration of 1843. The roofs are in good order, but there is severe decay of some of the stonework, potentially leading to loss of historic fabric. A grant has been offered.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### SITE NAME:

#### Acklam Wold barrow group: a bowl barrow 220m north west of Acklam Wold House, Acklam

DESIGNATION:	Scheduled Monument (No.1011543)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

# **ABBREVIATIONS** CA LB LPA NP RPG SM

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Acklam Wold barrow group: a bowl barrov	v 300m north wes	t of Acklam Wold House, Acklam
DESIGNATION:	Scheduled Monument (No.1011541)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Acklam Wold barrow group: a bowl barrov	v 300m south east	of Acklam Wold House, Acklam
DESIGNATION:	Scheduled Monument (No.1011570)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
TE NAME:	Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam		
DESIGNATION:	Scheduled Monument (No.1009928)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam		
DESIGNATION:	Scheduled Monument (No.1011574)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
WNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
	Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam		
SITE NAME:	Acklam Wold barrow group: a bowl barrov	v 450m south wes	t of Acklam Wold House, Acklam
	Scheduled Monument (No.1011573)	v 450m south wes	Extensive significant problems
DESIGNATION:	Scheduled Monument (No.1011573)  Arable ploughing		Extensive significant problems Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1011573)	CONDITION:	Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1011573)  Arable ploughing	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME:	Scheduled Monument (No.1011573)  Arable ploughing  Private	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE: SITE NAME: DESIGNATION:	Scheduled Monument (No.1011573)  Arable ploughing  Private  Acklam Wold barrow group: a bowl barrow	condition:  TREND:  CONTACT:  v on Wooing Nab,	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1011573)  Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539)	CONDITION: TREND: CONTACT:  v on Wooing Nab, CONDITION:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam  Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1011573)  Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539)  Arable ploughing	CONDITION: TREND: CONTACT:  v on Wooing Nab, CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: DWNER TYPE:	Scheduled Monument (No.1011573) Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539) Arable ploughing Private  Acklam Wold barrow group: a pair of bell by	CONDITION: TREND: CONTACT:  v on Wooing Nab, CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
ESIGNATION:  RINCIPAL VULNERABILITY:  WINER TYPE:  TE NAME:  ESIGNATION:  RINCIPAL VULNERABILITY:  WINER TYPE:  TE NAME:  ESIGNATION:	Scheduled Monument (No.1011573) Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539) Arable ploughing Private  Acklam Wold barrow group: a pair of bell be 200m south west of Acklam Wold House, A	condition: TREND: CONTACT:  v on Wooing Nab, CONDITION: TREND: CONTACT:  contact:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL YULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL YULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1011573)  Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539) Arable ploughing Private  Acklam Wold barrow group: a pair of bell to 200m south west of Acklam Wold House, and Scheduled Monument (No.1011547)	CONDITION: TREND: CONTACT:  v on Wooing Nab, CONDITION: TREND: CONTACT:  contact:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  // barrow  Extensive significant problems Declining
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DISTENAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1011573)  Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539)  Arable ploughing Private  Acklam Wold barrow group: a pair of bell to 200m south west of Acklam Wold House, and Scheduled Monument (No.1011547)  Arable ploughing	CONDITION: TREND: CONTACT:  V ON WOOING Nab, CONDITION: TREND: CONTACT:  DAIRY ON A CONDITION: TREND: CONTACT:  CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  // barrow Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL YULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DOWNER TYPE:	Scheduled Monument (No.1011573) Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539) Arable ploughing Private  Acklam Wold barrow group: a pair of bell be 200m south west of Acklam Wold House, a Scheduled Monument (No.1011547) Arable ploughing Private	CONDITION: TREND: CONTACT:  V ON WOOING Nab, CONDITION: TREND: CONTACT:  DAIRY ON A CONDITION: TREND: CONTACT:  CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  // barrow Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DESIGNATION:  PRINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1011573) Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539) Arable ploughing Private  Acklam Wold barrow group: a pair of bell to 200m south west of Acklam Wold House, and Scheduled Monument (No.1011547) Arable ploughing Private  Acklam Wold barrow group: two bowl barrow gr	CONDITION: TREND: CONTACT:  V ON Wooing Nab, CONDITION: TREND: CONTACT:  DARROWS and a bow Acklam CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  // barrow  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:  ITE NAME:  DESIGNATION:  RINCIPAL VULNERABILITY:  DWNER TYPE:	Scheduled Monument (No.1011573) Arable ploughing Private  Acklam Wold barrow group: a bowl barrow Scheduled Monument (No.1011539) Arable ploughing Private  Acklam Wold barrow group: a pair of bell to 200m south west of Acklam Wold House, and Scheduled Monument (No.1011547) Arable ploughing Private  Acklam Wold barrow group: two bowl barrow scheduled Monument (No.1011537)	CONDITION: TREND: CONTACT:  V ON WOOING Nab, CONDITION: TREND: CONTACT:  DARROWS and a bow Acklam CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Advise 01904 601901  Acklam Extensive significant problems Declining Principal Heritage at Risk Advise 01904 601901  // barrow  Extensive significant problems Declining Principal Heritage at Risk Advise 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Scheduled Monument (No.1007500)  Arable clipping Private	CONDITION:	Generally unsatisfactory
		with major localised problems
Private	TREND:	Declining
· maco	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
Long barrow 530m north of Keeper's Cott	age, Allerston	
Scheduled Monument (No.1020330)	CONDITION:	Generally satisfactory but with significant localised problems
Plant growth	TREND:	Declining
Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
Long barrow 630m north west of Scamridg	ge Farm, Allerston	
Scheduled Monument (No.1020832)	CONDITION:	Generally satisfactory but with significant localised problems
Arable clipping	TREND:	Declining
Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
Prehistoric linear boundary on Stonygate N	100r, 550m west o	f Warren House Farm, Allerston
Scheduled Monument (No.1020695)	CONDITION:	Generally satisfactory but with significant localised problems
Arable clipping	TREND:	Declining
Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
Round barrow 470m north of Keeper's Co	ttage, Allerston	
Scheduled Monument (No.1020331)	CONDITION:	Generally satisfactory but with significant localised problems
Plant growth	TREND:	Declining
Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
Round barrow 600m west of Scamridge Fa	rm, Allerston	
Scheduled Monument (No.1020831)	CONDITION:	Generally satisfactory but with minor localised problems
Arable clipping	TREND:	Improving
Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
Round barrow 250m NNE of Easthorpe Co	ottages, Amotherb	у
Scheduled Monument (No.1014566)	CONDITION:	Extensive significant problems
Arable ploughing	TREND:	Declining
Private	CONTACT:	Principal Heritage at Risk Adviser
		01904 601901
	Scheduled Monument (No.1020330)  Plant growth Government or Agency  Long barrow 630m north west of Scamridge Scheduled Monument (No.1020832)  Arable clipping Private  Prehistoric linear boundary on Stonygate Marable clipping Private  Round barrow 470m north of Keeper's Conscheduled Monument (No.1020331)  Plant growth Government or Agency  Round barrow 600m west of Scamridge Face Scheduled Monument (No.1020831)  Arable clipping Government or Agency  Round barrow 250m NNE of Easthorpe Conscheduled Monument (No.1014566)  Arable ploughing	Plant growth Government or Agency  Long barrow 630m north west of Scamridge Farm, Allerston Scheduled Monument (No.1020832)  Arable clipping Private  Prehistoric linear boundary on Stonygate Moor, 550m west of Scheduled Monument (No.1020695)  Arable clipping Private  CONTACT:  Round barrow 470m north of Keeper's Cottage, Allerston Scheduled Monument (No.1020331)  Scheduled Monument (No.1020331)  Plant growth Government or Agency  CONTACT:  Round barrow 600m west of Scamridge Farm, Allerston Scheduled Monument (No.1020831)  CONDITION:  Round barrow 600m west of Scamridge Farm, Allerston Scheduled Monument (No.1020831)  CONDITION:  Round barrow 600m west of Scamridge Farm, Allerston Scheduled Monument (No.1020831)  CONDITION:  Round barrow 250m NNE of Easthorpe Cottages, Amotherb Scheduled Monument (No.1014566)  CONDITION:  Round barrow 250m NNE of Easthorpe Cottages, Amotherb Scheduled Monument (No.1014566)  CONDITION: TREND:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 310m NNE of Easthorpe Lo	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No.1014565)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 330m north of Easthorpe Lo	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No.1014567)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 360m north of Easthorpe Lodge, Amotherby		
DESIGNATION:	Scheduled Monument (No.1014568)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 380m NNW of Easthorpe L	odge, Amotherby	
DESIGNATION:	Scheduled Monument (No.1014569)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Iron Age settlement, Barton-le-Street		
DESIGNATION:	Scheduled Monument (No.1003666)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Pockley Gates round barrow 600m west of	f Beadlam Grange,	Beadlam
DESIGNATION:	Scheduled Monument (No.1019341)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OVA (A JED TV/DE	Private	CONTACT:	Principal Heritage at Risk Adviser
OWNER I TPE:			01904 601901
	A bowl barrow on Birdsall Wold, 250m nor	rth west of Vessey	
SITE NAME:	A bowl barrow on Birdsall Wold, 250m nor Scheduled Monument (No.1007571)	th west of Vessey	
SITE NAME: DESIGNATION:		·	Pasture Farm, Birdsall  Extensive significant problems  Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007571)	CONDITION:	Pasture Farm, Birdsall  Extensive significant problems  Declining
OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No.1007571)  Arable ploughing	CONDITION: TREND: CONTACT:	Pasture Farm, Birdsall  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1007571) Arable ploughing Private	CONDITION: TREND: CONTACT:	Pasture Farm, Birdsall  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No.1007571) Arable ploughing Private  A bowl barrow on Birdsall Wold, 250m sou	CONDITION: TREND: CONTACT:  uth east of Vessey I	Pasture Farm, Birdsall Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Pasture Farm, Birdsall

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	A bowl barrow on Birdsall Wold, 300m north east of Vessey Pasture Farm, Birdsall			
DESIGNATION:	Scheduled Monument (No.1007570)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	A bowl barrow on Birdsall Wold, 425m eas	t of Aldro Farm, B	irdsall	
DESIGNATION:	Scheduled Monument (No.1007512)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	A bowl barrow on Birdsall Wold, 475m north west of Vessey Pasture Farm, incorporating part of a linear boundary, Birdsall			
DESIGNATION:	Scheduled Monument (No.1007575)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	A bowl barrow on Birdsall Wold, 580m east of Aldro Farm, Birdsall			
DESIGNATION:	Scheduled Monument (No.1007514)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	A bowl barrow on Birdsall Wold, 750m eas	t of Aldro Farm, B	irdsall	
DESIGNATION:	Scheduled Monument (No.1007468)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	A bowl barrow on Birdsall Wold, between	Birdsall Dale and V	essey Pasture Dale, Birdsall	
DESIGNATION:	Scheduled Monument (No.1007442)	CONDITION:	Generally satisfactory but with minor localised problem	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
		CONTACT:	01904 601901	
	A bowl barrow on Birdsall Wold, between			
SITE NAME:	A bowl barrow on Birdsall Wold, between Scheduled Monument (No.1007443)			
SITE NAME: DESIGNATION:		Birdsall Dale and V	essey Pasture Dale, Birdsall	
SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007443)	Birdsall Dale and V	Yessey Pasture Dale, Birdsall  Extensive significant problems  Declining	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1007443)  Arable ploughing	Birdsall Dale and V  CONDITION:  TREND:  CONTACT:	Yessey Pasture Dale, Birdsall Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901	
SITE NAME: DESIGNATION:	Scheduled Monument (No.1007443) Arable ploughing Private	Birdsall Dale and V  CONDITION:  TREND:  CONTACT:	Tessey Pasture Dale, Birdsall  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No.1007443) Arable ploughing Private  A bowl barrow on Birdsall Wold, between	Birdsall Dale and V  CONDITION:  TREND:  CONTACT:  Birdsall Dale and V	Yessey Pasture Dale, Birdsall Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901 Yessey Pasture Dale, Birdsall	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Three bowl barrows on Birdsall Wold, 400m north west of Vessey Pasture Farm, Birdsall			
DESIGNATION:	Scheduled Monument (No.1007574)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two bowl barrows on Birdsall Wold, 850m	east of Aldro Farr	n, Birdsall	
DESIGNATION:	Scheduled Monument (No.1007403)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two bowl barrows on Birdsall Wold, betwe	en Birdsall Dale a	nd Vessey Pasture Dale, Birdsall	
DESIGNATION:	Scheduled Monument (No.1007441)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Hedon Howe tumulus, Burythorpe			
DESIGNATION:	Scheduled Monument (No.1005487)	CONDITION:	Generally unsatisfactory with major localised problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Roman site south west of Kennythorpe, Bu	rythorpe		
DESIGNATION:	Scheduled Monument (No.1004070)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Bossall Hall: a quadrangular castle, Buttercr	ambe with Bossall		
DESIGNATION:	Scheduled Monument (No.1008016)	CONDITION:	Generally satisfactory but with minor localised problem	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Cawthorne medieval settlement remains 15	50m north east of	West Cawthorne, Cropton	
DESIGNATION:	Scheduled Monument (No.1018951)	CONDITION:	Generally satisfactory but with minor localised problem	
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Stable	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow 350m north west of Hen Fl	atts, Cropton		
DESIGNATION:	Scheduled Monument (No.1018408)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
			Principal Heritage at Risk Adviser	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

Arable ploughing Private CONDICT Principal Heritage at Risk Adviser 01904 601901  Foston medieval settlement and moated monastic grange, Foston  ESCHAMINE Private CONDICT Principal Heritage at Risk Adviser 01904 601901  Localised/imited stock erosion TRAD. CONDICT Principal Heritage at Risk Adviser 01904 601901  BORGANIAN BURNET Private CONDICT Private Scheduled Monument (No.1004059)  ESCHAMINE Boythorpe settlement site, Foxholes  ESCHAMINE Private CONDICT Private Significant problems  DESCHAMINE Scheduled Monument (No.1004046) CONDICT Private Significant problems  DESCHAMINE Private CONDICT Private Private CONDICT Private Significant problems  DESCHAMINE Private CONDICT Private Private CONDICT Private Significant problems  DESCHAMINE Scheduled Monument (No.1004047) CONDICT Private Significant problems  DESCHAMINE Scheduled Monument (No.1004047) CONDICT Private Significant problems  DESCHAMINE Private CONDICT Private Privat	SITE NAME:	Round barrow 550m north of High Nova F	arm, Cropton	
Private constant Private constant Private constant Principal Harriage at Risk Adviser 01904 601901  Foston medieval settlement and moated monastic grange, Foston Generally satisfactory but with significant localised problems provided the private constant of the private constant Private constant of the private constan	DESIGNATION:	Scheduled Monument (No.1015440)	CONDITION:	Extensive significant problems
FOSTERIAME  FOSTON Medieval settlement and moated monastic grange, Foston  Scheduled Monument (No.1019388)  CONDITION  Generally satisfactory but with significant localised problems  Declining  Declining  Private  CONFICE  Priva	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	9
Foston medieval settlement and moated monastic grange, Foston  Scheduled Monument (No.1019388)  CONDINION  Scheduled Monument (No.1019388)  CONDINION  Declining  Private  CONTACE  Principal Heritage at Risk Adviser 01904 601901  Declining  Private  Boythorps settlement site, Foxholes  Scheduled Monument (No.1004059)  CONDINION  Arable ploughing  TREND  Declining  Private  CONTACE  Principal Heritage at Risk Adviser 01904 601901  CONDINION  CONDINION  Private  CONTACE  Principal Heritage at Risk Adviser 01904 601901  CONDINION  Private  CONTACE  Principal Heritage at Risk Adviser 01904 601901  CONDINION  CONDI	OWNER TYPE:	Private	CONTACT:	
Scheduled Monument (No.1019388) CONDITION CONTROL VALIDATION  Localised/firrited stock erosion TITONO Declining Private Private  Boythorpe settlement site, Foxholes SEREMATION Scheduled Monument (No.1004059) Arable ploughing Private  Romano-British settlement, Foxholes Scheduled Monument (No.1004059) Scheduled Monument (No.1004046) Scheduled Monument (No.1004047) Scheduled Monume				01904 601901
but with significant localised problems converses and provide conv	SITE NAME:	Foston medieval settlement and moated m	onastic grange, Fo	ston
Private Contract: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Boythorpe settlement site, Foxholes  Description: Scheduled Monument (No.1004059) Concornor: Extensive significant problems  Declining Private Contract: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Romano-British settlement, Foxholes  Soft NAME: Romano-British settlement, Foxholes  Soft NAME: Scheduled Monument (No.1004046) Concornor: Extensive significant problems  Private Contract: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Settlement site at Butterwick, Foxholes  Soft NAME: Settlement site at Butterwick, Foxholes  Soft NAME: Settlement site at Butterwick, Foxholes  Soft NAME: Scheduled Monument (No.1004047) Concornor: Extensive significant problems  Declining Contract: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Scheduled Monument (No.1004047) Concornor: Extensive significant problems  Declining Contract: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  Soft NAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  Description: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  Description: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  Description: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Three round barrows north east of Ganton Wold Farm, Ganton  Description: Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Three round barrows north east of Ganton Wold Farm, Ganton  Description: Principal Heritage at Risk Adviser 01904 601901  Fixtensive significant problems  Declining Principal Heritage at Risk Adviser 01904 601901  Soft NAME: Three round barrows north east of Ganton Wold Farm, Ganton  Description: Principal Heritage at Risk Adviser 01904 601901  Fixtensive significant problems  Declining Principal Heritage at Risk Adviser 01904 601901	designation:	Scheduled Monument (No.1019388)	CONDITION:	Generally satisfactory but with significant localised problems
Boythorpe settlement site, Foxholes  SETENAME  BOYTHORD Scheduled Monument (No.1004059)  CONDITION  Arable ploughing  Private  ROMAND-British settlement, Foxholes  DESCRIPTION  Scheduled Monument (No.1004069)  THEND  DESCRIPTION  Private  ROMAND-British settlement, Foxholes  DESCRIPTION  Scheduled Monument (No.1004046)  CONDITION  Private  CONDITION  Extensive significant problems  Declining  Private  CONDITION  Declining  Private  CONDITION  Declining  Private  CONDITION  Extensive significant problems  Declining  Declining  Declining  Private  Settlement site at Butterwick, Foxholes  DESCRIPTION  DESCRIPTION  Scheduled Monument (No.1004047)  CONDITION  Extensive significant problems  Declining  Private  CONDITION  Declining  Private  CONDITION  Extensive significant problems  Declining  Private  CONDITION  Extensive significant problem	PRINCIPAL VULNERABILITY:		TREND:	9
Scheduled Monument (No.1004059) CONDITION Extensive significant problems Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEINAME: Romano-British settlement, Foxholes  DESCONATION: Scheduled Monument (No.1004046) CONDITION Extensive significant problems  DESCONATION: Arable ploughing TRIND: Declining  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETTENAME: Settlement site at Butterwick, Foxholes  DESCONATION: Scheduled Monument (No.1004047) CONDITION Extensive significant problems  DESCONATION: Scheduled Monument (No.1004047) CONDITION Extensive significant problems  DESCONATION: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETENAME: Settlement site at Butterwick, Foxholes  DESCONATION: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETENAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  DESCONATION: Scheduled Monument (No.1013682) CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETENAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESCONATION: Scheduled Monument (No.1003688) CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETENAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESCONATION: Scheduled Monument (No.1003688) CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESCONATION: Scheduled Monument (No.1003687) CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESCONATION: Scheduled Monument (No.1003687) CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three Private CONTACT: Principal Heritage at Risk Adviser 01904 601901	OWNER TYPE:	Private	CONTACT:	
Arable ploughing TREND. Declining Principal Heritage at Risk Adviser 01904 601901  ROMARTHE ROMANDERABUTY: OWNERTHE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  REPLICATION VALUERABUTY: Arable ploughing TREND. Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Settlement site at Butterwick, Foxholes  DESCRATION: Scheduled Monument (No.1004047) CONDITION: Extensive significant problems  DESCRATION: Scheduled Monument (No.1004047) CONDITION: Extensive significant problems  DESCRATION: Arable ploughing TREND. Declining  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  RETERMAND: ROMARTHE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  RETERMAND: Scheduled Monument (No.1013682) CONDITION: Extensive significant problems  DESCRATION: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  ROMARTHE ROUM BARROW: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  DESCRATION: Arable ploughing TREND: Declining  DECLINION: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  Three round barrows north east of Ganton Wold Farm, Ganton  Three round barrows north east of Ganton Wold Farm, Ganton  Three round barrows north east of Ganton Wold Farm, Ganton  DESCRATION: Arable ploughing TREND: Declining  Private CONDITION: Extensive significant problems  PRINCIPAL VALUERABUTY: Arable ploughing TREND: Declining  DESCRATION: Private CONDITION: Extensive significant problems  PRINCIPAL VALUERABUTY: Arable ploughing TREND: Declining  DESCRATION: Private CONDITION: Extensive significant problems  DESCRATION: PRIVATE CONDITION: Extensive significant problems  DESCRATION: PRIVATE CONDITION: Exten	SITE NAME:	Boythorpe settlement site, Foxholes		
OWNERTING  Private  Romano-British settlement, Foxholes  Scheduled Monument (No.1004046)  Settlement site at Butterwick, Foxholes  Settlement site at Butterwick, Foxholes  Scheduled Monument (No.1004047)  Settlement site at Butterwick, Foxholes  Scheduled Monument (No.1004047)  Scheduled Monument (No.1004047)  Settlement site at Butterwick, Foxholes  Scheduled Monument (No.1004047)  Scheduled Monument (No.1004047)  Scheduled Monument (No.1004047)  Scheduled Monument (No.1004047)  Scheduled Monument (No.1013682)  Scheduled Monument (No.1013682)  Scheduled Monument (No.1013682)  Scheduled Monument (No.1013682)  Scheduled Monument (No.1004047)  Scheduled	DESIGNATION:	· · · · · · · · · · · · · · · · · · ·	CONDITION:	Extensive significant problems
ROMAND-British settlement, Foxholes  Scheduled Monument (No.1004046) CONDITION Extensive significant problems  PRINCIPAL VULNERABLITH: OWNERTHYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETTENAME: Settlement site at Butterwick, Foxholes  Scheduled Monument (No.1004047) CONDITION Extensive significant problems  PRINCIPAL VULNERABLITH: OWNERTHYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETTENAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  SETTENAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  SETTENAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  DESIGNATION Arable ploughing TREND Declining  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETTENAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION Scheduled Monument (No.1003688) CONDITION Extensive significant problems  DESIGNATION Scheduled Monument (No.1003688) CONDITION Declining  DOWNENTIFIE ROUND BRITISH Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SETENAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION Scheduled Monument (No.1003688) CONDITION Extensive significant problems  DESIGNATION Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION Scheduled Monument (No.1003687) CONDITION Extensive significant problems  DESIGNATION Scheduled Monument (No.1003687) CONDITION Extensive significant problems  DESIGNATION Private Priv	PRINCIPAL VULNERABILITY:		TREND:	9
ROMANDAL PRIVATE  ROMANDAL PRIVATE  ROMANDAL PRIVATE  REPRESENTATION  SCHEDUL VALUERRABILITY:  Arable ploughing  TREND:  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STEINAME:  Settlement site at Butterwick, Foxholes  SETENAME:  Settlement site at Butterwick, Foxholes  SETENAME:  Settlement site at Butterwick, Foxholes  SETENAME:  Scheduled Monument (No.1004047)  CONDITION:  Extensive significant problems  Declining  TREND:  Declining  TREND:  Declining  OWNERTHYPE:  Private  Round barrow 250m ENE of High Baxtonhowe, Fryton  DESIGNATION:  SCHEDULED HERITAGE AT RISK Adviser 01904 601901  STEINAME:  ROUND BARRABILITY:  Arable ploughing  TREND:  Declining  Declining  Declining  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STEINAME:  ROUND BARRABILITY:  Arable ploughing  TREND:  DEClining  DEClining  DECLINING  DESIGNATION:  SCHEDULED HORIZON VALUERRABILITY:  Arable ploughing  TREND:  DECLINING  DESIGNATION:  SCHEDULED HORIZON VALUERRABILITY:  Arable ploughing  TREND:  DECLINING  TREND:  DECLINING  DECLINING	OWNER TYPE:	Private	CONTACT:	
Scheduled Monument (No.1004046)  Scheduled Monument (No.1004046)  Arable ploughing  Private  Private  Settlement site at Butterwick, Foxholes  Scheduled Monument (No.1004047)  STERNO:  Declining  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STERNO:  Designation  Scheduled Monument (No.1013682)  STERNOR  Scheduled Monument (No.1013682)  STERNOR  Scheduled Monument (No.1013688)  Scheduled Monument (No.1013687)  Sc				01904 601901
Arable ploughing TREND: Declining Principal Heritage at Risk Adviser 01904 601901  SETE NAME: Settlement site at Butterwick, Foxholes  DESIGNATION: Scheduled Monument (No.1004047) CONTINCT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Declining TREND: Declining CONTINCT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  Scheduled Monument (No.1013682) CONDITION: Extensive significant problems  DESIGNATION: Arable ploughing TREND: Declining CONTINCT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  DESIGNATION: Scheduled Monument (No.1003688) CONTINCT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Three round barrows north east of Ganton Wold Farm, Ganton  Scheduled Monument (No.1003687) CONTINCT: Extensive significant problems  DESIGNATION: Scheduled Monument (No.1003687) CONTINCT: Principal Heritage at Risk Adviser 01904 601901	SITE NAME:	Romano-British settlement, Foxholes		
Private  Settlement site at Butterwick, Foxholes  Stename: Scheduled Monument (No.1004047) CONDITION: Extensive significant problems  Private Private Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  Stensive significant problems  Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  Stename: Round barrow 250m ENE of High Baxtonhowe, Fryton  Designation: Scheduled Monument (No.1013682) CONTACT: Private Private Private Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  Stename: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  Designation: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  Stename: Declining Private Pr	DESIGNATION:	Scheduled Monument (No.1004046)	CONDITION:	Extensive significant problems
STEINAME: Settlement site at Butterwick, Foxholes  DESIGNATION: Scheduled Monument (No.1004047) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  STEINAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  DESIGNATION: Scheduled Monument (No.1013682) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  STEINAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  DESIGNATION: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  STEINAME: Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  DESIGNATION: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	9
Scheduled Monument (No.1004047)  Scheduled Monument (No.1004047)  Arable ploughing  Private  Private  Round barrow 250m ENE of High Baxtonhowe, Fryton  Designation:  Scheduled Monument (No.1013682)  Scheduled Monument (No.1013682)  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  Reprivate  Round barrow 250m ENE of High Baxtonhowe, Fryton  Designation:  Scheduled Monument (No.1013682)  CONDITION:  Extensive significant problems  Private  Private  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  Reprivate  Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  Designation:  Scheduled Monument (No.1003688)  CONDITION:  Extensive significant problems  Private  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  Thence  There round barrows north east of Ganton Wold Farm, Ganton  Designation:  Scheduled Monument (No.1003687)  CONDITION:  Extensive significant problems  Private  Three round barrows north east of Ganton Wold Farm, Ganton  Designation:  Scheduled Monument (No.1003687)  CONDITION:  Extensive significant problems  Private  Three round barrows north east of Ganton Wold Farm, Ganton  Designation:  Scheduled Monument (No.1003687)  CONDITION:  Extensive significant problems  Private  Private  Private  Private  Private  Private  Private  Private	OWNER TYPE:	Private	CONTACT:	
Arable ploughing TREND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow 250m ENE of High Baxtonhowe, Fryton  DESIGNATION: Scheduled Monument (No.1013682) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DECLINING: Declining  DECLINING: Declining  TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DECLINING: Declining  DECLINING: Declining  DECLINING: Declining  DECLINING: Principal Heritage at Risk Adviser	SITE NAME:	Settlement site at Butterwick, Foxholes		
Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Round barrow 250m ENE of High Baxtonhowe, Fryton  Scheduled Monument (No.1013682) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  ROUND BESTE NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  EXTENAME: Three round barrows north east of Ganton Wold Farm, Ganton  EXTENAME: Three round barrows north east of Ganton Wold Farm, Ganton  EXTENAME: Three round barrows north east of Ganton Wold Farm, Ganton  EXTENAME: Three round barrows north east of Ganton Wold Farm, Ganton  EXTENAME: Three round barrows north east of Ganton Wold Farm, Ganton  EXTEND: Declining  Declining  EXTEND: Declining  Declining  EXTEND: Declining	DESIGNATION:	Scheduled Monument (No.1004047)	CONDITION:	Extensive significant problems
Round barrow 250m ENE of High Baxtonhowe, Fryton  DESIGNATION: Scheduled Monument (No.1013682) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DESIGNATION: Principal Heritage at Risk Adviser  01904 601901  ROUNDERTYPE: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  ESTE NAME: Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DOWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser  DESIGNATION: PRINCIPAL VULNERABILITY: Declining  DESIGNATION: PRINCIPAL VULNERABILITY: Declining  DESIGNATION: Principal Heritage at Risk Adviser  DESIGNATION: PRINCIPAL VULNERABILITY: Declining  DESIGNATION: Principal Heritage at Risk Adviser  DESIGNATION: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	8
DESIGNATION: Scheduled Monument (No.1013682) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser  ODESIGNATION: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow 250m ENE of High Baxtonh	owe, Fryton	
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1013682)	CONDITION:	Extensive significant problems
Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:	
Round barrow 700yds (640m) north east of Brompton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
DESIGNATION: Scheduled Monument (No.1003688) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser				01904 601901
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow 700yds (640m) north east o	of Brompton Wold	Farm, Ganton
Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three round barrows north east of Ganton Wold Farm, Ganton  DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1003688)	CONDITION:	Extensive significant problems
Three round barrows north east of Ganton Wold Farm, Ganton  Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	9
Three round barrows north east of Ganton Wold Farm, Ganton  Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
DESIGNATION: Scheduled Monument (No.1003687) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser				01904 601901
PRINCIPAL VULNERABILITY: Arable ploughing trend: Declining owner type: Private contact: Principal Heritage at Risk Adviser	SITE NAME:	Three round barrows north east of Ganton	n Wold Farm, Gan	ton
OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1003687)	CONDITION:	Extensive significant problems
	PRINCIPAL VULNERABILITY:		TREND:	8
	OWNER TYPE:	Private	CONTACT:	
				01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Round barrow 450m south west of Coney Hill Farm, Gilling East					
DESIGNATION:	Scheduled Monument (No.1014082)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNERTYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			
SITE NAME:	Round barrow 500m SSW of Coney Hill Fa	ırm, Gilling East				
DESIGNATION:	Scheduled Monument (No.1014083)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			
SITE NAME:	Round barrow 530m NNW of Maidenswor	th Farm, Grimsto	ne			
DESIGNATION:	Scheduled Monument (No.1013599)	CONDITION:	Generally unsatisfactory			
			with major localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			
SITE NAME:	Round barrow on Grimston Moor 350m n	orth east of Black	Gill Plantation, Grimstone			
DESIGNATION:	Scheduled Monument (No.1013444)	CONDITION:	Generally satisfactory but with significant localised problems			
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving			
OWNERTYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			
SITE NAME:	Round barrow 300m north of Rye House I	arm, Helmsley				
DESIGNATION:	Scheduled Monument (No.1019596)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			
SITE NAME:	Round barrow 420m north of Rye House I	arm, Helmsley				
DESIGNATION:	Scheduled Monument (No.1019595)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			
SITE NAME:	East Heslerton Brow barrow group: a bow	barrow I.Ikm eas	st of Manor Wold Farm, Heslerton			
DESIGNATION:	Scheduled Monument (No.1011578)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			
SITE NAME:	East Heslerton Brow barrow group: a bow	barrow I.3km eas	st of Manor Wold Farm, Heslerton			
DESIGNATION:	Scheduled Monument (No.1011579)	CONDITION:	Extensive significant problems			
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining			
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901			

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	East Heslerton Brow barrow group: a bow	l barrow 750m eas	st of Manor Wold Farm, Heslerton	
DESIGNATION:	Scheduled Monument (No.1011580)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	East Heslerton Brow barrow group: a long	barrow 1000m ea	st of Manor Wold Farm, Heslerton	
DESIGNATION:	Scheduled Monument (No.1011516)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Heslerton Brow barrow group: a bowl barr	row 230m north e	ast of Wold Barn, Heslerton	
DESIGNATION:	Scheduled Monument (No.1011585)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Heslerton Brow barrow group: a bowl barr	row 250m north v	vest of Wold Barn, Heslerton	
DESIGNATION:	Scheduled Monument (No.1011582)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Heslerton Brow barrow group: three bowl	barrows 300m no	rth east of Wold Barn, Heslerton	
DESIGNATION:	Scheduled Monument (No.1011586)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	New Bield round barrow and ringwork, He	eslerton		
		eslerton  CONDITION:	Extensive significant problems	
DESIGNATION:	New Bield round barrow and ringwork, He Scheduled Monument (No.1004105) Arable ploughing		Extensive significant problems Declining	
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1004105)	CONDITION:		
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1004105)  Arable ploughing	CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No.1004105) Arable ploughing Private	CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Igham  Generally unsatisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No.1004105) Arable ploughing Private  Round barrow 100m north west of Moor H	CONDITION: TREND: CONTACT:  House Farm, Hovir	Declining Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1004105) Arable ploughing Private  Round barrow 100m north west of Moor H Scheduled Monument (No.1014709)	CONDITION: TREND: CONTACT:  House Farm, Hovir CONDITION:	Declining Principal Heritage at Risk Adviser 01904 601901  Igham  Generally unsatisfactory with major localised problems	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1004105) Arable ploughing Private  Round barrow 100m north west of Moor H Scheduled Monument (No.1014709)  Arable clipping	CONDITION: TREND: CONTACT:  House Farm, Hovir CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Igham Generally unsatisfactory with major localised problems Declining Principal Heritage at Risk Adviser	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1004105) Arable ploughing Private  Round barrow 100m north west of Moor H Scheduled Monument (No.1014709)  Arable clipping Private	CONDITION: TREND: CONTACT:  House Farm, Hovir CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Igham  Generally unsatisfactory with major localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Generally satisfactory	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1004105) Arable ploughing Private  Round barrow 100m north west of Moor H Scheduled Monument (No.1014709)  Arable clipping Private  Round barrow 250m west of Calf Close W Scheduled Monument (No.1013552)	CONDITION: TREND: CONTACT:  House Farm, Hovir CONDITION: TREND: CONTACT:	Declining Principal Heritage at Risk Adviser 01904 601901  Igham  Generally unsatisfactory with major localised problems Declining Principal Heritage at Risk Adviser 01904 601901	
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No.1004105) Arable ploughing Private  Round barrow 100m north west of Moor H Scheduled Monument (No.1014709)  Arable clipping Private  Round barrow 250m west of Calf Close W	CONDITION: TREND: CONTACT:  House Farm, Hovir CONDITION: TREND: CONTACT:  Yood, Hovingham CONDITION:	Declining Principal Heritage at Risk Adviser 01904 601901  Igham  Generally unsatisfactory with major localised problems Declining Principal Heritage at Risk Adviser 01904 601901  Generally satisfactory but with significant localised problems	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round barrow 350m south west of Moor I	House Farm, Hovi	ngham
DESIGNATION:	Scheduled Monument (No.1013545)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Round barrow 400m ESE of Theaker Waste	er's Spring, Hoving	ham
DESIGNATION:	Scheduled Monument (No.1013553)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 500m NNW of Moor Hous	e Farm, Hovinghar	n
DESIGNATION:	Scheduled Monument (No.1013547)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 700m north of Moor House	e Farm, Hovinghan	n
DESIGNATION:	Scheduled Monument (No.1013546)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Medieval moated site I50m south east of L	ow Hutton Post C	Office, Huttons Ambo
DESIGNATION:	Scheduled Monument (No.1014384)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Improving
DWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows I/2 mile (800m) north	east of Duggleby	High Barn, Kirby Grindalythe
DESIGNATION:	Scheduled Monument (No.1004165)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moated site known as Vivers Hill Castle, 30	00m north east of	the parish church, Kirkbymoorside
DESIGNATION:	Scheduled Monument (No.1015811)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Starfits round barrow, 450m north east of	Starfits House, Kir	kbymoorside
DESIGNATION:	Scheduled Monument (No.1015810)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining .
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
RIORITY (FOR BUILDINGS)			ABBREVIATIONS

- PRIORITY (FOR BUILDINGS)

  A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

ABBREVIATIONS
CA Conserv
LB Listed B
LPA Local PI
NP Nationa
RPG Register
SM Schedul
UA Unitary
WHS World I ATIONS
Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site

Anable ploughing moves the provide contract principal Heritage at Risk Adviser 01904 601901  Esh's round barrow: a long barrow and later bowl barrow 400m north of Cross Thoms Barn, Lutton Stephane Scheduled Monument (No.101576) costeriors Extensive significant problems necessary and provide ploughing near Declining Near	SITE NAME:	Roman villa, Langton			
Esh's round barrow: a long barrow and later bowl barrow 400m north of Cross Thorns Barn, Lutton  Scheduled Monument (No.1011576)  CONDUCT  Schensive significant problems  RECHANAMARIN: Arable ploughing  Private  CONDUCT  Principal Heritage at Risk Adviser 01904 601901  Sit Navie  Long barrow 650m south east of Cross Thorns Barn, Luttons  Scheduled Monument (No.1011575)  consument  Rechanamarin: Arable ploughing  Private  CONDUCT  CONDUCT  CONDUCT  Principal Heritage at Risk Adviser 01904 601901  RECHANAMARIN: CONDUCT  CONDUCT  Principal Heritage at Risk Adviser 01904 601901  RECHANAMARIN: CONDUCT  Private  CONDUCT  Private  CONDUCT  CONDUCT  Private  CONDUCT  CONDUCT  CONDUCT  Conduct  Private  CONDUCT  CONDUCT  Conduct  Private  CONDUCT  CONDUCT  Conduct  Conduct  Private  CONDUCT  Conduct  Conduct  Private  CONDUCT  Conduct  Conduct  Private  CONDUCT  Conduct  Conduct  Conduct  Conduct  Private  CONDUCT  C	DESIGNATION:	Scheduled Monument (No.1004884)	CONDITION:	Extensive significant problems	
DITENSE.  Est's round barrow: a long barrow and later bowl barrow 400m north of Cross Thorns Barn, Lutton BARRADANION  Arable ploughing mino Declining BARRADANION  Private Contract Private Private  Long barrow 650m south east of Cross Thorns Barn, Luttons BARRADANION  Scheduled Monument (No.1011575) Constitute BARRADANION  Arable ploughing Mino Contract Private Private Septificant problems BARRADANION  Arable ploughing Mino Contract Private Septificant problems Private Contract Private Declining BARRADANION  Round barrow 1/4 mile (400m) north west of Broom House, Luttons BARRADANION  BARRADANION  Round barrow 1/4 mile (400m) north west of Broom House, Luttons BARRADANION  BARRADANION  Round barrow 1/4 mile (400m) north west of Broom House, Luttons  BARRADANION  BARRADANION  Round Barrow 1/4 mile (400m) north west of Broom House, Luttons  BARRADANION  BARRADANION  Round Barrow 1/4 mile (400m) north west of Broom House, Luttons  BARRADANION  BARRADANION  Round Barrow 1/4 mile (400m) north west of Broom House, Luttons  BARRADANION  BARRADANION  BARRADANION  BARRADANION  Arable ploughing Mino Declining  Private Contract Principal Heritage at Risk Adviser  01904 601901  BARRADANION  BARR	PRINCIPAL VULNERABILITY:		TREND:		
Scheduled Monument (No.1011576) CONDITION: Extensive significant problems Declining CONDITION: Private DISTRICT DESCRIPTION OF THE PRIVATE DESCRIPTI	OWNER TYPE:	Private	CONTACT:		
PRINCIPLY VALIDADARIAN  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  Three bowl barrows 200m west of Belle Via Farm, Luttons  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  Three bowl barrows 200m west of Belle Via Farm, Luttons  Scheduled Monument (No.101514)  CONNECT Principal Heritage at Risk Adviser 01904 601901  Three bowl barrows 200m west of Belle Via Farm, Luttons  Declaring  Private  Three bowl barrows 200m west of Belle Via Farm, Luttons  Declaring  Private  Three bowl barrows 200m west of Belle Via Farm, Luttons  Declaring  Private  Three bowl barrows 200m west of Belle Via Farm, Luttons  Declaring  Private  Three bowl barrows 200m west of Belle Via Farm, Luttons  Declaring  Private  Three bowl barrows 200m west of Belle Via Farm, Luttons  Declaring  Private  Three bowl barrows 200m west of Belle Via Farm, Luttons  Declaring  Private  Declaring  Private  Private  Declaring  Tranc. Declaring  Tranc. Declaring  Private  Declaring	SITE NAME:	Esh's round barrow: a long barrow and late	r bowl barrow 40	0m north of Cross Thorns Barn, Luttons	
Private  Long barrow 650m south east of Cross Thorms Barn, Luttons  Basconations  Scheduled Monument (No.1011575)  CENTRITION  Arable ploughing  Trends  CONSECT  Principal Heritage at Risk Adviser Declining  CONSECT  O1904 601901  STENAME  Round barrow 1/4 mile (400m) north west of Broom House, Luttons  Declining  CONSECT  O1904 601901  STENAME  Round barrow 1/4 mile (400m) north west of Broom House, Luttons  Declining  Trends  Declining  Private  CONSECT  Principal Heritage at Risk Adviser O1904 601901  Trends  Declining  Private  Three bowl barrows 200m west of Belle Vie Farm, Luttons  DESCONAITON  Scheduled Monument (No.1011514)  CONSECTION  Scheduled Monument (No.1004885)  CONSECTION  Scheduled Monument (No.1004885)  CONSECTION  CONSECTION  Arable ploughing  TRENDS  DECLINING  DECLINING  DECLINING  CONSECTION  CONSECTION  Arable ploughing  TRENDS  DECLINING  CONSECTION  CONSECTION  Arable ploughing  TRENDS  CONSECTION  Private  CONSECTION  CONSECTION	DESIGNATION:	Scheduled Monument (No.1011576)	CONDITION:	Extensive significant problems	
DESCRIPTION STREAMS AND THE PROCESS TO STREAMS AND THE PROCESS TO STREAMS AND THE PROCESS AND	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	~	
Scheduled Monument (No.1011575)  CONJUNION  Extensive significant problems  Private  Private  Round barrow I/4 mile (400m) north west of Broom House, Luttons  Declining  Private  Round barrow I/4 mile (400m) north west of Broom House, Luttons  Declored Private  Round barrow I/4 mile (400m) north west of Broom House, Luttons  Declored Private  Round barrow I/4 mile (400m) north west of Broom House, Luttons  Declored Private  Declored Private  Private  Private  Private  CONTINCT:  Private  Private  Three bowl barrows 200m west of Belle Vue Farm, Luttons  Declored Private  Declored Private  Declored Private  Declored Private  Declored Private  CONTINCT:  Private  Declored	OWNER TYPE:	Private	CONTACT:		
Arable ploughing Private CONTACT Principal Heritage at Risk Adviser 01904 601901  RETENAME: Round barrow I/4 mile (400m) north west of Broom House, Luttons  DESCANTION Scheduled Monument (No.1004114) CONDITION: Extensive significant problems  Private CONTACT Principal Heritage at Risk Adviser 01904 601901  There bowl barrows 200m west of Belle Vue Farm, Luttons  DESCANTION: Three bowl barrows 200m west of Belle Vue Farm, Luttons  DESCANTION: Three bowl barrows 200m west of Belle Vue Farm, Luttons  DESCANTION: Three bowl barrows 200m west of Belle Vue Farm, Luttons  DESCANTION: Scheduled Monument (No.1011514) CONDITION: Extensive significant problems  PRIVATE CONTACT: Principal Heritage at Risk Adviser 01904 601901  THEND DESCANTION: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  THEND DESCANTION: Scheduled Monument (No.1004885) CONDITION: Generally satisfactory but with significant localised problems  PRIVATE CONTACT: Principal Heritage at Risk Adviser 01904 601901  THEND DESCANTION: Arable ploughing TIEND DEclining Principal Heritage at Risk Adviser 01904 601901  THEND DESCANTION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  DESCANTION: Scheduled Monument (No.1003258) CONDITION: Declining Principal Heritage at Risk Adviser 01904 601901  THEND DESCANTION: Scheduled Monument (No.1003258) CONDITION: Declining Principal Heritage at Risk Adviser 01904 601901  THEND DESCANTION: Scheduled Monument (No.1003258) CONDITION: Generally satisfactory but with significant localised problems  DESCANTION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  DESCANTION: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901	SITE NAME:	Long barrow 650m south east of Cross Th	orns Barn, Luttons	·	
Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: ROund barrow I/4 mile (400m) north west of Broom House, Luttons  DESCAPION Scheduled Monument (No.1004114) CONDITION Extensive significant problems  Declining Trans. Declining  Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three bowl barrows 200m west of Belle Vue Farm, Luttons  DESCANATION: Scheduled Monument (No.101514) CONDITION: Extensive significant problems  DESCANATION: Scheduled Monument (No.101514) CONDITION: Extensive significant problems  Declining Private Declining  Declining Private Private Principal Heritage at Risk Adviser 01904 601901  SITE NAME: ROMAN OUNBARBUTY: Arable ploughing TRAND Declining  DESCANATION: Scheduled Monument (No.1004885) CONDITION: Generally satisfactory but with significant localised problems  Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Middleton Heights round barrow, Middleton  DESCANATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  DECLINING  DECLINING  Private Declining Private Declining TRAND Declining  Declining Private Declining  Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESCANATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  DESCANATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  DESCANATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  DESCANATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  DESCANATION: Private CONTACT: Principal Heritage at Risk Adviser  DESCANATION: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1011575)	CONDITION:	Extensive significant problems	
Round barrow I/4 mile (400m) north west of Broom House, Luttons  DESIGNATION: Scheduled Monument (No.1004114) CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three bowl barrows 200m west of Belle Vue Farm, Luttons  Designation: Scheduled Monument (No.1011514) CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three bowl barrows 200m west of Belle Vue Farm, Luttons  Designation: Designatio	PRINCIPAL VULNERABILITY:		TREND:		
Scheduled Monument (No.1004114) CONDITION Extensive significant problems PRINCIPLULINERABLITY: Arable ploughing TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Three bowl barrows 200m west of Belle Vue Farm, Luttons  Scheduled Monument (No.1011514) CONDITION Extensive significant problems PRINCIPLULINERABLITY: Arable ploughing TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  TREND: Declining Private Private  Roman fort, Malton  Scheduled Monument (No.1004885) CONDITION Generally satisfactory but with significant localised problems PRINCIPLULINERABLITY: Arable ploughing TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Middleton Heights round barrow, Middleton  DESIGNATION Scheduled Monument (No.1003258) CONDITION Extensive significant problems DESIGNATION Scheduled Monument (No.1019777) CONDITION Generally satisfactory But With significant localised problems DESIGNATION Scheduled Monument (No.1019777) CONDITION Generally satisfactory But With significant localised problems DESIGNATION Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	' "	
Arable ploughing THEND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Three bowl barrows 200m west of Belle Vue Farm, Luttons  DESIGNATION: Scheduled Monument (No.1011514)  SCHEDING THEND: Declining THEND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Roman fort, Malton  DESIGNATION: Scheduled Monument (No.1004885)  SCHEDING THEND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Roman fort, Malton  DESIGNATION: Arable ploughing THEND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VILLIERABLITY: Arable ploughing THEND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Black Howe round barrow, Newton  Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Ut with significant localised problems  DESIGNATION: Policining Private CONTACT: Principal Heritage at Risk Adviser ONDITION: Declining Private Private CONTACT: Principal Heritage at Risk Adviser Private CONTACT: Private Priva	SITE NAME:	Round barrow I/4 mile (400m) north west	of Broom House,	Luttons	
OWNER TIPE Private Pri	DESIGNATION:	Scheduled Monument (No.1004114)	CONDITION:	Extensive significant problems	
STEINAME Three bowl barrows 200m west of Belle Vue Farm, Luttons  DESCRIPTION Scheduled Monument (No.1011514) CONDITION Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  STEINAME ROMAN FORT, Malton  DESCRIPTION Scheduled Monument (No.1004885) CONDITION Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  STEINAME Middleton Heights round barrow, Middleton  DESCRIPTION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  STEINAME Black Howe round barrow, Newton  SETENAME Black Howe round barrow, Newton  SCheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: OF PRINCIPAL STEINAME  PR	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
Scheduled Monument (No.1011514)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  Private  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  ROWNERTYPE  ROMAN fort, Malton  Scheduled Monument (No.1004885)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTYPE  Private  Middleton Heights round barrow, Middleton  SETE NAME: Middleton Heights round barrow, Middleton  SETE NAME: Middleton Heights round barrow, Middleton  SETE NAME: Scheduled Monument (No.1003258)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining  OWNERTYPE  Principal Heritage at Risk Adviser 01904 601901  SETE NAME: Black Howe round barrow, Newton  Scheduled Monument (No.1019777)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: ONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Declining  OWNERTYPE  Plant growth  TREND: Declining  OWNERTYPE  Private  CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:		
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Roman fort, Malton  DESIGNATION: Scheduled Monument (No.1004885) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Middleton Heights round barrow, Middleton  Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Three bowl barrows 200m west of Belle Vo	ue Farm, Luttons		
Private Contact: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Roman fort, Malton  DESIGNATION: Scheduled Monument (No.1004885) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1011514)	CONDITION:	Extensive significant problems	
STIE NAME ROMAN FOR FRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser O1904 601901  STIE NAME: Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  DESIGNATION: CONTACT: Principal Heritage at Risk Adviser O1904 601901  STIE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
DESIGNATION:  Scheduled Monument (No.1004885)  CONDITION: Generally satisfactory but with significant localised problems Declining OWNERTYPE  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Middleton Heights round barrow, Middleton  Designation: Scheduled Monument (No.1003258)  CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing  TREND: Declining OWNERTYPE: Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining OWNERTYPE: Private  CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:		
But with significant localised problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Roman fort, Malton			
PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1004885)	CONDITION:	Generally satisfactory	
Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  Desclining CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems principal vulnerability: Plant growth TREND: Declining  OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser				but with significant localised problems	
Middleton Heights round barrow, Middleton  DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems  PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	•	
DESIGNATION: Scheduled Monument (No.1003258) CONDITION: Extensive significant problems PRINCIPAL VULNERABILITY: Arable ploughing TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Black Howe round barrow, Newton  DESIGNATION: Scheduled Monument (No.1019777) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:		
PRINCIPAL VULNERABILITY:  Arable ploughing  Private  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Black Howe round barrow, Newton  DESIGNATION:  Scheduled Monument (No.1019777)  CONDITION:  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  CONTACT:  Principal Heritage at Risk Adviser	SITE NAME:	Middleton Heights round barrow, Middleto	n		
OWNER TYPE:  Private  Private  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Black Howe round barrow, Newton  DESIGNATION:  Scheduled Monument (No.1019777)  CONDITION:  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining OWNER TYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1003258)	CONDITION:	Extensive significant problems	
Black Howe round barrow, Newton  Scheduled Monument (No.1019777)  CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  OWNER TYPE: Private  CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	•	
DESIGNATION:  Scheduled Monument (No.1019777)  CONDITION:  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNER TYPE:  Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:		
but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Black Howe round barrow, Newton			
OWNERTYPE: Private contact: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1019777)	CONDITION:	but with significant localised problems	
	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	~	
	OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

CA LB LPA NP RPG SM UA WHS

SITE NAME:	Beacon Hill ringwork siege castle and Roya	l Observer Corps	post, Pickering
DESIGNATION:	Scheduled Monument (No.1019091)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 140m west of Haugh Rigg, P	ickering	
DESIGNATION:	Scheduled Monument (No.1020230)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 280m south west of Haugh	Rigg, Pickering	
DESIGNATION:	Scheduled Monument (No.1019781)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 400m north east of Haugh	Rigg, Pickering	
DESIGNATION:	Scheduled Monument (No.1019778)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 570m south of Saintoft Gra	nge, Pickering	
DESIGNATION:	Scheduled Monument (No.1020115)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 600m SSW of Saintoft Gran	ge, Pickering	
DESIGNATION:	Scheduled Monument (No.1020114)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Iron Age barrow cemetery, East Field, Rillin	gton	
DESIGNATION:	Scheduled Monument (No.1004072)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Moated site and ridge and furrow cultivation	on 230m south eas	st of Manor Farm, Scackleton
DESIGNATION:	Scheduled Monument (No.1015491)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Unknown
THE TOLET LET TOLET I	Private		Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

	Round barrow on Knapton Brow, Scampsto	on	
DESIGNATION:	Scheduled Monument (No.1004109)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Part of Leppington medieval village, a moat of the former parish church of St Helen, Sc		
DESIGNATION:	Scheduled Monument (No.1011515)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow I/2 mile (800m) NNE of Set	trington House S	effrington
		-	-
DESIGNATION:	Scheduled Monument (No.1004159)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:  OWNER TYPE:	Arable ploughing Private	TREND: CONTACT:	Declining Principal Heritage at Risk Adviser
OWNER TYPE:	rrivale	CONTACT:	01904 601901
SITE NAME:	Round barrow I/4 mile (400m) south west	of Many Thorns F	arm, Settrington
DESIGNATION:	Scheduled Monument (No.1004160)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow north east of Lawson's Wold	d Barn, Sherburn	
DESIGNATION:	Scheduled Monument (No.1003140)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private		Principal Heritage at Risk Adviser
OWNER TIPE:	Tivate	CONTACT:	01904 601901
	Three round barrows south of Prodham's V		01904 601901
SITE NAME:	Three round barrows south of Prodham's V	Wold Farm, Sherbu	01904 601901
SITE NAME: DESIGNATION:	Three round barrows south of Prodham's V		01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Three round barrows south of Prodham's V	Wold Farm, Sherbu	orn  Extensive significant problems
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing	<b>Wold Farm, Sherbu</b> CONDITION:  TREND:	orn  Extensive significant problems  Declining
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing	Vold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke of	Irn  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing Private  Aldro earthworks: a bowl barrow and part	Vold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke of	Irn  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing Private  Aldro earthworks: a bowl barrow and part 500m north west of Brown Moor Farm, Th	Vold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke or ixendale	Irn  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  In Birdsall Wold,
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing Private  Aldro earthworks: a bowl barrow and part 500m north west of Brown Moor Farm, Th Scheduled Monument (No.1007483)	Wold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke or ixendale  CONDITION:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  In Birdsall Wold, Extensive significant problems
SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing Private  Aldro earthworks: a bowl barrow and part 500m north west of Brown Moor Farm, Th Scheduled Monument (No.1007483) Arable ploughing	Wold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke or ixendale  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Birdsall Wold, Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing Private  Aldro earthworks: a bowl barrow and part 500m north west of Brown Moor Farm, Th Scheduled Monument (No.1007483) Arable ploughing Private  Aldro earthworks: a bowl barrow on Birds:	Wold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke or ixendale  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  In Birdsall Wold, Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  In the west of Brown Moor Farm, Thixend
SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY: PRINCIPAL VULNERABILITY:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing Private  Aldro earthworks: a bowl barrow and part 500m north west of Brown Moor Farm, Th Scheduled Monument (No.1007483) Arable ploughing Private	Vold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke or ixendale  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Birdsall Wold, Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION:	Three round barrows south of Prodham's V Scheduled Monument (No.1004089) Arable ploughing Private  Aldro earthworks: a bowl barrow and part 500m north west of Brown Moor Farm, Th Scheduled Monument (No.1007483) Arable ploughing Private  Aldro earthworks: a bowl barrow on Birds: Scheduled Monument (No.1007484)	Vold Farm, Sherbu  CONDITION: TREND: CONTACT:  of a cross-dyke or ixendale  CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Birdsall Wold, Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  rth west of Brown Moor Farm, Thixend Extensive significant problems

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

ITE NAME:	Aldro earthworks: a bowl barrow on Hang 400m north west of Stone Sleights Farm,T		d
DESIGNATION:	Scheduled Monument (No.1007496)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Aldro earthworks: a cross-dyke on Birdsall	Wold, 200m west	of Brown Moor Farm, Thixendale
DESIGNATION:	Scheduled Monument (No.1007485)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Barrow near Middle Plantation, Thixendale		
DESIGNATION:	Scheduled Monument (No.1004171)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Barrow west of Bradeham Farm, Thixendal	e	
DESIGNATION:	Scheduled Monument (No.1004170)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Hanging Grimston barrow group: a bowl ba	arrow 300m east o	
	Hanging Grimston barrow group: a bowl ba	arrow 300m east o	
DESIGNATION:	Scheduled Monument (No.1007906)  Arable ploughing		of Stone Sleights Farm, Thixendale  Extensive significant problems  Declining
DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007906)	CONDITION:	of Stone Sleights Farm, Thixendale  Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007906)  Arable ploughing	CONDITION: TREND: CONTACT:	of Stone Sleights Farm, Thixendale  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Scheduled Monument (No.1007906) Arable ploughing Private	CONDITION: TREND: CONTACT:	of Stone Sleights Farm, Thixendale  Extensive significant problems  Declining  Principal Heritage at Risk Adviser  01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl ba	condition:  TREND:  CONTACT:  arrow 450m north	of Stone Sleights Farm, Thixendale  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The east of Wold Farm, Thixendale Extensive significant problems Declining
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl ba Scheduled Monument (No.1007982)	CONDITION: TREND: CONTACT:  arrow 450m north	of Stone Sleights Farm, Thixendale  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  n east of Wold Farm, Thixendale Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl ba Scheduled Monument (No.1007982) Arable ploughing	condition: trend: contact:  arrow 450m north condition: trend: contact:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Declining Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl bath of the second ploughing Scheduled Monument (No.1007982) Arable ploughing Private	condition: trend: contact:  arrow 450m north condition: trend: contact:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Declining Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901
DESIGNATION: PRINCIPAL YULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL YULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl based by the second secon	CONDITION: TREND: CONTACT:  arrow 450m north CONDITION: TREND: CONTACT:	of Stone Sleights Farm, Thixendale  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The east of Wold Farm, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The west of Thixendale Grange, Thixendale Extensive significant problems Declining Declining
SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl based by the second secon	CONDITION: TREND: CONTACT:  arrow 450m north CONDITION: TREND: CONTACT:  arrow 650m south CONDITION:	of Stone Sleights Farm, Thixendale  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The east of Wold Farm, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The west of Thixendale Grange, Thixendale Extensive significant problems
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl based by the second secon	CONDITION: TREND: CONTACT:  arrow 450m north CONDITION: TREND: CONTACT:  arrow 650m south CONDITION: TREND: CONTACT:	of Stone Sleights Farm, Thixendale  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The east of Wold Farm, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The west of Thixendale Grange, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The Wold Farm,
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl base Scheduled Monument (No.1007982) Arable ploughing Private  Hanging Grimston barrow group: a bowl base Scheduled Monument (No.1008481) Arable ploughing Private  Hanging Grimston barrow group: a long base base should be supported by the second sec	CONDITION: TREND: CONTACT:  arrow 450m north CONDITION: TREND: CONTACT:  arrow 650m south CONDITION: TREND: CONTACT:	of Stone Sleights Farm, Thixendale  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The east of Wold Farm, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The west of Thixendale Grange, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The Wold Farm,
DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY: OWNER TYPE:  SITE NAME: SITE NAME: SITE NAME:	Scheduled Monument (No.1007906) Arable ploughing Private  Hanging Grimston barrow group: a bowl base of the second	CONDITION: TREND: CONTACT:  arrow 450m north CONDITION: TREND: CONTACT:  arrow 650m south CONDITION: TREND: CONTACT:	of Stone Sleights Farm, Thixendale  Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The east of Wold Farm, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The west of Thixendale Grange, Thixendale Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  The Wold Farm, Thixendale Grange, Thixendale Grange, Thixendale Thixendale Grange, Thixendale Grange, Thixendale Grange, Thixendale Gr

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

ITE NAME:	Hanging Grimston barrow group: four bow 600m SSW of Thixendale Grange, Thixenda		t of a cross dyke
DESIGNATION:	Scheduled Monument (No.1008484)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hanging Grimston barrow group: four bow	vI barrows on Unc	leby Stoop,Thixendale
DESIGNATION:	Scheduled Monument (No.1008474)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hanging Grimston barrow group: three bo	wl barrows 350m	north east of Wold Farm,Thixendale
DESIGNATION:	Scheduled Monument (No.1007977)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hanging Grimston barrow group: three bo	wl barrows 600m	south west of Thixendale Grange,Thixenc
DESIGNATION:	Scheduled Monument (No.1008483)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow north of manor house, Thix	kendale	
DESIGNATION:	Scheduled Monument (No.1004128)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow south east of Gill's Farm, Th	nixendale	
DESIGNATION:	Scheduled Monument (No.1004537)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrows south of Gill's Farm, Thixe	ndale	
DESIGNATION:	Scheduled Monument (No.1004149)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrows south west of Riggs Farm,	Thixendale	
DESIGNATION:	Scheduled Monument (No.1004554)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining .
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	The Queen Dike: part of a cross-dyke 600r	m east of Wold Fa	rm,Thixendale
DESIGNATION:	Scheduled Monument (No.1007919)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow east of Weaverthorpe Ling,	Weaverthorpe	
DESIGNATION:	Scheduled Monument (No.1004098)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow north west of Mount Spanie	el,Weaverthorpe	
DESIGNATION:	Scheduled Monument (No.1003141)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Section of linear earthwork in Pasture Plan	tation,Weavertho	rpe
DESIGNATION:	Scheduled Monument (No.1007864)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows on Weaverthorpe Past	ure,Weaverthorpe	e
DESIGNATION:	Scheduled Monument (No.1004097)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows south east of Pasture	Farm, Weaverthor	pe
DESIGNATION:	Scheduled Monument (No.1004166)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrows on Wharram Percy Wold, V	Vharram	
DESIGNATION:	Scheduled Monument (No.1004127)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow I I 00m west of High Fordon I	Farm, Willerby	
DESIGNATION:	Scheduled Monument (No.1007745)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Bowl barrow 700m north west of High Fo	rdon Farm,Willerb	у	
DESIGNATION:	Scheduled Monument (No.1007746)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Bowl barrow 800m west of High Fordon F	arm,Willerby		
DESIGNATION:	Scheduled Monument (No.1007744)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Prior Moor round barrow, Willerby			
DESIGNATION:	Scheduled Monument (No.1004106)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow south east of Willerby Wole	d House,Willerby		
DESIGNATION:	Scheduled Monument (No.1004112)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Round barrow west of Willerby Wold Hou	se,Willerby		
DESIGNATION:	Scheduled Monument (No.1004107)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901	
SITE NAME:	Two round barrows north east of Ganton	Dale, Willerby		
DESIGNATION:	Scheduled Monument (No.1004111)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
	Private	CONTACT:	Principal Heritage at Risk Adviser	
OWNER TYPE:			01904 601901	
	Two round barrows, Staxton Brow, Willerb	у	01904 601901	
SITE NAME:	Two round barrows, Staxton Brow, Willerb Scheduled Monument (No.1004090)	Y CONDITION:	Extensive significant problems	
ITE NAME: DESIGNATION:				
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1004090)	CONDITION:	Extensive significant problems Declining Principal Heritage at Risk Adviser	
SITE NAME: DESIGNATION: PRINCIPAL VULNERABILITY:	Scheduled Monument (No.1004090)  Arable ploughing	CONDITION: TREND:	Extensive significant problems Declining	
OWNER TYPE:  SITE NAME:  DESIGNATION: PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No.1004090)  Arable ploughing	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:	Scheduled Monument (No.1004090) Arable ploughing Private	CONDITION: TREND: CONTACT:	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901  Generally satisfactory	
SITE NAME:  DESIGNATION:  PRINCIPAL VULNERABILITY:  OWNER TYPE:  SITE NAME:	Scheduled Monument (No.1004090) Arable ploughing Private  Wilton Hall moated site 250m south of Ma	CONDITION: TREND: CONTACT: anor Farm, Wilton	Extensive significant problems Declining Principal Heritage at Risk Adviser 01904 601901	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Round ba	rrow I/4 mile (400m) south east of New	wton South \	Wold Farm, Wintringham
DESIGNATION:	Scheduled	Monument (No.1003136)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plo	pughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round ba	rrow 330yds (300m) NNW of Ladyhills	,Wintringha	m
DESIGNATION:	Scheduled Monument (No.1003135)		CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	A 11 1 1		TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round ba	rrow north east of Wintringham South	Wold Farm,	Wintringham
DESIGNATION:	Scheduled	Monument (No.1004163)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round ba	rrow west of Newlands Lane,Wintringl	nam	
DESIGNATION:	Scheduled	Monument (No.1004538)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable plo	oughing	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Three rou	and barrows on West Heslerton Wold,	Wintringham	
DESIGNATION:	Scheduled	Monument (No.1004110)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clip	pping	TREND:	Declining
OWNER TYPE:	Private		CONTACT:	Principal Heritage at Risk Adviser 01904 601901
Z.A.	SITE NAME:	Ebberston Hall, Ebberston and Yedingham	design of El	th water features c1718 integral to the oberston Hall and views of the wider landsca oped cascade water features (listed grade II*)
	DESIGNATION:	Registered Park and Garden Grade II*, also 5 LBs, 2 SMs	in need of a south over-	consolidation and repair, trees in parkland to
TA.	CONDITION:	Generally satisfactory but with significant localised problems		
	VULNERABILITY	e Low		
	TREND:	Declining		
POTENTIAL PROPERTY OF THE PROP		Drivate single extract	C , , D	
	OWNER TYPE:	Private, single owner	Contact: Pr	incipal Heritage at Risk Adviser 01904 60190
	OWNER TYPE:	Castle Howard Handerskelfe/		easure grounds and park with a mixture of



Castle Howard, Henderskelfe/ SITE NAME: Huttons Ambo/Slingsby/Welburn/ Bulmer/Coneysthorpe

DESIGNATION: Registered Park and Garden Grade I, also 65 LBs, 2 SMs Generally satisfactory CONDITION:

but with significant localised problems vulnerability: Low

Declining OWNER TYPE: Private, single owner

Gardens, pleasure grounds and park with a mixture of geometric and less formal features developed c1698-1738 by Charles Howard, third Earl of Carlisle and Sir John Vanbrugh (1664-1726) possibly with some advice from Stephen Switzer (1682-1745). Key buildings and structures in the landscape are in need of consolidation and repair; sections of the grand approach avenues have over-mature trees in need of replacement.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.


  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM UA WHS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site Conservation Area

#### **SCARBOROUGH**



Dovecote at Cloughton Hall, SITE NAME:

High Street, Cloughton


DESIGNATION: Listed Building Grade II, SM, CA

Very bad CONDITION: N/A OCCUPANCY: B (B) PRIORITY:

OWNER TYPE:

Dovecote, probably C17. Believed to be the only example in the country of a circular tiered dovecote. Building suffered partial collapse following heavy snowfall. Grant aid offered for repairs.

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Martin, SITE NAME:

Private

Main Street,

Seamer

Substantial C12 church with later medieval alterations. Nave roof recovered and nave south wall repaired with grant. Further stonework repairs are required, particularly to the chancel.

DESIGNATION: Listed Place of Worship Grade I, CA Poor CONDITION: F(D) PRIORITY: OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St John the Evangelist,

Baxtergate, Whitby

Early Victorian church with three parallel roofs. Main roofs reslated with grant, but further work needed to lower roofs and stonework.

DESIGNATION: Listed Place of Worship Grade II, CA CONDITION: Poor F (D) PRIORITY: OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

		AA	
			-
1			4

SITE NAME:

#### Bowl barrow 700m north of Betton Farm, East Ayton

DESIGNATION:	Scheduled Monument (No.1008128)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Bowl barrow 920m north of Betton Farm, East Ayton		
DESIGNATION:	Scheduled Monument (No.1008129)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Bowl barrow 950m north of Betton Farm, East Ayton		
DESIGNATION:	Scheduled Monument (No.1008130)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Roman signal station, Carr Naze, Filey		
DESIGNATION:	Scheduled Monument (No.1004187)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets. **ABBREVIATIONS** 

CA LB LPA NP RPG SM UA WHS

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Elf Howe round barrow, Folkton		
DESIGNATION:	Scheduled Monument (No.1004091)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Flixton Wold, Folkton		
DESIGNATION:	Scheduled Monument (No.1004113)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Flotmanby Brow, Folkton		
DESIGNATION:	Scheduled Monument (No.1004096)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow on Flotmanby Wold, Folkton		
DESIGNATION:	Scheduled Monument (No.1004095)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow south of Long Plantation, Foll	kton	
DESIGNATION:	Scheduled Monument (No.1004539)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Sharpe Howes, round barrows, Folkton		
DESIGNATION:	Scheduled Monument (No.1004182)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two round barrows north west of Danebury Manor, Folkton		
DESIGNATION:	Scheduled Monument (No.1004092)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Group of circular and rectangular enclosure	s, near Cansdale	Whin, Hunmanby
DESIGNATION:	Scheduled Monument (No.1004065)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
OWNER TIFE.			
OWINER TIPE.			01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	Round barrow south of Grange Farm, Hun	manby	
DESIGNATION:	Scheduled Monument (No.1004093)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 60m west of Beacon Farm,	Irton	
DESIGNATION:	Scheduled Monument (No.1008476)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 450m north east of Moor Ho	ouse Farm, Scarboi	rough
DESIGNATION:	Scheduled Monument (No.1008139)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow 600m north of Moor House	Farm, Scarborough	١
DESIGNATION:	Scheduled Monument (No.1008138)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Round barrow 460m south of Oliver's Mou	unt Farm, Scarboro	ough
DESIGNATION:	Scheduled Monument (No.1021233)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Section of linear earthwork on Seamer Mo	or Hill, Scarborou	gh
DESIGNATION:	Scheduled Monument (No.1008135)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Three barrows at Seamer Beacon and the	ruins of Baron Alb	ert's Tower, Scarborough
DESIGNATION:	Scheduled Monument (No.1008486)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Bowl barrow I50m north of Moor House	Farm, Seamer	
DESIGNATION:	Scheduled Monument (No.1008133)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901


- PRIORITY (FOR BUILDINGS)

  A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## NOTE: 2011 priority categories are given in brackets.

SITE NAME:	Bowl barrow 450m north west of Moor House Farm, Seamer			
DESIGNATION:	Scheduled Monument (No.1008519)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Advise 01904 601901	
SITE NAME:	Bowl barrow 550m NNW of Moor House	Farm, Seamer		
DESIGNATION:	Scheduled Monument (No.1008136)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Advise 01904 601901	
SITE NAME:	Bowl barrow 800m north west of Moor House Farm, Seamer			
DESIGNATION:	Scheduled Monument (No.1008137)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Advise 01904 601901	
SITE NAME:	Star Carr Early Mesolithic settlement site,	960m NNW of W	oodhouse Farm, Seamer	
DESIGNATION:	Scheduled Monument (No.1401425)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Advise 01904 601901	
SITE NAME:	Dean Road/Manor Road Cemetery			
	Conservation Area	CONDITION:	Very bad	
DESIGNATION:		TREND:	Improving significantly	
DESIGNATION:  VULNERABILITY:	Medium Chris Hall (LPA) 01723 232 481	TREND:	improving significantly	



Chapel to Huddleston Hall (now barn), Former chapel with C15 origins, C16 rebuilding to SITE NAME: west of house, Laith Staid Lane,

Huddleston with Newthorpe

DESIGNATION: Listed Building Grade II\* Poor Vacant OCCUPANCY: C (C) PRIORITY: Private OWNER TYPE:

the east and later alterations. The building is disused and the roof coverings are in poor repair, resulting in water ingress to the interior.

Contact: Principal Heritage at Risk Adviser 01904 601901



Huddleston Hall. SITE NAME: Laith Staid Lane,

Huddleston with Newthorpe

DESIGNATION: Listed Building Grade II\* Poor CONDITION:

Part occupied OCCUPANCY: C(C)PRIORITY:

OWNERTYPE: Private

Late C16 manor house, now used as a farmhouse. The roofs are in poor condition resulting in water ingress to the interior, and there is some decaying stonework. A full repairs programme planned but work has not yet been carried out.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM UA WHS Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Stables to Huddleston Hall, SITE NAME:

south east of house, Laith Staid Lane, Huddleston with Newthorpe

DESIGNATION: Listed Building Grade II\*

Fair CONDITION:

Part occupied OCCUPANCY:

C(C)Private OWNER TYPE:

Stables of the late C16 with C19 additions and alterations. The roof coverings have some missing tiles.

Contact: Principal Heritage at Risk Adviser 01904 601901



Abbot's Staith Buildings, SITE NAME:

Water Lane.

Selby

DESIGNATION: Listed Building Grade II\*, SM, CA

Poor CONDITION:

Part occupied OCCUPANCY:

C(C)PRIORITY: Company OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901

the nave and aisles.

C15 or early C16, two storey, 'H' shaped plan warehouse built for Selby Abbey. Mainly of magnesium limestone ashlar with some brick. The roof is modern, the building is in poor condition and the roof is deteriorating.



Church of St Wilfrid, SITE NAME:

Main Street,

Monk Fryston

DESIGNATION: Listed Place of Worship Grade I

Poor CONDITION:

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Church apparently with Anglo-Saxon origins, although predominantly C13 and C14 in date. Grant has been offered for the repair of the tower and re-roofing of

Contact: Principal Heritage at Risk Adviser 01904 601901

ASSESSMENT AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO PERSON NAMED I	[編集] 川
THE T	
	-

SITE NAME:

#### St Andrew's College and moat, 440m north east of College Farm, Acaster Selby

DESIGNATION:	Scheduled Monument (No.1017457)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Brocket Hall moated site, Appleton Roebuck		
DESIGNATION:	Scheduled Monument (No.1008228)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Mote Hill: a moated site, two fishponds and part of an adjacent field system 500m west of Nun Appleton Hall, Appleton Roebuck		
DESIGNATION:	Scheduled Monument (No.1008229)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser

SITE NAME:	Parkshaw moated site, 170m north west of Wood Farm, Balne		
DESIGNATION:	Scheduled Monument (No.1016025)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

01904 601901

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site UA WHS

SITE NAME:	Catterton Hall moated site and adjacent bu	uilding platform, C	atterton
DESIGNATION:	Scheduled Monument (No.1017456)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Castle Hill moated site, 350m south of St F	eter and St Paul's	Church, Drax
DESIGNATION:	Scheduled Monument (No.1017455)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Scurff Hall moated site, Drax		
DESIGNATION:	Scheduled Monument (No.1017485)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Kelfield moated site and fishpond, I 80m no	rth of Kelfield Ch	urch, Kelfield
DESIGNATION:	Scheduled Monument (No.1017459)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Toulston medieval village, manor house site	and early garden	earthworks, Newton Kyme cum Toulston
DESIGNATION:	Scheduled Monument (No.1017922)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Two Roman forts, two Roman camps, vicus Bronze Age barrows and Neolithic henge n		re, f Newton Kyme, Newton Kyme cum Toulsto
DESIGNATION:	Scheduled Monument (No.1017693)	CONDITION:	Extensive significant problems
RINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Danes Hills square barrow cemetery, 300m	south of Adamso	on Farm, Riccall
DESIGNATION:	Scheduled Monument (No.1018603)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

PRINCIPAL VULNERABILITY:  Drainage/dewatering OWNERTYPE:  Local authority  Drainage/dewatering OWNERTYPE:  Docal authority  Drainage/dewatering CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Thorpe Hall moated monastic grange, Selby  DESIGNATION:  Scheduled Monument (No.1017460)  Drainage/dewatering TREND: Drainage/dewatering TREND: Unknown  OWNERTYPE:  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Danes Hills square barrow cemetery on Crook Moor, Skipwith  DESIGNATION: Scheduled Monument (No.1016619)  CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNATION: Scheduled Monument (No.1015543)  CONDITION: Generally satisfactory 01904 601901	SITE NAME:	York prebendary manor moated site, 300m	north west of Ha	wthorn Farm, Riccall
Private Drainage/dewatering Private common Principal Heritage at Risk Adviser 01904 601901  Paradise Lodge moated site and grange of the Prior of Bolton, Ryther cum Ossendyke common Scheduled Monument (No.1008225) common Generally satisfactory but with significant localised problem mescric varianteement (No.1008225) common Generally satisfactory but with significant localised problem on the private Common Scheduled Monument (No.1017460) common Generally satisfactory but with significant localised problems on the private Common Scheduled Monument (No.1017460) common Generally satisfactory but with minor localised problems on the private Common Scheduled Monument (No.1017460) common Generally satisfactory but with minor localised problems on the private Common Scheduled Monument (No.1016619) common Generally satisfactory but with significant localised problems on the private Common Generally satisfactory but with significant localised problems of the private Common Scheduled Monument (No.1016619) common Generally satisfactory but with significant localised problem on the private Common Generally satisfactory but with significant localised problem on the private Common Generally satisfactory but with significant localised problem on the private Common Generally satisfactory but with significant localised problem on the private Common Generally satisfactory but with significant localised problem on the private Common Generally satisfactory but with significant localised problem on the private Common Generally satisfactory with minor localised problem on the private Common Generally satisfactory with minor localised problem on the private Common Generally unsatisfactory with minor localised problems on the private Common Private Common Generally unsatisfactory with minor localised problems on the private Common Private Private Common Generally unsatisfactory with minor localised problems on the private Common Scheduled Monument (No.1018601) common Generally unsatisfactory with minor localised problems on the private	DESIGNATION:	Scheduled Monument (No.1018212)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Scheduled Monument (No.100825)  CONDITION  Generally satisfactory but with significant localised problem renconsultations and problem to the significant localised problem renconsultation.  Drainage/dewatering  Thorpe Hall moated monastic grange, Selby  STENAME  Scheduled Monument (No.1017460)  CONDITION  Drainage/dewatering  THEND  Unknown  Principal Heritage at Risk Adviser 01904 601901  STENAME  Danes Hills square barrow cemetery on Crook Moor, Skipwith  STENAME  Danes Hills square barrow cemetery on Crook Moor, Skipwith  STENAME  Danes Hills square barrow cemetery on Crook Moor, Skipwith  STENAME  Danes Hills square barrow cemetery on Crook Moor, Skipwith  STENAME  Declining  FRANCIPLULALERABLETT:  Principal Heritage at Risk Adviser 01904 601901  STENAME  Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNAME  STENAME  Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNATION  SCHEDULALERABLETT:  Drainage/dewatering  TREND  TREND				Stable Principal Heritage at Risk Adviser
Date Hills square barrow cemetery on Crook Moor, Skipwith Danes Hills square barrow cemetery on Crook Moor, Skipwith Danes Hills square barrow cemetery on Crook Moor, Skipwith Danes Hills square barrow cemetery on Crook Moor, Skipwith Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description Danes Hills square barrow cemetery on Crook Moor, Skipwith Description	SITE NAME:	Paradise Lodge moated site and grange of the	he Prior of Bolton	n, Ryther cum Ossendyke
OWNERTHYSE  Local authority  CONNECT: Principal Heritage at Risk Adviser 01904 601901  Thorpe Hall moated monastic grange, Selby  DESIGNATION  Scheduled Monument (No.1017460)  CONDITION: Generally satisfactory but with minor localised problems  Private  Drainage/dewatering  TREND: Unknown  Private  Danes Hills square barrow cemetery on Crook Moor, Skipwith  DESIGNATION  Scheduled Monument (No.1016619)  CONDITION: Generally satisfactory but with significant localised problem proving  OWNERTHYSE  Private  Danes Hills square barrow cemetery on Crook Moor, Skipwith  DESIGNATION  Scheduled Monument (No.1016619)  CONDITION: Generally satisfactory but with significant localised problem proving  OWNERTHYSE  Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNATION  Scheduled Monument (No.1015543)  CONDITION: Generally satisfactory but with significant localised problem Improving  Private  Moated site and fishpond I 40m south of St Helen's Church, Skipwith Improving  Private  Private  CONTINCT: Principal Heritage at Risk Adviser 01904 601901  REPRODUCTION VALNEABURD  Drainage/dewatering  TREND: Improving  Private  ROUND BERTONE  ROUND BERTONE  ROUND BERTONE  ROUND BERTONE  ROUND BERTONE  Private  ROUND BERTONE  ROUND	DESIGNATION:	Scheduled Monument (No.1008225)	CONDITION:	Generally satisfactory but with significant localised problems
Thorpe Hall moated monastic grange, Selby  BERGMATION  Scheduled Monument (No.1017460)  CONDITION  Generally satisfactory but with minor localised problems  THEND: Unknown  Private  Drainage/dewatering  THEND: Unknown  Private  Danes Hills square barrow cemetery on Crook Moor, Skipwith  DESIGNATION  Scheduled Monument (No.1016619)  CONDITION  Generally satisfactory but with significant localised problem  Private  Declining  OWNER TYPE  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNATION: Scheduled Monument (No.1015543)  CONDITION: Generally satisfactory but with significant localised problem  Private  Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNATION: Scheduled Monument (No.1015543)  CONDITION: Generally satisfactory but with significant localised problem  Private  Drainage/dewatering  THEND: Drainage/dew	PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
Scheduled Monument (No.1017460)  CONDITION:  Generally satisfactory but with minor localised problems  PRINCIPAL VALINIERABLITY:  Drainage/dewatering  TINEND:  Unknown  Private  Danes Hills square barrow cemetery on Crook Moor, Skipwith  DESIGNATION:  Scheduled Monument (No.1016619)  CONDITION:  Generally satisfactory but with significant localised problem  PRINCIPAL VALINIERABLITY:  Plant growth  TINEND:  Descripal Heritage at Risk Adviser  01904 601901  TINEND:  Descripal Heritage at Risk Adviser  01904 601901  Moated site and fishpond 140m south of St Helen's Church, Skipwith  DESCRIPANTON:  Scheduled Monument (No.1015543)  CONDITION:  Scheduled Monument (No.1015543)  CONDITION:  Scheduled Monument (No.1015543)  CONDITION:  Private  Drainage/dewatering  TINEND:  Drainage/dewatering  TINEND:  Private  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  STENAME:  Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESCRIPANTON:  Scheduled Monument (No.1018604)  CONDITION:  Scheduled Monument (No.1018604)  CONDITION:  Scheduled Monument (No.1018604)  CONDITION:  Private  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  STENAME:  Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESCRIPANTON:  Scheduled Monument (No.1018601)  CONDITION:  Generally unsatisfactory with major localised problems  Private  DESCRIPANTON:  Scheduled Monument (No.1018601)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VALUERABLITY: OPRICAL VALUERABLITY:  Private	OWNER TYPE:	Local authority	CONTACT:	, ,
Drainage/dewatering TREND: Unknown OWNERTIFIE: Private CONTACT: Principal Heritage at Risk Adviser O1904 601901  STEINAME: Danes Hills square barrow cemetery on Crook Moor, Skipwith DESIGNATION: Scheduled Monument (No.1016619) CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VALUE AND DECIDING OWNERTIFIE: Private CONTACT: Principal Heritage at Risk Adviser O1904 601901  Moated site and fishpond I 40m south of St Helen's Church, Skipwith DESIGNATION: Scheduled Monument (No.1015543) CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VALUERABILITY: O Trainage/dewatering TREND: Improving OWNERTIFIE: Private CONTACT: Principal Heritage at Risk Adviser O1904 601901  STEINAME: Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith DESIGNATION: Scheduled Monument (No.1018604) CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VALUERABILITY: Plant growth TREND: Declining OWNERTIFIE: Private CONTACT: Principal Heritage at Risk Adviser O1904 601901  STEINAME: Round barrow on Skipwith Common, 810m south east of Adamson Farm, Skipwith DESIGNATION: Scheduled Monument (No.1018604) CONDITION: Generally unsatisfactory with major localised problems OWNERTIFIE: Private CONTACT: Principal Heritage at Risk Adviser O1904 601901  STEINAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems DESIGNATION: Principal Heritage at Risk Adviser O1904 601901	SITE NAME:	Thorpe Hall moated monastic grange, Selby		
Drainage/dewatering TREND: Unknown OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Danes Hills square barrow cemetery on Crook Moor, Skipwith  DESIGNATION: Scheduled Monument (No.1016619) CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VILINEABULTY: Plant growth TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Moated site and fishpond 140m south of St Helen's Church, Skipwith  DESIGNATION: Scheduled Monument (No.1015543) CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VILINEABULTY: Drainage/dewatering TREND: Improving OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESIGNATION: Scheduled Monument (No.1018604) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VILINEABULTY: Declining OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith DESIGNATION: Scheduled Monument (No.1018601) CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems DESIGNATION: Principal Heritage at Risk Adviser 01904 601901	DESIGNATION:	Scheduled Monument (No.1017460)	CONDITION:	
Danes Hills square barrow cemetery on Crook Moor, Skipwith  DESCRIPTION  Scheduled Monument (No.1016619)  CONDITION  Generally satisfactory but with significant localised problem  PRINCIPLA VULNERABILITY:  Plant growth  TREND  Declining  Private  Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESCRIPTION  STIE NAME:  Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESCRIPTION  SCHEDULED AND STIE NAME:  DESCRIPTION  Drainage/dewatering  TREND  Drainage/dewatering  TREND  Drainage/dewatering  TREND  DESCRIPTION  Private  Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESCRIPTION  STIE NAME:  Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESCRIPTION  SCHEDULED AND SCHEDULE  Private  ROUNDING  Private  ROUNDING  Private  ROUNDING  Private  ROUNDING  Private  ROUNDING  Private  ROUNDING  REPROCED Declining  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901  TREND  Declining  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901  TREND  Declining  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901  TREND  Declining  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901  TREND  Declining  Private  ROUNDING  Generally unsatisfactory with major localised problems DESCRIPTION  TREND  Declining  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901	PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	
Scheduled Monument (No.1016619)  Scheduled Monument (No.1016619)  Scheduled Monument (No.1016619)  Scheduled Monument (No.1016619)  STENAME  Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESCRIPTION  Scheduled Monument (No.1015543)  STENAME  Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESCRIPTION  SCHEDULE AND Scheduled Monument (No.1018604)  STENAME  Round Barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESCRIPTION  Scheduled Monument (No.1018604)  SCHEDULE AND SC	OWNER TYPE:	Private	CONTACT:	
Dut with significant localised problem PRINCIPAL VALNERABLITY: Plant growth TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALNERABLITY: OPTIGINATE AND PRINCIPAL VALNERABLITY: Drainage/dewatering TREND: Improving OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALNERABLITY: OPTIGINATE AND PRIVATE AND PRINCIPAL VALNERABLITY: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALNERABLITY: Plant growth TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALNERABLITY: Plant growth TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALNERABLITY: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALNERABLITY: OF Scheduled Monument (No.1018601)  PRINCIPAL	SITE NAME:	Danes Hills square barrow cemetery on Cr	ook Moor, Skipwi	th
Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNATION: Scheduled Monument (No.1015543) CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Improving Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith DESIGNATION: Scheduled Monument (No.1018604) CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining Condition: Generally unsatisfactory with major localised problems DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining CONTACT: Principal Heritage at Risk Adviser ONTACT: Principal Heritage	DESIGNATION:	Scheduled Monument (No.1016619)	CONDITION:	Generally satisfactory but with significant localised problems
STEENAME: Moated site and fishpond I 40m south of St Helen's Church, Skipwith  DESIGNATION: Scheduled Monument (No.1015543) CONDITION: Generally satisfactory but with significant localised problem PRINCIPAL VULNERABILITY: Drainage/dewatering TREND: Improving Improving CONNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME ROUND barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith DESIGNATION: Scheduled Monument (No.1018604) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: OF Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNERTYPE Private CONTACT: Principal Heritage at Risk Adviser Private CONTACT: Private Private CONTACT: Private CO	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	
DESIGNATION:  Scheduled Monument (No.1015543)  CONDITION:  Generally satisfactory but with significant localised problem with significant localised problem limproving.  Drainage/dewatering  TREND:  Improving  OWNERTYPE:  Principal Heritage at Risk Adviser 01904 601901  STE NAME:  Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESIGNATION:  Scheduled Monument (No.1018604)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNERTYPE:  Principal Heritage at Risk Adviser 01904 601901  STE NAME:  Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION:  Scheduled Monument (No.1018601)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNERTYPE:  Plant growth  TREND:  Declining  OWNERTYPE:  Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	, ,
Drainage/dewatering TREND: Improving OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESIGNATION: Scheduled Monument (No.1018604) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser  OUNDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Moated site and fishpond I40m south of St	Helen's Church, S	Skipwith
OWNER TYPE Private Private Private Private Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESIGNATION: Scheduled Monument (No.1018604) PRINCIPAL VULNERABILITY: Plant growth Private Private Private Round barrow on Skipwith Common, 810m south of Skipwith  DESIGNATION: Scheduled Monument (No.1018601) STE NAME: Round barrow on Skipwith Common, 810m south of Skipwith  DESIGNATION: Scheduled Monument (No.1018601) TREND: Declining OWNER TYPE Private Private Private Principal Heritage at Risk Adviser 01904 601901  TREND: Declining OWNER TYPE Private Principal Heritage at Risk Adviser 01904 601901  TREND: Private Principal Heritage at Risk Adviser Principal Heritage at Risk Adviser Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1015543)	CONDITION:	Generally satisfactory but with significant localised problems
Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith  DESIGNATION: Scheduled Monument (No.1018604) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser  01904 601901  SITE NAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	. 0
DESIGNATION:  Scheduled Monument (No.1018604)  PRINCIPAL VULNERABILITY:  Plant growth  Private  Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION:  Scheduled Monument (No.1018601)  STE NAME:  Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION:  Scheduled Monument (No.1018601)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNER TYPE:  Private  CONTACT:  Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
With major localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow on Skipwith Common, 800m	south east of Ad	amson Farm, Skipwith
OWNERTYPE:  Private  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION:  Scheduled Monument (No.1018601)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND: Declining  OWNERTYPE:  Private  CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1018604)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith  DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:		TREND:	9
DESIGNATION: Scheduled Monument (No.1018601) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Round barrow on Skipwith Common, 810m	south of Skipwit	h Church, Skipwith
PRINCIPAL VULNERABILITY: Plant growth TREND: Declining owner type: Private contact: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1018601)	CONDITION:	·
	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
	OWNER TYPE:	Private	CONTACT:	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

Scheduled Monument (No.1018605)	CONDITION:	Generally unsatisfactory
		with major localised problems
Plant growth	TREND:	Declining
Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
	Plant growth	Plant growth TREND:

SITE NAME:	Steeton Hall medieval magnate's residence and manorial centre, South Milford		
DESIGNATION:	Scheduled Monument (No.1015504)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Steeton medieval village, moated site and fishpone	ds, Steeton	
DESIGNATION:	Scheduled Monument (No.1017555)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901


SITE NAME:	Whitley Thorpe moated Templar grange site, 600	m north wes	t of Fulham House,Whitley
DESIGNATION:	Scheduled Monument (No.1017458)	CONDITION:	Generally satisfactory
			but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901



SITE NAME:

High, bleak, arable land near Tadcaster was the scene of a ten-hour battle in March 1461 during the Wars of the Roses. 28,000 were said to have been killed. Still actively farmed and under the plough, the below-ground battlefield archaeology - artefacts and arrowheads from the battle has been consistently targeted by metal detectorists, some unauthorised and working independently of any agreed archaeological survey. At least one episode of deep ploughing may have disturbed a possible mass grave. Contact: Principal Heritage at Risk Adviser 01904 601901

#### YORKSHIRE DALES (NP)



Barden Church, SITE NAME: B6160, Barden, Craven

Battle of Towton,

DESIGNATION: Listed Building Grade I Fair CONDITION: Vacant OCCUPANCY: C(C)PRIORITY-OWNERTYPE: Private

C16 former chapel. The interior is derelict and there is some water penetration and damage. The chapel roof has been repaired but it remains vacant. An options appraisal has been undertaken with the Estate and Yorkshire Dales National Park Authority and is due for completion in 2012.

Contact: Principal Heritage at Risk Adviser 01904 601901



Lead cupola, SITE NAME: flue and chimney, Grassington, Craven

DESIGNATION: Scheduled Monument

Poor CONDITION: N/A OCCUPANCY: PRIORITY: F(D) OWNERTYPE: Private Smelt mills, flues and chimney of a lead processing complex. Built in 1792. Some consolidation has been undertaken but the flue system is still in urgent need of repair. Grant-aided solution agreed and works are due to be completed in late summer 2012.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

## **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



ITE NAME:	Lodge Hall, Ingman Lodge Road,
	Selside, Horton in Ribblesdale,
	Cravon

Craven

Private

Farmhouse dated 1687. Structural cracks to main (east) front and bulge on north side. Roof reported to leak badly with attendant decay. Integral part of a working farm.

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Occupied OCCUPANCY: C(C)

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME:	Nappa Hall, Askrigg, Richmondshire
DESIGNATION:	Listed Building Grade I
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	F (F)
OWNER TYPE:	Private

A fortified Manor House built in 1459 for James Metcalf. A wing was added in C17. Most of the medieval portion has not been occupied for some years. There has recently been a change in ownership and some repairs have been carried out. However, the floors in the west tower are still in a rotten and dangerous state and the roof coverings over the great hall and the south east wing are in very poor condition.



Church of St Mary the Virgin, SITE NAME: Arkengarthdale, Richmondshire

Early C19 church. Masonry now in good order. Grant-aided urgent window repair is underway. Third phase of grant for re-roofing offered. Photo copyright: Owton Architects.

Contact: Principal Heritage at Risk Adviser 01904 601901

DESIGNATION: Listed Place of Worship Grade II, CA Poor CONDITION: F (F) PRIORITY: Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Margaret, Gruel Street, Hawes, Richmondshire

1851 church with fine later furnishings. Roofs in poor condition, extensive repointing required, glazing poor. Grant offered for first phase of repair.

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor D (C) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

	腁	AA	
		M	<b>A</b>
200 m	<b>用</b>	1 6	TO SHARE

SITE NAME:

SITE NAME

# Bolton Parks Lead Mine and ore works, Castle Bolton with East and West Bolton, Richmondshire

Scheduled Monument (No.1018712) Generally unsatisfactory DESIGNATION: CONDITION: with major localised problems PRINCIPAL VULNERABILITY: Extensive animal burrowing TREND: Private Principal Heritage at Risk Adviser OWNER TYPE: CONTACT:

01904 601901

#### Large univallate hillfort on Ingleborough Hill, Clapham cum Newby, Craven SITE NAME:

Scheduled Monument (No.1008876) DESIGNATION: CONDITION: Generally unsatisfactory with major localised problems Extensive visitor erosion Declining PRINCIPAL VULNERABILITY: TREND: Private Principal Heritage at Risk Adviser OWNER TYPE CONTACT:

01904 601901

#### Kinsey Cave, Giggleswick Scar, Giggleswick, Craven

DESIGNATION:	Scheduled Monument (No.1010295)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets

#### **ABBREVIATIONS** CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site

SITE NAME:	Multi-period lead mines and processing wo Grassington, Craven	rks and 20th cent	ury barytes mill on Grassington Moor,
DESIGNATION:	Scheduled Monument (No.1018333)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Sargill ore hearth lead smelt mill, on North High Abbotside, Richmondshire	Rigg, 340m south	east of Sargill Lead Mine,
DESIGNATION:	Scheduled Monument (No.1018338)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Meal Bank Quarry Hoffmann kiln, quarry a	nd lime works, Ing	leton, Craven
DESIGNATION:	Scheduled Monument (No.1020889)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Victoria Cave, Langcliffe Scar, Langcliffe, Cra	ven	
DESIGNATION:	Scheduled Monument (No.1010290)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Marrick ore hearth lead smeltmill, Marrick,	Richmondshire	
DESIGNATION:	Scheduled Monument (No.1015824)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Gunnerside Gill lead mines and ore works,	Melbecks, Richmo	ondshire
DESIGNATION:	Scheduled Monument (No.1015830)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Beldi Hill Low Level lead mine and ore wo	rks, Muker, Richmo	ondshire
DESIGNATION:	Scheduled Monument (No.1015408)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### ABBREVIATIONS

SITE NAME:	West Stonesdale lead mine and ore works, Muker, Richmondshire		
DESIGNATION:	Scheduled Monument (No.1015407)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Farfield Mill (Sedbergh)		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Robert White (LPA) 01969 652360	NEW ENTRY?:	No
SITE NAME:	Swaledale and Arkengarthdale barns and wa	alls	
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Robert White (LPA) 01969 652360	NEW ENTRY?:	No

## SOUTH YORKSHIRE

#### **BARNSLEY**



Brierley Road,
Brierley

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNERTYPE: Company

Grimethorpe Hall,

House, circa 1670, altered in C18, C19 and C20, which requires extensive repairs. Although standing in an amply sized site, the surrounding area is residential. The setting has been eroded by construction of housing to the west. Consent was granted for conversion to a restaurant in 2005, but the scheme has failed.

Contact: Principal Heritage at Risk Adviser 01904 601901



Conservatory and linking bridge at north west corner of Wentworth Castle, Stainborough

DESIGNATION: Listed Building Grade II\*, CA, RPG I
CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: F (D)

OWNERTYPE: Trust

Conservatory built in 1877, probably by Crompton and Fawkes, located immediately west of the house. The conservatory is situated in the early C18 formal gardens on the west side of the house. English Heritage grant has been offered towards the full repair of the conservatory and works are about to start. The Conservatory will be restored to use on completion.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Gun Room, Wentworth Castle, Stainborough

DESIGNATION: Listed Building Grade II\*, CA, RPG I

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNERTYPE: Trust

Probably built as a banqueting house or a bath-house, it was used as a gun room in the C19. The interior has exceptionally fine plasterwork. Repairs to the walls and roof were carried out in 2006-07, but a further phase of conservation is required to the interior which is in very poor condition.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Dovecote at Glebe Farm, Tankersley

DESIGNATION: Listed Building Grade II, SM

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

Stone built dovecote and cart shed, built in 1735 as part of the Glebe Farm for Richard Goodwin, Rector 1715-52. A particularly good example, complete with full interior and a rare set of spiked protective grilles over the dove holes. In a state of serious disrepair with a temporary roof structure in place. Potential for low key use, ancillary to residential.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

# ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS WOrld Heritage Site



Low Forge, SITE NAME: Wortley

designation: Scheduled Monument

CONDITION: N/A OCCUPANCY: C (C) OWNERTYPE: Private

Roofless remains of an early C18 water-powered iron forge, including waterwheel and tilt-hammer, associated wheelraces, forge and bloomery building; in need of repair.

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Peter including attached Church and attached wall and gateway, 1893-1910 by SITE NAME: wall and gateway to south west, Brinckman Street

Temple Moore. In generally good order; nave appears to have been re-slated. Slates to chancel roof look poor and there is salting brickwork to the Lady Chapel.

DESIGNATION:	Listed Place of Worship Grade II*
CONDITION:	Poor
PRIORITY:	C (C)
OW/NER TYPE:	Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



Bull House Chapel, SITE NAME: Manchester Road, Penistone

Non-conformist chapel, previously Presbyterian and Methodist, dated to 1692. Simple, single-storey rectangular plan and constructed from coursed stone with a stone slate roof. The chapel lies in an isolated position outside the town, adjacent to the manor. The roof and ceiling are in poor condition. Grant offered.

DESIGNATION: Listed Place of Worship Grade II Poor CONDITION:

D (D) PRIORITY: OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Helen, High Street, Thurnscoe

Victorian church with Georgian tower, the rest rebuilt in 1887. Clay tiled roofs to nave and south east corner are in poor condition, although regularly repaired. Eroded stonework to porch.

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor C(C)PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

5	1500	<b>美观</b>	13000	
1			量	

SITE NAME:

#### East Gawber Hall colliery fanhouse, 800m north east of Croft Farm, Barnsley

DESIGNATION:	Scheduled Monument (No.1017748)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Elsecar Colliery Newcomen engine, Barnsley		
DESIGNATION:	Scheduled Monument (No.1004790)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Heavy Anti-aircraft gunsite 330m south east of Lowfield Farm, Barnsley		
DESIGNATION:	Scheduled Monument (No.1019872)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

**ABBREVIATIONS** CA LB LPA NP RPG SM

UA WHS

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Monk Bretton standing cross, Barnsley		
DESIGNATION:	Scheduled Monument (No.1013765)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Rockley blast furnace, Barnsley		
designation:	Scheduled Monument (No.1004820)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Rockley engine house, Barnsley		
DESIGNATION:	Scheduled Monument (No.1004821)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Wortley Top Forge, Hunshelf		
DESIGNATION:	Scheduled Monument (No.1018262)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Flooding	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Romano-British settlements at Finkle Stree	t,Wortley	
DESIGNATION:	Scheduled Monument (No.1004801)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Water powered bloomery, iron forge and r	olling mill at Low	Forge, Wortley
DESIGNATION:	Scheduled Monument (No.1020626)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Elsecar		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving significantly

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### **DONCASTER**



SITE NAME: Moat Hall ruins. **Braithwell** 

Ruins of medieval monastic grange and post-medieval dwelling, consisting of arched doorway and low walls, in poor repair.

**DESIGNATION: Scheduled Monument** 

Very bad CONDITION: N/A OCCUPANCY:

A(A)Private OWNER TYPE:

PRIORITY-

Contact: Principal Heritage at Risk Adviser 01904 601901



Stable to Hickleton Hall including SITE NAME: the Stable Cottage and attached walls and gate piers, Hickleton Hall, Hickleton

DESIGNATION: Listed Building Grade II\*, CA, RPG II

Fair CONDITION: Vacant OCCUPANCY: E (E) PRIORITY OWNER TYPE: Charity Mid C18 stable block, now store and house with attached walls and gate piers. Possibly by James Paine, who designed Hickleton Hall, 1745-48, for Godfrey Wentworth. The stable block stands to the north of the Hall, which occupies an elevated position towards the north end of the registered site. Repairs have been carried out to the roofs and the building is now in fair condition, but disused.

Contact: Principal Heritage at Risk Adviser 01904 601901



Christ Church, SITE NAME: Thorne Road

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION: C(C)PRIORITY:

Religious organisation OWNER TYPE:

A Gothic style church dating to 1827/9. It is constructed from limestone ashlar with a slate roof and copper spire. It has a four stage south tower. Declared redundant in 1989, it was bought by Reachout Christian Fellowship in 1994. Ten years later and at significant cost, it opened again for worship. Requires urgent remedial roof works and repairs to falling internal ceiling plaster.

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Peter. SITE NAME: Warmsworth Road Known as 'The White Church'. Consecrated in 1942 and mentioned in a wartime broadcast from Berlin by the notorious 'Lord Haw Haw'. Windows in poor condition.



DESIGNATION: Listed Place of Worship Grade II

Poor

OWNER TYPE: Religious organisation Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St George, Church Lane.

Doncaster


Major Victorian church, replacing the medieval parish church which was destroyed by fire. Several phases of repair undertaken, but further work required to stonework, including central tower. Grant offered.

DESIGNATION: Listed Place of Worship Grade I CONDITION: Poor

D (New entry) PRIORITY:


Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Lawrence. SITE NAME Station Road,

Norman church. C12 origin, C13 arcades, the rest mostly C15. Tower in poor condition.



Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

**ABBREVIATIONS** CA LB LPA NP RPG SM

UA WHS

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Church of St Mary, SITE NAME:

Main Street, Sprotbrough

Medieval church, significant decay to medieval oak roofs. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade I, CA

Very bad CONDITION: D (D) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Site of St Helen's Chapel, Barnburgh and Harlin	gton	
DESIGNATION:	Scheduled Monument (No.1004799)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Manor Holt moated site, Bawtry		
DESIGNATION:	Scheduled Monument (No.1012453)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moat Hall moated site and site of external anci	llary buildings	, Braithwell
DESIGNATION:	Scheduled Monument (No.1012461)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman Ridge, Roman road, north west of Don	caster, Brodsw	rorth
DESIGNATION:	Scheduled Monument (No.1003672)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman fort at Robin Hood's Well, Burghwallis		
DESIGNATION:	Scheduled Monument (No.1002930)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman potteries 300yds (270m) north east of	Rossington Br	ridge, Cantley
DESIGNATION:	Scheduled Monument (No.1004787)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE: 2011 priority categories are given in brackets.

SITE NAME:	Castle Hills motte and bailey castle, Langthw	aite, Adwick le S	treet, Doncaster
DESIGNATION:	Scheduled Monument (No.1013654)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moat Hills moated site, Bentley, Doncaster		
DESIGNATION:	Scheduled Monument (No.1013655)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Edlington Wood Roman settlement, Edlingto	n	
DESIGNATION:	Scheduled Monument (No.1004824)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Moat Hill moated site, Fenwick		
DESIGNATION:	Scheduled Monument (No.1011920)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Castle Hill, Hampole		
DESIGNATION:	Scheduled Monument (No.1004794)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Icehouse 720m south east of Bath House Fa	rm, High Melton	
DESIGNATION:	Scheduled Monument (No.1020715)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Earthworks on Sutton Common, Norton		
DESIGNATION:	Scheduled Monument (No.1004816)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

SITE NAME:	Rossington Roman fort, Rossington		
DESIGNATION:	Scheduled Monument (No.1004823)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Thorpe in Balne moated site, chapel and fis	hpond,Thorpe in	Balne
DESIGNATION:	Scheduled Monument (No.1012111)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Tickhill Castle, Tickhill		
DESIGNATION:	Scheduled Monument (No.1004828)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Hatfield High Street		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Marr		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Mexborough		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	St George's, Doncaster		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Thorne Central, Thorne		
designation:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No
SITE NAME:	Thorne Road, Doncaster		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ATIONS
Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site CA LB LPA NP RPG SM UA WHS

SITE NAME:	Woodlands		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Malcolm Thomas (LPA) 01302 735199	NEW ENTRY?:	No

<b>PEAK</b>	DISTRICT	(NP)
		(131)

SITE NAME:	Bailey Hill motte and bailey castle, High Bradfield, Bradfield, Sheffield		
DESIGNATION:	Scheduled Monument (No.1013217)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Castle Hill motte and bailey castle, High Bradfield, Bradfield, Sheffield		
DESIGNATION:	Scheduled Monument (No.1017612)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Cowell Flat prehistoric field system, 350m s	south east of Mort	timer House, Bradfield, Sheffield
DESIGNATION:	Scheduled Monument (No.1017833)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### **ROTHERHAM**



ITE NAME:	25 and 27 High Street
	Rotherham

Known as The Three Cranes. Late medieval house. Signs of structural decay, faulty rainwater goods.

IC I I CI CC I I

DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Contact: Principal Heritage at Risk Adviser 01904 601901



CITE NAME	Keppels Column, Admirals Crest,
SITE NAME:	Thorpe Common, Rotherham
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)

Monumental column built 1773-80. Now on the edge of Wentworth Woodhouse Estate. The building is closed to the public, although emergency repairs have been carried out to the viewing platform and stairwell. There are significant structural cracks and stonework erosion. The internal staircase is unsafe.

Contact: Principal Heritage at Risk Adviser 01904 601901



Thorpe Salvin Old Hall (ruins of), SITE NAME: Ladyfield Road, Thorpe Salvin

Gatehouse and imposing three storey south facade of mid C16 stone-built mansion built by Henry Sanford (died 1582) standing in an open courtyard. Grant has been offered for a condition survey.

DESIGNATION: Listed Building Grade II\*, SM, CA CONDITION: Poor N/A OCCUPANCY: C (C) PRIORITY: OWNERTYPE: Private

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

OWNERTYPE: Local authority

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented

### NOTF: 2011 priority categories are given in brackets.

# **ABBREVIATIONS** CA LB LPA NP RPG SM UA WHS



Stable block and riding school, SITE NAME: Wentworth Woodhouse,

Wentworth

DESIGNATION: Listed Building Grade I, RPG II\*

Fair CONDITION: Vacant OCCUPANCY: PRIORITY: E (E)

OWNERTYPE: Private

Stable block and riding school, I 760s, situated approx 300 metres north-west of the house.

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Michael and All Angels, SITE NAME: Church Street, Great

Houghton

C17 chapel, severe stone decay and poor roofs.

Grant offered for repair.



DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Very bad D (D)

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Leonard, SITE NAME: Doncaster Road,

Thrybergh

Medieval church with fine monuments. Roofs in poor condition. Grant offered for repair.



DESIGNATION: Listed Place of Worship Grade II\*, CA

Very bad CONDITION: D (D) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Peter and St Paul, Todwick

Medieval church with CII nave, CI4 chancel and CI5 tower with C18 and C19 alterations. Tower parapets

and pinnacles in poor condition.

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION: Poor PRIORITY: C(C)

OWNERTYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

		1	WAS	
		7	1000	
歷	21		78	1

SITE NAME:

#### Roman Ridge (Roman road): section 135yds (120m) long, east of Hoober House, Brampton Bierlow

DESIGNATION:	Scheduled Monument (No.1004830)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Roman Ridge (Roman road): section south of Hoober House, Brampton Bierlow		
DESIGNATION:	Scheduled Monument (No.1004831)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Roman Ridge: section 300yds (270m) long	Roman Ridge: section 300yds (270m) long on Birchcliff Bank, Brampton Bierlow		
DESIGNATION:	Scheduled Monument (No.1004809)	CONDITION:	Generally satisfactory	
			but with significant localised problems	
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			01904 601901	

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

#### NOTE: 2011 priority categories are given in brackets.

**ABBREVIATIONS** CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

Scheduled Monument (No.1004810)  CONJUNTATION  PRINCIPAL MINIMATION  Arable clipping  Private  CENTRO  Principal Heritage at Risk Adviser  O1904 601901  SCHEMPLE  Kimberworth motte and bailey castle, Rotherham  Datoming  TRAND  Scheduled Monument (No.1013469)  COLUMNA  CONJUNTATION  CONJUNTATION	SITE NAME:	Roman Ridge: section 400yds (370m) long s	outh of Abdy Far	m, Brampton Bierlow
Arable dipping Trivate Contact Principal Heritage at Risk Adviser 01904 601901  Kimberworth motte and bailey castle, Rotherham  Scheduled Monument (No.1013469) Condition Generally unsatisfactory with major localised problems  Private Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherh Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherh Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherh Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 110yds (100m) long on the Office Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherh Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 400yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherh Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham Declining Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham Declining Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham Declining Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham Contact Principal Heritage at Risk Adviser 01904 601901  Billiande Roman Ridge:	DESIGNATION:	Scheduled Monument (No.1004810)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Scheduled Monument (No.1013469)  Scheduled Monument (No.1013469)  Scheduled Monument (No.1013469)  Scheduled Monument (No.1013469)  Scheduled Monument (No.1004813)  Scheduled Monument (No.1004835)  Scheduled Monument (No.1004813)  Scheduled Monument (No.1004814)  Scheduled Monument (No.1004811)  Scheduled Monument (No.1004807)				Declining Principal Heritage at Risk Adviser
with major localised problems Dumping TRENDS Declining Declining Connectives Private CONNECT: Principal Heritage at Risk Adviser 01904 601901  SETERAME: Roman Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherh DESCRIPTION Scheduled Monument (No.1004835) CONDITION Scheduled Monument (No.1004835) CONDITION DECLINING DESCRIPTION Scheduled Monument (No.1004835) CONDITION DECLINING DESCRIPTION Private CONTECT: Principal Heritage at Risk Adviser 01904 601901  SETERAME: Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherh DESCRIPTION DESCRIPTION Scheduled Monument (No.1004813) CONDITION DESCRIPTION DESCRIPTION Scheduled Monument (No.1004813) CONDITION DESCRIPTION DESCRI	SITE NAME:	Kimberworth motte and bailey castle, Rothe	erham	
Description  Roman Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherh Description  Scheduled Monument (No.1004835)  Scheduled Monument (No.1004836)  Scheduled Monument (No.1004833)  Scheduled Mon	DESIGNATION:	Scheduled Monument (No.1013469)	CONDITION:	,
ROMAN Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm, Rotherh (1940-10048) Scheduled Monument (No.1004835) CONDICENT Generally satisfactory but with minor localised problems ownexture. Private Contact: Private Private Contact: Private Private Contact: Private Contact: Private Private Contact: Private Contact: Private Private Private Private Contact: Private	PRINCIPAL VULNERABILITY:	Dumping	TREND:	
Scheduled Monument (No.1004835)  CONDITION  Generally satisfactory but with minor localised problems  Private  Private  Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherh  DESCRATION  Scheduled Monument (No.1004813)  CONDITION  Generally satisfactory but with significant localised problems  PRIVATE LOCATION:  Arable clipping  TRIND  Declining  OWNERTYPE  Private  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901  TRIND  Declining  OWNERTYPE  Private  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901  CONTINCT:  PRINCIPAL VALUE ARABILITY:  Moderate visitor erosion  TRIND  Declining  CONNERTYPE  Local authority  CONTINCT:  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESCRATION  Scheduled Monument (No.1004808)  CONDITION:  Generally satisfactory but with significant localised problems  Declining  CONNERTYPE  Local authority  CONTINCT:  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESCRATION:  Scheduled Monument (No.1004811)  CONTINCT:  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESCRATION:  Scheduled Monument (No.1004811)  CONTINCT:  Principal Heritage at Risk Adviser 01904 601901	OWNER TYPE:	Private	CONTACT:	·
Dut with minor localised problems Declining Declining Private Private Description Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherh DESCRIPTION SCHEMANIE ROMAN RIdge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherh DESCRIPTION DESCRIPTIO	SITE NAME:	Roman Ridge: section I I Oyds (100m) long, 4	50yds (410m) NI	NE of Kimberworth Park Farm, Rotherhan
Private Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherh DESIGNATION: Scheduled Monument (No.1004813) CONDITION Generally satisfactory but with significant localised problems PRINCIPAL VALNERABILITY: Arable clipping TREND: Declining OWNER TYPE Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME ROMAN RIdge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham DESIGNATION: Scheduled Monument (No.1004808) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VALNERABILITY: Moderate visitor erosion TREND: Declining OWNER TYPE Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME ROMAN RIdge: section 400yds (370m) long in Wath Wood, Rotherham DESIGNATION: Scheduled Monument (No.1004811) CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME ROMAN RIGGE: section 400yds (370m) long in Wath Wood, Rotherham DESIGNATION: Scheduled Monument (No.1004811) CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME ROMAN RIGGE: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother DESIGNATION: Scheduled Monument (No.1004807) CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME ROMAN RIGGE: South east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother DESIGNATION: Scheduled Monument (No.1004807) CONDITION: Generally satisfactory but with significant localised problems DESIGNATION: Deterioration — in need of management TREND: Declining Principal Heritage at Risk Adviser Pr	DESIGNATION:	Scheduled Monument (No.1004835)	CONDITION:	
ROMAR RIDGE: SECTION 300yds (270m) long north of Birchwood (east of Chemical Cottages), Rotherhobersonanton  Scheduled Monument (No.1004813)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VALNERABLITY:  Arable clipping  TREND:  Declining  CONTACT:  Private  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESIGNATION:  Scheduled Monument (No.1004808)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VALNERABLITY:  Moderate visitor erosion  TREND:  Declining  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  STEENAME:  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION:  Scheduled Monument (No.1004811)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VALNERABLITY:  Moderate vehicle damage/erosion  TREND:  Declining  CONNERTIYE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  STEENAME:  ROMAN Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherstone  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  STEENAME:  ROMAN Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherstone  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  STEENAME:  ROMAN Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherstone  CONTACT:  Principal Heritage at Risk Adviser  01904 601901	PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	<u> </u>
Scheduled Monument (No.1004813)  CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VILLIERABILITY: Arable clipping  TREND: Declining  OWNER TYPE  Private  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESIGNATION: Scheduled Monument (No.1004808)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: Moderate visitor erosion  TREND: Declining  OWNER TYPE  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No.1004811)  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No.1004811)  CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VILLIERABILITY: Moderate vehicle damage/erosion  TREND: Declining  OWNER TYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherson Designation: Scheduled Monument (No.1004807)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: OCNITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: OCNITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: OCNITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: OCNITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: Ocnition: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: Ocnition: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: Ocnition: Generally satisfactory but with significant localised problems  PRINCIPAL VILLIERABILITY: Ocnition: Generally satisfactory but with significant localised probl	OWNER TYPE:	Private	CONTACT:	
Deterioration:  Arable clipping  TREND:  Declining  OWNERTYPE  Private  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESIGNATION:  Scheduled Monument (No.1004808)  OWNERTYPE  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STE NAME:  Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  Designation:  Scheduled Monument (No.1004808)  OWNERTYPE  Local authority  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STE NAME:  Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION:  Scheduled Monument (No.1004811)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate vehicle damage/erosion  TREND:  Declining  OWNERTYPE  Local authority  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STE NAME:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherson  Designation:  Scheduled Monument (No.1004807)  Scheduled Monument (No.1004807)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Detlining  OWNERTYPE  Local authority  Principal Heritage at Risk Adviser  Detlining  OWNERTYPE  Detlining	SITE NAME:	Roman Ridge: section 300yds (270m) long r	orth of Birchwoo	od (east of Chemical Cottages), Rotherhan
Private CONTACT: Principal Heritage at Risk Adviser 01904 601901  ROMANETYPE ROMANIE: Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham DESIGNATION: Scheduled Monument (No.1004808) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Moderate visitor erosion TREND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion TREND: Declining CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherson Contact: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherson Contact: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherson Contact: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Deterioration — in need of management TREND: Declining 0000000000000000000000000000000000	DESIGNATION:	Scheduled Monument (No.1004813)	CONDITION:	·
ROMAN Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane, Rotherham  DESIGNATION:  Scheduled Monument (No.1004808)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate visitor erosion  TREND: Declining  OWNERTYPE  Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No.1004811)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion  TREND: Declining  OWNERTYPE  Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rotherson  DESIGNATION: Scheduled Monument (No.1004807)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management  TREND: Declining  OWNERTYPE  Local authority  Declining  OWNERTYPE  Local authority  Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	<u> </u>
DESIGNATION:  Scheduled Monument (No.1004808)  CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Moderate visitor erosion  TREND: Declining OWNER TYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No.1004811) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion  TREND: Declining OWNER TYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother than the significant localised problems  PRINCIPAL VULNERABILITY: Designation: Scheduled Monument (No.1004807) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Private	CONTACT:	
But with significant localised problems PRINCIPAL VULNERABILITY: Moderate visitor erosion TREND: Declining OWNERTYPE Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No.1004811) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion TREND: Declining OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Roth DESIGNATION: Scheduled Monument (No.1004807) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Roman Ridge: section 400yds (370m) long f	rom Hill Top Lane	to Little Common Lane, Rotherham
CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No.1004811) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion TREND: Declining  OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother Designation: Scheduled Monument (No.1004807) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining  OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1004808)	CONDITION:	· · · · · · · · · · · · · · · · · · ·
Roman Ridge: section 400yds (370m) long in Wath Wood, Rotherham  DESIGNATION: Scheduled Monument (No.1004811) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion TREND: Declining  OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser  01904 601901  ROMAN Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Rother than the significant localised problems  DESIGNATION: Scheduled Monument (No.1004807) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining  OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	9
DESIGNATION:  Scheduled Monument (No.1004811)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Moderate vehicle damage/erosion  TREND:  Declining  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Roth  DESIGNATION:  Scheduled Monument (No.1004807)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  OWNER TYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser	OWNER TYPE:	Local authority	CONTACT:	
but with significant localised problems PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Roth DESIGNATION: Scheduled Monument (No.1004807) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Deterioration — in need of management TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Roman Ridge: section 400yds (370m) long in	n Wath Wood, Ro	therham
OWNERTYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  SITE NAME:  Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Roth DESIGNATION:  Scheduled Monument (No.1004807)  CONDITION:  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining OWNERTYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1004811)	CONDITION:	·
Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top), Roth DESIGNATION:  Scheduled Monument (No.1004807)  Scheduled Monument (No.1004807)  CONDITION:  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY:  Deterioration — in need of management  TREND:  Declining  OWNER TYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	-	TREND:	
DESIGNATION: Scheduled Monument (No.1004807) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Deterioration – in need of management TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Local authority	CONTACT:	
but with significant localised problems  PRINCIPAL VULNERABILITY: Deterioration – in need of management TREND: Declining  OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Roman Ridge: south east of Hill Top (section	n 700yds (660m)	long, Meadowhall Road to Hill Top), Rothe
PRINCIPAL VULNERABILITY: Deterioration – in need of management TREND: Declining  OWNER TYPE: CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1004807)	CONDITION:	
	PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
	OWNER TYPE:	Local authority	CONTACT:	

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Swinton Pottery (The Rockingham Works),	310m and 120m r	north west of Keeper's Cottage, Rotherha
DESIGNATION:	Scheduled Monument (No.1020067)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate natural erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman Ridge: section 330yds (300m) long,	south of Dog Ken	nel Pond, Wentworth Park, Wentworth
DESIGNATION:	Scheduled Monument (No.1004833)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman Ridge: section 500yds (460m) long,	north of Dog Ken	nel Pond,Wentworth Park,Wentworth
DESIGNATION:	Scheduled Monument (No.1004832)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Doncaster Road, Rotherham Town Centre		
			Very bad
DESIGNATION:	Conservation Area	CONDITION:	very bad
DESIGNATION: VULNERABILITY:	Conservation Area Medium	CONDITION: TREND:	Deteriorating Deteriorating
			,
vulnerability: Contact:	Medium	TREND:	Deteriorating
VULNERABILITY: CONTACT: SITE NAME:	Medium Jonathan Bell (LPA) 01709 823 811	TREND:	Deteriorating
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban	TREND: NEW ENTRY?:	Deteriorating No
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban Conservation Area	TREND:  NEW ENTRY?:  CONDITION:	Deteriorating No  Very bad
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban  Conservation Area Low	TREND:  NEW ENTRY?:  CONDITION:  TREND:	Deteriorating No  Very bad Improving
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban  Conservation Area Low Jonathan Bell (LPA) 01709 823 811	TREND:  NEW ENTRY?:  CONDITION:  TREND:	Deteriorating No  Very bad Improving
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban  Conservation Area Low Jonathan Bell (LPA) 01709 823 811  Rotherham Town Centre	TREND:  NEW ENTRY?:  CONDITION:  TREND:  NEW ENTRY?:	Deteriorating No  Very bad Improving No
VULNERABILITY:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban  Conservation Area Low Jonathan Bell (LPA) 01709 823 811  Rotherham Town Centre  Conservation Area	TREND: NEW ENTRY?:  CONDITION: TREND: NEW ENTRY?:	Deteriorating No  Very bad Improving No  Very bad
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban  Conservation Area Low Jonathan Bell (LPA) 01709 823 811  Rotherham Town Centre  Conservation Area Low	TREND: NEW ENTRY?:  CONDITION: TREND: NEW ENTRY?:  CONDITION: TREND:	Deteriorating No  Very bad Improving No  Very bad Improving
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  VULNERABILITY:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban  Conservation Area Low Jonathan Bell (LPA) 01709 823 811  Rotherham Town Centre  Conservation Area Low Jonathan Bell (LPA) 01709 823 811	TREND: NEW ENTRY?:  CONDITION: TREND: NEW ENTRY?:  CONDITION: TREND:	Deteriorating No  Very bad Improving No  Very bad Improving
VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:  DESIGNATION:  VULNERABILITY:  CONTACT:	Medium Jonathan Bell (LPA) 01709 823 811  Greasborough, Rotherham Urban  Conservation Area Low Jonathan Bell (LPA) 01709 823 811  Rotherham Town Centre  Conservation Area Low Jonathan Bell (LPA) 01709 823 811  Wales, Rotherham South	TREND: NEW ENTRY?:  CONDITION: TREND: NEW ENTRY?:  CONDITION: TREND: NEW ENTRY?:	Deteriorating No  Very bad Improving No  Very bad Improving No





Loxley United Reformed Church, SITE NAME: Loxley Road,

Bradfield

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: OCCUPANCY: Vacant PRIORITY: C (C) OWNERTYPE: Private Former church, 1787. Closed in 1994. Recently suffered from further vandalism, condition deteriorating.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

## ABBREVIATIONS

ATIONS
Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site CA LB LPA NP RPG SM UA WHS



Leah's Yard, SITE NAME:

20-22 Cambridge Street,

Sheffield

DESIGNATION: Listed Building Grade II\*, CA

Poor CONDITION: Vacant OCCUPANCY: D(D)PRIORITY

OWNER TYPE: Local authority

Mid C19 cutlery/silversmithing works, with late C19 alterations. General decay, some fire damage. Use for shops and food/drink agreed and included in "New Retail Quarter" proposals. Some patch repairs to the roof have been carried out.

Contact: Principal Heritage at Risk Adviser 01904 601901

Cemetery chapel built in circa 1836. Lead has been stolen from the roof and not reinstated, risking further

structural deterioration.



SITE NAME: Nonconformist Chapel,

> General Cemetery, Cemetery Road, Sheffield

DESIGNATION: Listed Building Grade II\*, CA, RPG II\*

Poor CONDITION: Vacant OCCUPANCY: A(A)PRIORITY: Trust

OWNER TYPE:



Wicker Arch and adjoining viaduct, SITE NAME: The Wicker,

Sheffield

Listed Building Grade II\* DESIGNATION:

CONDITION:

Part occupied OCCUPANCY:

C (C) PRIORITY-OWNER TYPE: Company Railway viaduct, 1848. Main arch listed grade II\* has been cleared and overhauled but the remaining arches are suffering from stone theft (parapets) and general lack of maintenance. Many of the adjacent (grade II listed) viaduct arches are in use for workshops but remain in poor repair.

Contact: Principal Heritage at Risk Adviser 01904 601901

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Gateway and adjoining walls at garden entrance to Oakes Park, Norton, Sheffield

Listed Building Grade II\*, CA, RPG II DESIGNATION:

Poor CONDITION: N/A OCCUPANCY: C(C)PRIORITY-

Private

Contact: Principal Heritage at Risk Adviser 01904 601901

Early C18 and early C19 gateway with ornamental iron gates leading to C18 gardens. The gates are rusty and the gate piers are in poor condition. The park is also at risk.



Seventh Day Adventist Church SITE NAME: adjoining school and boundary wall, Andover Street

Victorian chapel, now Seventh Day Adventist Church. Roofs and rainwater goods in poor condition.



DESIGNATION: Listed Place of Worship Grade II, CA

Poor CONDITION: C(C)PRIORITY:

OWNER TYPE: Religious organisation Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Paul. Wordsworth Avenue,

Sheffield

1960s church by Basil Spence. Repairs carried out to body of church, but extensive repair needed to the concrete cloisters which extend from the front of the church. A grant has been offered for repairs.

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION:

PRIORITY: B (New entry)

OWNERTYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

## **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

SITE NAME:	Little Matlock rolling mill immediately sout	h and east of Oliv	e Terrace, Bradfield
DESIGNATION:	Scheduled Monument (No.1019857)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Handlands Romano-British settlement, 460	m south west of \	Noodseats Farm, Ecclesfield
DESIGNATION:	Scheduled Monument (No.1017835)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Willow Garth moated site and fishpond, Ed	clesfield	
DESIGNATION:	Scheduled Monument (No.1012477)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Former Sanderson's Darnall Steelworks and	d Don Valley Glass	sworks, Darnall Road, Sheffield
DESIGNATION:	Scheduled Monument (No.1021424)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Mousehole Forge, Malin Bridge, Sheffield		
DESIGNATION:	Scheduled Monument (No.1004804)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Roman Ridge: section 600yds (550m) long	between Jenkin La	ne (now Road) and Tylers Street, Sheffield
DESIGNATION:	Scheduled Monument (No.1004806)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	The Shepherd Wheel, Sheffield		
DESIGNATION:	Scheduled Monument (No.1002931)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Iron Age and Roman quern workings on Wharncliffe Rocks, Stocksbridge		
DESIGNATION:	Scheduled Monument (No.1004802)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 01904 601901



Oakes Park, SITE NAME: Sheffield

DESIGNATION: Registered Park and Garden Grade II, also CA, 9 LBs

Extensive significant problems CONDITION:

VULNERABILITY: High TREND: Declining

OWNER TYPE: Mixed, multiple owners

Gardens and pleasure grounds with early to mid C18 origins, an early C19 terrace and parkland probably of early C19 date. Park and gardens compromised by multiple use, condition of park is poor and listed structures in very poor condition.

Contact: Principal Heritage at Risk Adviser 01904 601901



Sheffield General Cemetery, SITE NAME: Sheffield

DESIGNATION: Registered Park and Garden Grade II\*,

also CA, 9 LBs

CONDITION: Generally unsatisfactory

with major localised problems

Declining

ocal authority, multiple owners

Cemetery of 1836 designed by Sheffield architect Samuel Worth (fl. 1830) with a chapel, catacombs and a cemetery office, and a layout which makes dramatic use of a quarried hillside site. An extension of 1846 for Anglican burials, laid out by Robert Marnock (1800-89). The cemetery retains both its Anglican and Non-Conformist Chapels (listed grade II\*) the latter a building at risk. Site managed by The Friends of Sheffield General Cemetery.

Contact: Principal Heritage at Risk Adviser 01904 601901

	SITE NAMI	=			Kelham Isl	and
2.314			上海		OWNER TYPE:	Lo
2	1/2		1樓	1	TREND:	D
The same of		11			VULNERABILITY	: H
- 65	I BETTER	N2	TECHNOLOGY NO	200 Sec.		

#### d

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	John Stonard (LPA) 0114 273 4472	NEW ENTRY?:	Yes

SITE NAME:	Sheffield	General	Cemetery	/
------------	-----------	---------	----------	---

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	John Stonard (LPA) 0114 273 4472	NEW ENTRY?:	No

DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	John Stonard (LPA) 0114 273 4472	NEW ENTRY?:	No

#### **WEST YORKSHIRE**

#### **BRADFORD**



Manningham Mill (ancillary buildings SITE NAME: and boiler house), Heaton Street, Heaton, Bradford

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Fair

OCCUPANCY: Part occupied

C (F) PRIORITY

OWNERTYPE: Company

Silk mill, with boiler house, chimney and warehouse. Built in 1873. Scheme of residential and office conversion complete. Mill no longer a risk but ancillary buildings and boiler house are.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site UA WHS



Leventhorpe Hall, SITE NAME: 1289 and 1291 Thornton Road, Lower Grange, Bradford

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY: D(D)PRIORITY: OWNERTYPE: Private Late C17 house with C19 additions. Windows are broken, the roof is sagging with missing slates. The east wall is failing. The site in general has substantially deteriorated but not the Hall. Residential scheme has consent for the whole site, but work has stalled.

Contact: Principal Heritage at Risk Adviser 01904 601901




SITE NAME: Mill Building at Low Mills, Low Mill Lane.

Keighley

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: Vacant OCCUPANCY: D (D) PRIORITY: OWNER TYPE: Company Late C18. Early cotton mill, adjacent to supermarket and car park. Application approved for residential use but little progress on site as yet.



Fair CONDITION:

Part occupied OCCUPANCY: F (F) PRIORITY: OWNER TYPE: Company

Main four storey spinning mill complex. The engine house, which still contains the mill engine, is deteriorating. Part converted to residential use, part in commercial and manufacturing use. The Chimney was extensively repaired in 2005.

Contact: Principal Heritage at Risk Adviser 01904 601901

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Clement, SITE NAME: Barkerend Road

Church dating to 1894, of dressed limestone with slate roof. Its principle feature of interest is the interior designed by Morris and Co. Grant-aided repairs are underway to the nave and north aisle roofs.

DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Poor
PRIORITY:	F (F)
OWNER TYPE:	Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of All Saints, SITE NAME: Little Horton Lane

Noble Victorian church with prominent south east tower and spire. Previous phases of repair complete, but some high-level stonework is in poor repair. Grant offered for repairs.

DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Poor
PRIORITY:	D (F)
OWNER TYPE:	Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Chad, St Chad's Road

1916 Arts and Crafts church. Poor roofs to east apses and Lady Chapel. Grant offered for roof repairs.

DESIGNATION:	Listed Place of Worship Grade II, CA
CONDITION:	Poor
PRIORITY:	D (D)
OWNER TYPE:	Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

**ABBREVIATIONS** CA LB LPA NP RPG SM

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site



Church of St Paul, SITE NAME: St Paul's Avenue

Small Gothic church dating to 1838 and constructed from sandstone with ashlar dressings. Grant offered for repairs to the tower, spire and rainwater goods.

DESIGNATION: Listed Place of Worship Grade II, CA Poor CONDITION:

PRIORITY: D (D) Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Stephen, Donisthorpe Street, Bradford

Victorian city church. The roofs are in poor condition, leading to extensive water penetration and timber decay. A grant has been offered.

DESIGNATION: Listed Place of Worship Grade II

D (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



St Michael and All Angels, SITE NAME:

Church Street, Haworth, Keighley

Large Victorian church with C16 tower. Roof coverings in poor condition and deterioration of mural paintings.

Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II\*, CA

Poor CONDITION: D (D) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St James, Thornton Road,

Thornton

Large Victorian church with Morris glass. Slate roofs in poor condition. Grant offered for repairs.

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: Poor D (D) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Late prehistoric enclosed settlement known	as Round Dykes	Camp on Addingham Low Moor, Addingham
DESIGNATION:	Scheduled Monument (No.1018259)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Cup and ring marked rock north of Pennythorn Hill, Baildon		
DESIGNATION:	Scheduled Monument (No.1012684)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Cup-marked rock on slight bank north east of Glovershaw quarry, Baildon		
DESIGNATION:	Scheduled Monument (No.1009724)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

**ABBREVIATIONS** CA LB LPA NP RPG SM Conservation Area

Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site UA WHS

Scheduled Monument (No.1009718) cospinos Generally unsatisfactory with major localised problems (No.1009718) cospinos (Generally unsatisfactory with major localised problems (No.1012408) cospinos (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, including adjacent cup-marked rock, Baildon usosonios (Scheduled Monument (No.1012408) cospinos (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, including adjacent cup-marked rock, Baildon usosonios (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, including adjacent cup-marked rock, Baildon usosonios (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, including adjacent cup-marked rock, Baildon usosonios (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon usosonios (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904 601901)  White Northernmost of two cairns east of Glovershaw quarry, Baildon (September 19904	SITE NAME:	Enclosed settlement known as 'Soldier's Trench' including a cup-marked rock, Baildon				
Extensive visitor erosion  Extensive visitor erosion  Extensive visitor erosion  Extensive  Local authority  Northermost of two cairns east of Glovershaw quarry, including adjacent cup-marked rock, Baildon control  Extensive visitor erosion  Extensive visitor eros	DESIGNATION:	Scheduled Monument (No.1009718)	CONDITION:	·		
Scheduled Monument (No.1013408)  Scheduled Monument (No.1013408)  Scheduled Monument (No.1013408)  Scheduled Monument (No.1013408)  Setting Owners (Scheduled Monument (No.1012683)  Setting Owners (No.1012683)  Scheduled Monument (No.1012683)  Setting Owners (No.1012684)  Scheduled Monument (No.1012676)  Setting Owners (No.1012676)  Se				Declining Principal Heritage at Risk Adviser		
with major localised problems Plant growth Declining Compared Declining Plant growth Declining D	SITE NAME:	Northernmost of two cairns east of Glove	rshaw quarry, inclu	iding adjacent cup-marked rock, Baildon		
Plant growth TIBBLE CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Round cairm and curving bank on Pennythorn Hill, Balldon  Scheduled Monument (No.1012683) CONTEXT: With major localised problems  Pennopal Audistration: Plant growth TIBBLE Declining  OWNERTIFIE ROUND Cairm on east flank of Baildon Hill, Baildon  Stre NAME: Round cairm on east flank of Baildon Hill, Baildon  Scheduled Monument (No.1012676) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Scheduled Monument (No.1012676) CONTEXT: Declining  OWNERTIFIE Local authority CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009722) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009722) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009722) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  Scheduled Monument (No.1009725) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONTEXT: Principal Heritage at Risk Adviser 01904 601901  Stre NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONTEXT: Principal Heritage at Risk Adviser 01904 601901	DESIGNATION:	Scheduled Monument (No.1013408)	CONDITION:	·		
ROUND CAITY AND CONTROL DESIGNATION   Scheduled Monument (No.1012683)   CONDITION   Generally unsatisfactory with major localised problems    Plant growth   TREND   Declining   Principal Heritage at Risk Adviser   01904 601901    STEINAME   Round cairn on east flank of Baildon Hill, Baildon    DESIGNATION   Scheduled Monument (No.1012676)   CONDITION   Generally satisfactory but with significant localised problems    PRINCIPAL VALIDEMABLETY   Plant growth   TREND   Declining    OWNEX TIPE   Local authority   CONTROL   Principal Heritage at Risk Adviser    O1904 601901    STEINAME   Small cup-marked rock 30m east of Glovershaw quarry, Baildon    DESIGNATION   Scheduled Monument (No.1009722)   CONDITION   Generally unsatisfactory with major localised problems    PRINCIPAL VALIDEMABLETY:   Extensive visitor erosion   TREND   Declining    OWNEX TIPE   Local authority   CONTROL   Principal Heritage at Risk Adviser    O1904 601901    STEINAME   Southernmost of two cairns east of Glovershaw quarry, Baildon    DESIGNATION   Scheduled Monument (No.1009725)   CONTROL   Principal Heritage at Risk Adviser    O1904 601901    STEINAME   Southernmost of two cairns east of Glovershaw quarry, Baildon    DESIGNATION   Scheduled Monument (No.1009725)   CONTROL   Principal Heritage at Risk Adviser    O1904 601901    STEINAME   Southernmost of two cairns east of Glovershaw quarry, Baildon    DESIGNATION   Scheduled Monument (No.1009725)   CONTROL   Principal Heritage at Risk Adviser    O1904 601901    STEINAME   Cairn 330m north of Woodhead on Harden Moor, Bradford    DESIGNATION   Scheduled Monument (No.1018239)   CONDITION   Generally satisfactory but with significant localised problems    Declining   Principal Heritage at Risk Adviser    O1904 601901   TREND   Declining   Principal Heritage at Risk Adviser    O1904 601901   TREND   Declining   Principal Heritage at Risk Adviser    O1904 601901   TREND   DECINING   Principal Heritage at Risk Adviser    O1904 601901   TREND   DECINING   Principal Heritage at Risk Adviser    O1904	PRINCIPAL VULNERABILITY:	Plant growth	TREND:			
Scheduled Monument (No.1012683)  CONDITION.  Generally unsatisfactory with major localised problems  Declining  CONTINCT:  Principal Heritage at Risk Adviser  01904 601901  AREAD:  CONDITION:  Generally unsatisfactory with major localised problems  Declining  CONTINCT:  Principal Heritage at Risk Adviser  01904 601901  CONDITION:  Generally satisfactory but with significant localised problems  Declining  CONTINCT:  Principal Heritage at Risk Adviser  01904 601901  CONTINCT:  Principal Heritage at Risk Adviser  01904 601901  CONTINCT:  CONTINCT:	OWNER TYPE:	Local authority	CONTACT:			
With major localised problems  Plant growth  Round cairn on east flank of Baildon Hill, Baildon  DESCINATION:  Round cairn on east flank of Baildon Hill, Baildon  DESCINATION:  Scheduled Monument (No.1012676)  CONDITION:  Plant growth  DESCINATION:  Plant growth  DESCINATION:  Scheduled Monument (No.1012676)  CONDITION:  Principal Heritage at Risk Adviser 01904 601901  Generally satisfactory but with significant localised problems  PRINCIPAL VALINTABRILITY:  DESCINATION:  DESCINATION:  Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESCINATION:  Scheduled Monument (No.1009722)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VALINTABRILITY:  Declining  OWNERTYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  DESCINATION:  Scheduled Monument (No.1009725)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VALINTABRILITY:  DEClining  OWNERTYPE:  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STENAME:  Southernmost of two cairns east of Glovershaw quarry, Baildon  DESCINATION:  Scheduled Monument (No.1009725)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VALINTABRILITY:  Declining  OWNERTYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  STENAME:  Cairn 330m north of Woodhead on Harden Moor, Bradford  DESCINATION:  Scheduled Monument (No.1018239)  CONTACT:  Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALINTABRILITY:  DECLINING  DESCINATION:  Scheduled Monument (No.1018239)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VALINTABRILITY:  DECLINING  DESCINATION:  DESCINATION:  Principal Heritage at Risk Adviser 01904 601901  PRINCIPAL VALINTABRILITY:  DECLINING  DESCINATION:  Principal Heritage at Risk Adviser 01904 601901	SITE NAME:	Round cairn and curving bank on Pennytho	orn Hill, Baildon			
PRINCIPAL VALNERABLITY:  Description  Streame:  Round cairn on east flank of Baildon Hill, Baildon  Streame:  Round cairn on east flank of Baildon Hill, Baildon  Streame:  Round cairn on east flank of Baildon Hill, Baildon  Streame:  Scheduled Monument (No.1012676)  Condition:  Generally satisfactory but with significant localised problems principal Heritage at Risk Adviser oli904 601901  Streame:  Small cup-marked rock 30m east of Glovershaw quarry, Baildon  Description:  Scheduled Monument (No.1009722)  Condition:  Generally unsatisfactory with major localised problems  Principal Heritage at Risk Adviser oli904 601901  Extensive visitor erosion  Trend:  Contract:  Principal Heritage at Risk Adviser oli904 601901  Streame:  Southernmost of two cairns east of Glovershaw quarry, Baildon  Description:  Scheduled Monument (No.1009725)  Condition:  Generally unsatisfactory with major localised problems  Principal Heritage at Risk Adviser oli904 601901  Streame:  Southernmost of two cairns east of Glovershaw quarry, Baildon  Description:  Generally unsatisfactory with major localised problems  Principal Heritage at Risk Adviser oli904 601901  Streame:  Cairn 330m north of Woodhead on Harden Moor, Bradford  Description:  Cairn 330m north of Woodhead on Harden Moor, Bradford  Description:  Contract:  Principal Heritage at Risk Adviser oli904 601901  Figure Market  Cairn 330m north of Woodhead on Harden Moor, Bradford  Description:  Contract:  Principal Heritage at Risk Adviser oli904 601901  Figure Market  Cairn 330m north of Woodhead on Harden Moor, Bradford  Description:  Contract:  Principal Heritage at Risk Adviser oli904 601901  Figure Market  Cairn 330m north of Woodhead on Harden Moor, Bradford  Description:  Contract:  Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1012683)	CONDITION:	the state of the s		
ROUND CAIRM AND CAIRM BUTTY PLANT BESIDEN AND CONTRACTS  ROUND CAIRM AUGUSTATION Scheduled Monument (No.1012676)  ESTE NAME  Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESCRATION Scheduled Monument (No.1009722)  STIE NAME  Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESCRATION Scheduled Monument (No.1009722)  CONTRACTS  PRINCIPAL VULNERABUTY:  Extensive visitor erosion  TREND:  Declining  CONTRACTS  Principal Heritage at Risk Adviser  O1904 601901  STIE NAME:  Southernmost of two cairns east of Glovershaw quarry, Baildon  DESCRATION:  SCHEDULA GONTRACTS  Principal Heritage at Risk Adviser  O1904 601901  STIE NAME:  Southernmost of two cairns east of Glovershaw quarry, Baildon  DESCRATION:  Scheduled Monument (No.1009725)  CONDITION:  Generally unsatisfactory  with major localised problems  PRINCIPAL VULNERABUTY:  Plant growth  THEND:  Declining  OWNERTYPE:  Local authority  CONTRACTS  Principal Heritage at Risk Adviser  O1904 601901  STIE NAME:  Cairn 330m north of Woodhead on Harden Moor, Bradford  DESCRATION:  Scheduled Monument (No.1018239)  CONTRACTS  Principal Heritage at Risk Adviser  O1904 601901  STIE NAME:  Cairn 330m north of Woodhead on Harden Moor, Bradford  DESCRATION:  Scheduled Monument (No.1018239)  CONDITION:  Generally satisfactory  but with significant localised problems  PRINCIPAL VULNERABUTY:  Plant growth  THEND:  Declining  OWNERTYPE:  Local authority  CONTRACTS  Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
DESIGNATION: Scheduled Monument (No.1012676) condition: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009722) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Declining  OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725) CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Scheduled Monument (No.1009725) CONDITION: Generally unsatisfactory with major localised problems  DESIGNATION: Declining  OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  SCHEDURAL VULNERABILITY: Plant growth TREND: Declining  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  DESIGNATION: Principal Heritage at Risk Adviser	OWNER TYPE:	Local authority	CONTACT:			
Dut with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  Local authority  Declining  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009722) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Declining  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STEENAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE: Local authority Plant growth TREND: Declining  OWNERTYPE: Plant growth TREND: Declining  OWNERTYPE: Plant growth TREND: Declining  OWNERTYPE: Principal Heritage at Risk Adviser	SITE NAME:	Round cairn on east flank of Baildon Hill, B	saildon			
CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009722) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VILLNERABILITY: Extensive visitor erosion TREND: Declining  OWNERTYPE Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VILLNERABILITY: Plant growth TREND: Declining  OWNERTYPE Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VILLNERABILITY: Plant growth TREND: Declining  OWNERTYPE Local authority CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1012676)	CONDITION:	· · · · · · · · · · · · · · · · · · ·		
STIE NAME:  Small cup-marked rock 30m east of Glovershaw quarry, Baildon  DESIGNATION:  Scheduled Monument (No.1009722)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Extensive visitor erosion  TREND: Declining  OWNERTYPE:  Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  OWNERTYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  STIE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  OWNERTYPE: Local authority  Plant growth  TREND: Declining  OWNERTYPE: Local authority  Plant growth  TREND: Declining  OWNERTYPE Local authority  Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
DESIGNATION: Scheduled Monument (No.1009722) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Extensive visitor erosion TREND: Declining  OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser  01904 601901  Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725) CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser  01904 601901  STEE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	OWNER TYPE:	Local authority	CONTACT:			
With major localised problems  PRINCIPAL VULNERABILITY: Extensive visitor erosion  TREND: Declining  OWNERTYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  OWNERTYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  OWNERTYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Small cup-marked rock 30m east of Glover	rshaw quarry, Baild	on		
OWNERTYPE  Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION: Scheduled Monument (No.1009725)  CONDITION: Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  OWNERTYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239)  CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth  TREND: Declining  OWNERTYPE: Local authority  CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1009722)	CONDITION:	·		
SITE NAME:  Southernmost of two cairns east of Glovershaw quarry, Baildon  DESIGNATION:  Scheduled Monument (No.1009725)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  CONTACT:  Principal Heritage at Risk Adviser  01904 601901   Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION:  Scheduled Monument (No.1018239)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNER TYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining		
DESIGNATION:  Scheduled Monument (No.1009725)  CONDITION:  Generally unsatisfactory with major localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  CONTACT:  Principal Heritage at Risk Adviser  01904 601901  Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION:  Scheduled Monument (No.1018239)  CONDITION:  Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNER TYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser	OWNER TYPE:	Local authority	CONTACT:			
With major localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNERTYPE: Local authority CONTACT: Principal Heritage at Risk Adviser  01904 601901  SITE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Southernmost of two cairns east of Glover	shaw quarry, Baild	on		
PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser 01904 601901  SITE NAME: Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1009725)	CONDITION:			
Cairn 330m north of Woodhead on Harden Moor, Bradford  DESIGNATION: Scheduled Monument (No.1018239) CONDITION: Generally satisfactory but with significant localised problems  PRINCIPAL VULNERABILITY: Plant growth TREND: Declining  OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining		
DESIGNATION:  Scheduled Monument (No.1018239)  CONDITION:  Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY:  Plant growth  TREND:  Declining  OWNER TYPE:  Local authority  CONTACT:  Principal Heritage at Risk Adviser	OWNER TYPE:	Local authority	CONTACT:			
but with significant localised problems PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	SITE NAME:	Cairn 330m north of Woodhead on Harde	n Moor, Bradford			
PRINCIPAL VULNERABILITY: Plant growth TREND: Declining OWNER TYPE: Local authority CONTACT: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1018239)	CONDITION:	Generally satisfactory but with significant localised problems		
,	PRINCIPAL VULNERABILITY:	Plant growth	TREND:	-		
	OWNER TYPE:	Local authority	CONTACT:	_		

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

SITE NAME:	Twelve Apostles stone circle, Burley Moor,	Burley	
DESIGNATION:	Scheduled Monument (No.1011763)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Late prehistoric enclosed settlement know	n as Castle Stead	Ring, Cullingworth
DESIGNATION:	Scheduled Monument (No.1018258)	CONDITION:	Generally satisfactory
DESIGNATION:	Scrieduled Floridifient (140.1010250)	CONDITION:	but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Late prehistoric enclosed settlement know	n as Catstones Ri	ng on Catstones Hill, Cullingworth
DESIGNATION:	Scheduled Monument (No.1018240)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Cairnfield, carved rocks and associated cur east of Gill Head Reservoir, llkley	ved bank at north	west end of Green Crag Slack,
DESIGNATION:	Scheduled Monument (No.1013872)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Cup and Ring marked rock known as the H	Hanging Stone Roc	k, Ilkley
DESIGNATION:	Scheduled Monument (No.1012008)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Enclosure with carved rocks and disturbed	cairn known as G	Green Crag Enclosure, Ilkley
DESIGNATION:	Scheduled Monument (No.1012840)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901
SITE NAME:	Two cup marked rocks in path south east of	of quarry at Cow	and Calf Rocks, Ilkley
DESIGNATION:	Scheduled Monument (No.1012838)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

ATIONS
Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site CA LB LPA NP RPG SM UA WHS



Whinburn, SITE NAME: Keighley

DESIGNATION: Registered Park and Garden Grade II

also 3 LBs

Generally satisfactory CONDITION:

but with minor localised problems

vulnerability: Low

Unknown

OWNERTYPE: Private, single owner

Gardens and pleasure grounds partly laid out c1897 with additional formal landscaping and features dating from 1912 to 1938, with some design work in the latter period by TH Mawson and Son. Formerly owned by Bradford City Council, now in private ownership and lay vacant for a number of years suffering decay and vandalism. New owners in process of repairing house and grounds.

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Apsley Crescent, Manningham, Bradford		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
	,		
SITE NAME:	Devonshire Park and Cliffe Castle, Keighley		
	Conservation Area		Door
DESIGNATION:	Low	CONDITION:	Poor
VULNERABILITY:		TREND:	Deteriorating No.
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
SITE NAME:	Great Horton		
DECICNIATION I	Conservation Area	CONDITION	Very bad
DESIGNATION: VULNERABILITY:	Low	CONDITION: TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
CONTACT:	JOHACNOYA (EIA) 012/1 133/32	INEVV EINTRE:	INO
SITE NAME:	Haworth, Keighley		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
CONTACT.	JOHN (CN OYU (E171) 012/11 133732	INEVV EINTIKI!.	140
SITE NAME:	Idle and The Green		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
	, , , ,		
SITE NAME:	Keighley Town Centre		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
	Jan. 1911 (2007)		
SITE NAME:	North Park Road		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
			No
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	INU
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	INO
CONTACT:  SITE NAME:	Jon Ackroyd (LPA) 01274 433952  St Paul	NEW ENTRY?:	INO
		NEW ENTRY?:  CONDITION:	Very bad
SITE NAME:	St Paul		
SITE NAME:  DESIGNATION:	St Paul  Conservation Area	CONDITION:	Very bad

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM UA WHS

Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site

SITE NAME:	The Goitside, Bradford		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Jon Ackroyd (LPA) 01274 433952	NEW ENTRY?:	No
SITE NAME:	Thornton		
SITE NAME:  DESIGNATION:	Thornton  Conservation Area	CONDITION:	Very bad
		CONDITION: TREND:	Very bad Deteriorating

#### BRADFORD / KIRKLEES / LEEDS



SITE NAME: Battle of Adwalton Moor, Drighlington

DESIGNATION: Registered Battlefield

CONDITION: Generally unsatisfactory with major localised problems


Declining

moorland outside Bradford in which some 14,000 men fought, gave control of the north of England to the Royalists. The battlefield faces various development pressures, notably from an industrial zone at its west end.

The 1643 battle during the English Civil War on

Contact: Principal Heritage at Risk Adviser 01904 601901

#### CALDERDALE



SITE NAME: Double aisled barn to north west of Kirklees Priory Gatehouse, Kirklees Park, Brighouse

DESIGNATION: Listed Building Grade I
CONDITION: Fair
OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNER TYPE: Private

VULNERABILITY: Medium

OWNERTYPE: Private

TRENID:

Aisled barn. One of the farm buildings of the Priory (now gone), with a C15 timber frame, which was later stone-clad. Whole complex continuing to decay. North east corner of stables and north threshing porch appear unstable. A report on development options is under consideration by the owners.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Home Farm Building No. 6, Kirklees Park, Brighouse

DESIGNATION: Listed Building Grade II\*
CONDITION: Very bad

OCCUPANCY: Vacant
PRIORITY: A (A)
OWNERTYPE: Private

Early C17 cowhouse, two cell house, possibly slaughter house. Gable wall partially collapsed and unstable.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Kirklees Priory Gatehouse,

Kirklees Park, Brighouse

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor
OCCUPANCY: Vacant
PRIORITY: A (A)
OWNER TYPE: Private

Gatehouse to the Priory (now gone). Early C16, part timber-framed. Holding repairs in place, but beginning to fail. Feasibility and consent for office or dwelling recently obtained. Timber decay ongoing, so that work is becoming urgently necessary.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: L-shaped aisled barn, Kirklees Park,

Brighouse

DESIGNATION: Listed Building Grade II\*

CONDITION: Fair
OCCUPANCY: Vacant
PRIORITY: C (C)
OWNER TYPE: Private

Aisled barn, early C16, encased in stone during the early to mid C17. Part of a little used farm complex. Area of roof missing to north and some timber decay to frame.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



Malthouse, SITE NAME: Kirklees Park, **Brighouse** 

DESIGNATION: Listed Building Grade I

Fair CONDITION: Vacant OCCUPANCY: C(C)PRIORITY: Private OWNER TYPE:

Malthouse, late C17. It forms part of a little used farm complex. Building appears to be in a stable condition.

Contact: Principal Heritage at Risk Adviser 01904 601901



Scout Hall, SITE NAME: Lee Lane. Halifax

PRIORITY:

OWNER TYPE:

DESIGNATION:

Late C17 house. Part repaired with English Heritage grant, part derelict. Repair and reuse under discussion with Conservation Officer at Calderdale.

DESIGNATION: Listed Building Grade II\* Poor CONDITION: Vacant OCCUPANCY: B (B)

Private

Contact: Principal Heritage at Risk Adviser 01904 601901



Former lock-up, SITE NAME: 121 Keighley Road, Illingworth, Halifax

Listed Building Grade II\*

Located on the north side of the A629 Halifax -Keighley Road, the lock-up is a small two storey building of coursed sandstone walls and stone slate roof dated 1823. The building is vacant. The roof covering and roof drainage is in very poor condition.

Very bad CONDITION: Vacant OCCUPANCY: PRIORITY: A(A)

OWNERTYPE: Local authority

Contact: Principal Heritage at Risk Adviser 01904 601901



Broad Bottom Old Hall, SITE NAME: Mytholmroyd, Hebden Royd

Late medieval timber-framed open hall encased in stone in the mid C16. Watertight but vacant for some years. Vulnerable to decay without a sustaining use.

DESIGNATION: Listed Building Grade II\* Fair CONDITION: Vacant C(C)PRIORITY: Private OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Barn to north west SITE NAME: of Greenwood Lee, Widdop Road, Heptonstall

Late C16 aisled barn. Major failure of roof structure and loss of roof covering. Residential conversion of the barn and nearby outbuildings has been approved.

Listed Building Grade II\* DESIGNATION: Very bad CONDITION: Vacant OCCUPANCY: C (C) PRIORITY-OWNERTYPE: Private

Todmorden Town Hall,

Contact: Principal Heritage at Risk Adviser 01904 601901



Halifax Road, Todmorden DESIGNATION: Listed Building Grade I, CA Poor CONDITION: Part occupied

C (New entry)

Town Hall opened in 1875. Designed by John Gibson for Samuel, John and Joshua Fielden, local textile manufacturers. Classically detailed in the form of an apsidal temple raised on a high basement. The impressive triangular pediment contains finely carved statuary. The left hand side represents

Lancashire and the right hand side Yorkshire.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

ABBREVIATIONS

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site



SITE NAME:

Church of St Mary, Salt Drake, Halifax

Small 1848 church with west tower and spire. Repairs to the spire are complete. Roof repairs are underway with grant aid.

DESIGNATION: Listed Place of Worship Grade II Poor CONDITION:

F (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901

1857 classical chapel and Sunday school. Extensive repairs carried out to roofs but rainwater goods still poor and high level pointing required. Grant offered.

SITE NAME: Hope Baptist Church, New Road. Hebden Bridge, Hebden Royd

DESIGNATION: Listed Place of Worship Grade II, CA CONDITION: Poor

F (F) PRIORITY: Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Christ Church, SITE NAME:

Wharfe Street, Sowerby Bridge Fine early C19 town church with prominent west tower. Lower parts of the church repaired with grant. Tower roof and parapets poor and grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II

Poor CONDITION:

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Camp at Kirklees Park, Calderdale		
DESIGNATION:	Scheduled Monument (No.1005806)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Mill gas plant, Shaw Lodge Mills, Calderdale		
DESIGNATION:	Scheduled Monument (No.1005783)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Ventilation chimney and furnace house 260m south of Park Farm, Calderdale		
DESIGNATION:	Scheduled Monument (No.1017655)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Blackstone Edge Roman road, Ripponden		
DESIGNATION:	Scheduled Monument (No.1005819)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)


- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets. **ABBREVIATIONS** Conservation Area

CA LB LPA NP RPG SM Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site UA WHS

SITE NAME:	Cairnfield on Ringstone Edge Moor, 240m	south west of Clay	House, Ripponden
DESIGNATION:	Scheduled Monument (No.1018560)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Akroydon		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Kate Peach (LPA) 01422 392267	NEW ENTRY?:	No
SITE NAME:	Elland		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Kate Peach (LPA) 01422 392267	NEW ENTRY?:	No
SITE NAME:	Todmorden		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Kate Peach (LPA) 01422 392267	NEW ENTRY?:	No

#### **KIRKLEES**



Milnsbridge House, SITE NAME: 2-6 Dowker Street, Huddersfield

DESIGNATION: Listed Building Grade II\*, CA CONDITION: Fair Part occupied OCCUPANCY: PRIORITY: E (E) Private OWNER TYPE:

Mid C18 house now in engineering use. Pediments conceal modern flat roof. Scheme approved for residential conversion but works not yet commenced.

Contact: Principal Heritage at Risk Adviser 01904 601901



Westwood Mills. SITE NAME: Lowestwood Lane, Linthwaite, Huddersfield DESIGNATION: Listed Building Grade II\*, CA Very bad CONDITION: Vacant OCCUPANCY:

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering. Consents for conversion to residential use and new build residential development approved October 2005.

Hopton Congregational Church, SITE NAME: Calder Road, Mirfield DESIGNATION: Listed Building Grade II\*

A(A)OWNERTYPE: Company

Fair

Vacant

C(C)

PRIORITY:

CONDITION:

OCCUPANCY:

OWNERTYPE: Private

PRIORITY:

Former church and attached school buildings to rear dated 1829. Largely unaltered and retaining box pews in the body of the church and original windows throughout. Water penetration has resulted in patches of timber decay and a failing roof truss. Planning permission granted for enabling development subject to a \$106 agreement over phasing of repair work to the church. Some repairs to roof already carried out.

Contact: Principal Heritage at Risk Adviser 01904 601901

Contact: Principal Heritage at Risk Adviser 01904 601901



PRIORITY (FOR BUILDINGS)

Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

D Slow decay; solution agreed but not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use). Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. NOTE: 2011 priority categories are given in brackets. **ABBREVIATIONS** 

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Christ Church, SITE NAME: Church Lane, Batley and Liversedge 1812-16 by Thomas Taylor of Leeds. Gothic in style with west tower. Tower roofs are in poor repair. Grant offered.

DESIGNATION: Listed Place of Worship Grade II

CONDITION:

PRIORITY: D (New entry)

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Parish Church of St Peter, Kirkgate,

Birstall,

Batley and Liversedge

One of the earliest churches to occupy the present site of St Peter's was built circa I 100. The present church was essentially rebuilt in the 1860s. Grant aid has been offered

for roof and masonry repairs.

DESIGNATION: Listed Place of Worship Grade II\*, CA CONDITION:

D (D) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of the Holy Spirit, SITE NAME:

> Bath Road. Heckmondwike, Batley and Liversedge

Roman Catholic church, 1914-15, with minor late C20 alterations. Byzantine revival style. Grant offered for roof and window repairs.

Listed Place of Worship Grade II, CA DESIGNATION: Poor CONDITION:

D (D) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Mary,

Spen Lane. Cleckheaton 1850-51 by Dobson of Leeds, Gothic in style with north west tower. Tower in poor repair. Chancel and south transept roofs are leaking. Grant offered.

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME:

Church of St Aidan, Radcliffe Street, Skelmanthorpe, Denby Dale

St Aidan's was opened on September 28 1895. Urgent repairs have been carried out to the bell-cote and chimney. Further roof repairs will be required in

the future.

DESIGNATION: Listed Place of Worship Grade II, CA CONDITION:

C(C)PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME:

Church of St Michael and All Angels, Church Street, Dewsbury

Fine medieval tower, chancel and side chapels. Nave and aisles by GE Street. The Savile Chapel, built in 1477 contains fine glass of the same date. This rare medieval survival of glass is now in danger and needs to be displayed within a controlled environment if it is to survive. Grant has been offered for this purpose and also to carry out a programme of urgent conservation works to restore important C17 and C18 funerary monuments, all of which have suffered damage

from water ingress.

Contact: Principal Heritage at Risk Adviser 01904 601901



PRIORITY:

CONDITION:

Poor D (New entry)

OWNER TYPE: Religious organisation

DESIGNATION: Listed Place of Worship Grade I

### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

**ABBREVIATIONS** CA LB LPA NP RPG SM UA WHS

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME: Church of St Peter, Kirkgate, Huddersfield The present church is the third to have stood on the site and was built in I 836. The internal plaster work and the roofs have been repaired with grant aid. A further grant has been offered towards stonework repairs.

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION: Poor PRIORITY: D (F)

owner type: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

1829 by John Oates in Gothic style. Repairs are needed to tower roof. Grant offered.

SITE NAME: Church of St Stephen, Lidget Street, Huddersfield

DESIGNATION: Listed Place of Worship Grade II

condition: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

Church of 1857-59 by Sir CG Scott. South west tower

SITE NAME: Church of St Thomas, Manchester Road,

Manchester Road, and spire. Roofs in poor condition. Grant offered.
Huddersfield

DESIGNATION: Listed Place of Worship Grade II\*

condition: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: The Apostolic Church, Mountjoy Road, Huddersfield Small mid-C19 Apostolic Church constructed from ashlar to facade, with rock-cut stone elsewhere and rusticated quoins. Simple rectangular plan with four bay facade. In poor condition.

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: Poor PRIORITY: C (C)

OWNERTYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St John, St John's Road, Huddersfield Fine Victorian church by William Butterfield. West tower and spire. Structural movement in south wall. Grant offered.

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION: Poor PRIORITY: B (A)

OWNERTYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

1785-86 classical chapel with stone slate roof. Roofs in



Shelley Methodist Church, Shelley Far Bank,

Kirkburton

poor repair. Grant offered for repairs.

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor

PRIORITY: D (New entry)

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets. ABBREVIATIONS
CA Conser
LB Listed E
LPA Local P
NP Nationa
RPG Registe
SM Schedu

UA WHS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Church of St Bartholomew, SITE NAME:

Greens End Road,

Meltham

Georgian church with early Victorian tower and late Victorian chancel. The tower stonework is in poor condition and the interior damp. The roof coverings are failing. Grant offered for tower repair.

DESIGNATION: Listed Place of Worship Grade II

Poor CONDITION:

PRIORITY: D (New entry)

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St James, Church Street.

Slaithwaite and Marsden

1746 classical church, Victorian tower and chancel. Galleried interior. Tower parapets and roof are in poor condition. Grant offered.

DESIGNATION: Listed Place of Worship Grade II

D (New entry) PRIORITY:

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Emley Day Holes, 200m east of Churchill Farm, Denby Dale		
DESIGNATION:	Scheduled Monument (No.1017656)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Late prehistoric enclosed settlement on Castle Hill, 550m north of Broadstone Lodge, Denby Dale			
DESIGNATION:	Scheduled Monument (No.1018554)	CONDITION:	Extensive significant problems	
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining	
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser	
			01904 601901	

DESIGNATION: Scheduled Monument (No.1005786)  PRINCIPAL VULNERABILITY: Scrub/tree growth  OWNER TYPE: Private  CONDITION: Generally satisfactory but with significant localised problems  TREND: Declining  CONTACT: Principal Heritage at Risk Adviser  0.1904-601901	SITE NAME:	Medieval ironstone pits south of Bentley Grange,	Denby Dale	
PRINCIPAL VULNERABILITY: Scrub/tree growth TREND: Declining OWNER TYPE: Private contact: Principal Heritage at Risk Adviser	DESIGNATION:	Scheduled Monument (No.1005786)	CONDITION:	Generally satisfactory
OWNER TYPE: Private CONTACT: Principal Heritage at Risk Adviser				but with significant localised problems
	PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
01904 601901	OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
01701 001701				01904 601901

SITE NAME:	Crosland Lower Hall moated site, Meltham		
DESIGNATION:	Scheduled Monument (No.1013896)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

SITE NAME:	Castle Hall Hill motte and bailey castle, Mirfield		
DESIGNATION:	Scheduled Monument (No.1009929)	CONDITION:	Generally unsatisfactory
			with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

  C Clared.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

### **ABBREVIATIONS**

CA LB LPA NP RPG SM UA WHS Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site

SITE NAME:	Birkby, Huddersfield		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Anne Ross (LPA) 01484 222066	NEW ENTRY?:	No
SITE NAME:	Dewsbury		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Anne Ross (LPA) 01484 222066	NEW ENTRY?:	No
SITE NAME:	Edgerton, Huddersfield		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Anne Ross (LPA) 01484 222066	NEW ENTRY?:	No
CONTACT:	Anne Ross (LPA) 01484 222066	NEW ENTRY?:	
CONTACT:  SITE NAME:	Anne Ross (LPA) 01484 222066  Holmfirth	NEW ENTRY?:	
		NEW ENTRY?:  CONDITION:	
SITE NAME:	Holmfirth		No
SITE NAME:  DESIGNATION:	Holmfirth  Conservation Area	CONDITION:	No Poor

#### **LEEDS**



Stank Hall quasi-manorial site, Dewsbury Road, Beeston

Remains of a major yeoman farm of sub-manorial type, with surviving barn of CI5 of eight bays. Southern-most bays rebuilt in stone mid C17. Roof slates missing.

DESIGNATION: Listed Building Grade II\*, SM, CA Very bad CONDITION: Vacant OCCUPANCY: PRIORITY: A(A)

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Temple Works gate lodge, . Marshall Street, Holbeck

Small derelict gate lodge to spinning, water, steam and flax mill of I 836-40 designed by Bonomi in the Egyptian style. Walls stable, but lacks a roof.

DESIGNATION: Listed Building Grade II\*, CA CONDITION: Poor N/A C(C)PRIORITY: Company OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Ledston Hall, SITE NAME: Hall Lane, Ledston

DESIGNATION: Listed Building Grade I, RPG II

CONDITION: Part occupied OCCUPANCY: PRIORITY: E (E)

OWNERTYPE: Private

Country house now partly subdivided into flats, situated in late C17/C18 walled gardens with terraces to south and west, grass terraces to the east and an early C18 park to the north. Five periods of building starting in c1200 with chapel and kitchen. Landscape condition is generally fair to good. Long term future under consideration through preparation of a conservation plan and feasibility study.

Contact: Principal Heritage at Risk Adviser 01904 601901



First Leeds White Cloth Hall, SITE NAME: 98-101 (consecutive) Kirkgate,

DESIGNATION: Listed Building Grade II\*, CA Very bad CONDITION: Vacant OCCUPANCY: PRIORITY: C(C)

which is being proposed for the Heritage Lottery Fund Townscape Heritage Initiative programme.

An exceptionally rare example of an early C18 arcaded cloth hall. Part of generally dilapidated block along Kirkgate,

Cloth hall built in 1711. Derelict and deteriorating.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

OWNERTYPE: Company

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site



Temple Mill. SITE NAME: Marshall Street, Holbeck, Leeds

DESIGNATION: Listed Building Grade I, CA

Very bad CONDITION: Vacant OCCUPANCY: D(F)PRIORITY:

Brick-vaulted former spinning shed by Bonomi, Egyptian facade, 1836-40. Brick-vaulted roof with circular rooflights. Failure of tie bar has caused collapse of two front bays. Other bays vulnerable to similar failure. Proposals for structural repair have been developed and are under discussion.

Contact: Principal Heritage at Risk Adviser 01904 601901



Hunslet Mill. SITE NAME:

Company

Goodman Street, Hunslet. Leeds

DESIGNATION: Listed Building Grade II\*

Poor CONDITION: OCCUPANCY: Vacant D (D) PRIORITY: OWNER TYPE: Company

Flax mill of 1838 with later infill in south block. Housing development agreed, but not yet underway.



St Marys Convent Church SITE NAME: (Mount Saint Mary), Church Road, Richmond Hill, Leeds

Listed Building Grade II\* DESIGNATION: Poor CONDITION:

Vacant OCCUPANCY: D (D) PRIORITY: OWNER TYPE: Company Former Roman Catholic Church, 1852, by Joseph Hansom. Chancel and transepts by EW Pugin, 1866. Gothic style. Presbytery roof slates are partly missing, the windows are boarded and broken and the interior of the church has been stripped. Surveyed following concern of the Council for public safety. Holding works have been undertaken. Housing development has received consent.

Contact: Principal Heritage at Risk Adviser 01904 601901

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Memorial to Queen Victoria, Woodhouse Lane, Woodhouse Moor,

DESIGNATION: Listed Building Grade II\*, CA Poor CONDITION: N/A

C(C)Local authority OWNER TYPE:

1903 by Sir George Frampton. Portland stone base supporting an enthroned bronze statue of Queen Victoria. The base is flanked by bronzes of "Peace" and "Industry". The figure of Industry is severely damaged and now in store. The remaining bronzes are corroding. Formerly located in front of the Town Hall.

Contact: Principal Heritage at Risk Adviser 01904 601901



Rothwell Castle, SITE NAME: Church Street (off), Rothwell

Scheduled Monument, CA DESIGNATION:

Poor N/A OCCUPANCY: C (C) PRIORITY-OWNERTYPE: Private Ruined chapel to medieval manor complex. C14. Masonry needs to be consolidated. The site is part of an active Local Heritage Initiative scheme to investigate its surroundings.

Contact: Principal Heritage at Risk Adviser 01904 601901



Gazebo north of Clumpcliffe SITE NAME: Farmhouse, Methley Lane, Methley, Rothwell

DESIGNATION: Listed Building Grade II\* Very bad CONDITION:

Vacant PRIORITY: B (B) OWNERTYPE: Private

Hunting lodge dated 1708 on rainwater heads. Total collapse of the front elevation. Temporary cover on the flanking roofs has failed. Residential conversion agreed. Work still not implemented other than removal of debris. Site fenced.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets

**ABBREVIATIONS** 

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Thorpe Hall, SITE NAME: Middleton Lane, Thorpe on the Hill

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: Vacant OCCUPANCY: A(A)

Former farmhouse, 1735. Unitary Development Plan proposes employment land use allocation (offices). Some windows broken and gutters failed. Ceiling

collapsed in one room. Roof holed.

Private Contact: Principal Heritage at Risk Adviser 01904 601901 OWNER TYPE:



Church of the Epiphany, SITE NAME: Beech Lane

Superb 1930s art deco church. Roofs and windows in poor condition. Grant offered for repair.

DESIGNATION:	Listed Place of Worship Grade I
CONDITION:	Poor
PRIORITY:	D (D)
OWNER TYPE:	Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Stephen, SITE NAME: Morris Lane

Original church dates from 1829 but a new spire was erected in the 1830s after a lightening strike. Grant aid has been offered for chancel roof repairs.

DESIGNATION: Listed Place of Worship Grade II Very bad CONDITION: D (D) PRIORITY: OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Wilfrid, Selby Road

Significant 1930s Expressionist church. Roof in very poor structural condition. One phase of repair complete and grant offered for further work.

DESIGNATION: Listed Place of Worship Grade II\* CONDITION: Poor D (D) PRIORITY: OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME:

Church of St Mark, SITE NAME: St Mark's Road

Early C19 Commissioners' Church with fine west tower. Roofs repaired under previous grant offer. A further grant has been offered for tower, vestry roof and aisle stonework.

DESIGNATION: Listed Place of Worship Grade II Poor CONDITION: D (D) PRIORITY:

OWNER TYPE: Religious organisation Contact: Principal Heritage at Risk Adviser 01904 601901

Linear earthwork, part of the Aberford Dyke system, extending 770m east from Humphrey Dale Cottage, Aberford

DESIGNATION:	Scheduled Monument (No.1016953)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

TE NAME:	Dalton Parlours Roman villa and Iron Age settlement, Bramham cum Oglethorpe

DESIGNATION:	Scheduled Monument (No.1017560)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

**ABBREVIATIONS** CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument UA WHS Unitary Authority World Heritage Site

SITE NAME:	Cairn west of Craven Hall Hill, Leeds		
DESIGNATION:	Scheduled Monument (No.1010355)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Medieval farmstead in Ireland Wood, 150m	north east of Coc	okridge Hospital, Leeds
DESIGNATION:	Scheduled Monument (No.1018553)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Stone hut circle settlement in Clayton Woo	od on the south w	rest side of Iveson Drive, Leeds
DESIGNATION:	Scheduled Monument (No.1018814)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Stone hut circle settlement in Iveson Wood	i, Leeds	
DESIGNATION:	Scheduled Monument (No.1018815)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Linear earthworks known as Woodhouse N		uth Dyke,
DESIGNATION:	Scheduled Monument (No.1016954)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Howley Hall: a 16th century country house	and gardens, Mor	ley
DESIGNATION:	Scheduled Monument (No.1016323)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Settlement site revealed by aerial photogra	phy near Moat Ho	ouse, Walton
DESIGNATION:	Scheduled Monument (No.1003801)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.



High Royds Hospital, SITE NAME: Aireborough

DESIGNATION: Registered Park and Garden Grade II,

Extensive significant problems CONDITION:

VULNERABILITY: High Declining

OWNER TYPE: Mixed, multiple owners

The grounds of an echelon-style psychiatric hospital, opened in 1888, including airing courts, sports grounds, woodland and parkland. Hospital under conversion to residential use including extensive new build within the grounds. Historic landscape now significantly compromised and peripheral areas neglected.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Oulton Hall

DESIGNATION: Registered Park and Garden Grade II,

also CA, 2 LBs

Generally satisfactory CONDITION:

but with significant localised problems

vulnerability: Low Stable TRENID:

OWNER TYPE: Mixed, multiple owners

Park and pleasure grounds laid out in 1809-10 in part to designs by Humphry Repton, with mid C19 additions by WA Nesfield. Chequered C20 history and now split as a hotel and golf course. De Vere hotel group restored the main building. The garden layout survives in part but golf course and new development predominate.

Contact: Principal Heritage at Risk Adviser 01904 601901

SITE NAME:	Buslingthorpe, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Phil Ward (LPA) 0113 247 8146	NEW ENTRY?:	No
SITE NAME:	Chapeltown, Leeds		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Phil Ward (LPA) 0113 247 8146	NEW ENTRY?:	No
SITE NAME:	Holbeck, Leeds		
SITE NAME:  DESIGNATION:	Holbeck, Leeds  Conservation Area	CONDITION:	Very bad
	<i>'</i>	CONDITION: TREND:	Very bad No significant change
DESIGNATION:	Conservation Area		•
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	No significant change
DESIGNATION: VULNERABILITY:	Conservation Area Medium	TREND:	No significant change
DESIGNATION:  VULNERABILITY:  CONTACT:	Conservation Area Medium Phil Ward (LPA) 0113 247 8146	TREND:	No significant change
DESIGNATION:  VULNERABILITY:  CONTACT:  SITE NAME:	Conservation Area Medium Phil Ward (LPA) 0113 247 8146  Stank Hall, Leeds	TREND: NEW ENTRY?:	No significant change No

WAKEFIELD



SITE NAME: Malt House approx 15 metres south west of Blacker Hall Farmhouse, Crigglestone Branch Road, Chevet

DESIGNATION: Listed Building Grade II\*

Very bad CONDITION: OCCUPANCY: Vacant

A(A)PRIORITY

OWNERTYPE: Private

Rare early-mid C17 malt house located approx 15m south west of Blacker Hall Farmhouse. Impressive group value. Recent partial collapse of front wall, roof covering missing, roof timbers collapsing. Imminent danger of total collapse. Local Authority working closely with owner to find a sustainable future use.

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

#### **ABBREVIATIONS**

CA LB LPA NP RPG SM UA WHS

Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



SITE NAME:	Pontefract Castle,
	Pontefract

designation: Scheduled Monument

CONDITION: N/A OCCUPANCY: PRIORITY: B (B)

OWNER TYPE: Local authority

Substantial ruins comprising motte, bailey and Saxon cemetery. The fabric of the ruins needs substantial consolidation. A condition survey has been prepared. Grant has been awarded for the first two phases of repair. Emergency works complete.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: The Hermitage, Southgate, **Pontefract** 

DESIGNATION: Listed Building Grade I

Very bad CONDITION: Vacant OCCUPANCY:

A (New entry) PRIORITY: Health Authority OWNER TYPE:

The Hermitage consists of two below ground chambers hewn out of sandstone. The deeper chamber dates from 1386 and consists of a short corridor which leads to a spiral stair which descends to a well. The second chamber, known as the Oratory, is later and consists of a spiral stair which leads to a cell with altar and fireplace.

Contact: Principal Heritage at Risk Adviser 01904 601901



Quaker Meeting House, SITE NAME: Pontefract Road, Ackworth

DESIGNATION: Listed Place of Worship Grade II\*, CA Poor CONDITION: C(C)PRIORITY:

OWNER TYPE: Religious organisation

A two storey building in classical style constructed in 1847 from sandstone ashlar with a slate roof. It is currently in use as part of a school. Low level stonework is badly eroding. Two windows are broken. Roof in poor repair.

Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Mary, New Road, Badsworth

Medieval village church with fine west tower. The sandstone of the south elevation is much eroded. Grant offered for repair.



DESIGNATION: Listed Place of Worship Grade I

CONDITION: Poor

D (New entry) PRIORITY:

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of the Holy Trinity, SITE NAME: Church Street,

Ossett

Impressive Victorian church with central tower and spire. Mostly in good repair, but west and east stonework is poor. Grant offered.



DESIGNATION: Listed Place of Worship Grade II\*

CONDITION:

PRIORITY:

D (New entry)

OWNER TYPE: Religious organisation Contact: Principal Heritage at Risk Adviser 01904 601901



SITE NAME: Church of St Giles, Market Place,

Pontefract

Medieval and Georgian town church. Roofs in good repair but stonework to south elevation is in poor condition. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION:

PRIORITY: D (New entry)

OWNERTYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01904 601901

#### PRIORITY (FOR BUILDINGS)

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets. **ABBREVIATIONS** 

CA LB LPA NP RPG SM Conservation Area Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



Church St Peter, SITE NAME: Church Lane, South Hiendley

Medieval village church, roofs in poor condition. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade I

Poor CONDITION: PRIORITY: D (D)

Religious organisation OWNER TYPE:

Contact: Principal Heritage at Risk Adviser 01904 601901



Church of St Paul, SITE NAME: St Paul's Drive. Wakefield

Church of 1823-25 by Atkinson of York, with west tower. Roof in poor condition. Grant offered for repair.

DESIGNATION: Listed Place of Worship Grade II

D (New entry) PRIORITY:

	OWNERTYPE: Religious organisation	Contact: Principal Heritage at Risk Adviser 01904 601	
SITE NAME:	Newland Preceptory, Newland with Woodhou	ıse Moor	
DESIGNATION:	Scheduled Monument (No.1012153)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Sharlston Common coal and ironstone working	ngs, Sharlston	
DESIGNATION:	Scheduled Monument (No.1018399)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Site of post-medieval tannery, Felkirk, South H	liendley	
DESIGNATION:	Scheduled Monument (No.1005775)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Prehistoric enclosed settlement known as Sou	uth Kirkby Cam	np, South Kirkby and Moorthorpe
DESIGNATION:	Scheduled Monument (No.1018818)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 01904 601901
SITE NAME:	Earthwork west of Ferrybridge, Knottingley, V	Vakefield	

#### PRIORITY (FOR BUILDINGS)

DESIGNATION:

OWNER TYPE:

PRINCIPAL VULNERABILITY:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.

  B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

Arable ploughing

Private

E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Scheduled Monument (No.1005789)

F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE: 2011 priority categories are given in brackets.

Declining

01904 601901

CONDITION:

TREND:

CONTACT:

#### **ABBREVIATIONS**

Extensive significant problems

Principal Heritage at Risk Adviser

Conservation Area
Listed Building
Local Planning Authority
National Park
Registered Park and Garden
Scheduled Monument
Unitary Authority
World Heritage Site CA LB LPA NP RPG SM UA WHS

SITE NAME:	Ferrybridge near Knottingley,Wakefield		
DESIGNATION:	Scheduled Monument (No.1005799)	CONDITION:	Generally satisfactory
			but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser
			01904 601901

#### WAKEFIELD / BARNSLEY / KIRKLEES



SITE NAME: Bretton Hall,
West Bretton/Denby Dale/
High Hoyland

DESIGNATION: Registered Park and Garden Grade II, also CA, 23 LBs
CONDITION: Generally satisfactory

but with significant localised problems vulnerability: Medium

TREND: Improving
OWNER TYPE: Mixed, multiple owners

Pleasure grounds of late C18 and early C19, parkland of C18 with earlier origins. Associations with Richard Woods and Robert Marnock. Part of parkland accommodates Yorkshire Sculpture Park, part country park. Hall is owned by Wakefield Council who is negotiating with potential purchaser of the Hall for hotel use. First phase of conservation and repair works now complete including the restoration of dramatic views across the lakes. Park now threatened by application for opencast mining operations within the Registered area.

Contact: Principal Heritage at Risk Adviser 01904 601901

YORK (UA)			
SITE NAME:	Strensall, York		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Leigh Weston (LPA) 01904 551329	NEW ENTRY?:	No
SITE NAME:	The Racecourse and Terry's Factory, York		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Leigh Weston (LPA) 01904 551329	NEW ENTRY?:	No

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published September 2012 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST