Heritage at **Risk**



Midlands Register 2022

Contents

The Register	III	Newark and Sherwood Rushcliffe	78 82
Criteria	111	Rutland (UA)	83
Key statistics	VI	Herefordshire, County of (UA)	84
Key to the Entries	VII		94
Entries on the Register by local planning	IX	Shropshire (UA)	
authority		Staffordshire	109
Derby, City of (UA)	I	East Staffordshire Lichfield	109 109
Derbyshire	2	Newcastle-under-Lyme	
Amber Valley	2	South Staffordshire	112
Bolsover	4	Stafford	113
Chesterfield	5	Staffordshire Moorlands	4
Derbyshire Dales	6	Tamworth	115
Erewash	7	Stoke-on-Trent, City of (UA)	115
High Peak	8	Telford and Wrekin (UA)	118
North East Derbyshire	9		
Peak District (NP)	10	Warwickshire	119
South Derbyshire	10	North Warwickshire	119
Leicester, City of (UA)	13	Nuneaton and Bedworth	122
Leicestershire	16	Rugby	123
	16	Stratford-on-Avon	124
Blaby Charnwood	16	Warwick	128
Harborough	18	West Midlands	130
Hinckley and Bosworth	20	Birmingham	130
Melton	20	Coventry	135
North West Leicestershire	24	Dudley	137
Oadby and Wigston	26	Sandwell	139
Lincolnshire	26	Solihull	139
		Walsall	I 4 0
Boston	26	Wolverhampton, City of	4
East Lindsey Lincoln	28 36	Worcestershire	143
North Kesteven	38	Bromsgrove	143
South Holland	42	Malvern Hills	145
South Kesteven	44	Redditch	147
West Lindsey	48	Worcester	147
North East Lincolnshire (UA)	53	Wychavon	148
North Lincolnshire (UA)	54	Wyre Forest	152
West Northamptonshire (UA)	58		
North Northamptonshire (UA)	64		
Nottingham, City of (UA)	67		
Nottinghamshire	70		
Ashfield	70		
Bassetlaw	70		
Broxtowe	76		
Gedling	77		
Mansfield	78		

THE REGISTER

The Heritage at Risk Register includes historic buildings and sites that are at risk of loss through neglect, decay or development, or are vulnerable to becoming so. It includes all types of designated heritage assets, including Conservation Areas, which are designated and assessed by Local Planning Authorities.

The aim of the Register is to focus attention on those places in greatest need. Historic England, in partnership with others, is able to help tackle heritage at risk. We work with owners, friends groups, developers and other stakeholders to find imaginative solutions for historic places and sites at risk across England.

More information about our role, the advice and funding available, and useful <u>publications</u> and <u>guidance</u> is available on our <u>website</u>.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are assessed according to the nature of the site. The risk assessment methodologies outlined below are based on factors which can threaten the different types of heritage assets and lead to them becoming at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be listed on the National Heritage List for England; and in secular (non-worship) use. And either:

- a grade I or II* listed building, or
- a grade II listed building in London, or
- a structural scheduled monument with upstanding remains.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'partoccupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. A few buildings remain on the Register in good condition whilst solutions are being implemented as a reminder of the need for monitoring, and to ensure that repair and re-use are seen through to completion.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II* or grade II on the National Heritage List for England and be used as a public place of worship at least six times a year.

The method used to assess whether a place of worship is at risk is essentially the same as that used to assess other historic buildings or structures (as outlined above), with one important difference: the criterion as to whether a building is occupied is not used as by their nature, places of worship are in use. Places of worship will be assessed as at risk and added to the Register if their condition is assessed to be very bad or poor.

It is often the case that only part of a church building, e.g. the tower or one of the aisles, is in very bad or poor condition, and it then becomes a matter of professional judgement whether this puts the whole building at risk. Usually if a major or a very significant element of a church is considered to be at risk then the judgement is made that the whole building is at risk and it is included in the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even to good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register, archaeological sites must be designated as scheduled monuments on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology.

The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'. The trend will also be recorded as 'improving', 'stable', 'declining' or 'unknown'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be designated as grade I, grade II* or grade II on the National Heritage List for England. Parks and gardens are assessed in terms of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register, battlefields must be included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

Each battlefield is assessed against four key criteria:

• Landscape readability – is it possible to understand the context of the battle?

- Landscape features are hedgerows, walls and trees which had a significant impact on the battle still in place?
- Archaeological integrity is the archaeology of the battle being disturbed?
- Ambiance are activities such as development having a negative impact on the setting of the site?

Current condition, future vulnerability and trend are all taken into account.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register, wrecks must be designated as protected wreck sites on the National Heritage List for England.

Wreck sites are assessed based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability.

Wrecks are considered to be at risk if there is a significant likelihood of loss or further loss of historical, archaeological or artistic significance from it within the foreseeable future.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage. The monitoring process ensures that the significance of the site is identified and maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Once a year Historic England asks every local authority in England to consider the state of its conservation areas and fill in (and update as appropriate) risk assessment questionnaires for those that cause concern or are believed to no longer be at risk.

Conservation areas that are deteriorating or are in very bad or poor condition and not expected to change significantly in the next three years are defined as being at risk.

Categories for condition, vulnerability and trend are included for each conservation area on the Heritage at Risk Register. The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. Conservation areas identified as at risk in 2009 but not reassessed since using the revised methodology are included on the Register but with limited information.

Conservation area entries are removed from the Register once issues have been identified, plans put in place to address them, and positive progress is being made.

THE EFFECT OF COVID-19 ON THE COLLECTION AND COLLATION OF THE STATISTICS USED FOR THE 2022 REGISTERS

Since early 2020, the Covid-19 pandemic has impacted on data collection and collation for both our staff and our local authority colleagues. As there was less disruption during the 2022 reporting year, we have been able to carry out more on-site checks of entries on, additions to and removals from the Register. Where this hasn't been possible deskbased assessments and updates have been carried out.

Key Heritage at Risk Statistics for the Midlands 2022

BUILDINGS AND STRUCTURES

- Of the 22,516 grade I and II* listed buildings (excluding places of worship) in England, 756 (3.4%) are on the Register. Of the 3,683 listed secular buildings in the Midlands 191 (5.2%) are on the Register.
- In addition to this, of the 3,010 scheduled monuments in the Midlands, 57 (1.9%) are on the Register assessed as structural scheduled monuments (i.e. using the buildings or structures methodology).
- 14 building or structure entries (including structural scheduled monuments) have been removed from the previous Midlands Register (2021) for positive reasons and 10 have been added.

PLACES OF WORSHIP

- Of the 14,792 listed places of worship in England, 919 (6.2%) are on the Register. Of the 3,367 listed places of worship in the Midlands 266 (7.9%) are on the Register.
- 24 places of worship entries have been removed from the previous Midlands Register (2021) for positive reasons and 25 have been added.

ARCHAEOLOGY

- Of the 19,933 scheduled monuments in England, 1,961 (9.8%) are on the Register assessed as archaeology. Of the 3,010 scheduled monuments in the Midlands, 205 (6.8%) are on the Register assessed as archaeology.
- 7 archaeology entries have been removed from the previous Midlands Register (2021) for positive reasons, and 3 have been added.

PARKS AND GARDENS

Of the 1,699 registered parks and gardens in England 104 (6.1%) are on the Register. Of the 305 registered parks and gardens in the Midlands, 15 (4.9%) are on the Register.

One park and garden entry has been removed for positive reasons and none have been added to the previous Midlands Register (2021).

BATTLEFIELDS

Of the 47 registered battlefields in England, 3 (6.4%) are on the Register. None of the 12 registered battlefields in the Midlands are on the Register.

WRECK SITES

Of the 54 protected wreck sites around England's coast, 4 (7.4%) are on the Register. There are no protected wreck sites in the Midlands.

CONSERVATION AREAS

- There are 490 conservation areas on the Register across England. Of these, 128 are in the Midlands
- 5 conservation areas have been removed for positive reasons and 3 have been added to the previous Midlands Register (2021).

HISTORIC ENGLAND FUNDING

- £2.16 million in grant was spent on 29 entries (including conservation areas) on the Midlands Register during 2021/22.
- In addition, £0.40 million of Covid-19 pandemic recovery funding was spent on 3 entries.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include structural scheduled monuments and listed buildings (excluding listed places of worship); archaeology assessments include earthworks and buried archaeology. Please note that some sites may have more than one entry under different risk assessment methodologies, for example if a site has more than one listing for its different elements or if it consists of both buried and structural remains.

2022 HAR data as at 11 am 11 July 2022

2021 HAR data as at 12am 19 July 2021

Key to the entries

The Register includes the following risk assessment types:

- Building or structure (for grade I and II* listed Buildings, grade II listed buildings in London and structural scheduled monuments)
- Place of worship (for grade I, II* and II listed buildings)
- Archaeology (for scheduled monuments earthworks and buried archaeology)
- Park and garden (for Registered parks and gardens)
- Battlefield (for Registered battlefields)
- Wreck site (for Protected wreck sites)
- Conservation area (for conservation areas)

(Please note not all assessment types appear in each of the regional registers.)

ORDER OF ENTRIES

Please refer to the 'Contents' page to see the order that the Planning Authorities are presented in.

Please note that Unitary Authorities are ordered under their own names and may not appear in the same section as the other planning authorities in their ceremonial (or former) county.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

DESIGNATION/LISTING

The principal designation/listing type is noted for each entry:

- Listed Building (LB) grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II*
 or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Any other listing types that also apply to the site are also noted (e.g. location within a World Heritage Site (WHS); where a LB or SM is sited within a CA or RPG; or where a CA contains many LBs or SMs).

If an entry is dual designated on the National Heritage List for England (i.e. it is both a listed building and a scheduled monument) the two designations will be joined with an 'and' (e.g. 'Scheduled Monument and Listed Building grade I').

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments – archaeology assessments, parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use.

Occupancy (or use) is noted as follows:

- vacant (or not in use)
- part occupied (part in use)
- occupied (in use)
- unknown
- not applicable (for structural scheduled monuments)

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as 'high', 'medium' or 'low'.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

The priority category for the previous year for the entry is given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

- CA Conservation Area
- HE Historic England
- NLHF National Lottery Heritage Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- PWS Protected Wreck Site
- RB Registered Battlefield
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
DERBY, CITY OF (UA)	1		1	1			
Derby, City of (UA)	4	· 1	0	0	0	0	1
DERBYSHIRE		1		1			
Amber Valley	8	3	I	0	0	0	0
Bolsover	2	. 0		0	0	0	2
Chesterfield	3		0	0	0	0	0
Derbyshire Dales	2	. 3	2	0	0	0	0
Erewash		2	0		0	0	3
High Peak	3	1		0	0	0	0
North East Derbyshire	l	0	<u> </u>	0	0	0	3
Peak District (NP)	0		<u> </u>	0	0	0	0
South Derbyshire	10	3	2		0	0	0
LEICESTER, CITY OF (UA)		1		1			
Leicester, City of (UA)	6	4	0	0	0	0	3
LEICESTERSHIRE							
Blaby	0		0		0	0	0
Charnwood	5		2		0	0	2
Harborough		8		0	0	0	0
Hinckley and Bosworth		2	0		0	0	3
Melton		4	0		0	0	
North West Leicestershire	2		0		0	0	0
Oadby and Wigston	0		0	0	0	0	0
Boston	2		I	0	0	0	4
East Lindsey	10		4		0	0	6
Lincoln	2		I	0	0	0	6
North Kesteven	3		5		0	0	2
South Holland	3		4	0	0	0	2
South Kesteven	6		7	1	0	0	1
West Lindsey	7		7	0	0	0	3
West Lindsey / Bassetlaw [†]		0	0	0	0	0	0
NORTH EAST LINCOLNSH	RE (UA)						
North East Lincolnshire (UA)	3	0	2	0	0	0	6
NORTH LINCOLNSHIRE (U	A)		1	1			
North Lincolnshire (UA)	3	4	12	0	0	0	2
WEST NORTHAMPTONSHI	RE (UA)				·		
West Northamptonshire (UA)	14	12	10	0	0	0	2
NORTH NORTHAMPTONS	HIRE (UA)	7		1			
North Northamptonshire (UA)	6	5	2	0	0	0	I
NOTTINGHAM, CITY OF (L							
Nottingham, City of (UA)	2	. 6	0	0	0	0	14
NOTTINGHAMSHIRE		1					
Ashfield	0			I	0	0	
Bassetlaw	10			<u> </u>	0	0	
Broxtowe	2			0	0	0	3
Broxtowe / Erewash [†]	I	0	0		0	0	0
Gedling	2		2		0	0	0
Mansfield	0			0	0	0	
Newark and Sherwood	6		5		0	0	3
Rushcliffe RUTLAND (UA)		4	2	0	0	0	0
\mathbf{R} (1) (Δ (N) (1 (Δ)							

	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HEREFORDSHIRE, COUNTY	OF (UA)						
Herefordshire, County of (UA)	14	21	19	0	0	0	2
SHROPSHIRE (UA)							
Shropshire (UA)	24	22	36	0	0	0	0
STAFFORDSHIRE							
East Staffordshire	I	0	2	0	0	0	0
Lichfield	3	1	3	0	0	0	1
Newcastle-under-Lyme	2	0	0	0	0	0	0
Peak District (NP)	2	0	4	0	0	0	0
South Staffordshire	I	0	2	0	0	0	0
Stafford	2	0	2	0	0	0	2
Staffordshire Moorlands	5	0	2	0	0	0	2
Tamworth	1	0	0	0	0	0	0
STOKE-ON-TRENT, CITY OF	F (UA)						
Stoke-on-Trent, City of (UA)	6	3	0	0	0	0	5
TELFORD AND WREKIN (UA	۹)	-					
Telford and Wrekin (UA)	4	2	3	0	0	0	0
WARWICKSHIRE		1					
North Warwickshire	10	I	3	0	0	0	0
Nuneaton and Bedworth	2	0	0	0	0	0	0
Rugby	0	0	8	I	0	0	0
Stratford-on-Avon	2	10	8	0	0	0	2
Warwick	3	3	7	2	0	0	0
WEST MIDLANDS		1					
Birmingham	9	10	I	I	0	0	8
Coventry	3	2	I	I	0	0	3
Dudley	I	3	I	0	0	0	4
Sandwell	2	0	I	0	0	0	2
Solihull	1	0	0	0	0	0	0
Walsall	0	2	0	0	0	0	6
Walsall / Sandwell [†]	0	0	0	I	0	0	0
Wolverhampton, City of	2	4	0	0	0	0	9
Dudley / Bromsgrove [†]	0	0	I	0	0	0	0
WORCESTERSHIRE		1					
Bromsgrove	2		0	1	0		1
Malvern Hills	2	6	3	I	0	0	0
Redditch	0	0	2	0	0	0	1
Worcester	1	1	1	0	0		1
Wychavon	5		5	I	0		0
Wyre Forest	3		0	0	0	0	3
TOTAL	248	266	205	15	0	0	128

[†] Sites that cross local planning authority boundaries

DERBY, CITY OF (UA)			
	SITE NAME:	Darley Abbey Mills (North Complex) North Mill, engine house, boiler house, Old Lane, Darley Abbey, Derby	Former manufacturing cotton textile factory built by the Evans family of Darley Abbey. North Mill, thought to date from the mid-1820s, is a three-storey brick building with attic. Temporary high level repairs funded via a Historic
	DESIGNATION:	Listed Building grade II*, CA, WHS	England grant in 2012, but the roof needs wholesale renewal. There is extensive decay of parapets indicating leaking gutters. Spalling to brickwork at high level. Much of
	CONDITION:	Fair	the building is now occupied with a mix of small office accommodation. The Council are still working with the
F	OCCUPANCY:	Occupied/in use	owners to encourage comprehensive repair.
© Derby City Council	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1067808	Contact: Rosemary Thompson 07768 215540
	SITE NAME:	Darley Abbey Mills (North Complex) preparation building, cottage, workshop and cart sheds, Old Lane, Darley Abbey, Derby	Known as the proto-fireproof building, this range forms the northernmost part of the former manufacturing cotton textile factory built by the Evans family of Darley Abbey. Dating from c1790, the L shaped brick range is in poor condition with water ingress through the roof, poor
	DESIGNATION:	Listed Building grade II*, CA, WHS	guttering, eroded brickwork and bowed east gable. The building is continuing to deteriorate.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	

© Derby City Council



© Historic E

City Council	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1067809	Contact: Rosemary Thompson 07768 215540
England	SITE NAME:	Darley Abbey Mills (South Complex) East Mill and West Mill, Old Lane, Darley Abbey, Derby	Former manufacturing cotton textiles factory built by the Evans family of Darley Abbey. Long Mill was rebuilt and enlarged following fire damage in 1788. West Mill was added c1819-21. The exteriors of the buildings have
	DESIGNATION:	Listed Building grade I, CA, WHS	decayed over time with significant loss of render to upper storeys, cavernous stone decay and localised evidence of faulty rainwater goods leading to water ingress. Significant
	CONDITION:	Poor	roof repairs are required to two mill buildings. The conversion of Long Mill and West Mill is now complete.
	OCCUPANCY:	Occupied/in use	Repairs to Long Mill were completed in 2020 and it is no
	PRIORITY CATEGORY:	D (D)	longer at risk.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1279399	Contact: Rosemary Thompson 07768 215540



© Historic England Archive

	LIST ENTRY NOPIBER:	12/9399	Contact: Rosemary Thompson 07768 215540
3	SITE NAME:	Allestree Hall, Allestree Park, Derby	House, 1802. Landscaped park now a golf course. The internal condition is poor, but the building is in fair
-	DESIGNATION:	Listed Building grade II*	condition overall. Following the production of a Heritage Assessment and Planning Brief, the City Council have
	CONDITION:	Fair	successfully marketed Allestree Hall. The new owner has been granted listed building consent and planning
	OCCUPANCY:	Part occupied/part in use	applications to repair and convert the hall and outbuildings
	PRIORITY CATEGORY:	C (C)	to a wedding venue/hotel accommodation.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1215234	Contact: Rosemary Thompson 07768 215540

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

I

HERITAGE AT RISK 2022 / MIDLANDS / DERBY, CITY OF (UA) / AMBER VALLEY

S	SITE NAME:	Church of St Thomas the Apostle, Pear Tree Road, Derby	Large urban parish church of rock faced masonry of c1881 by J Peacock. The National Lottery Heritage Fund has grant
	DESIGNATION:	Listed Place of Worship grade II	aided two phases of repairs which addressed significant problems with roofs, high level masonry and internal
	CONDITION:	Poor	plasterwork. The second phase, completed in 2018, included the careful dismantling and rebuilding of the east
	PRIORITY CATEGORY:	D (C)	window. However, many other windows are in poor
	OWNER TYPE:	Religious organisation	condition and require urgent repair. The Quinquennial Inspector has prepared costings to support any grant
AND TO THE PARTY OF THE PARTY	LIST ENTRY NUMBER:	1230642	funding opportunities which may arise.

Contact: Hanna Good 07825 318060

© Historic England

SITE NAME:	Green Lane and St Peter's, Arboretum Ward		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Chloe Oswald (LPA) 01332 640809

DERBYSHIRE

© Histo

AMBER VALLEY

	SITE NAME:	Codnor Castle remains, Castle Lane, Aldercar and Langley Mill	Castle ruins and earthworks dating to the early CI3 and later. Formerly affected by open-cast coal mining. A major			
	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	repair programme was completed in 2008. Until recently the Codnor Castle Heritage Trust was carrying out maintenance at the site and running public events with the			
	CONDITION:	Poor	owner's permission. The C16 farmhouse (grade II) was abandoned, at risk, and has suffered vandalism. The Lower			
	OCCUPANCY:	N/A	Court east wall is in danger of collapse and was temporarily			
	PRIORITY CATEGORY:	C (C)	supported. The property was sold in 2021. The new owner has begun work on site.			
	OWNER TYPE:	Commercial company				
toric England	LIST ENTRY NUMBER:	1007047 and 1109025	Contact: Ben Robinson 07823 327796			

	SITE NAME:	Horseshoe Weir and Rock Weir, Bridge Foot, Belper	Massive gritstone weirs and sluices developed from 1796- to support the adjacent mill complex. Self-seeded woody		
	DESIGNATION: Listed Building grade II*, C WHS		growth is displacing masonry in Horseshoe Weir (to the east of the town bridge). Masonry has been lost from the centre of Rock Weir (to the west of the town bridge). The		
	CONDITION:	Fair	weirs are in different ownerships and associated with adjacent property awaiting redevelopment. A condition		
	OCCUPANCY:	N/A	survey of Rock Weir has been carried out. This identifies		
	PRIORITY CATEGORY:	C (C)	repair and maintenance needs.		
	OWNER TYPE:	Commercial company			
© Historic England	LIST ENTRY NUMBER:	1335702	Contact: Ben Robinson 07823 327796		



	SITE NAME:	North Mill, Bridge Foot, Belper	Important example of early 'fireproof' mill, 1803-4. Used
	DESIGNATION:	Listed Building grade I, CA, WHS	for offices and part leased for museum use. Amber Valley Borough Council and Historic England are deeply concerned about the condition of the roof and occasional
	CONDITION:	Poor	flooding in the basement. The owner has undertaken some temporary repairs and the introduction of mechanical
	OCCUPANCY:	Part occupied/part in use	ventilation. These repairs are failing and wholesale re-
	PRIORITY CATEGORY:	A (C)	roofing is required. The adjoining grade II East Mill is vacant and in poor condition. Proposals have been submitted for
	OWNER TYPE:	Commercial company	residential and mixed used conversion of the mill complex.
-	LIST ENTRY NUMBER:	1186846	Contact: Ben Robinson 07823 327796

© Historic England

PRIORITY	CATEGORIES	

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / AMBER VALLEY

HERITAGE AT RISK 2022 / MIDLAI	NDS / AMBER VALLEY		
1	SITE NAME:	Road archway and footbridge (including offices), Bridge Foot, Belper	Footbridge linking former mills. Late C18-early C19. The archway served a defensive role, with gun embrasures protecting the former Counting House in West Mill. Past
	DESIGNATION:	Listed Building grade II*, CA, WHS	incidents of road traffic collisions appear to have been resolved by the installation of signage by Derbyshire County Council. However, roof coverings remain in a poor
	CONDITION:	Poor	condition (turnerised and patched) and renewal is
	OCCUPANCY:	N/A	required. The building remains unoccupied. Proposals have been submitted for the residential and mixed use
The Manager	PRIORITY CATEGORY:	C (C)	conversion of the mill complex.
© Historic England	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1087395	Contact: Ben Robinson 07823 327796
	SITE NAME:	Remains of Horsley Castle, Horsley	A military royal castle from C12-C14, which overlooks the strategically important Derwent valley. The base of the
	DESIGNATION:	Scheduled Monument, CA	small Norman keep partially survives. The area was quarried extensively in C19. Substantial masonry still
Star and the	CONDITION:	Poor	remains, and walls are up to five metres high in places. The
	OCCUPANCY:	N/A	remains are in woodland under heavy scrub/ivy cover. There is some loss of stonework to the base of the keep
	PRIORITY CATEGORY:	C (C)	and vegetation is extensive and intrusive.
and the second	OWNER TYPE:	Unknown	
© Historic England	LIST ENTRY NUMBER:	1009293	Contact: Ben Robinson 07823 327796
	SITE NAME:	Heage Windmill, Dungley Hill, Ripley	Early C19. Part restored 1971-3 and restored again to working order 1997-2002. The ends of both sheers are
A Same	DESIGNATION:	Listed Building grade II*	suffering from historic wood rot. One sheer also displays signs of decay pockets and localised damage inside the cap.
	CONDITION:	Poor	Emergency external sheer repairs were undertaken in 2018. The curb rollers and iron track require modifications.
	OCCUPANCY:	Part occupied/part in use	The cap gutter has deteriorated, and there is rainwater
	PRIORITY CATEGORY:	C (New entry)	ingress. There is adjacent high-level spalling of the stonework, alongside sporadic mortar loss. The Heage
	OWNER TYPE:	Community interest group	Windmill Society and Derbyshire County Council are keen
© Heage Windmill Society	LIST ENTRY NUMBER:	1109016	to effect repairs. Contact: Imogen Newcombe 07387 524030
	SITE NAME:	South Wingfield Station Building, Holm Lane, South Wingfield	Built in 1839-40 to the designs of Francis Thompson, a pioneering engineer of the railway era, for the North Midland Railway. It is one of the earliest railway stations in
State of the second sec	DESIGNATION:	Listed Building grade II*, CA	the world and is the sole survivor of Thompson's picturesque stations on the Derby to Leeds line. The
	CONDITION:	Poor	building was acquired by the Derbyshire Historic Buildings Trust in late 2019 following successful compulsory
	OCCUPANCY:	Vacant/not in use	purchase proceedings by Amber Valley Borough Council.
	PRIORITY CATEGORY:	F (B)	Historic England grant-aided the statutory action and has awarded the Trust a grant for urgent work which will
The second se	OWNER TYPE:	Private	complete in summer 2022.
© Historic England	LIST ENTRY NUMBER:	1045917	Contact: Amanda White 0121 625 6890
	SITE NAME:	South Wingfield Manor Farmhouse, South Wingfield	Farmhouse east of the inner gateway of South Wingfield Manor, mid-C18, with stone slate and pantile roofs. Some
	DESIGNATION:	Listed Building grade I and Scheduled Monument, CA	slipped stone slates leaving holes in the roof and the possibility of water ingress. There is also vegetation growth on parts of the property.
	CONDITION:	Poor	
	OCCUPANCY:	Unknown	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1109156 and 1014829	Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / AMBER VALLEY / BOLSOVER



NAME:	Church of the Holy Trinity, Derby Road, Milford, Belper	Church, dating from 1848 by architect H Moffatt. Church room and vestry added in 1910. By 2014, rainwater goods
IGNATION:	Listed Place of Worship grade II, CA, WHS	required localised repairs and improvement failed joints and disposal of water at ground level was inadequate and or ineffective. There were numerous slipped slates from
NDITION:	Poor	the north aisle roof. The church has been the subject of heritage crime.
ORITY CATEGORY:	C (C)	nentage chine.
/NER TYPE:	Religious organisation	
ENTRY NUMBER:	1087346	Contact: Hanna Good 07825 318060

© Historic England



© Mr Roy Millett. Source: Historic England Archive

a state	SITE NAME:	Church of St James, Wirksworth Road, Idridgehay and Alton	Parish church of 1854-5, designed by H. I. Stevens in the Decorated style. Ashlar gritstone with nave, nave porch, chancel, north aisle and north east tower with broach spire
	DESIGNATION:	Listed Place of Worship grade II, CA	and lucarnes. The upper south and west corner of the tower is subject to increasing structural movement, with further movement evident at the basal stonework of the
	CONDITION:	Poor	spire. Re-pointing to the upper tower and spire is required alongside the renewal of the bell chamber floor and further
	PRIORITY CATEGORY:	C (New entry)	roofing repairs. The Parochial Church Council are keen to
	OWNER TYPE:	Religious organisation	effect repairs and are investigating potential funding avenues.
	LIST ENTRY NUMBER:	5873	Contact: Imogen Newcombe 07387 524030

	SITE NAME:	Church of All Saints, Lower Road, Mackworth	Parish church with fabric from early C14, late C14 and C15. The church was restored in 1851. A fire tore through
	DESIGNATION:	Listed Place of Worship grade I, CA	the building in early December 2020 which destroyed the interior and roofs. The shell of the building has been secured.
	CONDITION:	Very bad	
AT A state. Termine Brunn	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1158642	Contact: Tim Allen 07770 610214

© Historic England

SITE NAME:	Butterley Works blast furnaces, canal tunnel and underground wharf, Ripley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1404832
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Tim Allen 07770 610214

BOLSOVER

© Historic England Archive	SITE NAME:	Barlborough Hall, Ward Lane, Barlborough	Part rendered hall with impressive stone porch of c1583-4 attributed to Robert Smythson and built for Sir Francis
	DESIGNATION:	Listed Building grade I, RPG grade II, CA	Rodes. A second porch was added in 1825 after the hall was sold and converted for school use. The exterior was rendered with a cement gauged mix in mid C20. The render is cracked, the later porch suffers cramp damage and the original porch has suffered significant erosion. Historic England grant aided project development works
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	were completed in 2017. A repair scheme has been discussed with the owners.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1108972	Contact: Hannah Reynolds 07557 827971

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / BOLSOVER / CHESTERFIELD

	SITE NAME:	Engine house, chimney and headstocks to the former Pleasley Colliery, Chesterfield Road, Pleasley	Disused colliery, late C19 with headstocks and winding engines. Owned by The Land Trust. The site includes a pit museum and recently improved visitor facilities. Restoration and maintenance led by a good local team of
	DESIGNATION:	Scheduled Monument and Listed Building grade II	volunteers from the Friends of Pleasley Pit / Pleasley Pit Trust. A programme of repairs was completed in 2011 and much of the site is in a fair condition. However, major
	CONDITION:	Poor	repairs are required to address the deteriorating condit of the chimney and structural concerns adjacent to the
	OCCUPANCY:	Part occupied/part in use	southern headstock. Historic England is providing advice
© Historic England	PRIORITY CATEGORY:	B (F)	and support.
C motorie England	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1015641 and 1045855	Contact: Ben Robinson 07823 327796

SITE NAME:	Pinxton Castle motte and fortified manor with mo	ated site and five fis	shponds, South Normanton / Pinxton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010025
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Bolsover, Old Bolsover		
DESIGNATION:	Conservation Area, 51 LBs, RPG grade II*, 3 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Kim Wyatt (LPA) 01246 242288
SITE NAME:	Clowne, Clowne / Whitwell		
DESIGNATION:	Conservation Area, 5 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Kim Wyatt (LPA) 01246 242288

CHESTERFIELD

	SITE NAME:	Brampton Manor Barn, Old Hall Road	Late C16/early C17 barn with massive cruck trusses under a stone and slate roof. Multiple slate failures allowing water
	DESIGNATION:	Scheduled Monument and Listed Building grade II	to penetrate and significant cracking (historic) to gable elevation. The barn suffered vehicle damage in 2019. Planning permission granted in December 2021 for the
	CONDITION:	Very bad	residential conversion of the adjacent grade II
	OCCUPANCY:	Part occupied/part in use	pub/restaurant. This includes Conditions requiring the repair and consolidated of the Barn, which will be
	PRIORITY CATEGORY:	D (D)	sympathetically converted to garages. A repair scheme is being developed and it is hoped that works will start on site
	OWNER TYPE:	Private	before the end of 2022.
	LIST ENTRY NUMBER:	1004600 and 1031926	Contact: Nick Carter 0121 625 6860

© Historic	England
------------	---------



	SITE NAME:	Gazebo at Brampton Manor, Old Hall Road, Brampton	Early C18 gazebo with stone slated 'fish scale' roof. The ground floor is used for storage. The upper floor has
	DESIGNATION:	Listed Building grade II*	suffered significant graffiti and some of the ceiling boarding is missing or otherwise defective. Slating appears to be in
	CONDITION:	Fair	fair condition, but the building is periodically infested with ivy. There appears to be no rainwater goods (by design).
	OCCUPANCY:	Part occupied/part in use	Planning proposals for residential conversion have been
	PRIORITY CATEGORY:	C (C)	submitted for the wider site.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1088267	Contact: Ben Robinson 07823 327796

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / CHESTERFIELD / DERBYSHIRE DALES

	SITE NAME:	Walton Works, Walton Fields Road, Brampton	Former cotton wick mill, late C18 and later; significant for its early and novel fireproof construction. Mainly three
	DESIGNATION:	Listed Building grade II*	storeys with two and four storey elements. Most of the building is vacant and in very poor condition despite some
PPD DU	CONDITION:	Poor	temporary high level repairs. Proposals for conversion of the mill within a mixed use scheme have been submitted
	OCCUPANCY:	Vacant/not in use	for statutory consent. Buildings continue to deteriorate.
	PRIORITY CATEGORY:	C (C)	
- Longette	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1391084	Contact: David Walsh 0121 625 6888

© Historic England

	SITE NAME:	Church of St Thomas, Chatsworth Road, Chesterfield	Parish church of 1830-31 by Woodhead & Hurst, with chancel 1888 by Naylor and Sale. Restored 1903 by
SH	DESIGNATION:	Listed Place of Worship grade II	Adams. The church historically suffered from water ingress, with repairs to the tower grant aided by the National
	CONDITION:	Fair	Lottery Heritage Fund and completed in 2017. The water ingress has caused subsequent damage to the highly ornate
	PRIORITY CATEGORY:	C (New entry)	nave ceiling panels, causing a loss of decoration and
	OWNER TYPE:	Religious organisation	plasterwork. Urgent repairs to the ceiling panels were undertaken in December 2021, alongside the safeguarding
	LIST ENTRY NUMBER:	1088299	of detaching banners and boss. The Parochial Church Council are keen to undertake a repair programme.

© Anthony Short & Partners

©

© Historic Er

DERBYSHIRE DALES

- in Ma	SITE NAME:	Cromford Mill, Buildings 1,18, 26 and Aqueduct, Mill Road, Cromford	Cotton mill factory complex dating from 1771. Gritstone with Welsh slate roofs. Building 18, the original mill, suffered significant fire damage in 1929 - two storeys were
	DESIGNATION:	Listed Building grade I, CA, WHS	destroyed. The building houses an introductory film associated with the visitor centre in Building 17 on the ground floor, but the upper storey is unoccupied, and its
Eline Anna Manager	CONDITION:	Very bad	lightweight roof structure and asbestos roof covering is failing. Historic England awarded the Arkwright Society
	OCCUPANCY:	Part occupied/part in use	Covid 19 Emergency Response Fund grants to address lo of revenue and a project development grant in 2021 to consider re-roofing options.
San State Children	PRIORITY CATEGORY:	A (F)	
© Historic England	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1248010	Contact: Ben Robinson 07823 327796

1 Miles	SITE NAME:	Stable block and Coach House at Longford Hall Farm, Long Lane, Longford	Stable block circa 1760-65 attributed to the Derby architect Joseph Pickford. Red brickwork with stone dressings. Whitehurst of Derby clock on central pediment.
1.1.1	DESIGNATION:	Listed Building grade II*, CA	Fine interior with Tuscan columns. Suffering loss of historic fabric and water ingress. Temporary fencing to protect
i i i li i i	CONDITION:	Very bad	public right of way was erected in 2014. Planning permission granted for conversion of adjacent farm
Mark.	OCCUPANCY:	Vacant/not in use	buildings to holiday accommodation requires some repairs
	PRIORITY CATEGORY:	A (A)	to the stable roof. A further planning application for business use of surrounding farm buildings has been
	OWNER TYPE:	Private	submitted. Repair work has not progressed.
England	LIST ENTRY NUMBER:	1281396	Contact: Ben Robinson 07823 327796



Early English to Perpendicular cruciform church with SITE NAME: Church of St Mary, Church central tower. Restored in 1870 by GG Scott and again in Yard, Wirksworth C20. By 2019, the aged roof coverings were defective and Listed Place of Worship grade I, actively leaking. A National Lottery Heritage Fund grant DESIGNATION was awarded in early 2020 for the replacement of nave CA roof coverings. Work was completed in summer 2020, CONDITION: Poor alongside the replacement of the north transept roof tiles. PRIORITY CATEGORY: The Parochial Church Council are maintaining other roofs. C (C) Below ground drainage is thought to be problematic. OWNER TYPE: Religious organisation Supporters are working hard to raise funds for ongoing maintenance and repairs. LIST ENTRY NUMBER: 1335090

Contact: Imogen Newcombe 07387 524030

Contact: Imogen Newcombe 07387 524030

© Peter Rogan, Peter Rogan Assoicates Ltd

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / DERBYSHIRE DALES / EREWASH

	SITE NAME:	Church of St Mary, Rakes Lane,	Medieval C12 church with rebuilding in 1854, constructed
toric England			Contact: Imogen Newcombe 07387 524030
	LIST ENTRY NUMBER:	1088158	when funding permits.
I HADDL	OWNER TYPE:	Religious organisation	coverings are at the end of their lives, and failures are addressed as they arise, but slate roofs need re-covering
	PRIORITY CATEGORY:	F (F)	Response Fund grant. Aisle, chancel and chapel roof
the state	CONDITION:	Poor	elsewhere have been repaired and renewed through an Historic England Covid-19 Emergency Heritage at Risk
	DESIGNATION:	Listed Place of Worship grade I, RPG grade I, CA	north nave wall which suffered as a result of water ingress over a sustained period. Guttering has been repaired and stonework continues to dry out. Rainwater goods
	SITE NAME:	Church of St Peter, The Green, Edensor, Derbyshire Dales	Church of C12 and C15. Rebuilt in 1867 by GG Scott. The condition of the church is generally fair except for the

© Historic England	Area 1	SITE NAME:	Church of St Mary, Rakes Lane, Tissington and Lea Hall, Derbyshire Dales	of coursed limestone with rebuilding in 1854, constructed of coursed limestone with gritstone dressings and slate roofs. Fabric appears to be in good condition generally and
		DESIGNATION:	Listed Place of Worship grade II*, CA	the church is well-maintained. However, there is localised damp staining including to the tympanum over the south door and the nave roof covering is at the end of its
		CONDITION:	Poor	economic lives. The shallow pitched slopes will require re- slating soon subject to potential fundraising avenues.
		PRIORITY CATEGORY:	C (C)	siating soon subject to potential fundraising avenues.
		OWNER TYPE:	Religious organisation	
	© Historic England	LIST ENTRY NUMBER:	1109271	Contact: Imogen Newcombe 07387 524030

SITE NAME:	Bradley Park bowl barrow, Bradley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008067
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Lumsdale Mills and associated water management f	features, Matlock T	own / Tansley
SITE NAME: DESIGNATION:	Lumsdale Mills and associated water management f Scheduled Monument, LB grade II, CA	features, Matlock To List entry number:	own / Tansley 1417570
	Ŭ		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1417570

EREWASH

© Histo



	SITE NAME:	Dale Abbey, The Village, Dale Abbey	Wall footings and standing east wall of Dale Abbey, a house of Premonstratensian Canons founded in circa 1200.
	DESIGNATION:	Scheduled Monument, LB grade I, CA	The mostly late C13 remains were excavated in the late C19 and left exposed. The east wall and footings were consolidated, and the museum was repaired and re-roofed
	CONDITION:	Fair	in the early 2000s. However, the museum subsequently suffered from significant condensation. Historic England
	OCCUPANCY:	Part occupied/part in use	grant aided investigation work through a Section 17
	PRIORITY CATEGORY:	C (C)	Management Agreement in 2015. Grant assistance to address these issues was declined but the owner funded a
	OWNER TYPE:	Private	partial scheme in 2020.
	LIST ENTRY NUMBER:	1007061	Contact: Amanda White 0121 625 6890

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / EREWASH / HIGH PEAK

	SITE NAME:	United Reformed Church and attached parish rooms, Wharncliffe Road, Ilkeston	Roof design and rainwater disposal arrangements were problematic and not readily accessible for repair. Problems with slating and undersized and complicated rainwater
N. C.	DESIGNATION:	Listed Place of Worship grade II, CA	goods were addressed in 2020. The movement in tower pinnacles, the leaning tower walkway and the cause of movement in the front steps have yet to be addressed. An
m Mal-	CONDITION:	Poor	application to the National Lottery Heritage Fund in 2018 was unsuccessful. The congregation continues to fundraise
	PRIORITY CATEGORY:	F (F)	for a further phase of repairs but Covid-19 has impacted
	OWNER TYPE:	Religious organisation	upon this.
© Historic England	LIST ENTRY NUMBER:	1140446	Contact: Amanda White 0121 625 6890
	SITE NAME:	All Saints Church, Church	Parish church from late CI2 with some fabric from early



© Peter Rogan Associates Ltd

	SITE NAME:	All Saints Church, Church Street, Ockbrook and Borrowash	Parish church from late C12 with some fabric from early C14. Four stage tower with later broached stone spire. The church was rebuilt between 1800 -1835 and minor
	DESIGNATION:	Listed Place of Worship grade II*, CA	alterations took place in C20. The church was the subject of Heritage Crime in 2019. The chancel ceiling has been removed as a result of the water damage. The top most
	CONDITION:	Poor	capstone of the spire and the base stone beneath it have split. The top section of the spire is also open jointed.
	PRIORITY CATEGORY:	A (A)	Temporary strapping is in place but permanent repairs are
	OWNER TYPE:	Religious organisation	required. The congregation is keen to effect repairs.
	LIST ENTRY NUMBER:	1087941	Contact: Hanna Good 07825 318060

SITE NAME:	Ilkeston Town Centre, Ilkeston			
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Low	CONTACT:	Erewash Borough Council 0115 907 2244	
SITE NAME:	Long Eaton Town Centre, Long Eaton			
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Erewash Borough Council 0115 907 2244	
SITE NAME:	Morley			
DESIGNATION:	Conservation Area, 9 LBs, SM	NEW ENTRY ?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Erewash Borough Council 0115 907 2244	

HIGH PEAK

© Historic England



Е

use).

SITE NAME:	Stodhart Tunnel, Hayfield Road, Chapel-en-le-Frith	T o
DESIGNATION:	Listed Building grade II*	st V
CONDITION:	Poor	b tu
OCCUPANCY:	N/A	b
PRIORITY CATEGORY:	C (C)	ad de
OWNER TYPE:	Private	d
LIST ENTRY NUMBER:	1334843	pi

ramway tunnel entrance, 1796. Considered to be the oldest surviving rail-related tunnel in the world. Some stones missing, repointing and vegetation removal needed. Nater penetrating the tunnel roof and attached walls are owing due to tree roots. Concern over the distorted unnel lining which requires propping. Later section in etter condition but entrance blocked. Secure from public ccess. Discussions are ongoing with one of the owners to letermine how Historic England can encourage levelopment of a local trust to take forward repairs and resentation to the public.

Contact: Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / HIGH PEAK / NORTH EAST DERBYSHIRE

LIST ENTRY NUMBER:

Cowdale quarry, limestone

King Sterndale

Very bad

N/A

A (A)

Private

1399726

Scheduled Monument



Cowdale Quarry retains elements of the complete industrial process of lime quarrying and processing within extraction and processing site, their original setting. Some of the standing structures are in a very bad condition. Intrusive tree and scrub growth is widespread. Historic England gave advice to inform a planning application for a mineral water bottling plant, encouraging provisions to address the condition of the scheduled monument. The development has not progressed. The site has various low key uses. Unauthorised access and damage has been reported.

Contact: Ben Robinson 07823 327796

Contact: Hannah Reynolds 07557 827971

© Historic England



SITE NAME:	Torr Vale Mill, New Mills	Remarkable survival of a textile factory c1790. Long term
DESIGNATION:	Listed Building grade II*, CA	heritage at risk site with significant improvement in the last few years. A manufacturing business, office space, events
CONDITION:	Poor	venue, bar/restaurant, retail units and holiday accommodation have been created. Historic England grant
OCCUPANCY:	Part occupied/part in use	for the repair of the main mill building roof is due to
PRIORITY CATEGORY:	F (F)	complete. Further phases of repair work are required other buildings/areas of the site. The owner is working
OWNER TYPE:	Commercial company	with Historic England, the Local Authority and Heritage Trust to secure viable uses and funding for remaining areas
LIST ENTRY NUMBER:	972	of the site.

© Historic England

© Historic England



- Inter	SITE NAME:	Church of St Edmund, Back Street, Castleton, High Peak	C12 parish church with later fabric. Rainwater disposal is problematic; there are large damp patches internally,
	DESIGNATION:	Listed Place of Worship grade II*, CA	blocked drains and significant condensation. Historic England and the National Lottery Heritage Fund awarded a grant to re-cover the nave roof in c1996. Further funds
	CONDITION:	Poor	were awarded in 2010 for remedial work. The church continues to suffer on account of defects in the rainwater
	PRIORITY CATEGORY:	D (D)	disposal system. An application to the National Lottery
	OWNER TYPE:	Religious organisation	Heritage Fund was unsuccessful in 2013. The church had since raised funds, but progress has stalled.
	LIST ENTRY NUMBER:	1087866	Contact: Amanda White 0121 625 6890

SITE NAME:	Melandra Castle Roman fort		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004595
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Carter 0121 625 6860

NORTH EAST DERBYSHIRE

			*
4	- AL		
	FC		
1	-1-1-1	A H	62

	line				
	SITE NAME:	Coke ovens, Dronfield / Unstone			
	DESIGNATION:	Scheduled Monument			
	CONDITION:	Very bad			
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	D (D)			
	OWNER TYPE:	Private			
	LIST ENTRY NUMBER:	1018379			

Coke ovens, C19. Divided ownership and in gradual decline. Conservation plan and commissioned survey completed but future management remains unresolved.

Contact: Ben Robinson 07823 327796

© Historic England

PR	IOR	ITY	CAT	E	GOR	IES	

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ŬA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / NORTH EAST DERBYSHIRE / PEAK DISTRICT (NP) / SOUTH DERBYSHIRE

SITE NAME:	Ruins of Trinity Chapel, Brackenfield		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1007037
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Clay Cross Town Centre, Clay Cross		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	(LPA) 01246 217180
SITE NAME:	Eckington and Renishaw Park, Eckington, Eckingtor	n / Killamarsh	
DESIGNATION:	Conservation Area, 38 LBs, part in RPG grade II*, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	(LPA) 01246 217180
SITE NAME:	Morton		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	(LPA) 01246 217180
PEAK DISTRICT (NP)			
SITE NAME:	Alport smelt mill, Harthill, Derbyshire Dales		

SITE IVALE.	Alport smelt mill, Flattini, Derbysnite Dales		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1009704
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Carter 0121 625 6860

SOUTH DERBYSHIRE

	SITE NAME:	Four bottle kilns at TG Greens Pottery, John Street, Church Gresley, Swadlincote	Four C19 bottle kilns and surrounding factory complex of the T G Green & Co pottery, which is particularly famous for its 'Cornish Ware'. The buildings are vacant and have
	DESIGNATION:	Listed Building grade II*	suffered from vandalism. Long standing defects to roof coverings, rainwater goods, and unsecured openings have
The search and the J	CONDITION:	Very bad	not been addressed. Roof trusses have failed causing major collapses. The owner has applied to demolish selected
STATE PROPERTY	OCCUPANCY:	Vacant/not in use	buildings. Historic England has discussed a grant-aided
	PRIORITY CATEGORY:	A (A)	condition survey with the owner and Council. The Council instead intends to work on a feasibility study for the site,
	OWNER TYPE:	Private	but no progress has been made.
© Historic England	LIST ENTRY NUMBER:	1280950	Contact: Ben Robinson 07823 327796

	SITE NAME:	Brizlincote Hall Farmhouse, Brizlincote Lane, Bretby	Country house, now farmhouse. Built in 1707 for the Second Earl of Chesterfield in red brick and sandstone
	DESIGNATION:	Listed Building grade II*	ashlar. The building has been deteriorating for many years and stonework is heavily weathered. There are numerous
	CONDITION:	Poor	defects, such as missing and broken masonry elements and eroded and spalling brickwork. The rainwater goods have
	OCCUPANCY:	Part occupied/part in use	historically leaked, which is causing damage to the fine
	PRIORITY CATEGORY:	C (C)	panelled interior.
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1096480	Contact: Hanna Good 07825 318060

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH DERBYSHIRE



A THE	SITE NAME:	Coalbrookdale footbridge, (on former Egginton Estate), Egginton	Footbridge, 1812. Cast-iron curved bridge. Bears the inscription 'Coalbrookdale 1812'. Structurally unsound. Sections of the ironwork are missing or corroded. The
	DESIGNATION:	Listed Building grade II*	upstream flood arches have partially collapsed. The brick abutment walls are in need of consolidation and repair. The
	CONDITION:	Very bad	sluice gate appears to be non-functional. Initial discussions were held with the landowner about options and funding.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1140125	Contact: Ben Robinson 07823 327796

© Historic England



	SITE NAME:	Elvaston Castle, Borrowash Road, Elvaston	Country house, 1633, altered C18 and early C19, has formal gardens to the south, south east, pleasure grounds
	DESIGNATION:	Listed Building grade II*, RPG grade II*	to the north and north east, and a range of courtyards and outbuildings to the west. Gardens were laid out 1830-1851 by William Barron. Permanent repairs to garden structures,
	CONDITION:	Fair	survey and strategic options report all completed with grants from Historic England. The Castle has been re-
	OCCUPANCY:	Part occupied/part in use	roofed and the orchid house has been re-glazed, with the
	PRIORITY CATEGORY:	D (D)	entire roof now water-tight. An on-going programme of repairs is being undertaken in accordance with the
	OWNER TYPE:	Local authority	masterplan for the site.
	LIST ENTRY NUMBER:	1334604	Contact: Erika Diaz Petersen 0121 625 6879

© Historic England



© Historic England



	SITE NAME:	Overseal House, 10-14, Acresford Road, Overseal	CI9 additions. Believed to have been built for Joseph
	DESIGNATION:	Listed Building grade II*	Wilkes, a local industrialist. The building has fallen into disrepair in recent years. Formerly a guest house, the
A AND	CONDITION:	Poor	current occupiers plan to refurbish the property. There is evidence of localised structural movement, which may be
	OCCUPANCY:	Part occupied/part in use	able, external joinery is in poor condition and it is evident
A THE P	PRIORITY CATEGORY:	C (C)	that there has been water ingress through the rear bay roof. Externally, paths and steps have been' lost' under
Contraction of the local distribution of the	OWNER TYPE:	Private	undergrowth. The ha-ha is deteriorating.
	LIST ENTRY NUMBER:	3 62	Contact: Amanda White 0121 625 6890

. . .

. . . .

.....

~ . ~

	SITE NAME:	Shardlow Hall, London Road, Shardlow and Great Wilne	Small country house built in 1684. Some remodelling was undertaken in 1726 by Francis Smith of Warwick, and again
	DESIGNATION:	Listed Building grade II*, CA	in 1768 by Joseph Pickford when Palladian flanking wings were added. Was in use as a Preparatory school in the
	CONDITION:	Poor	early C20 and used as offices of the Ministry of Agriculture, Fisheries and Food from 1946 to 1986. The hall is now
	OCCUPANCY:	Part occupied/part in use	surrounded by poor quality C20 buildings. Roofs are in
	PRIORITY CATEGORY:	C (C)	need of repair. The windows are in poor condition and the internal panelling is beginning to splinter. The building has
	OWNER TYPE:	Private	been the victim of heritage crime. Some patch repairs have been undertaken.
	LIST ENTRY NUMBER:	1088368	Contact: Hanna Good 07825 318060

© Historic England



OCCUPANCY. N/A PRIORITY CATEGORY: F (F) OWNER TYPE: Local authority © South Derbyshire District Council LIST ENTRY NUMBER: 1007076 and 1088337

SITE NAME:

DESIGNATION:

CONDITION:

D

Е

surviving stone bridge in England. Spans River Trent. Medieval with alterations in C18. Bridge at risk from the volume of traffic. Unacceptable damage to parapets occurring from regular road traffic accidents. Further traffic calming measures and enforcement of weight restrictions are required. Repair and maintenance programme underway within the terms of a management agreement.

River bridge and causeway combine to form the largest

Contact: Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Swarkestone Bridge, Stanton by

Scheduled Monument and Listed

Bridge / Swarkestone

Building grade I, 2 CAs

Fair

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH DERBYSHIRE



	SITE NAME:	Remains of Swarkestone Old Hall, Derby Road, Swarkestone	Remains of Swarkestone Old Hall and complex of walls relating to the gardens of the Old Hall, C16. All buildings
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	are in a state of decay with dislodged bricks and stone work particularly prevalent to the tops of walls and in openings. Owner has worked with Natural England
	CONDITION:	Poor	through a Countryside Stewardship Scheme in the past to address these issues. Cows have now been replaced by
	OCCUPANCY:	N/A	sheep, thereby reducing attrition to the walls. The owners
	PRIORITY CATEGORY:	C (C)	wish to undertake further repairs.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1280604	Contact: Hanna Good 07825 318060

© Historic England

© Historic England



	SITE NAME:	Walton Hall, attached stables and garden wall, Main Street, Walton upon Trent	Small early C18 country house in red brick with stone detailing, effectively a symmetrical box. Grade II outbuildings are in a poor condition. The hall is in new	
TEST.	DESIGNATION:	Listed Building grade II*, CA	ownership and a phased programme of works is underv	
	CONDITION:	Fair		
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1159300	Contact: Rosemary Thompson 07768 215540	

SITE NAME

DESIGNATION:

CONDITION:

OCCUPANCY:

LIST ENTRY NUMBER:





issues. Historic England grant-aided urgent staircase repairs PRIORITY CATEGORY: C (C) in 2017 and roof and other structural repairs in 2018. The latter completed in late 2019. Modern additions were OWNER TYPE: Commercial company repaired in early 2020. LIST ENTRY NUMBER: 1088352 Contact: Amanda White 0121 625 6890 Largely C14 church, incorporating part of a C12 monastic church. The tower is C15 and the remainder is C18 and SITE NAME: Church of St George and St Mary, Church Street, Church C19. The church lies to the north of a former colliery site Gresley and there is a history of structural movement, including to DESIGNATION: Listed Place of Worship grade II* the stair turret. The National Lottery Heritage Fund Grants for Places of Worship scheme grant aided localised tree CONDITION: Poor management, drainage and turret structural repairs in 2015. PRIORITY CATEGORY: The nave and chancel slate roofs are in poor condition. D (D) There is also a loss of fabric at parapet level. A 2020 OWNER TYPE: Religious organisation National Lottery Heritage Fund grant for development

© Historic England



SITE NAME: All Saints Church, Dalbury, **Dalbury** Lees DESIGNATION Listed Place of Worship grade II* CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1334550

1204963

Weston Hall, Main Street,

Weston upon Trent

Poor

Listed Building grade II*

Part occupied/part in use

© Historic England

Contact: Hanna Good 07825 318060 Parish church dating from C13 with minor C18 alterations. Restored in 1844 and north aisle added. A programme of repairs has been completed over several years. The south wall of the nave (which retained patches of inappropriate cement-based mortar) was particularly damp but is drying out following the installation of new drains in 2019. The marble pulpit and pews were badly affected by damp and their condition is being monitored. The Parochial Church Council were invited to apply for an Historic England Covid 19 Heritage at Risk Recovery Grant but were unable to pursue an application.

A large ambitious country house c1625-30, only ever part built. Reputedly used as a barracks for soldiers when Civil

War fighting broke out in Weston in 1644. Lower floors

have been in hospitality use since the 1990s; upper floors may always have been vacant. Kitchen and bar facilities

were upgraded post 2011. By 2017 roof coverings were in

poor condition and there were some significant structural

Contact: Amanda White 0121 625 6890

work has been completed.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

use)

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building LB
- Local Planning Authority National Park I PA
- NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH DERBYSHIRE / LEICESTER, CITY OF (UA)

	SITE NAME:	Church of St James, London Road, Shardlow and Great Wilne	Parish church, 1846, by H I Stevens. The tower has a history of structural movement and there is a long history of iron cramp damage generally with some previous repairs
	DESIGNATION:	Listed Place of Worship grade II, CA	having failed. Rainwater disposal is problematic and cast- iron windows are in poor condition. A repair project supported by the National Lottery Heritage Fund
	CONDITION:	Poor	completed in late 2019 but not all necessary repairs were affordable. Recipient of an Historic England Covid 19
	PRIORITY CATEGORY:	A (F)	Emergency Heritage at Risk Response Fund grant in 2020
	OWNER TYPE:	Religious organisation	for further repairs. Further repairs are required; a large fragment of stone has recently fallen.
© Historic England	LIST ENTRY NUMBER:	1088362	Contact: Hanna Good 07825 318060

SITE NAME:	Swarkestone Lows round barrow cemetery and part of an aggregate field system 300m north west of The Lowes Farm, Swarkestone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019060
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Twyford henge and Round Hill bowl barrow, Twyfo	rd and Stenson	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011436
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Nick Carter 0121 625 6860



© Historic England

	Twyford henge ar	nd Round Hill bowl barrow, Twyfo	rd and Stenson	
	Scheduled Monun	nent	LIST ENTRY NUMBER:	1011436
	Extensive significa	nt problems	TREND:	Declining
NERABILITY:	Animal burrowing	g - moderate	NEW ENTRY ?:	No
	Private		CONTACT:	Nick Carter 0121 625 6860
	SITE NAME:	Elvaston Castle, Elvaston	A unique Victorian fantasy, the work of designer Williar Barron, which showcased the use of native and exotic evergreen trees as a winter garden. Later one of the country's earliest country parks. High use and lack of investment over many years has seen major decline in t condition of infrastructure, built and planted features. Historic England grant-aided repairs to listed structures within the garden and appraisals to help inform the futu direction of the site. In 2022, planning and listed buildin consent applications have been submitted for works to implement Phase I of the masterplan.	
	DESIGNATION:	Registered Park and Garden grade II*, 19 LBs		
- Aller	CONDITION:	Generally unsatisfactory with major localised problems		
	VULNERABILITY:	High		
	TREND:	Declining		
and the second	NEW ENTRY ?:	No		
1	OWNER TYPE:	Mixed, multiple owners		
	LIST ENTRY NUMBER:	1000404	Contact: Erika Di	az Petersen 0121 625 6879

LEICESTER, CITY OF (UA)



SITE NAME: Newarke Wall (Along north west end of Gardens of Newarke Houses Museum), the Newarke DESIGNATION: Listed Building grade II*, SM, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1361054

Wall, c1423, which formed the boundary of St Mary-de-Castro and The Newarke. Coursed stone with ramp coping. Approximately fifteen feet high. Stone walling has suffered slow decay over many years - there has been significant weathering of walling material and dressings. Deterioration has been exacerbated by past inappropriate repairs including cement based pointing mortars. There is potentially damaging woody rooted plant growth also. Leicester City Council are responsible for undertaking repairs. Funding is currently targeted at higher priority repair work elsewhere in the city.

Contact: Rachel Jordan 0121 625 6854

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / LEICESTER, CITY OF (UA)

- A A	SITE NAME:	Abbey ruins, precinct walls, and remains of Cavendish House, Abbey Park	C12 Augustinian monastery, precinct walls and remains of C17 Cavendish House in a C19 public park. Urgent repairs needed on stretches of the precinct wall, cavendish House and medieval niche. Project development work was
	DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade I, part in RPG grade II*	completed with Historic England grant aid in 2019. Leicester City Council has subsequently been progressing programmes repair across the site. Cavendish House has
	CONDITION:	Very bad	been completed and the niche is due to be consolidated summer 2022. Most of the precinct walls have been
	OCCUPANCY:	N/A	addressed. Works are still needed on sections of the
	PRIORITY CATEGORY:	F (F)	eastern precinct wall.
Historic England Archive	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1012149 and 1074051; 1074052; 1361406	Contact: Nick Carter 0121 625 6860
	SITE NAME:	County Court including remains of Leicester Castle - John O'Gaunts cellar, Castle Yard	Building on the site of Leicester Castle, built by Robert Le Bossu c1168. Slighted in the Civil War, the present brick facade dates to c1695. Converted to courts in 1856. The
22/11	DESIGNATION:	Listed Building grade I and Scheduled Monument, CA	former County Court has been repaired and converted fo university use and is no longer at risk. However, the medieval John O'Gaunt cellar is still in urgent need of
	CONDITION:	Poor	repair. Ingress of water is placing the fabric at risk. Leicester City Council is exploring options with the
	OCCUPANCY:	Vacant/not in use	potential to stabilise the structure and improve access to in
Contraction of the second	PRIORITY CATEGORY:	C (C)	
D Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1200622 and 1012147	Contact: Rachel Jordan 0121 625 6854
the state	SITE NAME:	Parish Church of St Peter, Church Road, Belgrave	The church has been closed as a place of worship since 2010. The building has since been vacant except for
	DESIGNATION:	Listed Building grade II*, CA	occasional use as a concert/recital venue by a local community group. Subject to heritage crime in 2011, a
	CONDITION:	Fair	temporary solution was put in place which is now reaching
	OCCUPANCY:	Vacant/not in use	the end of its effective life. The building fabric and surrounding church yard appear to be kept in fair conditio
	PRIORITY CATEGORY:	E (E)	but a permanent solution to the long term vacancy and required repairs has not yet been found, the building
	OWNER TYPE:	Religious organisation	condition continues to deteriorate. The building is being
D Historic England	LIST ENTRY NUMBER:	1074029	marketed. Contact: Hannah Reynolds 07557 827971
	SITE NAME:	HSBC Bank, 31, Granby Street, Leicester	Former HSBC bank, 1872-74 by Joseph Goddard in the French Gothic Revival style. Large banking hall with
A CONTRACTOR	DESIGNATION:	Listed Building grade II*, CA	elaborate timber roof and stained glass. The main building is currently used for worship. Stained glass windows have
	CONDITION:	Poor	been repaired and the upper floors converted. Urgent
	OCCUPANCY:	Part occupied/part in use	repairs were completed on one roof in March 2018 with financial support from Leicester City Council. A High Stre
	PRIORITY CATEGORY:	C (C)	Heritage Action Zone grant aided repair programme is ongoing, due for completion late 2022.
	OWNER TYPE:	Commercial company	ongoing, due for completion late 2022.
) Leicester City Council	LIST ENTRY NUMBER:	1074047	Contact: Imogen Newcombe 07387 524030
	SITE NAME:	St Saviour's Church, St Saviour's Road, Leicester	Former church built 1875-7 by Sir GG Scott. Brick in the Early English style with a broach spire, gable and rose
	DESIGNATION:	Listed Building grade II*	window which dominate the locality. No longer in ecclesiastical use and vacant. Significant repairs are require
	CONDITION:	Poor	to the spire, roof and guttering. Planning and Listed Buildin
	OCCUPANCY:	Vacant/not in use	Consent applications have been approved to enable new Christian worship in the church. Works have started on
	PRIORITY CATEGORY:	D (D)	site.
	OWNER TYPE:	Religious organisation	
© Historic England	LIST ENTRY NUMBER:	1074774	Contact: Janine Dykes 0121 6256870
PRIORITY CATEGORIES A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. 3 Immediate risk of further rapid	 D Slow decay; solution not yet implemented E Under repair or in fa repair, but no user ir 	d. (where applicable) end use o nir to good user identified; or functionally	or Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
 - agreed but not yet implemented.
- ry ted).
- NP
 National Park

 RPG
 Registered Park and Garden

 SA
 Scheduled Monument

 UA
 Unitary Authority

 WHS
 World Heritage Site

14

HERITAGE AT RISK 2022 / MIDLANDS / LEICESTER, CITY OF (UA)

	,		
	SITE NAME:	Church of St Mary De Castro, Castle Yard, Leicester	A National Lottery Heritage Fund grant was awarded in 2011 for a detailed assessment of the spire. The condition
	DESIGNATION:	Listed Place of Worship grade I, SM, CA	of masonry was such that urgent dismantling was necessary, this was completed in summer 2014. Much further repair work has been undertaken as part of a four-
	CONDITION:	Poor	year staged plan to tackle backlog repairs. The next phase will include masonry repairs to the south wall and south
	PRIORITY CATEGORY:	D (D)	aisle gable. Fundraising is underway. There are currently
	OWNER TYPE:	Religious organisation	no plans to rebuild the spire.
	LIST ENTRY NUMBER:	1074070	Contact: Janine Dykes 0121 6256870
listoric England			

© Hist



	SITE NAME:	St Margaret's Church, Church Gate, Leicester	Large, mainly C15, city centre church. By 2019 various sandstone walling had deteriorated and was shedding stone
	DESIGNATION:	Listed Place of Worship grade I	fragments. Scaffolding above the west door of the tower has now been removed. There were localised flashing
	CONDITION:	Very bad	defects, vegetation, rainwater disposal issues at high and low level and water penetration. An Expression of Interest
	PRIORITY CATEGORY:	C (F)	was submitted to the National Lottery Heritage Fund in
	OWNER TYPE:	Religious organisation	2019. An Historic England Covid-19 Emergency Heritage at Risk Response Fund award enabled repairs to the south
	LIST ENTRY NUMBER:	1074072	porch and the tower has been repaired through a Heritage Stimulus Fund award.

© Historic England



© Historic England

© Historic England

	1-	
Par al		心理
	Z	く開
	-	

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

			5
A	SITE NAME:	Serbian Orthodox Church of St George, Rutland Street, Leicester	Built in 1823-7 by William Parsons; the chancel was added by Sir Arthur Blomfield in 1879. In use as a Serbian Orthodox place of worship in the centre of Leicester.
	DESIGNATION:	Listed Place of Worship grade II*, CA	Work to roof coverings and timber repairs, rainwater goods and drainage was funded in two phases under the joint Historic England/ National Lottery Heritage Fund
1-5	CONDITION:	Fair	repair grants scheme in 2014. The fabric remains at risk from water penetration caused by the blockages of the high
	PRIORITY CATEGORY:	C (C)	level rainwater disposal system due to the proximity of
	OWNER TYPE:	Religious organisation	churchyard trees. Plans have been submitted to open views to the church by reducing the tree cover.
	LIST ENTRY NUMBER:	1299776	Contact: Ben Robinson 07823 327796

Urban church of 1872-79 by GE Street in a Gothic style. By
2014, tower masonry and roof coverings were in poor
condition, however the fan scaffold has now been
removed. A first phase of repairs has been completed with
funding from the National Lottery Heritage Fund under the
Grants for Places of Worship to address the deterioration
of the tower. Due to unforeseen circumstances, repairs to
the baptistery and south porch roof were not completed.
Repairs are also required to several other roofs.
Discussions are ongoing about prioritising repair
programmes.
P. 68. a

Contact: Imogen Newcombe 07387 524030

Contact: Imogen Newcombe 07387 524030

SITE NAME:	All Saints, Leicester		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Justin Webber (LPA) 0116 454 4638
SITE NAME:	Churchgate, Leicester		
SITE NAME: DESIGNATION:	Churchgate, Leicester Conservation Area, 6 LBs	NEW ENTRY?:	No
	-	NEW ENTRY?: TREND:	No Deteriorating

Church of St Peter, St Peter's

Listed Place of Worship grade II

Road, Leicester

Religious organisation

Very bad

1361047

A (A)

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park

 - Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / LEICESTER, CITY OF (UA) / BLABY / CHARNWOOD

SITE NAME:	Market Place, Leicester		
DESIGNATION:	Conservation Area, 30 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Justin Webber (LPA) 0116 454 4638

LEICESTERSHIRE

BLABY

LABY			
	SITE NAME:	Church of St Bartholomew, Foston Lane, Kilby	Church of C10 or C11 origin though most is early C14. Extensively restored and altered in 1874. Granite rubble
	DESIGNATION:	Listed Place of Worship grade II*	with limestone dressings and Swithland slate roofs. West tower, nave with north aisle and chancel in one. Chancel
	CONDITION:	Fair	movement was brought to Historic England's attention in 2020. Historic England subsequently gave a Covid-19
	PRIORITY CATEGORY:	F (B)	Emergency Heritage at Risk Response Fund grant later in
	OWNER TYPE:	Religious organisation	2020 to investigate. Structural repairs have since been undertaken. Repairs arising from an unrelated problem
and a start of	LIST ENTRY NUMBER:	1177157	with roof coverings are in hand and are due to complete later in 2022.

© Historic England

CHARNWOOD

Contact: Amanda White 0121 625 6890

Â.	SITE NAME:	The Temple of Venus, Garendon Park, Ashby Road, Loughborough	Temple designed by Ambrose Phillipps, 1730s. Located in open parkland, one kilometre south/south west of the site of Garendon Hall. Aligned on the Triumphal Arch to the
	DESIGNATION:	Listed Building grade II*, RPG grade II	west along an avenue of alternating deciduous and coniferous trees. Temple not used, but in fair condition although not regularly maintained. The outline application
	CONDITION:	Fair	for a Sustainable Urban Extension was approved in 2015, subject to a Section 106 Agreement requiring repair and
	OCCUPANCY:	Vacant/not in use	restoration of the park and its buildings. A reserved
© Historic England	PRIORITY CATEGORY:	D (D)	matters planning application was submitted in 2020 that includes the restoration of the park.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1116109	Contact: Erika Diaz Petersen 0121 625 6879

	SITE NAME:	The Triumphal Arch, Garendon Park, Ashby Road, Loughborough	Triumphal entrance archway designed by Ambrose Phillipps, 1730s. Located on the edge of pleasure grounds around White Lodge, 1100 metres south west of the site
	DESIGNATION:	Listed Building grade I, RPG grade II	of Garendon Hall. Aligned on the Temple of Venus to the east along an avenue of trees. Arch and lodge in fair condition although not regularly maintained. The outline
	CONDITION:	Fair	application for a Sustainable Urban Extension was approved in 2015, subject to a Section 106 Agreement
A ROUTA	OCCUPANCY:	N/A	requiring repair and restoration of the park and its
© Historic England	PRIORITY CATEGORY:	D (D)	buildings. A reserved matters planning application was submitted in 2020 that includes the restoration of the park.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1361136	Contact: Erika Diaz Petersen 0121 625 6879



	SITE NAME:	Taylor's Bell Foundry (on east side of Cobden Street), Freehold Street, Loughborough	Bell foundry c1859 with late C19 and early C20 additions and alterations. The only historic purpose-built bell foundry in England in use. By 2011 buildings were in poor condition.
	DESIGNATION: Listed CONDITION: Poor	Listed Building grade II*	Historic England grant aided much urgent work. The National Lottery Heritage Fund awarded a grant to
		Poor	develop a major repair and public access project in 2018 followed by a grant of c 3.5M in 2021 for works. Work is
OCCUPANCY:	Occupied/in use	expected to commence in summer 2022 and finish in late	
1 SE	PRIORITY CATEGORY:	F (F)	2023. Funds are insufficient to tackle all repair needs. Further urgent work took place in 2020 with Historic
OWNER TYPE:	Commercial company	England Heritage Stimulus Funds.	
	LIST ENTRY NUMBER:	1236293	Contact: Amanda White 0121 625 6890

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / CHARNWOOD

	SITE NAME:	Taylor's Bell Foundry (on west side of Cobden Street), Freehold Street, Loughborough	Bell foundry c1859 with late C19 and early C20 additions and alterations. The only historic purpose-built bell foundry in England in use. By 2011 buildings were in poor condition.
	DESIGNATION:	Listed Building grade II*	Historic England grant aided much urgent work. The National Lottery Heritage Fund awarded a grant to
	CONDITION:	N: Poor develop :	develop a major repair and public access project in 2018 followed by a grant of c 3.5M in 2021 for works. Work is
	OCCUPANCY:	Occupied/in use	expected to commence in summer 2022 and finish in late
	PRIORITY CATEGORY:	F (F)	2023. Funds are insufficient to tackle all repair needs. Further urgent work took place in 2020 with Historic
	OWNER TYPE:	Charity (heritage)	England Heritage Stimulus Funds.
© Historic England	LIST ENTRY NUMBER:	1264685	Contact: Amanda White 0121 625 6890
	SITE NAME:	Ulverscroft Priory ruins, Priory Lane, Ulverscroft	The Priory of St Mary was founded in 1134 by Robert, Earl of Leicester, and was taken over by the Augustinian order
	DESIGNATION:	Scheduled Monument and Listed Building grade I	in 1174. Visible remains date to C13, C14 and C15. Parts of the outbuildings have been restored as two cottages. The Parlour/Prior's lodging is propped and has a
A AAAA	CONDITION:	Very bad	temporary roof. A schedule of repairs was prepared
	OCCUPANCY:	Part occupied/part in use	several years ago, but no further progress has been made. Historic England is seeking engagement with the owner to
	PRIORITY CATEGORY:	D (D)	update condition assessment and repair schedule.
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1008554 and 1295073	Contact: Nick Carter 0121 625 6860
$(\mathbf{y}_{i}) \in \mathcal{Y}_{i}$	SITE NAME:	Church of All Saints, Main Street. Cossington	Church of C13-C15 and C19 constructed of granite rubble stone with stone dressings. Awarded a grant from the

	SITE NAME:	Church of All Saints, Main Street, Cossington	Church of C13-C15 and C19 constructed of granite rubble stone with stone dressings. Awarded a grant from the
	DESIGNATION:	Listed Place of Worship grade II*, CA	Listed Places of Worship Roof Repair Fund in 2015. Roofs are in good condition but below ground drainage is defective. Chancel wall plaster has detached, and the south
	CONDITION:	Poor	aisle is damp. The Parochial Church Council applied to the
	PRIORITY CATEGORY:	C (C)	National Lottery Heritage Fund in 2018 and to Historic England's Covid 19 Emergency Heritage at Risk Response
	OWNER TYPE:	Religious organisation	Fund in 2020 but were unsuccessful.
	LIST ENTRY NUMBER:	1228032	Contact: Hanna Good 07825 318060
-			

	SITE NAME:	Church of St John the Baptist, Main Street, South Croxton	Ironstone rubble church, with ashlar dressings throughout, dating mostly from C14. West tower with spire of large
	DESIGNATION:	Listed Place of Worship grade II*, CA	and squared rubble, three stages and buttressed, on an ashlar plinth. The tower masonry is weathered with some unstable high-level stonework. There are signs internally
	CONDITION:	Poor	that the nave roof and tower are leaking. The rainwater goods require overhauling and possible upgrading. The
	PRIORITY CATEGORY:	C (C)	below ground drainage may also be poor. Repairs to tower
	OWNER TYPE:	Religious organisation	louvres and floors completed through grant support from Historic England's Covid 19 Emergency Heritage at Risk
	LIST ENTRY NUMBER:	1361188	Response Fund.
oric England			Contact: Hanna Good 07825 318060

Deserted medieval village of Hamilton, Barkby Thorpe SITE NAME: DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012557 Generally satisfactory but with significant localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY ?: No Stock erosion - extensive OWNER TYPE: CONTACT: Tim Allen 07770 610214 Private

PRIORITY CATEGORIES

© Leicester DAC

© Histor

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park

 - Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

1000379

	.			
SITE NAME:	Bradgate: house,	chapel, garden and watermill, Nev	wtown Linford	
DESIGNATION:	Scheduled Monu	ment, 3 LBs, RPG grade II	LIST ENTRY NUMBER:	1008831
CONDITION:	Generally satisfac problems	ctory but with minor localised	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion	- extensive	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority		CONTACT:	Amanda White 0121 625 6890
	SITE NAME:	Garendon Park		dian landscape c1730, complete with
	DESIGNATION:	Registered Park and Garden grade II, 13 LBs, SM	triumphal arch and temple (both buildings at risk), de by Ambrose Phillipps, a member of the Society of Dilettanti. Now seriously degraded. An outline applic for a Sustainable Urban Extension was approved in 2 subject to a Section 106 Agreement requiring the rep and restoration of the park and its buildings. A reserv	
- HAL	CONDITION:	Generally satisfactory but with significant localised problems		
	VULNERABILITY:	High	matters planning	application was submitted in 2020 that
	TREND:	Declining	includes the restoration of the park.	
	NEW ENTRY?:	No		
© Historic England	OWNER TYPE:	Private		

Contact: Erika Diaz Petersen 0121 625 6879

SITE NAME:	Shelthorpe		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Martin Jones 01509 634971
SITE NAME:	Shepshed		
SITE NAME: DESIGNATION:	Shepshed Conservation Area, 13 LBs	NEW ENTRY?:	No
	·	NEW ENTRY?: TREND:	No Deteriorating
DESIGNATION:	Conservation Area, 13 LBs		

HARBOROUGH

	SITE NAME:	Withcote Hall, Oakham Road, Withcote	Country house, early C18, incorporating earlier Tudor building, outbuildings and walled garden. Detailed condition
DESIGNATION: CONDITION: OCCUPANCY:	DESIGNATION:	Listed Building grade II*	survey carried out in early 2002 part-funded by Historic England. The house deteriorated to a very bad condition
	Poor	through neglect and water ingress. The roof required repair and recovering; there was extensive rot, structural	
	OCCUPANCY:	Vacant/not in use	movement and defective plasterwork. Repairs commenced
	PRIORITY CATEGORY:	E (E)	in 2019 and have largely been completed externally. Historic England is researching the building and continues
	OWNER TYPE:	Private	to provide advice to the owner's agent and Harborough District Council during ongoing repairs.
	LIST ENTRY NUMBER:	1074844	Contact: Ben Robinson 07823 327796

© Historic England



	SITE NAME:	Church of St Mary, Gilmorton Road, Ashby Magna	Church of late C13 but restored and provided with a new chancel in 1861. The church comprises a four-stage
	DESIGNATION:	Listed Place of Worship grade II*	embattled west tower, nave with north aisle and blind clerestory and chancel with north vestry. Walls are of
A CO	CONDITION:	Poor	random granite rubble with field pebble galletting and limestone dressings. The stonework to the tower is in need
	PRIORITY CATEGORY:	A (A)	of repair and the rainwater goods are in a poor condition
	OWNER TYPE:	Religious organisation	with the downpipes displaced on the south side of the nave. The church was the subject of heritage crime in 2018
	LIST ENTRY NUMBER:	1061550	and subsequent funding avenues were explored.
			Contact: Hanna Good 07825 318060

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / HARBOROUGH

	SITE NAME:	Church of St Peter, Horninghold, Horninghold	The earliest fabric of this small church dates to the CI2 and CI3, with later CI5 work. Restored in 1844, 1904 and
	DESIGNATION:	Listed Place of Worship grade II*, CA	1936. Collyweston slates on the chancel and porch roofs are failing and require repair. Investigations are required to determine the extent of plaster failure to the chancel
	CONDITION:	Very bad	ceiling. The gutters and downpipes are inadequate and not sufficiently discharging water. Drainage works have been
	PRIORITY CATEGORY: OWNER TYPE:	A (A)	undertaken and works to the nave and aisles has been
		Religious organisation	completed through grant support from Historic England's Covid-19 Emergency Heritage at Risk Response Fund.
	LIST ENTRY NUMBER:	1360671	Contact: Imogen Newcombe 07387 524030

© Historic England



SITE NAME:	Church of St John the Baptist, King's Norton	Church in the Gothic Revival style. Built 1757-75 by John Wing the Younger of Leicester for William Fortrey, the
DESIGNATION:	N: Listed Place of Worship grade I, CA end of its life generally in f	Squire of King's Norton. Nave and chancel under one roof. The roof covering is in poor condition and is nearing the end of its life. Renewal is required. Rainwater goods are
CONDITION:		generally in fair condition but where there have been historic blockages to downpipes this has accelerated cramp
PRIORITY CATEGORY:	C (C)	damage in the stonework. Some repointing of stonework
OWNER TYPE:	Religious organisation	and some minor stonework repairs are required. The parapet pinnacles are suffering from cramp damage and are
LIST ENTRY NUMBER:	1360627	also in need of repair.
		Contact: Imogen Newcombe 07387 524030

Small parish church with fabric from C12, C13 and C15.

Restored late C19 by H.L Goddard of Leicester. Tower

of defects, it appears to be generally structurally sound. The tower roof is poorly detailed and has been leaking for

some time. Internal floors and access are poor. Pointing

Below ground drainage may also be poor. An application to the National Lottery Heritage Fund for repair programmes

generally has eroded or is defective. Rainwater goods serving the nave and the chancel require overhauling.

was unsuccessful in early 2019.

Contact: Hanna Good 07825 318060

masonry is weathered but whilst there are localised areas

© Leicester DAC



Church of St John the Baptist, Little Stretton DESIGNATION: Listed Place of Worship grade II* CONDITION: Very bad PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1294797

SITE NAME:

© Historic England

© Historic England

SITE NAME: Church dating from C12, C13, C15 and rebuilt in 1838. Church of St Giles, Gartree Rubble stone, with course squared stone and ashlar tower. Road, Great Stretton, Little Comprising nave, chancel, west tower and south porch. Stretton The tower is mainly of C15 construction. There are several DESIGNATION: Listed Place of Worship grade II* open joints to the exterior and some masonry repairs are needed. Guttering and downpipes are in need of CONDITION: Very bad refurbishment and improvements to below ground PRIORITY CATEGORY: A (A) drainage are needed. The interior shows signs of damp. The church is no longer used for worship. Repairs to the OWNER TYPE: Religious organisation base of the tower and parapet where undertaken in 2013. Discussions as to the building's future are on-going. LIST ENTRY NUMBER: 1074853 Contact: Janine Dykes 0121 6256870



SITE NAME:	Church of St Michael, Loddington Lane, Loddington	Church of mainly CI3 and CI4 work with early CI5 nave roof structure. The nave roof leaks, some roof coverings
DESIGNATION:	Listed Place of Worship grade II*, CA	are displaced and rainwater goods are in poor condition. Below ground drainage appears to be problematic. The nave roof structure and pew platforms have suffered from
CONDITION:	Very bad	wood boring insect attack. Localised areas of wall plaster have failed and some floor tiles had been colonised by
PRIORITY CATEGORY:	C (C)	algae. Applications to the National Lottery Heritage Fund
OWNER TYPE:	Religious organisation	for grants in 2017 (Grants for Places of Worship) and 2019 were unsuccessful. The PCC are keen to effect repairs.
LIST ENTRY NUMBER:	1361009	Contact: Hanna Good 07825 318060

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / HARBOROUGH / HINCKLEY AND BOSWORTH

	SITE NAME:	Church of St Leonard, Misterton with Walcote	Parish Church of coursed limestone, sandstone with ashlar dressings. Built in C14 and restored 1863 by William Smith.
	DESIGNATION:	Listed Place of Worship grade II*	West tower with octagonal spire, nave with clerestory, north and south aisle, and chancel. The church has been
	CONDITION:	Poor	the subject of heritage crime in 2017, 2018 and 2019. Repairs were recently undertaken in 2020. The rainwater
- 61	PRIORITY CATEGORY:	A (A)	goods are inadequate and have caused subsequent damp,
	OWNER TYPE:	Religious organisation	requiring further investigation. The Parochial Church Council remain keen to effect repairs.
	LIST ENTRY NUMBER:	1294954	Contact: Imogen Newcombe 07387 524030

© Mr Ian Paterson. Source: Historic England Archive

	SITE NAME:	Church of St Andrew, Main Street, Owston and Newbold	Church including remains of the former Augustinian Priory. C13, C14 and later fabric. Restored 1861. Fair order
	DESIGNATION:	Listed Place of Worship grade I, SM, CA	generally bar iron-jacking in the spire top. There is longstanding movement in a southern buttress and some masonry needs repairing, especially in the vicinity of leaking
	CONDITION:	Poor	rainwater goods. There is vegetation due to defective rainwater goods. A specification is to be prepared to
Store .	PRIORITY CATEGORY:	F (E)	inform grant funding bids. Tower and spire works
	OWNER TYPE:	Religious organisation	completed through an Historic England Covid-19 Emergency Heritage at Risk Response Fund award in 2020.
zland	LIST ENTRY NUMBER:	1074871	Contact: Imogen Newcombe 07387 524030

© Historic England

SITE NAME:	Moated site at Ingarsby, Hungarton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010839
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Rachel Jordan 0121 625 6854

HINCKLEY AND BOSWORTH

	SITE NAME:	Stables and kennels to Bradgate House, Bradgate Hill, Groby	Complex of brick stables and kennels built 1856 to house the 7th Earl of Stamford's 47 horses. Largely ruinous by
4	DESIGNATION:	Listed Building grade II*	1988 and now derelict and in very bad condition notwithstanding consolidation work undertaken in the early
Ala Card	CONDITION:	Very bad	2000s. The complex has not been maintained for many years and is actively deteriorating. There are multiple
A LO AL	OCCUPANCY:	Vacant/not in use	structural concerns and periodic collapses of masonry.
	PRIORITY CATEGORY:	A (A)	There is uncontrolled and significant ivy growth and self- seeded trees. The local authority has served an Urgent
a series and a series of	OWNER TYPE:	Commercial company	Works Notice. Historic England has awarded grant aid and is providing technical advice.
England	LIST ENTRY NUMBER:	1361383	Contact: Amanda White 0121 625 6890

© Historic E



© Historic England

SITE NAME:	Church of the Holy Trinity, Orton Lane, Twycross	Rural church of C14 origin but considerably restored / rebuilt c. 1841. The church has suffered from periodic
DESIGNATION:	Listed Place of Worship grade II*	plaster ceiling failure on account of the poor spacing of plaster laths historically and subsequent periodic water
CONDITION:	Poor	ingress. Roofs were partially re-covered, and some plaster panels were renewed c 2011 with grant aid from Historic
PRIORITY CATEGORY:	A (A)	England and the National Lottery Heritage Fund. A Cultural
OWNER TYPE:	Religious organisation	Recovery Fund: Grants for Programmes of Major Works award was made in 2021 for a broader scheme of roof
LIST ENTRY NUMBER:	1294757	repairs and ceiling plaster renewal. Work should complete in 2022.
		111 2022.

Contact: Amanda White 0121 625 6890

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG

- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / HINCKLEY AND BOSWORTH / MELTON



Parish church, early CI4 with later alterations and additions. The walls are of ashlar construction. Recessed spire rebuilt 1797 and partly taken down in 1950. The chancel roof was recently renewed. The church was subject to heritage crime in 2019. Works to address these issues are now complete. Internal plaster work in the south aisle, stonework repairs to window, glazing repairs and the internal stonework of the spire require further investigation. The Parochial Church Council remain keen to effect repairs.

Contact: Hanna Good 07825 318060

© IoE. Mr Peter J Ellis

SITE NAME:	Barwell B (Arthur Street), Barwell		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Grundy (LPA) 01455 255671
SITE NAME:	Hinckley Hollycroft, Hinckley		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Paul Grundy (LPA) 01455 255671
SITE NAME:	Hinckley Town Centre		
DESIGNATION:	Conservation Area, 24 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Paul Grundy (LPA) 01455 255671

MELTON

© Historic England

Justin	SITE NAME:	Church of St Michael, Main Street, Edmondthorpe,	Former church, mainly CI4. The interior is notable for the fine series of CI7 and CI8 memorials. Now under the
111		Wymondham	guardianship of the Churches Conservation Trust. The building was the subject of heritage crime in 2016. Storm
1 To	DESIGNATION:	Listed Building grade I, CA	damage in early 2020 left the interior vulnerable to water
MIN-	CONDITION:	Fair	ingress, however recent works to the rainwater goods has resolved this. The interior is suffering from low level damp.
	OCCUPANCY:	Part occupied/part in use	The Churches Conservation Trust has undertaken a wide
	PRIORITY CATEGORY:	F (A)	programme of repairs with grant support from Historic England's Covid-19 Emergency Heritage at Risk Response
ACC LANGE	OWNER TYPE:	Charity (heritage)	Fund.
	LIST ENTRY NUMBER:	1075128	Contact: Imogen Newcombe 07387 524030



Church dating from C13 and repairs of C17 and C19. SITE NAME: Church of St Leonard, Church Single cell church with nave and chancel under a pitched Lane, Holwell, Ab Kettleby roof. Walls of coursed squared ironstone and limestone. Listed Place of Worship grade The church was subject to heritage crime in 2019. The DESIGNATION: II*, CA church is keen to effect repairs and permissions are being sought. Recipient of Historic England Covid-19 Emergency CONDITION Poor Heritage at Risk Response Fund award in 2020 for new PRIORITY CATEGORY: roof coverings. Historic England have additionally provided A(A)technical advice regarding re-roofing. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1295131 Contact: Dale Dishon 07889 808148

© Leicester DAC

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / MELTON

	SITE NAME:	Church of All Saints, Church Hill, Knipton, Belvoir	Medieval ironstone church with C13 tower and chancel and C14 nave and north aisle; south aisle built and restored
	DESIGNATION:	Listed Place of Worship grade II*, CA	in C19. The condition of the exterior is fair, but there are areas of weathering. Some localised repointing is required. The chancel, north aisle and north porch roof coverings
	CONDITION:	Poor	require renewal. There is water ingress to the interior o the church. Rainwater goods and disposal require maintenance and improvement. The church was subject
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	heritage crime in 2020. Some repairs completed with grant support from Historic England's Covid 19 Emergency
	LIST ENTRY NUMBER:	1075083	Heritage at Risk Response Fund in 2021
r DAC			Contact: Hanna Good 07825 318060

© Leicester |



	SITE NAME:	Church of St John the Baptist, Church Lane, Muston, Bottesford	Church, C13 nave and aisles, C14 tower and chancel. Restored 1875-6 by C Kirk. A Listed Places of Worship Roof Repair Fund grant was accepted in May 2015 and the
	DESIGNATION:	Listed Place of Worship grade II*	nave, chancel, south aisle and south porch roofs have been repaired. Rainwater goods have also been renewed,
	CONDITION:	Very bad	however there is no adequate drainage and there are issues of damp. Works to the south porch roof were
	PRIORITY CATEGORY:	C (C)	completed in Spring 2020. Repointing is still required to the
			ironstone tower and there is poor cementitious pointing to walls elsewhere.
ALC: N	LIST ENTRY NUMBER:	1360899	Contact: Hanna Good 07825 318060

© Historic England

© Historic England

\$3654

	SITE NAME:	Church of St James, Church Lane, Little Dalby, Burton and Dalby	Parish church of coursed and squared ironstone rubble with limestone ashlar dressings. The tower was rebuilt, transepts added and the remainder remodelled by R.
	DESIGNATION:	Listed Place of Worship grade II*	Brandon, 1851. A National Lottery Heritage Fund and Historic England Repair Grant for Places of Worship was
	CONDITION:	Poor	awarded in 2009. The church was subject to heritage crime in 2019, with works to address these issues now complete.
	PRIORITY CATEGORY:	C (A)	Further repairs are required.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1176630	Contact: Hanna Good 07825 318060

SITE NAME: Church of St Mary the Virgin, Main Street, Wyfordby, Freeby A small parish church of C13 origin with C14 additions. Restored in 1869 and again in 1965. The church has suffered repeated occurrences of heritage crime. Recent DESIGNATION: Listed Place of Worship grade II repair works have been completed, however remaining temporary protective sheeting is in poor condition and is CONDITION: Very bad no longer waterproof. The Diocesan Historic Churches Support Officer is providing advice and fundraising is still PRIORITY CATEGORY: A (A) underway. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1061258 Contact: Imogen Newcombe 07387 524030

© Historic England



	SITE NAME:	Church of St Thomas of Canterbury, Church Lane, Frisby on the Wreake	Parish church of C12 and later additions. North aisle rebuilt c.1820 and chancel rebuilt by H1 Stevens in 1848. Coursed and squared ironstone rubble with ashlar dressings. Some
12	DESIGNATION:	Listed Place of Worship grade I, CA	roof coverings are at the end of their serviceable lives and require renewal. Drainage appears to be contributing to damp on the north side. The tower and nave require
CONDITION:	CONDITION:	Poor	repointing and repair. Recipient of an Historic England Covid 19 Emergency Heritage at Risk Response Fund grant
	PRIORITY CATEGORY:	F (F)	in 2020 to re-roof the baptistry. These works were
	OWNER TYPE:	Religious organisation	completed in 2021.
	LIST ENTRY NUMBER:	1360878	Contact: Hanna Good 07825 318060

© Historic England

PR	NORITY C	ATEGORIES
А	Immediate	risk of further rat

- А Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- Conservation Area Listed Building Local Planning Authority National Park LB LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / MELTON

	SITE NAME:	Church of St Luke, Church Lane, Gaddesby	Parish church of C12 origin with contributions of C13, C14 and late C18 porch. North aisle roof coverings leak and
	DESIGNATION:	Listed Place of Worship grade I, CA	there is localised low level damp including adjacent to the south porch and in the vicinity of the fine monument at the east end of the north aisle. It is hoped to commence north
	CONDITION:	Fair	aisle roof repairs in 2022. The rainwater disposal system requires localised repairs and some self-seed vegetation
	PRIORITY CATEGORY:	C (New entry)	should be tackled sooner rather than later.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1307542	Contact: Amanda White 0121 625 6890
England			

© Historic England



SITE NAME:	Church of St Peter, Church Lane, Saxelbye, Grimston	Parish church of C13 origin, contributions of C14 and C15 and restored 1856-7. The church is constructed of
DESIGNATION:	Listed Place of Worship grade II*, CA	ironstone with limestone dressings. The ironstone tower is topped with a limestone spire. Tower masonry is quite badly eroded and, whilst this is common for ironstone,
CONDITION:	Poor	some erosion is considerable and some sizeable masonry fragments had fallen to the ground. Pointing is in poor /
PRIORITY CATEGORY:	A (C)	very poor condition generally. There are very many open
OWNER TYPE:	Religious organisation	joints and several holes have formed.
LIST ENTRY NUMBER:	1075032	Contact: Imogen Newcombe 07387 524030

© Historic England

SIT	SITE NAME:	Church of St Peter, Main Street, Kirby Bellars	A large C13 church, former priory, with C14, C15 and C16 work. Restored late C18, in 1820, and late C19. Ironstone
1	Designation: Listed Place of Worship grade I 2013 following a National Lottery		walling and a limestone spire. Spire repairs undertaken in 2013 following a National Lottery Heritage Fund Grants for
	CONDITION:	Very bad	Places of Worship grant. An unsuccessful application to the National Lottery Heritage Fund in 2018. The church was
	PRIORITY CATEGORY:	A (A)	the subject of heritage crime in 2017. Repairs to the tower
OWNER TYPE: Religious organisation are fruiting	masonry, roofs and drainage are urgently required; there are fruiting bodies. Historic England's Covid 19 Emergency		
a the	LIST ENTRY NUMBER:	1261717	Heritage at Risk Response Fund awarded funds to develop repair proposals.

© Historic England

© Historic England

Contact: Hanna Good 07825 318060 SITE NAME: Church of St Peter, Main Street, Redmile Listed Place of Worship grade DESIGNATION: II*, CA CONDITION: Fair PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

Parish church, CI3 fabric with CI4 tower and chancel. CI5 and C19 re-modelling. The south aisle roof was re-covered in felt during the 1980s but, by 2011, it had failed. A National Lottery Heritage Fund grant was awarded in December 2011 for urgent works. These were completed in summer 2013 but there are significant full height movement cracks at the west end of the north nave and south clerestory wall. Recipient of an Historic England Covid-19 Emergency Heritage at Risk Response Fund award to investigate movement. Investigations have taken place and repair needs have been identified.

Contact: Amanda White 0121 625 6890



SITE NAME:	Church of St Helen, Barkerstone Lane, Plungar, Redmile	Parish church dating from C15 with an earlier C14 tower. The south aisle was rebuilt, and the chapel added in 1855- 56. Constructed from ironstone with limestone dressings.
DESIGNATION:	Listed Place of Worship grade II*	The church has been the subject of heritage crime in 2019. The tower roof and subsequent roof structure are in poor condition and damp, with significant repairs required. The parish is keen to effect repairs and are investigating possible
CONDITION:		
PRIORITY CATEGORY:	A (A)	funding avenues.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1075010	Contact: Hanna Good 07825 318060

© Leicester DAC

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

LIST ENTRY NUMBER:

1075013

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA WHS

Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / MELTON / NORTH WEST LEICESTERSHIRE

	SITE NAME:	Church of St Egelwin the Martyr, Church Street, Scalford	Large rural parish church of C13 origin with C15 contributions. Tower rebuilt 1639 and chancel rebuilt
	DESIGNATION:	Listed Place of Worship grade II*, CA	1845. Restored 1858 by Millican and Smith. The church is built of local ironstone with limestone dressings. Some tower masonry blocks have eroded significantly,
	CONDITION:	Poor	particularly at belfry and parapet levels where there are noticeable holes and gaps. Falling masonry fragments are a
	PRIORITY CATEGORY:	E (E)	significant concern. Below ground drainage was also
	OWNER TYPE:	Religious organisation	problematic. Recipient of Historic England's Covid-19 Emergency Heritage at Risk Response Fund award in 2020
	LIST ENTRY NUMBER:	1075018	to address drainage issues.
			Contact: Imogen Newcombe 07387 524030

© Historic England



SITE NAME:	Church of St Mary, Chadwell, Scalford	Parish church of C12 origin with C13 additions. Repaired C17 and restored 1865-6 by R W Johnson. There has been
DESIGNATION:	Listed Place of Worship grade II*	a long history of structural movement. A number of structural ties are evident to the tower and there is
CONDITION:	Poor	extensive cracking to the chancel, of which widened during 2018. It is thought that a lack of below ground drainage,
PRIORITY CATEGORY:	C (C)	clay subsoil and the long dry summer of 2018 are
OWNER TYPE:	Religious organisation	contributing factors. The Parochial Church Council are in receipt of professional structural engineering advice,
LIST ENTRY NUMBER:	1075015	alongside support from the Diocesan Historic Churches Support Officer.

© Historic England

	SITE NAME:	Church of St Peter, Chapel Lane, Wymondham	Church of C13 origin with C14 and 15 contributions. Much restored in C19. Ironstone church with ashlar	
	DESIGNATION:	Listed Place of Worship grade I, CA	dressings comprising west tower with spire, nave with clerestory, north and south aisles, north and south transepts, chancel, vestry and south porch. Much of the	
	CONDITION:	Fair	ironstone is badly weathered. Tower stonework is in particularly poor condition with many open joints, locali	
	PRIORITY CATEGORY:	C (New entry)	holes and notable cracking. North aisle roof coverings are	
	OWNER TYPE:	Religious organisation	in poor condition and require replacement. The church architect has prepared repair proposals, but resources are	
	LIST ENTRY NUMBER:	1177844	limited, and funding opportunities are scarce.	
			Contact: Amanda White 0121 625 6890	

© Historic England

SITE NAME:	Melton Mowbray		
DESIGNATION:	Conservation Area, 95 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Tony Ebbs 01664 502313

NORTH WEST LEICESTERSHIRE

ALL CARLES	SITE NAME:	Snibston Colliery, Ashby Road	Buildings, structures, machinery and buried remains of
1 10 A 19 A	DESIGNATION:	Scheduled Monument	former Snibston Colliery and adjoining railway, built 1832-4 by the engineers George and Robert Stephenson. Leicestershire County Council completed a major scheme of repairs under SMC. Schemes for housing development are underway, and a revised offer to visitors. This includes
MA CA	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (E)	cafe facilities and bookable paid tours, alongside a free exhibition. Much progress has been made recently by the
	OWNER TYPE:	Local authority	County Council and local partners, but conservation challenges remain. Historic England has provided advice
	LIST ENTRY NUMBER:	1018472	and has amended designations

© Historic England

Contact: Nick Carter 0121 625 6860

Contact: Imogen Newcombe 07387 524030

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH WEST LEICESTERSHIRE

ITE NAME:	The Royal Hotel, Station Road, Ashby-de-la-Zouch	Hotel built c. 1826 and constructed of red brick and stone. Large porch with Greek Doric columns where the fluting	
DESIGNATION:	Listed Building grade II*, CA	has been removed. Since the hotel closed in 2018 the building has been vacant and has suffered from heritage	
CONDITION:	Poor	crime. The roofs and rainwater disposal system require renewal. Delamination of stone 'slips' to elevations.	
DCCUPANCY:	Vacant/not in use	Internally there is defective plaster work and failing ceilings	
RIORITY CATEGORY:	C (C)	as a result of water ingress and stolen pipework. The building owners commissioned a condition report in 2020.	
OWNER TYPE:	Commercial company	There is a live planning application on the site for a large amount of new development.	
IST ENTRY NUMBER:	1073594	Contact: Hector Martin	
0 0 0 0	ESIGNATION: CONDITION: DOCCUPANCY: RIORITY CATEGORY: DWNER TYPE:	Ashby-de-la-ZouchDESIGNATION:Listed Building grade II*, CADONDITION:PoorDOCCUPANCY:Vacant/not in useRIORITY CATEGORY:C (C)WINER TYPE:Commercial company	

T

© North West Leice Council

	SITE NAME:	Church of St Michael and All Angels, Church Street, Appleby Magna	Possibly C14 origin, west of former moated manor house. External drainage renewed and extended in 2016 with funds from the Listed Places of Worship Roof Repair Fund.
	DESIGNATION:	Listed Place of Worship grade II*, CA	Low level plaster removed. Pews, platforms and boxes require sensitive repair once masonry has dried. Window tracery and glazing in poor condition. Specialist reports
	CONDITION:	Poor	were obtained for an application to the National Lottery Heritage Fund but the scheme was suspended in 2020 due
	PRIORITY CATEGORY:	A (A)	to Covid-19. Recipient of Historic England's Covid-19
	OWNER TYPE:	Religious organisation	Emergency Heritage at Risk Response Fund award in 2020 for repairs to chancel windows, now completed.
	LIST ENTRY NUMBER:	1177814	Contact: Imogen Newcombe 07387 524030

Church of St Margaret of Antioch, Main Street,

CA

B (A)

Very bad

Blackfordby, Ashby-de-la-Zouch

Listed Place of Worship grade II,



© Historic England

© Historic England



© Historic England



	OWNER TYPE:	Religious organisation	Response Fund. Repairs to the west end gable were due to start in spring 2022.	
	LIST ENTRY NUMBER:	1073641	Contact: Hanna Good 07825 318060	
	SITE NAME:	Church of St Edward King and Martyr, Clapgun Street, Castle Donington	An early C13 parish church, with aisles widened C14. Restored in 1876-77 by William Smith of the Adelphi, London. The church was subject to heritage crime in 2019.	
	DESIGNATION:	Listed Place of Worship grade II*, CA	Repairs have been undertaken to address this. The roof the base of the tower spire is cracked and allowing water in. Rainwater goods are defective and drainage requires attention. The interior is suffering from low level damp.	
	CONDITION:	Poor		
	PRIORITY CATEGORY:	C (C)		
aller.	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1361370	Contact: Hanna Good 07825 318060	
1	SITE NAME:	Church of St Mary, Ashby Road, Coleorton, Coleorton	Parish church with C14 and C15 work restored c1850 sitting adjacent to Coleorton Hall. Joints in the guttering	
NF C	DESIGNATION:	Listed Place of Worship grade II*, CA	and downpipes have failed in places leading to saturation of surrounding stonework and the basal courses of the walls. There is also considerable moss growth at plinth level on	
	CONDITION:	Poor	the north side of the tower and the drainage channels are not working efficiently. The interior of the church is damp	
	PRIORITY CATEGORY:	C (C)	and the plaster work to the walls and ceiling has failed in	
	OWNER TYPE:	Religious organisation	places. The Parochial Church Council are considering options.	
	LIST ENTRY NUMBER:	1073571	Contact: Imogen Newcombe 07387 524030	

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

A prominently sited church built 1856-8 by H I Stevens. It replaces an earlier church and includes a C18 monument

and a fragment of medieval stained glass in the chancel. The nave has a 5-bay hammerbeam roof. The church is suffering from blocked gutters, slipped slates, plant growth to the

spire and undersized rainwater goods. Temporary covering of the west end gable after partial collapse of the external

Response Fund. Repairs to the west end gable were due to

skin in 2020 was undertaken with grant support from Historic England's Covid 19 Emergency Heritage at Risk

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

ŬA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / NORTH WEST LEICESTERSHIRE / OADBY AND WIGSTON / BOSTON

	SITE NAME:	Church of St Michael, Ravenstone with Snibstone	Parish church of early C14, restored C19. Stonework is in very poor condition, particularly to the octagonal broached
	DESIGNATION:	Listed Place of Worship grade II*, CA	spire and tower. The 2018 Quinquennial Inspection identified several movement cracks requiring urgent investigation. Further urgent repairs are needed to the
	CONDITION:	Poor	tower, the internal and external faces of the spire and masonry elsewhere. A defective rainwater disposal system
	PRIORITY CATEGORY:	C (C)	is causing significant damp issues. Major repairs have since
	OWNER TYPE:	Religious organisation	been undertaken with support from Historic England's Covid-19 Emergency Heritage at Risk Response Fund.
	LIST ENTRY NUMBER:	1074380	Contact: Imogen Newcombe 07387 524030

© Ms Elaine Allen. Source Historic England Archive

OADBY AND WIGSTON

	•		
	SITE NAME:	Church of St Wistan, Church Nook, Wigston	Early C14 tower remains of a church demolished C17. The rest was rebuilt in 1853 by Walker and Goodacre and
	DESIGNATION:	Listed Place of Worship grade II, CA	restored 1877 by R J & J Goodacre. Tower of limestone, otherwise uncoursed granite rubble and Welsh slate roof. The rainwater disposal system is undersized and ineffective.
	CONDITION:	Poor	Failing joints in gutters have caused long-term water ingress
	PRIORITY CATEGORY:	A (A)	into earthen mortar core of walls, resulting in separation of external fabric. The failure of the external face is evident.
	OWNER TYPE:	Religious organisation	The Parochial Church Council were previously keen to effect repairs and seek funding, however the process of
	LIST ENTRY NUMBER:	1361576	closure is underway.
Architect)			Contact: Imogen Newcombe 07387 524030

© Mark Stewart (A

LINCOLNSHIRE

BOSTON			
	SITE NAME:	Shodfriars Hall, 2 and 4, South Street	Former Guild Hall, c1400. C17 additions. Restored and extended by John Oldrid Scott and George Gilbert Scott
	DESIGNATION:	Listed Building grade II*, CA	Jnr 1873-75 for Boston Conservative Club, adding theatrical hall to the rear. Following Historic England
	CONDITION:	Poor	funded investigations, urgently necessary works at high level have been attended to. Extensive further repairs are
	OCCUPANCY:	Part occupied/part in use	required as result of long-term water ingress and vacanc
	PRIORITY CATEGORY:	A (A)	Decay to timber frame and degradation of internal surface finishes remain. Part-occupied. New owner in discussion
	OWNER TYPE:	Commercial company	with Local Authority to secure viable future use/users.
© Historic England	LIST ENTRY NUMBER:	1388998	Contact: Hannah Reynolds 07557 827971

Rochford Tower, Rochford

Scheduled Monument and Listed

Tower Lane, Fishtoft

1016693 and 1062088

Religious organisation

Church of St Peter and St Paul, Church Lane, Algarkirk

Listed Place of Worship grade I

Building grade I

Very bad

N/A


A (A)

Private

Poor

C (C)

1164857



SITE NAME:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY

LIST ENTRY NUMBER:

© Historic England



© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Brick tower, c1460 with C17 and C19 alterations. There

collapsing inwards. Brickwork on the parapet is unstable

together with timber and floor remnants in the unroofed interior. Minimal repairs were carried out in 1988, including

repointing the south east turret. Nothing has been done

since. The owner has not been able to take up an offer of

Historic England grant funding for a condition survey and

Parish church dating from the C12. Extensive roof repairs were completed in 2014 under a joint Historic England and

National Lottery Heritage Fund Repair grant for Places of

Worship. Improvement to the below-ground drainage system is required; there has been a recent outbreak of dry

rot at floor level. The church is experiencing structural

Church Council is considering future options.

Contact: Ben Robinson 07823 327796

movement, cracking to walling and damage to windows. The church has been a victim of heritage crime. The

National Lottery Heritage Fund Stage Two grant awarded in 2018 was withdrawn in early 2020. The Parochial

elevations. The infill in the original west window is

Contact: Hanna Good 07825 318060

options appraisal.

are vertical cracks in the brickwork on the north and west

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument
- SM ΪA
- Unitary Authority World Heritage Site WHS
- 26

HERITAGE AT RISK 2022 / MIDLANDS / BOSTON

	SITE NAME:	Church of All Saints, Old Main Road, Fosdyke	Church of 1871 in the Geometric style constructed from red brick with ashlar dressings and slate roof with covered
	DESIGNATION:	Listed Place of Worship grade II	spire. The building is in poor condition. Rainwater goods are defective and numerous downpipes and gutters leak.
	CONDITION:	Poor	There is evidence of movement between the tower and aisle; defects in the valley gutter between the two have
	PRIORITY CATEGORY:	C (C)	allowed water to penetrate inside. There is a large crack
	OWNER TYPE:	Religious organisation	the east window and signs of movement elsewhere. Some minor repairs have been completed and discussions have
	LIST ENTRY NUMBER:	1360494	taken place regarding a future repair project.
			Contact: Ben Robinson 07823 327796

© Historic England

SITE NAME:	Church of St James, Church End Road, Freiston	Large parish church of C12 and later date, with pre- Conquest origins, formerly the church of Freiston Priory.
DESIGNATION:	Listed Place of Worship grade I	The church forms one element of the wider Priory and post-Dissolution complex. There is significant direct risk of
CONDITION:	Poor	damage to fabric and loss of associated archaeological remains which comprise an important part of the setting of
PRIORITY CATEGORY:	A (A)	the church. This is due to works immediately adjacent to
OWNER TYPE:	Religious organisation	the church, but latterly beyond the control of the church authorities.
LIST ENTRY NUMBER:	1308415	Contact: Ben Robinson 07823 327796
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Road, Freiston DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation

© Historic England

	SITE NAME:	Church of St Mary and St Nicholas, Church Lane, Wrangle	Parish church of limestone ashlar with fabric from C13- C16. Restored 1875-8 by Ewan Christian. The church was the subject of heritage crime in 2019 and a temporary
	DESIGNATION:	Listed Place of Worship grade I, CA	solution has been put in place. The Parochial Church Council are keen to effect repairs and are investigating possible funding sources.
	CONDITION:	Poor	-
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© Mr John Scarbro. Source: Historic England Archive	LIST ENTRY NUMBER:	1308367	Contact: Imogen Newcombe 07387 524030

SITE NAME:	Multon Hall moated site, Frampton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018584
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Bicker		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY: High		CONTACT:	Matthew Bentley 01529 461499
SITE NAME:	Boston, Boston Town Centre		
DESIGNATION: Conservation Area, 225 LBs		NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Matthew Bentley 01529 461499
SITE NAME:	Kirton		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Matthew Bentley 01529 461499

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Swineshead		
DESIGNATION:	Conservation Area, 7 LBs, SM	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Chris Holliday (LPA) 01205 314337

EAST LINDSEY

	SITE NAME:	Windmill, east Street, Alford	Windmill. Tower mill of 6 floors. 1837, restored 1979, built
	DESIGNATION:	Listed Building grade I, CA	by Alford millwright, Sam Oxley. Tarred brick. The wooden ogee cap and sails were removed for safety c.2020
	CONDITION:	Very bad	following identification of rot to structural elements. Sails now entirely lost, cap and fantail require substantial repair.
	OCCUPANCY:	Vacant/not in use	A temporary cap is in place over the top floor of the mill to
	PRIORITY CATEGORY:	B (New entry)	minimise further deterioration. Lincolnshire County Council is keen to effect repairs and working towards full
	OWNER TYPE:	Local authority	cap and sail reinstatement. Options are also being explored to bring back into use following repair.
	LIST ENTRY NUMBER:	46936	Contact: Imogen Newcombe 07387 524030

© East Lindsey District Council

Windmill of five storeys. 1813 by Oxleys of Alford, restored SITE NAME: Dobson's Windmill, High Street, 1947. Tarred brick. Wooden ogee shaped cap with Burgh Le Marsh moulded brick eaves, ball finials, fantail and 5 'left handed' DESIGNATION: Listed Building grade I patent sails. The mill suffered storm damage in early 2020 which destroyed the sails, cap and fantail. A temporary cap CONDITION: Very bad is in place over the top floor of the mill to minimise further OCCUPANCY: deterioration and initial repairs have been undertaken. Part occupied/part in use Lincolnshire County Council is keen to effect repairs and PRIORITY CATEGORY: B (B) are exploring options for full cap and sail reinstatement. OWNER TYPE: Local authority LIST ENTRY NUMBER: 1222732 Contact: Imogen Newcombe 07387 524030

© Lincolnshire County Council




© Historic England



© Historic England

	SITE NAME:	Church Close (The Old Parsonage), High Street, Coningsby	Former rectory, now house. C14 and C15 with later additions and alterations. Rare domestic example of a C1 cruck framed hall, with high status carvings. Only the C19
	DESIGNATION:	Listed Building grade I	wing is occupied. Water ingress from roof, decaying timberwork, and cracks in brickwork. A condition survey
	CONDITION:	Poor	and development appraisal was carried out in 2014, funded by Historic England. Proposals have not progressed.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1215282	Contact: Hannah Reynolds 07557 827971



PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

28

	SITE NAME:	Friskney Methodist Chapel, Chapel Lane, Friskney	Typical Fenland chapel of 1839, with later alterations. No longer used for worship.
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
© East Lindsey District Council	LIST ENTRY NUMBER:	1267369	Contact: Ben Robinson 07823 327796



© Historic England

	SITE NAME:	Remains of Roman wall, Horncastle	Roman curtain wall, late C3 to mid C4, which survives as both standing masonry and as buried remains in various
	DESIGNATION:	Scheduled Monument and Listed Buildings - 5 grade I, CA	ownerships. One visible section has been incorporated into Horncastle Library. The condition of each section of the monument varies, but uncontrolled vegetation growth and
	CONDITION:	Fair	weathering threatens several of the exposed sections. Historic England grant-aided reapirs of the southwest
	OCCUPANCY:	N/A	corner of the wall circuit are due to complete in 2022.
ALC: NO	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	1005034 and 1063769; 1251668; 1262504; 1262720; 1262704	Contact: Amanda White 0121 625 6890

	SITE NAME:	The Sycamores, Westgate, Louth	House, early C19, in Elizabethan style. Some repairs previously carried out, Further repairs are necessary and
	DESIGNATION:	Listed Building grade II*, CA	overall condition is deteriorating.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
A State of the sta	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1063180	Contact: Hannah Reynolds 07557 827971

1 N	SITE NAME:	Church of All Saints, Church Lane, Maltby Le Marsh	Former parish church, late C13 to early C14, tower rebuilt in 1700, chancel altered 1788. The building has been sold
	DESIGNATION:	Listed Building grade II*	and Planning Permission has been granted for change of use to an artist's studio. Some repairs have been carried out.
	CONDITION:	Fair	
1-20	OCCUPANCY:	Vacant/not in use	
1	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© East Lindsey District Council	LIST ENTRY NUMBER:	1146990	Contact: Ben Robinson 07823 327796



	SITE NAME:	Revesby Abbey and stable yard, Main Road, Revesby	Country house and stable block, 1845. Approached from the south by a 1km drive, set in a medieval deer park,
	DESIGNATION:	Listed Building grade I, RPG grade II, CA	landscaped in late C18. House, gardens and stable privately owned. Current owner has made progress with repairs to the stable block, but the main house is still at serious risk.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1288157	Contact: David Walsh 0121 625 6888

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT	RISK 2022	EAST LINDSEY



SITE NAME: Parish church, now redundant. Early C13, C14, C15, 1854, Church of St Botolph, Church 1871, C20. Subject to repeated heritage crime the building Lane, Skidbrooke with Saltfleet is now in ruinous state. Recent sudden movement to the Haven north-east corner of the church has necessitated closure to DESIGNATION: Listed Building grade I the public while emergency stabilisation and holding repairs were undertaken. The owners are keen to undertake CONDITION: Very bad further investigations to establish the broader repair needs OCCUPANCY: and options to bring the building back into use, they are Vacant/not in use seeking funding and local engagement to do so. PRIORITY CATEGORY: A (New entry) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1165864 Contact: Hannah Reynolds 07557 827971

© Historic England



ANA A	SITE NAME:	Church of St Swithin, Church Lane, Baumber	Parish church, coursed limestone rubble construction with fabric from CI1, CI2 and CI3. Completely brick clad and
	DESIGNATION:	Listed Place of Worship grade I	refenestrated in 1758. Restored in 1892 by W. Scorer. The church was the subject of heritage crime in 2019. Repairs
	CONDITION:	Poor	are required to the roof. The Parochial Church Council are exploring funding options and are keen to effect repairs.
PRIORITY CATEGOR	PRIORITY CATEGORY:	C (A)	exploring funcing options and are keen to ellect repairs.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1063173	Contact: Imogen Newcombe 07387 524030

© Mr Roger H Mockford. Source: Historic England Archive

© Diocese of Lincoln

	SITE NAME:	Church of St Julian, Church Lane, Benniworth	Parish church with mid-C12 fabric, rebuilt by James Fowler in 1875. There is loose and fallen stonework in the north
	DESIGNATION:	Listed Place of Worship grade II	parapet, with open and washed out mortar joints at high- level on the tower and spire. There is historical structural
	CONDITION:	Poor	movement within the tower, and cracking in the nave and transepts. There are issues of long-term damp and
	PRIORITY CATEGORY:	C (New entry)	rainwater ingress, with dry-rot and decayed structural roof
	OWNER TYPE:	Religious organisation	timbers, with loose and fallen high-level plasterwork. The church suffers from poor ventilation. The Parochial Church
	LIST ENTRY NUMBER:	1063091	Council are keen to undertake repairs and minor roofing works are scheduled.
			Contact: Imogen Newcombe 07387 524030
			8

	SITE NAME:	Church of St Peter and St Paul, Main Street, Bolingbroke, Bolingbroke	Parish church of 1360, possible built for John of Gaunt. Partly destroyed in the Civil War and restored in 1866. Constructed from rubblestone with ashlar dressings and a
	DESIGNATION:	Listed Place of Worship grade II*, CA	slate roof. The building has been poorly maintained but a local interest group has been formed and are actively seeking funding to undertake repairs. A Covid 19 Emergency Heritage at Risk Response Fund Grant has enabled urgent holding repairs to be undertaken, however
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (New entry)	a broader scope of repairs is required to address issues
A dealer of the second s	OWNER TYPE:	Religious organisation	with roofs, rainwater goods, drainage and structural issues with boiler chimney.
© Historic England	LIST ENTRY NUMBER:	1359705	Contact: Imogen Newcombe 07387 524030
			-



	LIST ENTRY NUMBER:	1359705	Contact: Imogen Newcombe 07387 524030
1	SITE NAME:	Church of St Margaret, Main Street, Bucknall	C13 church, restoration by James Fowler of 1884. The south chancel roof is showing signs of nail fatigue and there
1	DESIGNATION:	Listed Place of Worship grade II*	are slipped tiles to the south slope of the nave roof and damaged ridge tiles. Recovering may be required. Historic
1	CONDITION:	Poor	cracking is evident on most elevations and some recent cracks require monitoring. Evidence of damp internally on
	PRIORITY CATEGORY:	C (C)	the north side. Some of the windows are suffering the
1	OWNER TYPE:	Religious organisation	effects of iron- jacking. The Parochial Church Council were successful in a recent funding bid in November 2021 and
	LIST ENTRY NUMBER:	1359927	are continuing to be advised by the Diocesan Historic Churches Support Officer.

© Historic England

Contact: Imogen Newcombe 07387 524030

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- Conservation Area Listed Building Local Planning Authority National Park LB LPA
- NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA WHS Unitary Authority World Heritage Site

SITE NAME:	Church of St Helen, Church Lane, East Keal	Parish church with fabric from C13 and C14. Restored and rebuilt externally with tower of 1853-4 by Stephen Lewin.
DESIGNATION:	Listed Place of Worship grade II*	Repairs to the tower cladding are now complete, however the roofs are coming to the end of their lives and there are
CONDITION:	Poor	numerous tingles and slipped slates. The rainwater goods are also in need of repair. The Parochial Church Council
PRIORITY CATEGORY:	D (D)	were successful in a recent funding bid in November 2021
OWNER TYPE:	Religious organisation	and are continuing to be advised by the Diocesan Historic Churches Support Officer on further fundraising avenues.
LIST ENTRY NUMBER:	1166170	Contact: Imogen Newcombe 07387 524030
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Lane, East KealDESIGNATION:Listed Place of Worship grade II*CONDITION:PoorPRIORITY CATEGORY:D (D)OWNER TYPE:Religious organisation

© Mr John Scarbro. Source: Historic England Archive

SITE NAME:	Church of St Nicholas, Church Lane, East Kirkby	Parish church with C13, C14, C16, extensively restored C19 and 1904-6. The tower is unusually located to the
DESIGNATION:	Listed Place of Worship grade II*	south, and contains the entrance porch. The west wall heavily buttressed. The site has been subject to heritage
CONDITION:	Fair	crime. Rainwater goods need repairing, and the north side of the church needs vegetation management in order to
PRIORITY CATEGORY:	A (A)	allow maintenance access. Greensand stonework walling
OWNER TYPE:	Religious organisation	heavily eroded, and suffers from previous cement pointing internally and externally.
LIST ENTRY NUMBER:	68096	Contact: Ben Robinson 07823 327796
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Lane, East KirkbyDESIGNATION:Listed Place of Worship grade II*CONDITION:FairPRIORITY CATEGORY:A (A)OWNER TYPE:Religious organisation

© Historic England

A CONSTRUCTION OF CONSTRUCTION			
	SITE NAME:	Church of All Saints, Church Lane, Friskney	Parish church. Late C12, late C13, mid C14, mid C15, restored by W. Butterfield in 1879. Limestone rubble and
	DESIGNATION:	Listed Place of Worship grade I	ashlar, some red sandstone, some red brick and some render. Stone coped gables and cross finials. The church
	CONDITION:	Poor	has been subject to heritage crime and is at risk of water ingress. The PCC are keen to effect repairs, fundraising has
	PRIORITY CATEGORY:	D (D)	been impeded by CoVID-19.
	OWNER TYPE:	Religious organisation	
And the second	LIST ENTRY NUMBER:	1223280	Contact: Imogen Newcombe 07387 524030

© Historic England

an a	SITE NAME:	Church of St Helen, Biscathorpe, Gayton Le Wold	Small rural parish church of 1847 by WA Nicholson of Lincoln in a Gothic style. Lined stucco render with ashlar
	DESIGNATION:	Listed Place of Worship grade II*	dressings and a slated roof. There is localised render failure and broken glass. Various slate roof defects are evident,
	CONDITION:	Very bad	and there is subsequent water ingress through the tower and nave roofs. Isolated iron cramp damage. The church is
	PRIORITY CATEGORY:	A (A)	presently disused, and the process of closure is underway.
- fulletine	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1168152	Contact: Imogen Newcombe 07387 524030

© Historic England



SITE NAME:	Church of St Clement, Church Lane, Grainthorpe	A s de
DESIGNATION:	Listed Place of Worship grade I	res
CONDITION:	Poor	Th Fo
PRIORITY CATEGORY:	C (C)	gra
OWNER TYPE:	Religious organisation	on rep
LIST ENTRY NUMBER:	1308429	rep W

spacious Marshland church, dating from the C12, with corated and perpendicular phases. There is evidence of a storation circa 1740 when the battlemented parapets d the ogee north door might have been constructed. ne chancel was restored and shortened in 1876 by wler. The north aisle roof is of considerable age, with affiti, including hands and boots and three sailing ships ne dated 1740. Roof coverings and stonework are in poor pair. National Lottery Heritage Fund Grants for Places of /orship grant was offered in 2015. Works are now complete. A further phase of works is needed.

© Historic England

Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of All Saints, Church Lane, Greetham with Somersby	Parish church with C12 origins and heavily restored in 1903 with the chancel, vestry and porch rebuilt. Constructed
	DESIGNATION:	Listed Place of Worship grade II	from dressed stone with some red brick and render and half-timbering. The church was subject to heritage crime in
	CONDITION:	Poor	2019. A Faculty application for these repair works was approved in 2019, and the Parochial Church Council are
	PRIORITY CATEGORY:	B (B)	keen to undertake these repairs. Support for investigating
	OWNER TYPE:	Religious organisation	potential funding avenues is being provided by the Diocesan Historic Churches Support Officer.
	LIST ENTRY NUMBER:	1147285	Contact: Imogen Newcombe 07387 524030

© Historic England

	SITE NAME:	Church of St Edith, Tinkle Street, Grimoldby	A substantial church of Spilsby greensand with much eroded stone. Its C16 roof structure still survives, but this
The second second	DESIGNATION:	Listed Place of Worship grade I	ancient timberwork has suffered from extensive dampness due to defective roof coverings and very bad high level
ATATA MIA	CONDITION:	Poor	rainwater disposal arrangements. Recently re-roofed with National Lottery Heritage Fund Grant for Places of
	PRIORITY CATEGORY:	C (C)	Worship funding. Structural movement to the tower and
	OWNER TYPE:	Religious organisation	south aisle and the condition of stonework to the tower gives cause for concern. The church has been a victim of
	LIST ENTRY NUMBER:	1359986	heritage crime.
			Contact: Ben Robinson 07823 327796

Church of St Andrew, Holegate,

Listed Place of Worship grade II

Religious organisation

Very bad

1062998

Lane, Huttoft

A (New entry)

1360009

Religious organisation

Poor

A (A)

Halton Holegate

© Historic England

A INCOMPANY	An and a second
	and the second se

SITE NAME:

DESIGNATION:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

CONDITION:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE-

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England

© GMS Architecture

© Historic England

	SITE NAME:	Church of St John the Baptist, Gravel Pit Lane, High Toynton	Parish church of green sandstone rubble blocks and limestone ashlar dressings. Rebuilt in 1872 by Ewan
			Contact: Imogen Newcombe 07387 524030
	LIST ENTRY NUMBER:	1359727	will assist with repairs to the organ loft, vestry and chancel roofs.
	OWNER TYPE:	Religious organisation	since been completed. An Historic England's Covid-19 Emergency Heritage at Risk Response Fund award in 2021
	PRIORITY CATEGORY:	F (F)	Grant was awarded in 2020 for roof repairs. These have
	CONDITION:	Poor	scheme. Further phases are needed to repair the south aisle and porch roofs. A National Lottery Heritage Fund
	DESIGNATION:	Listed Place of Worship grade II*	Nave roof repairs completed 2015 through the National Lottery Heritage Fund Grant for Places of Worship
10 10		i laicon i loicgace	

locks and limestone ashlar dressings. Rebuilt in 1872 by Ewan Christian, re-using some mid C12 fragments. Nave with south-west porch tower, chancel with vestry. The nave roof has a number of slipped slates and requires repair and renewal, as do the rainwater goods. The tower has suffered with structural movement historically and there have been attempts to underpin the structure, however the tower collapsed in early 2020. A National Lottery Heritage Fund Grant was awarded in early 2022 for investigatory and repair works to the tower.

A large parish church. Early work from CI4 with early CI5

west tower. Chancel ceiling has a painted scheme of 1894.

Contact: Imogen Newcombe 07387 524030

Parish church from C13, with restorations in 1869, 1882 Church of St Margaret, Church and 1910. The tower is in poor condition and inaccessible, due to pigeon detritus and nesting. The chancel roof has Listed Place of Worship grade I missing and slipped slates, with failing tile battens. This has deteriorated to create holes in the roof, permitting water ingress into the building and onto the laths. The rainwater goods are defective and blocked with vegetation, with further damp and biological growth on most elevations. There is a hairline crack and void in the south porch. The parish are working with the Diocese to consider future repair schemes.

Contact: Imogen Newcombe 07387 524030

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- ΪA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Church of St Lawrence, The Green, Revesby, Revesby	Parish church dating to 1891 by C. Hodgson Fowler in the Decorated style. Ashlar with plain tiled roofs. Western
	DESIGNATION:	Listed Place of Worship grade II, CA	tower, nave, chancel, south porch, vestry. The church has suffered batten failure to north side of the nave roof. Rainwater goods appear undersized, are nearing the end of
	CONDITION:	Poor	their lives and will require renewal. Masonry is saturated and vegetation is colonising as a result of defective gutters.
	PRIORITY CATEGORY:	A (New entry)	Some slipped tiles are also visible on the south slope of
	OWNER TYPE:	Religious organisation	nave roof. The church is otherwise in fair condition and appears to be well cared for. The PCC are keen to effect
	LIST ENTRY NUMBER:	1215306	repairs.
nd			Contact: Hanna Good 07825 318060

© Historic England



1	SITE NAME:	Church of St Benedict, Church Lane, Scrivelsby	Situated in an open field. The church dates from C13 and C15, with chancel and nave and an arcaded Early English
	DESIGNATION:	Listed Place of Worship grade II*	north aisle. To the north west end is the tower and spire built from Ancaster limestone in the 1860s. The building
	CONDITION:	Poor	exterior was remodelled in the 1860s and 1870s. Nave and north aisle roofs need re-slating. The church is damp.
-	PRIORITY CATEGORY:	D (F)	Below ground drainage needs repair. A National Lottery
	OWNER TYPE:	Religious organisation	Heritage Fund grant was awarded in December 2019 to address the roof and rainwater goods. These works were
T	LIST ENTRY NUMBER:	1252195	completed in 2021. Monitoring of structural issues to the chancel is ongoing.

© Historic England



			Contact: Ben Robinson 07823 327796
	SITE NAME:	Church of St Oswald, Church Lane, Strubby with Woodthorpe	This small parish church was largely rebuilt in 1857 by Maughan and Fowler, and the chancel by Ewan Christian in 1874. The construction is banded brickwork and
	DESIGNATION:	Listed Place of Worship grade II*	greenstone, there is an open timber bellcote and facetted copper spirelet. The building suffers from seasonal ground
co	CONDITION:	Poor	movement. The north vestry is attached to the chancel but is inadequately founded and has suffered irreversible
THE R	PRIORITY CATEGORY:	C (C)	structural movement and needs to be rebuilt. The parish is
1	OWNER TYPE:	Religious organisation	keen to effect repairs and may apply to the National Lottery Heritage Fund.
	LIST ENTRY NUMBER:	1062988	Contact: Ben Robinson 07823 327796

© Historic England

© Historic England



'E NAME:	Church of Holy Trinity, Sleaford Road, Tattershall	Former Norman under license by
SIGNATION:	Listed Place of Worship grade I, CA	1500, undertaker William Waynfle Restored 1893-9
ONDITION:	Poor	at the end of thei below ground dr
IORITY CATEGORY:	C (C)	require maintena
WNER TYPE:	Religious organisation	pinnacle bases. T discussing repair
T ENTRY NUMBER:	1215320	England's Covid-
		Contact: Imogen

n church converted into a Collegiate church King Henry VI in 1439. Constructed 1440-en by Ralph Cromwell, completed by ete. Glass removed to Stamford 1754. 97. Significant bat roost. Roof coverings are eir working lives. There are issues with Irainage and various rainwater goods ance. Some repairs are needed to fractured The Parochial Church Council are options, with grant support from Historic -19 Emergency Heritage at Risk Fund.

Contact: Imogen Newcombe 07387 524030



		0
SITE NAME:	Church of St Helen, Main Road, Theddlethorpe St. Helen	This parish church dates from the CI4; CI5 tower constructed of squared green sandstone with limestone
DESIGNATION:	Listed Place of Worship grade II*	bands, chancel and aisles were rebuilt by SS Teulon in 1866 using mixed stone rubble. Clerestory stonework is eroding
CONDITION:	Very bad	and render lumps are falling onto south aisle roof. East nave wall is holed; stone fall has damaged the chancel roof
PRIORITY CATEGORY:	A (A)	slating. Gutters and downpipes are in very bad condition
OWNER TYPE:	Religious organisation	and are not discharging water away from the building. South nave rainwater is eroding south aisle buttress
LIST ENTRY NUMBER:	1147259	stonework.
		Contact: Ben Robinson 07823 327796

© Historic England

PRIORITY CATEGORIES А

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D


Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site



© East Lindsey District Council

SITE NAME:	Neolithic long barrow 350m south west of Syca	more Farm, Binbrook	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018893
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Slight univallate hillfort on Swinhope Hill 430m r	north west of Glen Inr	nes House, Binbrook
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018839
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 280m south of Burgh Top	p Farm, Burgh on Bain	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013904
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 525m north east of Valley St. Andrew	y House: one of a grou	up known as Deadmen's Graves, Claxb
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017464
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	St Peter's Church, Low Toynton		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1004937
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Bowl barrow 100m south west of Gally Hill Farr	m, Ludford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013891
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY ?:	No

PRIORITY CATEGORIES

OWNER TYPE:

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet

implemented. C Slow decay; no solution agreed. Slow decay; solution agreed but F not yet implemented.

Private

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

CONTACT:

ABBREVIATIONS

Ben Robinson 07823 327796

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

	Neolithic long barrow 680m west of Maide	nwell House, Maidenwell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018891
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 850m ENE of Ruckla	and House, Maidenwell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013913
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 870m ENE of Ruckla	and House, Maidenwell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015203
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 300m south east of	Flint Hill House, Scamblesb	у
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015196
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Small multivallate hillfort 340m south east o	of North Road Farm, Tatte	rshall Thorpe
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018353
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 320m north west of	Skendleby Psalter, Ulceby	with Fordington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013918
	Extensive significant problems	TREND:	Declining
CONDITION:	Externative significant problems		Declining
	Arable ploughing	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:			0
PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing	NEW ENTRY?: CONTACT:	No Ben Robinson 07823 327796
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable ploughing Private	NEW ENTRY?: CONTACT:	No Ben Robinson 07823 327796
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Arable ploughing Private Neolithic long barrow 575m WSW of Man	NEW ENTRY?: CONTACT: or Warren Farm, Welton I	No Ben Robinson 07823 327796 Le Wold
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION:	Arable ploughing Private Neolithic long barrow 575m WSW of Man Scheduled Monument	NEW ENTRY?: CONTACT: or Warren Farm, Welton I LIST ENTRY NUMBER:	No Ben Robinson 07823 327796 Le Wold 1013908
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY:	Arable ploughing Private Neolithic long barrow 575m WSW of Man Scheduled Monument Extensive significant problems	NEW ENTRY?: CONTACT: Or Warren Farm, Welton I LIST ENTRY NUMBER: TREND:	No Ben Robinson 07823 327796 Le Wold 1013908 Declining
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Arable ploughing Private Neolithic long barrow 575m WSW of Man Scheduled Monument Extensive significant problems Arable ploughing	NEW ENTRY?: CONTACT: OR Warren Farm, Welton I LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	No Ben Robinson 07823 327796 Le Wold 1013908 Declining No Ben Robinson 07823 327796
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME:	Arable ploughing Private Neolithic long barrow 575m WSW of Man Scheduled Monument Extensive significant problems Arable ploughing Private	NEW ENTRY?: CONTACT: OR Warren Farm, Welton I LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT:	No Ben Robinson 07823 327796 Le Wold 1013908 Declining No Ben Robinson 07823 327796
PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION:	Arable ploughing Private Neolithic long barrow 575m WSW of Man Scheduled Monument Extensive significant problems Arable ploughing Private Small multivallate hillfort 460m east of Old	NEW ENTRY?: CONTACT: Or Warren Farm, Welton I LIST ENTRY NUMBER: TREND: NEW ENTRY?: CONTACT: Abbey Farm, Woodhall Spa	No Ben Robinson 07823 327796 Le Wold 1013908 Declining No Ben Robinson 07823 327796
CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE: SITE NAME: DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: DESIGNATION: CONDITION: CONDITION: PRINCIPAL VULNERABILITY:	Arable ploughing Private Neolithic long barrow 575m WSW of Man Scheduled Monument Extensive significant problems Arable ploughing Private Small multivallate hillfort 460m east of Old Scheduled Monument	NEW ENTRY?: CONTACT: OR Warren Farm, Welton I LIST ENTRY NUMBER: TREND: NEW ENTRY? CONTACT: Abbey Farm, Woodhall Spi LIST ENTRY NUMBER:	No Ben Robinson 07823 327796 Le Wold 1013908 Declining No Ben Robinson 07823 327796 a 1017880

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Alford, town centre, Alford		
DESIGNATION:	Conservation Area, 46 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Emilie Wales (LPA) 01507 601111 ex 3148
SITE NAME:	Binbrook, village centre, Binbrook		
DESIGNATION:	Conservation Area, 10 LBs, SM	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Emilie Wales (LPA) 01507 601111 ex 3148
SITE NAME:	Louth, Town centre, contiguous residential	areas & park, Louth / E	lkington
DESIGNATION:	Conservation Area, 197 LBs	NEW ENTRY ?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Emilie Wales (LPA) 01507 601111 ex 3148
SITE NAME:	Spilsby, town centre, Spilsby		
DESIGNATION:	Conservation Area, 32 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Emilie Wales (LPA) 01507 601111 ex 3148
SITE NAME:	Wainfleet, All Saints and St Marys, Wainflee	et All Saints / Wainfleet	St. Mary / Croft
DESIGNATION:	Conservation Area, 24 LBs, 2 SMs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Emilie Wales (LPA) 01507 601111 ex 3148
SITE NAME:	Wragby, village centre, Wragby		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Emilie Wales (LPA) 01507 601111 ex 3148

LINCOLN



© Historic England

SITE NAME:	Greyfriars former monastic building, Broadgate	The building is believed to be one of the earliest Franciscar churches in Europe and the oldest friary building in England
DESIGNATION:	Scheduled Monument, LB grade I, CA	It was remodelled for other uses, including a school a latterly a museum. The main clay tile roof covering is poor condition. The Welsh slate roof of the C19 exte
CONDITION:	Poor	has been repaired. The building is currently vacant. However, City of Lincoln Council is working in partnershi
OCCUPANCY:	Vacant/not in use	with Heritage Lincolnshire on a National Lottery Heritage
PRIORITY CATEGORY:	D (D)	Fund project to undertake repairs and convert to a visitor centre, venue and office.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1005029	Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Colonia wall and lower west gate, The Park, Lincoln	The remains of the lower west gate of the Roman colonia and adjoining walls. The remains were excavated in the
	DESIGNATION:	Scheduled Monument and Listed Building grade I, CA	1970s and now serve as a thoroughfare. Weathering and vandalism have caused significant fabric loss. Vegetation is encroaching on the length of colonia wall north of the gate.
	CONDITION:	Very bad	Historic England has provided management advice to Čity
	OCCUPANCY:	N/A	of Lincoln Council.
A D	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
Historic England	LIST ENTRY NUMBER:	1004986 and 1388731	Contact: Ben Robinson 07823 327796
	SITE NAME:	Church of St Swithin, Free School Lane, Lincoln	Built in the 1860s-70s by James Fowler of Louth and considered by Pevsner to be 'without doubt his most
	DESIGNATION:	Listed Place of Worship grade II*, CA	important church'. In the Early English style. Repairs to the chancel roof and parapet gutters and high level stonework were completed in 2013 and a medieval sculpture on the
	CONDITION:	Poor	east gable was conserved. However, there is still extensive
THE CHICKNER CONTRACTOR	PRIORITY CATEGORY:	C (C)	wall stonework decay and the condition of the chancel windows is still a major concern.
LI IN PLAT	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1388543	Contact: Ben Robinson 07823 327796
Historic England			
	SITE NAME:	Church of St Peter at Gowts, High Street, Lincoln	Ancient church with CI I nave and tower. North aisle and porch dated 1852, by W A Nicholson. The chancel was
H	DESIGNATION:	Listed Place of Worship grade I, CA	enlarged in 1887 by C H Fowler. There is some general erosion of stonework and pointing. The west tower in particular has evidence of historical structural movement,
	CONDITION:	Poor	possibly related to issues of decay within the bell frame. Further investigation of the cause is needed, alongside
	PRIORITY CATEGORY:	C (C)	further monitoring.
- Alter of	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1388599	Contact: Imogen Newcombe 07387 524030
Historic England			
	SITE NAME:	Cathedral Church of the Blessed Virgin Mary, Minster Yard, Lincoln	One of England's finest cathedrals and an iconic landmark, established 1072. Programmes of repair are addressing the decay of fabric, yet the condition of high-level masonry and
A REAL	DESIGNATION:	Listed Place of Worship grade I, CA	some roofs remain a concern. Historic England has funded repairs to the southwest and northwest turrets. National Lottery Heritage Fund awarded funding towards a £16
	CONDITION:	Fair	million project; Lincoln Cathedral Connected. The project includes visitor facilities, repairs to the west front and
	PRIORITY CATEGORY:	F (F)	conservation of the Romanesque Frieze. Awarded grant
	OWNER TYPE:	Religious organisation	support from Historic England's Covid 19 Emergency Heritage at Risk Response Fund.
Historic England	LIST ENTRY NUMBER:	1388680	Contact: Ben Robinson 07823 327796
4	SITE NAME:	Church of St Hugh and attached vestry, Monks Road, Lincoln	City centre church of 1892-3 by Albert Vicars with a history of stone failure. By 2018, the condition of masonry,
	DESIGNATION:	Listed Place of Worship grade II, CA	particularly the spire, tower and pinnacles at the base of the spire was poor. Past inappropriate render repairs were failing and there has been several falls of masonry and
	CONDITION:	Very bad	render fragments. Repairs were tendered in early 2020 to
PR	PRIORITY CATEGORY:	F (F)	inform an application to the National Lottery Heritage func- but the scheme was suspended in March due to Covid-19.
	OWNER TYPE:	Religious organisation	Scaffolding was erected in 2020 to protect passers-by and repairs were completed in 2021.

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / LINCOLN / NORTH KESTEVEN

SITE NAME:	Lincoln Roman colonia wall at Cecil Street		
DESIGNATION:	Scheduled Monument, 5 LBs, part in CA	LIST ENTRY NUMBER:	1003569
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Carline, Lincoln		
DESIGNATION:	Conservation Area, LB grade II*	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Sarah Harrison (LPA) 01522 873760
SITE NAME:	Cathedral and City Centre, Lincoln		
DESIGNATION:	Conservation Area, 322 LBs, 21 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Sarah Harrison (LPA) 01522 873760
SITE NAME:	Gowts Bridge, Lincoln		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Harrison (LPA) 01522 873760
SITE NAME:	Lindum and Arboretum, Lincoln		
DESIGNATION:	Conservation Area, 20 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Harrison (LPA) 01522 873760
SITE NAME:	Swanpool, Lincoln		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Harrison (LPA) 01522 87376
SITE NAME:	West Parade and Brayford, Lincoln		
DESIGNATION:	Conservation Area, 9 LBs, SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly

NORTH KESTEVEN



SITE NAME:	Somerton Castle and outbuildings, Castle Lane, Boothby Graffoe	Early C14 castle with C17 outbuildings. The extensiv disrepair and the farm bui
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade I	new owner is undertaking project. This has been info archaeological investigatic
CONDITION:	Fair	Local Planning Authority a and refurbishment of the
OCCUPANCY:	Vacant/not in use	Repairs and conversion o
PRIORITY CATEGORY:	F (F)	southwest towers and ot
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1005015 and 1360511; 1061975	Contact: Ben Robinson 0

7 farmhouse and later ive property had fallen into uildings were largely redundant. A ng a major repair and conversion formed by thorough surveys and ons, and has been advised by the and Historic England. The repair house has been completed. of the ruined northeast and ther buildings are nearly complete.

© Historic England

LIST EN

D

Е

07823 327796

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH KESTEVEN

	SITE NAME:	Manor Farmhouse, Helpringham, Helpringham	C15 origin, largely C17 with C18 and C19 alterations. An Urgent Works Notice, underwritten by Historic England,
	DESIGNATION:	Listed Building grade II*, CA	was served and implemented in 2008/2009. Proposals for repair and renovation which are tied to a larger housing
	CONDITION:	Very bad	development in the village were agreed by the Local Planning Authority in 2014/15. Work on the farmhouse
	OCCUPANCY:	Vacant/not in use	began in 2019. These works led to the demolition of a large amount of the building including the front elevation and roof structure of the principal range. Historic England
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	has advised the Local Authority and owner regarding remedial works.
nd	LIST ENTRY NUMBER:	1061814	Contact: Janine Dykes 0121 6256870

© Historic England



© Historic England Archive

	SITE NAME:	Former maltings of Bass Industrial Estate, Mareham Lane, Sleaford	Maltings, 1892-1905. A vast complex of buildings. Long disused and has suffered from fires and vandalism. A feasibility study was undertaken in collaboration with
	DESIGNATION:	Listed Building grade II*	Phoenix Trust. The site was sold. Planning permission and Listed Building Consent was given for mixed use
	CONDITION:	Poor	development and conversion several years ago, but this has not been implemented. The buildings and site continue to
	OCCUPANCY:	Part occupied/part in use	deteriorate.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1062154	Contact: Ben Robinson 07823 327796



SITE NAME:	Church of St Edith, Church Lane, Anwick	Parish church of limestone ashlar construction with some coursed rubble. Built late C13, C14, restored 1859. The
DESIGNATION:	Listed Place of Worship grade I	chancel was restored 1900, and the south aisle in 1915. The church has been the subject of heritage crime in 2019
CONDITION:	Poor	and a temporary solution has been put in place. The Parochial Church Council are keen to effect repairs and
PRIORITY CATEGORY:	C (C)	have sought permissions for a programme of repair works.
OWNER TYPE:	Religious organisation	Fundraising is underway, with support from the Diocesan Historic Churches Support Officer.
LIST ENTRY NUMBER:	1061829	Contact: Imogen Newcombe 07387 524030
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Lane, AnwickDESIGNATION:Listed Place of Worship grade ICONDITION:PoorPRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

© Historic England

	SITE NAME:	Parish Church of St Denys, Main Street, Aswarby and Swarby	Church of C12 origins with later C14 and C15 work. Restored in 1850 by Edward Blore. The stability of the
	DESIGNATION:	Listed Place of Worship grade I, CA	masonry spire is of concern and the top courses were taken down for safety reasons in 2015. Repair works und a National Lottery Heritage Fund grant-aided project wa completed in 2019, but further repair works are required
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1360619	Contact: Ben Robinson 07823 327796

© Historic England

	SITE NAME:	Church of All Saints, Main Street, Beckingham	Medieval church restored in 18 scheme in the chancel dating to
	DESIGNATION:	Listed Place of Worship grade I	been severely damaged by m C20. The chancel, organ char
	CONDITION:	Fair	north aisle have all been re-roo and National Lottery Heritage F
	PRIORITY CATEGORY:	C (C)	Repairs to the south aisle and se
	OWNER TYPE:	Religious organisation	undertaken previously and repa associated timber work have re
	LIST ENTRY NUMBER:	1360525	Concerns remain over the char pew platforms.
			P P

© Historic England

888. Evidence of a painted o the mid-late CI9 which has dern paints used in the midnber and vestry, nave and ofed with Historic England Fund repair fund grant aid. south porch roofs have been pairs to the tower roof and recently been completed. ancel interior and condition of

Contact: Hanna Good 07825 318060

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

39

HERITAGE AT RISK 2022 / MIDLANDS / NORTH KESTEVEN

	SITE NAME:	Church of St Michael, Church Street, Billinghay	A village centre parish church dating from C12, C14, and C15. The tower and spire were rebuilt in 1787, the spire
	DESIGNATION:	Listed Place of Worship grade I, CA	rebuilt again in 1912. The north aisle was rebuilt in 1856. The roofs to the chancel, south porch and organ chamber are in poor condition and need re-slating. Funding is in
	CONDITION:	Poor	place for repairs but Covid-19 has hindered progress.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1204770	Contact: Ben Robinson 07823 327796
: England			

© Historic E

© Historic England



k	Walk, Brant Broughton and Stragglethorpe GF Bodley in 1873-76. The church was th heritage crime in 2010 and 2014. Rainwat	Parish church with fabric from C11, rebuilt and altered by GF Bodley in 1873-76. The church was the subject of heritage crime in 2010 and 2014. Rainwater goods and	
	DESIGNATION:	Listed Place of Worship grade I, CA	parapet gutters are impacted with detritus and vegetation at ground level, which is affecting disposal. All require review and clearing. The nave, north aisle and chancel
	CONDITION:	Poor	roofs require repairs and overhauling in places, alongside associated timber, rainwater goods and flashing repairs.
	PRIORITY CATEGORY:	C (New entry)	The south clerestory and north aisle require localised high-
	OWNER TYPE:	Religious organisation	level stonework repairs.
	LIST ENTRY NUMBER:	47497	Contact: Imogen Newcombe 07387 524030



	SITE NAME:	Church of St Michael, Stragglethorpe Lane, Brant Broughton and Stragglethorpe	Parish church with fabric from C11 and late C12, restored c.1980. The church lacks rainwater goods, which is causing internal damp, efflorescence and epilithic growths on the
	DESIGNATION:	Listed Place of Worship grade I	internal walls and floors. Drainage is ineffective, as it is full of gravel and detritus. There is moderate structural
	CONDITION:	Poor	movement, causing external and internal cracking at wall junctions, soffits and reveals, with associated bulging of the
	PRIORITY CATEGORY:	C (New entry)	north aisle wall. The roof requires tile replacement, and
	OWNER TYPE:	Religious organisation	repointing is needed both externally and internally.
	LIST ENTRY NUMBER:	1061900	Contact: Imogen Newcombe 07387 524030

© Historic England Archive

- Agen	SITE NAME:	Parish Church of St Andrew, Kelby, Culverthorpe and Kelby	Parish church, CI2-CI4 constructed of coursed limestone rubble and ashlar. The tower and spire were rebuilt in
1 Carlos	DESIGNATION:	Listed Place of Worship grade I, CA	1850. There are a few slipped slates to the chancel roof and some localised repointing is required. The church interior is suffering from damp. The church has been
王國國際	CONDITION:	Poor	subject to heritage crime.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1360583	Contact: Imogen Newcombe 07387 524030

© Historic England



SITE NAME:	Church of St Peter, Church Lane, Navenby	Parish church from C13-C15, mid C18 and restored 1875- 6 with C20 additions. Constructed of limestone rubble and
DESIGNATION:	Listed Place of Worship grade I, CA	ashlar with ashlar dressings. The tower was rebuilt in the mid C18. The church has been subject to heritage crime. Support is being provided by the Diocesan Historic
CONDITION:	Poor	Churches Support Officer.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1147458	Contact: Imogen Newcombe 07387 524030

© IoE. Mr James Brown

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / NORTH KESTEVEN



© Diocese of Lincoln

SITE NAME:	Parish Church of St Peter, Laundon Road, Threekingham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	3069

Church with fabric from C12, C13 and C14. The spire was restored in 1872. At the west end of the nave are 2 large recumbent figures of a knight and his lady; reputed to be Sir Lambert de Trikyngham (d. 1280) and his wife. The church was subject to heritage crime in 2019 and requires repairs. Rainwater goods are in need of refurbishment and below ground drainage improvements are required. Some repointing and patch repairs are required to the tower and at high level. Sections of the interior are suffering from damp related issues. Potential funding avenues are being reviewed.

Contact: Imogen Newcombe 07387 524030

SITE NAME:	Settlement site 650yds (600m) east of Holme He	ouse, Heckington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004927
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman villa west of Hill Holt Farm, Norton Disr	iey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005018
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - moderate	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Butt Mound bowl barrow, Butt Lees, Silk Willou	ghby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Folk Moot bowl barrow, Butt Lees, Silk Willoug	ıby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018900
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Silkby Chapel remains, Butt Lees, Silk Willoughb	y	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018901
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No		No	
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH KESTEVEN / SOUTH HOLLAND



© Historic England

SITE NAME:	Rauceby Hospital, Sleaford / Silk Willoughby	Rauceby Hospital was designed as the Kesteven County Lunatic Asylum by renowned asylum specialist G T Hine.
DESIGNATION:	Registered Park and Garden grade II, part in CA	William Goldring's plan for the grounds was drawn up in 1900 and implemented over the next few years with inmate labour. Rauceby served as an RAF hospital during
CONDITION:	Extensive significant problems	World War Two. It was here that pioneering plastic surgery was carried out for aircrew who had suffered
VULNERABILITY:	High	severe burns. The hospital closed in the late 1990s and the
TREND:	Declining	grounds have been extensively developed for housing, which continues. The central core of the complex remains
NEW ENTRY?:	No	derelict and its future has yet to be secured.
OWNER TYPE:	Commercial company, multiple owners	
LIST ENTRY NUMBER:	1001471	Contact: Erika Diaz Petersen 0121 625 6879

SITE NAME:	Rauceby Hospital, Sleaford		
DESIGNATION:	Conservation Area, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Gareth Hughes 01529 414155
SITE NAME:	Sleaford No. 1, Sleaford No. 2 and Sleaford Extens	ion, Sleaford	
SITE NAME: DESIGNATION:	Sleaford No. 1, Sleaford No. 2 and Sleaford Extens Conservation Area, 141 LBs, SM	ion, Sleaford NEW ENTRY?:	No
	,	,	No Deteriorating

SOUTH HOLLAND

	SITE NAME:	Old office block of Land Settlement Association, Mallard Road, Low Fulney, Spalding	House, C17 re-fronted in the C18 and incorporating medieval monastic ruins. Stands within an area of intensive market gardens with limited curtilage. Suffering serious
	DESIGNATION:	Listed Building grade II*	structural damage. There is uncontrolled woody plant growth to one elevation. Urgent works were carried out in
	CONDITION:	Very bad	2004, underwritten by Historic England grant aid. In 2008, permission was granted to build glasshouses near to the
	OCCUPANCY:	Vacant/not in use	building, further restricting the curtilage. Historic England
	PRIORITY CATEGORY:	A (A)	has offered the Council support to prepare for further enforcement action.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1359567	Contact: Hanna Good 07825 318060



SITE NAME:	Crowland Manor, 5, East Street, Crowland	Former manor, 1690, with mid-C18 additions possibly by William Sands the younger of Spalding. Limestone ashlar
DESIGNATION:	Listed Building grade II*, CA	north front and red brick south front with ashlar dressings. Some repair works undertaken previously but the property
CONDITION:	Very bad	was in a very bad condition at the time of its sale. The current owner has cleared the grounds, carried out
OCCUPANCY:	Occupied/in use	drainage improvements, installed temporary propping and
PRIORITY CATEGORY:	C (C)	undertaken some repairs. Replacement of failing stone slate roof coverings and structural repairs are required. The
OWNER TYPE:	Private	owner is not yet able to discuss potential grant funding nor progress major repairs.
LIST ENTRY NUMBER:	1359273	Contact: Ben Robinson 07823 327796

© Historic England

PRIORITY CATEGORIES

implemented.

А

В

Immediate risk of further rapid deterioration or loss of fabric; no

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet

C Slow decay; no solution agreed.

© Historic England

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH HOLLAND

LIST ENTRY NUMBER:

1067614

		-	
	SITE NAME:	Sneaths Mill, Lutton Gowts, Lutton	Octagonal brick tower windmill, 1779, incorporating the remains of an earlier C18 mill. Unique in Lincolnshire and
	DESIGNATION:	Listed Building grade I	the oldest surviving tower mill in the county. Ceased to work in the 1930s and emergency repairs carried out in
Mar Mar	CONDITION:	Poor	1992. Historic England funded urgent repairs to make the building weather tight in 2011 and a comprehensive
	OCCUPANCY:	Vacant/not in use	assessment of the timber machinery in 2018. Planning
	PRIORITY CATEGORY:	D (D)	permission has been obtained to convert the outbuildings and piggery. A National Lottery Heritage Fund grant was
and the second second	OWNER TYPE:	Charity (heritage)	awarded to help the Sneaths Mill Trust to develop a comprehensive project and build capacity.
istoric England	LIST ENTRY NUMBER:	1064530	Contact: Ben Robinson 07823 327796
	SITE NAME:	Broad Street Methodist Church and attached Sunday School, Broad Street, Spalding	Methodist church, built by F Boreham in 1887. The attached Sunday School serves as a church hall and provides services to the wider community. Red brick
	DESIGNATION:	Listed Place of Worship grade II, CA	construction with ashlar dressings and decorative banding. The extensive slate roofs suffered widespread nail fatigue. Re-roofing of the church was completed in 2014 following
	CONDITION:	Fair	a joint Historic England and National Lottery Heritage Fund Repair Grants for Places of Worship grant. There are a
	PRIORITY CATEGORY:	C (C)	number of defects with the Sunday School and rear range
	OWNER TYPE:	Religious organisation	roofs. These buildings remain vulnerable. The church is well used by the local community.
			. ,

© Historic England

© His



Parish church c. | 180-| 190, mid-C14, restored 1798, 1843 SITE NAME: Church of St Mary Magdalen, and 1860-2 by C Bennett of Lynn. Limestone rubble and Hallgate, Fleet, Fleet ashlar. All the window tracery restored in C19. The church Listed Place of Worship grade I, was subject to heritage crime in 2020. A Faculty application DESIGNATION: CA for subsequent repair works has been approved, and the Parochial Church Council are keen to undertake these CONDITION: Poor repairs and investigate potential funding avenues. PRIORITY CATEGORY: C (C) OWNER TYPE-Religious organisation LIST ENTRY NUMBER: 1146568 Contact: Imogen Newcombe 07387 524030

Contact: Hanna Good 07825 318060

© Mr David Brown. Source: Historic England Archive



	SITE NAME:	Church of Holy Trinity, Hillgate, Gedney Hill	Parish church dating from the late-C14 and mid-C15, restored by James Fowler of Louth in the 1870s. The
-	DESIGNATION:	Listed Place of Worship grade II*	church is unusual for Lincolnshire in its internal timber frame and fine timber nave arcades. There are deeply
	CONDITION:	1001	eroded sections of pointing to the tower, decay to structural timbers to the tower roof and water ingress via
	PRIORITY CATEGORY:		the tower roof covering. Re-covering of part of the south
E	OWNER TYPE:	Religious organisation	aisle roof is also required. Ongoing support and advice is being provided by the Diocesan Historic Churches Support
-	LIST ENTRY NUMBER:	4677	Officer.
			Contact: Imogen Newcombe 07387 524030

© Historic England

SITE NAME:	Settlement north east of Whitebread Farm, Crowland		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER:		1004978
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Settlement north of The Parks, Deeping St. Nichola	s	
SITE NAME: DESIGNATION:	Settlement north of The Parks, Deeping St. Nichola Scheduled Monument	S LIST ENTRY NUMBER:	1004980
			1004980 Declining
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but $\ \ F$ not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building CA

- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH HOLLAND / SOUTH KESTEVEN

SITE NAME:	Settlement south west of The Parks, Deeping St.	Nicholas	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004981
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Settlement south east of Lower Delgate Farm, W	/eston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002945
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Dawsmere, Gedney		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	High	CONTACT:	Gregory Watkinson 01775 764560
SITE NAME:	Long Sutton		
DESIGNATION:	Conservation Area, 29 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Gregory Watkinson 01775 764560

SOUTH KESTEVEN

	SITE NAME:	Angel and Royal Hotel, High Street, Grantham	One of the few remaining English medieval inns, dating from late C14 with substantial C18 additions at the rear.
	DESIGNATION:	Listed Building grade I, CA	Currently in use as a hotel. Much of the ornately decorated stone frontage has suffered severe erosion, and many of
	CONDITION:	Fair	the corniced figures are now unrecognisable or missing. Historic England has encouraged the owners to investigate
	OCCUPANCY:	Occupied/in use	the condition of the stone frontage further. The building is
	PRIORITY CATEGORY:	C (C)	otherwise in good condition.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1062486	Contact: Marie Twomey 0121 625 6838

© Historic England



SITE NAME:	Bridge over lake, Grantham Road, Harlaxton	Circa 1822-1838. Impressive stone bridge over lake: an important part of the historic landscape. Several balusters
DESIGNATION:	Listed Building grade II*, RPG grade II*	missing and vegetation growing out of parapets. Evidence of severe frost shattering and crumbling stonework. A parkland management plan has been completed with grant
CONDITION:	Poor	funding from Historic England.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Educational (independent)	
LIST ENTRY NUMBER:	87968	Contact: Erika Diaz Petersen 0121 625 6879

© Historic England

Contact: Erika Diaz Petersen 0121 625 6879

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Ornamental garden steps 50 metres south west of Harlaxton Manor, Grantham Road, Harlaxton	Ornamental garden steps, 1838-1844, situated in the early C19 formal gardens to the south west of the house. Retaining wall in poor condition. Steps are sound although some re-bedding needed. Repointing needed for open
	DESIGNATION:	Listed Building grade II*, RPG grade II*	joints. Significant erosion of detail. Condition survey undertaken with Historic England grant aid. A parkland management plan has also been completed with grant
	CONDITION:	Poor	funding from Historic England.
	OCCUPANCY:	N/A	
© Historic England	PRIORITY CATEGORY:	C (C)	
C Filotorie England	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1236717	Contact: Erika Diaz Petersen 0121 625 6879
	SITE NAME:	Railway tunnel attached to Harlaxton Manor, Grantham Road, Harlaxton	Curved brick viaduct containing a narrow gauge railway for supplying the service courtyard, 1838-1844. Part repaired; screen wall and platform remain in derelict state. Further
	DESIGNATION:	Listed Building grade I, RPG grade II*	brickwork and masonry repair and repointing is needed. A parkland management plan has been completed with Historic England grant funding.
	CONDITION:	Poor	
and the second	OCCUPANCY:	N/A	
and the second second	PRIORITY CATEGORY:	C (C)	
© Historic England	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1298440	Contact: Erika Diaz Petersen 0121 625 6879
	SITE NAME:	Greyfriars Gate, Stamford	Part late CI4 or early CI5, restored with substantial late
	DESIGNATION:	Scheduled Monument, part in CA	C19 additions. The lodges and chamber are no longer used. Some evidence of historic structural movement is visible. The chamber over the arch and south lodge
	CONDITION:	Fair	suffered water ingress and the north lodge roof decayed beyond repair. Roofs have now been replaced and
P.G.	OCCUPANCY:	Vacant/not in use	repaired, masonry repairs have been carried out and the
	PRIORITY CATEGORY:	E (E)	building is secure. However, there is not yet a firm plan to re-use the building.
	OWNER TYPE:	Health authority	
© Historic England	LIST ENTRY NUMBER:	1005006	Contact: Ben Robinson 07823 327796
	SITE NAME:	Seats, balustrades and terraces to east of Stoke Rochford Hall, Stoke Rochford	Seats, balustrades and terraces to the east of Stoke Rochford Hall. 1841-45, by William Burn. Acquired by the previous owner in 2016 by which time the terrace walls were in very poor condition as a result of rusting iron
	DESIGNATION:	Listed Building grade I, RPG grade II*	cramps and poor original detailing. Damage was
Care AN IN MARCE	CONDITION:	Poor	progressive and accelerating. Some balusters were loose and at risk of falling. Historic England had been in
	OCCUPANCY:	N/A	communication with a former leaseholder about repairs. The building was sold in late 2019. Contact has yet to be
		1 1/ / 1	
		A (A)	made with the new owner.
© Historic England	PRIORITY CATEGORY:	A (A)	made with the new owner.
© Historic England	PRIORITY CATEGORY:	A (A) Commercial company 1360353	made with the new owner. Contact: Amanda White 0121 625 6890
© Historic England	PRIORITY CATEGORY: OWNER TYPE:	Commercial company	Contact: Amanda White 0121 625 6890 Parish church c.1300, with various phasing from C14 through to 1631 and the C19, of ashlar construction. Some
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Commercial company 1360353 Church of St Peter, Town	Contact: Amanda White 0121 625 6890 Parish church c.1300, with various phasing from C14
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	Commercial company 1360353 Church of St Peter, Town Street, Claypole	Contact: Amanda White 0121 625 6890 Parish church c.1300, with various phasing from C14 through to 1631 and the C19, of ashlar construction. Som rendering with ashlar dressings. Cruciform plan with west tower with spire. The church was the recipient of a Roof Repair Fund grant in 2015 to re-roof the chancel and
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Commercial company 1360353 Church of St Peter, Town Street, Claypole Listed Place of Worship grade I	Contact: Amanda White 0121 625 6890 Parish church c.1300, with various phasing from C14 through to 1631 and the C19, of ashlar construction. Som rendering with ashlar dressings. Cruciform plan with west tower with spire. The church was the recipient of a Roof Repair Fund grant in 2015 to re-roof the chancel and vestry. The church has been the subject of heritage crime. A Faculty was approved in June 2021, and the Parochial
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Commercial company 1360353 Church of St Peter, Town Street, Claypole Listed Place of Worship grade I Poor	Contact: Amanda White 0121 625 6890 Parish church c.1300, with various phasing from C14 through to 1631 and the C19, of ashlar construction. Som rendering with ashlar dressings. Cruciform plan with west tower with spire. The church was the recipient of a Roof Repair Fund grant in 2015 to re-roof the chancel and vestry. The church has been the subject of heritage crime. A Faculty was approved in June 2021, and the Parochial Church Council are keen to undertake these repairs.
© Historic England	PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION: PRIORITY CATEGORY:	Commercial company 1360353 Church of St Peter, Town Street, Claypole Listed Place of Worship grade 1 Poor A (A)	Contact: Amanda White 0121 625 6890 Parish church c.1300, with various phasing from C14 through to 1631 and the C19, of ashlar construction. Som rendering with ashlar dressings. Cruciform plan with west tower with spire. The church was the recipient of a Roof Repair Fund grant in 2015 to re-roof the chancel and vestry. The church has been the subject of heritage crime. A Faculty was approved in June 2021, and the Parochial

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH KESTEVEN

	SITE NAME:	Church of St Michael and All Angels, Main Street, Edenham	Parish church with C8, C12, C13, C15 and early C16 fabric, plus C19 work. The chancel and south aisle roof
	DESIGNATION:	Listed Place of Worship grade I	coverings have been renewed and parapet stone work secured in 2014-15, funded by a National Lottery Heritage
	CONDITION:	Poor	Fund Repair Grants for Places of Worship scheme grant. The nave roof is leaking and the significant monuments in
	PRIORITY CATEGORY:	C (C)	the chancel require conservation due to continued damage
	OWNER TYPE:	Religious organisation	by damp conditions over many years. The porch barrel- vaulted plaster ceiling is damaged from water ingress
SA	LIST ENTRY NUMBER:	1146587	although the porch roof slating has now been renewed. The below-ground drainage has also been renewed.
			The below ground drainage has also been renewed.

© Historic England



10.0	SITE NAME:	Church of St Andrew, Church Lane, Haconby	Late C12 parish church with early C13, c.1300, and C15 additions. Restored C19. Coursed ironstone rubble,
	DESIGNATION:	Listed Place of Worship grade I	limestone ashlar with some render. The church has been subject to heritage crime and is suffering from water
	CONDITION:	Poor	ingress. A Faculty application for repair works has been approved, and the Parochial Church Council are keen to
	PRIORITY CATEGORY:	D (C)	undertake these repairs.
	OWNER TYPE:	Religious organisation	
-	LIST ENTRY NUMBER:	1360134	Contact: Imogen Newcombe 07387 524030

Contact: Ben Robinson 07823 327796

© Diocese of Lincoln

	SITE NAME:	Church of St Swithun, Church Street, Long Bennington	Located on the site of the former priory, a large parish church dating from early CI3, with CI4, (aisles
	DESIGNATION:	Listed Place of Worship grade I	constructed) C15, and C19 work, restored 1902-3 by Scorer and Gamble Architects, (ceilings in nave and aisles
	CONDITION:	Poor	assumed from this date). The church north aisle has suffered from structural movement related to poor
	PRIORITY CATEGORY:	C (C)	rainwater disposal arrangements and ground drainage
© Historic England	OWNER TYPE:	Religious organisation	affecting the bearing strata. A National Lottery Heritage Fund Grant for Places of Worship grant, to address the
	LIST ENTRY NUMBER:	1062891	chancel roof and drainage, was completed in 2019. The church is drying out but a further phase of repairs is
			required.
			Contact: Ben Robinson 07823 327796
	SITE NAME:	Church of St Mary, Church Lane, North Witham	Parish church. Late CI1, CI3-CI5 and restored in 1887. Constructed of ashlar and coursed limestone rubble. Two
	DESIGNATION:	Listed Place of Worship grade I	stage C14 ashlar tower. The church was subject to heritage crime in 2019 and is suffering from water ingress due to the
	CONDITION:	Poor	failing of the temporary cover. Potential funding avenues

are being explored and engagement with the Diocesan PRIORITY CATEGORY: A (A) Historic Churches Support Officer is ongoing. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1360327 Contact: Imogen Newcombe 07387 524030

© Historic England



D

Е

SITE NAME:	Church of St James, Church Street, Skillington	CII fabric. Problems with rising damp, the below-ground drainage system and water dispersal from the building
DESIGNATION:	Listed Place of Worship grade I, CA	needs to be addressed. It is possible that part of the nave requires re-roofing, and the north aisle and south transept/chapel and porch roof coverings require repair.
CONDITION:	Poor	There is water ingress to several roofs. Ivy growth has taken hold externally to the tower and vestry. The church
PRIORITY CATEGORY	"· D (D)	has been the subject of heritage crime. Repairs completed
OWNER TYPE:	Religious organisation	with grant support from Historic England's Covid 19 Emergency Heritage at Risk Response Fund. Further
LIST ENTRY NUMBER	1168300	repairs required. Funds are being sought.

Contact: Hanna Good 07825 318060

© Historic England

PR	IOR	ITY C	ATEC	GOR	IES	

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious now user (applicable only obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument

- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH KESTEVEN

	SITE NAME:	Church of St James, Village Street, Woolsthorpe By Belvoir	Church, 1847 by GG Place of Nottingham. Built in the early C14 style on the site of the former St Mary's Chapel of
	DESIGNATION:	Listed Place of Worship grade II, CA	Ease. The church has suffered problems associated with structural movement and roofing defects. A National Lottery Heritage Fund Repair Grant for Places of Worship
	CONDITION:	Poor	Lottery Heritage Fund Repair Grant for Places of Worship funded the renewal of nave and south aisle roofing and extensive roof timber repairs and structural works in 2014-
	PRIORITY CATEGORY:	C (C)	15. The condition of the stonework to the tower and the
	OWNER TYPE:	Religious organisation	main body of the church is of concern and the interior needs repair following many years of damage from water
	LIST ENTRY NUMBER:	1168645	ingress.
© Historic England			Contact: Imogen Newcombe 07387 524030

SITE NAME:	Bronze Age saltern, Billingborough				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004961		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796		
SITE NAME:	Five barrows north west of Heath Farm, Great	Ponton			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004998		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796		
SITE NAME:	Settlement site at Greatford, Greatford / Barho	m and Stowe			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004957		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796		
SITE NAME:	Settlement site east of Greatford village, Greatford / Barholm and Stowe				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004934		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796		
SITE NAME:	Settlement between Long Drove and Dowsby D	Prain, Rippingale			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004977		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796		
SITE NAME:	Settlement between Rippingale Running Dike an	d Long Drove, Ripping	gale		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004976		
CONDITION:	Extensive significant problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / SOUTH KESTEVEN / WEST LINDSEY

SITE NAME:	Causewayed camp, Uffington			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1004938
CONDITION:	Extensive significa	ant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Ben Robinson 07823 327796
- mark	SITE NAME:	Harlaxton Manor, Harlaxton	A mid-C19 park and gardens with contemporary Jacobean/Baroque garden buildings, walled kitchen gar and house. Historic split management of landscape and conversion of house and gardens to institutional use, deterioration of built features (buildings at risk) and de of wider parkland due to arable agriculture. Several gar buildings and structures have been repaired, and a park plan prepared, with Historic England grants and other	
	DESIGNATION:	Registered Park and Garden grade II*, 17 LBs, part in CA		
a ya	CONDITION:	Generally satisfactory but with significant localised problems		
A CONTRACTOR	VULNERABILITY:	Medium		
	TREND:	Improving		College is progressing plans for tensive parkland formerly in separate
	NEW ENTRY?:	No	ownership.	
© Historic England	OWNER TYPE:	Educational (independent)		
	LIST ENTRY NUMBER:	1000982	Contact: Erika D	iaz Petersen 0121 625 6879

SITE NAME:	Grantham		
DESIGNATION:	Conservation Area, 156 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Kerry Walmsley (LPA) 01476 406472

WEST LINDSEY

© Historic England	SITE NAME:	Newsham Bridge, Brocklesby Park, Brocklesby	Late C18 gothic bridge, circa 1772, probably designed by Lancelot 'Capability' Brown. Brown's work at Brocklesby
	DESIGNATION:	Listed Building grade I, RPG grade I	Park included the extension of Newsham Lake, in the C17 and C18 parkland to the east of the Hall. Stonework chipped, details broken away. Prone to vandalism. Masonry
	CONDITION:	Poor	repair works completed. Bridge deck to be completed in 2022. Full lenth of lake restored to hold water.
	OCCUPANCY:	N/A	2022. I dirichti of lake restored to fiold water.
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1063419	Contact: David Walsh 0121 625 6888



© Historic England

	SITE NAME:	Bridge over lakes at Norton Place, Norton Place, Glentham	Bridge, 1776 by John Carr. Parapet has collapsed and damage is occurring from tree roots; the sluice gate and			
	DESIGNATION:	Listed Building grade II*, RPG grade II	weirs are blocked. Some trees have been removed in the past but the area around the bridge has since become overgrown with self-set vegetation, and the bridge			
	CONDITION:	Very bad	continues to deteriorate.			
	OCCUPANCY:	N/A				
R	PRIORITY CATEGORY:	A (A)				
0283	OWNER TYPE:	Private				
	LIST ENTRY NUMBER:	1165038	Contact: Erika Diaz Petersen 0121 625 6879			

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

48

	SITE NAME:	Church of St George, Goltho Road, Goltho	This enigmatic small brick church is in the care of the Churches Conservation Trust. It has a C16 nave and late
	DESIGNATION:	Listed Building grade II*	C17 or early C18 chancel and is surrounded by the buried remains of the settlement it once served. Its simply
	CONDITION:	Very bad	furnished interior and roof were destroyed by fire on 21st October 2013. The shell of the building has been secured,
	OCCUPANCY:	Vacant/not in use	stabilised and covered. It is regularly monitored, however there are no immediate plans for repair and rebuilding.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
ic England	LIST ENTRY NUMBER:	1308371	Contact: Imogen Newcombe 07387 524030



© Historic

© Historic England

© Historic England

Great Limber the Temp evidence Listed Building grade I, RPG Natural E	The Pelham Mausoleum, 1787-1792, by Wyatt; based on he Temple of Sibyl at Tivoli. Deteriorating stonework and		
	DESIGNATION:		evidence of water ingress. Loss of detail at high level. Natural England Stewardship scheme in progress. Repair works ongoing, to be completed in 2023.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (C)	
I Read and	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1063361	Contact: David Walsh 0121 625 6888



	SITE NAME:	Gate, mounting block and wall, Kettlethorpe Hall, Hall Lane, Kettlethorpe	Gateway, C14 with C18 alterations. Eroded brickwork, repointing and repair required.
Cas 1	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	47 72	Contact: Ben Robinson 07823 327796

	SITE NAME:	Gates and piers to Nettleham Hall, Hall Lane, Nettleham	Gate and gate piers, circa 1720. Attributed to Francis or William Smith of Warwick. Relocated from the demolished
	DESIGNATION:	Listed Building grade I	St Peter at Arches Church in Lincoln and once led to Nettleham Hall. Ironwork is in very poor condition and
	CONDITION:	Very bad	some stonework is displaced. Some of the Victorian railings have been stolen from the side walls and stonework has
	OCCUPANCY:	N/A	been damaged. Condition survey completed and consent
	PRIORITY CATEGORY:	A (A)	applied for to repair the gates and restore the driveway to a principal dwelling incorporating the ruined hall.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1165868	Contact: David Walsh 0121 625 6888

© Historic England

© Historic England



Torksey Scheduled Monument and Listed DESIGNATION: Building grade I CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1005056 and 1064079

Torksey Castle, Trent Side,

Remains of country house of 1560 slighted in the Civil War. The west wall and part of south wall remain. Major structural repairs were carried out in 1991 and a watching brief was maintained. The main structure appears stable but repairs to exposed brickwork required. Fabric and buried remains under threat from vegetation growth. A condition survey was carried out several years ago and options for repairs, access and interpretation have been investigated. No further progress has been made.

Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

SITE NAME:

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

SITE NAME:	Church of St Martin, Church Lane, Blyton	Parish church with fabric dating from CII, CI3 to CI6 and c.1860. Constructed of coursed limestone rubble and rock
DESIGNATION:	Listed Place of Worship grade I	faced ashlar. The north aisle was rebuilt in C19. The church was subject to heritage crime in 2019. The Parochial
CONDITION:	Poor	Church Council are keen to undertake repairs and investigate potential funding avenues. Support is being giv by the Diocese, alongside advice from the Diocesan
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	Historic Churches Support Officer.
LIST ENTRY NUMBER:	1064159	Contact: Imogen Newcombe 07387 524030
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Lane, BlytonDESIGNATION:Listed Place of Worship grade ICONDITION:PoorPRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

© Diocese of Lincoln

	SITE NAME:	Church of All Saints, Lincoln Road, Holton cum Beckering	Rural parish church of CI3 origin with contributions of CI4 and CI5. Later CI9 restorations by GG Scott. South slope
	DESIGNATION:	Listed Place of Worship grade I	of nave roof is tingled, with some slipped slates. The church was the subject of heritage crime in 2017 and a temporary solution has been put in place. Some urgent repairs have been undertaken.
	CONDITION:	Fair	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1064035	Contact: Imogen Newcombe 07387 524030

© Historic England

1,11,1	SITE NAME:	Church of St Michael, East Torrington, Legsby	Victorian church of 1848-50 by SS Teulon. Widespread roof defects to all slated roofs, with nave requiring re- roofing. The west elevation has widespread open joints. Some missing eaves stones to north of nave. Evidence of water ingress internally. Some gutters to the nave south slope have become detached.
	DESIGNATION:	Listed Place of Worship grade II	
	CONDITION:	Very bad	
	PRIORITY CATEGORY:	A (A)	siepe have become detached.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1359514	Contact: Ben Robinson 07823 327796

© Historic England

ons took
from C12 to C15. Restorations took 1868. The church has been subject to ere are concerns over the asbestos
bestos aisles which
r staining in d there is a
outh west
rside of the . The
to develop
r

© Diocese of Lincoln



		-
SITE NAME:	Church of St Thomas, Main Road, North Willingham	Parish church with C14 fabric. The is evidence of high-level structural movement in the nave, with associated internal
DESIGNATION:	Listed Place of Worship grade II	cracking. The tower suffers from damp, and there is significant loss of plasterwork. Sarking boards within the
CONDITION:	Very bad	nave and chancel have rotted and further are decaying, with signs of wet-rot and water ingress. The bell chamber
PRIORITY CATEGORY:	A (New entry)	shows signs of beetle and worm attack. The church suffers
OWNER TYPE:	Religious organisation	from poor ventilation, with the walls and stone floors damp and slippery underfoot, with signs of efflorescence. The
LIST ENTRY NUMBER:	1064043	Parochial Church Council are currently reviewing potential

© Historic England

funding avenues. Contact: Imogen Newcombe 07387 524030

Contact: Imogen Newcombe 07387 524030

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Andrew, Main Street, Kirkby cum Osgodby, Osgodby	Parish church with fabric from early C13, early C14, C15 and 1790, undergoing restoration in 1891, 1900 and 1923. Roughly coursed ironstone rubble, squared coursed
	DESIGNATION:	Listed Place of Worship grade II*	limestone and ironstone. The church was the subject of heritage crime in 2019. Roof repairs have been undertaken.
	CONDITION:	Poor	The Nave roof appears to be nearing its serviceable life. There are some isolate areas of deep pocket erosion to
in the second	PRIORITY CATEGORY:	C (A)	the tower, friable stone and previous cementitious
	OWNER TYPE:	Religious organisation	pointing. Considerable vegetation growth to the chancel. The PCC are keen to effect repairs.
	LIST ENTRY NUMBER:	1166092	Contact: Imogen Newcombe 07387 524030
Historic England			

© Historic England

AK &	SITE NAME:	Church of St Margaret, Usselby, Osgodby	Two cell C14 church, restored C18 and C19. Nave, chancel and west bellcote. Random rubble ironstone with
	DESIGNATION:	Listed Place of Worship grade II	gauged brick window arches, roofs are diminished random slate. Timber window frames, cast iron casements and
	CONDITION:	Poor	plain leaded glazing. Numerous issues including ivy growth blocked and slipped downpipes, localised defects and
	PRIORITY CATEGORY:	A (A)	cracks and broken glass. Roofs appear to be in good order
	OWNER TYPE:	Religious organisation	but bellcote at risk of immediate loss. The closure process has started.
and a second	LIST ENTRY NUMBER:	1166119	Contact: Ben Robinson 07823 327796

© Historic England

	SITE NAME:	Church of St John the Baptist, High Street, Scampton	Dating from C14, the church had a major restoration by Bodley & Garner 1876-7. This would appear to be the date of the nave and chancel roof structures. The church lies on the edge of the village and is surrounded by a churchyard, part of which contains the graves of 64 airmen, maintained by the Commonwealth War Graves Commission. A Listee Places of Worship Roof Repair Fund grant was completed in 2017. A further phase of work has also been completed. Repairs are still required to the tower roof and funds have
	DESIGNATION:	Listed Place of Worship grade II*	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1359492	been secured to undertake this work.
			Contact: Ben Robinson 07823 327796

© Historic England

	SITE NAME:	Church of St Mary, Church Lane, Stow	A parish church of lofty proportions which includes the transepts and crossing of an early collegiate church, dating
	DESIGNATION:	Listed Place of Worship grade I, SM	from C11. The nave and chancel are C12. There was a major restoration by JL Pearson in 1850-67 when the chancel vaulting was reconstructed. Several re-roofing
	CONDITION:	Poor	projects have recently been completed. The church is damp having suffered water ingress through defective roof
	PRIORITY CATEGORY:	C (C)	coverings and underground drainage for many years.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1146624	Contact: Ben Robinson 07823 327796

© Historic England

SITE NAME: Hengiform monument 260m north west of Honeypot Cottage				
	Hengiform monument 260m north west of Honeypot Cottage			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1017020				
CONDITION: Extensive significant problems TREND: Declining				
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No				
OWNER TYPE: Private CONTACT: Ben Robinson 07823 327796	5			
SITE NAME: Owmby Roman settlement, Fillingham				
SITE NAME: Owmby Roman settlement, Fillingham DESIGNATION: Scheduled Monument, part in RPG grade II				
, , ,				
DESIGNATION: Scheduled Monument, part in RPG grade II LIST ENTRY NUMBER: 1004922				

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Ash Hill long barrow in Swinhope Park, Swinhop	e	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013886
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Cromwell's Grave, a Neolithic long barrow 300r	n west of Hoe Hill Fa	rm, Swinhope
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013885
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 450m west of Hoe Hill Fa	rm, Swinhope	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013901
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 380m south west of Thor	ganby House, Thorga	nby
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020359
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Neolithic long barrow 300m ESE of Walesby To	p Farm, Walesby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013914
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Gainsborough Riverside, Gainsborough		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Clive Fletcher 07771502052
SITE NAME:	Gainsborough Town, Gainsborough		
DESIGNATION:	Conservation Area, 39 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Liz Mayle 01427675144
SITE NAME:	Market Rasen		
		NEW ENTRY ?:	No
DESIGNATION:	Conservation Area, 45 LBs		NU
designation: condition:	Conservation Area, 45 LBs Poor	TREND:	Improving

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

LINCOLNSHIRE / NOTTINGHAMSHIRE

WEST LINDSEY / BASSETLAW

	SITE NAME:	Torksey Viaduct over River Trent, Trent Side, Torksey	Tubular iron girder railway bridge and viaduct, 1849. Designed by John Fowler. The main span was strengthened
ALL THE PARTY	DESIGNATION:	Listed Building grade II*	in 1897. Disused since the closure of the line in 1959 and decayed slowly thereafter. Repairs carried out in 2015 to
Charles and the second	CONDITION:	Fair	enable a public footpath to be constructed along one side of the viaduct. The footpath opened in April 2016. The
THE XALLET	OCCUPANCY:	N/A	other side is unused and some further repairs are requi
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	1359456	Contact: Rosemary Thompson 07768 215540

1117

©

NORTH EAST LINCOLNSHIRE (UA) 13.50 - 100 and the

	SITE NAME:	Grimsby Haven Lock and Dock Wall 58 metres Long adjoining to West, Lock Hill	Lock basin and quayside wall by John Rennie, built 1798/1799. This lock separated the tidal haven from the Humber estuary, creating the first dock at Grimsby.
	DESIGNATION:	Listed Building grade II*	Vaulted dock walls were employed here; an innovative form of dock construction later replicated at Hull and
Lot 1	CONDITION:	Poor	Grimsby on a much larger scale. The lock and dock walls
- THE WELL	OCCUPANCY:	Vacant/not in use	are now partly covered by spoil. Localised collapse, open joints, missing and broken bollards and railings signal the
© E.Ravenscroft/ENGIE/NELC	PRIORITY CATEGORY:	C (C)	neglect suffered by this historic structure.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1379856	Contact: Ben Robinson 07823 327796
	SITE NAME:	The Grimsby Ice Factory, Gorton Street, Grimsby	Ice production works dating from 1900-1910 that served the Grimsby fishing fleet, facilitating its development and
	SITE NAME: DESIGNATION:		the Grimsby fishing fleet, facilitating its development and international renown during the C20. The factory closed in
		Gorton Street, Grimsby	the Grimsby fishing fleet, facilitating its development and international renown during the C20. The factory closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to
	DESIGNATION:	Gorton Street, Grimsby Listed Building grade II*	the Grimsby fishing fleet, facilitating its development and international renown during the C20. The factory closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. The loss of roof coverings and non- secure openings has exposed the interior, including
	designation: condition:	Gorton Street, Grimsby Listed Building grade II* Very bad	the Grimsby fishing fleet, facilitating its development and international renown during the C20. The factory closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. The loss of roof coverings and non- secure openings has exposed the interior, including extensive wooden floors, to increasing levels of weather
	DESIGNATION: CONDITION: OCCUPANCY:	Gorton Street, Grimsby Listed Building grade II* Very bad Vacant/not in use	the Grimsby fishing fleet, facilitating its development and international renown during the C20. The factory closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. The loss of roof coverings and non- secure openings has exposed the interior, including



SITE NAME:	Former Heavy Anti-Aircraft Gun Site, Keelby Road, Stallingborough	Second World War and early post-War Heavy Anti- Aircraft gun site. One of only six of the surviving 5.25 inch HAA sites known nationally. The site is overgrown and
DESIGNATION:	Listed Building grade II*	suffers from vandalism. The concrete structures are deteriorating.
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1403222	Contact: Ben Robinson 07823 327796

© E.Ravenscroft/ENGIE/NELC

SITE NAME:	Civil War earthwork fort 350m north east of Walk Farm, Irby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007735
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH EAST LINCOLNSHIRE (UA) / NORTH LINCOLNSHIRE (UA)

SITE NAME:	Premonstratensian priory chapel 170m south we	st of Priory Farm, W	est Ravendale
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1019867
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Central Area, Grimsby		
DESIGNATION:	Conservation Area, 25 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Louise Jennings 01472 324266
SITE NAME:	Central Sea Front, Cleethorpes		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Louise Jennings 01472 324266
SITE NAME:	Holme Hill, Grimsby		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Louise Jennings 01472 324266
SITE NAME:	The Kasbah		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Louise Jennings 01472 324266
SITE NAME:	Victoria Mills, Grimsby		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Louise Jennings 01472 324266
SITE NAME:	Wellow, Grimsby		
DESIGNATION:	Conservation Area, 27 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating

NORTH LINCOLNSHIRE (UA)

	< / /		
	SITE NAME:	United Reformed Church, Chapel Lane, Barton	Chapel and adjoining manse erected by the Barton Independent congregation in 1806. It is the oldest surviving
M P	DESIGNATION:	Listed Building grade II*, CA	Barton Independent chapel in Lincolnshire, with its original seating still intact. Constructed of locally-made red brick
The second second	CONDITION:	Very bad	with rubbed brick and stone dressings. The roof of the chapel is clad in Welsh slate. The manse is occupied and
	OCCUPANCY:	Vacant/not in use	being repaired. The chapel is in very bad condition and is
	PRIORITY CATEGORY:	A (A)	currently without a use. A condition survey has been produced.
	OWNER TYPE:	Private	
ngland	LIST ENTRY NUMBER:	1051598	Contact: Imogen Newcombe 07387 524030

© Historic Eng

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH LINCOLNSHIRE (UA)

	SITE NAME:	Hibaldstow Mill and walls to mill pond and wheel race, Ings Lane, Hibaldstow	Combined wind and watermill, 1802, by James Middleton of Hibaldstow. Some repairs undertaken, but further work required to both exterior and interior.
	DESIGNATION:	Scheduled Monument and Listed Buildings - I grade II*; I grade II	
I I I MAR	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
© Historic England Archive	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1008528 and 1083709; 1162093	Contact: Ben Robinson 07823 327796
	SITE NAME:	Manor Farmhouse, East Halton Road, North Killingholme	Medieval, C17 to C19 manor house on a scheduled moated site. Exceptional multi-period survival for this
	DESIGNATION:	Listed Building grade II*, SM	region. The roof was repaired in 1980, but little has been done since and the interior is propped with scaffolding. A
	CONDITION:	Very bad	feasibility study has been completed.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
© Historic England Archive	LIST ENTRY NUMBER:	1346854	Contact: Ben Robinson 07823 327796
	SITE NAME:		Parish church with spacious west tower of four stages. The lower section of tower and circular stair turret date from
	DESIGNATION:	Listed Place of Worship grade I	CII, when it was the main body of the church with a chancel to the east. Walls contain large squared ashlars,
	CONDITION:	Very bad	herringbone rubble and reused Roman gritstone. CI4-CI5

	DESIGNATION:	Listed Place of Worship grade I	chancel to the east. Walls contain large squared ashlars,
	CONDITION:	Very bad	herringbone rubble and reused Roman gritstone. C14-C top stage to the tower. Some urgent repairs have been
for the second	PRIORITY CATEGORY:	C (C)	undertaken but work to the tower and roofs is still
	OWNER TYPE:	Religious organisation	required.
	LIST ENTRY NUMBER:	1161801	Contact: Ben Robinson 07823 327796

© Historic England

	SITE NAME:	Church of the Holy Trinity, Temperance Avenue, Messingham	The church's external envelope has been largely rebuilt around its medieval core: the west tower in 1784 by Thomas Bell following collapse of the spire, the chancel,
THE REAL	DESIGNATION:	Listed Place of Worship grade II*	nave and aisles in 1817-1818 by Edward Wilson. The short elevations of the south aisle signal that at one time the aisle
	CONDITION:	Poor	roof was dual pitched and a box gutter located at the foot of the clerestory. The main roofs are covered in
	PRIORITY CATEGORY:	D (D)	Westmorland slate, laid to diminishing courses; they leaked
	OWNER TYPE:	Religious organisation	and required renewal. National Lottery Heritage Fund grant-aided works are now complete, and further repair
	LIST ENTRY NUMBER:	1346835	work is expected.
© Historic England			Contact: Ben Robinson 07823 327796
1 Miles	SITE NAME:	Church of All Saints, Church Lane, Saxby All Saints	Late C13 church rebuilt between 1845 and 1849 by George Gilbert Scott in the Decorated style, with tower

Listed Place of Worship grade II,

Religious organisation

rebuilt by Neville in 1873. The National Lottery Heritage Fund Grants for Places of Worship scheme funded roof repairs in 2013, of which have since been completed. A further phase of works is still needed in order to repair the tower masonry.

Contact: Imogen Newcombe 07387 524030

© Historic England

PRIORIT	Y	CAI	EGC	DRIE2

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

DESIGNATION:

CONDITION:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

CA

Fair

C (C)

1103702

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH LINCOLNSHIRE (UA)

	SITE NAME:	Church of St Nicholas, Church Lane, Ulceby	Large church with tall C13 spire. C15 nave roof and clerestory. Restorations in C19. Previous roof leaks had left
	DESIGNATION:	Listed Place of Worship grade I	the interior damp. The tower masonry is eroded and there is some loose high-level stonework. The church has been
	CONDITION:	Poor	subject to heritage crime. National Lottery Heritage Fund Grants for Places of Worship grant-aided repairs were
	PRIORITY CATEGORY:	D (D)	completed in early 2020. Repairs are still required to the tower, and the Parochial Church Council are in receipt of
	OWNER TYPE:	Religious organisation	structural engineering advice for this, alongside added
	LIST ENTRY NUMBER:	1227927	support from the Diocesan Historic Churches Support Officer.
			Officer.

© Historic England

Contact: Imogen Newcombe 07387 524030

SITE NAME:	Money Field Roman site, Dragonby		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005224
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Heavy Anti-aircraft gunsite 220m east of West M	arsh Cottage, Barrov	w upon Humber
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020024
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Yarborough Camp large univallate hillfort, Croxt	on	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016427
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Romano-British settlement near Staniwells Farm,	Hibaldstow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005221
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman settlement, Kirmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005206
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Romano-British villa at Mount Pleasant Farm, Kir	ton in Lindsey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013627
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / NORTH LINCOLNSHIRE (UA)

SITE NAME:	North Garth moated site and associated enclosures, North Killingholme		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007815
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Axholme Carthusian Priory and post-Dissolution g	arden earthworks,	Melwood Park, Owston Ferry
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1017487
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tim Allen 07770 610214
SITE NAME:	Kinaird motte and bailey castle, Owston Ferry		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017556
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Old Winteringham Roman settlement, Winteringh	am	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005243
CONDITION:	Extensive significant problems TREND: Declining		Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Howe Hill bowl barrow, Wootton		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1009346		1009346
CONDITION:	Generally unsatisfactory with major localised TREND: Declining problems		Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman site 400yds (370m) north east of Worlaby	Church, Worlaby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005233
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Crowle		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Eddie Rychlak (LPA) 01724 297000
SITE NAME:	Winterton		
DESIGNATION:	Conservation Area, 25 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Eddie Rychlak (LPA) 01724 297000

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

WEST NORTHAMPTON	SHIRE (UA)		
	SITE NAME:	8, 8a, 9 and 9a, George Row	The Northampton & County Club occupies one of the
APPE L	DESIGNATION:	Listed Building grade II*, CA	town's most important buildings. Its medieval vaulted cellars survived the Great Fire of Northampton in 1675.
AL DE LET	CONDITION:	Poor	The building later became Northampton's first Infirmary. There is a notable C17 staircase and ceiling and a C19
	OCCUPANCY:	Occupied/in use	billiards room. The building suffers from cumulative
	PRIORITY CATEGORY:	C (C)	alterations, under-use and lack of repair. A condition survey and options appraisal were completed with Historic
	OWNER TYPE:	Private	England funding in 2014. Historic England discussed a grant for selected priority repairs with Club management, but
	LIST ENTRY NUMBER:	1039667	this was not progressed.
© Historic England			Contact: Ben Robinson 07823 327796
L	SITE NAME:	Old Church of St John the Baptist, Matton Lane, Boughton	Ruined church of Norman origin with CI4 and CI5 material. Nave, chancel and aisles partially survive but have
	DESIGNATION:	Scheduled Monument	suffered as a result of extensive, deep rooted ivy growth in the past and suffer, more generally, from antisocial
	CONDITION:	Poor	behaviour. Historic England grant aided vegetation removal and stone consolidation in 2017-18. St John's was
	OCCUPANCY:	N/A	subsequently removed from the register. There have been
	PRIORITY CATEGORY:	C (C)	some localised mortar failures. Vandalism in May 2019 prompted re-addition to the register. Historic England has
	OWNER TYPE:	Religious organisation	worked with church representatives to consider the problems.
© Historic England	LIST ENTRY NUMBER:	1003894	Contact: Hannah Reynolds 07557 827971
	SITE NAME:	Terrace gardens, Castle Ashby Park, Castle Ashby	Terraced gardens, 1864, to north and east of Castle Ashby House. Designed by WB Thomas with decorated Blashfield
And a second discovery of the	DESIGNATION:	Listed Building grade II*, RPG grade I, part in CA	terracotta balustrading and other features. Balustrade in very poor state and has largely been dismantled or lost. Large sections of replacement with Jesmonite artificial
	CONDITION:	Very bad	replica. End bastion section and fountains still intact. Condition survey and structural investigation have been
	OCCUPANCY:	N/A	undertaken to inform ongoing discussion on management
	PRIORITY CATEGORY:	A (A)	actions.
	OWNER TYPE:	Private	
© Historic England	LIST ENTRY NUMBER:	89676	Contact: Dale Dishon 07889 808148

	SITE NAME:	Church of St Mary, Horton, Hackleton	Former church, C13 and C14 fabric, repaired and altered c1720 at the expense of the Earl of Halifax. There is a
1 Martin 2	DESIGNATION:	Listed Building grade II*	known history of seasonal structural movement, and internal plasterwork has fallen as a result. Rainwater goods
	CONDITION:	Poor	are in very bad condition. There are areas of poor stonework, such as to the tower and areas affected by
The sub-	OCCUPANCY:	Vacant/not in use	leaking gutters. The chancel roof covering is in poor
Contraction of the second	PRIORITY CATEGORY:	C (C)	condition, with slipped and missing slates. The Church Commissioners have approved a pastoral scheme for sale
	OWNER TYPE:	Religious organisation	of the building and part of the churchyard.
© Historic England	LIST ENTRY NUMBER:	1190174	Contact: Dale Dishon 07889 808148

Mars.	
	NIL CONTRACT
And Tel	

	SITE NAME:	Astwell Castle Farm (Gatehouse Tower), Helmdon	The three-storey gatehouse tower with stair and garderobe turrets. Originally formed the east range of a
	DESIGNATION:	Scheduled Monument	moated courtyard house and now represents the sole standing remains of the C15 house incorporated into an
	CONDITION:	Poor	early CI7 manor house. A condition survey, commissioned by the owner, has identified repair needs.
	OCCUPANCY:	Vacant/not in use	The partially collapsed north store roof has been
	PRIORITY CATEGORY:	B (B)	temporarily covered. The historic buildings, with farmyard and around 30 acres of surrounding land are being
	OWNER TYPE:	Private	marketed.
	LIST ENTRY NUMBER:	1003902	Contact: Ben Robinson 07823 327796

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



SITE NAME:	Stable block and outbuildings at Wakefield Lodge, Potterspury	Stable block, outbuildings and attached walls and gate piers. Mid C18. Outbuildings now dwelling. Stable block has been
DESIGNATION:	Listed Building grade II*, RPG grade II	re-roofed and is watertight. Interior finishes in poor condition. Repair works been carried out to the exterior, including replacement of eroded stone window cills and
CONDITION:	Fair	repair/redecoration of some of the timber windows. Further repairs anticipated.
OCCUPANCY:	Part occupied/part in use	ra the repairs and pated.
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1190683	Contact: Dale Dishon 07889 808148

© Historic England

	SITE NAME:	Former Weedon Barracks, Outer Walls to Magazine Enclosure, Bridge Street, Weedon Bec	Defensive walls with lean-to structures at east and west end of enclosure, early CI9. Red brick in Flemish style with intermediate piers. Part of an extraordinary Napoleonic military complex. Brickwork is in poor condition; both
	DESIGNATION:	Listed Building grade II*	lean-to structures have suffered partial collapse. Vegetation is damaging the brickwork further. The site has been
	CONDITION:	Poor	underused for many years and was left in a poor conditic The magazine enclosure is now in the same ownership as
	OCCUPANCY:	N/A	the adjacent depot enclosure. Historic England is grant
	PRIORITY CATEGORY:	A (A)	aiding the repair of the Depot's north east bastion; work is due to complete in 2022.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1342983	Contact: Amanda White 0121 625 6890



Weedon Bec DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY. N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Private © Historic England LIST ENTRY NUMBER: 1076513

SITE NAME:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER

Canal enclosure walls to north, military complex. Brickwork is in poor condition and Bridge Street, Lower Weedon, vegetation growth is damaging. The whole site was underused for many years and was left in poor condition. It was sold in early 2013 and is now home to various businesses. The owner is considering further development. A condition survey of non-beneficial elements was carried out with Historic England grant aid c. 2015. Bastion repairs were identified as a priority. Historic England awarded funds for the repair of the north east bastion in 2021; work is due to complete in 2022.

Early C19 structure part of an extraordinary Napoleonic

Contact: Amanda White 0121 625 6890

Early C19 structure part of an extraordinary Napoleonic Canal enclosure walls to south, Weedon Bec military complex. Brickwork is in poor condition and vegetation growth is damaging. The whole site was Listed Building grade II* underused for many years and was left in poor condition. It was sold in early 2013 and is now home to various businesses. The owner is considering further development. A condition survey of non-beneficial elements was carried out with Historic England grant aid c. 2015. Bastion repairs were identified as a priority. Historic England awarded funds for the repair of the north east bastion in 2021; work Private is due to complete in 2022. 1281680 Contact: Amanda White 0121 625 6890

© Historic England

SITE NAME:	Outer wall and north west bastion, Weedon Bec
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1076512

Poor

N/A

A (A)

Early C19 structure part of an extraordinary Napoleonic military complex. Brickwork is in poor condition and vegetation growth is damaging. The whole site was underused for many years and was left in poor condition. It was sold in early 2013 and is now home to various businesses. The owner is considering further development. A condition survey of non-beneficial elements was carried out with Historic Éngland grant aid c. 2015. Bastion repairs were identified as a priority. Historic England awarded funds for the repair of the north east bastion in 2021; work is due to complete in 2022.

Contact: Amanda White 0121 625 6890

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY.

PRIORITY CATEGORY:

LIST ENTRY NUMBER



© Historic England

© Historic England

SITE NAME:	Outer wall and south east bastion, Bridge Street, Lower Weedon, Weedon Bec	Early C19 structure part of an extraordinary Napoleonic military complex. Brickwork is in poor condition and vegetation growth is damaging. The whole site was
DESIGNATION:	Listed Building grade II*	underused for many years and was left in poor condition. It was sold in early 2013 and is now home to various
CONDITION:	Poor	businesses. The owner is considering further development. A condition survey of non-beneficial elements was carried
OCCUPANCY:	N/A	out with Historic Éngland grant aid c. 2015. Bastion repairs
PRIORITY CATEGORY:	A (B)	were identified as a priority. Historic England awarded funds for the repair of the north east bastion in 2021; work
OWNER TYPE:	Private	is due to complete in 2022.
LIST ENTRY NUMBER:	1342980	Contact: Amanda White 0121 625 6890



	SITE NAME:	Outer walls and north east bastion, Bridge Street, Lower Weedon, Weedon Bec	Early C19 structure part of an extraordinary Napoleonic military complex. Brickwork is in poor condition and vegetation growth is damaging. The whole site was
	DESIGNATION:	Listed Building grade II*	underused for many years and was left in poor condition. It was sold in early 2013 and is now home to various
	CONDITION:	Poor	businesses. The owner is considering further development. A condition survey of non-beneficial elements was carried
	OCCUPANCY:	N/A	out with Historic Éngland grant aid c. 2015. Bastion repairs
	PRIORITY CATEGORY:	E (B)	were identified as a priority. Historic England grant aided repairs are and due to complete in 2022.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1281700	Contact: Amanda White 0121 625 6890



© Historic England



OWNER TYPE: Private LIST ENTRY NUMBER: 1203443 Contact: Amanda White 0121 625 6890 Gate arch, early C17, constructed of limestone ashlar. SITE NAME: Gate arch south of south front Some open joints and stonework decay. There is a gradual of Manor House, Winwick Manor, Winwick loss of decorative details from natural erosion. Repairs were planned but have not been implemented. DESIGNATION: Listed Building grade II* CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: D (D) OWNER TYPE: Private

© Historic England



SITE NAME:	Church of St Andrew, Church Walk, Billing, Billing	Church dating fr was partially reb
DESIGNATION:	Listed Place of Worship grade I, CA	1867 by EF Law. with the exception church was subject
CONDITION:	Fair	Lottery Heritage spring 2019 to re
PRIORITY CATEGORY:	C (C)	complete. Som
OWNER TYPE:	Religious organisation	Vegetation remo The Parochial Cl
LIST ENTRY NUMBER:	1039722	Diocese to addr

West lodge, Weedon Depot,

Listed Building grade II*

Part occupied/part in use

Weedon Bec

Fair

C (C)

1278961

Bridge Street, Lower Weedon,

rom CI2 with CI3-I4 phases. The church built after 1759, with further restoration in . Constructed from course stone rubble ion of the north chapel which is ashlar. The ject to heritage crime in 2018. A National e Fund Heritage Grant was awarded in repair the roofs. and these works are now e localised repointing is still required. oval has highlighted some areas of decay. Church Council are working with the ress these issues.

Lodge/gatehouse, early C19, to an extraordinary

Napoleonic military complex. The whole site was underused for many years and was left in poor condition.

Sold in early 2013 and now home to various businesses. All

structural repairs completed, and external steps reinstated. Building fully weathertight and in partial use. Bastion repairs

funds for the repair of the north east bastion in 2021; work

were identified as a priority. Historic England awarded

is due to complete in 2022.

Contact: Imogen Newcombe 07387 524030

Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

© Peterborough DAC

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Church of St John the Baptist, Church Road, Boddington	C13, C14 and C17 church, comprising aisled nave, chance south transept and C14 three-stage west tower, all of
1 december 1	DESIGNATION:	Listed Place of Worship grade I	squared coursed ironstone. The nave roof of C19 has C14 corbels. Ground drainage is poor, church is damp
30	CONDITION:	Poor	internally. A condition survey has been produced. Windo masonry repairs were completed 2020 but repairs to drainage channel and stonework elsewhere are required.
H	PRIORITY CATEGORY:	C (C)	
110	OWNER TYPE:	Religious organisation	The PČC are working with Diocese Historic Church Support Officer to source further funding.
	LIST ENTRY NUMBER:	1041214	Contact: Hannah Reynolds 07557 827971

© Historic England

800

	SITE NAME:	Church of St Peter and St Paul, Church Lane, Chacombe	C14 church. Probably all one build but some later windows. C14 wall painting depicting Crucifixion of St
di na	DESIGNATION:	Listed Place of Worship grade I, CA	Peter; possibly more undiscovered. Generally well maintained but the building has been subject to heritage crime. Several roofs require permanent repair solutions
IT IT IT	CONDITION:	Very bad	and rainwater goods require attention. On-going struct issues to the south aisle require urgent repairs, chancel movement is being monitored. PCC keen to effect rep
	PRIORITY CATEGORY:	A (A)	
-	OWNER TYPE:	Religious organisation	and are working with the Diocesan Historic Church Support Officer to explore funding options.
nd	LIST ENTRY NUMBER:	1041190	Contact: Hannah Reynolds 07557 827971

© Historic England

	SITE NAME:	Church of All Saints, Church Lane, Clipston	Early C13 church with monuments to the Buswells. The tower was rebuilt in the restoration of 1884-85. Aisled
	DESIGNATION:	Listed Place of Worship grade I	nave, south aisle and vestry have tall three-light windows and plain glass. A C20 extension provides chapel, kitchen
	CONDITION:	Poor	and toilets. The church is damp internally. Listed Places Worship Roof Repair Fund grant repairs were complet in 2018. The external drainage is defective, and repairs
	PRIORITY CATEGORY:	C (C)	
TI-SA	OWNER TYPE:	Religious organisation	required to the rainwater goods. A recent steeplejack survey revealed concerns about spire stonework. The
	LIST ENTRY NUMBER:	1067033	parish are continuing to work with the Diocesan Historic Churches Support Officer.
			Charches Support Officer.

© Historic England

Contact: Imogen Newcombe 07387 524030

	Lane, Cold Higham church with C13 tower, a saddleba	A small mixed ironstone/ limestone/ brownstone parish church with C13 tower, a saddleback stage added in the	
and the second	DESIGNATION:	Listed Place of Worship grade II*	C14, with stone slate roof. Chancel rebuilt 1880-82. Structural movement to the east end has occurred leaving
	CONDITION:	Poor	the masonry vulnerable to water ingress and there is erosion of all ironstone; this is a particular concern at high
	PRIORITY CATEGORY:	C (C)	level on the tower. PCC is keen to effect repairs and
	OWNER TYPE:	Religious organisation	exploring funding options with Diocesan Historic Church Support Officer.
	LIST ENTRY NUMBER:	1190319	Contact: Hannah Reynolds 07557 827971

© Historic England



SITE NAME:	Church of All Saints, Church Lane, Croughton	Parish church of coursed limestone rubble built C12 to C14. The interior contains an important series of C14 wall
DESIGNATION:	Listed Place of Worship grade I, CA	paintings; scenes form 'Life of Christ' in the aisles and fragments of a 'Last Judgement' at east end of the nave. The church has been subject to heritage crime. Roof repairs
CONDITION:	Poor	completed 2021 but wall paintings need conservation and porch roof suffers slipped slates. The congregation is keen
PRIORITY CATEGORY:	C (A)	to effect repairs and are fundraising.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1192503	Contact: Hannah Reynolds 07557 827971

© J. Brecon/Diocese ofPeterborough

	CA	church has been subject to heritage
NDITION:	Poor	completed 2021 but wall paintings porch roof suffers slipped slates. T
ORITY CATEGORY:	C (A)	to effect repairs and are fundraisin
NER TYPE:	Religious organisation	
ENTRY NUMBER:	1 1 9 2 5 0 3	Contact: Hannah Reynolds 07557

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Denys, Clipston Road, Kelmarsh	C14 Church with C19 work by JK Colling. There is extensive cracking to the east end of the chancel, the east
	DESIGNATION:	Listed Place of Worship grade II*	window and to the east and north elevations of the north aisle, however various repairs were undertaken in 2020.
- ARE CAR	CONDITION:	Very bad	The interior shows further signs of movement with the S John Hanbury wall monument now open jointed. Rainwater goods require maintenance, yet gutters have recently been repaired. The Parochial Church Council an keen to effect further repairs, with further funding require
Second Second	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
Alexandra and a second second	LIST ENTRY NUMBER:	1370062	for the reinstatement of the east window and works to the longstanding cracks in the north chapel.
			longstanding cracks in the north chapel.

Contact: Imogen Newcombe 07387 524030

	SITE NAME:	Church of All Saints, Daventry Road, Norton	A large ironstone church, with C13 tower. Its C16 and C17 history is connected with the demolished Norton Hall.
	DESIGNATION:	Listed Place of Worship grade I	Internally a fine C18 three-storey west screen with various monuments. South aisle stained glass by Willement c1850.
	CONDITION:	Poor	The condition of high-level stonework is very bad, and below ground rainwater disposal is not functional and
	PRIORITY CATEGORY:	C (C)	requires repair. The condition of the windows is poor with
	OWNER TYPE:	Religious organisation	broken glass and deteriorating stonework. The interior is damp and roofing works are required. The Parochial
	LIST ENTRY NUMBER:	1076507	Church Council are keen to effect repairs and are engaged with the Diocese.
 h			

Contact: Imogen Newcombe 07387 524030

1 and	SITE NAME:	Church of St Michael, Stowe IX Churches	Church, with tall Saxon west tower, nave, chancel, north and south aisles, south porch. Body of church rebuilt in
	DESIGNATION:	Listed Place of Worship grade I	1639 and again in 1859. The render to the tower is in poor condition and has detached in several places. A National
	CONDITION:	Poor	Lottery Heritage Fund grant project for repairs to the tower, roof, rainwater goods & masonry awarded, post- contract defects awaiting resolution.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
Miles	LIST ENTRY NUMBER:	1343558	Contact: Hannah Reynolds 07557 827971

© Historic England

© Historic England

© J. Brecon/Diocese ofPeterborough

	SITE NAME:	Church of St Mary, Thenford	Parish church of late C12, early C14 and Perpendicular.
	DESIGNATION:	Listed Place of Worship grade I, CA	There is C15 stained glass in the north aisle. The north porch was rebuilt 1885. The church has been subject to heritage crime in 2016, 2018 and 2019. The interior
	CONDITION:	Very bad	suffered severe water ingress prior to a temporary felt ro being fitted. There are issues relating to the below groun drainage and the interior is suffering from damp. The
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	congregation is keen to effect repairs and is working with the Historic Churches Support Officer at the Diocese to
- And a state of the state of t	LIST ENTRY NUMBER:	1371503	source funding do so.
			Contact: Hannah Reynolds 07557 827971

© Historic England



SITE NAME:	Church of St John the Baptist, High Street South, Tiffield	Church. C13 and C14. Restored, south aisle and porch added 1859 by EF Law; further restoration and rebuilding 1873 by HC Vernon. High level stonework repairs are needed to the tower. Repairs are required to the nave and chancel roof; drainage channel and the rainwater goods are largely inadequate. Works to address roof repairs, rainwater goods and drainage due to complete summer 2022.
DESIGNATION:	Listed Place of Worship grade II*, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1040916	Contact: Hannah Reynolds 07557 827971

© Historic England

PRIORITY	CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / WEST NORTHAMPTONSHIRE (UA)

	SITE NAME:	Church of St Peter and St Paul, Church Lane, Watford	Church, CI4 origin with CI5 and CI8 work. Restored CI9. Tower and drainage repairs, jointly funded by
	DESIGNATION:	Listed Place of Worship grade I	Historic England and the National Lottery Heritage Fund, completed late 2013. Nave and Chancel roof and
PI C	CONDITION:	Poor	rainwater goods repairs completed in 2019. Further drainage and low level masonry repairs are required. There
	PRIORITY CATEGORY:	C (C)	is some damp internally and some areas of flooring may
	OWNER TYPE:	Religious organisation	require specialist cleaning. The church has been the victim of heritage crime. Fundraising continues for final phase of
	LIST ENTRY NUMBER:	1077018	repairs.
			Contact: Hannah Reynolds 07557 827971

© Historic England

SITE NAME:	Multivallate hillfort at Hunsbury Hill		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012150
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman villa, Chipping Warden and Edgcote		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006616
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman villa south east of Cosgrove Hall, Cosgrove	9	
DESIGNATION:	Scheduled Monument, 2 CAs	LIST ENTRY NUMBER:	1003874
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Univallate hillfort 250m south and a bowl barrow 3	300m south east of	Castle Dykes Farm, Farthingstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018857
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman villa north of Road Hill Farm, Harpole		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003901
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Two bowl barrows and a henge 600m east of Mill	Hill Farm, Naseby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012148
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / WEST NORTHAMPTONSHIRE (UA) / NORTH NORTHAMPTONSHIRE (UA)

	LANDS / WEST NORTHAMPTONSHIRE (OA) / NORTH NORTH		
SITE NAME:	Site of Bannaventa, Norton / Whilton / Long Bu	ckby	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003879
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman villa south east of Stokegap Lodge, Stoke	Bruerne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003878
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Former World War I National Filling Factory, B	anbury, Warkworth	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1409811
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Castle Hill ringwork, Weedon Lois, Weston and	l Weedon	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010252
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Rachel Jordan 0121 625 6854
SITE NAME:	Old Stratford		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Mandy Lumb (LPA) 01327 322262
SITE NAME:	St Crispin Hospital, Upton, Upton		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Jane Jennings (LPA) 01604 837637

NORTH NORTHAMPTONSHIRE (UA)

	Ш.,	K	III	II	I
H		4	10		III
		-	II 00 1	And a state of the second s	And and an other states of the state of the

SITE NAME:	Apethorpe Palace, Apethorpe	Country house, late C15/early C17. Following a
DESIGNATION:	Listed Building grade I, RPG grade II	Compulsory Purchase Order in 2004 by the Secretary of State, Historic England took possession of the site and carried out a programme of repairs over the following
CONDITION:	Fair	decade. The building was sold on to private buyers in 2015 and they have been carrying out a comprehensive
OCCUPANCY:	Part occupied/part in use	programme of further repairs and renovations, including
PRIORITY CATEGORY:	F (F)	reversal of harmful mid-C20 alterations by the school. Phase I of the repair programme has been completed and
OWNER TYPE:	Private	Phase II is expected to be completed in late 2022. Public access for 50 days a year is managed by English Heritage.
LIST ENTRY NUMBER:	1040083	Contact: Dale Dishon 07889 808148

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument NP RPG SM
- UA Unitary Authority WHS World Heritage Site

*	SITE NAME:	Ashton Mill, Oundle Road, Ashton	Former C18 -C19 water-powered corn mill, adapted circa 1900 to form electricity-generating and water-pumping
In the second second	DESIGNATION:	Listed Building grade II*, CA	station for the Rothschild estate at Ashton village and Ashton Wold. Housed the Dragonfly Museum until 2001,
	CONDITION:	Fair	since unoccupied. Historic England grant aided localised
	OCCUPANCY:	Vacant/not in use	urgent repairs of building fabric in 2014/15 and urgent mill machinery repairs in early 2016. The building remains
	PRIORITY CATEGORY:	C (C)	unused and suffers occasional heritage crime.
	OWNER TYPE:	Commercial company	
listoric England	LIST ENTRY NUMBER:	1040278	Contact: Dale Dishon 07889 808148
	SITE NAME:	Barnwell Castle, Barnwell	The ruins of a fortified residence dating to the mid CI3,
	DESIGNATION:	Listed Building grade I, RPG grade II, SM, CA	built on a quadrangular plan with corner towers and a gatehouse entrance. Despite the demolition of its internal buildings in the late C17, Barnwell Castle survives in a
	CONDITION:	Poor	remarkably complete form. In recent years vegetation growth and deterioration of the local limestone, especially
	OCCUPANCY:	N/A	where wall cores are exposed, has led to fabric loss and
	PRIORITY CATEGORY:	E (C)	vulnerability to localised collapse. A five-year programme of repair work commenced in 2021, completing repairs to
	OWNER TYPE:	Private	southeast tower and gatehouse in 2021.
listoric England	LIST ENTRY NUMBER:	1294426	Contact: Tim Allen 07770 610214
	SITE NAME:	Lilford Hall, Lilford-cum- Wigsthorpe	Country house, 1635 and 1656, extended and altered in C18 by Henry Flitcroft and in C19 and early C20. The roo
	DESIGNATION:	Listed Building grade I	covering is in poor condition leading to water ingress and distress to the upper storeys. The front bays require
	CONDITION:	Poor	structural attention. Some repairs were carried out by the previous owners but further works are required, notably t
	OCCUPANCY:	Part occupied/part in use	the roofs and stables. The property has now transferred to
	PRIORITY CATEGORY:	C (C)	new ownership and discussions are being held with Histor England.
Standard States	OWNER TYPE:	Private	
listoric England	LIST ENTRY NUMBER:	1189554	Contact: Dale Dishon 07889 808148
	SITE NAME:	Dovecote, circa 160 metres north east of Newton Field Centre, Newton and Little Oakley	An exceptionally large late C16/early C17 dovecote of squared coursed limestone, closely laid in tight courses, with stone slate roof and hipped lanterns. Central coping ornamented with Tresham trefoils. Two low round-heade
I THE	DESIGNATION:	Listed Building grade I, SM	and chamfered doors; one retains its heavy double-rebated door. Interior has around 2000 nesting boxes in two lofty
	CONDITION:	Poor	chambers. Masonry is generally in fair order albeit there ar
and a second second	OCCUPANCY:	Vacant/not in use	a few isolated missing stones. Roof slates and lanterns are in poor condition. Some patch roof repairs undertaken in
	PRIORITY CATEGORY:	C (C)	2015 but re-roofing is required. Subject to occasional vandalism.

© Historic England

	SITE NAME:	TE: Dovecote on site of manor house and gardens, Wakerley	
	DESIGNATION:	Scheduled Monument, part in CA	collapse of the occurred and the courses above
	CONDITION:	Poor	instability to the livestock is con
	OCCUPANCY:	N/A	INVESTOCK IS COIT
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	1003626	Contact: Hanna

Private

1192042

of rectangular stone dovecote, CI6-CI8. boxes with alighting steps inside. Partial internal east wall nesting boxes has the wall to the north has collapsed to a few ground level. There is evidence of structural ne south and east elevations. It is likely that ntributing to the displacement of stonework.

nah Reynolds 07557 827971

Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

Е

OWNER TYPE:

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH NORTHAMPTONSHIRE (UA)



SITE NAME:	Church of St Nicholas, Main Street, Bulwick	Mainly C13 and C14 church, restored 1870 by Slater & Carpenter. Rainwater goods are in poor condition and
DESIGNATION:	Listed Place of Worship grade I, CA	many leak badly, with some sections broken. Maintenance or repair is urgently needed. Some gutters are blocked with grass and vegetation. External drainage and water dispersal
CONDITION:	Poor	in general is poor, with ineffective drainage channels contributing to dampness internally. Some evidence of
PRIORITY CATEGORY:	C (C)	leaks to the nave and south aisle roofs, and the chancel
OWNER TYPE:	Religious organisation	ridge is also letting in water. Sources of grant funding for repairs are being explored,
LIST ENTRY NUMBER:	1191576	Contact: Hannah Reynolds 07557 827971

© J. Brecon/Diocese ofPeterborough



	SITE NAME:	Church of St Peter, Main Road, Lowick	Church with fabric from early C14, late C14 and C15 for the Greene family of Drayton House. There are a number
	DESIGNATION:	Listed Place of Worship grade I, CA	of monuments within the church, the earliest to Sir Rolf Greene who died in 1417. The building was restored 1869 and 1887. Repointing required, particularly to the western
	CONDITION:	Poor	elevation of the south transept. The church was subject to heritage crime in 2020. The Historic Churches Support
	PRIORITY CATEGORY:	A (A)	Officer at Peterborough Diocese is supporting the Parish
OWNER TYPE:	OWNER TYPE:	Religious organisation	to find sources of funding for repairs.
-	LIST ENTRY NUMBER:	1040265	Contact: Hannah Reynolds 07557 827971

© J. Brecon/Diocese ofPeterborough

	SITE NAME:	Church of St Peter, Berrister Place, Raunds	Large urban church of C12-C14, with wall paintings. There is history of movement at the west end, with the northwest
	DESIGNATION:	Listed Place of Worship grade I	corner of the north aisle settling and the south aisle requiring tying by 2013. Stained-glass panels had been
	CONDITION:	Poor	temporarily removed, with the wall paintings now conserved. A National Lottery Heritage Fund Grants for
	PRIORITY CATEGORY:	D (C)	Places of Worship grant was awarded mid-2017 for
	OWNER TYPE:	Religious organisation	localised underpinning and repairs. A structural roof timber in the nave is at high-risk of failure, yet a solution for its repair has been identified. The Diocesan Historic Churches
	LIST ENTRY NUMBER:	1192206	repair has been identified. The Diocesan Historic Churches Support Officer is providing advice.
			each each each each each each each each

© Diocese of Peterborough

Contact: Imogen Newcombe 07387 524030

	SITE NAME:	Church of St Leonard, Rockingham, Rockingham	Church of C13 origin. Rebuilt in 1660-70 after it was destroyed in the Civil War. Restored in C19. The church
	DESIGNATION:	Listed Place of Worship grade II*, SM, CA	has a history of structural movement with notable movement occurring in 2014 and continuing through 2018 and 2019. By 2020 the east wall and south wall of the
	CONDITION:	Poor	chapel were invested with ivy and chapel roof coverings were in poor condition. Historic England Covid 19
	PRIORITY CATEGORY:	C (F)	Emergency HAR funds were awarded in 2020 to
	OWNER TYPE:	Religious organisation	investigate movement, remove ivy and undertake roof repairs. This work has been completed. St Leonard's may
	LIST ENTRY NUMBER:	1286197	be a candidate for removal from the Register later in 2022
			Contact: Amanda White 0121 625 6890

© Historic England



SITE NAME:	Church of St Lawrence, Church Street, Stanwick	Church, of C13 and C14 and restored 1858. Regular coursed and squared coursed limestone with ashlar spire.
DESIGNATION:	Listed Place of Worship grade I	New roof structure and covering added to nave in 1858. The nave has a steep gabled roof with Collyweston slates
CONDITION:	Poor	laid in diminishing courses, castellated ashlar parapet and gable finial. The Collyweston slates are now reaching the
PRIORITY CATEGORY:	C (C)	end of their serviceable life and require replacement to
OWNER TYPE:	Religious organisation	prevent water ingress. The parish are working with the Diocesan Historic Churches Support Officer to explore
LIST ENTRY NUMBER:	1192232	sources of grant funding.

© Historic England

Contact: Imogen Newcombe 07387 524030

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH NORTHAMPTONSHIRE (UA) / NOTTINGHAM, CITY OF (UA)

SITE NAME:	Site revealed by aerial photography north of Easton Lodge, Easton Maudit		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003876
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman villa, Little Addington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003630
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Wellingborough Town Centre		
DESIGNATION:	Conservation Area, 93 LBs, SM	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	John Udall (LPA) 01933 231925

NOTTINGHAM, CITY OF (UA)

© For use

	SITE NAME:	County House, 23, High Pavement	Townhouse, with possible C15 or C16 origins, rebuilt between 1728 and 1733, remodelled and extended in 1833
	DESIGNATION:	Listed Building grade II*, CA	to form judges' lodgings, subsequently converted to offices in 1922, and further extended in 1930 and 1949. The
	CONDITION:	Very bad	building is in a very bad condition. The bressumer beam in the north west wing has failed and there is defective
	OCCUPANCY:	Vacant/not in use	plasterwork throughout. One of the staircases has failed.
	PRIORITY CATEGORY:	B (B)	Listed Building consent for a new use has been granted. The owner is working with Nottingham City Council on
	OWNER TYPE:	Commercial company	future plans. The building is unoccupied.
se in HAR register	LIST ENTRY NUMBER:	1270805	Contact: Clive Fletcher 07771502052

Durce: Historic	SITE NAME:	Dovecote 600m east of Home Farm	Early C18, restored c1970. There are issues of widespread spalling to overall brickwork, notably the gables. The west
	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	gable's parapet and kneeler shows vertical cracking. The parapet is in poor condition, with cement repointing and loss of the original copings. The roof shingles are
	CONDITION:	Poor	deteriorating, creating holes in the roof and the possibility of water ingress. The basal courses on the north elevation
	OCCUPANCY:	N/A	are in poor condition, with biological growths and heavily
	PRIORITY CATEGORY:	F (New entry)	eroded mortar joints. Nottingham City Council commissioned a condition survey to inform future repairs
	OWNER TYPE:	Local authority	and are keen to undertake these.
	LIST ENTRY NUMBER:	1016950 and 1270435	Contact: Imogen Newcombe 07387 524030



© Mr David Kennedy. Sou England Archive

> Church of St Augustine, Apostle of England, Woodborough Road SITE NAME: DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1406263

C20 church by John Sidney Brocklesby, begun in 1921 but never finished church displays, an accomplished architectural design and interior fixtures and fittings of significant quality, notably the organ of 1740, stained glass and rood screen. Pitched roofs above the domes and the tower were never built. Roof coverings have been problematic and internal plasterwork containing asbestos had fallen on several occasions. Asbestos was removed in 2016 and the asphalt covered domes and flat roof were treated with a resin-based waterproofing system in 2021. The concrete domes remain unrepaired.

Contact: Imogen Newcombe 07387 524030

PRIORITY CATEGORIES

© Peter Rogan Associates Ltd

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NOTTINGHAM, CITY OF (UA)

L	SITE NAME:	Woodborough Road Islamic Social Centre	Baptist church 1893, by Watson Fothergill of Nottingham. Internally the building is in a poor condition, with damp,
	DESIGNATION:	Listed Place of Worship grade II	mould and active dry rot throughout the building. The ceiling has large holes, and there are signs of structural
	CONDITION:	Poor	movement above the central archway and of the mezzanine joists. The tower roof has missing slates and
	PRIORITY CATEGORY:	A (New entry)	deteriorated coverings, which is permitting water ingress.
	OWNER TYPE:	Mixed, multiple owners	The Pakistan Centre and the Nottingham School of Boxing are eager to undertake a repair programme. Further advice
	LIST ENTRY NUMBER:	1255289	on repairs and grant funding is being sought.
			Contact: Imogen Newcombe 07387 524030

© © Mrs Mollie Toy. Source Historic England Archive



	SITE NAME:	Capitol Bingo and Social Club, Churchfield Lane	Cinema, now Zionist Church. 1936-37 by Reginald Cooper. Red brick and reconstituted stone construction.
	DESIGNATION:	Listed Place of Worship grade II	Auditorium retains most of its original features. The roof is in poor condition and needs recovering, rainwater dispersal
	CONDITION:	Poor	also needs to be addressed. Some emergency repairs to stabilise the buildings condition were completed with an
	PRIORITY CATEGORY:	A (A)	Historic England Repair Grant. Water continues to
	OWNER TYPE:	Religious organisation	penetrate the interior is causing damage to the remarkable fibrous plasterwork. A National Lottery Heritage Fund
	LIST ENTRY NUMBER:	1246786	Development Phase project has commenced, it is hoped a Delievery Phase project will follow.

Contact: Hannah Reynolds 07557 827971

Grand urban parish church. Mostly CI5 with later CI9

restoration by George Gilbert Scott. There are several

areas requiring urgent masonry repair. In addition, several

roofs require repair and rainwater goods need attention to

prevent water ingress and decay. The tower roof has recently been repaired. A Grant for Places of Worship was

awarded in 2014 by the National Lottery Heritage Fund,

© Historic England



LIST ENTRY NUMBER:

1255013

© Historic England

enabling nave roof covering repairs. The Parochial Church Council are keen to effect repairs with grant support from Historic England's Covid-19 Emergency Heritage at Risk Religious organisation Response Fund. LIST ENTRY NUMBER: 1342118 Contact: Imogen Newcombe 07387 524030 SITE NAME: A large church in the heart of the city of Nottingham. C12 Church of St Peter, St Peter's origins though mainly C15 in date with some C13 and C14 work. Later C19 and C20 additions. A National Lottery Gate, Nottingham Listed Place of Worship grade I, DESIGNATION: Heritage Fund award enabled the nave and south aisle CA roofs to be recovered in 2020. The north aisle slated roof leaks and requires urgent repair. The chancel slate roof is suffering from nail fatigue. The Parochial Church Council CONDITION: Poor PRIORITY CATEGORY: C (C) are keen to explore potential funding avenues for repair programmes. OWNER TYPE: Religious organisation

© Historic England



SITE NAME:	Church of St Peter, Hartley Road, Nottingham	Church, 1812 by Henry Moses Wood in the Early English and Decorated styles. The present building replaced an
DESIGNATION:	Listed Place of Worship grade II	earlier building, of which little survives. The chancel is later and dates to 1872. The roof coverings generally are in poor
CONDITION:	Poor	condition and water ingress has caused damage to the interior decoration. Broken and leaking rainwater goods
PRIORITY CATEGORY:	C (C)	have saturated the stonework. The church has been the
OWNER TYPE:	Religious organisation	subject of antisocial behaviour. Grant funding being sought.
LIST ENTRY NUMBER:	1270769	Contact: Hanna Good 07825 318060

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Hanna Good 07825 318060

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / NOTTINGHAM, CITY OF (UA)

SITE NAME:	Alfreton Road/Gamble Street, Nottingham		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Bulwell, Nottingham		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Canning Circus, Nottingham		
DESIGNATION:	Conservation Area, 25 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Hine Hall, Nottingham		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Mapperley Hospital, Nottingham		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	New Lenton, Nottingham		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Nottingham Canal, Nottingham		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Old Market Square, Nottingham		
DESIGNATION:	Conservation Area, 126 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Medium	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Old Sneinton, Nottingham		
designation:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	Sneinton Market, Nottingham		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / NOTTINGHAM, CITY OF (UA) / ASHFIELD

SITE NAME:	Star Buildings, Nottingham		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	The Arboretum, Nottingham		
DESIGNATION:	Conservation Area, 39 LBs, 2 RPGs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	The Lace Market, Nottingham		
DESIGNATION:	Conservation Area, 119 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Thomas Street (LPA) 0115 8764149
SITE NAME:	The Station, Nottingham		
	-		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Thomas Street (LPA) 0115 8764149

NOTTINGHAMSHIRE

ASHFIELD

SITE NAME:	Wansley Hall manorial site, Selston		
DESIGNATION:	Scheduled Monument, LB grade II, part in CA	LIST ENTRY NUMBER:	1019869
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796



© Historic England

	problems		TREND:	Declining	
ITY:	Collapse		NEW ENTRY?:	No	
	Private		CONTACT:	Ben Robinson 07823 327796	
	SITE NAME:	Annesley Hall, Annesley		mains of CI3 motte and bailey castle. CI7	
	DESIGNATION:	Registered Park and Garden grade II*, 5 LBs, 2 SMs	terraces around the Hall with late C19 garden, pleasure grounds and walled garden. Site at risk due to lack of cohesive management, condition of key listed buildings ar		
	CONDITION:	Generally satisfactory but with significant localised problems	internal and external development pressures. The Hall (Grade II) suffered a serious fire in May 2015. An options appraisal and parkland management plan have been completed to help inform a sustainable future for the site and secure its conservation. Potentially harmful development proposals have been submitted for land to		
A Company	VULNERABILITY:	High			
	TREND:	Stable			
	NEW ENTRY?:	No		England has provided advice.	
	OWNER TYPE:	Mixed, multiple owners			
	LIST ENTRY NUMBER:	1001077	Contact: Erika Di	az Petersen 0121 625 6879	

SITE NAME: S	Sutton in Ashfield Church and Market Place		
DESIGNATION: (Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Duty Planner (LPA) 01623 457388

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

BASSETLAW



SITE NAME Gateway and walls from Manor Farm to churchyard, Torksey Street DESIGNATION: Listed Building grade I CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private

1276407

Darlton

Very bad

1212465

Hodsock

Fair

C (C)

Private

1187689

A (A)

LIST ENTRY NUMBER:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Limestone gateway and brick walls, mid C16. Stonework on the south face is very eroded, particularly on the decorative plaques and lintel above the gateway, all which requires repair. The north face (including the plaques) is less eroded, but subsequent repointing is still required. The mortar joints to the brick wall are now deeply recessed and in need of repointing. The ivy growth on the walls is extensive and is displacing the stone copings.

Contact: Hanna Good 07825 318060

© Historic England



	SITE NAME:	Worksop Priory gatehouse, Cheapside, Worksop	Gatehouse, early C14, with a slightly later south porch containing what is believed to be the only surviving English
I	DESIGNATION:	Listed Building grade I, CA	medieval 'walk through' shrine. The gatehouse requires comprehensive repair, as demonstrated by a condition
	CONDITION:	Poor	survey funded by grant aid from Historic England. An initial body of repairs focusing on the shrine, funded by a Repair
	OCCUPANCY:	Vacant/not in use	Grant for Places of Worship, was completed summer
	PRIORITY CATEGORY:	C (C)	2016. Further repairs are needed to the interior, exterior stonework, rainwater goods and statues. Options for
	OWNER TYPE:	Religious organisation	future uses and funding possibilities are being explored.
	LIST ENTRY NUMBER:	1045028	Contact: Hanna Good 07825 318060

© Historic England



© Historic England

© Historic England



Church of St Oswald, Main Street, Dunham-on-Trent DESIGNATION: Listed Building grade I Very bad Vacant/not in use PRIORITY CATEGORY: B (A) Private 1370101 LIST ENTRY NUMBER:

Hodsock Priory Gatehouse,

Listed Building grade I

Vacant/not in use

Church of St Giles, Main Street,

Listed Building grade II*

Vacant/not in use

Religious organisation

junction between nave and chancel is open to the elements, allowing water to penetrate the building. Rainwater goods are defective, Self-set trees in the valley gutter between the north vestry and chancel. There are blocked hoppers elsewhere, and smashed windows. Residentiall conversion under discussion. Contact: David Walsh 0121 625 6888 Former church, C15 in origin, but with the exception of the

Former church, probably early C13. The church was largely

rebuilt in 1855 by Hine and Evans, with the chancel rebuilt

in 1863. The building has suffered from widespread

structural movement with vertical cracks to several elevations. The tiled roofs have numerous defects and the

tower all rebuilt in 1862 by TC Hine. There are serious concerns about the tracery work to the very large belfry openings, and the structural integrity is severely compromised in several places. There are localised stonework defects elsewhere. The slated roofs, gutters and downpipes are all in very poor condition. Water ingress is evident in numerous places. Conversion to a two bed dwelling has been approved. Roof repairs are underway.

Contact: Ben Robinson 07823 327796

Early C16 gatehouse and bridge. Imposing entrance to later house with gardens. Whilst the house is occupied and used as a wedding venue, the gatehouse is unused and requires comprehensive maintenance. Historic England has encouraged the development of options for reuse of the gatehouse combined with full repair of the structure. Following the commissioning of a condition survey, essential repairs have now been carried out. A bid to the National Lottery Heritage Fund for an educational and restoration project has been considered.

Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)


Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

_. . . .

- 1	SITE NAME:	East stable and outbuildings at Shireoaks Hall, Thorpe Lane, Shireoaks	Early C18 stable and outbuildings, possibly by Sir Thomas Hewitt, located to north west of the Hall, and set in C17 and early C18 formal landscape. A pair to the West Stable.	
	DESIGNATION:	Listed Building grade II*, RPG grade II*, SM, 2 CAs	There are many slipped, broken and displaced slates on the roof. Masonry is open jointed, cracked and displaced particularly in the vicinity of former downpipes. The	
	CONDITION:	Very bad	building is shrouded in vegetation and a self-set sapling is growing through the roof. The outbuildings are in a ruinous	
	OCCUPANCY:	Vacant/not in use	state. Historic England is encouraging the local authority to	
	PRIORITY CATEGORY:	A (A)	consider options to secure this site.	
) Historic England	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1045054	Contact: Amanda White 0121 625 6890	
A	SITE NAME:	Shireoaks Hall, Thorpe Lane, Shireoaks	Country house, circa 1600 with later alterations, set in remains of C17 and early C18 gardens. The hall has been	
	DESIGNATION:	Listed Building grade II*, RPG grade II*, SM, 2 CAs	much altered historically, including the removal of the storey. There is some significant cracking and loose masonry at high level; there is a risk of imminent colla	
	CONDITION:	Very bad	Roofs are evidently in poor condition and some ceiling plaster has failed. Rainwater goods appear to be ineffective	
	OCCUPANCY:	Vacant/not in use	and undersized. The north elevation has been shrouded in	
A G T AL	PRIORITY CATEGORY:	A (A)	vegetation. Historic England is encouraging the local authority to consider options to secure this site.	
	OWNER TYPE:	Private	, ,	
) Historic England	LIST ENTRY NUMBER:	1370408	Contact: Amanda White 0121 625 6890	
	SITE NAME:	West stable at Shireoaks Hall, Thorpe Lane, Shireoaks	Early C18 stable and outbuildings, possibly by Sir Thomas Hewitt, located to north west of the Hall, and set in C17	
	DESIGNATION:	Listed Building grade II*, RPG grade II*, SM, 2 CAs	and early C18 formal landscape. A pair to the East Stable. There are many slipped, broken and displaced slates on the roof. Past slate repairs are now failing, and the north ridge	
	CONDITION:	Very bad	is missing. Masonry is open jointed, cracked and displaced	
到这个不可以	OCCUPANCY:	Vacant/not in use	particularly in the vicinity of former downpipes. The stable and outbuildings are shrouded in vegetation. Historic	
the section of the P	PRIORITY CATEGORY:	A (A)	England is encouraging the local authority to consider options to secure this site.	
	OWNER TYPE:	Private		
) Historic England	LIST ENTRY NUMBER:	1045055	Contact: Amanda White 0121 625 6890	
			Fault C19 and way which lies on an axis of Saulhy Hall	



© Historic England

E Godson. Source: Historic nive	SITE NAME:	The Old Grammar School, Number 4, and attached Wall, Gate and Steps, Lincoln Road, Tuxford	Former school dating to 1669, with late C18 reorganisation. The building has not been maintained and is actively deteriorating, with considerable structural issues within both the timbers and brickwork. Rainwater goods
	DESIGNATION:	Listed Building grade II*, CA	are corroded, defective and blocked with detritus. The window timbers and dormer cheeks are failing, with
	CONDITION:	Poor	potential detachment. Internal and boundary brickwork has partially collapsed in places, creating significant voids, with
	OCCUPANCY:	Part occupied/part in use	some areas of masonry unsupported and at risk of further
	PRIORITY CATEGORY:	A (New entry)	collapse. There are ongoing issues of asbestos, damp, mould and beetle infestation.
	OWNER TYPE:	Community interest group	
	LIST ENTRY NUMBER:	1224333	Contact: Imogen Newcombe 07387 524030

PRIORITY CATEGORIES

© Mr Derek F England Archiv

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no Е
 - obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / BASSETLAW

	SITE NAME:	Methodist Church, Grove Street	Church and meeting rooms of 1880 by Bellamy and Hardy. Localised ceiling plaster failures in 2014 lead to the closure
	DESIGNATION:	Listed Place of Worship grade II, CA	of the main part of the building. Investigations took place in 2015 and repairs followed in 2020 with grant support from Historic England's Covid-19 Emergency Heritage at Risk
	CONDITION:	Fair	Response Fund. Loose plaster was secured and fallen elements reinstated. Below ground drainage in the vicinity
	PRIORITY CATEGORY:	F (F)	of the stair tower was renewed in 2020. Funds were
	OWNER TYPE:	Religious organisation	separately raised for internal redecorations in 2021. The first service in over five years occurred in summer 2021.
	LIST ENTRY NUMBER:	1393069	Monitoring is ongoing.
ects			Contact: Imogen Newcombe 07387 524030

© Soul Archite

, 11	SITE NAME:	Church of All Saints, Torksey Street	Parish church. C10, early C13, c.1300, C14, C15, C16, C17, restored 1894, nave roof restored 1902. Possible on-
	DESIGNATION:	Listed Place of Worship grade I	going movement of aisles away from nave, requires structural investigation/monitoring. North aisle west
	CONDITION:	Poor	window has been removed for safety and repair; south aisle west window vulnerable due to movement. Roof
	PRIORITY CATEGORY:	C (New entry)	finishes are coming to the end of their serviceable life,
	OWNER TYPE:	Religious organisation	water ingress threatens structural timbers. Rainwater goods and drainage require attention. Isolated pockets of
	LIST ENTRY NUMBER:	1233879	deep stone erriosion. The Parish and 'Friends' Group are keen to effect repairs and are seeking funding.
			······································

© Historic England



© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

	SITE NAME:	Parish Church of St Michael the Archangel, Bridgegate, West Retford	Large urban church with tall decorative tower and spire. Earliest sections date to C14 but church extensively restored C19 and extended C20. Masonry is generally in
	DESIGNATION:	Listed Place of Worship grade II*, CA	fair condition but there are poor parapet abutment details and various localised repairs are evident. There is significant erosion of jamb stones and jointing to south porch arch
	CONDITION:	Poor	and gable. There is potential water ingress and damp internally. A Listed Places of Worship Roof Repair Fund
	PRIORITY CATEGORY:	C (C)	grant enabled roofs and rainwater goods to be repaired in
	OWNER TYPE:	Religious organisation	2016. Further repair programmes are required.
	LIST ENTRY NUMBER:	1370357	Contact: Imogen Newcombe 07387 524030

Church of St Swithun,

Religious organisation

II*, CA

Poor

A (A)


1370346

Church, CI3 origins, with major rebuilding work in the 1650s following the collapse of the central tower. The Churchgate, East Retford church has been suffering from many leaks and was subject Listed Place of Worship grade to heritage crime in 2018. Nave and aisle roof coverings were repaired with a National Lottery Heritage Fund grant in 2010 and a second phase of repairs to the transept roofs and tower was completed in 2014. Overhauling works to the chancel roof has recently been undertaken. Further masonry repairs, alongside interior works, are still required and these will be carried out as funding avenues allow.

Contact: Imogen Newcombe 07387 524030

Contact: Imogen Newcombe 07387 524030

© Historic England



© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / BASSETLAW

	SITE NAME:	Church of St Cuthbert and St Mary, Worksop Priory, Priorswell Road, Worksop	Augustinian priory, now Parish church. C11, C12, C13, C14, restored 1845-49 by R. Nicholson. C20 additions including Crossing Tower, sanctuary and east end by
	DESIGNATION:	Listed Place of Worship grade I, CA	Laurence King 1966-74. Regular and irregularly coursed ashlar and squared rubble; slate and flat roofs. The church building has suffered from Heritage Crime. Roof to the
	CONDITION:	Poor	crossing tower has dislodged panels to spire skirt and damage has occurred to timber substrate. Glazed panels
	PRIORITY CATEGORY:	A (New entry)	are letting water in. Structural concerns over condition of
	OWNER TYPE:	Religious organisation	tower. Various open joints. Issues identified with drainage. The PCC are seeking funding for repairs.
rl Andrews, Soul Architects Ltd	LIST ENTRY NUMBER:	1156758	Contact: Hanna Good 07825 318060

-	SI
	D
	С
	PI
	С
	L

Simple church of C12 and C13 origins now consisting Church of St Giles, Piper Lane, ITE NAME: principally of a combined nave and chancel with bellcote to Carburton the west and mono-pitch vestry to the north side of the ESIGNATION: Listed Place of Worship grade II* chancel. Externally the church has a cementitious render coat and there is evidence of structural movement to the CONDITION: Poor east end gable. Nave roof covering appears functional. RIORITY CATEGORY: C (C) Vestry roof and rainwater goods are in need of repair. Water ingress internally has caused damage to the WNER TYPE: Religious organisation plasterwork and ceiling panels. The church was formally closed in October 2018. IST ENTRY NUMBER: 1370105

© Historic England

© Car



SITE NAME:

DESIGNATION:

CONDITION


CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England



Poor

C (New entry)

1224198

Religious organisation

Fair

Church of St Peter and St Paul, North Green, East Drayton

Listed Place of Worship grade I,

Parish church of CI3 origin with CI5 and CI9 fabric, restored 1885 by G. Somers Clarke Junior. Dressed coursed rubble and ashlar, with angle buttresses, tower, nave, aisles, north vestry, south porch and chancel. The nave and chancel roofs require extensive repair due to signs of nail fatigue. The rainwater goods require repair, redecoration and clearing of detritus. As a result, the interior is suffering from high levels of damp. The Parochial Church Council are keen to effect repairs and are investigating potential funding avenues.

Contact: Imogen Newcombe 07387 524030

Contact: Imogen Newcombe 07387 524030

work. Restored in 1857 by the Ecclesiastical Commissioners. Heavily embattled and described by

A parish church of late C12 origins with C13 and C15

externally. Extensive works recently completed to nave roof and medieval timber structure under a National

Pevsner as a 'very complete' late medieval church

© Mr Gerard Sheridan, Source: Historic England Archive

D

Е

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ΪA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / BASSETLAW

	SITE NAME:	Church of All Saints, Church Street, Misterton	Church, with fabric dating from the C13 but with C14, C15, C17, C19 and C20 contributions. The tower and
	DESIGNATION:	Listed Place of Worship grade I	spire was rebuilt in 1847-8 and there was a partial restoration elsewhere. The north aisle has suffered from
	CONDITION:	Poor	structural movement and defective ground drainage is suspected. Further investigation into the cause of the
	PRIORITY CATEGORY:	C (C)	movement is needed before repairs are implemented.
	OWNER TYPE:	Religious organisation	North aisle buttresses are unstable in places and there is a need for repointing once movement has stabilised. The
	LIST ENTRY NUMBER:	1302717	tower stonework at belfry stage is open jointed and localised repair is needed.
			io canoca i opani io neococa

© Historic England



SITE NAME:	Church of St Matthew, Main Street, Normanton on Trent	Parish church C13-C15 constructed of coursed rubble and ashlar. Restored C19 and C20. The church was subject to
DESIGNATION:	Listed Place of Worship grade II*	heritage crime in 2019 and the interior suffered from subsequent water ingress. The interior remains damp. The
CONDITION:	Poor	tower roof is nearing the end of its life. Some pointing and isolated masonry repairs are required. The church
PRIORITY CATEGORY:	D (D)	undertook a programme of repairs in early 2020 and is
OWNER TYPE:	Religious organisation	keen to undertake further repairs once potential funding avenues are available.
LIST ENTRY NUMBER:	1233792	Contact: Hanna Good 07825 318060

Contact: Ben Robinson 07823 327796

© Historic England

	SITE NAME:	Church of All Saints, Church Street, South Leverton	Parish church. CI2, CI3, CI4, CI5. Chancel restored by Ewan Christian, 1868; remainder restored by C.
	DESIGNATION:	Listed Place of Worship grade II*	east end of the chancel away from nave and within the tower, which require structural investigation/ monitoring The rainwater goods and drainage also require attention, sections are failing or missing, low-level damp and moss internally. Isolated pockets of deep stone and pointing
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1275880	erosion. Parish are keen to effect repairs.
			Contact: Imogen Newcombe 07387 524030

© Historic England

「北京の一下」で

SITE NAME:	Roman fort and a section of Roman road 350m north west of Holly House Farm, Scaftworth		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018529
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796



© Historic England

	Private		CONTACT:	Ben Robinson 07823 327796	
	SITE NAME:	Shireoaks Hall, Shireoaks	The core of an extensive late C17 and early C18 landscape		
	DESIGNATION:	Registered Park and Garden grade II*, 4 LBs, part in SM, 2 CAs	park with early C17 gardens and a grand late C17 wate feature. The site is deteriorating, in multiple ownership with buildings at risk and a lack of strategic managemen External development has had an impact upon its setti and appreciation.		
	CONDITION:	Extensive significant problems			
	VULNERABILITY:	High			
	TREND:	Declining			
	NEW ENTRY ?:	No			
	OWNER TYPE:	Private, multiple owners			
	LIST ENTRY NUMBER:	1000367	Contact: Erika Di	iaz Petersen 0121 625 6879	

SITE NAME:	Worksop		
DESIGNATION:	Conservation Area, 60 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Michael Tagg (LPA) 01909 533427

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

BROXTOWE

© Historic Engla

	SITE NAME:	Willoughby Almshouses and adjoining Boundary Wall, Church Lane, Cossall	Group of eight almshouses with two projecting wings built in 1685 for George Willoughby. Brick construction with plain tile roofs. There are some open joints in the copings
	DESIGNATION:	Listed Building grade II*, CA	on the gables and at parapet level. The houses have been boarded up and would benefit from better ventilation. The
	CONDITION:	Poor	interiors are suffering from damp and damp related issues.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1247951	Contact: Rosemary Thompson 07768 215540

	SITE NAME:	Kimberly Road, Nuthall Wright and formerly in the garden of Nuthall Terr	A Gothic summerhouse, circa 1759, probably by Thomas Wright and formerly in the garden of Nuthall Temple.
	DESIGNATION:	Listed Building grade II*, CA	Coursed and square rubble and brick with ashlar dressings and pantile roof. Significant vegetation growth around and
	CONDITION:	Poor	over the roofs into the upper gutters. Loss of roof covering has permitted structural timber decay and localised
	OCCUPANCY:	Vacant/not in use	instability in the decayed masonry, particularly in the rear
	PRIORITY CATEGORY:	C (C)	gable masonry which is at risk of collapse if continued water ingress is not prevented.
and the	OWNER TYPE:	Private	
gland	LIST ENTRY NUMBER:	248 77	Contact: Hanna Good 07825 318060

SITE NAME:	Greasley Castle, Greasley		
DESIGNATION:	Scheduled Monument, 3 LBs	LIST ENTRY NUMBER:	1020943
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Eastwood		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Francesca Siviter 0115 9173080
SITE NAME:	Kimberley		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Francesca Siviter 0115 9173080
SITE NAME:	Nuthall		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Francesca Siviter 0115 9173080

PRIORITY CATEGORIES

- implemented. C Slow decay; no solution agreed.

 A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 D Slow decay; solution agreed but a provide the solution agreed but not yet implemented.
 D Slow decay; solution agreed but a provide the solu use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

NOTTINGHAMSHIRE / DERBYSHIRE

BROXTOWE / EREWASH

	SITE NAME:	Bennerley Viaduct, Awsworth Road (part located in Erewash Borough), Awsworth	An exceptional iron railway viaduct, 1878-9 c.500m long. Disused and unmaintained for decades. An application to the National Heritage Lottery Fund in 2017 for repairs and
Alla Alla Alla	DESIGNATION:	Listed Building grade II*	a pathway across the viaduct was unsuccessful. Historic England subsequently awarded a two-stage grant in early
	CONDITION:	Poor	2019; development work and essential repairs followed in 2019 and 2020. Work temporarily stopped due to Covid-
	OCCUPANCY:	N/A	19. Historic England Heritage Stimulus funding enabled the
	PRIORITY CATEGORY:	F (F)	reinstatement of parapets. Remedial re-pointing is required. The western approach has been reinstated and
	OWNER TYPE:	Charity (non-heritage)	the viaduct has been decked.
© Historic England	LIST ENTRY NUMBER:	40437	Contact: Amanda White 0121 625 6890

NOTTINGHAMSHIRE

GEDLING


	SITE NAME:	Newstead Abbey and adjoining boundary wall, Newstead Park, Newstead	Priory cl 165, post-Dissolution country house, now a visitor attraction and museum, set in formal gardens and parkland. Home of the poet Lord Byron. By 2018, stone
	DESIGNATION:	Listed Building grade I, RPG grade II*	fragments were falling from the adjoining priory church ruin and the area was cordoned off. Historic England awarded a two-stage grant in 2018 and repairs were completed in
to an Andreas	CONDITION:	Poor	2020. Roof coverings of the main house are at the end of their effective lives. Leaks are addressed as they occur, but
A AN	OCCUPANCY:	Occupied/in use	re-slating is now required. Development work is required
A AN	PRIORITY CATEGORY:	C (C)	as an initial step in planning for repairs.
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1265325	Contact: Amanda White 0121 625 6890



LIST ENTRY NUMBER:

1265301

© Historic England



Nottingham Corporation Water Department. The timber porch is sited on the east elevation and is approached via balustraded steps. Mansard roof carried on balusters. Renovated in 2004. Significant scarf joints evident to principle posts. Several structural timbers have suffered significant deterioration with some having suffered a considerable loss of section. Modern paint finishes are trapping moisture. Rainwater goods are failing and allowing water to penetrate the structure. A Historic England Development grant was awarded in Spring 2022.

Contact: Hanna Good 07825 318060



SITE NAME:	Church of the Good Shepherd, Thackery's Lane, Woodthorpe	Significant modern concrete church designed on Litur Movement principles with stained glass windows by P
DESIGNATION:	Listed Place of Worship grade II*	Reyntiens. The church is suffering severe concrete decay problems requiring urgent specialist attention to avoid loss
CONDITION:	Poor	of historic fabric. An extensive programme of grant- assisted repairs, jointly funded by Historic England and
PRIORITY CATEGORY:	A (A)	National Lottery Heritage Fund, successfully renewed
OWNER TYPE:	Religious organisation	complex roofing and ensured concrete facing panels are safe and weather tight. Mullions and glazing require further
LIST ENTRY NUMBER:	1376603	extensive repairs, Historic England technical staff visited in late 2021.

© Historic England

late 2021.

Contact: Amanda White 0121 625 6890

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / GEDLING / MANSFIELD / NEWARK AND SHERWOOD

SITE NAME:

CONDITION:

OWNER TYPE:

SITE NAME:	Round Hill, Lambley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006379
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Papplewick Pumping Station, Papplewick, Papplewick	k / Ravenshead	
DESIGNATION:	Scheduled Monument, 5 LBs, part in RPG grade II	LIST ENTRY NUMBER:	1006373
designation: Condition:	Scheduled Monument, 5 LBs, part in RPG grade II Generally satisfactory but with significant localised problems	LIST ENTRY NUMBER:	1006373 Declining
	Generally satisfactory but with significant localised		

MANSFIELD

© Historic England

	1

Large urban church in central Mansfield of 1855-56 and Church of St John the later north porch c1906. Following completion of Evangelist, St John Street, Mansfield development work the nave roof was repaired with funds from the National Heritage Lottery Fund in 2016. The Listed Place of Worship grade II, chancel and organ chamber and vestry roofs are suffering DESIGNATION: CA from nail fatigue and are leaking. The structural integrity of the spire - currently strapped - is of particular concern and Very bad is being monitored. A Historic England Covid 19 Recovery PRIORITY CATEGORY: Fund award in 2020 investigated issues with the internal B (B) ceiling plaster. A drone survey of the spire was also Religious organisation undertaken. Further works are required. LIST ENTRY NUMBER: 1215129 Contact: Hanna Good 07825 318060

SITE NAME:	Roman villa ESE of Northfield House		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006387
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Bridge Street, Mansfield		
DESIGNATION:	Conservation Area, 27 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Denise Varley (LPA) 01623 463806

NEWARK AND SHERWOOD



1	SITE NAME:	Church of St Nicholas, Church Lane, Hockerton	Former C12 to C14 church, with a restoration by Hodgson Fowler in 1876. The building is in very bad condition.
Contraction of the second	DESIGNATION:	Listed Building grade II*	Previous historic movement is evident in the stonework, and it is possible this is still ongoing. Rainwater goods are
	CONDITION:	Poor	defective and choked with vegetation and detritus. There are numerous slipped and missing slates to pitched roofs
	OCCUPANCY:	Part occupied/part in use	and some ridge tiles are loose. Some vegetation has been cleared from the north side of the building. Archaeological works have been undertaken, and a new use has been
	PRIORITY CATEGORY:	F (B)	
	OWNER TYPE:	Religious organisation	approved which includes various repair schemes and renovations.
	LIST ENTRY NUMBER:	1045486	Contact: Imogen Newcombe 07387 524030

© Historic England

PRIORITY CATEGORIES

D

Е

А

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid
- В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

F	SITE NAME:	Former White Hart Hotel, 34, Market Place, Newark	Former hotel and latterly building society. C14th with C15th, C16th extensions, C17th and C19th additions and
	DESIGNATION:	Listed Building grade II*, CA	remodelling. Restored 1983 and 1990. Lower floors have been vacant for c.2 years, upper floors vacant c.10 years.
	CONDITION:	Poor	No on-going cyclical maintenance and gutter clearing
	OCCUPANCY:	Vacant/not in use	programme has led to numerous isolated areas of severe water ingress, which threaten the important historic timber
	PRIORITY CATEGORY:	C (C)	frame. High internal moisture levels exacerbated by long- term vacancy. No solution or future use agreed. Historic
	OWNER TYPE:	Commercial company	England and Local Authority working with owner to
© Historic England	LIST ENTRY NUMBER:	1196426	address issues and find a viable new use.
C Historic England			Contact: Hannah Reynolds 07557 827971
	SITE NAME:	Ollerton Hall, Main Street, Ollerton and Boughton	Country House, c. 1700. Sold by Newark and Sherwood District Council to a developer in 2008. The developer
	DESIGNATION:	Listed Building grade II*, CA	commenced a care home development, but this work was not completed. The District Council re-acquired the
	CONDITION:	Poor	property in 2016. Some repairs to the envelope of the
	OCCUPANCY:	Vacant/not in use	building have been carried out and incomplete development works have been removed from the grounds.
	PRIORITY CATEGORY:	C (C)	Historic England contributed to the costs of a condition survey. The District Council has entered into an agreement
Part of the second seco	OWNER TYPE:	Local authority	with another developer to progress repairs and conversion
© Historic England	LIST ENTRY NUMBER:	1045598	to apartments. Contact: Ben Robinson 07823 327796
- 0			Contact: Ben Robinson 07623 327776
1216	SITE NAME:	Sundial 50 metres east of Church of Holy Rood, Church Lane, Ossington	An early C17 sundial. Tuscan column with chamfered square base and four dials. It stands in a wooded churchyard in what was previously the gardens of nearby
	DESIGNATION:	Listed Building grade II*	Ossington Hall, now demolished. The stones forming the stepped base have slipped and open joints will allow
	CONDITION:	Poor	rainwater to penetrate. The stone column and cubic top
	OCCUPANCY:	N/A	has lost some detail and there are localised pockets of decay.
And the second s	PRIORITY CATEGORY:	C (C)	
A LOUGH STORY	OWNER TYPE:	Unknown	
© Historic England	LIST ENTRY NUMBER:	1301995	Contact: Imogen Newcombe 07387 524030
	SITE NAME:	North range at The Saracen's Head, Market Place, Southwell	Unoccupied wing of the hotel. The north range (and hotel) has been dated to circa 1460 with early and late C19 and
	DESIGNATION:	Listed Building grade II*, CA	C20 alterations and additions. The north range is a two storey six bay range of timber-framed close studding with
	CONDITION:	Poor	brick underbuild and nogging. Irregular fenestration with late C19 casements. Some decay, collapse of the lime ash
	OCCUPANCY:	Vacant/not in use	floor and limited penetration by vegetation. Listed Building
	PRIORITY CATEGORY:	D (D)	Consent for repairs has been granted, alongside grant support from Historic England's Covid 19 Emergency
	OWNER TYPE:	Commercial company	Heritage at Risk Response Fund. Surveys and a repair schedule have been completed.
© Alan Joyce, Architects	LIST ENTRY NUMBER:	1369925	Contact: Hanna Good 07825 318060
	SITE NAME:	Upton Hall, Main Road, Upton	Country house, 1832, by WJ Donthorn. Now used by the
	DESIGNATION:		British Horological Institute as offices, education and a
	CONDITION:	Listed Building grade II*, CA	clock museum. Roof coverings, copings and rainwater goodsis in poor condition, with corresponding internal
	CONDITION.	Poor	dampness and signs of active dry rot. The adjacent stables

dampness and signs of active dry rot. The adjacent stables and courtyard structures contribute to the setting of the hall, they are in very poor condition and at significant risk of loss. Previous proposals for works to the hall and repair of the stables for educational use have fallen through. Further advice on repair need and grant funding is being sought.

Contact: Hannah Reynolds 07557 827971

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Occupied/in use

Educational (independent)

C (C)

1179760

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NEWARK AND SHERWOOD

	SITE NAME:	Church of St Margaret, Church Hill, Bilsthorpe	Small parish church centrally located in an elevated churchyard. Tower, nave, chancel, south porch and chapel,
	DESIGNATION:	Listed Place of Worship grade I, CA	north vestry. There is general masonry decay in several areas and deep open jointing to walling which is becoming unstable. A temporary fix has been undertaken to the high-
	CONDITION:	Very bad	level rainwater goods, however a long-term solution is needed. The provision for managing rainwater drainage
	PRIORITY CATEGORY:	A (A)	away from the building and on-going maintenance is still
	OWNER TYPE:	Religious organisation	required.
	LIST ENTRY NUMBER:	1045616	Contact: Imogen Newcombe 07387 524030
pric England			

© Historic England

新



SITE NAME:	Church of All Saints, Newark Road, Hawton	Church, CI3, with CI4 and CI5 additions. Restored in 1880 by CH Fowler, with a further restoration in the
DESIGNATION:	Listed Place of Worship grade I	1960s. The chancel contains a C14 Easter Sepulchre. The tower is considered unsafe. High level stonework to the
CONDITION:	Poor	tower needs repairing. A National Lottery Heritage Fund grant awarded in 2018 to address the urgent repairs to the
PRIORITY CATEGORY:	C (C)	bell frame, flooring and belfry is complete. Repairs to the
OWNER TYPE:	Religious organisation	parapets of the south aisle are also complete. However, further repairs to tower masonry are still required, and
LIST ENTRY NUMBER:	1046031	investigations are needed into possible movement of the south aisle.
		south asic.

Contact: Imogen Newcombe 07387 524030

© Historic England

	SITE NAME:	Church of St Giles, Langford Lane, Holme	Substantial rural church with west tower and spire, double plan nave and chancel, south porch and turret stair. Steeply
	DESIGNATION:	Listed Place of Worship grade I	pitched clay pantiled roofs. Internally in good order and generally well maintained. Some recent repair work has
	CONDITION:	Fair	been completed to the tower masonry, valley gutters, external rendering, and south porch roof.
	PRIORITY CATEGORY:	F (C)	external rendering, and south portinition.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1302380	Contact: Ben Robinson 07823 327796

© Historic England

	SITE NAME:	Church of St Mary, Church Lane, Kilvington	Small church rebuilt in 1852 on the site of the earlier church. Built in lias walling, there is consequent widespread
	DESIGNATION:	Listed Place of Worship grade II	stone erosion throughout and the south porch has a significant structural fault resulting in a displaced gable and
	CONDITION:	Poor	arch masonry. There is an associated accumulation of general maintenance requirements and subsequent low-
	PRIORITY CATEGORY:	A (A)	level damp-related decay, however gutter and drainage
	OWNER TYPE:	Religious organisation	works were recently completed.
LATING	LIST ENTRY NUMBER:	1178578	Contact: Imogen Newcombe 07387 524030

© Historic England



© Mark Goodwill-Hodgson (Architect)

NA A	SITE NAME:	Church of St Mary Magdalene and attached railing, Church Walk, Newark	Parish church dating from c1180. South aisle and four-stage spire constructed in early C14; the main nave mid-C15. The church was restored in1853 by GG Scott. Nave roof,
Part	DESIGNATION:	Listed Place of Worship grade I, CA	south porch and spire restored 1913. The church has been the victim of heritage crime. Several roofs are leaking and require renewal. The rainwater goods are generally in fair
X	CONDITION:	Poor	order but require overhauling and clearing of detritus. Some areas of stonework are open jointed. Several
1	PRIORITY CATEGORY:	A (A)	windows have broken panes and loss to hood moulds.
.(a)	OWNER TYPE:	Religious organisation	Drainage channels require attention. The Parochial Church Council are keen to effect repairs.
)	LIST ENTRY NUMBER:	1279450	Contact: Hanna Good 07825 318060

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.


NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / NEWARK AND SHERWOOD

	SITE NAME:	Church of St Wilfrid, Main Street, North Muskham	Church, C12 origin of Blue Lias stone. A Listed Places of Worship Roof Repair Fund grant in 2016 enabled the
	DESIGNATION:	Listed Place of Worship grade I	repair of rainwater goods and the tower's parapet gutter. The lower stages of tower are heavily weathered; a
	CONDITION:	Very bad	considerable masonry repairs are needed. The building was rendered historically. The church has been subject to
	PRIORITY CATEGORY:	A (A)	heritage crime. Recipient of an Historic England Covid- Emergency Heritage at Risk Response Fund grant in 20 for roof repairs. Historic England commenced a resear
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1178997	project in 2022 looking at the performance of Blue Lias repairs to inform future repair guidance.
storic England			Contact: Amanda White 0121 625 6890

© Historic England



© Historic England

Contact: Ben Robinson 07823 327796

SITE NAME:	Settlement 3/4 mile (1198m) W of Cromwell Vil	lage, Cromwell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003490
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tim Allen 07770 610214
SITE NAME:	Site discovered by aerial photography NNE of vi	llage, Cromwell	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003487
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Roman camp 470m south of Carr Banks Farm, F	arnsfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018121
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Iron Age settlement, South Muskham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003494
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Bowl barrow 160m south east of Wharf Farm, T	horpe	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017563
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NEWARK AND SHERWOOD / RUSHCLIFFE

SITE NAME:	Newark		
DESIGNATION:	Conservation Area, 351 LBs, RPG grade I, 5 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Oliver Scott 01636 655847
SITE NAME:	Ollerton, Ollerton and Boughton		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Medium	CONTACT:	Oliver Scott 01636 655847
SITE NAME:	Upton		
DESIGNATION:	Conservation Area, 22 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Low	CONTACT:	Oliver Scott 01636 655847

RUSHCLIFFE

© Historic England	SITE NAME:	Conservatory at Flintham Hall, Flintham	Conservatory, 1853-59, integral to house. Cast iron superstructure with high percentage of original glass,
	DESIGNATION:	Listed Building grade I, RPG grade II, CA	deteriorating and failing due in part to ventilation problems and water ingress leading to loss of historic fabric. Water damage to interior stonework. Some repair work has been
	CONDITION:	Poor	carried out.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1272727	Contact: Ben Robinson 07823 327796

	SITE NAME:	Church of St Giles, Fern Road, Cropwell Bishop	Church dating back to CI3. Numerous problems. There are signs that extensive structural movement is causing
	DESIGNATION:	Listed Place of Worship grade I	damage to the historic fabric. It is not clear if this movement is ongoing. Repairs to the rainwater goods,
	CONDITION:	Poor	drainage and roofs were completed in 2015. A period of monitoring should follow to establish the effect of ground
	PRIORITY CATEGORY:	C (C)	movement and any corresponding cracks in masonry.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1045650	Contact: Ben Robinson 07823 327796

© Historic England



SITE NAME: Parish Church of St Andrew. A large village church. Heavily restored in the 1860s. ets. pleted in storic re remain mpness in try roof

© Historic England

		Church Lane, Langar, Langar cum Barnstone	Prominent crossing tower with crenellated parapet Structural repairs to the north transept were comp
	DESIGNATION:	Listed Place of Worship grade I, CA	2013 via a National Lottery Heritage Fund and Hist England Repair Grant for Places of Worship. There a number of rainwater management issues and dam
	CONDITION:	Poor	low level masonry still threatens several important monuments within the church. Repairs to the vestr
	PRIORITY CATEGORY:	C (C)	have been undertaken.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1264793	Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).


ABBREVIATIONS

- CA LB LPA NP RPG SM UA WHS

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / RUSHCLIFFE / RUTLAND (UA)





SITE NAME:	Church of St Peter and St Paul, Old Hall Drive, Widmerpool	Parish church of ashlar construction dating from C14 but virtually rebuilt between 1888-95. The church was subject
DESIGNATION:	Listed Place of Worship grade II*	to heritage crime in 2019. The Parochial Church Coun has undertaken repairs, with recent repairs to the root
CONDITION:	Poor	and the north aisle's plasterwork. Further repairs are outstanding.
PRIORITY CATEGORY:	C (C)	oustanding.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1242476	Contact: Imogen Newcombe 07387 524030

© Historic England

SITE NAME: Succession of rectilinear enclosures south west of Shelford Manor			
DESIGNATION:	IATION: Scheduled Monument		1006372
CONDITION:	CONDITION: Extensive significant problems		Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Ben Robinson 07823 327796
SITE NAME:	Margidunum Roman Station, East Bridgford / Newt	on / Bingham / Car	Colston
SITE NAME: DESIGNATION:	Margidunum Roman Station, East Bridgford / Newt Scheduled Monument	on / Bingham / Car LIST ENTRY NUMBER:	Colston 1006395
	0 0	U	
DESIGNATION:	Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1006395

RUTLAND (UA)



SITE NAME:	Old Hall ruins, Exton Park	Remains of a hall, late C16/early C17, located in C19
DESIGNATION:	Scheduled Monument and Listed Building grade II, RPG grade II	pleasure grounds, around 150 metres south of current house, with remains of C17 terraces to south east. Vegetation growth is being managed, but the ruins are
CONDITION:	Fair	decaying steadily. Parts are well preserved, particularly the south elevation and chimneys. The west gable is vulnerable
OCCUPANCY:	N/A	with cracks, open joints and unsupported masonry.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1005477 and 1073771	Contact: Ben Robinson 07823 327796

© Historic England

Contact: Ben Robinson 07823 327796

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ŬA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / RUTLAND (UA) / HEREFORDSHIRE, COUNTY OF (UA)

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

	()	, (),	
	SITE NAME:	Church of St Edmund, Church Road, Egleton	Small parish church of largely Norman, albeit altered, origin comprising nave with clerestory, chancel and west tower
	DESIGNATION:	Listed Place of Worship grade I, CA	with short spire. Notable richly carved tympanum over the C12 south door. Chancel roof coverings are at the end of their life and need replacement. There is low level damp
The state	CONDITION:	Poor	and some local thought that changes in the water table may be contributing to damp issues. Drains have been cleared
1- STORE	PRIORITY CATEGORY:	C (New entry)	and any changes in the level of damp might be monitored.
Transforder Televiser	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1073761	Contact: Amanda White 0121 625 6890
nd			

© Historic England

Á	SITE NAME:	Church of St John the Evangelist, Church Street, Ryhall	Church, c.1200 in origin, C13 tower and spire, C14 porch. Mostly C15 and restored 1857. The nave, north and south
And	DESIGNATION:	Listed Place of Worship grade I, CA	aisle roofs are nearing the end of their lives, with associated historic leaks. The rainwater goods and stonework has been repaired through Historic England's Covid-19
ATAT A	CONDITION:	Poor	Emergency Heritage at Risk Response Fund, yet there appears to be a backlog of routine maintenance. The
	PRIORITY CATEGORY:	D (C)	Parochial Church Council are keen to effect further repairs
MORE TO A	OWNER TYPE:	Religious organisation	and have made good progress with their fundraising, with ongoing support from the Diocesan Historic Churches
	LIST ENTRY NUMBER:	1320352	Support Officer.
. Brecon/Diocese ofPeterborough			Contact: Imogen Newcombe 07387 524030
	SITE NAME:	Church of St Andrew, Stoke Dry	Small parish church of early C12 origin. Largely re-built early C13 and C14 with C15 additions. Restored in 1898.
	DESIGNATION:	Listed Place of Worship grade I	The church was the subject of heritage crime in 2018, however repairs were undertaken in early 2022. Previous
	CONDITION:	Fair	water ingress has damaged plasterwork, alongside causing

D (A)

1237061

early C12 origin. Largely re-built n C15 additions. Restored in 1898. pject of heritage crime in 2018, undertaken in early 2022. Previous water ingress has damaged plasterwork, alongside causing sections of a historic painting scheme to become detached. The Parochial Church Council are keen to undertake a repair scheme and remove associated cementitious plaster. Religious organisation

Contact: Imogen Newcombe 07387 524030

© Historic England

© I. E

HEREFORDSHIRE, COUNTY OF (UA)

	· · ·		
Mar	SITE NAME:	Eastern half of the Outer Gatehouse to Wigmore Abbey, Adforton	Associated with the remains of a late C12 and C14 abbey. The Outer Gatehouse comprises two buildings, of which this is the eastern building. It is without a roof and in very
	DESIGNATION:	Listed Building grade I	poor condition with extensive tree growth penetrating parts of the structure. Survey work to inform conservation is required. Structural assessment by Historic England in
	CONDITION:	Very bad	is required. Structural assessment by Historic England in 2011 indicated that elements of collapse were likely; some
	OCCUPANCY:	N/A	collapse of the outer skin of stonework has since taken
	PRIORITY CATEGORY:	A (A)	place.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1082061	Contact: Marie Twomey 0121 625 6838

© Historic England



SITE NAME:	Walsopthorne Farmhouse, Walsopthorne, Ashperton	A c.1600 timber framed house built on a C plan to give an impression of size and stature. It is of two storeys built on a
DESIGNATION:		stone plinth with stone mullioned windows to the cellar and has a plain clay tile roof. The east range was historically
CONDITION:	Poor	the 'high' end, the west range was converted to farm use in the C19 with the addition of two brick hop kilns. The roof,
OCCUPANCY:	Part occupied/part in use	rainwater goods, infill panels, doors and windows are in
PRIORITY CATEGORY:	C (C)	poor condition and there is evidence of movement in the east and west ranges.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1302708	Contact: Steven McLeish 0121 625 6884

© Historic England

PR	IORITY CATEGORIES	
А	Immediate risk of further rapid	D

Е

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site




SITE NAME:	Ruined Church of St Mary, Avenbury	A ruined C12 church. The tower stands to full height, the roof survived to the mid C20 but has fallen in. The walls of	
DESIGNATION:	Scheduled Monument and Listed Building grade II*	the nave and chancel are half collapsed and survive only to a few feet in places. Fragments of decorated interior plaster survive. Vegetation clearance has been carried out by the	
CONDITION:	Very bad	owners under an Historic England Management Agreement. The walls are generally stable but are highly exposed.	
OCCUPANCY:	Vacant/not in use		
PRIORITY CATEGORY:	A (A)		
OWNER TYPE:	Private		
LIST ENTRY NUMBER:	1005356 and 1349633	Contact: Neil Rimmington 07775 550 674	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	AvenburyDESIGNATION:Scheduled Monument and Listed Building grade II*CONDITION:Very badOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:A (A)OWNER TYPE:Private	

SITE NAME:	Belmont House, Belmont Rural	A late C18 country house by James Wyatt, extended and
DESIGNATION:	Listed Building grade II*	remodelled by E.W. Pugin c. 1860. The property has been unused since 2014 and is deteriorating through
CONDITION:	Poor	longstanding lack of regular maintenance. Holes in the roof and broken windows allow rain entry and increased risk of
OCCUPANCY:	Vacant/not in use	rot and decay. Delamination and erosion of stonework is a
PRIORITY CATEGORY:	A (A)	problem. A new use for the building is critical to its future and should be encouraged through the planning process.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1167079	Contact: Steven McLeish 0121 625 6884
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:Listed Building grade II*CONDITION:PoorOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:A (A)OWNER TYPE:Commercial company

© Historic England

© Historic England



© Historic England Archive



1	SITE NAME:	New Court Lugwardine Herefordshire, Lugwardine	Small country house, C18 with earlier origins and remodelled in the Gothic style in the early C19. Three storey U-plan with low outbuildings to the rear. Sandstone	
	LIST ENTRY NUMBER:	1005355	Contact: Cristina Gardiner 0121 625 6850	
100	OWNER TYPE:	Religious organisation		
	PRIORITY CATEGORY:	C (C)		
	OCCUPANCY:	Vacant/not in use	repair.	
	CONDITION:	Poor	the window openings and the internal archways. The community are fundraising and are developing a scheme of	
	DESIGNATION:	Scheduled Monument, LB grade II*, CA	the west tower retaining its roof. The masonry is deteriorating due to the persistent seasonal flooding and exposure to the elements. This is especially focussed on	
	Llanwarne		C13 ruined parish church with C14 and later alterations and additions. In poor condition as a roofless ruin with only	

an with low outbuildings to the rear. Sandstor ashlar with slate roofs. The slate roofs need replacing and the high level stonework is severely eroded. Stonework, roof repairs and rainwater goods repair reported to have been carried out in 2019.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Listed Building grade II*

Occupied/in use

Poor

F (F)

Private

1099834

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- ŬA WHS
 - Unitary Authority World Heritage Site

	SITE NAME:	Outbuilding east of Marstow Court (formerly listed as the Granary at Marstow), Marstow	Reputedly associated with the manor of the Knights Hospitallers who held lands in Marstow and probably originally a house, CI 5. Built of sandstone rubble under a
1.	DESIGNATION:	Listed Building grade II*	Welsh slate roof with C18 and C19 alterations. The building is now in agricultural use. The stonework and
41 2 3 3 4 4	CONDITION:	Poor	pointing are generally in poor condition; there are slipped
	OCCUPANCY:	Part occupied/part in use	and missing roof slates and the windows and doors are in poor condition. A scheme for conversion was approved
	PRIORITY CATEGORY:	D (D)	several years ago, but works are yet to take place.
	OWNER TYPE:	Private	
) Historic England	LIST ENTRY NUMBER:	2 47 5	Contact: Steven McLeish 0121 625 6884
	SITE NAME:	Barn and attached cowhouse built onto Glibes Farmhouse, Michaelchurch Escley	A four bay barn with an extra bay for a cow house and further loft bay linking to the farmhouse, which has collapsed. Probably C18 in date. A temporary metal sheet
	DESIGNATION:	Listed Building grade II*	roof protects the building, which is unused and in need of comprehensive repair. The owner has no proposals for the
-	CONDITION:	Very bad	repair of the building, and its future is uncertain.
4,	OCCUPANCY:	Vacant/not in use	
U.S.	PRIORITY CATEGORY:	A (A)	
ALL PROPERTY.	OWNER TYPE:	Private	
) Historic England	LIST ENTRY NUMBER:	1223446	Contact: Chris Miners 0121 625 6835
	SITE NAME:	Glibes Farmhouse, Michaelchurch Escley	A remote farmhouse probably C17 with C18 alterations. The walls are of thin coursed rubble stone. The roof was o
	DESIGNATION:	Listed Building grade II*	stone tiles but has been temporarily replaced with metal sheet. The building is unoccupied and in need of
	CONDITION:	Very bad	comprehensive repair. A programme of urgent works including repair of the temporary roof and rebuilding
A STOCKARD AND A STOCKARD	OCCUPANCY:	Vacant/not in use	fallen masonry, has improved its condition but the chimney
	PRIORITY CATEGORY:	C (C)	stacks are deteriorating and further long term repairs are necessary.
and all the second	OWNER TYPE:	Private	,
) Historic England	LIST ENTRY NUMBER:	1223549	Contact: Chris Miners 0121 625 6835
	SITE NAME:	Urishay Castle, Peterchurch	Remains of C12 motte castle, a ruined C17 house and a partly ruined C16 chapel. The chapel is stable and in good
	DESIGNATION:	Scheduled Monument and Listed Building grade II*	condition, but the CI7 house is without a roof and the masonry is disintegrating as a result. Lintels are also failing
	CONDITION:	Poor	and in danger of collapse. An assessment of the structure to establish the survival of medieval fabric and development
	OCCUPANCY:	N/A	of a strategy are required. Clearance of ground level
	PRIORITY CATEGORY:	A (A)	vegetation and some fencing has been undertaken
	OWNER TYPE:	Private	
) Historic England	LIST ENTRY NUMBER:	1014547 and 1099487	Contact: Neil Rimmington 07775 550 674
) Historic England	LIST ENTRY NUMBER:	1014547 and 1099487 Court Farmhouse, Preston Wynne	Contact: Neil Rimmington 07775 550 674 A former hall house dating from the CI4 which retains a spere truss and cruck truss. This building is now used for



SITE NAME:	Court Farmhouse, Preston Wynne	A former hall house dating from the CI4 which retains a spere truss and cruck truss. This building is now used for
DESIGNATION:	Listed Building grade II*	storage with residential accommodation in the later C17 house which was added to the south end. Essential
CONDITION:	Poor	stabilisation and roofing works have previously been undertaken but the condition of the building continues to
OCCUPANCY:	Part occupied/part in use	decline.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1099380	Contact: Steven McLeish 0121 625 6884

© Historic England

- PRIORITY CATEGORIES
- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

A	SITE NAME:	Post-medieval house at Willey Court, Willey	This monument includes the buried, earthwork and upstanding remains of the post-medieval house and
All and in	DESIGNATION:	Scheduled Monument	gardens at Willey Court. The owners are in negotiations with Historic England to determine an appropriate strategy for consolidation of the structural remains, which are the element at risk. A new Natural England Stewardship scheme should provide suitable, simple management of the
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	surrounding site in grazed pasture.
	OWNER TYPE:	Private	
Historic England	LIST ENTRY NUMBER:	1017251	Contact: Jez Bretherton 0121 625 6855

	SITE NAME:	Church of St Andrew, Wolferlow	St Andrew's is an early C12 church restored in 1863 by Kempson. It is constructed from stone under a roof of mixed concrete and clay tiles with timber framed tower and shingle spire. The churchyard is maintained and in use, sale of the building has been agreed; planning permission was granted for re-use as a dwelling but has lapsed. Holding repairs to roofs have been completed.
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Religious organisation	
gland	LIST ENTRY NUMBER:	1217197	Contact: Marie Twomey 0121 625 6838

Large parish church created in c1634 from the derelict SITE NAME: Church of St Mary, Abbey Abbey church of the dissolved Cistercian Dore Abbey. The Dore, Abbey Dore c1220 transepts crossing and chancel remain with a C17 Listed Place of Worship grade I, tower inserted on the south east angle of the crossing. DESIGNATION: SM Repairs have been completed on the north chapel roof, remaining issues are: the roof and drainage from the tower CONDITION Poor as well as the sandstone ashlar walling, the south PRIORITY CATEGORY: C (C) ambulatory roof and parts of the north ambulatory roof. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1099794 Contact: Cristina Gardiner 0121 625 6850 © Historic England

	SITE NAME:	Church of St Peter, Birley, Birley with Upper Hill	Small parish church in a large level churchyard in the middle of a scattered village. CI2 and CI3 nave and chancel and
	DESIGNATION:	Listed Place of Worship grade I	late C14 south chapel. The west tower is c1200. A National Lottery Heritage Fund and Historic England
	CONDITION:	Poor	Repair Grant for Places of Worship funded repairs in 200 remedied tower roof problems and the stonework to the chancel and vestry. However, the sandstone rubble stonework is still poor on the tower and south chapel gable and structural issues have been identified. The churc
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1081970	has high aspirations and are working to increase the capacity for activities.
			capacity for activities.

Contact: Cristina Gardiner 0121 625 6850

Tiny chapel in the grounds of Brockhampton Park. Built in SITE NAME Chapel at Brockhampton Park, 1798 by Byfield in the Gothic Revival style of a nave and Brockhampton west tower. Grey sandstone ashlar with battlemented Listed Place of Worship grade parapets on the principal elevations but coursed rubble and DESIGNATION: II*, RPG grade II conventional eaves to the north. Structurally bowed slate roof. The ashlar stone mouldings are heavily eroded but CONDITION: Poor the parapet gutter was repaired in 2017. PRIORITY CATEGORY: C (C) OWNER TYPE-Religious organisation LIST ENTRY NUMBER: 1349630 Contact: Cristina Gardiner 0121 625 6850

© Historic England

© Historic England

© Historic Engla

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

ÍΙΑ

WHS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
 - - Unitary Authority World Heritage Site

	SITE NAME:	Church of St George, Burrington	Small rural church. Of medieval origins, the nave was rebuilt in c1855 by S Pountney Smith and the chancel rebuilt and shortened in 1864 by Bodley. Simple plan o chancel and nave with belfry. The church has been shu since 2016 as the roof is in a dangerous condition. The perimeter of the chuch has been cordoned off due to ongoing falls of tiles. The bad condition of the roof has
	DESIGNATION:	Listed Place of Worship grade II	
	CONDITION:	Very bad	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	caused falls of plaster inside the church.
	LIST ENTRY NUMBER:	1081799	Contact: Cristina Gardiner 0121 625 6850

© Historic England

	SITE NAME:	Church of St Mary, Craswall	Small rural parish church. Continuous early C15 nave and
	DESIGNATION:	Listed Place of Worship grade II*	chancel with belfry and C17 south entrance porch. Sandstone slate roofs with Welsh slate to the north pitch.
	CONDITION:	Very bad	Sandstone rubble walls partly rendered with sandstone ashlar window tracery. Timber boarded belfry. The wall have severe open jointing, structural cracking and the
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	render is falling. The roof slates and rooflights are failing. The rainwater goods have part fallen.
	LIST ENTRY NUMBER:	1078203	Contact: Cristina Gardiner 0121 625 6850

© Historic England

© Historic England

	SITE NAME:	Church of St Michael, Croft Park, Croft and Yarpole	Small parish church set next to Croft Castle on a Nationa Trust site. Small sandstone rubble nave and chancel with slate roof mostly from a 1515 rebuilding. The west end w remodelled in late C17 with an ogee capped cupola. Som of the cupola detailing has fallen off and been replaced wi a temporary felt covering. However, the felt has a short lifespan and urgent repairs are required.
	DESIGNATION:	Listed Place of Worship grade I, RPG grade II*	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	D (C)	incspan and digent repairs are required.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1166506	Contact: Cristina Gardiner 0121 625 6850

Chapel of St Silas, Bollingham, SITE NAME: Small chapel of three bays, and a nave and chancel. Rebuilt between 1865 and 1867 with the addition of south porch Eardisley and bellcote. The nave roof is CI4 and the roof is covered DESIGNATION: Listed Place of Worship grade II* with sandstone slates. These are heavily overgrown with moss and ferns, decaying the slates. Holes have appeared CONDITION: Very bad in the slates covering both roof pitches. The interior is PRIORITY CATEGORY: netted to catch falls of plaster from the roof lining. A (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1157325 Contact: Cristina Gardiner 0121 625 6850

© Historic England



SITE NAME:	Church of St John the Baptist, Grendon Bishop	Parish church built in 1787-88 with earlier origins. The church was altered and extended in 1870 by FR Kempson.
DESIGNATION:	Listed Place of Worship grade II	The church is built of old red sandstone rubble with tile roofs. The church has severe damp problems and slipped
CONDITION:	Very bad	tiles are allowing water into the chancel.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1307407	Contact: Cristina Gardiner 0121 625 6850

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

	SITE NAME:	Church of St Catherine, Hentland	Church of 1842 enlarged 1854-1901 in an Italianate style with apse, cloisters, narthex and campanile by J.P.Seddon
	DESIGNATION:	Listed Place of Worship grade I, CA	for the Rev. William Poole. Fine mosaic work and fittings, including marble altar and pulpit and carved wooden stalls The latest quinquennial report has identified the need for significant re-roofing, drainage upgrade, and further masonry and pointing repairs. The failure of parts of the roofs is now having a detrimental effect upon the interior
	CONDITION:	Poor	
Ann man and a second	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	with evidence of dampness and damage to timber work.
	LIST ENTRY NUMBER:	1214570	Contact: Cristina Gardiner 0121 625 6850
istoric England			

© Hist



	SITE NAME:	Church of St Peter, St Peter's Square, Hereford	Large urban parish church in the city centre of Hereford. A CI3 tower and four bay arcade, chancel and south chapel,
Ye-	DESIGNATION:	Listed Place of Worship grade II*, CA	all dating to c1300. Extensively rebuilt by Thomas Nicholson between 1880 and 1885. The valley between the nave and north aisle leaks and the south pitch slate roof
	CONDITION:	Poor	needs urgent renewal.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1196883	Contact: Cristina Gardiner 0121 625 6850

© Historic England

	SITE NAME:	Church of St Mary, Hope under Dinmore	Small but lengthy parish church on a hillside setting next to the A49. Heavily restored by Kempson in 1877 and 1896, with the small west tower and north chapel still retaining C12 and C13 fabric. The north chapel gable has structural movement and the cast iron gutters are cracked, rusting and leaking. The tower sandstone rubble is heavily eroded and has harmful vegetation growth.
	DESIGNATION:	Listed Place of Worship grade II*	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1301623	Contact: Cristina Gardiner 0121 625 6850

© Historic England

Mary, How Caple Wye. C14 c DESIGNATION: Listed Place of Worship grade II* tower, nave and the wing undersized designed for the wing undersized designed fo	SITE NAME:		Parish church in a hillside setting overlooking the River Wye. C14 chancel with a later low pitched roof. The
	tower, nave and chancel date to between 1693 and 1695, and the windows are C19. The rainwater goods are		
	CONDITION: Poor undersized and failing. T is delaminating and fallir	undersized and failing. The ashlar stonework of the tower is delaminating and falling. The parapet stonework of the	
PRIORITY CATEGORY: C (C)	C (C)	tower is structurally unsound next to the tower access	
A CONTRACTOR OF THE OWNER	OWNER TYPE:	Religious organisation	door.
	LIST ENTRY NUMBER:	1166452	Contact: Cristina Gardiner 0121 625 6850

© Historic England

	SITE NAME:	Church of St James, Kinnersley	Sandstone parish church predominantly of the C13 and
	DESIGNATION:	Listed Place of Worship grade I	CI4. Noted for a late CI9 decorative scheme by GF Bodley. The roofs, particularly to the north, were in poor
	CONDITION:	Poor	condition due to harmful vegetation growth The roof is now repaired. The interior shows significant signs of dar possibly associated with the poor condition of the roof.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	This is affecting much of the C19 decoration.
	LIST ENTRY NUMBER:	1157630	Contact: Cristina Gardiner 0121 625 6850

© Historic England

Ĥ

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Mary Magdalene, Leintwardine	Large complex church in the small town of Leintwardine. It consists of several phases of medieval work and
	DESIGNATION:	Listed Place of Worship grade I, CA	restorations in the late C19 and early C20. Repairs were carried out in 2004 but further work was required to roofs over the north aisle, and chapel, and to rainwater goods. A
	CONDITION:	Poor	National Lottery Heritage Fund and Historic England Repair Grant for Places of Worship for work to address
	PRIORITY CATEGORY:	C (C)	these was completed in 2014. However problems remain
	OWNER TYPE:	Religious organisation	with the north chapel roof and further problems have now emerged of falling mortar from the tower.
	LIST ENTRY NUMBER:	1349757	Contact: Cristina Gardiner 0121 625 6850
nd			

© Historic England

Harris	SITE NAME:	Christ Church, Llanwarne	Large circa 1864 church. Sandstone coursed rubble with
	DESIGNATION:	Listed Place of Worship grade II, CA	bath stone ashlar dressings and plain clay tile roofs. Cruciform plan with a polygonal apse and a lantern spire over the entrance porch. The sandstone has erosion
	CONDITION:	by the end ance port of the same source of the same	problems and has reacted badly with the limestone ashlar
	PRIORITY CATEGORY:	C (C)	causing severe decay especially on the entrance porch.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1099767	Contact: Cristina Gardiner 0121 625 6850
NAME AND ADDRESS OF TAXABLE PARTY OF TAXABLE PARTY.			

© Historic England

SITE NAME:	Church of the Nativity of the Blessed Virgin Mary, Madley	Large church with most phases built between C12 and C14. Aisled nave, outer south aisle, tower, entrance porch
DESIGNATION:	Listed Place of Worship grade I	and chancel with polygonal apse and crypt below. Major roof repairs are needed to the entire church. Repairs have
CONDITION:	Poor	been done to the chancel as there is a chancel repair liability, but the rest of the aisles and nave roofs continue fail and deteriorate. Failing rainwater goods and inadequa
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	ground drainage are exacerbating the problems. Some masonry repair and repointing also needed.
LIST ENTRY NUMBER:	1348768	Contact: Cristina Gardiner 0121 625 6850
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Blessed Virgin Mary, Madley DESIGNATION: Listed Place of Worship grade I CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

© Historic England

1	SITE NAME:	Church of St James, Ocle Pychard	Rural parish church. Coursed rubble walled continuous nave and chancel and partly integral west tower with a
	DESIGNATION:	Listed Place of Worship grade II*, CA	leaded broach spire. C19 decorative clay tile roof slopes are in very poor condition and need re-roofing. The rainwater goods are inadequate and in poor condition, as
	CONDITION:	Poor	are the surface water drains. There are low level open joints to the external walls and some damage to dressed
	PRIORITY CATEGORY:	C (C)	stonework.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1276199	Contact: Cristina Gardiner 0121 625 6850

© Historic England



SITE NAME:	Church of St Peter, B 4348, Peterchurch, Peterchurch	Large Norman church of nave, former tower base, char and apse with some later medieval features. Tower of I
DESIGNATION:	Listed Place of Worship grade I	century, with a fibreglass spire of 1972 replacing a stone spire removed in 1949. Interior remodelled for community
CONDITION:	Poor	use in 2009. The true condition of the spire is unknown, and options for its future repair need now to be
PRIORITY CATEGORY:	C (C)	considered. Other essential repairs remain outstanding
OWNER TYPE:	Religious organisation	from the 2016 QIR including replacing missing tiles, repair to roof flashings, urgent holding repair work to the tower
LIST ENTRY NUMBER:	1296560	parapet gutter, which is cracked and allowing water into

© Historic England

ne later medieval features. Tower of 13th reglass spire of 1972 replacing a stone 1949. Interior remodelled for community true condition of the spire is unknown, future repair need now to be r essential repairs remain outstanding R including replacing missing tiles, repair irgent holding repair work to the tower nich is cracked and allowing water into the tower.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- Conservation Area Listed Building Local Planning Authority National Park LB LPA
- NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site
- 90

SITE NAME: Church of St Peter, Pipe and Lyde Small parish church set at the end A49. Late C12 nave and C14 char	nurch set at the end of a village and facing the 2 nave and C14 chancel largely rebuilt by F 874 who also added the broach spire to the
DESIGNATION: Listed Place of Worship grade II* Kempson in 1874 who also added C13 tower. The roof needs repair	I the broach spire to the r and work is also needed
CONDITION: Poor to the tower.	
PRIORITY CATEGORY: C (C)	
OWNER TYPE: Religious organisation	
LIST ENTRY NUMBER: 1172739 Contact: Cristina Gardiner 0121 6	625 6850

© Historic England

1 martin	SITE NAME:	Church of St Mary, Stoke Edith	Large parish church, rebuilt by the Foleys of Stoke Edith
100	DESIGNATION:	Listed Place of Worship grade I	Park in 1740 in the Palladian style by Henry Flitcroft. The C14 tower with truncated spire was retained. The roof
11	CONDITION:	Very bad	leaks, causing rot in the nave beam and falls in the plasterwork. The ashlar stone facings are eroding severely.
	PRIORITY CATEGORY:	A (A)	A few stones have fallen from the tower and spire.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1099825	Contact: Cristina Gardiner 0121 625 6850

© Historic England

	SITE NAME:	Church of St Peter and St Paul, Church Road, Weobley	Large parish church at the edge of the village of Weobley. C13 nave and flanking aisles with C14 chancel extension
	DESIGNATION:	Listed Place of Worship grade I, CA	and north west tower. There is currently no solution to t problem of flaking sandstone ashlar on the tower and spi however it is being managed by high level metal guards as ground level fencing.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1301343	Contact: Cristina Gardiner 0121 625 6850

© Historic England

SITE NAME:	Offa's Dyke: the section extending 950yds (870m)	N and S of Big Oak	s, Byford / Bishopstone / Bridge Sollers
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001738
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Mouse motte and bailey castle, Cusop		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019488
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Neil Rimmington 07775 550 674
SITE NAME:	Dinedor Camp, Dinedor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001758
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Neil Rimmington 07775 550 674

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Promontory fort on Dorstone Hill, Dorstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014544
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Moated site 360 metres north of Joanshill Farm, Fo	ownhope / Mordifor	rd
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019853
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Blackfriars Friary, preaching cross and cemetery, a	nd hospital and cha	pel of St John in Hereford, Hereford
DESIGNATION:	Scheduled Monument, 3 LBs, part in CA	LIST ENTRY NUMBER:	1010797
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Neil Rimmington 07775 550 674
SITE NAME:	Huntington Castle, Huntington		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1002939 and 1157544
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Offa's Dyke: Rushock Hill section, extending 1630y	/ds (1490m) east to	Kennel Wood, Kington Rural / Knill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001731
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section S of Riddings Brook on Herro	ock Hill, Lower Har	pton / Kington Rural / Knill
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005358
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Natural erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Other	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section north west of Holme Marsh e	xtending 615 yards	(560 metres) to the railway, Lyonsha
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001735
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Bowl barrow 460 metres south of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014103
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Bowl barrow 490 metres south east of Milton Cro	ss, Pembridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014112
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Bowl barrow 550 metres south east of Milton Cro	ss, Pembridge	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014895
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	North Herefordshire Rowe Ditch, Pembridge / Sta	unton on Arrow	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005382
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Castle mound W of Court Farm, Rowlstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005366
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Sutton Walls (camp), Sutton / Marden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001747
CONDITION:	Extensive significant problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Thruxton Tump, a motte castle at Thruxton Court	t, Thruxton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015341
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Neil Rimmington 07775 550 674

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / HEREFORDSHIRE, COUNTY OF (UA) / SHROPSHIRE (UA)

SITE NAME:	Motte and bailey, west of St Mary's Church, Walterstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001778
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Roman town of Ariconium, Weston under Penyard	1	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005364
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Kington		
DESIGNATION:	Conservation Area, 124 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Herefordshire Council (LPA) 01432 260386
SITE NAME:	Ross-on-Wye, Ross-on-Wye / Bridstow		
DESIGNATION:	Conservation Area, 153 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
condition.			
VULNERABILITY:	Medium	CONTACT:	Herefordshire Council (LPA) 01432 260386

SHROPSHIRE (UA)

C HILL	SITE NAME:	Abutment of Roman Bridge at Radnor Bridge, Acton Burnell / Pitchford	The disrupted masonry abutment on the south bank of the Row Brook at Radnor Bridge is all that remains of a former bridge constructed by the Romans. A Management
	DESIGNATION:	Scheduled Monument	Agreement to compile a repairs specification to quantify and assess repair costs was funded by Historic England in
	CONDITION:	Very bad	2020. Tenders to consolidate the masonry structure were obtained in March 2021 but funding to enable the repair
	OCCUPANCY:	N/A	works to proceed has yet to be agreed.
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1006280	Contact: Bill Klemperer 0121 625 6847



© Historic England Archive

© Historic England

SITE NAME: Wattlesborough Castle (uninhabited parts), Alberbury with Cardeston DESIGNATION: Scheduled Monument and Listed Building grade I	Remains of a large square tower of the castle, now without a roof. Probably late C13 for Sir Robert Corbet. The wall heads are particularly vulnerable; some blocks of masonry		
	Scheduled Monument and Listed Building grade I	have fallen from high level. The owner was previously considering consolidation and re-roofing works to facilitate domestic use, but a repair and development scheme has	
	CONDITION: OCCUPANCY:	Poor	yet to be put forward.
		N/A	
4	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1006285 and 1366883	Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Alberbury Castle, Alberbury, Alberbury with Cardeston	The masonry remains of this CI3 castle tower keep are rapidly eroding, heavily colonised by ivy and assorted
	DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	vegetation and undermined by burrowing animals. A survey was commissioned by Historic England in 2013 as a basis for designing a programme of urgent repair works for
	CONDITION:	Very bad	discussion with the owner. Subsequent discussions with the Loton Park Estate in 2018 to find a way forward to
	OCCUPANCY:	N/A	consolidate and repair the ruin and make it safe and
Line Percent	PRIORITY CATEGORY:	A (A)	accessible to the public have stalled.
	OWNER TYPE:	Private	
) Historic England	LIST ENTRY NUMBER:	1020662 and 1175344	Contact: John Tiernan 0121 625 6839
No.	SITE NAME:	Barn to west of Hall Farmhouse, Aston Eyre	Used as a barn for many years, this building is in fact a medieval hall with a solar wing and dates from the C15.
	DESIGNATION:	Listed Building grade II*	Consent has been given for conversion back to residential use and repair works are ongoing.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
and the second	OWNER TYPE:	Private	
) Historic England	LIST ENTRY NUMBER:	1053205	Contact: Julie Taylor 0121 625 6848
-	SITE NAME:	48 Mill Street, Bridgnorth	This three-storey building, c. 1675, forms part of
Transmitter of T	DESIGNATION:	Listed Building grade II*, CA	commercial premises used as an antique centre. The oldes building fronting the road was in poor condition, but
	CONDITION:	Fair	extensive re-roofing and external render repairs have been
	OCCUPANCY:	Part occupied/part in use	completed with the benefit of funding from Historic England. Masonry works to the return elevation of the
	PRIORITY CATEGORY:	E (E)	building range immediately behind the front together with window and door repairs remain outstanding. Unoccupiec
	OWNER TYPE:	Private	for several years, plans to convert the front range into self
18 2	LIST ENTRY NUMBER:	1177762	contained holiday lets on three levels are under consideration.
) Historic England			Contact: John Tiernan 0121 625 6839
and the second	SITE NAME:	Rockley Farmhouse, Chirbury with Brompton	This early C17 farmhouse with C20 alterations is built on an H-shape plan and configured as two floors with an attic
	DESIGNATION:	Listed Building grade II*	the east wing was originally used for stabling and still contains stalls. Constructed in brickwork with steeply
A PART DE	CONDITION:	Poor	pitched tiled roofs, the building has an assortment of building fabric and structural defects affecting the external
	OCCUPANCY:	Vacant/not in use	walls, chimneys and roof. Temporary works to address
	PRIORITY CATEGORY:	C (C)	aspects of structural instability were put in place during the summer of 2019 but the long term sustainable use of the
	OWNER TYPE:	Commercial company	farmhouse and surrounding land by the Lymore Estate is still to be resolved.
) Historic England Archive	LIST ENTRY NUMBER:	1054405	Contact: John Tiernan 0121 625 6839
	SITE NAME:	Old Hall and attached garden wall, Old Marton, Ellesmere Rural	Large farmhouse, mid to late C16 with later additions and alterations. Timber framed with painted brick and rendere infill. The owner has repaired the roof, and repairs to the
	DESIGNATION:	Listed Building grade II*	timber frame and infill panels are on-going. The adjoining C18 garden wall, of red brick with moulded stone coping,
	CONDITION:	Poor	has partially collapsed.
		Vacant/not in use	
	OCCUPANCY:	vacant/ not in use	
	OCCUPANCY: PRIORITY CATEGORY:	F (F)	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument


HERITAGE AT RISK 2022 / MIDLANDS / SHROPSHIRE (UA)

	,	,	
	SITE NAME:	Kinlet Hall (including Office Wings and Stables), Kinlet	Kinlet Hall was built in 1729 and designed by Francis Sr of Warwick. A symmetrical composition constructed in
	DESIGNATION:	Listed Building grade I	brickwork and consisting of a seven-bay block flanked by courtyards with service wings, the Hall is three storeys high
	CONDITION:	Poor	with the top storey set above a cornice. The roof is configured as a series of pitched roofs in which only the
	OCCUPANCY:	Occupied/in use	outer slate-covered slopes are visible from ground level.
	PRIORITY CATEGORY:	F (D)	Four stone capped chimneys project above the ridge line. A comprehensive scheme of roof repairs under a
- Automation and	OWNER TYPE:	Private	temporary roof is now in progress and is due to be completed in spring 2023.
ic England	LIST ENTRY NUMBER:	1053832	Contact: John Tiernan 0121 625 6839

© Historic England

© Histori

	SITE NAME:	Adcote and adjoining Forecourt Walls, Little Ness	Adcote Hall was designed by Norman Shaw and built in 1876-81 for Mrs Rebecca Darby of the Coalbrookdale
	DESIGNATION:	Listed Building grade I	Ironmasters' family. Regarded as one of the finest houses of Shaw's maturity, it has been a girls' school since 1927. An
	CONDITION:	Poor	asymmetrical composition of ashlar sandstone walls, straight gables, soaring red brick chimney stacks and
	OCCUPANCY:	Occupied/in use	expansive mullion and transom windows, most of the pla
	PRIORITY CATEGORY:	C (C)	clay tile roof coverings, lead gutter linings and cast-iron rainwater goods appear to be original and are now in
	OWNER TYPE:	Educational (independent)	urgent need of renewal. Assorted structural defects in several locations also need to be addressed.
	LIST ENTRY NUMBER:	1055113	Contact: John Tiernan 0121 625 6839



	SITE NAME:	Remains of Lea Castle at Lower Lea Farm, Lea, Lydham	This monument consists of fragmentary remains of a C12 castle surviving in the middle of a working farm: it was
	DESIGNATION:	Scheduled Monument and Listed Building grade II, 2 LBs	formerly a castle of the Bishops of Hereford. A Victorian house abuts the castle remains which are heavily overgrown. There is an urgent need to reduce ivy growth and carry out consolidation works to the standing masonry Following encouragement by Historic England to undertake vegetation clearance and repair works, a grant application was submitted by the owner in 2018 but subsequently withdrawn for financial reasons. No further progress on
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
© Historic England	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	repair works has been made to date.
	LIST ENTRY NUMBER:	1021064 and 1054509	Contact: John Tiernan 0121 625 6839



	SITE NAME:	Brogyntyn Hall, Brogyntyn Park, Selattyn and Gobowen	A mainly C18 country house, extended in the C19, with most of the interior of this date. The property stands at the
	DESIGNATION:	Listed Building grade II*, RPG grade II, CA	centre of the grade II registered park and garden with pleasure grounds, a walled garden, lodges, cottages and model farm. Last used as offices the property has been
	CONDITION:	Poor	vacant for over a decade. Planning permission was granted for an enabling development housing scheme in the
	OCCUPANCY:	Vacant/not in use	grounds to secure the repair of the hall subject to a Section
	PRIORITY CATEGORY:	F (F)	106 agreement. Repairs to the hall are ongoing.
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1367373	Contact: Julie Taylor 0121 625 6848

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK	2022 / MIDLANDS	/ SHROPSHIRE	(UA)
------------------	-----------------	--------------	------

HERITAGE AT RISK 2022 / MIDLA	NDS / SHROPSHIRE (UA	A)	
T	SITE NAME:	Ditherington Flax Mill: Cross Building, Shrewsbury	Originally built in c.1799, the cross building was rebuilt in c.1812 after a fire. The cast iron frame represents the rapid
XUM	DESIGNATION:	Listed Building grade I, CA	development of the use of this material for fire-proofing in the first decade of the 19th century. Outline planning
	CONDITION:	Poor	approval was secured for the whole site in 2010, renewed in 2020 Funding has been secured for the repair of the
	OCCUPANCY:	Vacant/not in use	spinning mill. This building will be repaired in a later phase
the second s	PRIORITY CATEGORY:	B (B)	of the works.
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1428700	Contact: Nick Molyneux 0121 625 6857
	SITE NAME:	Ditherington Flax Mill: Flax Warehouse, Shrewsbury	Built c.1810 as part of the mill's expansion; the cast iron frame represents the rapid development of the use of this
	DESIGNATION:	Listed Building grade I, CA	material in the first decade of the C19. Outline planning approval was secured for the whole site in 2010, renewed
	CONDITION:	Poor	2020. Funding has been secured for the main spinning mill
in the second	OCCUPANCY:	Vacant/not in use	and the grade II listed malt kiln which adjoins this building. The warehouse will be repaired in a later phase.
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	42873	Contact: Nick Molyneux 0121 625 6857
	SITE NAME:	Ditherington Flax Mill: Apprentice House, Shrewsbury	Former apprentice house for the Flax Mill c.1812, now mothballed. Historic England is working in partnership with
	DESIGNATION:	Listed Building grade II*, CA	the local authority. Outline planning approval was secured for the whole site in 2010, renewed 2020. Work has
	CONDITION:	Poor	commenced on the main spinning mill, and this building will be part of a later phase.
	OCCUPANCY:	Vacant/not in use	be part of a later phase.
ALTER	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1254855	Contact: Nick Molyneux 0121 625 6857
	SITE NAME:	Ditherington Flax Mill: Spinning Mill, Shrewsbury	Former flax mill with five storeys, built in 1797 as the first iron framed building in the world. Converted to maltings in
	DESIGNATION:	Listed Building grade I, CA	1897. Outline planning approval was secured for the whole site in 2010, renewed in 2020. Funding has been secured
-	CONDITION:	Fair	for the first phase of works and this building as well as the
	OCCUPANCY:	Vacant/not in use	adjoining kiln are now being repaired. The scaffolding has been dismantled and the fitting out is underway.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1270576	Contact: Nick Molyneux 0121 625 6857
	SITE NAME:	Ditherington Flax Mill: Stove House and Dye House, Shrewsbury	Former drying stove house and dye house of the flax mill. Outline planning approval was secured for the whole site in 2010, renewed in 2020, Funding has been secured and the
	DESIGNATION:	Listed Building grade II*, CA	repair of the main spinning mill is underway. This building has been repaired to allow for a small Historic England
Alter Alter	CONDITION:	Poor	office. The main space has been cleared of later
CHIER VI	OCCUPANCY:	Part occupied/part in use	interventions to allow it be used for events, but the roof is still in need of major repair.
	PRIORITY CATEGORY:	В (В)	
	OWNER TYPE:	Government or agency	
© Historic England	LIST ENTRY NUMBER:	1270566	Contact: Nick Molyneux 0121 625 6857

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	The Old Rectory, Claypit	This C18 former rectory was used as a listening station	
	LIST ENTRY NUMBER:	1020850 and 1237180; 1264271	Contact: Jez Bretherton 0121 625 6855	
D Historic England Archive	OWNER TYPE:	Commercial company		
121 PROPERTY	PRIORITY CATEGORY:	B (B)	that the remains were significantly adapted as part of the designed landscape which includes the adjacent Hawkstone Follies. The masonry is in vulnerable condition and deteriorating. Invasive vegetation needs to be brought under control. A management plan for the site has been completed with recommendations.	
	OCCUPANCY:	N/A		
The Belleville	CONDITION:	Poor		
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, RPG grade I		
. THE	SITE NAME:	Red Castle, Hawkstone Park, Weston-under-Redcastle	The standing remains of a C12/C13 medieval castle in a largely restored C18 landscape. Recent research suggests	
	LIST ENTRY NUMBER:	1264219	Contact: Jez Bretherton 0121 625 6855	
) Historic England	OWNER TYPE:	Commercial company		
	PRIORITY CATEGORY:	C (C)	Late C18 windmill located just outside the registered park and garden at Hawkstone Hall which was designed by William Emes in the mid-C18. The windmill sits above the Hawk Lake in the part of the park which is now a golf course and benefits from extensive views. The building is no longer secure, and is deteriorating under a temporary roof erected in 1994. All internal machinery and floor structure has largely and recently collapsed with the exception of principal floor beams, curb ring, windshaft an brakewheel.	
	OCCUPANCY:	Vacant/not in use		
	CONDITION:	Very bad		
	DESIGNATION:	Listed Building grade II*		
	SITE NAME:	Hawkstone Windmill, Hawkstone Park, Weston- under-Redcastle		
© Historic England	LIST ENTRY NUMBER:	1055173	Contact: Julie Taylor 0121 625 6848	
the second second	OWNER TYPE:	Private		
	PRIORITY CATEGORY:	C (C)		
111 · · · · · · · · · · · · · · · · · ·	OCCUPANCY:	Vacant/not in use	Timber framed farmhouse dating from early C17 with C19 additions including a stone extension. The property has been unoccupied for over 20 years and is very dilapidated. The roof has holes, many infill panels are missing and parts of the frame have collapsed. The erection of scaffolding an a temporary roof is providing limited support and protection.	
	CONDITION:	Very bad		
	DESIGNATION:	Listed Building grade II*		
	SITE NAME:	Hargreaves Farmhouse, Winnington, Westbury		

1	SITE NAME:	The Old Rectory, Claypit Street, Whitchurch Urban	This C18 former rectory was used as a listening station during World War II. Urgent works were previously undertaken to make the main roof weatherproof but until recently the service wing remained in very poor condition, being badly affected by differential settlement. Section 106 contributions secured for the repair of the building enabled a scheme of underpinning and other works to be largely completed in 2019. The building was sold at the beginning of 2020 and the new owner is exploring options for the creation of a respite facility for military veterans.
	DESIGNATION:	Listed Building grade II*	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1056008	Contact: John Tiernan 0121 625 6839



© Historic England

	SITE NAME:	Range Approximately 20 metres south east of Castle Farmhouse, Wistanstow	A fortified manor house complex dating from 1677 set around a courtyard. The east and north wing are in partial low-key agricultural use and are at risk as the roof covering	
	DESIGNATION:	Listed Building grade II*, SM, CA	fails, allowing water to rot structural timbers, and loosen structural stonework. Long term plans for a mixed use conversion to holiday accommodation and heritage interpretation have not yet been implemented.	
	CONDITION:	Very bad		
	OCCUPANCY:	Part occupied/part in use	interpretation have not yet been implemented.	
	PRIORITY CATEGORY:	D (D)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1269775	Contact: Jez Bretherton 0121 625 6855	

PRIORITY CATEGORIES

© Historic England

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / SHROPSHIRE	<i>(</i> ΙΙΔ)	١
TIERTAGE AT RISK 2022 / TIIDEARDS / STIROT STIRE		,

	SITE NAME:	Snailbeach New Smeltmill, Worthen with Shelve	The monument comprises a smelt mill and slag mill built in 1862 for the Snailbeach Mining Company. The slag mill has been stabilised but standing remains of the smelt mill
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II	furnaces are in very poor condition due to invasive uncontrolled vegetation. Historic England has completed a
	CONDITION:	Very bad	archaeological survey to record the earthworks and ruined smelters at the site. Further vegetation clearance and
Service Barrier	OCCUPANCY:	N/A	emergency repairs are needed to secure this important
	PRIORITY CATEGORY:	A (A)	lead smelting complex.
	OWNER TYPE:	Private	
∋ Historic England	LIST ENTRY NUMBER:	1017764 and 1307989; 1055031	Contact: Marie Twomey 0121 625 6838
	SITE NAME:	Candle House, Snailbeach Lead Mine, Worthen with Shelve	This building is part of the scheduled site of the Snailbeach Lead Mine and was where miners collected their candles
	DESIGNATION:	Scheduled Monument and Listed Buildings - 10 grade II, LB grade II, part in CA	before going underground. It dates from the early C19 and is constructed from coursed rubble with brick dressings under the remains of a Welsh slate roof. The walls are substantially intact, but the roof has collapsed and the
	CONDITION:	Very bad	building is derelict.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
) Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1014866 and 1261135; 1055011; 1055012; 1176609; 1176636; 1176648; 1176660; 1366969; 1367007; 1055013	Contact: Marie Twomey 0121 625 6838
	SITE NAME:	Church of St Michael, Alberbury with Cardeston	The original C12 church was replaced by the existing nave and chancel built in 1749. The semi-detached west tower
	DESIGNATION:	Listed Place of Worship grade II	was added in 1844. Restored in 1905 by AE Lloyd Oswell, the church is built of uncoursed Alberbury breccia with
	CONDITION:	Poor	sandstone ashlar dressings and roofs mostly covered by
	PRIORITY CATEGORY:	D (D)	plain clay tiles. The slate covering to the tower roof has failed and needs to be re-laid. The parapet gutter also
and the second s	OWNER TYPE:	Religious organisation	requires complete renewal, the decorative weathervane overhauling and access up and onto the tower parapet
	LIST ENTRY NUMBER:	1055215	gutter improved. Fundraising to address these repairs is
) Historic England			currently in progress. Contact: John Tiernan 0121 625 6839
1000	SITE NAME:	Church of St Giles, Barrow	St Giles is one of the most complete surviving early churches in the county and consists of a CII nave and
	DESIGNATION:	Listed Place of Worship grade I	chancel and C12 west tower with a C18 top stage: the late
K I Class	CONDITION:	Poor	C19 north side chapel replaced a C17 earlier addition and the south porch was added C18. Restored by GE Street, i
	PRIORITY CATEGORY:	D (D)	has steeply pitched plain clay tile roof coverings and
	OWNER TYPE:	Religious organisation	replacement plastic rainwater goods: significant areas of primary masonry survive intact, Ineffective surface water
	LIST ENTRY NUMBER:	1367837	drainage and raised ground levels exacerbate damp conditions inside the church and rainwater goods and tilec roof coverings require renewal.
D Historic England			Contact: John Tiernan 0121 625 6839
1	SITE NAME:	Church of St Mary, Bedstone	The CI2 church of St Mary consists of a nave with a lower chancel, a CI7 west end timber framed bell-cote and a
	DESIGNATION:	Listed Place of Worship grade II*, CA	C19 shingled broached spire. The original chancel arch and two windows survived the restoration in 1878 - 9 by F R
	CONDITION:	Poor	Kempson who grouped the nave windows together. The spire was re-shingled in 1996 but is now in need of urgent
	PRIORITY CATEGORY:	C (C)	repair as is the bell-cote timber framing and infill panels
T/ - LAL	OWNER TYPE:	Religious organisation	below. Moisture levels within external walls requires the reduction of adjacent ground levels, the replacement of
P/Earl III			
	LIST ENTRY NUMBER:	1055017	impervious re-pointing and the installation of a perimeter surface water drainage system.

A Immediate risk of further rapid deterioration or loss of fabric; no

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

p	SITE NAME:	Church of St Mary, Bitterley	This late C13 church consists of a nave, chancel and west
	DESIGNATION:	Listed Place of Worship grade II*	tower. It was restored by Thomas Nicholson between 1880 and 1888 who added the south side timber porch,
dill	CONDITION:	Poor	the timber framed top stage to the tower and its short broad shingled spire. All the tile coverings to the nave,
and the second s	PRIORITY CATEGORY:	C (C)	chancel and porch roofs together with the cast iron
1 (A)	OWNER TYPE:	Religious organisation	rainwater goods are failing and require renewal. The surface water drainage system is largely ineffective and
	LIST ENTRY NUMBER:	1383652	needs to be replaced. Limited high-level masonry repairs are also required. Work to re-shingle the tower spire was
			are also required. Work to re-similigie the tower spire was

© Historic England



SITE NAME:	Church of St Mary, Cleeton St Mary, Bitterley	This church was built in 1876-8 and designed by Thomas Nicholson. It consists of a chancel with a lean-to north
DESIGNATION:	Listed Place of Worship grade II	vestry and a nave with a tower built into its west end. Recent repairs to the chancel roof have confirmed that the
CONDITION:	Poor	original tile batten fixings are failing and require renewal: other roofs are of the same date so must be considered
PRIORITY CATEGORY:	C (C)	equally suspect. Rainwater goods and the surface water
OWNER TYPE:	Religious organisation	drainage system also require overhauling. Following an unsuccessful application to the National Lottery Heritage
LIST ENTRY NUMBER:	1383665	Fund in 2019, the congregation are investigating other sources of grant funding.

completed at the end of 2020.

Contact: John Tiernan 0121 625 6839

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Church of Holy Trinity,

Religious organisation

Listed Place of Worship grade II

Church of St George, Church

Listed Place of Worship grade

Religious organisation

Buildwas

Poor

C (C)

1366860

Street, Clun

II*, CA

Poor

D (D)

1367257

© Historic England

© Historic England

© Historic England

	LIST ENTRY NUMBER:	1383665	sources of grant funding.
			Contact: John Tiernan 0121 625 6839
	SITE NAME:	Parish Church (dedication unknown), Boraston	This CI2 church was mostly rebuilt between 1884-7 by Henry Curzon at the expense of Lord Northwick of
-	DESIGNATION:	Listed Place of Worship grade II, CA	Burford House. Built as a chapel of Burford, it has a nave with a west tower and shingled spire, a south porch and an apsidal chancel with north side vestry. Differential
	CONDITION:	NDITION: Poor settlement has occurred a	settlement has occurred at the east end of the church and is thought to have been exacerbated by defective surface
	PRIORITY CATEGORY:	D (D)	water drainage. The chancel and vestry tiled roof coverings
4	OWNER TYPE:	Religious organisation	have been patch repaired but the oak shingles to the spire require complete renewal. A new surface water drainage
-	LIST ENTRY NUMBER:	1383416	system was installed in 2020.
			Contact: John Tiernan 0121 625 6839

This C18 church replaced a medieval one and consists of a nave and chancel with a north side vestry, a west end timber framed bell-cote and a south porch: the porch arch is formed of reused C13 mouldings above which a cast iron plate records its rebuilding as 1720. The walls of the church are constructed in squared sandstone blocks and roofs are covered in plain clay tiles. The bell-cote timber framing is original but the C20 render covering is no longer weatherproof and is effectively life-expired: wall frame timbers require assorted carpentry repairs and infill panels complete renewal.

Contact: John Tiernan 0121 625 6839

The C12 church of St George consists of a nave with same height chancel, north and south aisles, a north porch and a west tower of several stages. The body of the church sustained damage during the Civil War and was virtually reconstructed by GE Street in 1877. Roofs re-laid at that time are now failing and recently sustained storm damage has exacerbated conditions. The south aisle slate roof was stripped and re-laid in 2017 and the stone slate porch roof similarly overhauled in 2020 but plans and a timescale to deal with the nave, chancel and north aisle roof coverings are still to be agreed.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

ΪA

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Dorrington, Condover Thomas Hope of Netley Hall and built in	This church was designed by Edward Haycock for John Thomas Hope of Netley Hall and built in 1845. It consists
Land 2	DESIGNATION:	Listed Place of Worship grade II	of a nave with a west tower with spirelet, short transepts for family pews and a short chancel with flanking vestries.
	CONDITION:	Poor	Walls are constructed in tooled ashlar and steeply pitched roofs covered in plain clay tiles. The condition of the tower
	PRIORITY CATEGORY:	C (C)	parapet is poor as both finials to the east facing corner
	OWNER TYPE:	Religious organisation	pinnacles have been taken down and both corners secured back to the steeple with wire ties. Tower parapet access
	LIST ENTRY NUMBER:	1366638	needs to be improved and all cast iron rainwater goods overhauled.
			UVEI HAUIEU.

Contact: John Tiernan 0121 625 6839

	SITE NAME:	Church of St Peter, Coreley	This church has a CI3 unbuttressed west tower with a
	DESIGNATION:	Listed Place of Worship grade II*	later shingled broach spire. Both the nave and lower chancel were rebuilt in C18 in brickwork on the former
	CONDITION:	Poor	medieval footprint. Roofs are steeply pitched with plain clay tiles which appear to be almost at the end of their life,
	PRIORITY CATEGORY:	C (C)	along with most of the rainwater goods. Ineffective
	OWNER TYPE:	Religious organisation	drainage and/or roof leaks are responsible for the deteriorating condition of the vestry plasterwork. Stone
	LIST ENTRY NUMBER:	3837	repairs are also required to the chancel east window.
			Contact: John Tiernan 0121 625 6839

© Historic England

© Historic England

	SITE NAME:	Church of St Giles, Farlow	The church of St Giles was built in 1857-8 and consists of a
	DESIGNATION:	Listed Place of Worship grade II	nave with a west end bell-cote and a south side porch and a lower chancel with a north side vestry. Except for the
All I have	CONDITION:	Poor	south side of the nave, all other roof slopes are failing; underlying plaster infill ceiling panels to the exposed roof
	PRIORITY CATEGORY:	E (D)	structures are also known to be unstable. Rainwater goods
	OWNER TYPE:	Religious organisation	require increased capacity together with a new surface water drainage system. Works to re-lay the north slope of
	LIST ENTRY NUMBER:	8865	the nave roof together with assorted improvements to the rainwater goods are planned to be completed by the end
			of 2022.

© Historic England

100

	SITE NAME:	Church of St John the Baptist, Church Street, Ightfield	The C15 church of St John the Baptist consists of a nave with a west tower and a south porch, a north aisle and a
	DESIGNATION:	Listed Place of Worship grade II*	chancel. Designed in Perpendicular Gothic with crenellated parapets, multi-stepped buttresses and decorative finials, it
-	CONDITION:	condition: Poor is co	is constructed in grey ashlar stone and has steeply pitched roofs covered in plain clay tiles. The tower roof coverings
T	PRIORITY CATEGORY:	C (C)	and parapet gutter linings require complete renewal. High
	OWNER TYPE:	Religious organisation	level masonry repairs to the tower are also needed together with a new surface water drainage system. The
100	LIST ENTRY NUMBER:	1366502	congregation are investigating sources of grant funding to carry out repairs.

© Historic England



D

Е

SITE NAME:	Church of the Holy Trinity, Minsterley	Built as consists
DESIGNATION:	Listed Place of Worship grade II*	cote an elemen
CONDITION:	Fair	without unusual
PRIORITY CATEGORY:	D (D)	by the l
OWNER TYPE:	Religious organisation	Worshi
LIST ENTRY NUMBER:	1055228	masonr drainag

© Historic England

s a chapel of Westbury between 1688-9, the church s of a nave and chancel in one with a west end bellnd a south porch. The use of classical and baroque nts, the extensive use of brickwork, raking buttresses It offsets and a steeply pitched tiled roof, creates an al composition. A reduced scheme of repairs funded National Lottery Heritage Fund Grant for Places of nip was completed in 2020 but concealed defects itated the omission of assorted urgent high-level ry repairs and the installation of a new surface water drainage system.

Contact: John Tiernan 0121 625 6839

Contact: John Tiernan 0121 625 6839

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

	SITE
A Mark	DESI
STATING ST	CON
Best and the first	PRIC
	OW
	LIST


'E NAME:	Broadstone Chapel, Broadstone, Munslow	Set within a walled enclosure within open pasture, this C17 single cell former agricultural building with bi-annual church
SIGNATION:	Listed Place of Worship grade II	services was re-purposed as a chapel of ease to Munslow in 1843 when the west bell-cote, lancet windows and
ONDITION:	Poor	entrance were inserted. Built of rubble siltstone with dressed stone to openings and a pitched roof covered by
IORITY CATEGORY:	C (New entry)	plain clay tiles, cracks to the east wall corners indicates de-
WNER TYPE:	Religious organisation	bonding of the masonry core which needs urgent attention. Assorted repairs to the roof coverings, cast iron rainwater
T ENTRY NUMBER:	1383354	goods and the surface water drainage system are also urgently required.
		argenty required.

© Historic England



	SITE NAME:	Church of St John the Baptist, Nash	This C13 church has a nave and chancel under one continuous roof, a west tower and a south porch. Built as a
	DESIGNATION:	Listed Place of Worship grade II*	chapel of ease to St Mary Burford, it was given a broached spire in the CI4 and a north aisle in 1865: the nave roof
100	CONDITION:	Poor	structure also dates from C19. The plaster infill ceiling panels to the nave and north aisle roofs have become
	PRIORITY CATEGORY:	C (C)	unstable with age and require renewal. The spire timber
	OWNER TYPE:	Religious organisation	cladding also needs to be overhauled. Emergency masonry repairs to the east gable were carried out in 2018. A
	LIST ENTRY NUMBER:	1383565	scheme to address repairs to the spire cladding is in the process of being developed.

© Historic England



Church of St Chad. Stockton

Religious organisation

Religious organisation

Poor

C (C)

CA

Poor

D (C)

1189978

1053743

Listed Place of Worship grade II*

Church of St Mary, Stottesdon

Contact: John Tiernan 0121 625 6839

Contact: John Tiernan 0121 625 6839

This church has CI2 origins but was heavily restored in 1858-8 at the expense of TC Whitmore of Apley Park. The church has a nave with a west end tower, short transepts and a chancel with a north side vestry. The tower, transepts and nave roofs and associated parapet gutters urgently require renewal of surface coverings and linings. Assorted masonry repairs and repointing to both tower and nave walls are also required together with modifications to the surface water drainage system to control and manage water discharged from high level gargoyles and chutes.

Contact: John Tiernan 0121 625 6839

The church of St Mary consists of a nave with aisles, a west tower and a chancel. Although there are fragments of Listed Place of Worship grade I, Saxon masonry within the west wall of the nave, the tower and aisles are C12. The church as seen today was largely completed by the CI4 and was restored in the CI9 by Thomas Blashill. The C19 tile roof coverings require renewal along with the rainwater goods. Assorted high level masonry repairs are also needed as is a new surface water drainage system. The congregation have been awarded a National Lottery Heritage Fund grant and plan to start re-roofing works in summer 2022.

© Historic England

© Historic England

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE-

SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE-

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Church of St Michael, Silvington, Wheathill	This church consists of a short C12 nave with an asymmetrical west tower of similar date aligned with the
and the second	DESIGNATION:	Listed Place of Worship grade II*	north wall, a C14 chancel and a C16 porch. Walls are constructed in coursed and squared rubble reflecting the
	CONDITION:	Poor	local geology and roofs are steeply pitched and covered with red plain clay tiles. The nave north wall has raking
	PRIORITY CATEGORY:	A (A)	buttresses installed in C19 to address structural
3	OWNER TYPE:	Religious organisation	deficiencies. Extensive cracking to both nave and tower walls suggests inadequate bonding of the external facework
	LIST ENTRY NUMBER:	1383760	and the presence of voids in the core of the walls. The extent and scope of repairs has yet to be agreed.
			exterit and scope of repairs has yet to be agreed.

© Historic England



	SITE NAME:	Loughton Parish Church, Wheathill	This church was built in 1622 at the expense of Bonham Norton of Church Stretton to replace a C13 chapel.
1	DESIGNATION:	Listed Place of Worship grade II	Constructed in rubble stone with steeply pitched roofs covered by plain clay tiles, it consists of a nave with a west
	CONDITION:	Poor	bell-cote and a lower chancel. It was subsequently restored in 1904 when the south porch and north vestry were
No. of Concession, Name	PRIORITY CATEGORY:	C (C)	added. This was possibly the last occasion when all the roof
	OWNER TYPE:	Religious organisation	coverings were re-laid and accounts for their poor condition. Rainwater goods are also failing and a new
	LIST ENTRY NUMBER:	1383759	modified surface water drainage system is urgently required.

Contact: John Tiernan 0121 625 6839

© Historic England



SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© Historic England

		1505757	required.
			Contact: John Tiernan 0121 625 6839
	SITE NAME:	Church of St John the Baptist, Boot Street, Whittington	The earliest part of this red brick church is the west tower built in 1747: the neoclassical nave was designed by
L	DESIGNATION:	Listed Place of Worship grade II, CA	Thomas Harrison and built in 1805-6 and the pyramid roof added to the tower in 1894. The Early English chancel with south organ chamber and north chapel was added in 1861.
4	CONDITION:	Poor	Partial re-roofing of the north slope of the nave roof in 2017 has eliminated water ingress but all the cast iron
	PRIORITY CATEGORY:	C (C)	rainwater goods are defective and require renewal. The
	OWNER TYPE:	Religious organisation	surface water drainage system is also ineffective and complete renewal is anticipated. The Congregation are
	LIST ENTRY NUMBER:	1367372	reviewing sources of grant funding.
			Contact: John Tiernan 0121 625 6839

This small church set below the Stiperstones was built in 1839-40 to the designs of the rector, the Revd TF More under John Carline's supervision. It consists of a nave and chancel in one with a narrow west tower. The walls are constructed in coursed rubble stone and roofs covered by plain clay tiles. All the cast iron rainwater goods require overhauling as does the surface water drainage system. Following minor roof repairs carried out in 2021, the poor condition of the tile battens uncovered suggests that reroofing of the nave/chancel roof should be anticipated in the near future.

Contact: John Tiernan 0121 625 6839

© Historic England

SITE NAME: Little Shrawardine motte and bailey castle, Alberbury with Cardeston DESIGNATION Scheduled Monument LIST ENTRY NUMBER: 1019198 Generally unsatisfactory with major localised CONDITION Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY? Natural erosion - extensive No OWNER TYPE: CONTACT: Private Jez Bretherton 0121 625 6855 SITE NAME: Ringwork 540 metres north of Lane Farm, Alberbury with Cardeston DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019831 Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY ?: Arable clipping No OWNER TYPE: CONTACT: Jez Bretherton 0121 625 6855 Private

Church of All Saints, Worthen

Listed Place of Worship grade II

Religious organisation

with Shelve

Poor

D (D)

1055026

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.

С Slow decay; no solution agreed. Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building CA LB

- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA

Unitary Authority World Heritage Site WHS

SITE NAME:	Stanwardine moated site and associated fishpond, I	Baschurch	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Lower Cleeton moat, a moat and fishponds 380 m	etres south east of	Cleeton Court, Bitterley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010496
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	White Ladies (St Leonard's) Priory, Boscobel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015290
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Bowl barrow 450 metres north west of Felton Far	m, Bromfield	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007712
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Castle Tump, a motte castle and causeway, 150 me	etres west of Teme	Bridge, Burford
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Motte and bailey castle 150 metres north east of V	Vilmington, Chirbu	ry with Brompton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012864
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Motte castle 400m north east of Upper Gwarthlov	v Farm, Chirbury w	ith Brompton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013500
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

DistionationScheduled MonumentDETERTIONATION1003013COMMENTIONGenerally unstatisfactory with major localised predemaIMMANDeckningFIRECEND MINERMENTIVSchub/Tame growthNoNoOWNER TYPEOther not for profit groupCONTACT:Alison MacDonald 0121 625 6827Sin NomeOffa's Dyke: section one mile 730 yards (2290 merry:) from During 100 yards (274 metro) north of Lack Brook. Also in Prove: Walks. Chirbury with BromptonIO03797Sin NomeOffa's Dyke: section one mile 730 yards (2290 merry:) from During 100 yards (274 metro) north of Lack Brook. Also in Prove: Walks. Chirbury with BromptonIO03797Sin NomeConstructionScheduled MonumentISEN WARKS MILENNoConstructionDecentoration - in need of managementNew OWTACT:NoMINCHAUMURANAUTYScheduled Monument, CAISEN WARKS MULLENIO08396Sin North Camp: a Brate multivaliate billfort, CullentNoIO03173MINCHAUMURANAUTYScheduled Monument, CAISEN WARKSNoMINCHAUMURANAUTYScheduled MonumentISTENT NUMENIO21073MINCHAUMURANAUTYScheduled MonumentISTENT NUMENTIO21073MINCHAUMURANAUTYScheduled MonumentISTENT NUMENTIO21073MINCHAUMURANAUTYScheduled MonumentISTENT NUMENTIO21073MINCHAUMURANAUTYScheduled MonumentISTENT NUMENTIO21073MINCHAUMURANAUTYScheduled MonumentISTENT NUMENTIO21073MINCHAUMURANAUTYScheduled MonumentISTENT NUMENTIO	SITE NAME: Offa's Dyke: section 2/3 mile (1170 metres) long, north from southern boundary of Rownal Cow with Brompton			n boundary of Rownal Covert, Chirbu
problems problems Problems Problems Problems sextcond Vicine Browth Serub //tree growth New XII K72 No Sextcond Vicine Browth Orfa's Dyker section one mile 750 yards (2290 metrics) From Dudston Covert to a point 300 yards (274 aris Natio Orfa's Dyker section one mile 750 yards (2290 metrics) From Dudston Covert to a point 300 yards (274 aris Natio Scheduled Monument Interview Numers IO03797 constract Scheduled Monument No Declining sextexation Orfa's Dyker section one mile 750 yards (2290 metrics) Moin MacDonald 0121 625 6827 sextexation Scheduled Monument, CA ust DMTA'N NUMER Moin MacDonald 0121 625 6827 sextexation Scheduled Monument, CA ust DMTA'N NUMER IO08396 contract Provate Contract Jez Bretherton 0121 625 6827 sexted Mutatoment New MTA'n No Contract Jez Bretherton 0121 625 6827 sexted Mutatoment Scheduled Monument Scheduled Monument Scheduled Monument Jez Bretherton 0121 625 6827 sexted Mutatomant Scheduled Monument Jez DMT	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003013
Defense for profit group CNNTACE: Allson MacDonald 0121 625 6827 STRE NAME: Offa's Dyke: section one mile 750 yards (2290 metres) from Dudston Covert to a point 300 yards (274 STRE NAME: Offa's Dyke: section one mile 750 yards (2290 metres) from Dudston Covert to a point 300 yards (274 STRE NAME: Offa's Dyke: section one mile 750 yards (2290 metres) from Dudston Covert to a point 300 yards (274 STRE NAME: Scheduled Monument INE NAME NAME OWNERGRU: VULUERABUTY: Deterioration - in need of management NAW DUTY: No SCHEDULERABUTY: Deterioration - in need of management NAW DUTY: No SCHEDULERABUTY: Contract: Allson MacDonald 0121 625 6827 SCHEDULERABUTY: Scheduled Monument, CA USE INTEX NUMERS 1008396 CONTACT: Beclining Declining 1021 625 6827 SCHEDULERABUTY: Scrub frage multivalitate hillfort, Culmington / Craven Arms 1021 625 6827 SCHEDULERABUTY: Animal burrowing - extensive No 1021 625 6827 SCHEDULERABUTY: Animal burrowing - extensive No 1021 625 6827 SCHEDULERABUTY: Animal burrowing - extensive No 1	CONDITION:		TREND:	Declining
Construction Construction<	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Markan Markan Markan Marken Markan	OWNER TYPE:	Other not for profit group	CONTACT:	Alison MacDonald 0121 625 6827
ControllineGenerally unsatisfactory with major localised problemsTREMEDecliningRENCHAL WULRERABUTYDeterioration - in need of managementNEW ENTRYNoDeterioration - in need of managementNEW ENTRYAlison MacDonald 0121 625 6827DENTRYPrivateCONTACT:108396DESENATION:Scheduled Monument, CAUST ENTRY NURRERA100396DENTRYScheduled Monument, CANoDecliningDENTRYScheduled Monument, CANoDecliningDENTRYPrivateCONTACT:Jez Bretherton 0121 625 6857DENTRYPrivateCONTACT:Jez Bretherton 0121 625 6857DENTRYPrivateNorton Camp: a large multivallate hillfort, Culming:NoDENTRYScheduled MonumentLIT ENTRY NURRERNoDENTRYMixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6857DENTRYMixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6857DENTRYMixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6857DENTRYMixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6857DENTRYMixed MonumentLIT ENTRY NURRERIO2856DENTRYScheduled MonumentLIT ENTRY NURRERIO2856DENTRYPrivateCONTACT:Jez Bretherton 0121 625 6857DENTRYPrivateCONTACT:Jez Bretherton 0121 625 6857DENTRYScheduled MonumentLIT ENTRY NURRERIO2856DENTRYScheduled MonumentLIT ENTRY NURRE	SITE NAME:			
Decision of the second of the secon	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003797
WINEKTIPEPrivatePrivateONNIACE:Alison MacDonald 0121 625 68327WILL NAME:Kote castle 80 metres north east of Home Far.USE INTER NUMBER108396BERGMATION:Scheduled Monument, CANET INTER NUMBER1008396CONDITION:Extensive significant problemsTRAND:DecliningBERGMATION:Scrub/tree growthNOINTERNOINTERNOWILL NUMBERAOrthor Camp: a large multivallate hillfort, Culm.Verwen NUMBER1021073StableScheduled MonumentUST ENTER NUMBER1021073CONDITION:Generally unsatisfactory with major localised problemsTRAND:NoCONDITION:Generally unsatisfactory with major localised problemsTRAND:NoCONDITION:Mixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6855CONDITION:Scheduled MonumentUST ENTER NUMBER1012856CONDITION:Scheduled MonumentUST ENTER NUMBER1012856CONDITION:Scheduled MonumentUST ENTER NUMBER1012856CONDITION:Scheduled MonumentUST ENTER NUMBER1012856CONDITION:Offs Dyke: section 400m north and 170m est ENTER NUMBER1020904CONDITION:Offs Dyke: section 400m north and 170m est ENTER NUMBER102094CONDITION:Scheduled MonumentUST ENTER NUMBER102094CONDITION:Offs Dyke: section 400m north and 170m est ENTER NUMBER102094CONDITION:Scheduled MonumentUST ENTER NUMBER102094CONDITION:Sched	CONDITION:		TREND:	Declining
ATTE NAME: Motte castle 80 metres north east of Home Farm, Church Stretton Sessenation: Scheduled Monument, CA LIST ENTRY NUMBER: Doesling Sendo Trite Color Color Extensive significant problems TRENO: Deeclining RIRKCRAL VULNEKABULY: Scheduled Monument, CA Nov Deeclining RIRKCRAL VULNEKABULY: Scheduled Monument, CA Nov Deeclining OWINERTYPE: Private CONTACT: Jez Bretherton 0121 625 6855 Status Scheduled Monument LIST ENTRY NUMBER: 1021073 CONDITION Generally unsatisfactory with major localised TRENO: Stable CONDITION Generally unsatisfactory with major localised TRENO: No CONDITION Generally unsatisfactory with major localised TRENO: No OWINERTYPE: Mixed, multiple owners CONTACT: Jez Bretherton 0121 625 6855 STRENCENLUNKERABULY: Animal burrowing - extensive No Deelining Scheduled Monument LIST ENTRY NUMBER: 1012856 CONTACT: Jez Bretherton 0121 625 6855 Stable Scheduled Monument LIST ENTRY NUMBER: Deelining Scheduled Monument LIST ENTRY NUMBER: 1020904 CONTACT: Jez Bretherton 0121 625 6855 <tr< td=""><td>PRINCIPAL VULNERABILITY:</td><td>Deterioration - in need of management</td><td>NEW ENTRY ?:</td><td>No</td></tr<>	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No
DesiGNATION:Scheduled Monument, CAUST ENTRY NUMBER1008396CONDITION:Extensive significant problemsTREND:DecliningREINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoOWNER TYPE:PrivateCONTACT:Jez Bretherton 0121 625 6855STETENAME:Norton Camp: a large multivallate hillfort, Culmigton / Craven Arms:1021073DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1021073CONTION:Generally unsatisfactory with major localised problemsTREND:StableCONTACT:Jez Bretherton 0121 625 6855STEENAME:Animal burrowing - extensiveNEW ENTRY:NoDESIGNATION:Generally unsatisfactory with major localised problemsTREND:StableCONTACT:Jez Bretherton 0121 625 6855STEENAME:The Mount motte and bailey castle, 120 metres northeresTem, DiddleburyDESIGNATION:Generally unsatisfactory with major localised problemsTREND:DecliningCONTACT:PrivateOffa's Dyke: section 400m north and 170m east of HIIH Hous:NoCONTACT:Offa's Dyke: section 400m north and 170m east of Selley Hall, Llanfa':NoCONTACT:Generally satisfactory but with minor localised problemsTREND:DecliningSTEENAME:Offa's Dyke: section 400m north and 170m east of Selley Hall, Llanfa':NoCONTACT:Scheduled MonumentUST ENTRY NUMBER:NoCONTACT:Scheduled MonumentIST ENTRY NUMBER:NoDESIGNATION:Scheduled Mon	OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
CONDITIONExtensive significant problemsTRENO:DecliningRINCIPAL YULNERABUTY:Scrub/tree growthNEW ENTRY:NoSYNNER TYPE:PrivateCONTACT:JEJ Bretherton 0121 625 6855TRENOME:Notron Camp: a large multivallate hillfort, Culming-T/ Craven Arm:DESIGNATION:Scheduled MonumentUST ENTRY NUMBER:1021073CONDITIONGenerally unsatisfactory with major localised problemsINEND:StableCONDITION:Animal burrowing - extensiveNoIntendoWIRE TYPE:Named burrowing - extensiveCONTACT:JEZ Bretherton 0121 625 6855WIRE TYPE:The Mount motte and bailey castle, 120 metersVEST ENTRY NUMBER:1012856SCINDITION:Scheduled MonumentUST ENTRY NUMBER:1012856SCINDITION:Scheduled MonumentUST ENTRY NUMBER:1012856SCINDITION:Animal burrowing - extensiveNoIntendoSCINDITION:Offa's Dyke: section 400m north and 170m east of FHITY:NoSCINDITION:Scheduled MonumentUST ENTRY NUMBER:1020904SCINDITION:Scheduled MonumentUST ENTRY NUMBER:NoSCINDITION:Scheduled MonumentUST ENTRY NUMBER:No <td< td=""><td>ITE NAME:</td><td>Motte castle 80 metres north east of Home Farm,</td><td>Church Stretton</td><td></td></td<>	ITE NAME:	Motte castle 80 metres north east of Home Farm,	Church Stretton	
REINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY: No DWNER TYPE: Private CONTACT: Jez Bretherton 0121 625 6855 DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1021073 CONDITION: Generally unsatisfactory with major localised problems TREND: Stable REINCERL VULNERABILITY: Animal burrowing - extensive New ENTRY: No DOWNER TYPE: Mixed, multiple owners CONTACT: Jez Bretherton 0121 625 6855 STIE NAME: The Mount motte and bailey castle, 120 metres nort- east of Hill House: Io12856 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining Scheduled Monument UST ENTRY NUMBER: 1012856 East Stable CONDITION: Generally unsatisfactory with major localised problems TREND: Declining Scheduled Monument UST ENTRY NUMBER: 1012856 East Stable CONTACT: Private Offa's Dyke: section 400m north and 170m east of Selley Hall, Llanty Tweeton 0121 625 6855 STEENAME: Offa's Dyke: section 400m north and 170m east of Selley Hall, LLANTY NUMBER: 1020904 </td <td>DESIGNATION:</td> <td>Scheduled Monument, CA</td> <td>LIST ENTRY NUMBER:</td> <td>1008396</td>	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008396
WINER TYPE:PrivateONTACT:Jez Bretherton 0121 625 6855ATTE NAME:Norton Camp: a large multivallate hillfort, Culmigut-/ Craver1021073SEGRINATION:Scheduled MonumentUST ENTRY NUMBER:1021073CONDITION:Generally unsatisfactory with major localisedTREND:StableCONTACT:Jez Bretherton 0121 625 6855CONTACT:Jez Bretherton 0121 625 6855CONTACT:Scheduled MonumentUST ENTRY NUMBER:CONTACT:Scheduled MonumentUST ENTRY NUMBER:CONTACT:Scheduled MonumentUST ENTRY NUMBER:CONTACT:PrivateOntractorCONTACT:Jez Bretherton 0121 625 6855CONDITION:Generally unsatisfactory with major localisedTREND:CONTACT:PrivateOntractorCONTACT:Jez Bretherton 0121 625 6855CONTACT:PrivateOntractorCONTACT:Jez Bretherton 0121 625 6855CONTACT:Scheduled MonumentCONTACT:Jez Bretherton 0121 625 6855CONTACT:Scheduled MonumentCONTACT:Jez Bretherton 0121 625 6855CONTACT:Scheduled MonumentCONTACT:Scheduled MonumentCONTACT:NoCONTACT:Scheduled MonumentCONTACT:NoCONTACT:Scheduled MonumentCONTACT:	CONDITION:	Extensive significant problems	TREND:	Declining
Norton Camp: a large multivallate hillfort, Culmigton / Crave Arms Designation: Scheduled Monument List ENTRY NUMBER 1021073 Designation: Scheduled Monument List ENTRY NUMBER 1021073 CONDITION: Generally unsatisfactory with major localised problems TREND: Stable RINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY: No DWINER TYPE: The Mount motte and bailey castle, 120 metres nor - teast of Hill House: Total 265 6855 ENRICIPAL VULNERABILITY: Animal burrowing - extensive LIST ENTRY NUMBER 1012856 CONDITION: Scheduled Monument LIST ENTRY NUMBER 1012856 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining Scheduled Monument LIST ENTRY NUMBER 1012856 Stable CONDITION: Generally satisfactory but with minor localised problems TREND: Declining Scheduled Monument LIST ENTRY NUMBER 1020904 Stable CONDITION: Generally satisfactory but with minor localised problems TREND: Declining Scheduled Monument	RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Designation:Scheduled MonumentLIST ENTRY NUMBER:1021073CONDITION:Generally unsatisfactory with major localised problemsTREND:StableCONDITION:Animal burrowing - extensiveNEW ENTRY:NoDWNER TYPE:Mixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6855Affer NAME:The Mount motte and bailey castle, 120 metres northers to fHill House Farm, DiddleburyDesignation:Scheduled MonumentLIST ENTRY NUMBER:1012856CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningCONDITION:Offa's Dyke: section 400m north and 170m east of Selley Hall, LlanfairVaterdineDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020904CONDITION:Generally satisfactory but with minor localised problemsTREND:DecliningCONDITION:Scheduled MonumentLIST ENTRY NUMBER:1020904CONDITION:Generally satisfactory but with minor localised problemsTREND:DecliningCONDITION:Scrub/tree growthNEW ENTRY:NoATREND:Scrub/tree growthNEW ENTRY:NoATREND:Scheduled MonumentLIST ENTRY NUMBER:1020656ATREND:Scheduled MonumentLIST ENTRY NUMBER:1020656ATREND:Scheduled MonumentLIST EN	OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
CONDITION:Generally unsatisfactory with major localisedTREND:StableRINCIPAL VULNERABILITY:Animal burrowing - extensiveNoMixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6855MIXER TYPE:The Mount motte and bailey castle, 120 metres	ITE NAME:	Norton Camp: a large multivallate hillfort, Culming	gton / Craven Arms	5
ConcernedproblemsFind the find t	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021073
DWNER TYPE:Mixed, multiple ownersCONTACT:Jez Bretherton 0121 625 6855HTE NAME:The Mount motte and bailey castle, 120 metres nor teast of Hill HousersIo12856DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:Io12856CONDITION:Generally unsatisfactory with major localised problemsNEW ENTRY:NoRRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY:NoDOWNER TYPE:Offa's Dyke: section 400m north and 170m east of S-Iey Hall, Llanfair - WaterdineIo20904CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1020904CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1020904CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1020904CONDITION:Scheduled MonumentNEW ENTRY:NoCONDITION:Scheduled MonumentNET ENTRY NUMBER:1020656CONDITION:Scheduled MonumentNET ENTRY NUMBER:1020656CONDITION:Scheduled MonumentNEW ENTRY:NoCONDITION:Scheduled MonumentNEW ENTRY:No <td>CONDITION:</td> <td></td> <td>TREND:</td> <td>Stable</td>	CONDITION:		TREND:	Stable
STRE NAME: The Mount motte and bailey castle, 120 metres northeast of Hill House Farm, Diddlebury DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1012856 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining RINCIPAL VULNERABILITY: Animal burrowing - extensive New ENTRY: No OWNER TYPE: Private CONTACT: Jez Bretherton 0121 625 6855 STE NAME: Offa's Dyke: section 400m north and 170m east of Selley Hall, Llanfai: Waterdine DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1020904 CONDITION: Generally satisfactory but with minor localised problems TREND: Declining CONDITION: Scheduled Monument LIST ENTRY NUMBER 1020904 CONDITION: Generally satisfactory but with minor localised problems TREND: Declining CONDITION: Scrub/tree growth NEW ENTRY: No STE NAME: St. Julian's Well: a holy well in the middle of Livesey Scrub west of the junction with Sandpits DEGIONATION: Scheduled Monument LIST ENTRY NUMBER: 1020656 Statu Addition: Scheduled Monument LIST ENTRY NUMBER:	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
Designation: Scheduled Monument LIST ENTRY NUMBER: 1012856 conDiffion: Generally unsatisfactory with major localised problems TREND: Declining RINCIPAL VULNERABILITY: Animal burrowing - extensive NEW ENTRY P. No DWNER TYPE: Private CONTACT: Jez Bretherton 0121 625 6855 STEE NAME: Offa's Dyke: section 400m north and 170m east of Selley Hall, Llanfair Vaterdine DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020904 CONDITION: Generally satisfactory but with minor localised problems TREND: Declining CONDITION: Scrub/tree growth NEW ENTRY: No SWNER TYPE: Private CONTACT: Alison MacDonald 0121 625 6827 STEE NAME: St Julian's Well: a holy well in the middle of Livesey Koad, 155m south-west of the junction with Sandpits Road, Ludlow Scheduled Monument LIST ENTRY NUMBER: 1020656 STEE NAME: Scheduled Monument LIST ENTRY NUMBER: 1020656 STEE NAME: Scheduled Monument LIST ENTRY NUMBER: 1020656 STEE NAME: Scheduled Monument LIST ENTRY NUMBER: 1020656 DESIGNATION:	OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:NoDOWNER TYPE:PrivateONTACT:Jez Bretherton 0121 625 6855DESIGNATION:Offa's Dyke: section 400m north and 170m east of FUNTY NUMBER1020904DESIGNATION:Scheduled MonumentUST ENTRY NUMBER1020904CONDITION:Generally satisfactory but with minor localised problemsREND:DecliningCONDITION:Scrub/tree growthNEW ENTRY?:NoDWNER TYPE:PrivateCONTACT:Alison MacDonald 0121 625 6827STENAME:St Julian's Well: a holy well in the middle of Livesey - Surt NumbersIsten TARY NUMBER102056SelsGNATION:Scheduled MonumentUST ENTRY NUMBER1020656CONDITION:Scheduled MonumentIst ENTRY NUMBER1020656CONDITION:Scheduled MonumentIst ENTRY NUMBER1020656CONDITION:Scheduled MonumentIst ENTRY NUMBERIo20656CONDITION:Scheduled MonumentIst ENTRY NUMBERIo20656CONDITION:Scheduleg Scheduleg SchedulegI	SITE NAME:	The Mount motte and bailey castle, 120 metres no	orth east of Hill Ho	use Farm, Diddlebury
problemsproblemsPrivateDecliningPRINCIPAL VULNERABILITY:Animal burrowing - extensiveNEW ENTRY?:NoDWNER TYPE:PrivateCONTACT:Jez Bretherton 0121 625 6855Anter SourceOffa's Dyke: section 400m north and 170m east of Selley Hall, LlanfairWaterdineDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020904DECINITION:Generally satisfactory but with minor localised problemsTREND:DecliningDOUDITION:Scrub/tree growthNEW ENTRY?:NoDOUNER TYPE:PrivateCONTACT:Alison MacDonald 0121 625 6827DecliningSt. Julian's Well: a holy well in the middle of Livesey Road, 155m south with SandpitsNoDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020656DOUNTACT:Scheduled MonumentLIST ENTRY NUMBER:1020656DOUNTACT:Scheduled MonumentLIST ENTRY NUMBER:1020656DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020656DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020656DOUDITION:Generally satisfactory but with significant localised problemsTREND:DecliningDESIGNATION:Scrub/tree growthNEW ENTRY:No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012856
DWNER TYPE:PrivateCONTACT:Jez Bretherton 0121 625 6855DESIGNATION:Offa's Dyke: section 400m north and 170m east of Selley Hall, Llanfair WaterdineDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020904CONDITION:Generally satisfactory but with minor localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY?:NoDWNER TYPE:PrivateCONTACT:Alison MacDonald 0121 625 6827St Julian's Well: a holy well in the middle of Livesey Road, 155m south west of the junction with Sandpits Road, LudlowScheduled MonumentLIST ENTRY NUMBER:1020656CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1020656DecliningSt Julian's Well: a holy well in the middle of Livesey Road, 155m south west of the junction with Sandpits Road, LudlowILST ENTRY NUMBER:1020656CONDITION:Scheduled MonumentLIST ENTRY NUMBER:1020656CONDITION:Scheduled MonumentNEW ENTRY?NoCONDITION:Scheduled MonumentNEW ENTRY?NoCONDITION:Scheduled MonumentNEW ENTRY?NoCONDITION:Scheduled MonumentNEW ENTRY?No	CONDITION:		TREND:	Declining
STEE NAME: Offa's Dyke: section 400m north and 170m east of Selley Hall, Llanfair Waterdine DESIGNATION: Scheduled Monument LIST ENTRY NUMBER 1020904 CONDITION: Generally satisfactory but with minor localised problems Intended Declining CRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No DWNER TYPE: Private CONTACT: Alison MacDonald 0121 625 6827 GEIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020656 GENERAL VULNERABILITY: Scheduled Monument LIST ENTRY NUMBER: 1020656 CONDITION: Generally satisfactory but with significant localised problems IST ENTRY NUMBER: 1020656 CONDITION: Generally satisfactory but with significant localised problems INEW ENTRY: No	PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
Designation:Scheduled MonumentLIST ENTRY NUMBER:1020904CONDITION:Generally satisfactory but with minor localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoDWNER TYPE:PrivateCONTACT:Alison MacDonald 0121 625 6827Sitte NAME:St. Julian's Well: a holy well in the middle of LiveseySouth of the junction with SandpitsDesignation:Scheduled MonumentLIST ENTRY NUMBER:1020656CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningCONDITION:Scrub/tree growthNEW ENTRY:No	OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
CONDITION:Generally satisfactory but with minor localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY:NoDWNER TYPE:PrivateCONTACT:Alison MacDonald 0121 625 6827ATTE NAME:St Julian's Well: a holy well in the middle of LiveseyS-dd, LudlowSt St S	ITE NAME:	Offa's Dyke: section 400m north and 170m east of	f Selley Hall, Llanfai	r Waterdine
problems problems Problems Declining PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Alison MacDonald 0121 625 6827 SITE NAME: St Julian's Well: a holy well in the middle of Livesey Road, 155m south west of the junction with Sandpits DESIGNATION: Scheduled Monument IJST ENTRY NUMBER: 1020656 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020904
DWNER TYPE:PrivateCONTACT:Alison MacDonald 0121 625 6827STE NAME:St Julian's Well: a holy well in the middle of LiveseyRoad, Ludlowset of the junction with SandpitsDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1020656CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY?:No	CONDITION:		TREND:	Declining
St Julian's Well: a holy well in the middle of Livesey Road, I55m south west of the junction with Sandpits DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020656 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining RINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
Road, Ludlow Road, Ludlow DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1020656 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Scrub/tree growth NEW ENTRY?: No	OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Scrub/tree growthNEW ENTRY?:No	ITE NAME:		y Road, 155m south	n west of the junction with Sandpits
problems New ENTRY?: No	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020656
	CONDITION:		TREND:	Declining
DWNER TYPE: Local authority CONTACT: Marie Twomey 0121 625 6838	PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
	OWNER TYPE:	Local authority	CONTACT:	Marie Twomey 0121 625 6838

PRIORITY CATEGORIES

А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 D
 Slow decay; solution agreed but not yet implemented.
 F

 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but not yet implemented.
 F

 Slow decay; solution agreed but deterioration or loss of fabric; solution agreed but not yet implemented.
 D
 Slow decay; solution agreed but under repair or in fair to good repair, but no user identified; or obvious new user (applicable only to buildings capable of beneficial user)

 use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Offa's Dyke: section 1600yds (1460m) long, N from	n St John the Baptis	t's Church to River Unk, Mainstone
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003246
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Nickless moat, Milson		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009552
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Callow Hill Camp: a small multivallate hillfort, Mins	terley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019828
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Roman villa at Linley Hall, More		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1006253
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Small enclosed settlement on Fron, 340 metres we	st of St John's Chu	rch, Newcastle on Clun
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021069
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Offa's Dyke: section 730m south east of The Yew	Tree, Newcastle or	n Clun / Clun
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020900
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section 400 metres south west of Spri Waterdine	inghill Farm, Newca	astle on Clun / Clun / Llanfair
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020901
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME: Offa's Dyke: section 200yds (180m) long, S of The Royal Oak Inn, Oswestry Rural			westry Rural
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006260
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section 230yds (210m) long, SE from	Pentre-Shannel, Os	westry Rural
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1004767
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Roman villa 150 yards (140 metres) south east of	Lea Hall, Pontesbury	/
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006246
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Offa's Dyke: section 550yds (500m) long, on Bake	rs Hill, Selattyn and	Gobowen
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002933
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Ring cairn and Selattyn Tower on Selattyn Hill, Sel	attyn and Gobowen	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017237
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Bill Klemperer 0121 625 6847
SITE NAME:	Wat's Dyke, 420 metres long section, 190 metres Martin's Road, Selattyn and Gobowen	west of the junction	n between Preeshenlle Lane and St
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020617
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Uxacona Roman site (see also Telford and Wrekin	n Unitary Authority)	, Shifnal / St. Georges and Priorslee
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	Medieval fishpond reservoir north east of Haughmo	and Abbey and sou	th west of the hamlet of Haughton.
SITE NAME:	Uffington / Upton Magna	,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002953
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Robury Ring: a small enclosed settlement on Went	nor Prolley Moor,	Wentnor
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021072
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Hawcocks Mount ringwork castle 200 metres north	n east of Hawcock	s Farm, Westbury
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013494
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Upper Barn moat, Wistanstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Bowl barrow at The Napp, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017347
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Snailbeach New Smeltmill, 350 metres north east o	f Green Acres, Wo	orthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade	LIST ENTRY NUMBER:	1017764 and 1307989; 1055031
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Marie Twomey 0121 625 6838

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SI

D

С 0 PF 0 LIS

STAFFORDSHIRE

EAST STAFFORDSHIRE



ITE NAME:	Sinai Park, Burton on Trent, Shobnall	Mid-C17 timber framed house, one wing repaired some years ago. The remainder
DESIGNATION:	Listed Building grade II*, SM	condition and continues to deteriorate. It condition with areas of partial collapse bu
CONDITION:	Very bad	for its repair.
DCCUPANCY:	Part occupied/part in use	
RIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
IST ENTRY NUMBER:	1038484	Contact: Nick Molyneux 0121 625 6857

Mid-C17 timber framed house, one wing of which was repaired some years ago. The remainder is in very poor condition and continues to deteriorate. It is in critical condition with areas of partial collapse but no agreed plans or its repair.

© Historic England

SITE NAME: Enclosures and cursus 300 yards (270 metres) south east of Efflinch, Barton-under-Needwood DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006073 CONDITION: Unknown TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Nick Carter 0121 625 6860 SITE NAME: Timber circle, hengi-form monument and part of a pit alignment at Catholice, Barton-under-Needwood DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1019109				
CONDITION: Unknown TREND: Declining PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Nick Carter 0121 625 6860 SITE NAME: Timber circle, hengi-form monument and part of a pit alignment at Catholme, Barton-under-Needwood	SITE NAME: Enclosures and cursus 300 yards (270 metres) south east of Efflinch, Barton-under-Needwood			Barton-under-Needwood
PRINCIPAL VULNERABILITY: Arable ploughing NEW ENTRY?: No OWNER TYPE: Commercial company CONTACT: Nick Carter 0121 625 6860 SITE NAME: Timber circle, hengi-form monument and part of a pit alignment at Catholice, Barton-under-Needwood	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006073
OWNER TYPE: Commercial company CONTACT: Nick Carter 0121 625 6860 SITE NAME: Timber circle, hengi-form monument and part of a pit alignment at Catholme, Barton-under-Needwood	CONDITION:	Unknown	TREND:	Declining
SITE NAME: Timber circle, hengi-form monument and part of a pit alignment at Catholme, Barton-under-Needwood	PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
	OWNER TYPE:	Commercial company	CONTACT:	Nick Carter 0121 625 6860
DESIGNATION: Schodulod Monument LIST ENTRY NUMBER: 1019109	SITE NAME:	Timber circle, hengi-form monument and part of a	oit alignment at Ca	tholme, Barton-under-Needwood
	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019109
CONDITION: Unknown TREND: Declining	CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY: Mineral extraction/related subsidence NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY ?:	No
	OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Carter 0121 625 6860

LICHFIELD



SITE NAME:	Chetwynd Bridge (that part in Alrewas), Tamworth Road, Edingale / Fradley and Streethay / Alrewas	Chetwynd Bridge crosses the River Tame south east of Alrewas village. Designed by the County Surveyor Joseph Potter, it was manufactured in 1824 by the Coalbrookdale Company. Configured as three spans of cast iron arches
DESIGNATION:	Listed Building grade II*	with two stone cutwaters, the cast iron balustrades have become distorted by corrosion, misaligned and are
CONDITION:	Poor	generally in poor condition. Whilst they have no vehicle impact restraining capacity, remedial repairs are urgently
OCCUPANCY:	N/A	required to ensure that they remain secure, upright and
PRIORITY CATEGORY:	D (D)	intact. A repairs scheme is due to start in spring 2022 with completion anticipated in autumn 2022.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1038893	Contact: John Tiernan 0121 625 6839

© Historic England



Porch, walls and gatehouse to timber framed C15 country Manor House, Hamstall SITE NAME: house, substantially altered in C16 and C18 with brick hall, Ridware tower and courtyard walls. The tower remains as a DESIGNATION: Scheduled Monument, CA prominent garden folly with considerable structural issues. The house is still in use, but the tower is derelict and in CONDITION: Very bad very bad condition. Vegetation was cleared from the tower OCCUPANCY: N/A and a detailed recording survey has been completed. Further structural assessment of the site is needed. PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1006119 Contact: Marie Twomey 0121 625 6838

© Historic England

PR	IORI	TΥ	CAT	ЕС	GOR	IES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

HERITAGE AT	RISK 2022 /	MIDI ANDS /	LICHEELD



	SITE NAME:	Sandfields Pumping Station east Building, Chesterfield Road, Lichfield	This C19 engine house was built in 1872-3 by Henry Naden for the South Staffordshire Waterworks Company as an extension to their 1858 engine house, demolished
	DESIGNATION:Listed Building grade II*CONDITION:PoorOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:D (C)OWNER TYPE:Commercial company	when the replacement pump house was constructed in 1966. One of only four pumping stations in England to	
		Poor	retain its original Cornish beam engine in situ, water extraction ceased in 1997 and the surrounding land was
		Vacant/not in use	developed as housing. The building was upgraded to II* in
		D (C)	2014 and is currently unused. Negotiations to transfer ownership from the Developer Persimmon to the Lichfield
No.24		Waterworks Trust are in progress.	
	LIST ENTRY NUMBER:	1187742	Contact: John Tiernan 0121 625 6839

	SITE NAME:	Church of St John the Baptist, Edingale	The church of St John the Baptist has C13 origins and consists of a nave with a west tower and a chancel with a
	DESIGNATION:	Listed Place of Worship grade II*	north side organ chamber. Several phases of past repairs, remodelling and rebuilding are clearly evident. A Listed
	CONDITION:	Poor	Places of Worship Roof Repairs Grant awarded in June 2016 facilitated the renewal of the tower, nave and chancel
	PRIORITY CATEGORY:	D (D)	roof coverings, parapet gutter linings, rainwater goods and
	OWNER TYPE:	Religious organisation	new surface water drainage. A grant from the Cultural Recovery Fund programme has enabled high level masonry
	LIST ENTRY NUMBER:	1188243	and repointing works to be carried out but significant '
ngland			reponding work remains outstanding.

Contact: John Tiernan 0121 625 6839

© Historic England

© Historic England

SITE NAME:	Site of round barrow near River Tame, Alrewas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006090
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Air photographic site south west of Elford, Fisherw	rick	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006100
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Causewayed enclosure, Fradley and Streethay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002964
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Fazeley and Bonehill, Fazeley / Drayton Bassett		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Hines (LPA) 01543 308188

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

LIST ENTRY NUMBER:

NEWCASTLE-UNDER-LYME




SITE NAME Model farm complex south west of Betley Old Hall, Main Street, Betley DESIGNATION: Listed Building grade II*, CA CONDITION: Fair OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Private

1188395

Early C19 model farm including a range of cowhouses, a granary, cart shed, stables and watermill. Repairs are well underway with only the south range left to complete. Possible alternative uses for the buildings continue to be discussed with the Local Authority.

Contact: Julie Taylor 0121 625 6848

© Historic England



PEAK DISTRICT (NP)

Council

· · /			
	SITE NAME:	Hall Farmhouse, Church Street, Alstonefield, Staffordshire Moorlands	Hall Farmhouse, also known as Alstonefield Hall, is a substantial 16th century property which has evolved over time; reflecting the fortunes and needs of its various
	DESIGNATION:	Listed Building grade II*, CA	owners over the last 400years. In 2019 the new owner undertook the unauthorised extensive stripping out of the
	CONDITION:	Very bad	historic interior. The owner is in engaged discussions with the local authority but the situation remains unresolved.
	OCCUPANCY:	Vacant/not in use	
Marine	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1374580	Contact: Julie Taylor 0121 625 6848



	LIST ENTRY NUMBER:	1374580	Contact: Julie Taylor 0121 625 6848
	SITE NAME:	Critchlow Monument, Sheen, Staffordshire Moorlands	Chest tomb and railings to the Critchlow family, c. 1853 with large aedicular Gothic stone chest and spike headed
No.	DESIGNATION:	Listed Building grade II*, CA	wrought iron railing surround. The north face of the tomb has suffered two fragment losses to the blind arcading
R. S.	CONDITION:	Very bad	panels at the west and east end. The surrounding railings on all four sides have deteriorated where they fix into the
	OCCUPANCY:	N/A	stone base, in some cases to a point of complete loss,
	PRIORITY CATEGORY:	C (C)	potentially jeopardising the long term stability of the monument.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1374551	Contact: Marie Twomey 0121 625 6838

© Historic England

© Historic England

SITE NAME:	Bowl barrow 450 metres east of Stanshope, Alstonefield, Staffordshire Moorlands			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010798	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	NEW ENTRY ?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Carter 0121 625 6860	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- ÍΙΑ
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / PEAK DISTRICT (NP) / SOUTH STAFFORDSHIRE

SITE NAME:	Bowl barrow 350m south west of Merryton Low, Onecote, Staffordshire Moorlands				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008974		
CONDITION:	Extensive significant problems	TREND:	Improving		
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Government or agency	CONTACT:	Alison MacDonald 0121 625 6827		
SITE NAME:	Merryton Low bowl barrow, Onecote / Fawfieldhe	ad, Staffordshire M	oorlands		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1008973		
CONDITION:	Extensive significant problems	TREND:	Improving		
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - limited/localised	NEW ENTRY?:	No		
OWNER TYPE:	Government or agency	CONTACT:	Alison MacDonald 0121 625 6827		
SITE NAME:	Copper mines on Ecton Hill, Wetton, Staffordshire	Moorlands			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021175		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving		
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Nick Carter 0121 625 6860		

SOUTH STAFFORDSHIRE

©

	SITE NAME:	Stable Court at Four Ashes Hall, Four Ashes, Enville	The Stable Court at Four Ashes Hall consists of four ranges of outbuildings and dates from the mid to late C18
	DESIGNATION:	Listed Building grade II*	incorporating C20 alterations. A programme of urgent repairs to the principal range was completed in 2006 with
	CONDITION:	Very bad	Historic England funding but the rest of the complex remains in very poor condition. Historic England funded
	OCCUPANCY:	Vacant/not in use	project development work to assess and quantify the
	PRIORITY CATEGORY:	A (A)	remaining repairs which was completed in 2018. A scheme to develop the Stable Court as a sustainable wedding
THE REAL PROPERTY	OWNER TYPE:	Commercial company	venue with other business partners is currently being assessed.
© Historic England	LIST ENTRY NUMBER:	1277027	Contact: John Tiernan 0121 625 6839

SITE NAME:	Roman fort west of Eaton House, Brewood and Coven				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006098		
CONDITION:	Unknown	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855		
SITE NAME:	Roman camp, Kinvaston, Penkridge / Lapley, Strett	on and Wheaton A	ston		
SITE NAME: DESIGNATION:	Roman camp, Kinvaston, Penkridge / Lapley, Strette Scheduled Monument	on and Wheaton A	ston 1006104		
DESIGNATION:	Scheduled Monument Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1006104		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / STAFFORD

STAFFORD

© Historic England



SITE NAME: Engine House and Boiler House at Mill Meece Pumping Station, Standon DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Occupied/in use PRIORITY CATEGORY: E (E) OWNER TYPE: Utility LIST ENTRY NUMBER: 1039047

Former pumping station built c.1914 for the Staffordshire Potteries Waterworks Company. It now operates as a museum. The building was designed by William Campbell and constructed by Thomas Godwin and Son. The engine house and boiler house form part of an exceptionally complete pumping station site in which the integrated process of water pumping is still readable. Works to repair damage to the boilers caused by asbestos removal were completed in 2020, enabling the steam engines to be used once more. Roof repairs are expected to commence in 2022.

Contact: Marie Twomey 0121 625 6838

country house dated between 1833 and es Barry and an orangery of 1808 by ed in a CI8 and CI9 park by Capability the adjacent Italian gardens have been red, the existing Grade II* structures

© Historic England Archive

SITE NAME:	Remains of Trentham Hall, the Grand Entrance and Orangery, Park Drive, Trentham Gardens, Swynnerton	The remains of a country house dated between 1842 by Sir Charles Barry and an orangery of Tatham, all situated in a C18 and C19 park by Brown. Although the adjacent Italian gardens
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	successfully restored, the existing Grade II* st remain at risk.
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1190243	Contact: Erika Diaz Petersen 0121 625 6879

SITE NAME: Moated site in Reynold's Orchard, Eccleshall DESIGNATION: LIST ENTRY NUMBER: 1011051 Scheduled Monument Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY ?: No Animal burrowing - extensive CONTACT: OWNER TYPE: Alison MacDonald 0121 625 6827 Commercial company SITE NAME Multivallate hillfort at Bury Bank, Stone Rural LIST ENTRY NUMBER: 1008548 DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY NEW ENTRY? Scrub/tree growth No OWNER TYPE: CONTACT: Nick Carter 0121 625 6860 Private SITE NAME Stafford Town Centre DESIGNATION Conservation Area, 80 LBs, part in SM NEW ENTRY? No CONDITION: TREND: No significant change Poor VULNERABILITY: CONTACT: Alan Taylor 01785 619439 Low SITE NAME: Walk Mill, Eccleshall DESIGNATION: NEW ENTRY? Conservation Area, LB grade II No CONDITION: TREND: Very bad Deteriorating significantly VULNERABILITY: Medium CONTACT: Alan Taylor 01785 619439

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise. New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ΪA
- Unitary Authority World Heritage Site WHS

STAFFORDSHIRE MOORLANDS

	SITE NAME:	Biddulph Old Hall, Biddulph	Substantial remains of a mansion constructed in the 1580s
	DESIGNATION:	Scheduled Monument	for Francis Biddulph. It came under siege by the Parliamentarians in 1643 when the east range was
	CONDITION:	Fair	destroyed and the house fired. The tower was repaired in 2010 with the aid of Historic England grant funding.
	OCCUPANCY:	Occupied/in use	Historic England is continuing discussions with the owner
	PRIORITY CATEGORY:	C (C)	on the management and consolidation of the monument
	OWNER TYPE:	Private	
1	LIST ENTRY NUMBER:	1014688	Contact: Nick Carter 0121 625 6860


© Historic England

© Historic England



	SITE NAME:	Prospect Tower and attached wing, Knypersley, Biddulph	Built in 1828 by John Bateman as a gamekeeper's house and eye catcher on the Knypersley Hall estate landscape, this three storey octagonal tower constructed in red sandstone has been disused for more than 25 years and is
h.L	DESIGNATION:	Listed Building grade II*	
t N	CONDITION:	Poor	in a poor state of repair. The reoccupation of the building is limited by the presence of bats. An options appraisal for
The second second	OCCUPANCY:	Vacant/not in use	the building has been completed, which makes
	PRIORITY CATEGORY:	C (C)	recommendations for its future use.
141	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1037810	Contact: Marie Twomey 0121 625 6838





© Historic England



	SITE NAME:	The Wheldon School Michael Hutchinson Residential Centre (former Church of St Agnes), Hollinsclough, Staffordshire Moorlands	This C18 barn, converted to a combined church, school and schoolhouse in C19, was closed circa 1960 and made into a residential field study centre in 1974 for which it continued to be used until relatively recently. Internal flooding in 2018 has made the building uninhabitable. Crown reduction to a large tree close to the school was undertaken in 2019 and assorted works to ensure that the
	DESIGNATION:	Listed Building grade II*, CA	
	CONDITION:	Poor	building remains weatherproof and structurally stable were carried out in spring 2021. The owners are currently
	OCCUPANCY:	Vacant/not in use	reviewing feasibility options for re-using the building,
11	PRIORITY CATEGORY:	C (D)	including sale on the open market.
	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1252469	Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no Е obvious new user (applicable only to buildings capable of beneficial

use)

LIST ENTRY NUMBER:

1374612

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Julie Taylor 0121 625 6848

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2022 / MIDLANDS / STAFFORDSHIRE MOORLANDS / TAMWORTH / STOKE-ON-TRENT, CITY OF (UA)

			9
SITE NAME:	The Butter Cross, 650m west of Lowerhouse Farm	, Cheddleton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012665
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Dieu-la-Cres Abbey (remains of), Leek		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1006107
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Alton and Farley, Staffordshire Moorlands		
DESIGNATION:	Conservation Area, 100 LBs, part in RPG grade I, 3 SMs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395400
SITE NAME:	Cheadle		
DESIGNATION:	Conservation Area, 50 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395400

TAMWORTH

F.	SITE NAME:	Deanery wall, Lower Gungate, Tamworth	A C14 masonry wall which was part of St Editha's Deaner A Historic England engineer has inspected the three
	DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, 3 LBs, CA	surviving sections of wall, parts of which are in urgent need of maintenance and repair. The removal of plant growth, repointing and resetting of stones to wall tops are all
	CONDITION:	Poor	repointing and resetting of stones to wall tops are all required. As a boundary wall, the ownership is uncertain, and liability for repair unclear.
A CARLER	OCCUPANCY:	N/A	
Contraction of the second seco	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
© Historic England	LIST ENTRY NUMBER:	1006059 and 1197033; 1207833	Contact: Marie Twomey 0121 625 6838

STOKE-ON-TRENT, CITY OF (UA)

gand	SITE NAME:	Former Wedgwood Institute (Public Library), Queen Street, Burslem	This art school, gallery and library complex was built in 1869 and constructed in brick and terracotta with an ornamented facade. The long term aspiration for this	
	DESIGNATION:	Listed Building grade II*, CA	derelict building is to bring it back into use. A first phase of repairs to re-roof the front range and carry out other	
	CONDITION:	Poor	assorted works was finished in autumn 2016. A new use for the building needs to be secured, and a strategy put in	
	OCCUPANCY:	Part occupied/part in use	place to protect the building from further deterioration and	
	PRIORITY CATEGORY:	C (C)	undertake the next phase of repairs.	
	OWNER TYPE:	Charity (heritage)		
	LIST ENTRY NUMBER:	1195840	Contact: Julie Taylor 0121 625 6848	

© Historic Engla

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / STOKE-ON-TRENT, CITY OF (UA)

A A	SITE NAME:	Bethesda Methodist Chapel, Albion Street, Hanley	This former Methodist chapel was built in the C19; it is known as the 'Cathedral of the Potteries' and its interior is
	DESIGNATION:	Listed Building grade II*, CA	practically intact. The Historic Chapels Trust has completed external repairs with the help of grants from
	CONDITION:	Fair	Historic England and the National Lottery Heritage Fund: other minor repair works have been under taken with
	OCCUPANCY:	Vacant/not in use	support from The Friends group. Works to refurbish and
	PRIORITY CATEGORY:	F (F)	install toilets within the detached single storey vestry block were completed in 2019. The Trust is continually looking at
	OWNER TYPE:	Charity (heritage)	various options to increase the use of the building.
	LIST ENTRY NUMBER:	1195821	Contact: John Tiernan 0121 625 6839

© Historic England

© Histo

	SITE NAME:	Bottle oven and factory, Price and Kensington Teapot Works, Newcastle Street, Longport	This early C19 pottery complex contains a repaired bottle oven but is now practically derelict and mostly unoccupied. The site has been subject to fires, heritage crime and is in a
	DESIGNATION:	Listed Building grade II*, CA	very poor condition: it is highly vulnerable and continues to deteriorate. The roadside building range of this complex
	CONDITION:	Very bad	was demolished in November 2019 because it was in immediate danger of collapsing into the road. Historic
	OCCUPANCY:	Part occupied/part in use	England has offered technical support and advice to Stoke
	PRIORITY CATEGORY:	A (A)	City Council. Urgent works are required to stabilise the buildings whilst a long term solution is found for the site.
	OWNER TYPE:	Commercial company	
storic England	LIST ENTRY NUMBER:	1290799	Contact: Ben Robinson 07823 327796



© Historic England

Large redundant C19-C20 colliery in need of major repair SITE NAME: Chatterley Whitfield Colliery, Biddulph Road, Stoke-on-Trent and regeneration. The site includes 15 scheduled structures and five listed buildings. A heritage based regeneration DESIGNATION: Scheduled Monument programme was started based on a masterplan but a long term solution still needs to be agreed. The City Council CONDITION Very bad are continuing to explore longer term proposals which OCCUPANCY: Vacant/not in use include reuse of the site. PRIORITY CATEGORY: A (A) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1015947 Contact: Bill Klemperer 0121 625 6847

	SITE NAME:	Chatterley Whitfield: pithead baths complex (18-21), Biddulph Road, Stoke-on-Trent	Originally opened in the 1860s, Chatterley Whitfield became the first mine in Britain to draw more than a million tons of coal in a year in 1937. The pithead baths and
	DESIGNATION:	Listed Building grade II*	canteen were erected at this time and are of interest as an example of large-scale provision for miners in the early
	CONDITION:	Very bad	C20. On the closure of the mine, the buildings were used to accommodate a museum which has since closed. The
	OCCUPANCY:	Vacant/not in use	whole colliery site is now vacant and these buildings are in
	PRIORITY CATEGORY:	A (A)	very poor condition. The City Council are continuing to explore longer term proposals which include reuse of the
	OWNER TYPE:	Local authority	site.
© Historic England	LIST ENTRY NUMBER:	1260223	Contact: Bill Klemperer 0121 625 6847

	SITE NAME:	Mausoleum, Stone Road, Trentham	A mausoleum built for the Dukes of Sutherland around 1808 and set opposite one of the entrances to Trentham
	DESIGNATION:	Listed Building grade I, CA	Park. A package of urgent roof repairs were carried out with funding from Historic England and the Local Authority.
	CONDITION:	Fair	Further repairs to doors and the rear window have also been completed in recent years. The fabric is now generally
	OCCUPANCY:	N/A	sound with additional repair needs scoped, funding not yet
	PRIORITY CATEGORY:	F (F)	secured.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1210451	Contact: Marie Twomey 0121 625 6838

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / STOKE-ON-TRENT, CITY OF (UA)

		, (-)	
	SITE NAME:	Church of St John the Baptist, Cross Hill, Burslem	This church was largely rebuilt in 1717 but retains its medieval tower. Non-breathable paint on the nave
	DESIGNATION:	Listed Place of Worship grade II	external walls is trapping moisture causing significant levels of damp internally and the deterioration of the outer brick
	CONDITION:	Poor	face. Outbreaks of dry rot have occurred in the past and re-roofing with inappropriate and heavy concrete tiles on
	PRIORITY CATEGORY:	C (C)	the hipped nave roof is leading to structural problems. The
	OWNER TYPE:	Religious organisation	building has multiple fabric defects and has been subjected to heritage crime. Protracted negotiations to lease this
	LIST ENTRY NUMBER:	1291065	place of worship to the New Testament Church of God have yet to be concluded.
			have yet to be concluded.
toric England			Contact: John Tiernan 0121 625 6839
	SITE NAME:	Church of St Mark, Broad Street, Stoke-on-Trent	This Commissioners church was built c1830 and consists of a nave with galleries and a west tower; the chancel was
	DESIGNATION:	Listed Place of Worship grade II	added in 1868. The tower clock stage is subdivided by blind pointed panels with engaged shafts secured by ferrous
	CONDITION:	Poor	metal fixings and several of these have failed and fallen to

Constant and the second s		10	pointed parters with engaged sharts seed of len ous
1	CONDITION:	Poor	metal fixings and several of these have failed and fallen to the ground. Holding repairs to secure defective plaster
	PRIORITY CATEGORY:	D (D)	ceilings above the galleries were carried out in 2017 and
	OWNER TYPE:	Religious organisation	water ingress is suspected to be the cause of the problem. A National Lottery Heritage Fund delivery grant was
	LIST ENTRY NUMBER:	1220134	awarded in December 2021 and repair works are due to start in summer 2022.

Church of St John, Newcastle

Road, Stoke-on-Trent

Religious organisation

Very bad

1220810

F (New entry)

© Historic England

© Histo



Contact: John Tiernan 0121 625 6839 This C19 church was enlarged to its present size in 1908 and consists of a nave and chancel with a north porch, south aisle, south east chapel, vestry and a south west Listed Place of Worship grade II tower with a broached spire. The church was affected by a fire in April 2022 which resulted in damage to the nave and chancel roofs together with the loss of glazing to the chancel east window. All of the interior is contaminated by the effects of combustion. The building has been secured and damage is in the process of being assessed by the insurer's Loss Adjuster prior to repairs and refurbishment commencing in summer 2022.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Caldon Canal, Stoke-on-Trent		
DESIGNATION:	Conservation Area, 2 LBs, part in RPG grade II*, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680
SITE NAME:	Longton Town Centre, Longton		
DESIGNATION:	Conservation Area, 17 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680
SITE NAME:	Newcastle Street, Middleport		
SITE NAME: DESIGNATION:	Newcastle Street, Middleport Conservation Area, LB grade II	NEW ENTRY?:	No
	· ·	NEW ENTRY?: TREND:	No No significant change
DESIGNATION:	Conservation Area, LB grade II		
DESIGNATION: CONDITION:	Conservation Area, LB grade II Poor	TREND:	No significant change
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Area, LB grade II Poor High	TREND:	No significant change
DESIGNATION: CONDITION: VULNERABILITY: SITE NAME:	Conservation Area, LB grade II Poor High Stoke Town, Stoke	TREND: CONTACT:	No significant change Jane Corfield (LPA) 01782 236680

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA

LB LPA

Conservation Area Listed Building Local Planning Authority National Park NP

RPG Registered Park and Garden Scheduled Monument

SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / STOKE-ON-TRENT, CITY OF (UA) / TELFORD AND WREKIN (UA)

SITE NAME:	Trent & Mersey Canal, Stoke-on-Trent		
DESIGNATION:	Conservation Area, 20 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680

TELFORD AND WREKIN	(UA)		
	SITE NAME:	Site of pumping engine at Muxton Bridge colliery	Situated within Granville Country Park. Includes the standing, buried and earthwork remains of a former
	DESIGNATION:	Scheduled Monument	rotative beam pumping engine, used for draining coal workings at Muxton Bridge Colliery. The condition of the
	CONDITION:	Very bad	engine house is very bad, with loose mortar joints causing
rise of the second	OCCUPANCY:	Vacant/not in use	bricks to become dislodged. The site is suffering from extreme vegetation and scrub, with veteran trees
	PRIORITY CATEGORY:	A (B)	potentially impacting buried archaeological remains. Detritus has built up in the cyclinder pit. Remaining
	OWNER TYPE:	Local authority	brickwork is suffering from efloresence, spalling and iron-
© Historic England	LIST ENTRY NUMBER:	1018468	jacking. The Council are considering management options. Contact: Imogen Newcombe 07387 524030
a harrista	SITE NAME:	Gatehouse to former Caynton Manor, Edgmond	The gatehouse at Caynton Manor is the only intact survivor of a historic manorial complex. The building's upper rooms
ative at	DESIGNATION:	Listed Building grade II*	have elaborate decorative plasterwork friezes and an
	CONDITION:	Poor	overmantle featuring the arms of the Yonge family with the date 1635. Little is known of the building's original context
	OCCUPANCY:	Vacant/not in use	and use, or the house it served, but it has been used for farm related activities for many years. The building is
	PRIORITY CATEGORY:	A (A)	derelict, has assorted building fabric defects and its setting is compromised by the close proximity of a C19 barn and
a the state of the second	OWNER TYPE:	Private	other later additions. The gatehouse was listed grade II* in
© Historic England	LIST ENTRY NUMBER:	1459113	October 2018.
- 0			Contact: John Tiernan 0121 625 6839
J. F. F. S. Mar	SITE NAME:	Severn Wharf Building (Premises of Ironbridge Gorge Museum Trust), the Wharfage, The Gorge	Large former warehouse now Museum of the Gorge on the north bank of the River Severn. Built mid C19 of red brick with yellow brick dressings in the Gothick style. It has castellated parapets with pinnacles and buttresses and
THE PUTT	DESIGNATION:	Listed Building grade II*, CA, WHS	pointed arched openings. The four parallel pitches of plain clay tile roof have valleys and parapet gutters that leak. Valley gutters have been overlaid with successive layers of
	CONDITION:	Poor	gutter materials that now pond and leak. The wall plates below are consequently showing decay with structural
	OCCUPANCY:	Part occupied/part in use	implications.An Historic England Repair Grant has
© Historic England	PRIORITY CATEGORY:	B (B)	developed a solution.
0	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1293325	Contact: Chris Miners 0121 625 6835
ALL X	SITE NAME:	Charlton Castle, Wrockwardine	A medieval moated site which is very overgrown and has
	DESIGNATION:	Scheduled Monument	several uprooted trees damaging the earthworks. There are some elements of standing masonry exposed. The site
	CONDITION:	Very bad	needs an assessment of condition and the development of
1123 Aurolia	OCCUPANCY:	N/A	an appropriate management regime.
AN STATISTICS	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
Non- As as	LIST ENTRY NUMBER:	1019649	Contact: Marie Twomey 0121 625 6838

© Historic England Archive

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / TELFORD AND WREKIN (UA) / NORTH WARWICKSHIRE

		()	
	SITE NAME:	Church of St Peter, Church Road, St. Georges and Priorslee	The Church of St Peter was designed by Francis Halley of Shifnal and built between 1825 - 1827 to replace a C12
The second to	DESIGNATION:	Listed Place of Worship grade II	chapel and consisted of the present nave and west tower to which the chancel was added in 1903. The church is
1	CONDITION:	Poor	constructed in brindle brickwork with stone dressings and has slate-covered roofs. Concealed ferrous metal cramps
	PRIORITY CATEGORY:	A (A)	have disrupted the masonry to the tower bell lights which
A PERSONAL PROPERTY.	OWNER TYPE:	Religious organisation	has resulted in sections of stone falling off. The vestry has settled and rotated away from the chancel wall. All
	LIST ENTRY NUMBER:	1033297	rainwater goods were renewed in summer 2021 but all roofs require stripping and relaying.
© Historic England			Contact: John Tiernan 0121 625 6839



SITE NAME:	Church of St Peter, Wrockwardine	This C12 cruciform church has a nave and chancel, transepts and a crossing tower with later medieval chapels
DESIGNATION:	Listed Place of Worship grade I, CA	added to the north and south sides of the chancel. Subjected to numerous campaigns of alteration and repair over time with prominent structural reinforcement in the
CONDITION:	Poor	form of angle buttresses to the tower, a National Lottery Heritage Fund Grant for Places of Worship funded re-
PRIORITY CATEGORY:	D (D)	roofing and high-level masonry repairs to the crossing
OWNER TYPE:	Religious organisation	tower which were completed in 2018. All the remaining plain clay tile roofs and cast-iron rainwater goods are still in
LIST ENTRY NUMBER:	1030939	urgent need of repair and renewal.
		Contact: John Tiernan 0121 625 6839

© Historic England

©

SITE NAME:	Enclosed Iron Age farmstead immediately adjacent	to The Croft, Pave	Lane, Chetwynd Aston and Woodcote
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020275
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Canal aqueduct over River Tern, Rodington		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1006275
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Moated site and a fishpond 160 metres and 280 me	etres south of The	Farm, Charlton, Wrockwardine
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019649
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Marie Twomey 0121 625 6838

WARWICKSHIRE

NORTH WARWICKSHIRE

	SITE NAME:	Beech House, 19 Market Street, Atherstone	Town house in the Queen Anne style dated 1708. The interiors are largely unaltered and most of the original
	DESIGNATION:	Listed Building grade II*, CA	features are intact. The property has been vacant for several years. A scheme for the repair and refurbishment of
	CONDITION:	Poor	the building has been agreed following discussions between the owner and the Local Planning Authority. Recent work
	OCCUPANCY:	Vacant/not in use	undertaken to refurbish the exterior. No site visit has been
	PRIORITY CATEGORY:	D (D)	possible this year.
	OWNER TYPE:	Commercial company	
© Historic England	LIST ENTRY NUMBER:	1185175	Contact: Nick Molyneux 0121 625 6857

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB
- LPA NP RPG
- Conservation Area Listed Building Local Planning Authority National Park

- Registered Park and Garden Scheduled Monument
- SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH WARWICKSHIRE



© Historic England

SITE NAME:	Grendon Bridge, Grendon / Polesworth	Stone bridge, probably C15 constructed in sandstone. Now in poor condition with parts of the parapet missing. A
DESIGNATION:	Scheduled Monument and Listed Building grade II*	condition survey is needed to assess the scale of repairs. The owners are exploring funding options regarding its future assessment and repair.
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1005756 and 1186247	Contact: Marie Twomey 0121 625 6838



© Historic England Archive

	SITE NAME:	Hartshill Castle, Castle Road, Hartshill	Motte and bailey castle, converted C14 enclosure castle with remains of C16 farmhouse. Upstanding remains have
(All	DESIGNATION:	Scheduled Monument and Listed Building grade II	decayed due to erosion, structural problems and vandalism. Some on-going vegetation impacts. The Harold Lapworth Charitable Trust has undertaken consolidation
2	CONDITION:	Poor	works on the enclosure wall, vegetation management and good steps to reduce vandalism, anti-social behaviour and
	OCCUPANCY:	N/A	theft. Further vegetation works are needed and repair and
	PRIORITY CATEGORY:	A (A)	consolidation of the CI6 remains. Historic England are liaising with the landowners regarding these works and the
9. 31)	OWNER TYPE:	Private	on-going maintenance of the site.
	LIST ENTRY NUMBER:	1011197 and 1034748	Contact: Neil Rimmington 07775 550 674



DESIGNATION: Buildings - I grade II*; I grade II, part in CA CONDITION: Poor OCCUPANCY. Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Private LIST ENTRY NUMBER: 1019978 and 1116550; 1034721

Kingsbury Hall, Kingsbury

SITE NAME

A manor house of c. 1500 with late C16 and C18 rebuilding and early C19 wing. A scheme for the residential Scheduled Monument and Listed conversion of the building was approved and structural works undertaken. A new scheme in association with some neighbouring development has been applied for which could see the building repaired and in use.

Contact: Nick Molyneux 0121 625 6857

© Historic England



Substantial remains of an early CI4 Augustinian monastery SITE NAME: Maxstoke Priory, Church Road, including infirmary, precinct walls and outer gatehouse with Maxstoke attached barn and farmhouse. The buildings are steadily Scheduled Monument and Listed decaying, the granary range is in poor condition and the DESIGNATION: Buildings - 6 grade II*, 2 LBs infirmary structure is propped. Historic England has part funded repairs to the boundary walls and is working with CONDITION: Poor the owners to review the condition of the gatehouse and other sections, looking to address their condition. OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Private, multiple owners 1011195 and 1034822; Contact: Marie Twomey 0121 625 6838 LIST ENTRY NUMBER: 1034823; 1365129; 1034821; 1116038; 1320105

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no

D

Е

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Merevale Abbey, a Cistercian monastery, associated water control features and industrial remains, Merevale	Mid-C12 Cistercian monastery retaining several visible fragments of major monastic buildings but also earthwork and buried remains which illustrate the development of the monastery. Stonework in the refectory is eroding and
	DESIGNATION:	Scheduled Monument, 6 LBs, part in RPG grade II*	needs addressing through a condition assessment to inform conservation. Historic England is continuing to work with the Estate to address the site.
	CONDITION:	Poor	
Service and	OCCUPANCY:	N/A	
) Historic England	PRIORITY CATEGORY:	C (C)	
Historic England	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1014682	Contact: Marie Twomey 0121 625 6838
	SITE NAME:	Middleton Hall, Middleton	The main C18 house at Middleton hall is located on the
	DESIGNATION:	Listed Building grade II*	west side of an enclosed courtyard which incorporates CI4 and CI6 buildings with extensive early CI9 additions.
	CONDITION:	Poor	The house is L-shaped on plan with rendered walls, tiled roofs and moulded eaves cornices, the latter feature
LI III	OCCUPANCY:	Occupied/in use	concealing a perimeter gutter of variable width. These
	PRIORITY CATEGORY:	D (New entry)	gutters have been modified over time, built up and repaired with inappropriate materials to the point where urgent
	OWNER TYPE:	Charity (heritage)	repairs are now required. An Historic England repairs gran
	LIST ENTRY NUMBER:	1365196	 was awarded in March 2022 and repair works are due to commence in autumn this year.
D Historic England			Contact: John Tiernan 0121 625 6839
	SITE NAME:	Stables range north east of Middleton Hall, Middleton	Originally stables and a lodging block C1570, this building is timber framed with brick infill panels. It consists of a four-
	DESIGNATION:	Listed Building grade II*	bay main range with a two-bay cross wing at the north end and a two-storey gabled porch to the left of the centre.
22 - Change and a start of the	CONDITION:	Poor	There is a courtyard of farm buildings to rear. The building is disused and in need of repair to ensure its structural
A Long a mart	OCCUPANCY:	Vacant/not in use	stability and to keep it weatherproof. A Master plan to
	PRIORITY CATEGORY:	D (D)	develop the site as a heritage visitor centre has been produced, repurposing the stable block and adjacent
	OWNER TYPE:	Charity (heritage)	courtyard as the new visitor entrance to the Middleton Hal Estate.
) Historic England	LIST ENTRY NUMBER:	1365197	Contact: John Tiernan 0121 625 6839
	SITE NAME:	Moat, footbridge and gatepiers to Shustoke Hall Farmhouse, Moat House Lane, Shustoke	Homestead moat, footbridge and gate piers c. 1686, with late C18 service wing which is in poor condition. Substantial sections of overgrown walls and buttresses
	DESIGNATION:	Listed Building grade II*	were previously leaning outwards and required rebuilding. Much of this work has been carried out by the Estate.
	CONDITION:	Poor	Progress has been made since 2013 with repointing to the moat walls, but further repairs are needed. Historic
Contraction of the second	OCCUPANCY:	N/A	England is advising on repairs to the remaining sections.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
∋ Historic England Archive	LIST ENTRY NUMBER:	1226189	Contact: Marie Twomey 0121 625 6838
	SITE NAME:	Alvecote priory and dovecote, Shuttington	The listed and scheduled remains of a C12 Benedictine monastery. The primary structure on site represents the
	DESIGNATION:	Scheduled Monument, 2 LBs	C14 remodelling of the building and has been subject to heritage crime and natural deterioration. An associated
	CONDITION:	Poor	medieval dovecote is also affected by issues with its roof
A Contraction	OCCUPANCY:	N/A	covering, water penetration and vandalism. Historic England is encouraging the Local Authority to establish a
			management plan for the site and carry out repairs to the

© Historic England Archive

PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority, multiple owners LIST ENTRY NUMBER: 1020623

Contact: Marie Twomey 0121 625 6838

standing remains of the priory and dovecote.

management plan for the site and carry out repairs to the

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / NORTH WARWICKSHIRE / NUNEATON AND BEDWORTH



Church of St Mary, Sheepy Road, Atherstone	Large imposing church constructed in two parts with a central tower. Chancel may date from C12 as an
Listed Place of Worship grade II*, CA	independent chapel, and then remodelled c1383 when the nave was added. Older parts are built in rubble. Nave and aisles were rebuilt in 1849 in rubble granite, wagon roof
Poor	with moulded braces and purlins. The octagonal tower was part of the original chapel, but was remodelled in the
C (C)	CI3/CI4. Works to the roof have been completed but
Religious organisation	the high level stonework of the tower remains in poor condition and in need of repair.
1365164	Contact: Marie Twomey 0121 625 6838

© Historic England

SITE NAME:	Roman Camp, Mancetter		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1005736
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Merevale Abbey, a Cistercian monastery, associated	l water control fea	tures and industrial remains, Merevale
DESIGNATION:	Scheduled Monument, 6 LBs, part in RPG grade II*	LIST ENTRY NUMBER:	1014682
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Alvecote priory and dovecote, Shuttington		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1020623
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Marie Twomey 0121 625 6838

NUNEATON AND BEDWORTH

	SITE NAME:	Park Farmhouse, Arbury Park, Nuneaton	Late C15 farmhouse with C16 and C17 alterations, to the north west of Arbury Park. Following a building survey,
	DESIGNATION:	Listed Building grade II*	works were carried out to support and protect the structure while schemes and options for future use were
	CONDITION:	Very bad	considered and discussed by the Estate with Historic England. The estate has installed a protective steel roof
	OCCUPANCY:	Vacant/not in use	covering to help prevent further deterioration of the frag
	PRIORITY CATEGORY:	A (A)	timber frame.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1365048	Contact: Hannah Reynolds 07557 827971

© Historic England



SITE NAME:	The Tea House, Arbury Park, Nuneaton	Mid-C18 summerhouse east of Arbury Hall. Th
DESIGNATION:	Listed Building grade II*, RPG grade II*	north east shore of a sr C18 park. The roof has state of repair and cont
CONDITION:	Very bad	needed urgently to halt building.
OCCUPANCY:	Vacant/not in use	building.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1299615	Contact: Hannah Reyn

se located c.500 metres east north he Tea House is situated on the small lake on the eastern edge of the as collapsed and it is in a very bad ntinues to deteriorate. Action is It decay and save what is left of the

© Historic England

nolds 07557 827971

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument

- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / RUGBY

RUGBY			
SITE NAME:	Brandon Castle, Brandon and Bretford		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1011371
CONDITION:	Generally satisfactory but with significant localised problems		Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Barrow cemetery 400 metres north east of Bretfor	rd, Brandon and Br	retford / King's Newnham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005722
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Prehistoric pit alignment and associated features of Farm, Church Lawford / Thurlaston	n Lawford Heath, a	djacent to the northernmost Blue Boa
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020937
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Tripontium Roman Station, Churchover		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005759
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Prehistoric circular earthworks, King's Newnham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005717
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Bowl barrow on Lammas Hill, Wolston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016885
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Bowl barrow 490 metres north west of Abbey Far	m, Wolvey	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016845
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing NEW ENTRY?: No		No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / RUGBY / STRATFORD-ON-AVON

LIST ENTRY NUMBER:

1001343

SITE NAME:	Bowl barrow 900 metres north of Copston Farm, Wolvey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016846
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838



Small Regency landscape surrounding the shell of a grade II SITE NAME: Ryton House, Ryton-onlisted Regency villa. Late C20 extensions to the villa extend Dunsmore over the gardens. Longstanding lack of regular maintenance Registered Park and Garden has left the boundary belt, historic drive, shrubberies and DESIGNATION: grade II, part in LB grade II lakes in poor condition. The setting is compromised by roads and residential development. Its future is uncertain. Generally unsatisfactory with CONDITION: major localised problems VUI NERABII ITY: High TREND: Declining NEW ENTRY ?: No OWNER TYPE: Mixed, multiple owners

Contact: Erika Diaz Petersen 0121 625 6879

© Historic England

STRATFORD-ON-AVON

	SITE NAME:	St Nicholas' Church, Ettington Park, Ettington	The chapel of St Nicholas was built in the C13 to service the village of Ettington some two miles away. However, the
	DESIGNATION:	Scheduled Monument, LB grade I	building was superceded by a better located church in 1798 and is now partially ruinous. It is the family mausoleum of the Shirley family. The church has suffered from natural
	CONDITION:	Poor	erosion and other threats including birds nesting in the tower, structural decay of standing masonry and other
	OCCUPANCY:	N/A	issues associated with rainwater goods and cementitious
	PRIORITY CATEGORY:	D (D)	repairs. Repair works on the south wall of nave and exclusion of birds from tower completed. Ongoing repair
	OWNER TYPE:	Private	discussions
gland	LIST ENTRY NUMBER:	1005744	Contact: Marie Twomey 0121 625 6838

SITE NAME: Umberslade Baptist Chapel, Nonconformist estate chapel of 1877 by George Ingall for G.F. Muntz of Umberslade Park. The chapel has not been Spring Lane, Tanworth-in-Arden used as a place of worship for many years and has been DESIGNATION: Listed Building grade II* acquired by the Historic Chapels Trust. Roof repairs have been carried out and the building is drying out. A condition CONDITION: Fair survey has been completed and a management plan with OCCUPANCY: options for use is planned. Vacant/not in use PRIORITY CATEGORY: F (F) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER 1382428 Contact: Chris Miners 0121 625 6835 © Historic England SITE NAME:

© Historic Engl



In 1851-3 the Throckmorton family built a substantial Roman Catholic Church of St church and presbytery on the edge of their estate, from Peter Paul and Elizabeth, designs by Charle's Hansom. The Throckmorton family has Coughton been at Coughton Court since C15, and the house was a Listed Place of Worship grade Catholic recusant centre from the 1570s. The terracotta DESIGNATION: II*, CA tiled roof appears to be at the end of its life with several tiles dislodged and damp showing internally. Poor CONDITION: Poor cementitious repairs, some recent, may further erode and PRIORITY CATEGORY: C (C) damage the limestone. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1355381 Contact: Chris Miners 0121 625 6835

© Historic England

Р

PRIORITY	CATEGORIES	

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ΪA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / STRATFORD-ON-AVON

	SITE NAME:	Church of St Botolph, Church Lane, Farnborough	Church of medieval origins with some Norman features and a 'Scott spire' dating from 1875. It is built in soft
	DESIGNATION:	Listed Place of Worship grade II*, CA	ironstone and set close to Farnborough Hall. Repairs and maintenance carried out in the past year have addressed the poor rainwater goods and roof. The high level
	CONDITION:	Poor	stonework remains in poor condition, especially to the north-east corner of the north aisle.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1299775	Contact: Chris Miners 0121 625 6835

© Historic England



	SITE NAME:	Church of St Giles, Church Lane, Gaydon	Small ironstone ashlar church with moulded cornices, designed by Squirrill of Learnington and dating from 1852.
	DESIGNATION:	Listed Place of Worship grade II	The church is modest in size but is in poor condition externally due to the friability of the Horton Stone. Some
	CONDITION:	Poor	parts of the church are in poor structural condition, especially on the east gable, which has large cracks and the
	PRIORITY CATEGORY:	A (A)	tower and spire give concern. The gutters are also in poor
-	OWNER TYPE:	Religious organisation	condition.
	LIST ENTRY NUMBER:	84784	Contact: Chris Miners 0121 625 6835


© Historic England

SITE NAME:	Church of St Peter, Warwick Road, Kineton	The prominently located Church of St Peter, Kineton date from the C13, with alterations from the C14, C15 and C18. It was remodelled and repaired in 1873-89 but the soft local ironstone has not lasted well. A National Lotter Heritage Fund and Historic England Repair Grant for Place of Worship awarded in 2012 has repaired the high level and tower's stonework which was in extremely poor condition. Further repairs are needed to the stonework of
DESIGNATION:	Listed Place of Worship grade II*, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	the nave's elevations and to the rainwater goods to the nave.
LIST ENTRY NUMBER:	1381924	Contact: Chris Miners 0121 625 6835
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Road, KinetonDESIGNATION:Listed Place of Worship grade II*, CACONDITION:PoorPRIORITY CATEGORY:C (C)OWNER TYPE:Religious organisation

© Historic England

	SITE NAME:	Church of All Saints, Church Road, Ladbroke	C13 and C14 church with C15 additions, extensively restored in 1876 by Gilbert Scott. It has a square tower
	DESIGNATION:	Listed Place of Worship grade I, CA	with spire, constructed in banding of limestone lias and ironstone in square coursed rubble. The tower buttresses are built in ironstone. The church is built in lime lias with
	CONDITION:	Poor	ashlar dressing. Mostly red terracotta tiled roofs. Desp its general fair condition, the stone buttresses to the to
	PRIORITY CATEGORY:	C (C)	are badly eroded and have open joints. Some of the
	OWNER TYPE:	Religious organisation	stonework around the windows is badly delaminated and stonework at the base of the walls is also poor.
and the Co	LIST ENTRY NUMBER:	1035567	Contact: Chris Miners 0121 625 6835

© Historic England



SITE NAME:	Church of St Leonard, Vicarage Lane, Priors Marston	Late C13 origins although the aisle was enlarged in C14. The tower was remodelled or rebuilt in the 1720s and the
DESIGNATION:	Listed Place of Worship grade II, CA	chancel in 1863. The walls are built in ironstone, with limestone dressing, coursed rubble and tiled roofs. The stonework on the tower parapet is in very poor condition
CONDITION:	Poor	because of expanding metal cramps dislodging the stonework and this is now loose. The tracery to the tower
PRIORITY CATEGORY:	C (C)	windows also needs replacing as it has fallen in parts. The
OWNER TYPE:	Religious organisation	church is exploring funding to carry out repairs.
LIST ENTRY NUMBER:	1374950	Contact: Chris Miners 0121 625 6835

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / STRATFORD-ON-AVON

	SITE NAME:	Church of St Peter, Tysoe Road, Radway, Radway	Small parish church built in 1866 to replace a medieval church which was located in a different part of the village of
	DESIGNATION:	Listed Place of Worship grade II, CA	Radway, at the base of the Edge Hill battlefield site. The church was built in Gothic Revival style and has a three bay chancel, nave and aisles. It is built in local Hornton
	CONDITION:	Poor	ironstone and regularly coursed with terracotta plain tiled roofs. The tower has four stages with string courses, a
	PRIORITY CATEGORY:	C (C)	moulded cornice and a broach spire. The roof, which is still
	OWNER TYPE:	Religious organisation	original, is in very poor condition because of poor detailing despite maintenance. The condition of the rainwater goods
	LIST ENTRY NUMBER:	1184627	is poor.
ric England			Contact: Chris Miners 0121 625 6835



nch built in Decorated
e nave has a flat n a sloping site and using damp to the fabric.
ndition as are the to be of inadequate
the north-east corner
۱.
335
n nc t n.

© Historic England

© Histori



SITE NAME:	Church of St Andrew, Church Street, Temple Grafton	Original Saxon church rebuilt in 1875 by Frederick Pred in lias and coursed ironstone ashlar with quoined open				
DESIGNATION:	Listed Place of Worship grade II, CA	Plain red tiled nave roof with slated north and south air roof. The upper part of the porch is the staged belfry, turret in timber frame with lath and plaster, covered w				
CONDITION:	Poor	oak shakes. The timber frame turret is now in extremely poor condition with open joints and many of the shakes				
PRIORITY CATEGORY:	C (C)	missing. There are also issues with the condition of the root				
OWNER TYPE:	Religious organisation	finish, rainwater goods and high level stonework.				
LIST ENTRY NUMBER:	1382790	Contact: Chris Miners 0121 625 6835				

© Historic England



SITE NAME:	Church of St Michael, Church Hill, Warmington
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1355583

The church dates from the late C12 with additions in the CI3 and a mid-CI4 north aisle, chancel, vestry and west tower. The church was restored in 1850 and 1876 by Sir GG Scott. It is constructed in coursed local ironstone with ashlar stone tower, spire and dressing, with a terracotta tiled roof. The roof to the nave is in extremely poor condition and a large number of tiles have slipped. Despite some repairs carried out in 2017 the south part of the roof remains in poor condition, with rain leaking into the interior affecting the supporting timber structure.

Contact: Chris Miners 0121 625 6835

© Historic England

SITE NAME:	Enclosures 550 metres east of King's Mead		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Oversley Castle, Alcester		
SITE NAME: DESIGNATION:	Oversley Castle, Alcester Scheduled Monument	LIST ENTRY NUMBER:	1005750
		LIST ENTRY NUMBER: TREND:	1005750 Unknown
DESIGNATION:	Scheduled Monument		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.

C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA LB

- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
 - Registered Park and Garden Scheduled Monument

SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / STRATFORD-ON-AVON

TERTIAGE AT RISK 2022 / THIDE			
SITE NAME:	Castle Hill Motte, Brailes		
DESIGNATION:	Scheduled Monument LIST ENTRY NUMBER: 1018858		
CONDITION:	Generally satisfactory but with significant localised problems	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Double ditched enclosure east of Thornton Farm,	Ettington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002990
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Enclosures north of Old Pasture Farm, Hampton L	ucy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005714
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Site of building and enclosure 460 metres east of H	latton Rock Farm, I	Hampton Lucy
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005741
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing NEW ENTRY?: No		No
OWNER TYPE:	Commercial company, multiple owners CONTACT:		Marie Twomey 0121 625 6838
SITE NAME:	Rectangular Earthwork on Nebsworth, Ilmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005734
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Rabbit - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Multivallate hillfort on Meon Hill, Quinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011372
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Marie Twomey 0121 625 6838
SITE NAME:	Lower Shuckburgh		
DESIGNATION:	Conservation Area, 8 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326
VULNERABILITY:	High Southam	CONTACT:	Clare Eynon (LPA) 01789 260326
SITE NAME:		CONTACT:	Clare Eynon (LPA) 01789 260326
	Southam		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

WARWICK

VARVICK						
	SITE NAME:	Hunningham Bridge, Hunningham / Weston under Wetherley	Hunningham Bridge is a mid-C17 structure of sandstone ashlar spanning the river Leam and is currently in use as a public highway. The structure has had extensive repairs			
	DESIGNATION:	Scheduled Monument, LB grade II	following two incidents in 2015 which resulted in two demolished sections of the parapet. Unfortunately the bridge has been hit again since these repairs were			
	CONDITION:	Good	completed. The bridge remains at risk until traffic calming			
	OCCUPANCY:	N/A	measures can be reviewed and installed at the site to protect the bridge from further incidents.			
	PRIORITY CATEGORY:	F (F)				
Historic England	OWNER TYPE:	Local authority				
	LIST ENTRY NUMBER:	1005770	Contact: Marie Twomey 0121 625 6838			
No.	SITE NAME:	Remains of Old Castle Bridge, Mill Street, Warwick	Remains of a late medieval bridge. Ownership is split ways. Earlier proposals for stabilisation were very co and beyond available resources. It has been propose			
AN UL	DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I, CA	ownership should be transferred to a trust who would co- ordinate restoration and funding but this has not progressed. Historic England has advised the owner of the			
	CONDITION:	Very bad	southernmost section regarding eradication of Japanese Knotweed in order to facilitate inspection and repair of th			
	OCCUPANCY:	N/A	structure. Addressing the Knotweed will take several year			
	PRIORITY CATEGORY:	C (C)				
Historic England Archive	OWNER TYPE:	Mixed, multiple owners				
	LIST ENTRY NUMBER:	1005772 and 1035499	Contact: Marie Twomey 0121 625 6838			
-	SITE NAME:	Masters House, Warwick	The Leper Hospital of St Michael was founded in the C12:			
	DESIGNATION:	Listed Building grade II*, SM	the Master's House survives and is a timber framed buildir of C15 date built upon C12 foundations. The timber fram			
A BOOLESS A	CONDITION:	Very bad	and roof covering are in very poor condition and Urgent			
	OCCUPANCY:	Vacant/not in use	Works were undertaken by Warwick District Council in 2019 to keep the building weatherproof and maintain its			
	PRIORITY CATEGORY:	B (B)	structural stability. Platform Housing Group and the West Midlands Building Preservation Trust are in discussions wit			
	OWNER TYPE:	Private	the owner to acquire the site and develop the Master's			
	LIST ENTRY NUMBER:	1364850	House, St Michael's Chapel and the adjoining area for unsupported social housing.			
D Historic England Archive			Contact: John Tiernan 0121 625 6839			
	SITE NAME:	Church of All Saints, Bath Street, Royal Leamington Spa	This is an impressive Church. The design is a Continental Gothic bold and ornate. It was begun in 1843 by Dr. John Crait the Vicar with Architect LC Jackson Sir Arthur			
A A A	DESIGNATION:	Listed Place of Worship grade II*, CA	Craig the Vicar with Architect J.C. Jackson. Sir Arthu Blomfield added the West tower and two nave bays apse window (1851) has glass by Chance of Birming The Church has had major repairs undertaken throu years but because it is a large and complicated church			
	CONDITION:	Poor				
	PRIORITY CATEGORY:	C (C)	major issues have remained like the high level stonework			
	OWNER TYPE:	Religious organisation	and the glass of the windows.			
) Historic England	LIST ENTRY NUMBER:	1381145	Contact: Chris Miners 0117 975 1355			
A d Dit						
	SITE NAME:	Church of St Mary including Beauchamp Chapel, Warwick	This parish church was founded as a Collegiate Church in 1123. The nave, aisles, transept and tower were rebuilt by Sir W Wilson after the great fire of 1694, although the			
	DESIGNATION:	Listed Place of Worship grade I, CA	chancel dating from the C14 remained. The Beauchamp Chapel is an excellent example of Perpendicular design.			
Then I HE	CONDITION:	Poor	The church has fan vaulted ceilings and stone carvings. St Mary's has undergone much repair in recent years but the			
In a land the	PRIORITY CATEGORY:	C (C)	stonework is soft Arden stone and the tower requires			
	OWNER TYPE:	Religious organisation	urgent repair as it suffers from falling masonry. The congregation are exploring sources of funding for the			
	LIST ENTRY NUMBER:	1035500	repairs.			
© Historic England			Contact: Chris Miners 0121 625 6835			
RIORITY CATEGORIES			ABBREVIATIONS			
 A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. B Immediate risk of further rapid 	 D Slow decay; solution not yet implemented E Under repair or in farepair, but no user i 	d. (where applicable) end use c air to good user identified; or functional	nd NOTE CA Conservation Area or Last year's priority category is LB Listed Building y shown in brackets (otherwise, LPA Local Planning Authority			

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

use).

redundant buildings with new use agreed but not yet implemented.

- LPA
 Local Planning Authority

 NP
 National Park

 RPG
 Registered Park and Garden

 SM
 Scheduled Monument

 UA
 Unitary Authority

 WHS
 World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / WARWICK

MA 1	SITE NAME:	Church of St Michael, Rugby Road, Weston under Wetherley	Parish church in red sandstone ashlar situated in an elevated position with evidence of a C12 church in the north and south walls of the chancel. The red sandstone
	DESIGNATION:	Listed Place of Worship grade I	stonework is in extremely poor condition at all levels with delamination, open joints and hollow sections, erosion,
	CONDITION:	Poor	cracking and inappropriate repairs. Some structural cracks are present. Deformation on the south elevation appears
	PRIORITY CATEGORY:	A (A)	stable.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1325524	Contact: Chris Miners 0121 625 6835
oric England			

© Historic England

ALC: N

SITE NAME:	Roman settlement at Glasshouse Wood, Ashow /	Kenilworth			
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER:	1005723		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No		
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Marie Twomey 0121 625 6838		
site name:	Circular ditches enclosures south west of Wiggerland Wood Farm, Bishop's Tachbrook				
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003740		
CONDITION:	Unknown	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No		
OWNER TYPE:	Private				
SITE NAME:	Guy's Cave hermitage and other rock cut chamber	rs at Guy's Cliffe, Le	eek Wootton and Guy's Cliffe		
DESIGNATION:	Scheduled Monument, LB grade II, RPG grade II	LIST ENTRY NUMBER:	1019129		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No		
OWNER TYPE:	Religious organisation	Neil Rimmington 07775 550 674			
SITE NAME:	Wedgnock Park pale, dam, two watermill sites, bri Farm, Leek Wootton and Guy's Cliffe	dge and hollow way	y 200 metres north east of Goodrest		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013159		
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838		
SITE NAME:	Enclosures 410 metres north east of Sherbourne p	parish church, Shert	oourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005711		
CONDITION:	Unknown	TREND:	Unknown		
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY ?:	No		
OWNER TYPE:	Private	CONTACT:	Marie Twomey 0121 625 6838		
SITE NAME:	Warwick Castle (uninhabited parts), Warwick				
DESIGNATION:	Scheduled Monument, part in RPG grade I, CA	LIST ENTRY NUMBER:	1005757		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No		
OWNER TYPE:	Local authority	CONTACT:	Neil Rimmington 07775 550 674		

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / WARWICK / BIRMINGHAM

HERITAGE AT RISK 2022 / MIDLA	NDS / WARWICK / BI	RMINGHAM		
SITE NAME:	Enclosures and drove road 90 metres south of Manor House Farm, Wasperton			
DESIGNATION:	Scheduled Monu	Scheduled Monument		1005712
CONDITION:	Unknown		TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing		NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners		CONTACT:	Marie Twomey 0121 625 6838
	SITE NAME:	Stoneleigh Abbey, Stoneleigh / Ashow	Complex multi-phase landscape, incorporating a medie deer park and work by Repton, Nesfield and Percy Car The deer park is now a golf course. A business park and residential enclaves have been built within the historic landscape. A programme of restoration of the cascades bridges and other water features has been undertaken through the Natural England Stewardship scheme. Othe parts of the historic estate remain vulnerable. The route HS2 will separate the west and east sections of the registered park.	
	DESIGNATION:	Registered Park and Garden grade II*, 30 LBs, 2 SMs, part in CA		
	CONDITION:	Generally satisfactory but with significant localised problems		
	VULNERABILITY:	High		
© Historic England	TREND:	Improving		
O FIISTORIC England	NEW ENTRY ?:	Νο		

	- And
色於將編	the t
JTWATE,	

		and the second se	San A
	H		
			ì
A		-	

© Historic England

		-	
all see	TREND:	Improving	
	NEW ENTRY?:	No	
OWNER TYPE:		Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000377	Contact: Erika Diaz Petersen 0121 625 6879
	SITE NAME:	Guy's Cliffe, Warwick / Leek Wootton and Guy's Cliffe / Old Milverton	Picturesque landscape either side of the River Avon. The main house is in a ruinous state. The chapel is now a Masonic temple. Derelict gardens are periodically cleared
	DESIGNATION:	Registered Park and Garden grade II, 9 LBs, SM	by volunteers. Most of the park has been ploughed and the majority of parkland trees lost.
	CONDITION:	Extensive significant problems	
The second	VULNERABILITY:	High	
	TREND:	Declining	
	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER: 1001602		Contact: Erika Diaz Petersen 0121 625 6879

WEST MIDLANDS

BIRMINGHAM

Built in 18998-9 as the Birmingham Library (a private Birmingham Midland Institute, 9 SITE NAME: member's library) by F. Barry Peacock of architects Margaret Street B3 3BU Cossins, Peacock and Bewlay. Red brick, two storey DESIGNATION: Listed Building grade II*, CA building, plus basement and attic, with stone dressing and green stone tiled roof built in Jacobean. Two end gables CONDITION: Fair Entrance OC erior is torium and PRIC inwater nternal OW LIST

© Historic England

	i uli	reflect the neighbouring School of Art. Original E
CCUPANCY:	Occupied/in use	hall and staircase have been retained altered inte
IORITY CATEGORY:	C (New entry)	accommodating a concert hall, a basement audite an extension in 95 Cornwall St. The roof and rain
WNER TYPE:	Charity (non-heritage)	goods are in very poor condition affecting the int plasterwork with loss of fabric.
T ENTRY NUMBER:	1343095	Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / BIRMINGHAM					
	SITE NAME:	Highbury Hall, Yew Tree Road, Birmingham	Highbury Hall was built in 1879 as the family home of Joseph Chamberlain and designed by local architect JH		
	DESIGNATION:	Listed Building grade II*, RPG grade II	Chamberlain. It is a large and ornate brick and stone house surrounded by landscaped gardens. The interior of the house is elaborate and uses a variety of different materials.		
	CONDITION:	Poor	Currently the ground floor is used for events, but the upper two floors are vacant. The Main Hall and Northern		
	OCCUPANCY:	Part occupied/part in use	Range roofs were repaired in 2020. The Highbury Trust		
	PRIORITY CATEGORY:	C (C)	has received Stage I for an NLHF grant for repair and redevelopment of the hall.		
	OWNER TYPE:	Local authority			
© Historic England	LIST ENTRY NUMBER:	1076076	Contact: Cristina Gardiner 0121 625 6850		
	SITE NAME:	British Rail Goods Office (Curzon Street Station), Birmingham	Terminus of the London to Birmingham railway designed by Philip Hardwick. Built in 1837-8 in the Ionic style. The building is owned by the City Council and has been vacant		
	DESIGNATION:	Listed Building grade I	for more than a decade. Repairs to the roof have been undertaken, but water ingress is still a problem. Renovation		
	CONDITION:	Fair	by a partnership including HS2 has permission and the works commenced in 2021.		
	OCCUPANCY:	Vacant/not in use			
	PRIORITY CATEGORY:	F (F)			
	OWNER TYPE:	Local authority			
© Historic England	LIST ENTRY NUMBER:	1343086	Contact: Nick Molyneux 0121 625 6857		
4	SITE NAME:	Methodist Central Hall, Corporation Street, Birmingham	A substantial building of 1903-4 by E. and J.A. Harper in r brick and terracotta. The ground floor has various retail uses, otherwise entirely vacant. Permission was granted i		
A LANDER AND	DESIGNATION:	Listed Building grade II*, CA	2018 for hotel use but was never implemented. The site was purchased by new owners in early 2022. An		
	CONDITION:	Poor	application for conversion into several uses has been submitted to Birmingham City Council. Its condition has		
	OCCUPANCY:	Part occupied/part in use	deteriorated following recent storms. Historic England and		
	PRIORITY CATEGORY:	D (D)	the Council are working with the new owners to secure emergency temporary works to halt water ingress whilst		
	OWNER TYPE:	Commercial company	the applications are considered.		
© Historic England	LIST ENTRY NUMBER:	1075607	Contact: Sophie Clarke 0121 625 6828		
1	SITE NAME:	The Red Lion Public House, Soho Road, Birmingham	Public house, built 1901-2 by James & Lister Lea for the Holt Brewery Company. Built of red brick with a terracotta		
	DESIGNATION:	Listed Building grade II*	facade. The building is of notable completeness. Leaking roofs and windows and ingress of pigeons have caused		
	CONDITION:	Fair	significant problems. A new owner undertook urgent works, including repairs to roof, and gained Listed Building		
	OCCUPANCY:	Vacant/not in use	Consent for re-use as a public house/ restaurant. It was		
	PRIORITY CATEGORY:	C (C)	sold in 2016 and the new owner has plans to redevelop the site.		
	OWNER TYPE:	Commercial company			
© Historic England	LIST ENTRY NUMBER:	1276278	Contact: Sophie Clarke 0121 625 6828		
The MA	SITE NAME:	Perrott's Folly, Waterworks Road, Edgbaston	Built in 1758 by John Perrott as a folly adjacent to his house (long demolished). A six storey structure with circular stair tower attached. Adjoining waterworks tower said to be		
	DESIGNATION:	Listed Building grade II*	inspiration for Tolkien's 'The Two Towers'. Repairs		
	CONDITION:	Poor	addressing structural issues were completed some years ago and in 2021 a Toilet was added to improve the		
	OCCUPANCY:	Part occupied/part in use	usability of the space by visitors' groups. The structure is		
	PRIORITY CATEGORY:	B (B)	structurally stable but the roof and the ornate plaster ceiling on the top of the tower and the needs repairing		
	OWNER TYPE:	Other not for profit group	from the considerable damaged caused by rainwater penetration.		
© Historic England	LIST ENTRY NUMBER:	1076123	Contact: Cristina Gardiner 0121 625 6850		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

131

HERITAGE AT RISK 2022 / MIDLANDS / BIRMINGHAM

N. K	SITE NAME:	303 Icknield Street, Hockley	Built in 1883, by Martin and Chamberlain, The building was the Headmaster's house attached to Icknield Street School
	DESIGNATION:	Listed Building grade II*	(List No. 1076315) one of the Birmingham Board Schools.
	CONDITION:	Very bad	The domestic brick and terracotta building, with a tiled roof underwent unauthorised work which was halted. The
	OCCUPANCY:	Vacant/not in use	building is currently empty, in very poor condition and
	PRIORITY CATEGORY:	A (A)	suffering on-going rapid deterioration.
	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1291556	Contact: Cristina Gardiner 0121 625 6850

© Historic England

n m

	SITE NAME:	Public Baths, Moseley	Municipal baths with lavish terracotta decoration and
	DESIGNATION:	Listed Building grade II*	complete interiors. The baths were opened in 1907 as an addition to the Free Library (1895) forming a group of
	CONDITION:	Poor	public buildings. Threat of closure has been averted with the swimming group taking over the swimming operation
	OCCUPANCY:	Part occupied/part in use	until 2021. Following the repair of the Gala Pool roof,
	PRIORITY CATEGORY:	A (A)	Historic England is currently providing a substantial gra towards the repair of the Boardroom Roof and Front
	OWNER TYPE:	Local authority	facade in conjunction with Birmingham City Council and the World Monument Fund which will be completed in
	LIST ENTRY NUMBER:	1076274	August 2022.
			Contact: Cristina Gardiner 0121 625 6850

© Historic England

uilt in 1901 as the vicarage to St Agatha's Church in parkbrook and designed in an Arts and Crafts style by
nitect, W.H. Bidlake. Formerly
a housing association, the building is ship but has been subject to heritage
ering from dry rot and isolated
alised repairs have been carried out nding lack of regular maintenance with
g windows and other issues continuing.
ke 0121 625 6828

© Historic England

	SITE NAME:	Holy Church of the New Testament, 11-13 Oughton Road, Birmingham, B12 0DF and Friends Institute 220 Moseley Road, Birmingham	The building was commissioned by Richard Cadbury, designed by Ewan and James Harper it was completed in 1897. It contained to the front (Moseley Road) the Friends Institute with a coffee room a reading room, 37 classrooms for adult education and Sunday school and a large lecture
	DESIGNATION:	Listed Place of Worship grade II*	room for 400 people on the first floor. To the rear (Oughton Street) the building houses a large hall with 2000
	CONDITION:	Poor	worshippers' capacity with a gymnasium hall. The hall is now the Holy Church of the New testament; its roof and
	PRIORITY CATEGORY:	C (New entry)	rainwater goods are in poor condition.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1418995	Contact: Cristina Gardiner 0121 625 6850



SITE NAME: DESIGNATION: CONDITION: PRIORITY CATEGO OWNER TYPE:	SITE NAME:	Edward Road Baptist Church, Edward Road, Birmingham	This is an example of the Birmingham Terracotta School's work which combines Romanesque and Perpendicular
	DESIGNATION:	Listed Place of Worship grade II	details. There is evidence of damp at high level, the roof needs attention, the gutters need cleaning and the joints to
	CONDITION:	Poor	brick and terracotta blocks are badly eroded.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1343405	Contact: Cristina Gardiner 0121 625 6850

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022	/ MIDLANDS / BIRMINGHAM

HERITAGE AT RISK 2022 / MIDLA	NDS / BIRMINGHAM		
	SITE NAME:	Parish Church of All Sints (formerly St. Aidan), Herbert Road B10, Small Heath, Birmingham	Designed by TF Proud in 1893, this church is an example of local red bricks and buff terracotta, designed in the Perpendicular style with a lofty nave and clearstory windows. Two further bays and the apsidal baptistery were
	DESIGNATION:	Listed Place of Worship grade II*	added in 1898. The nave north roof is in poor condition with many slipped tiles. Rainwater goods are also in poor
H. A. H.	CONDITION:	Poor	condition. The building suffers from dampness through, walls and columns show the presence of salt efflorescence,
	PRIORITY CATEGORY:	D (D)	past cementicious repairs have compounded moisture
	OWNER TYPE:	Religious organisation	retention. The church has revceived a grant for the reainwatergoods completed by Autumn 2021.
© Historic England	LIST ENTRY NUMBER:	1343050	Contact: Cristina Gardiner 0121 625 6850
	SITE NAME:	Church of St Benedict, Hob Moor Road, Birmingham	Good example of a Byzantine revival Church, 1909, by Nichol and Nichol of Birmingham. It is a substantial church
	DESIGNATION:	Listed Place of Worship grade II	built in red brick and stone dressing and a plain tile roof. It has a basilica plan and the aisles and clearstories have
A Manh	CONDITION:	Poor	parapets. The apse, with battered buttresses and a dome roof, complements the overall good design of the church.
	PRIORITY CATEGORY:	C (C)	The church is in poor condition: the high-level brickwork,
	OWNER TYPE:	Religious organisation	due to leaking parapets gutters, has open joints and damp patches. The stonework is also badly eroded throughout.
	LIST ENTRY NUMBER:	1076300	The ashfelted dome and barrel roofs have also come to the end of their life.
© Historic England			Contact: Cristina Gardiner 0121 625 6850
	SITE NAME:	Church of St Michael, St Michael's Road, Birmingham	Large church on Soho Hill dating from 1855 by W. Bourne. Built in red Hollington stone with sandstone features and
AN	DESIGNATION:	Listed Place of Worship grade II, CA	string courses all fairly badly eroded. Nave roof is in poor condition causing rain water entry due to dislodged roof tiles especially on the s/w corner, the south aisle roof is in
	CONDITION:	Very bad	very poor condition. There is rain staining internally at junction between Lady Chapel and a turret. Rain water
	PRIORITY CATEGORY:	B (B)	goods in poor condition throughout. There are cracks in
	OWNER TYPE:	Religious organisation	the masonry and some of the buttresses; pointing at high level is badly eroded. Glass missing from leaded windows.
© Llistenia England	LIST ENTRY NUMBER:	1076210	Cold internally.
© Historic England			Contact: Cristina Gardiner 0121 625 6850
	SITE NAME:	Church of St Paul, St Paul's Square, Birmingham	Classical design by Roger Eykyn of Wolverhampton and built in 1777-9 although the upper part of the Spire and
	DESIGNATION:	Listed Place of Worship grade I, CA	tower was added in 1822-3 by Frances Goodwin. The church sits on the corner of the then Newhall estate and was given by Charles Colmore. 'Bilston Rag' stone with
	CONDITION:	Poor	rusticated quoins and Gibbs-style surrounds. The interior is classical. The church is suffering from severe issues from
	PRIORITY CATEGORY:	D (D)	leaking parapet gutters and rain water entry which has
	OWNER TYPE:	Religious organisation	damaged the interior plasterwork. The condition of the rainwater goods is also poor; there is shaling stonework
N Participation of the second	LIST ENTRY NUMBER:	1220815	and vegetation at high level.
© Historic England			Contact: Cristina Gardiner 0121 625 6850
	SITE NAME:	Church of St Nicholas, The Green, Birmingham	Large sandstone Church of Norman origins with nave, aisles chancel and south porch. Its outstanding feature is
	DESIGNATION:	Listed Place of Worship grade I, CA	the C15 spire and tower in 4 stages which is a local landmark. The Church has several urgent issues especially because it is built in soft sandstone and the stonework.
	CONDITION:	Poor	Repairs to the tower's stonework has been completed.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
© L listenia Fradra d	LIST ENTRY NUMBER:	1075549	Contact: Cristina Gardiner 0121 625 6850
© Historic England			

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / BIRMINGHAM

	SITE NAME:	Parish Church of St Peter and St Paul, Witton Lane, Birmingham	The original Anglican church dates from 1084, although nothing survives. The current large church dates from
	DESIGNATION:	Listed Place of Worship grade II*, CA	1879-90, the west tower from cr. C15, repaired in 1776. The south porch by J. A. Chatwin was added in 1908. The church is built in soft Hollington sandstone, which is very
	CONDITION:	Poor	poor in places with open joints. The spire weight and tie need addressing, as do the rainwater goods throughout.
	PRIORITY CATEGORY:	C (C)	Internally the timber block flooring is subject to rot and
	OWNER TYPE:	Religious organisation	insect infestation and need replacing.
	LIST ENTRY NUMBER:	1290008	Contact: Cristina Gardiner 0121 625 6850

© Historic England

© Historic England



	SITE NAME:	Church of St George, Westbourne Crescent, Edgbaston, Birmingham	Constructed in three separate phases to the design of JJ Scoles (1836-38), Charles Edge (1855-7) and JA Chatwin (1884-5) in a light coloured Alvechurch sandstone and a
	DESIGNATION:	Listed Place of Worship grade II, CA	slate roof. The two southern aisles were part of the origina first phase and the chancel north east vestry and tower were added to these in the second phase. The current
	CONDITION:	Fair	large nave and chancel replaced the former south aisle. The roof, rainwater goods and high level stonework were
	PRIORITY CATEGORY:	D (D)	repaired and a scheme for masonry repairs to the vestry is
	OWNER TYPE:	Religious organisation	now being planned but more high level stonework repairs are still needed.
	LIST ENTRY NUMBER:	1211414	Contact: Cristina Gardiner 0121 625 6850

A	SITE NAME:	lcknield Street School, Icknield Street, Hockley	Large Birmingham Board School designed in 1883 by Martin and Chamberlain. The building is partly occupied on
	DESIGNATION:	Listed Place of Worship grade II*	the ground floor as a Hindu temple for the purpose of worship and community use; the upper floors are vacant.
A J J MAN	CONDITION:	Very bad	The building is in poor condition generally: the steep slate roofs and valley gutters leak to the spaces below and the
	PRIORITY CATEGORY: OWNER TYPE:	A (A)	rainwater goods are in poor condition resulting in
		Local authority, multiple owners	rainwater entry affecting both roof and walls. Negotiations between the owners, the Council, and the tenants are on-
	LIST ENTRY NUMBER:	1076315	going and essential surveys have taken place.
			Contact: Cristina Gardiner 0121 625 6850

© Historic England

SITE NAME:	Kent's Moat			
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1020538
CONDITION:	Generally satisfactory but with significant localised problems		TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management		NEW ENTRY?:	No
OWNER TYPE:	Local authority		CONTACT:	Marie Twomey 0121 625 6838
	SITE NAME:	Highbury Hall	Gardens and landscaped grounds of 1879 by Edward Milner associated with a contemporary villa built for Josej Chamberlain. Greater part of grounds a public park since early C20. The condition of the park and gardens has declined significantly. Original built landscape features and water features are in poor condition. Disrupted drainage causing erosion and waterlogging problems. A successful phase of repair and restoration work has been undertake with Historic England and National Lottery Heritage Func support. A further grant from NLHF is supporting project development.	
	DESIGNATION:	Registered Park and Garden grade II, LB grade II*		
	CONDITION:	Generally unsatisfactory with major localised problems		
	VULNERABILITY:	Medium		
	TREND:	Improving		
	NEW ENTRY?:	No		
© Historic England	OWNER TYPE:	Local authority, multiple owners		
	LIST ENTRY NUMBER:	1001203	Contact: Erika D	iaz Petersen 0121 625 6879

SITE NAME:	Austin Village		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Chris Patrick 0121 3033910

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / BIRMINGHAM / COVENTRY

SITE NAME:	Barnsley Road		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Chris Patrick 0121 3033910
SITE NAME:	Digbeth / Deritend		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Julie Shaduwa 0121 3034527
SITE NAME:	Four Oaks		
DESIGNATION:	Conservation Area, 28 LBs, part in RPG grade II, part in SM	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Chris Patrick 0121 3033910
SITE NAME:	Lozells and Soho Hill		
DESIGNATION:	Conservation Area, 38 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	High	CONTACT:	Chris Patrick 0121 3033910
SITE NAME:	School Road		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Julie Shaduwa 0121 3034527
SITE NAME:	Steelhouse		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Chris Patrick 0121 3033910
SITE NAME:	Warwick Bar		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Julie Shaduwa 0121 3034527

COVENTRY



D

Е

use).

SITE NAME:	Numbers 36 and 37 and archway in between (Whitefriars Gate), Much Park Street
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1087114

This CI4 postern gatehouse of the Carmelite Friary has a clay tile roof and sandstone walls with later repairs in brickwork. The building was subject to heritage crime in 2008 and later repaired: it has remained vacant since then and is slowly deteriorating. The continuing threat of heritage crime, assorted masonry repairs and renewal of defective floor timbers above the archway are all issues to be addressed. A grant application has been made to Historic England by the historic Coventry Trust to assist with repairs to be completed by March 2023.

© Coventry HER 2014

Contact: Cristina	Gardiner 0121	625 6850
-------------------	---------------	----------

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / COVENTRY

	SITE NAME:	Basement on site of Old Star Inn, Earl Street, Coventry	Late medieval cellar of an inn now incorporated in the Civic Centre. Significant erosion of the sandstone took place as a
	DESIGNATION:	Listed Building grade II*	result of water damage. The stone vault was propped in 2008 and damaged stonework repaired. The buildings
	CONDITION:	Fair	above (with the exception of the recently listed former architects' offices) have been demolished. No site
	OCCUPANCY:	Vacant/not in use	inspection has been possible this year.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1115642	Contact: Nick Molyneux 0121 625 6857

© Historic England

© Historic England



	SITE NAME:	Nonconformist Chapel to the Cemetery, London Road, Coventry	This cemetery was designed by Joseph Paxton in 1843 and opened in 1847. The Nonconformist Chapel located at the southern end of the cemetery is part of that design but
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	attributed by the VCH to George Taylor. The Chapel is configured as a Greek temple with a portico entrance and flanking open pavilions but is currently disused and in a
	CONDITION:	Fair	vulnerable condition. The Historic Coventry Trust has plans for the cemetery to become part of a Heritage Park
	OCCUPANCY:	Vacant/not in use	and the chapel to be converted for office use. A grant
	PRIORITY CATEGORY:	D (E)	application has been made to Historic England to assist with repair works to complete in 2023.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1076624	Contact: Cristina Gardiner 0121 625 6850



SITE NAME: Church of St Mark and The church of St Mark was built in 1869 and consists of a boundary walls to Stoney clerestoried nave with aisles, a chancel, north porch and south vestry: the west end of the north aisle also has a tall Stanton Lane and Bird Street bell-cote. A church hall extension was added to the south DESIGNATION: Listed Place of Worship grade II side in 1962. Following closure in 1973, the church was internally remodelled and converted to a hospital CONDITION: Poor outpatient's department. Now relicensed and re-ordered PRIORITY CATEGORY: C (C) for public worship, it has a catalogue of building fabric defects that require urgent attention including reroofing OWNER TYPE: Religious organisation works, the renewal of rainwater goods, drainage and assorted high-level masonry repairs. LIST ENTRY NUMBER: 1104904 Contact: John Tiernan 0121 625 6839

	SITE NAME:	Church of St John the Baptist, Fleet Street, Coventry	The church of St John the Baptist is located at the head of Spon Street in the city centre. Built in the mid-C14, it was a
	DESIGNATION:	Listed Place of Worship grade I, CA	collegiate church and is largely Perpendicular in appearance with a crossing tower, transepts, clerestories to nave and chancel and aisles. Changes of plan are visible in several
	CONDITION:	Poor	places together with alterations to the fabric. The red sandstone used in its construction is of variable quality a its repair and maintenance is an on-going issue, in
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	particular, the condition of the nave clerestory. Defective transept roof coverings will also require renewal in the
	LIST ENTRY NUMBER:	1342889	future.
listoric England			Contact: John Tiernan 0121 625 6839

© His

© Historic England

SITE NAME:	Allesley Castle		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005907
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Neil Rimmington 07775 550 674

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / COVENTRY / DUDLEY

A FRONT	SITE NAME:	Stoney Road Allotments	A group of mid and late C19 detached urban pleasure
COVENTR	DESIGNATION:	Registered Park and Garden grade II*, 5 LBs	gardens retaining a nationally significant group of C19 and early C20 summerhouses and associated structures. The site is still actively used as allotments and tenanted by the
	CONDITION:	Generally unsatisfactory with major localised problems	Stoney Road Gardens Association (SRGA). The summer houses are the principal elements at risk, and have not been maintained since listing in 2001. A conservation
	VULNERABILITY:	Medium	management plan has been produced (2018) for the
NF2/2/2 相子	TREND:	Declining	gardens but not yet formally adopted. A grant from the National Lottery Heritage Fund has funded a condition
计自己分离器的过去式	NEW ENTRY?:	No	survey and feasibility study.
© Historic England	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1001494	Contact: Erika Diaz Petersen 0121 625 6879

SITE NAME:	Lady Herbert's Garden, Coventry		
DESIGNATION:	Conservation Area, 9 LBs, RPG grade II, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Coventry City Council Planning 02476831109
SITE NAME:	London Road, Coventry		
DESIGNATION:	Conservation Area, 10 LBs, part in RPG grade I, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Coventry City Council Planning 02476831109
SITE NAME:	Naul's Mill, Coventry		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Coventry City Council Planning 02476831109

DUDLEY

© Historic England

	SITE NAME:	Triangular Crane, Bumble Hole Boat Yard, Dudley	C19 triangular boat crane in very poor condition. Historic England funded a report on the condition and repair of the
	DESIGNATION:	Scheduled Monument, CA	monument in 1997. An application for Historic England funding was made but later withdrawn as no match funding
	CONDITION:	Very bad	was available for the repairs. The crane collapsed in 2002 and sections of structure remained stored in the yard. A
	OCCUPANCY:	N/A	joint initiative between Historic England, the Canal mov
	PRIORITY CATEGORY:	A (A)	the remains to secure storage and options of its reinstatement as a fixed crane are being investigated.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1005884	Contact: Cristina Gardiner 0121 625 6850



W.	SITE NAME:	Church of St Edmund, Castle Street, Dudley	Situated in the centre of Dudley, this red brick church (known locally as 'bottom church') was built in the Palladian
	DESIGNATION:	Listed Place of Worship grade II*, CA	style in the 1720s. Repair to the tower funded by the National Lottery Heritage Fund have been completed but issues with the shallow tiled roofs of the nave and its stone
	CONDITION:	Poor	parapets remain. The roof rain water drainage is also in fairly poor condition.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1287455	Contact: Cristina Gardiner 0121 625 6850

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / DUDLEY



SITE NAME:	Parish Church of St Thomas, High Street, Dudley	Large Georgian church built in Perpendicular style (known locally as 'top church'), designed by William Brooks from
DESIGNATION:	Listed Place of Worship grade II*, CA	1815 to 1818. The current church is a replacement of a medieval chapel, the remains of which are visible in the crypt. The church received a National Lottery Heritage
CONDITION:	Poor	Fund Grants for Places of Worship award in 2014 for high level stonework, which was shaling away in large sections
PRIORITY CATEGORY:	C (C)	and these repairs have been completed. However, there
OWNER TYPE:	Religious organisation	are more repairs needed to the pinnacles and parapet walls which will be addressed by the grant funding by the
LIST ENTRY NUMBER:	1075998	National Heritage Lottery.
		Contact: Cristina Gardiner 0121 625 6850

© Historic England



	SITE NAME:	Church of St James the Great, Salop Street, Dudley	A Commissioners' church of the mid-C19, designed by William Bourner. Sister church to St John the Evangelist,		
	DESIGNATION:	Listed Place of Worship grade II	Kate's Hill. The church is built of limestone with ashlar stone dressings. Emergency roof repairs carried out in		
	CONDITION:	Poor	2015 have revealed extensive significant problems with the roof of the nave.		
	PRIORITY CATEGORY:	A (A)			
	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1270305	Contact: Cristina Gardiner 0121 625 6850		

© Historic England

SITE NAME:	Dudley Castle		
DESIGNATION:	Scheduled Monument, 6 LBs, CA	LIST ENTRY NUMBER:	1014042
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Brierley Hill High Street		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jayne Pilkington, CMIFA, IHBC (LPA) 01384 814168
SITE NAME:	Stourbridge Branch Canal (Canal Street)		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Jayne Pilkington, CMIFA, IHBC (LPA) 01384814168
SITE NAME:	Wollaston		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington, CMIFA, IHBC (LPA) 01384 814168
SITE NAME:	Wordsley Church		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jayne Pilkington, CMIFA, IHBC (LPA) 01384 814168

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.

C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / SANDWELL / SOLIHULL

SANDWELL

SANDIVELL			
188 B	SITE NAME:	Soho Foundry, Foundry Lane, Smethwick	Foundry built in 1795: the world's first integrated steam engine manufactory, established by Boulton & Watt.
	DESIGNATION:	Listed Building grade II*, SM	Historic England and the local authority grant aided a temporary roof to stabilise the structure in 2009. That roof
	CONDITION:	Poor	is still protecting the core historic building. A local trust is in discussion with the owners to take on the ownership.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
The second	OWNER TYPE:	Commercial company	
© Historic England Archive	LIST ENTRY NUMBER:	1268451	Contact: Nick Molyneux 0121 625 6857
	SITE NAME:	Waterloo Hotel, Shireland Road, Smethwick	The Waterloo Hotel was built in 1907 by Wood and Kendrick for local brewers, Mitchells & Butler, in the
	DESIGNATION:	Listed Building grade II*, CA	baroque style with terracotta dressings. This is a near complete example of an Edwardian showpiece pub and

		Road, officiation	
	DESIGNATION:	Listed Building grade II*, CA	baroque style with terracotta dressings. This is a near complete example of an Edwardian showpiece pub and
	CONDITION:	Poor	commercial hotel, which retains many interior features including the ornately tiled basement grill room. The upper
San morel	OCCUPANCY:	Part occupied/part in use	floors have been converted into flats and are partially
	PRIORITY CATEGORY:	C (C)	occupied. Neglect of the ground floor and basement, leaking rainwater goods, broken window panes and the
	OWNER TYPE:	Commercial company	poor condition of joinery and basement railings put the building at risk.
	LIST ENTRY NUMBER:	1261644	Contact: Sophie Clarke 0121 625 6828

SITE NAME: Chances Glassworks, Smethwick LIST ENTRY NUMBER: DESIGNATION: Scheduled Monument, 5 LBs, CA 1021387 Generally unsatisfactory with major localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY ?: No Deterioration - in need of management OWNER TYPE: CONTACT: Nick Carter 0121 625 6860 Commercial company, multiple owners SITE NAME: High Street, West Bromwich, Black Country DESIGNATION: Conservation Area, 11 LBs NEW ENTRY? No CONDITION: Very bad TREND: No significant change VULNERABILITY: CONTACT: Mark Stretton (LPA) 0121 569 4033 Low SITE NAME: Market Place, Wednesbury, Black Country DESIGNATION: NEW ENTRY? No Conservation Area, 2 LBs CONDITION Very bad Improving VULNERABILITY: CONTACT: Mark Stretton (LPA) 0121 569 4033 Low

SOLIHULL

© Historic England



	SITE NAME:	Walford Hall Farmhouse, Solihull Road, Hampton in Arden	Grade II* listed C15 hall with cross wing, altered in C16 by extending it upwards to provide a first floor. Two storeys with pitched gabled roof with red terracotta tiles finish.
P	DESIGNATION:	Listed Building grade II*	Timber framed with later brick infills on red sandstone base and foundations. Two large brick chimneys each with 3
	CONDITION: Very bad OCCUPANCY: Vacant/not in use	star-shaped flues and elaborate capping. Flush casement windows, 1:2:1 with very fine astragals protected by	
		Vacant/not in use	boarding. The farmhouse is surrounded by a group of
-	PRIORITY CATEGORY: A (New entry)		agricultural buildings part of the listing. In very poor condition despite having undergone emergency repairs to
	OWNER TYPE:	Commercial company	patch up the roofs.
	LIST ENTRY NUMBER:	1342830	Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG

Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

Bit Number Church of S. Matthew, Church Hill, Watall Shatthew, Shurch Hill, Watall Shatthew,	HERITAGE AT RISK 2022 / MIDLAI	NDS / WALSALL			
Hill, Valsall Hiss config spine is a local landmark and list of performance of the spine of the stand out in the struct score. The syle of the shurch is predominantly Perpendical, Perpe	WALSALL				
Instantion Listed Place of Worship grade columnals church is predominantly Perpendicule, but C13 remains north also and north transport are needed. There is a needed mode in corth transport are needed. There is a needed mode in corth also and north transport are needed. There is a needed mode in corth also and north transport are needed. There is a needed mode in corth also and north transport are needed. There is a needed mode in corth also and north transport are needed. There is a needed mode in corth also and north transport are needed. There is a need mode in corth also and north transport are needed. There is a need mode in corth also and north transport are needed. There is a need windows throughout the church. If is and Light Mission Church (former Trinty Methodist Church J, Lindows and platescry, making it prominert on the street fronzage. A National Lottery Herings Fund and Historic countrols. Science and Historic Countrols. If is and Light Mission Church (former Trinty Methodist Church J, Lindows and platescry, making it prominert on the street fronzage. A National Lottery Herings Fund and Historic countrols. Science and Historic Countrols. If is a maxing it prominer to mode in a program development work vasis completed. The render is loose in many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the street for a many areas allowing with Maxing and the s		SITE NAME:		Its soaring spire	is a local landmark and its Bath stone
For repairs to the paraget gutters and governal trace. For repairs to the paraget gutters and windows throughout the church. Present replan Religious organisation windows throughout the church. Present replan Lat Definition of the formation of the classical sceneory, and the large cast iron windows throughout the church. Present replan STE NME Life and Light Mission Church (former Trinity Methodst Church, bin the Classical step, with round headst withenal and paraget and paraget. Present replant STE NME Life and Light Mission Church (former Trinity Methodst Church, bin the Classical step, with round headst with round headst replane Replant Grants for Present year, with replant to construct the paraget development work was completed. The render is loose in many areas allowing water to enter the bilding. STE NAME Religious organisation Contact: Cristina Gardiner 0121 625 6850 STE NAME Religious organisation New Year STE NAME Religious organisation New Year STE NAME Baroford Street, Walstall Neardford Street, Walstall		DESIGNATION:		church is predo survive in the cr	minantly Perpendicular, but Ć13 remains ypt. Repairs to the Welsh slated nave,
Incontrolation B (B) downpipes, fighl sevel stone-work and the large cast iron windows throughout the church. PHain's inglue Life and Light sign organisation Contact: Cristina Gardner 0121 625 6850 PHAIN's inglue Life and Light Mission Church Built as a Methodisk church in the 1860s, this large reaction windows shoughout the church. PHAIN's inglue Jate And Light Mission Church Built as a Methodisk church in the 1860s, this large reaction windows and plasters. making it pointent on the street church is in the Classical style, with rough head windows and plasters. making it pointent on the street church is in the Classical style, with rough head windows and plasters. making it pointent on the street church is in the Classical style, with rough head windows and plasters. making it pointent on the street church is in the Classical style, with rough head windows and plasters. making it pointent on the street church is in the Classical style, with rough head windows and plasters. making it pointent on the street church is in the Classical style, with rough head windows and plasters. making it pointent on the street church is in the Classical style, with rough head windows and plasters. The reaction with response on the street church is in the Classical style, with rough head windows and plasters. The reaction with response on the street church is in the Classical style, with rough head windows and plasters. The reaction with response on the street church is in the Classical style, with rough head windows and plasters. The reaction with response on the street church is in the Classical style, with response on the street church is in the Classical style, with response on the street church is in the Classical style, with response on theas street church is in		CONDITION:	Poor		
Bowerse England Owner Training Methods in Unit Market II 16 [5] Contact: Cristina Gardiner 0121 625 6850 Britanci England Still AMP (Lippe Mission Church Church), Joinon Street, Church, Joinon Street, Church, Joinon Street, Church, Joinon Street, Church, Joinon Street, Church, Joinon Street, Contact: Cristina Gardiner 0121 625 6850 Prease Highest Still American Church, Joinon Street, Contact: Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Contact Cristina Cristina Contact Cristina Cristina Conta		PRIORITY CATEGORY:	В (В)	downpipes; high	n level stonework and the large cast iron
Performance England Termande Term		OWNER TYPE:	Religious organisation	windows throug	ghout the church.
Bit MMIC Bit MMIC Life and Light Mission Church former Trinity Methodis: Willenhall Built as a Mathodist church in the 1860s, this large endered durch in the Cassical cycle, with no the starter formage. A National Lottery Phrase Fund and Historic Finance Eigen Bit MMIC Listed Place of Worship gradel Li, CONBITON Descent will phrase fund and Historic Finance Eigen Procent will be and the Eigen Starter Starter Work was acceived but only project dependent work was acceived but only project dependent acceived but only project dependent acceiv		LIST ENTRY NUMBER:	1116151	Contact: Cristin	na Gardiner 0121 625 6850
Image: Control Trinity Methodis: Church Ju Jinho Street, Willenhall Jinhouth Jeader Street, Willenhall Jinhouth Jeader Street, Willenhall Jinhouth Jeader Jinhouth Jinho	D Historic England				
Descent notive Listed Place of Worship grade II, CA received but only project development work was completed. The render is loss in many areas allowing water to enter the building. Defense Registed Poor Religious organisation UNIVER TYRE A (A) Defense Registed Religious organisation UNIVER TYRE No DEFENSE Registed IOT7170 Contact: Cristina Gardiner 0121 625 6850 STE NAME: Bloxwich High Street No DESIGNATION Very bad No significant change CONDITION Very bad No significant change VALNERABILITY: Low No STE NAME: Bradford Street, Walsall No DESIGNATION Very bad No VALNERABILITY: Medium Conservation Area, 5 LBs New UNITYS: DESIGNATION Conservation Area, 12 LBs No VALNERABILITY: Low No Inproving VALNERABILITY: Conservation Area, 12 LBs No Inproving VALNERABILITY: Low Conservation Area, 12 LBs No Inproving VALNERABILITY: Low Conser		SITE NAME:	(former Trinity Methodist rendered church Church), Union Street, windows and p		h is in the Classical style, with round heade ilasters, making it prominent on the street ional Lottery Heritage Fund and Historic
Defense England Float Float Defense England Notiner CATECONE A (A) Defense England List ENTRY INLINESE 1077170 Contact: Cristina Gardiner 0121 625 6850 STEENAME: Bloxwich High Street No Contact: Cristina Gardiner 0121 625 6850 DEFENSE England Conservation Area NEW ENTRY: No CONDITION Very bad TREND: No significant change VUINRAMEITY: Low CONTACT: Walsall Council Planning 01922650000 STENAME: Bradford Street, Walsall Deteriorating DESGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VUINRAMEITY: Medium contact: Cristina Gardiner 01922650000 STENAME: Bridge Street, Walsall Deteriorating DESGNATION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Very bad TREND: Improving VUINRAMEITY: Low contract: Walsall Council Planning 01922650000 STENAME:	T ALL THE	DESIGNATION:		received but on	ly project development work was
Bestore: Engend OWNER TITLE: Religious organisation Bestore: Engend UST ENTRY NUMBER: 1077170 Contact: Cristina Gardiner 0121 625 6850 SITE NAME: Bloxwich High Street New ENTRY: No DISSIGNATION: Conservation Area New ENTRY: No CONDITON: Very bad TREND: No significant change VUINERABLITY: Low constract: Walsall Council Planning 01922650000 SITE NAME: Bradford Street, Walsall New ENTRY: No OSIGNATION: Conservation Area, S LBs New ENTRY: No OSIGNATION: Conservation Area, IZ Bgrade II New ENTRY: No OSIGNATION: Conservation Area, LB grade II New ENTRY: No OSIGNATION: Conservation Area, LB grade III		CONDITION:	Poor	water to enter t	the building.
INSTRUCTION ENTRY NUMBER: 1077170 Contact: Cristina Gardiner 0121 625 6850 STE NAME Bloxwich High Street New KNTRY: No DESIGNATION: Conservation Area NEW KNTRY: No CONDITION: Very bad TREND: Walsell Council Planning 01922650000 STE NAME Bradford Street, Walsall CONTACT: Walsell Council Planning 01922650000 STE NAME Bradford Street, Walsall No Concornation DESIGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VILINERABILITY: Medium CONTACT: Walsall Council Planning 01922650000 STE NAME Bridge Street, Walsall No Conservation Area, 12 LBs No OSIGNATION: Conservation Area, LB grade II No No Conservation Area, LB grade II No CONDITION: Very bad TEND: No Conservation Area, LB grade II No Conservation Area, SLBS, RPG grade II* No Conservation Area, SLBS, SMI No ConTACT: Walsall Council		PRIORITY CATEGORY:	A (A)		
LISTENTRY NUMBER: 1077170 Contract: Cristina Gardiner 0121 625 6850 SITE NAME: Bloxwich High Street No DESIGNATION. Conservation Area NEW ENTRY: No CONDITION: Very bad TREND: No significant change UNINERABULTY: Low CONTACT: Walsall Council Planning 01922650000 STEE NAME: Bradford Street, Walsall Descionation Conservation Area, LBas No CONDITION: Conservation Area, LBas New ENTRY: No Descionation CONDITION: Conservation Area, 12 LBs New ENTRY: No No CONDITION: Conservation Area, 12 LBs New ENTRY: No No CONDITION: Conservation Area, 12 LBs New ENTRY: No No CONDITION: Conservation Area, LB grade II New ENTRY: No No CONDITION: Conservation Area, LB grade II New ENTRY: No No CONDITION: Conservation Area, LB grade II New ENTRY: No No CONDITION: Conservation Area, LB gr	© Historic England	OWNER TYPE:	Religious organisation		
DESIGNATION: Conservation Area NEW ENTRY: No CONDITION: Very bad TREND: No significant change VULNERABULTY: Low CONTACT: Walsall Council Planning 01922650000 STIE NAME: Bradford Street, Walsall No DESIGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VULNERABULTY: Medium CONTACT: Walsall Council Planning 01922650000 STIE NAME: Bridge Street, Walsall Deteriorating VULNERABULTY: Medium CONTACT: Walsall Council Planning 01922650000 STIE NAME: Bridge Street, Walsall Improving Improving VULNERABULTY: Low CONTACT: Walsall Council Planning 01922650000 VILNERABULTY: Low CONTACT: Walsall Council Planning 01922650000 STIE NAME: Conservation Area, LB grade II No No UNRERABUTY: Low CONTACT: Walsall Council Planning 01922650000 STIE NAME: Conservation Area, LB grade II <td< td=""><td>o ··-</td><td>LIST ENTRY NUMBER:</td><td>1077170</td><td>Contact: Cristin</td><td>na Gardiner 0121 625 6850</td></td<>	o ··-	LIST ENTRY NUMBER:	1077170	Contact: Cristin	na Gardiner 0121 625 6850
DESIGNATION: Conservation Area NEW ENTRY: No CONDITION: Very bad TREND: No significant change VULNERABULTY: Low CONTACT: Walsall Council Planning 01922650000 STIE NAME: Bradford Street, Walsall No DESIGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VULNERABULTY: Medium CONTACT: Walsall Council Planning 01922650000 STIE NAME: Bridge Street, Walsall Deteriorating Very 500000 VULNERABULTY: Medium CONTACT: Walsall Council Planning 01922650000 STIE NAME: Bridge Street, Walsall Improving Improving VULNERABULTY: Low CONTACT: Walsall Council Planning 01922650000 VILNERABULTY: Low CONTACT: Walsall Council Planning 01922650000 STIE NAME: Conservation Area, LB grade II NeW ENTRY: No UNLNERABULTY: Low CONTACT: Walsall Council Planning 01922650000 STIE NAME: Conserva					
CONDITION! Very bad TREND: No significant change VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 STRE MARE: Bradford Street, Walsall NEW ENTRY: No DESIGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VULNERABILITY: Medium CONTACT: Walsall Council Planning 01922650000 STRE NAME: Bridge Street, Walsall CONTACT: Walsall Council Planning 01922650000 STRE NAME: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Conservation Area, 12 LBs NEW ENTRY: No VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 STRE NAME: Caldmore Green, Walsall NEW ENTRY: No CONDITION: Conservation Area, LB grade II NEW ENTRY: No STRE NAME: Conservation Area, LB grade II NEW ENTRY: No significant change VULNERABILITY: Conservation Area, 17 LBs, RPG grade II* No Neighticant change VULNERABILITY: Conservation Area, 17 LBs, RPG grade II* No Neighticant change <t< td=""><td>SITE NAME:</td><td>Bloxwich High St</td><td>reet</td><td></td><td></td></t<>	SITE NAME:	Bloxwich High St	reet		
VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Bradford Street, Walsall New ENTRY: No DESIGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VULNERABILITY: Medium CONTACT: Walsall Council Planning 01922650000 SITE NAME: Bridge Street, Walsall CONTACT: Walsall Council Planning 01922650000 SITE NAME: Bridge Street, Walsall NEW ENTRY: No CONDITION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Caldmore Green, Walsall Improving DESIGNATION: Conservation Area, LB grade II NEW ENTRY: No CONDITION: Very bad TREND: No significant change VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Church Hill, Walsall New ENTRY: No DESIGNATION: Conservation Area, 17 LBs, RPG grade II* New ENTRY: No CONDITION: Very bad TREND: Improving	DESIGNATION:	Conservation Are	ea	NEW ENTRY?:	No
STIE NAME Bradford Street, Walsall DESIGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating VULNERABILITY: Medium CONTACT: Walsall Council Planning 01922650000 STIE NAME: Bridge Street, Walsall NEW ENTRY: No DESIGNATION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 STIE NAME: Caddmore Green, Walsall CONTACT: Walsall Council Planning 01922650000 STIE NAME: Cadmore Green, Walsall NEW ENTRY: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY: No CONDITION: Very bad TREND: Walsall Council Planning 01922650000 STIE NAME: Conservation Area, 17 LBs, RPG grade II* No Significant change VULNERABILITY: Low Conservation Area, 17 LBs, RPG grade II* No Significant Change VULNERABILITY: Conservation Area, 17 LBs, RPG grade II* No Significant Ch	CONDITION:	Very bad		TREND:	No significant change
DESIGNATION: Conservation Area, 5 LBs NEW ENTRY: No CONDITION: Very bad TREND: Deteriorating vULRERABILITY: Medium CONTACT: Walsall Council Planning 01922650000 SITE NAME: Bridge Street, Walsall Very bad NEW ENTRY?: No CONDITION: Conservation Area, 12 LBs NEW ENTRY?: No CONDITION: Very bad TREND: Improving VULRERABILITY: Low CONTACT: Walsall Council Planning 01922650000 STE NAME: Caldmore Green, Walsall NEW ENTRY?: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY?: No significant change VULRERABILITY: Low CONTACT: Walsall Council Planning 01922650000 STE NAME: Conservation Area, LB grade II NEW ENTRY?: No significant change VULRERABILITY: Low CONTACT: Walsall Council Planning 01922650000 STE NAME: Conservation Area, 17 LBs, RPG grade II* No No CONDITION: Very bad TREND: No	VULNERABILITY:	Low		CONTACT:	Walsall Council Planning 01922650000
CONDITION:Very badTREND:DeterioratingVULNERABILITY:MediumCONTACT:Walsall Council Planning 01922650000stTE NAME:Bridge Street, WalsallNEW ENTRY:NoDESIGNATION:Conservation Area, 12 LBsNEW ENTRY:NoCONDITION:Very badTREND:ImprovingvulnerabilitY:LowCONTACT:Walsall Council Planning 01922650000STE NAME:Caldmore Green, WalsallCONTACT:Walsall Council Planning 01922650000STE NAME:Caldmore Green, WalsallNEW ENTRY:NoCONDITION:Very badNEW ENTRY:No Significant changeVULNERABILITY:Conservation Area, LB grade IINEW ENTRY:No significant changeVULNERABILITY:Conservation Area, 17 LBs, RPG grade II*No Significant changeVULNERABILITY:Conservation Area, 17 LBs, RPG grade II*NoSTE NAME:Conservation Area, 17 LBs, RPG grade II*NoCONDITION:Very badTREND:NoCONDITION:Very badTREND:NoSTE NAME:Elmore Green, BloxwichTREND:NoSTE NAME:Elmore Green, BloxwichSitter NAME:NoSTE NAME:Elmore Green, BloxwichSitter NAME:NoSTE NAME:Conservation Area, 3 LBs, SMNEW ENTRY:NoSTE NAME:Very badTREND:No significant changeVULNERABILITY:Very badTREND:No significant change	SITE NAME:	Bradford Street,	Walsall		
VULRERABILITY: Medium CONTACT: Walsall Council Planning 01922650000 SITE NAME: Bridge Street, Walsall DESIGNATION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Caldmore Green, Walsall CONTACT: Walsall Council Planning 01922650000 SITE NAME: Conservation Area, LB grade II NEW ENTRY: No CONDITION: Very bad TREND: No significant change VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Conservation Area, LB grade II NEW ENTRY: No SITE NAME: Conservation Area, 17 LBs, RPG grade II* NEW ENTRY: No SITE NAME: Conservation Area, 17 LBs, RPG grade II* New ENTRY: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Elmore Green, Bloxwich No Site NATO:	DESIGNATION:	Conservation Are	ea, 5 LBs	NEW ENTRY?:	No
sitte name: Bridge Street, Walsall DESIGNATION: Conservation Area, 12 LBs New ENTRY?: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Caldmore Green, Walsall New ENTRY?: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY?: No CONDITION: Very bad TREND: No significant change VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 VULNERABILITY: Conservation Area, 17 LBs, RPG grade II* No Significant change VULNERABILITY: Conservation Area, 17 LBs, RPG grade II* No Improving VULNERABILITY: Low Contact:: Walsall Council Planning 01922650000 VULNERABILITY:	CONDITION:	Very bad		TREND:	Deteriorating
DESIGNATION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Very bad TREND: Improving VULNERABILITY: Conduction Contact: Walsall Council Planning 01922650000 STE NAME: Caldmore Green, Walsall NEW ENTRY: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY: No CONDITION: Very bad TREND: No significant change VULNERABILITY: Low Contact: Walsall Council Planning 01922650000 STE NAME: Church Hill, Walsall NEW ENTRY: No significant change VULNERABILITY: Conservation Area, 17 LBs, RPG grade II* No No CONDITION: Very bad TREND: No CONDITION: Conservation Area, 17 LBs, RPG grade II* No No CONDITION: Very bad TREND: No STE NAME: Elmore Green, Bloxwich Steventry: No STE NAME: Elmore Green, Bloxwich Steventry: No CONDITION: Very bad NEW ENTRY: No	VULNERABILITY:	Medium		CONTACT:	Walsall Council Planning 01922650000
DESIGNATION: Conservation Area, 12 LBs NEW ENTRY: No CONDITION: Very bad TREND: Improving VULNERABILITY: Conduction Contact: Walsall Council Planning 01922650000 STE NAME: Caldmore Green, Walsall NEW ENTRY: No DESIGNATION: Conservation Area, LB grade II NEW ENTRY: No CONDITION: Very bad TREND: No significant change VULNERABILITY: Low Contact: Walsall Council Planning 01922650000 STE NAME: Church Hill, Walsall Contact: Walsall Council Planning 01922650000 DESIGNATION: Conservation Area, 17 LBs, RPG grade II* No No CONDITION: Very bad TREND: Improving VULNERABILITY: Low Contact: Walsall Council Planning 01922650000 STE NAME: Conservation Area, 17 LBs, RPG grade II* No No CONDITION: Very bad TREND: No STE NAME: Elmore Green, Bloxwich Stername Stername STE NAME: Elmore Green, Bloxwich Stername No CONDITION:	SITE NAME:	Bridge Street, W	alsall		
VULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000SITE NAME:Caldmore Green, WalsallNEW ENTRY:NoDESIGNATION:Conservation Area, LB grade IINEW ENTRY:NoCONDITION:Very badTREND:No significant changeVULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000SITE NAME:Church Hill, WalsallCONTACT:Walsall Council Planning 01922650000SITE NAME:Conservation Area, 17 LBs, RPG grade II*NoNoCONDITION:Very badTREND:ImprovingVULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000SITE NAME:Conservation Area, 17 LBs, RPG grade II*New ENTRY:NoCONDITION:Very badTREND:ImprovingVULNERABILITY:Elmore Green, BloxwichWalsall Council Planning 01922650000SITE NAME:Elmore Green, BloxwichVery badNew ENTRY:DESIGNATION:Conservation Area, 3 LBs, SMNEW ENTRY:NoCONDITION:Very badTREND:No significant change	DESIGNATION:	Conservation Are	ea, 12 LBs	NEW ENTRY ?:	No
SITE NAME: Caldmore Green, Walsall DESIGNATION: Conservation Area, LB grade II NEW ENTRY?: No CONDITION: Very bad TREND: No significant change VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Church Hill, Walsall CONTACT: Walsall Council Planning 01922650000 SITE NAME: Conservation Area, 17 LBs, RPG grade II* New ENTRY?: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 STE NAME: Elmore Green, Bloxwich Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Elmore Green, Bloxwich Very bad No DESIGNATION: Conservation Area, 3 LBs, SM NEW ENTRY?: No CONDITION: Very bad TREND: No significant change	CONDITION:	Very bad		TREND:	Improving
DESIGNATION: Conservation Area, LB grade II NEW ENTRY?: No CONDITION: Very bad TREND: No significant change VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Church Hill, Walsall NEW ENTRY?: No DESIGNATION: Conservation Area, 17 LBs, RPG grade II* NEW ENTRY?: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low Conservation Area, 17 LBs, RPG grade II* New ENTRY?: No CONDITION: Very bad TREND: Improving Improving VULNERABILITY: Low Contact: Walsall Council Planning 01922650000 VULNERABILITY: Low Contact: Walsall Council Planning 01922650000 STE NAME: Elmore Green, Bloxwich VULNERABIL State Conservation Area, 3 LBs, SM New ENTRY?: No STEINTON: Very bad Yery bad TREND: No significant change	VULNERABILITY:	Low		CONTACT:	Walsall Council Planning 01922650000
CONDITION:Very badTREND:No significant changeVULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000SITE NAME:Church Hill, WalsallNEW ENTRY:NoDESIGNATION:Conservation Area, 17 LBs, RPG grade II*NEW ENTRY:NoCONDITION:Very badTREND:ImprovingVULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000SITE NAME:Elmore Green, BloxwichCONTACT:Walsall Council Planning 01922650000SITE NAME:Conservation Area, 3 LBs, SMNEW ENTRY:NoCONDITION:Very badTREND:No significant change	SITE NAME:	Caldmore Green	, Walsall		
CONDITION:Very badTREND:No significant changeVULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000site NAME:Church Hill, WalsallNEW ENTRY:NoDESIGNATION:Conservation Area, 17 LBs, RPG grade II*NEW ENTRY:NoCONDITION:Very badTREND:ImprovingVULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000SITE NAME:Elmore Green, BloxwichCONTACT:Walsall Council Planning 01922650000SITE NAME:Conservation Area, 3 LBs, SMNEW ENTRY:NoCONDITION:Very badTREND:No significant change	DESIGNATION:			NEW ENTRY?:	No
VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Church Hill, Walsall	CONDITION:		-	TREND:	No significant change
DESIGNATION: Conservation Area, 17 LBs, RPG grade II* NEW ENTRY?: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Elmore Green, Bloxwich VEW ENTRY?: No DESIGNATION: Conservation Area, 3 LBs, SM NEW ENTRY?: No CONDITION: Very bad TREND: No significant change	VULNERABILITY:			CONTACT:	
DESIGNATION: Conservation Area, 17 LBs, RPG grade II* NEW ENTRY?: No CONDITION: Very bad TREND: Improving VULNERABILITY: Low CONTACT: Walsall Council Planning 01922650000 SITE NAME: Elmore Green, Bloxwich VEW ENTRY?: No DESIGNATION: Conservation Area, 3 LBs, SM NEW ENTRY?: No CONDITION: Very bad TREND: No significant change	SITE NAME:	Church Hill, Wal	sall		
CONDITION:Very badTREND:ImprovingVULNERABILITY:LowCONTACT:Walsall Council Planning 01922650000SITE NAME:Elmore Green, BloxwichVery badVery badDESIGNATION:Conservation Area, 3 LBs, SMNEW ENTRY:NoCONDITION:Very badTREND:No significant change	DESIGNATION:	Conservation Are	ea, 17 LBs, RPG grade II*	NEW ENTRY?:	No
SITE NAME: Elmore Green, Bloxwich DESIGNATION: Conservation Area, 3 LBs, SM CONDITION: Very bad	CONDITION:			TREND:	Improving
DESIGNATION: Conservation Area, 3 LBs, SM NEW ENTRY?: No CONDITION: Very bad TREND: No significant change	VULNERABILITY:	Low		CONTACT:	Walsall Council Planning 01922650000
DESIGNATION: Conservation Area, 3 LBs, SM NEW ENTRY?: No CONDITION: Very bad TREND: No significant change	SITE NAME:	Elmore Green. B	loxwich		
CONDITION: Very bad TREND: No significant change	DESIGNATION:			NEW ENTRY?:	No
	CONDITION:			TREND:	
	VULNERABILITY:			CONTACT:	Walsall Council Planning 01922650000

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

140

WALSALL / SANDWELL

RK	SITE NAME:	Great Barr Hall, Walsall	Parkland and pleasure grounds, partly by Humphry Repton
	DESIGNATION:	Registered Park and Garden grade II, 3 LBs, part in CA	and John Nash. Much of the historic park was built over as a hospital in C20, in turn replaced by a modern housing estate. Due to longstanding lack of regular maintenance,
	CONDITION:	Extensive significant problems	the pleasure grounds and planting around the lakes are now completely overgrown. The banks of the lakes are
ALL STATIST	VULNERABILITY:	High	being eroded, though repairs to some outfalls and spillways
State State	TREND:	Declining	were carried out in 2017. Proposals for conversion of the hall to a hotel and new housing in the park have been
18 Di 105	NEW ENTRY?:	No	refused, and the house and associated land were put up for sale in 2021.
toric England	OWNER TYPE:	Private, multiple owners	Sale III 2021.
	LIST ENTRY NUMBER:	1001202	Contact: Erika Diaz Petersen 0121 625 6879

WOLVERHAMPTON, CITY OF

© Histo

©

	SITE NAME:	St Luke, Blakenhall	Gothic Revival church by GT Robinson of Learnington in
	LIST ENTRY NUMBER:	1201819	Contact: Cristina Gardiner 0121 625 6850
© Historic England	OWNER TYPE:	Commercial company	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	Occupied/in use	
	CONDITION:	Very bad	
	DESIGNATION:	Listed Building grade II*	a long term solution.
	SITE NAME:	The Greyhound and Punchbowl Inn (formerly Stoke Heath Manor House), High Street, Bilston	Mid-C16 manor house, restored in the 1930s. Of timber framed construction, strengthened with concrete skin in the 1930s. Now suffering from complex structural problems to the supporting concrete frame, which requires
	SITE NAME:	The Greybound and Punchbowl	Mid-C16 manor house restored in the 1930s. Of tim

	SITE NAME:	St Luke, Blakenhall	Gothic Revival church by GT Robinson of Leamington in
	DESIGNATION:	Listed Building grade II*	polychromatic brickwork erected in 1860. The decorated spire is a local landmark in the Blakenhall area. Closed as a
	CONDITION:	Poor	church in 2017 the building is now in use as an antiques centre. Rainwater goods remain in poor condition with
	OCCUPANCY:	Occupied/in use	leaks affecting the brickwork and wall structure. Most ro
	PRIORITY CATEGORY:	C (C)	show evidence of slipped or broken slates with the abutment of the north aisle with the nave being a particular
	OWNER TYPE:	Commercial company	problem, the reainwater goods are poor and the walls are extremely damp with loss of plaster.
	LIST ENTRY NUMBER:	1293038	Contact: Cristina Gardiner 0121 625 6850

© Historic England



SITE NAME:	Church of St Leonard, Church Street, Wolverhampton	This church was built in 1825 to designs by Francis Goodwin, and restored in the 1880s by Ewan Christian. It
DESIGNATION:	Listed Place of Worship grade II	is in the neoclassical style, finished in render with round headed windows and an octagonal tower. The interior has
CONDITION:	Poor	decorative plaster ceilings and balconies. The church was repairedLeaking parapet gutters are affecting the render
PRIORITY CATEGORY:	E (E)	externally and the plaster internally.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1282492	Contact: Cristina Gardiner 0121 625 6850

© Historic England

	SITE NAME:	Methodist Church, Darlington Street, Wolverhampton	Large Methodist Church dating from 1900-01 by Arthu Marshall, built on a previous church. Classical baroque		
	DESIGNATION:	Listed Place of Worship grade II*	built in brick and ashlar ground floor and dressings stone. Symmetrical facade with pediment and two stone towers		
	CONDITION:	Poor	and a large central cupola covered in copper over the main hall with 3-bay tunnel vaults with groin vaulted aisles and a		
	PRIORITY CATEGORY:	C (C)	semi-circular balcony. The church complex has undergor		
	OWNER TYPE:	Religious organisation	many alterations although it also retains many original features. The roof and rainwater goods are in poor		
	LIST ENTRY NUMBER:	1201807	condition and ongoing lack of maintenance.		
			Contact: Cristina Gardiner 0121 625 6850		

© Historic England

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB
- LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Church of St Martin and	Church cloister	and vicarage built 1938-9 by Lavander and	
1111	SHE NAHL.	attached cloister and vicarage, Dixon Street, Wolverhampton	Twentyman. Bri coped gables an	ick Modernist church with pantile roofs, d parapets. The elevations are plain excep	
FILL .	DESIGNATION:	Listed Place of Worship grade II		f St Martin by Donald Potter on the west e entrance. The interior is remarkably	
22640	CONDITION:	Poor		ch was originally lined with asbestos, which The roof and gutters are in need of repair so	
	PRIORITY CATEGORY:	C (C)	that leaks do no	t disturb the asbestos below. Previous	
	OWNER TYPE:	Religious organisation		eant the building was closed until the aks was repaired. Subsequently	
	LIST ENTRY NUMBER:	1282500		repair is needed.	
© Historic England			Contact: Cristin	a Gardiner 0121 625 6850	
Mini	SITE NAME: Catholic Church of St Mary and St John, Snow Hill, Wolverhampton		and extended 1 roof, it has an a	Roman Catholic Church built 1851-5 by Charles Hansom and extended 1879-80. Built in ashlar stone with a slate roof, it has an apsidal chancel and French Gothic treatment	
B SAAAAA	DESIGNATION:	Listed Place of Worship grade II*		outh side of the nave were carried out al Lottery Heritage Fund Grant for Places o	
	CONDITION:	Poor	Worship in 201	6. However, the north side also requires	
	PRIORITY CATEGORY:	C (C)	rain water pipes	to the high level stonework, gutters and	
The state	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1208140	Contact: Cristin	a Gardiner 0121 625 6850	
© Historic England					
SITE NAME:	Bilston Canal Co	rridor			
DESIGNATION:	Conservation Are	ea	NEW ENTRY?:	No	
CONDITION:	Very bad		TREND:	No significant change	
VULNERABILITY:	Low		CONTACT:	James Holliday 01902555622	
SITE NAME:	Bilston Town Ce	ntre			
DESIGNATION:	Conservation Are	ea	NEW ENTRY ?:	No	
CONDITION:	Very bad		TREND:	Deteriorating	
VULNERABILITY:	Low		CONTACT:	James Holliday 01902555622	
SITE NAME:	Bushbury Hill				
DESIGNATION:	Conservation Are	ea	NEW ENTRY?:	Νο	
CONDITION:	Very bad		TREND:	Deteriorating	
VULNERABILITY:	Medium		CONTACT:	James Holliday 01902555622	
				, ,	
SITE NAME:	Cleveland Road				
DESIGNATION:	Conservation Are	ea	NEW ENTRY?:	No	
CONDITION:	Very bad		TREND:	Improving	
VULNERABILITY:	High		CONTACT:	James Holliday 01902555622	
SITE NAME:	Park				
DESIGNATION:	Conservation Are	ea	NEW ENTRY?:	No	
CONDITION:	Poor		TREND:	Deteriorating	
VULNERABILITY:	Medium		CONTACT:	James Holliday 01902555622	
SITE NAME:	Springfield Brewe	ery			
DESIGNATION:	Conservation Are		NEW ENTRY ?:	No	
CONDITION:	Very bad		TREND:	Improving significantly	
VULNERABILITY:	High		CONTACT:	James Holliday 01902555622	
				,,,,	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / WOLVERHAMPTON, CITY OF / DUDLEY / BROMSGROVE

	The Oaks (Merridale Road)		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	James Holliday 01902555622
SITE NAME:	Union Mill		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	James Holliday 01902555622
SITE NAME:	Worcester Street		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	James Holliday 01902555622

WEST MIDLANDS / WORCESTERSHIRE

SI

DUDLEY / BROMSGROVE

SITE NAME:	Wychbury Camp (see also Bromsgrove, Worcestershire), Hagley			
DESIGNATION:	Scheduled Monument	1005900		
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY ?:	No	
OWNER TYPE:	Private, multiple owners	CONTACT:	Nick Carter 0121 625 6860	

WORCESTERSHIRE

BROMSGROVE

	1.0000000000000000000000000000000000000
	1000
	The state
	Fr-S
	き 注意 長島
A PARTY ROLL	ALL INSIGN
the set of	18.00.2005
and the second second second	Contraction of the

SITE NAME:	Temple of Theseus, Hagley Hall, Hagley	Doric temple of 1758 designed by James 'Athe Stewart. It stands in a grade I registered park a
DESIGNATION:	Listed Building grade I, RPG grade I	800 metres north of Hagley Hall. It is separate rest of the estate by the A456. This relatively location has rendered it vulnerable to vandalis
CONDITION:	Poor	fencing has been erected. Discussions continu owner on a strategy to secure the future of th
OCCUPANCY:	N/A	new, permanent visitor centre on the estate g
PRIORITY CATEGORY:	C (C)	planning permission in 2014. Construction of t building has not yet started; a temporary visito
OWNER TYPE:	Private	given consent in 2021.
LIST ENTRY NUMBER:	1348599	Contact: Erika Diaz Petersen 0121 625 6879

pric temple of 1758 designed by James 'Athenian' ewart. It stands in a grade I registered park and garden 0 metres north of Hagley Hall. It is separated from the t of the estate by the A456. This relatively isolated ation has rendered it vulnerable to vandalism so security cing has been erected. Discussions continue with the rner on a strategy to secure the future of the building. A w, permanent visitor centre on the estate gained nning permission in 2014. Construction of the main Iding has not yet started; a temporary visitor centre was en consent in 2021.

© Historic England



SITE NAME:	Hewell Grange, Tutnall and Cobley	Grand red sandstone former country house designed by architects Bodley & Garner in 1884-91 for Lord and Lady
DESIGNATION:	Listed Building grade I, RPG grade II*, CA	Windsor, later the Earl and Countess of Plymouth. Celebrated as one of the most important late 19th century country houses in England, with an accomplished blend of
CONDITION:	Fair	architectural styles. From 1946 the house was used by HM Prison Service as a borstal, and latterly as an open prison to
OCCUPANCY:	Vacant/not in use	HMP Hewell until its closure in autumn 2020. The site was
PRIORITY CATEGORY:	C (C)	placed on the market in early 2022. Historic England are working closely with the Ministry of Justice to secure its
OWNER TYPE:	Government or agency	sustainable future use.
LIST ENTRY NUMBER:	1100160	Contact: Steven McLeish 0121 625 6884

© Historic England

PRIORITY CATEGORIES	

D

Е

use).

Immediate risk of further rapid deterioration or loss of fabric; no А

- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / BROMSGROVE

	SITE NAME:	Church of St John the Baptist, St Johns Street, Bromsgrove	Large grade I urban church ina large churchyard near the centre of Bromsgrove. Much stonework repair is being
	DESIGNATION:	Listed Place of Worship grade I, 2 CAs	reported as urgent by the inspecting church architect, especially the spire.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1100363	Contact: Chris Miners 0121 625 6835
© Historic England			

		1
	1	10
about	91-	1 . 1
17 2	1	

	SITE NAME:	Church of St Laurence, Bear Hill, Alvechurch, Alvechurch	Large parish church. Mostly rebuilt between 1860 and 1861 by W Butterfield retaining only a C15 tower which was
	DESIGNATION:	Listed Place of Worship grade II*, CA	rémodelled in 1676. Badly eróded sandstone is affected by damp, especially on the north side and in the tower. Rainwater goods are in poor condition and the leaded
AL AN	CONDITION:	Poor	windows are also deteriorating. The church was awarded a National Lottery Heritage Fund Grant for Places of
	PRIORITY CATEGORY:	D (D)	Worship in February 2017 to fund repairs which has
	OWNER TYPE:	Religious organisation	addressed most of the faults.
5-19	LIST ENTRY NUMBER:	1100225	Contact: Chris Miners 0121 625 6835

© Historic England

	SITE NAME:	Christ Church, Catshill, Catshill and North Marlbrook	Large suburban parish church. Nave and west tower built in 1838 by Harvey Eginton and the east end of chancel and
	DESIGNATION:	Listed Place of Worship grade II	flanking chapels rebuilt by JA Chatwin in 1887, mostly in the Early English style. Red sandstone ashlar with slate
	CONDITION:	Poor	roofs. The sandstone is heavily eroded with harmful vegetation growth. Many leaks have sprung from the failing
	PRIORITY CATEGORY:	A (A)	parapet gutters.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1099541	Contact: Chris Miners 0121 625 6835

© Historic England

© Histor

	SITE NAME:	Hewell Grange, Tutnall and Cobley / Bentley Pauncefoot	Multi-phase landscape, including work influenced by 'Capability' Brown and Humphry Repton. Another period
	DESIGNATION:	Registered Park and Garden grade II*, 23 LBs, part in CA	of activity took place towards the end of C19 when the current house was built. Post-war development by the Prison Service has had a major impact on the legibility of
	CONDITION:	Extensive significant problems	the design. A management plan and partnership with the County Gardens Trust has led to renewed interest in and
	VULNERABILITY:	High	care for the designed landscape, including restoration of
	TREND:	Stable	key features. Following closure in autumn 2020, Historic England is working closely with the Ministry of Justice to
	NEW ENTRY?:	No	secure its sustainable future use.
oric England	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000886	Contact: Erika Diaz Petersen 0121 625 6879

SITE NAME:	Bromsgrove Town Centre, Centred on the High Street/Worcester Road,			
DESIGNATION:	Conservation Area, 53 LBs	No		
CONDITION:	Very bad	TREND:	Improving	
VULNERABILITY:	Low	CONTACT:	Mary Worsfold (LPA) 01527 881329	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

MALVERN HILLS



C15 timber framed farmhouse which originated as a cruck SITE NAME: Stone Farmhouse and attached Hop Kiln, Bromyard Road, framed hall house and was enlarged in the C16 and C19. There is a late C19 brick hop kiln attached on the rear Broadwas gable. The building has a medieval roof and timber framing. The condition of the hop kiln roof is very bad. The house DESIGNATION: Listed Building grade II* roof tiling is very bad in places. Some major work has been CONDITION: Very bad completed to repair and replace sections of the timber frame, reinstating a gable end. New owners are now OCCUPANCY: Occupied/in use developing a more comprehensive repair scheme. PRIORITY CATEGORY: B (B) OWNER TYPE: Private LIST ENTRY NUMBER: 1082977 Contact: Steven McLeish 0121 625 6884

© Historic England

© Historic England



	SITE NAME:	Chapel and Cloister at the Convent of the Holy Name, Ranelagh Road, Malvern	Former chapel designed by Comper & Bucknell in 1891-3 which forms part of a complex of buildings associated with the former Convent of the Holy Name. The building has
	DESIGNATION:	Listed Building grade II*, CA	been redundant for some years following the closure of the convent. The site is subject to applications for residential
	CONDITION:	Poor	redevelopment, however the chapel is suffering from blocked gutters and poor roofs. The future of the chapel
	OCCUPANCY:	Vacant/not in use	will be an integral part of any successful proposal for the
	PRIORITY CATEGORY:	C (C)	redevelopment of the area.
in the second se	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1082736	Contact: Steven McLeish 0121 625 6884

2	SITE NAME:	Church of St Mary, Church End, Hanley Castle	Large rural parish church. Largely C14 nave and north aisle with C17 rebuilt tower and east end. Interior is from the		
the second	DESIGNATION:	Listed Place of Worship grade II*, CA	1858 restoration. The tiled roofs of the nave and south porches need renewal. The sandstone ashlar needs localised repair.		
	CONDITION:	Poor			
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Religious organisation			
	LIST ENTRY NUMBER:	1349232	Contact: Chris Miners 0121 625 6835		

© Historic England Archive



Large medieval church of the Benedictine Priory, founded SITE NAME: Priory Church of St Mary and St Michael, Church Street, Malvern in 1085, it is now a large parish church that dominates the centre of Malvern. It has the largest display of C15 stained Listed Place of Worship grade I, glass in England as well as rich furnishings and finishes. DESIGNATION: CA Overall in fair condition but there is a major problem with the stained glass which needs urgent repair. Other CONDITION: Very bad problems are the high level stonework of the tower and PRIORITY CATEGORY: the high level masonry to south windows. The parish are C (C) undertaking a pilot project to repair the stained glass and OWNER TYPE: Religious organisation surrounding fabric to inform a major project of repairs and improved facilities. LIST ENTRY NUMBER: 1082794 Contact: Chris Miners 0121 625 6835

© Historic England



SITE NAME:	Church of St John, Mamble, Mamble	with C14 and C16 phases. Sandstone rubble with ashlar dressings, brick additions and tiled roofs. Timber bell towe with shingled bell turret. The Blount Chapel on the north side of the chancel has been roofless for a long time. The bricks are starting to show severe effervescence at high level possibly as a result of the rebuilding of the brick and tile coping of the wall head. Harmful ivy growth is also a problem on the north side of the chapel. Plans for
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	level possibly as a result of the rebuilding of the brick and
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1081406	restoration of the chapel have now been developed.
		Contact: Chris Miners 0121 625 6835

© Historic England Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site ŴĤS

HERITAGE AT RISK 2022 / MIDLANDS / MALVERN HILLS

	SITE NAME:	Church of St Peter and St Lawrence, Powick	Large rural church on the edge of a small village. Sandstone ashlar and coursed rubble walls with plain clay roofs.
1	DESIGNATION:	Listed Place of Worship grade I, CA	Structural problems at the junctions of the south aisle.and the south transept for which joint and stone cracking is the evidence. This will need monitoring.
	CONDITION:	Fair	
	PRIORITY CATEGORY:	D (New entry)	
n c	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1166920	Contact: Chris Miners 0121 625 6835
: England			

© Historic Er

-	SITE NAME:	Church of St Mary, Ripple	Large village centre parish church. Cruciform plan with
	DESIGNATION:	Listed Place of Worship grade I, CA	aisles flanking the nave and a two storey gabled north entrance porch. The tower over the crossing is three stage with a late C18 cap. The stone slate roofs and the tiled
1	CONDITION:	Poor	aisle roofs have slipped and are missing tiles. There are areas of severe stone erosoion and structural cracking at
	PRIORITY CATEGORY:	C (C)	the east end.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1349090	Contact: Chris Miners 0121 625 6835

© Historic England

	SITE NAME:	Stoke Bliss Church, Stoke Bliss	Small parish church with entrance through a south tower
	DESIGNATION:	Listed Place of Worship grade II*	with a squat spire, nave and chancel. Plaster has fallen from the ceiling and interior has had to be cordened off. Other
	CONDITION:	Poor	problems are faults with the tiled roofs, rainwater downpipes and eroded stonework.
	PRIORITY CATEGORY:	D (D)	downpipes and eroded stonework.
11	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1179715	Contact: Chris Miners 0121 625 6835
A CONTRACTOR OF			

© Historic England

SITE NAME:	Enclosure 110 yards (100 metres) north of St Bartholomew's Church, Grimley			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005296	
CONDITION:	Unknown	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Religious organisation	CONTACT:	Marie Twomey 0121 625 6838	
SITE NAME:	Enclosure west of Church Farm, Grimley			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005315	
CONDITION:	Unknown	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Religious organisation	CONTACT:	Marie Twomey 0121 625 6838	
SITE NAME:	Moated site at Earl's Court, Rushwick			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017229	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Other not for profit group	CONTACT:	Rachel Jordan 0121 625 6854	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2022 / MIDLANDS / MALVERN HILLS / REDDITCH / WORCESTER

SITE NAME:	Witley Court, Great Witley / Hillhampton / Little Witley	Pre-eminent C19 landscape in multiple ownership. Parts of the registered park and garden are well cared for but there
DESIGNATION:	Registered Park and Garden grade II*, 19 LBs, SM	are concerns about intrusive development in the park, loss of parkland trees and the need for repair and maintenance of the historic boundary walls and features. The wider park
CONDITION:	Generally unsatisfactory with major localised problems	lacks a Conservation Management Plan to inform future land management and potential development.
VULNERABILITY:	High	
TREND:	Declining	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000901	Contact: Erika Diaz Petersen 0121 625 6879

REDDITCH

© Historic England

SITE NAME:	Park Wood Camp, Ipsley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005334
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	Feckenham manorial moated site, Feckenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Nick Carter 0121 625 6860
SITE NAME:	St Stephens Green Redditch		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Mary Worsfold (LPA) 01527 881329

WORCESTER



Single section of the medieval city walls. A variety of repair SITE NAME: City walls: section extending 130 feet (40 metres) from the back of No. 27 New Street to and maintenance has taken place along the city walls in the past, and some sections of the wall have been repaired with Historic England grant aid. This section remains at risk Windsor Row and is affected by damaging plant growth. The owner of DESIGNATION: Scheduled Monument, CA part of this stretch undertook beneficial works to remove a lot of this in 2019; although areas outside of their control CONDITION: Poor still needs to be addressed, and more permanent barriers OCCUPANCY: N/A installed. Maintenance works are also is now needed to tackle re-emerging vegetation PRIORITY CATEGORY: C (A) OWNER TYPE: Mixed, multiple owners LIST ENTRY NUMBER: 1005282 Contact: Nick Carter 0121 625 6860

© Historic England

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

D

Е

- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA
- LB I PA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / WORCESTER / WYCHAVON

	SITE NAME:	Church of St Helen, Fish Street, Worcester	Although its foundation predates that of the Anglo Saxon Diocese of c675, the church of St Helen dates primarily
LING	DESIGNATION:	Listed Place of Worship grade II*, CA	from C15 and consists of a nave and chancel with aisles, a south porch and a west tower. The presence of iron cramps in conjunction with the red sandstone used for
	CONDITION:	Fair	rebuilding in the C19 is causing accelerated deterioration and failure of the facework. A limited scheme of high level
	PRIORITY CATEGORY:	C (C)	masonry repairs funded by a National Lottery Heritage
and the	OWNER TYPE:	Religious organisation	Fund Grant for Places of Worship was completed in 2019 but masonry repairs to the south aisle and lowest stage of
	LIST ENTRY NUMBER:	1389795	the tower remain to be attended to.
oric England			Contact: John Tiernan 0121 625 6839

© Histor

SITE NAME:	City walls: section S of The Butts, extending 150ft (50m) between Angel Place and Bath Cottage			
DESIGNATION:	Scheduled Monument and Listed Building grade II, CA	LIST ENTRY NUMBER:	1003777 and 1390185	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Nick Carter 0121 625 6860	
SITE NAME:	Lowesmoor, Worcester			
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Improving	
VULNERABILITY:	Medium	CONTACT:	Paul Collins 01905 722129	

WYCHAVON

	SITE NAME:	31 High Street, Droitwich Spa	C14 timber framed town house. The front range
	DESIGNATION:	Listed Building grade II*, CA	incorporates historic timber work in the roof and wall frames. C17 extensions to the rear were in very bad
	CONDITION:	Poor	condition with structural failure to the timber frame and walls. Failed rainwater goods and a roof in poor condition
	OCCUPANCY:	Vacant/not in use	let in water into the structure and rotted the frame. A
	PRIORITY CATEGORY:	F (F)	scheme to convert and upgrade for use as an office, retail units and a residential unit has been approved. An Historic
	OWNER TYPE:	Private	England Repair Grant was given in 2017 and basic repairs are complete. It remains at risk until an occupant is found
	LIST ENTRY NUMBER:	1296659	to complete the fit-out.

© Historic England



C15 and earlier remains of the Evesham Abbey buildings SITE NAME: The Almonry, Merstow Green, now converted as a museum, Rubble stone and timber-Evesham frame with Cotswold stone roofs. It is in bad condition due DESIGNATION: Listed Building grade I, CA to the clear signs of structural instability of the timber frame. Much of the stone slate roofing is nearing the end of CONDITION: Very bad its life and the timber frame has developed weaknesses and OCCUPANCY: rot, particularly at sole plate level. The museum is currently Occupied/in use looking to apply for public funding for repairs to the PRIORITY CATEGORY: D (C) building and rejuvenation of the exhibits it holds.following project development work with Cultural Recovery Fund OWNER TYPE: Local authority gran aidt. LIST ENTRY NUMBER: 1302722 Contact: Chris Miners 0121 625 6835

© Historic England



SITE NAME:	Abbot Chyryton wall, Boat Lane, Evesham	Part of the outer precinct wall of Evesham Abbey, built by Abbot William de Chyryton between 1317 and 1344, which originally extended from the river to the Abbey. Previous consolidation has partially failed due to vandalism.
DESIGNATION:	Scheduled Monument and Listed Building grade II	Previous consolidation has partially failed due to vandalism. Some parts of wall are still in very bad condition, and wall
CONDITION:	Very bad	footings are diminishing. Discussions are ongoing with associated parties to agree a long term solution.
OCCUPANCY:	N/A	associated parties to agree a long term solution.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1005501 and 1350435	Contact: Neil Rimmington 07775 550 674

PRIORITY CATEGORIES

© Historic England

- Immediate risk of further rapid deterioration or loss of fabric; no А
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no Е obvious new user (applicable only to buildings capable of beneficial

use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

Contact: Chris Miners 0121 625 6835

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS

Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / WYCHAVON

	SITE NAME:	Abbot Reginalds Wall, Evesham Abbey, Evesham	Abbot Reginalds wall forms part of the main ecclesiastical complex of Evesham Abbey, built between 1317 and 1344
	DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, CA	fragments of which still survive. The rebuilding of the collapsed section and repairs to an adjoining wall have bee completed, but sections of wall were still in poor condition Historic England offered a Repair Grant for a scheme of
	CONDITION:	Poor	repair and consolidation. This is part of a wider restoration
	OCCUPANCY:	N/A	of the former allotment gardens being carried out by the Evesham Abbey Trust and the ongoing repairs are due to
×	PRIORITY CATEGORY:	E (C)	be completed in 2022.
© Historic England	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1005298 and 1081349; 1081350	Contact: Chris Miners 0121 625 6835
	SITE NAME:	Westwood House, Westwood	A grand hunting lodge dating from 1612 now converted to
Lunau A	DESIGNATION:	Listed Building grade I, RPG grade II	apartments. Square core with added diagonal wings of three and four storeys. Brick with sandstone dressings very ornate slate covered roofs. There are now growi
	CONDITION:	Poor	problems with the wall structure, windows and roof. Some repairs have been carried out but many other areas need
A DESTRUCTION	OCCUPANCY:	Part occupied/part in use	urgent repairs.
	PRIORITY CATEGORY:	C (C)	
and an in the	OWNER TYPE:	Private, multiple owners	
© Historic England	LIST ENTRY NUMBER:	1173950	Contact: Chris Miners 0121 625 6835
idines a	SITE NAME:	Church of St Mary, Church Road, Aston Somerville	Small rural parish church at the edge of a village. Simple plan of chancel, nave, tower and north porch. Stone slate
The A	DESIGNATION:	Listed Place of Worship grade I	roof and limestone ashlar and rubble walls. CI3 with CI4 additions. A major crack on the east gable end (now
	CONDITION:	Poor	repointed with lime mortar) is symptomatic of serious structural movement in the chancel, which is still active.
	PRIORITY CATEGORY:	A (A)	The church is now reported to be closed for worship.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1214230	Contact: Chris Miners 0121 625 6835

© Historic England

2	SITE NAME:	Church of St James, Bredicot, Bredicot	Small church in the old rectory garden with three-bay nave/chancel, south porch and bellcote. Walls are lias
and the second s	DESIGNATION:	Listed Place of Worship grade II	rubble with ashlar sandstone dressings and tiled roof. Circa 1300 and restored in 1843 by AE Perkins. The sandstone
	CONDITION:	Poor	of the window masonry is heavily eroded and falling apart.
	PRIORITY CATEGORY:	A (A)	
-38	OWNER TYPE:	Religious organisation	
·	LIST ENTRY NUMBER:	1117084	Contact: Chris Miners 0121 625 6835

© Historic England



SITE NAME:	Church of St John the Baptist, Church Walk, Crowle, Crowle	The original medieval church was demolished and rebuilt in the 1880s to designs by Frederick Preedy in the Decorated
DESIGNATION:	Listed Place of Worship grade II*, CA	style with a tall west tower. The church is constructed from lias limestone rubble with ashlar stone dressings under a plain clay tile roof with decorative ridges. The roof
CONDITION:	Poor	and rainwater goods are in poor condition and minor repairs are required to the stonework. A National Lottery
PRIORITY CATEGORY:	C (C)	Heritage Fund Repair Grant for Places of Worship was
OWNER TYPE:	Religious organisation	offered in February 2013 but not accepted, and therefore no work has taken place.
LIST ENTRY NUMBER:	1081275	Contact: Chris Miners 0121 625 6835

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / WYCHAVON

-the	SITE NAME:	Church of St Nicholas, Dormston	Small rural medieval parish church. Simple nave and chancel with a timber framed west tower that received a National
DESIGNATION	DESIGNATION:	Listed Place of Worship grade I	Lottery Heritage Fund and Historic England Repair Grant for Places of Worship in 2011. Persistent high levels of
	CONDITION:	Poor	damp at low level in the nave and north chancel walls are now an urgent problem.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	685	Contact: Chris Miners 0121 625 6835

© Historic England

	SITE NAME:	Church of St Andrew, St Andrew's Street, Droitwich Spa, Droitwich Spa	et, Droitwich Spa, Worship grade I, Worship Grade I, Wors
A DA IN	DESIGNATION:	Listed Place of Worship grade I, CA	south side. Tiled roof and the rainwater system of the north east chapel are leaking, causing decay in the C15
	CONDITION:	Poor	ceiling below. Other roofs and high level walls were repaired with a National Lottery Heritage Fund and Historic England Repair Grant for Places of Worship ove
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	decade ago.
© Historic England	LIST ENTRY NUMBER:	1167974	Contact: Chris Miners 0121 625 6835

-	SITE NAME:	Church of St Peter, Port Street, Evesham	Large C19 urban church in the Decorated Gothic revival style. It has an assymetrical plan with a large south tower
	DESIGNATION:	Listed Place of Worship grade II, CA	and spire. This spire has shed stone causing some of the churchyard to be roped off.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (New entry)	
Ind -	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1350073	Contact: Chris Miners 0121 625 6835
yright			

© HE staff copyrigh

© Historic England



	LIST ENTRY NUMBER:	1350073	Contact: Chris Miners 0121 625 6835
	SITE NAME:	Church of St Nicholas, Middle Littleton, North and Middle Littleton	Small Anglican parish church. C13 origins, C15 tower upper stages. Early C16 battlemented S chapel. Heavily restored by Preedy 1876 with new nave N wall and
	DESIGNATION:	Listed Place of Worship grade II*, CA	chancel. Lias stone walling with ashlar dressings and plain tiled roofs. Mostly in fair condition but the tiled roofs the stonework need repair. Falls of stone from the tower are
	CONDITION:	Poor	the most recent manifestation
a Con	PRIORITY CATEGORY:	D (New entry)	
1	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1303224	Contact: Chris Miners 0121 625 6835



	LIST ENTRY NUMBER:	1303224	Contact: Chris Miners 0121 625 6835
~	SITE NAME:	Church of St John the Baptist, Wickhamford	Small rural church 13th century origins with 17th century rebuilding and 20th century restorations. Simple plan of
-	DESIGNATION:	Listed Place of Worship grade I, CA	west tower, nave and lower east chancel. The cotswo
	CONDITION:	Poor	
I KAN	PRIORITY CATEGORY:	D (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1287774	Contact: Chris Miners 0117 975 1355

© Historic England

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / WYCHAVON

SITE NAME:	Enclosures north east of Fernhill Farm, Charlton / Cropthorne				
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1005286	
CONDITION:	Unknown		TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	5	NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Marie Twomey 0121 625 6838	
SITE NAME:	Settlement site N	NNE of Fernhill Farm, Charlton / C	Cropthorne		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1005287	
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	5	NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Marie Twomey 0121 625 6838	
SITE NAME:	Evesham Abbey	(remains of), Evesham			
DESIGNATION:	Scheduled Monu	iment, 2 LBs, CA	LIST ENTRY NUMBER:	1005297	
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Improving	
PRINCIPAL VULNERABILITY:	Deterioration - i	n need of management	NEW ENTRY?:	No	
OWNER TYPE:	Local authority		CONTACT:	Neil Rimmington 07775 550 674	
SITE NAME:	Settlement site r	north of Spring Hill, Fladbury			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1005352	
CONDITION:	Unknown		TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	Arable ploughing		No	
OWNER TYPE:	Private, multiple	owners	CONTACT:	Marie Twomey 0121 625 6838	
SITE NAME:	Moated site 120	metres south east of Huntingdrop	Farm, Hanbury		
DESIGNATION:	Scheduled Monu	iment	LIST ENTRY NUMBER:	1017311	
CONDITION:	Extensive signific	ant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Deterioration - i	n need of management	NEW ENTRY?:	No	
OWNER TYPE:	Private		CONTACT:	Marie Twomey 0121 625 6838	
	SITE NAME:	Westwood Park, Westwood / Doverdale / Droitwich Spa / Hampton Lovett / Ombersley	Elements of a C17 garden and park associated with an imposing hunting lodge, later a house. Some garden and park changes and additions of C18 to early C20 date. Th vast majority of the park is in intensive cultivation and stripped of parkland trees. There is some post-war development in the vicinity of the main house. Residentia		
ALL IT TO MACHINE THE	DESIGNATION:	Registered Park and Garden grade II, 10 LBs			
	CONDITION:	ITION: Generally unsatisfactory with major localised problems		development and expansion of a business park affect setting, particularly to the north and east.	
	VULNERABILITY:	High			
D Historic England	TREND:	Stable			
	NEW ENTRY?: No				
	OWNER TYPE: Mixed, multiple owners				

Contact: Erika Diaz Petersen 0121 625 6879

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

1000899

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

WYRE FOREST




SITE NAME:	Severn Bridge including Flanking Arches and Balustrade, Bewdley	Bridge over the river Severn, 1798 by Thomas Telford. Mostly sandstone forming three arches over river, two
DESIGNATION:	Listed Building grade I, CA	towpath arches on south bank, 14 arches on north bank extending about 50 metres to south east; balustrades on
CONDITION:	Poor	river part of stone, cast iron on land. The stone balustrade is suffering extensive stone erosion as are the flanking piers.
OCCUPANCY:	N/A	The cast iron is rusting badly. There have been incidents of
PRIORITY CATEGORY:	C (C)	traffic impactdamage to the balustrades.
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1100000	Contact: Chris Miners 0121 625 6835

© Historic England



	SITE NAME:	Churchill Forge, Churchill Lane, Churchill, Churchill and Blakedown	Early C19 hand forge building that made spades and shovels, comprising three brick buildings, two water wheels, a dam and large mill pond. The forge is still in
	DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II, part in CA	working order and is managed by the Churchill Forge Trust. The Trust are continuously progressing maintenance and conservation tasks within the site and have recently
	CONDITION:	Very bad	completed comprehensive repair works to the spillway weir. They are exploring options to better understand the
	OCCUPANCY:	Part occupied/part in use	conservation management needs of the buildings within the
	PRIORITY CATEGORY:	B (B)	site, and opportunities for future funding.
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1005274 and 1348320; 1100650; 1100651	Contact: Nick Carter 0121 625 6860

© Historic England



© Historic	England	Archive
------------	---------	---------



SITE NAME:

DESIGNATION:

CONDITION:

OWNER TYPE:

LIST ENTRY NUMBER:

Church of St George, Coventry Georgian Gothic church with elaborate gable buttresses and tower with turret and pinnacles, by Francis Goodwin, Street, Kidderminster 1821-24. The roof was destroyed by fire in 1922 but Listed Place of Worship grade II* rebuilt, and the church was remodelled by Giles Gilbert Scott in 1923-25. At the west end the roof from this work Poor is now leaking at both side valley gutters. PRIORITY CATEGORY: C (C) Religious organisation

Contact: Chris Miners 0117 975 1355

© Historic England

SITE NAME:	Gilgal, Stourport-on-Severn, East of Stourport Town Centre			
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No	
CONDITION:	Very bad	TREND:	Deteriorating significantly	
VULNERABILITY:	Medium	CONTACT:	Peter Bassett (LPA) 01562 732928	
SITE NAME:	Green Street, Kidderminster, Town centre			
SITE NAME: DESIGNATION:	Green Street, Kidderminster, Town centre Conservation Area, 3 LBs	NEW ENTRY?:	No	
	, ,	NEW ENTRY?: TREND:	No Deteriorating	
DESIGNATION:	Conservation Area, 3 LBs			

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

use)

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

1100088

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

WHS

Conservation Area Listed Building CA

- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM

ÍΙΑ

Unitary Authority World Heritage Site

HERITAGE AT RISK 2022 / MIDLANDS / WYRE FOREST

SITE NAME:	Ribbesford, 2 miles south of Bewdley		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Peter Bassett (LPA) 01562 732928

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric; no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

This document is one in a series of regional registers produced as part of Historic England's national Heritage at Risk programme. The registers for other regions and previous Heritage at Risk publications can be found at historicengland.org.uk/advice/heritage-at-risk/ registers-and-publications/ More information about Historic England's Heritage at Risk programme can be found at historicengland.org.uk/advice/heritage-at-risk/

Heritage at Risk Published November 2022 4th Floor, Cannon Bridge House 25 Dowgate Hill London EC4R 2YA © Copyright Historic England 2022 Product code: HE0073



Midlands Register 2022