Heritage at Risk



Contents

Heritage at Risk	III
The Register	VII
Content and criteria	VII
Criteria for inclusion on the Register	IX
Reducing the risks	ΧI
Key statistics	XIV
Publications and guidance	XV
Key to the entries	XVII
Entries on the Register by local planning authority	XIX
County Durham (UA)	1
Northumberland (UA)	10
Northumberland (NP)	27
Tees Valley	34
Darlington (UA) Hartlepool (UA) Middlesbrough (UA) North York Moors (NP) Redcar and Cleveland (UA) Stockton-on-Tees (UA)	34 35 36 37 37 39
Tyne and Wear	40
Gateshead Newcastle upon Tyne North Tyneside South Tyneside Sunderland	40 42 45 45 46

II







he case studies and figures in this leaflet give you a glimpse into the reasons why some of our most precious historic buildings and places are 'at risk' in the North East and what we are doing to help. As our Angels Awards show, community action is increasingly important in saving many of the cherished monuments at risk like Blacka Burn Shieling. If you want to save a site we can put you in touch with people who can help – just contact us. We also need to remember that many buildings capable of economic use (a growing category on our national Register) and conservation areas offer an opportunity for heritage-led regeneration. Places like the Ouseburn Valley, Newcastle show that bringing new life to historic areas can contribute positively to the economy of the region, adding to its distinctiveness and pulling power for investment.

Carol Pyrah Planning Director, North East



The unpredictable economic climate remains the main harmful issue haunting the challenge to create viable solutions for heritage at risk in the North East. The scale of the task (for example, 12.5% of our scheduled monuments

are considered to be 'at risk') means it cannot be tackled alone. All parties, big and small, have a role in promoting the value of our shared heritage and its long-term survival. Promisingly, creative approaches to re-use, committed owners, partnerships and multi-source investment have resulted in 18 entries being removed from the 2015 Heritage at Risk Register .

A major achievement is the full repair of **Felton Park Glasshouse**; a complex case that took almost 20 years to resolve. Increasingly, the intricacies of delivering an appropriate solution for heritage at risk can take a prolonged effort. Appointing the proper professional team is the essential starting-point, as proven by **Linnels Mill** and **Corbridge Bottle Kilns** – two sites where carefully targeted Historic England grant aid was used to great effect by external specialists. Both have been removed from the Register.

Another successful partnership is with Natural England, whose Countryside Stewardship scheme can deliver

positive management solutions for archaeology. Closely linked is the on-going battle to deliver effective ways of controlling bracken, which is the principal vulnerability factor in 8.0% of our archaeological entries on the 2016 Register. Grants for immediate works and subsequent site management have been awarded to several owners over the past year.

An area of great potential is to continue developing awareness amongst community and volunteer groups as to how vital their contribution is in protecting heritage assets, whether it is a large conservation area or a small archaeological site. Such a policy paid dividends for **Blacka Burn Shieling**, where trained volunteers (the training part-funded by Historic England) in Northumberland National Park surveyed the site and facilitated its removal from the Register.

Whatever the success, one certainty is that the challenges haunting heritage will test everyone's ingenuity and resolve, as demonstrated by the 18 sites added to the 2016 Register. There is no standing still, so urban cemeteries will be a priority for our work in the coming year. As will supporting local authorities in developing their own heritage at risk strategies and assisting them in taking enforcement action where appropriate. In uncertain times, only a partnership will help banish the various bogeymen threatening our shared heritage.

Kate Wilson Principal Adviser, Heritage at Risk

Cover image: Marsden Lime Kilns, Marsden, South Tyneside. The lime kilns on the coast at Marsden operated from 1874 to the 1960s, built in five phases as the demand for lime increased and improvements were made in the manufacturing process. As the site expanded, earlier single pot masonry kilns were superseded by circular brick kilns with numerous iron expansion bands. The monumental structure had been slowly deteriorating for many years but major repairs are in progress, funded by the owner and Historic England. This work will be completed in 2016, allowing removal of the site from the Heritage at Risk Register.



There are **300** assets on the **North East** Register, **2** fewer than in 2015

Felton Park Greenhouse Felton, Northumberland



The glasshouse at Felton Park was erected around 1830 to designs attributed to John Claudius Loudon. It measures 90 x 30 feet and stands against an 18th-century brick garden wall that is over 13 feet high. The slender, curved roof, of wrought iron glazing bars with delicate panes of fish-scale glass, rests elegantly

on a dressed stone plinth. The structure represents an important example of 19th-century architectural engineering, created at a time when estate owners were developing their gardens by introducing exotic plants from abroad. Although many glasshouses were built for horticultural purposes in the 19th century, few have survived and the curvilinear example at Felton is one of only twenty to survive in England.

Following decades of neglect, the glasshouse had been on the Heritage at Risk Register since 1998. The good news is that an extensive repair programme (managed by Spence & Dower architects and funded by the owner, Northumberland County Council, Historic England, the Heritage Lottery Fund and the Country Houses Foundation) has resulted in the building being removed from the Register. The repair project showcased the wide range of specialist craft skills involved in repairing and conserving historic metal and glass. It won a commendation at the Georgian Group Architectural Awards in 2015 and a certificate of commendation at the Historic England Angel Awards in 2016. Work has also begun on introducing new plants and shrubs to join the two surviving camellias and large vine.

The site is privately owned and managed but now that the glasshouse has been repaired, it can be visited by prior arrangement with the owner (visit www. feltonparkgreenhouse.org). It is located a short walk from the centre of Felton village along a minor road.

Stockton & Darlington Railway County Durham

Opened in 1825, the Stockton and Darlington Railway combined locomotive-haulage of coal with the carriage of passengers by horse-drawn vehicle. Embankments, cuttings, bridge abutments and the splendid masonry arch over the River Skerne at Darlington are amongst the fragmentary remains today, parts of which are protected as a scheduled monument.

Elements of the railway have been on the Heritage at Risk Register since 2000 but multiple ownership of the scheduled monument complicates progress. Nevertheless, Historic England has engaged with numerous partners to improve the condition and maintenance of the monument. Yet, despite some heartening progress, much remains to be done as encroachment, vandalism and neglect continue to take their toll on this important piece of our industrial heritage.

An example of what can be done is the work achieved by the Brusselton Incline Group (see image), established



specifically to promote and preserve the stretch of the railway running from Brusselton to West Auckland (visit www.brusseltoninclinegroup.webs.com for more information). 2025 will see the bicentenary of the railway, giving Historic England and partners a target date by which to resolve the issues affecting the monument.

50th Anniversary of Conservation Areas

In 2017, Historic England will celebrate the 50th anniversary of conservation areas. These precious historic areas, from urban and industrial to rural and remote, create a strong sense of place and are likely to be what you think of when you think of special local character.

We'll carry out research into people's attitudes towards conservation areas and the challenges they

face in protecting them. We also plan to analyse local authorities' conservation area survey data to better understand what puts conservation areas up and down the country at risk. Finally, at a time when local authority resources are under pressure, we'll ask how local civic groups and organisations can become more involved to help safeguard conservation areas.

For more information contact:

Kate Wilson, Historic England North East Bessie Surtees House, 41-44 Sandhill, Newcastle-upon-Tyne, NE1 3JF Telephone: 0191 269 1255

Email: northeast@HistoricEngland.org.uk

Twitter: @HE_NorthEast

For a different format of this document contact our customer services department on:

Telephone: 0370 333 0608 Textphone: 0800 015 0516

Email: customers@HistoricEngland.org.uk

Product code: 52036

Find out what's at risk by searching or downloading the online Heritage at Risk Register at:

HistoricEngland.org.uk/har

THE REGISTER

Content and criteria

DESIGNATION

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of designated assets. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture, Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

In June 2016 Historic England launched Enriching the List, a crowdsourcing initiative opening up the entries on the National Heritage List to contributions by users. Anyone can register as a volunteer and submit extra information about one of the assets on the List or submit photographs to illustrate it. This additional content will then be available for anyone to view with but separate from the official List Entry.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Culture Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II* and II. Grade I buildings are of outstanding interest, and II* are particularly important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are over 376,000 listed entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. Nearly 20,000 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and, often most seriously of all, wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not designated. Instead, they are managed through the planning system and other regimes.

REGISTERED PARKS AND GARDENS

There are over 1,600 designed landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II*, and the Gardens Trust on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where often thousands were killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For almost 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently nearly 10,000 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of designation. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be:

- designated and included on the National Heritage List for England
- a grade I or II* listed building
- a grade II listed building in London
- a structural scheduled monument with upstanding remains
- in secular (non-worship) use

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been

repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register places of worship must be designated and listed grade I, II* or II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register archaeological sites must be designated as scheduled monuments and included on the National Heritage List for England. Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it ranging from 'extensive significant problems', to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register parks and gardens must be designated as grade I, II* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register battlefields must be designated and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings
- pressures of particular use within the site e.g. arable cultivation
- damage e.g. unregulated metal detecting

Battlefields are removed from the Register either when damaging activities cease, are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register wrecks must be designated and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Historic England has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. The information provides a detailed assessment of each conservation area. An overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

One of the primary aims of the Historic England Corporate Plan 2015-2018 is reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grants to help remove heritage from the Register

Dedicated Heritage at Risk teams in our nine regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website, www.historicengland.org.uk. Key publications and guidance are listed on pages XV-XVI.

BUILDINGS AND STRUCTURES

Our nine regional teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law.

Historic England can help with access to funding. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk for all asset types and Section 17 Management Agreements which are smaller grants for scheduled monuments. More information on funding can be found on the Historic England website. The support of other grant providers, including the Heritage Lottery Fund and Natural England, is also critical.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We are therefore working with local authorities to encourage them to develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; 'Stopping the Rot' is our published guidance on this. Our Heritage at Risk Solicitor can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the <u>Architectural Heritage Fund</u> and fund their regional support officers to work across the country. They help BPTs and other notfor-profit organisations to access funding, carry out feasibility studies and develop solutions for buildings at risk. The <u>Heritage Network Trust</u> also provides information about support officers and BPTs. Guidance and case studies are available on the <u>Historic England</u> website.

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The <u>Maintenance</u> <u>Cooperatives Project</u> run by the Society for the Protection of Ancient Buildings helps to connect, inform and empower those people who look after places of worship. Other successful initiatives include the Yorkshire Maintenance Project run by the National Churches Trust.

The Heritage Lottery Fund runs the <u>Grants for Places</u> <u>of Worship</u> scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. Historic England's architects and surveyors, based in our regional Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's <u>Listed Places of Worship scheme</u>, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. New Work in Historic Places of Worship helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part funded by Historic England, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

ARCHAEOLOGY

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of the 19,850 scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agrienvironment grant schemes to best effect. This has been especially important under the new Countryside Stewardship Scheme, under which the first agreements commenced in January 2016. Historic England, Natural England and local authority curators have collaborated on developing a new web portal for the scheme which provides local advice to support landowner applications. Our work in partnership with

Natural England on agri-environment schemes has removed 778 scheduled monuments from the Register since 2009. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke recommendations for each monument, enabling cultivation to continue where it does not present a risk. It will also be an important tool for advising owners on the longer term management of their monuments as the existing ten year Environmental Stewardship agreements gradually expire.

Although great progress has been made, analysis of entries on the Register shows that prehistoric barrows continue to be one of the most 'at risk' types of archaeological site on the Register. Unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites - even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key. The delivery of this will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

BATTLEFIELDS

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the National Planning Policy Framework makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal detecting.

Historic England also continues to encourage greater access to battlefields and the improvement of their amenity value and visitors' understanding of the impact these dramatic historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their

national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival.

Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from <u>Historic England</u>.

CONSERVATION AREAS

Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them as well as those of us whose job it is to manage them or make decisions about their future.

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management.

Local authorities complete the Conservation Areas Survey, providing us with an understanding of what is particularly affecting the character and appearance of conservation areas, what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

Key statistics

BUILDINGS AND STRUCTURES

- Nationally, 3.8% of grade I and II* listed buildings (excluding places of worship) are on the Register.
 In the North East the percentage is 6.2% (60 listed secular buildings).
- 6 building or structure entries have been removed from the 2015 North East Register because their futures have been secured, and 1 has been added.
- 68.7% of buildings or structures (79) on the North East baseline 1999 Register have been removed because their futures have been secured, compared to the national figure of 61.2%.

PLACES OF WORSHIP

- Nationally, 6.3% of listed places of worship are on the Register. In the North East, 5.5% (27) are on the Register.
- 3 places of worship have been removed from the North East Register following repair work, and 3 have been added.

ARCHAEOLOGY

- 2,528 (13.9%) of England's 19,848 scheduled monuments are on the Register. 175 (12.5%) of the North East's 1,397 scheduled monuments are on the Register.
- 7 archaeology entries have been removed from the 2015 North East Register for positive reasons, and 9 have been added.
- 34.7% of archaeology entries (59) on the North East baseline 2009 Register have been removed for positive reasons, compared to the national figure of 42.2%.
- Nationally, damage from arable cultivation is the greatest cause of risk affecting 39% of

archaeological entries on the Register. In the North East the proportion is 7.9%. The greatest risk, to 39.6% of entries on the North East Register is from unrestricted plant, scrub and tree growth. The national figure for plant, scrub and tree growth is 26.2%.

PARKS AND GARDENS

- 95 (5.8%) of England's 1,639 registered parks and gardens are on the Register. Of the 55 registered parks and gardens in the North East, 6 (10.9%) are on the Register.
- I park and garden entry has been added to the 2015 North East Register.

BATTLEFIELDS

Of the 46 registered battlefields in England, 6
(13.0%) are on the Register. Of the 6 registered
battlefields in the North East, 1 is on the Register.

WRECK SITES

 Of the 49 protected wreck sites around England's coast, 6 (12.2%) are on the Register. The North East's single protected wreck site is not on the Register.

CONSERVATION AREAS

- 8,286 of England's 9,848 conservation areas have been surveyed by local authorities and 496 (6.0%) are on the Register. Of the 299 conservation areas in the North East, 283 have been surveyed and 31 (11.0%) are on the Register.
- 2 conservation areas have been removed from the 2015 North East Register for positive reasons, and 4 have been added.

HISTORIC ENGLAND FUNDING

• £463,000 in grant was spent on 13 entries on the North East Register during 2015/16.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

<u>Assessment of Heritage at Risk from Environmental</u> <u>Threat: Key Message</u> (2013)

<u>Caring for Places of Worship 2010</u> (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 — Grappling with a 140-Year-Old Conservation Problem (2014) — <u>Historic England</u> Research News 21, available online

<u>Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers</u> (2013)

Heritage at Risk 2010 - Report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2016 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Online Register – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database.

<u>How to Assess the Condition of Historic Buildings</u> – an on-line introduction to assessing condition.

<u>Monuments at Risk (2008)</u> – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

<u>Protected Wreck Sites at Risk: A Risk Management</u> <u>Handbook</u> (2008)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

<u>Stopping the Rot: A Guide to Enforcement Action</u> <u>to Save Historic Buildings</u> (2016)

<u>Vacant Historic Buildings: An Owner's Guide to</u> <u>Temporary Uses, Maintenance and Mothballing</u> (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit <u>Heritage at Risk</u> where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the <u>National Heritage List for England</u> online database. Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address.

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website – <u>Historic England Publications</u>.

<u>Caring for Historic Graveyard and Cemetery</u> <u>Monuments</u> (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation

Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

<u>Caring for Places of Worship</u> (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

<u>Conservation Area Designation, Appraisal and Management</u> (2016)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Conservation and Management of War Memorial Landscapes (2016)

The Conservation, Repair and Management of War Memorials (2015)

Constructive Conservation in Practice (2008)

<u>Constructive Conservation: Sustainable</u> <u>Growth for Historic Places</u> (2013)

<u>Creativity and Care: New Works in English Cathedrals</u> (2009)

The Disposal of Heritage Assets: Guidance Note for Government Departments and Non Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological Sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Farming the Historic Landscape: Caring for Historic Parkland (2005)

Guidance notes and application forms for grants:

- <u>Historic England Grant Schemes</u> overview of all our current grant schemes
- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Repair Grants for Heritage at Risk (2015)

Guidance on Looking after Historic Buildings

Guidance on Improving Streets and Public Spaces

Heritage Crime Prevention: A Guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

<u>Heritage Works: the Use of Historic Buildings in Regeneration</u> (2013)

<u>Landscape Advice Note: Trees and the Law</u> (2014)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

Management and Maintenance of Historic Parks and Gardens. The English Heritage Handbook (2007)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2007)

<u>Pillars of the Community: the Transfer of Local</u> <u>Authority Heritage Assets</u> (2015)

<u>Post-War Public Art: Protection, Care and Conservation</u> (2016)

<u>Practical Building Conservation</u> — revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012–2015)

<u>Scheduled Monument Consent: A Guide for Owners and Occupiers</u> (2014)

<u>Shared Interest: Celebrating Investment in the Historic Environment</u> (2006)

Theft of Metal from Church Buildings (2011)

<u>Valuing Places: Good Practice in Conservation Areas</u> (2011)

Key to the entries

The Register includes the following risk assessment types:

• Building or structure

(grade I and II* listed buildings, grade II listed buildings in London and structural scheduled monuments)

Place of worship

(grade I, II* and II listed buildings)

Archaeology

(scheduled monuments – earthworks and buried archaeology)

• Park and garden

(Registered parks and gardens)

Battlefield

(Registered battlefields)

Wreck site

(Protected wreck sites)

Conservation area

(Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments), parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA Conservation Area
HE Historic England
HLF Heritage Lottery Fund
LB Listed Building

LPA Local Planning Authority

NP National Park

PWS Protected Wreck Site
RB Registered Battlefield
RPG Registered Park and Garden

SM Scheduled Monument UA Unitary Authority

WHS World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
COUNTY DURHAM (UA)							
County Durham (UA)	24	3	21	I	0	0	8
NORTHUMBERLAND (UA)							
Northumberland (UA)	30	8	57	2	0	0	3
NORTHUMBERLAND (NP)							
Northumberland (NP)	2	0	49	0	0	0	0
TEES VALLEY							
Darlington (UA)	3	I	1	0	0	0	3
Hartlepool (UA)	0	2	2	0	0	0	4
Middlesbrough (UA)	0	0	0	0	0	0	2
North York Moors (NP)	0	0	2	0	0	0	0
Redcar and Cleveland (UA)	6	I	2	I	0	0	4
Stockton-on-Tees (UA)	2	0	0	0	0	0	0
TYNE AND WEAR							
Gateshead	6	I	2	0	0	0	l
Newcastle upon Tyne	5	7	2	2	0	0	0
Newcastle upon Tyne / Gateshead [†]	0	0	0	0	I	0	0
North Tyneside	0	0	0	0	0	0	1
South Tyneside	2	2	0	0	0	0	3
Sunderland	6	2	I	0	0	0	2
Sunderland / Gateshead [†]	1	0	0	0	0	0	0
TOTAL	87	27	139	6	1	0	31

 $The sub-region Tees \ Valley is included to group the following unitary authorities: Darlington, Hartlepool, Middlesbrough, Redcar and Cleveland, Stockton- on -Tees and North York Moors National Park$

 $^{^\}dagger$ Sites that cross local planning authority boundaries

COUNTY DURHAM (UA)



© Historic England

SITE NAME: West Mural Tower at Auckland Castle, Auckland Castle Park, Bishop Auckland

Listed Building grade I, RPG DESIGNATION: grade II*, CA

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1196445

LIST ENTRY NUMBER:

SITE NAME:

PRIORITY CATEGORY:

OWNER TYPE:

Two-storey viewing tower in the grounds of Auckland Castle. C13, with later alterations. The building requires urgent consolidation works as there is an immediate risk of loss of historic fabric. A statement of significance was completed in 2011. A repair scheme has been drawn up with funding from Historic England and a grant is being explored for a first phase of urgent works.

Contact: Kate Wilson 0191 269 1221

ALC: Y
THE CO.

© Historic England

SITE NAME: Brancepeth Castle, Brancepeth Listed Building grade I, RPG DESIGNATION: grade II, CA CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: D (D) OWNER TYPE: Private

1159012

Anthony Salvin. It was occupied by the army during World War II and then by glassware makers JA Joblings. Parts of the building are currently occupied, while others are used for events and other activities. Some urgent repairs have been completed within the past few years, and further works are being planned with the aid of a condition survey report prepared in 2015.

Brancepeth Castle is a medieval fortress that was greatly

enlarged in the C19 by architects John Paterson and, later,

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME: Hedleyhill Colliery coke works, 500 metres south west of Hazlet House, Brandon and Byshottles / Hedleyhope DESIGNATION: Scheduled Monument CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A(A)

C18-C19 lines of brick-built coke ovens. Many bricks have been dislodged by livestock sheltering within them. Livestock have also eroded the grassy banks between each oven and established tree growth occurs along the entire structure.



© Historic England

OWNER TYPE: Private LIST ENTRY NUMBER: 1018230

Contact: Kate Wilson 0191 269 1221

Church, 50 metres north east of Croxdale Hall, Croxdale Hall, Croxdale and Hett Scheduled Monument and Listed DESIGNATION: Buildings - I grade I; I grade II, RPG grade II*, CA CONDITION: OCCUPANCY: Vacant/not in use

Medieval former church with nave dating back to late CII and chancel to late C12. Altered in later centuries but Norman south doorway contains the original door with iron hinges. On the Croxdale Estate and rarely opened up. There is severe damp in the building, both rising damp in the floors and walls and penetrating damp over the chancel

LIST ENTRY NUMBER: 1019820 and 1120740; 1120741

C (C)

Private

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument

Unitary Authority World Heritage Site



© Historic England

DESIGNATION: Listed Building grade II*, CA

CONDITION: Fair

OCCUPANCY: Occupied/in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Government or agency

LIST ENTRY NUMBER: 1120616

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

C15 granary building, erroneously known as "The Tithe Barn", forming part of an important group of medieval farm buildings. The building lies outside the secure perimeter of the adjoining prison and is used as part of the Prison Officers' Club. The roof, stonework and close-studded upper floor require attention. Repointing of the barn has begun but further works are required, particularly to the granary.

Bridge over the River Wear designed in 1772-8 by George

Nicholson for the Dean and Chapter of Durham Cathedral. The masonry of the arches has deteriorated significantly in recent years; however, a programme of remedial works, part-funded by Historic England, was completed on the southern arch during 2011/12. Works

have yet to be completed on the northern arch.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Prebends' Bridge, Durham and Framwellgate
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA, WHS
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Religious organisation 1002337 and 1121354

Contact: Kate Wilson 0191 269 1221



© Niven Architects

SITE NAME:	Castle wall, behind 3, North Bailey, Durham and Framwellgate
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Charity (heritage)

1322845

C12 castle wall with base of angle tower. Consists of coursed squared sandstone. Suffering from progressive collapse of wall face and the core requires urgent attention to avoid further substantial failure. A comprehensive programme of urgent repair is under discussion with the owner, Local Authority and Historic England.

Contact: Sara Rushton 0191 269 1222



© Historic England

SITE NAME:	Ushaw Home Farm, main block and wall attached, Esh
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Charity (non-heritage)

LIST ENTRY NUMBER: 1185963

Part of a planned farm, constructed 1851-2 to designs by Joseph Hansom. Of three storeys, the main range is built into the bankside so that the lower two floors have ground level access. Two attached side wings and a projecting central bay create an E-shaped plan. Many original internal features survive. There is general deterioration to most external elements, including missing or displaced verge stones to some gable ends, defective rainwater goods and cracking to masonry walls. Many areas of slipped or displaced roof slates are allowing the ingress of rainwater.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Former Junior Seminary Chapel of St Aloysius, Ushaw College, Ushaw, Esh
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

1299434

Charity (non-heritage)

Former Roman Catholic junior seminary chapel of 1857-59 by Edward W Pugin in the Gothic Revival style. Temporary urgent repairs were undertaken at the end of 2015 to stop significant water ingress caused by heritage crime. Discussions are in progress to define an economically viable strategy for the site as a whole and to ensure the early completion of a substantive phase of permanent repairs to the chapel.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

OWNER TYPE:

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Dovecote, 45 metres south of Gainford Hall, Gainford
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1121116

Dovecote, C17, within the grounds of Gainford Hall. Stone repairs, roof renewal and repointing required.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Gainford Hall, Low Road, Gainford
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private

Manor house circa 1600-1603, substantially restored in the late C19. A condition survey was completed in 2004 with funding from Historic England. Discussions are underway about a programme of substantive repairs to the roofs and external walling.

1323010 Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Hamsterley Hall, Hamsterley, Consett
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F(A)

Private

Mid C18 Gothic country house, possibly with older core. The house also has C19 and C20 additions. The building was saved from dereliction by the previous owners, who also part-restored the front range. Urgent repair works to the roof are in progress and these should be completed in 2017; meanwhile, options are being explored to secure the site's long-term future.

LIST ENTRY NUMBER: Contact: Martin Lowe 0191 269 1233 1067550

SITE NAME:	Medieval chapel at Harbour House Farm, Plawsworth, Kimblesworth and Plawsworth
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Other not for profit group
LIST ENTRY NUMBER:	1002325 and 1120959

Former chapel. A rare survival of a private manorial chapel dating to the C13-C14. A buttress was built in 2008 to support the leaning southern wall; however, further consolidation and repointing work is required.

© Historic England

SITE NAME:	Iron gates and railings, Lambton Castle, Lambton Park, Little Lumley
DESIGNATION:	Listed Building grade II*, RPG grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1311161

Posts, gates and railings on the north west drive to Lambton Castle forming a large and elaborate wrought iron gateway. Certain details are missing and the gateway is slowly decaying. In 2010, Historic England grant-aided a condition survey with costed priorities for repair works. The project has stalled, although options are now being explored to help secure the long-term future of the various historic buildings and structures on the estate.

Contact: Kate Wilson 0191 269 1221

Contact: Tom Gledhill 0191 269 1203

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

A DE
X
The same of the sa

© Historic England

SITE NAME:	Lamb Bridge, Lambton Park, Little Lumley
DESIGNATION:	Listed Building grade II*, RPC grade II
CONDITION:	Very bad

N/A

B (B)

Private

1120952

Ashlar sandstone bridge over the River Wear. Built in 1819 by Ignatius Bonomi for John Lambton, first Earl of Durham. The bridge has structural distortions that are causing concern about its stability. Some works have been undertaken, including on-going structural monitoring, but a substantive repair programme has yet to be undertaken.

Contact: Kate Wilson 0191 269 1221

9000	
	4.

© Historic England Archive

SITE NAME:	Gateway, Mortham Tower, Rokeby
DESIGNATION:	Listed Building grade I, RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1160832

Late medieval gateway to grade I medieval fortified manor house, set within landscaped Rokeby Park (registered grade II*). An inspection has revealed structural movement in the gateway.

Contact: Kate Wilson 0191 269 1221



© Historic England Archive

SITE NAME:	Sherburn House Bridge, Shincliffe
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

1002341

Mid-medieval stone bridge, dating from 1335 but upper part rebuilt at unknown later date. Tree growth and water ingress has started to push out masonry, as evidenced by pronounced gaps running throughout the structure. Drainage channels empty adjacent to the bridge abutments and this compounds the ongoing erosion.

© Historic England

SITE NAME:	Brandon Walls lead mine, Stanhope
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1015831

Mid-C19 lead mining complex situated on the east bank of the Rookhope Burn. The site was abandoned around 1903 and some elements of the complex are now in need of conservation action.

C18 and C19 lead mine suffering from extensive flood damage and erosion problems. A Conservation Management Plan has been prepared. Funding to deliver the necessary repair works has yet to be identified.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Greenlaws, Daddry Shield, Stanhope
DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNED TYPE	District

OWNER TYPE: Private

Contact: Kate Wilson 0191 269 1221

1015828 and 1231495; LIST ENTRY NUMBER: 1231496; 1231634; 1231675; 1278086; 1278087

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building

Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Westgate Primitive Methodist Chapel, Westgate, Stanhope
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Charity (heritage)

1232510

Contact: Kate Wilson 0191 269 1221

inform a management plan.

-	
il in	
	A CAMBON AND A STATE OF THE PARTY OF THE PAR

© Historic England

SITE NAME:	Coke ovens at Inkerman Farm, Tow Law / Cornsay
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1018228

Post-medieval beehive coke ovens. The management of the site was reviewed in 1998 with the involvement of Tow Law Town Council, which had a local heritage initiative. Historic England grant-aided the consolidation works, excavation and recording of finds. The initial repair programme is complete and half of the site is now open to the public. However, consolidation of the rest of the site is still required.

Former Primitive Methodist chapel, with attached schoolroom, constructed in 1871 to the design of George Race Junior & Atkinson and incorporating parts of an earlier C19 chapel. Investigative works and urgent repairs, part-funded by Historic England, were completed in 2013. While an agreed viable use for the chapel and schoolroom has yet to be found, an updated condition assessment and conservation statement are being prepared in 2016 to help

Contact: Kate Wilson 0191 269 1221

Contact: Martin Lowe 0191 269 1233



© Historic England Archive

SITE NAME:	Clock Tower, Windlestone Hall, Windlestone Park, Windlestone
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1160369

Early C19 clock tower and stables gateway by Ignatius Bonomi. The cupola was repaired with a Historic England grant in 1989, but stonework repairs are now needed. The clock faces have been removed.



© Historic England

SITE NAME:	Windlestone Hall, Windlestone Park, Windlestone
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Fair
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private

1160327

Large house, circa 1835, by Ignatius Bonomi for Sir Robert Johnson Eden. Incorporates an earlier C16 house. Surrounded by gardens and parkland and a cluster of estate buildings, including stables. The majority of the Hall was made habitable in 2013 but repairs are still required in the west wing and uncertainty remains over its long-term

Contact: Martin Lowe 0191 269 1233



© Historic England Archive

SITE NAME:	Harperley Working Camp, World War II Prisoner of War camp at Craigside, Wolsingham
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1020730

Very rare surviving example of a World War II Prisoner of War camp. Used by both German and Italian prisoners of war. 85% of original buildings in roofed condition. Wall paintings and internal fittings have survived too. Following a series of investigative surveys, a programme of conservation works, funded by Historic England, commenced in 2011. A second phase of work to the canteen and theatre was completed in 2013. Discussions are now underway with the owner to secure the completion of a programme of urgent works to some of the other buildings.

Contact: Lee McFarlane 0191 269 1239

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS		
CA	Conservation Area	
LB	Listed Building	
LPA	Local Planning Authority	
NP	National Park	
RPG	Registered Park and Garde	
SM	Scheduled Monument	
UA	Unitary Authority	
WHS	World Heritage Site	

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Church of St Anne, Market Place, Bishop Auckland
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1292201

medieval chapel. Tall aisled nave with clerestory windows, gabled south porch and distinctive west belfry. Chancel with organ chamber and vestry. A first phase of repairs to the north roof slopes was completed in 2015 with grant aid from the Heritage Lottery Fund. Funding to enable a second phase of repairs to the south roof slopes, and to areas of high-level stonework, is now being pursued.

Church of 1846-8 by William Thompson, on the site of a

Contact: Kate Wilson 0191 269 1221

T	ALL .	
Fig.		
111	6140,00	
	1 1/1	

© Historic England

SITE NAME:	Church of St Mary, Easington, Easington Village
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1231813

Perched on a hilltop at the west end of the old village of Easington, St Mary's consists of a west tower, a four-bay aisled nave and a chancel with organ chamber and vestry. It dates mostly from the early C13, although the tower is Norman and the chancel was largely rebuilt in 1853. While the church is in reasonable overall repair, there is an immediate structural problem affecting one of the arcade columns. Temporary internal propping has been installed. The Heritage Lottery Fund has offered a grant to enable a repair scheme to be drawn up.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Mary and St Stephen, Church Lane, Wolsingham
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1232841

Late C12 tower with later top. Remaining parts of the church (aisled nave, chancel with north vestry and organ chamber, and gabled south porch) of 1848 by William Nicholson. There are problems with the external stonework, including deep pockets of erosion to the north west buttress of the tower, areas of cracking, open joints and loose pointing. There is some internal water ingress. A grant has been offered by the Heritage Lottery Fund to allow repairs to be undertaken.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Derwentcote steel cementation furnace, iron finery forge and drift coal mine		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1015522
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	English Heritage	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Barnard Castle: ringwork, shell keep castle, chapel a	and dovecote, Barn	ard Castle
DESIGNATION:	Scheduled Monument, 2 LBs, CA	LIST ENTRY NUMBER:	1007505
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW EN		NEW ENTRY?:	No
OWNER TYPE: Private, multiple owners CON		CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	A cairn, a carved rock and a rubble bank, in the sou south east of Far East Hope, Barningham Moor, Bar		Scale Knoll Allotment, 800 metres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017431
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG UA Unitary Authority
WHS World Heritage Site

	(-)		
SITE NAME:	Cairnfield partly enclosed by a bank, on the east si Moor, 550 metres south of Hurst Hill, Barningham	de of Woodclose C	ill, Scale Knoll Allotment, Barningham
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017435
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Carved rock and cairn in Rowley Intake, 410 metro	es south east of Co	wclose House, Barningham Moor,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017422
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Carved rock and prehistoric enclosure on west sic Haythwaite, Barningham Moor, Barningham	le of Scale Knoll Gi	ll, 410 metres south west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017440
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Prehistoric enclosure 530 metres, and a rubble bar Barningham Moor, Barningham	nk 500 metres, east	of Haythwaite in Scale Knoll Allotme
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017436
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
ITE NAME:	Ring cairn 350 metres east of Haythwaite, Barningl	nam Moor, Barningl	nam
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017424
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
ITE NAME:	Unenclosed settlement, 260 metres south east of Cowclose House, Barningham Moor, Barningham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017423
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Grange and chapel, Bear Park, Bearpark		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1002346
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	ITY: Vandalism New entry?: No		No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	, ,		
SITE NAME:	Enclosures and industrial workings on Cockfield Fe Softley	l, Cockfield / Even	wood and Barony / Lynesack and
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002314
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Remains of the Stockton and Darlington Railway, Ed	herley / Shildon / '	West Auckland
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, part in CA	LIST ENTRY NUMBER:	1002315 and 1159141; 1160402
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Roman period native settlement at Calf Holm, imm	ediately west of D	ine Holm Scar, Forest and Frith
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019162
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Packhorse bridge, Headlam		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1002359
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two Romano-British hut circles and three shielings Holwick	on Holwick Scars	, 250 metres south of Hungry Hall,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019455
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Lanchester Roman fort (Longovicium), Lanchester		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Area of carved bedrock, 120 metres south of The F	Rigg, Lartington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018253
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Carved bedrock	with cups and grooves, 170 metr	es south east of The	s south east of The Rigg, Lartington		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1018251		
CONDITION:	Generally unsatis problems	factory with major localised	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Natural erosion	- extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Cup, ring and gro	oove-marked rock 170 metres sc	outh west of West Lo	oups's, Cotherstone Moor, Lartington		
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1016595		
CONDITION:	Generally satisfactory problems	ctory but with significant localised	TREND:	Stable		
PRINCIPAL VULNERABILITY:	Natural erosion	- moderate	NEW ENTRY?:	No		
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Four areas of carving on a rock outcrop 200 metres		res south west of Th	e Rigg, Lartington		
DESIGNATION:	Scheduled Monument		LIST ENTRY NUMBER:	1018250		
CONDITION:	Generally unsatisfactory with major localised problems		TREND:	Declining		
PRINCIPAL VULNERABILITY:	Natural erosion - extensive		NEW ENTRY?:	No		
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221		
SITE NAME:	Pike Law lead hu	ishes and mines, Newbiggin / For	est and Frith			
DESIGNATION:	Scheduled Monu	ment	LIST ENTRY NUMBER:	1015835		
CONDITION:	Generally satisfac problems	ctory but with significant localised	TREND:	Declining		
PRINCIPAL VULNERABILITY:	Animal burrowin	g - extensive	NEW ENTRY?:	No		
OWNER TYPE:	Private	· ·		Kate Wilson 0191 269 1221		
	SITE NAME:	Croxdale Hall, Croxdale and Hett	set in parkland o	d garden accompanying a country house, f early to mid-C18 origin. The walled		
	DESIGNATION:	Registered Park and Garden grade II*, 17 LBs, 2 SMs, part in CA	Croxdale Hall ha the C15. Mainter	are by the designer Lewis Kennedy. s been the seat of the Salvin family since nance of the gardens has fallen back in the waterbodies are in poor and		
	CONDITION:	Generally unsatisfactory with major localised problems	deteriorating cor the Orangery are	ndition. The notable 'cranked' walls flanki e in an advanced state of decay. Historic ed out recent research into the		
			Lingiano nas cal II	Ca Cac recent research into the		



© Historic England

SITE NAME:	Croxdale Hall, Croxdale and Hett
DESIGNATION:	Registered Park and Garden grade II*, 17 LBs, 2 SMs, part in CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Private

1001271

ıg significance of the walled garden and is in discussion with the owner regarding future management

Contact: Chris Mayes 0191 269 1226

SITE NAME:	Annfield Plain, Stanley		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Bishop Auckland		
SITE NAME: DESIGNATION:	Bishop Auckland Conservation Area, 69 LBs, part in RPG grade II*, 2 SMs	NEW ENTRY?:	No
	Conservation Area, 69 LBs, part in RPG grade II*, 2	NEW ENTRY?: TREND:	No Improving significantly

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area Listed Building LPA Local Planning Author NP National Park RPG Registered Park and G SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

TENTIAGE AT NISK 2016 /	NORTH EAST / COUNTY DORHALT (OA) / NORTHOLIBEREAND (OA)		
SITE NAME:	Bowburn, Cassop-cum-Quarrington		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Cockfield		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Kirk Merrington, Spennymoor		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Seaham		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Medium	CONTACT:	David Sparkes (LPA) 03000 267125
SITE NAME:	Trimdon Village, Trimdon		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
	Poor Medium	TREND: CONTACT:	Deteriorating David Sparkes (LPA) 03000 267125
CONDITION: VULNERABILITY: SITE NAME:			
VULNERABILITY:	Medium		
VULNERABILITY: SITE NAME:	Medium Windlestone Park, Windlestone	CONTACT:	David Sparkes (LPA) 03000 267125

NORTHUMBERLAND (UA)



Allenheads lead ore works,
Allendale

DESIGNATION: Scheduled Monument and Listed
Building grade II

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Private

Built in the C19, the Allenheads mine was the largest single lead mine in the North Pennines. Much of the complex is well cared for; however, some buildings are not weathertight and are becoming increasingly endangered. A report on the required scope of works has been prepared by Historic England, and funding is now in place from the Heritage Lottery Fund to secure their delivery.

© Historic England

SITE NAME:

Holmslinn lead mine, 200 metres south east of Holmes, Sinderhope, Allendale

DESIGNATION:

Scheduled Monument and Listed Building grade II

CONDITION:

Very bad

OCCUPANCY:

N/A

PRIORITY CATEGORY:

C (C)

Private

A series of standing and buried remains of one of four mine shafts in the East Allen valley. The shaft, 70 metres deep, was dug in 1855. The tower base enclosing the shaft, the engine bed and wheel pit (grade II listed) is being damaged by tree roots. Parts of the wheel pit collapsed in 2011. A broad repair solution has been agreed, and a Management Plan prepared, with support from Natural England. Funding has yet to be identified for the necessary works.

LIST ENTRY NUMBER: 1015848 and 1154939 Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

OWNER TYPE:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

OWNER TYPE

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Bondgate Tower, Bondgate Within, Alnwick
DESIGNATION:	Scheduled Monument and Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)

Private

1006597 and 1041513

The east gate of the former town wall, built circa 1450 by the second Earl of Northumberland. Consists of a recessed central portal between two projecting semi-octagonal towers. The main defects relate to damage from high-sided vehicles passing through the central portal. Further impact of a similar nature could cause a serious collapse. Discussions are underway to manage this risk.

Early C19 townhouse in plain ashlar, with three storeys and a basement. Most of the original interior detailing is still present. The building is vacant and deteriorating due to a lack of maintenance. A condition survey has been prepared and the owner is looking to convert the building to a new

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	General Lambert's House, 31 and 33, Narrowgate, Alnwick
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1041425 Contact: Martin Lowe 0191 269 1233



© Historic England

SITE NAME:	Eastern winding house and shaft head building, Woodhorn Colliery, Ashington
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (F)
OWNER TYPE:	Local authority

Winding house and shaft-head gear attached to the former Woodhorn Colliery. Built circa 1894, with later alterations. Repairs were carried out to the building as part of a major improvement scheme for the entire site that was completed in 2006. Significant corrosion has reappeared in the steelwork and concrete meaning that the structure requires further remedial work.

LIST ENTRY NUMBER: ||53|23

© Historic England

SITE NAME:	Hydraulic silo, 70 metres east of Cragend Farmhouse, Cartington
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1153196

Experimental hydraulic silo, circa 1895, by Lord Armstrong. Linear plan comprising a rectangular silage bay on each side of a taller cross-gabled centre. The interior contains a hydraulic engine and turbine. Repairs have been completed to the roof of the central section. A further phase of works is required to bring the external envelope back into full repair. Options are being explored for the building's future use.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Little Swinburne Tower, Little Swinburne, Chollerton
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1011412 and 1044908

Remote C15 tower house in a poor state of repair. Part of Little Swinburne shrunken medieval village. Surrounded by fallen masonry and in need of urgent attention to prevent further falls. A repair scheme has been identified but has yet to be implemented.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full ladar repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).



© Historic England

SITE NAME: Twizel medieval tower house and folly, Twizel, Duddo Scheduled Monument and Listed DESIGNATION: Building grade II*, RPG grade II* CONDITION: Very bad OCCUPANCY:

N/A PRIORITY CATEGORY: C (C)

OWNER TYPE: Private LIST ENTRY NUMBER: 1018445 and 1042168

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

Contact: Sara Rushton 0191 269 1222

The present building incorporates the remains of a

medieval tower house that was later developed into an

now stands to three storeys. The site is unmanaged and

shows signs of structural instability, including substantial vertical cracks around many of the arches and window

openings. A measured survey has been completed and

discussions are underway to develop a repair scheme.

C18 folly by Sir Francis Blake. Originally five storeys high, it



© Historic England

SITE NAME:	Ford Castle, Ford
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority

1371004

Originally a C14 quadrilateral castle with four corner towers, converted to a mansion in 1694 and further altered in 1761 (for John Hussey Delaval) and 1862 (for the Marchioness of Waterford). Now used for residential courses and as a venue for functions. A number of repairs have been undertaken to address the areas most affected by rainwater ingress, but further work is required. A programme of repairs is in progress.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME Ford Colliery, Ford Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: D (D) OWNER TYPE: Charity (non-heritage)

1020746 and 1154125

Monument including above and below ground remains of Ford Colliery. The colliery worked from at least the middle of the C17 through to 1919. The site includes the engine house chimney which was repaired in 2008/9. A condition survey has been prepared for the engine house and pit head and a programme of archaeological recording and borehole investigations is on-going, funded by Historic England. A full repair scheme now needs to be developed and implemented to enable public access to these structures.

Contact: Kate Wilson 0191 269 1221



© Historic England Archive

SITE NAME:	Entrance gates to Hartford Hall, Hartford Bridge, Hartford
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

1041381

Gates made by the Coalbrookdale Company and exhibited at the Vienna Exhibition of 1873. Historic England offered grant-aid towards the repair of the gates, but that project later stalled when the then owners of the estate went into administration. The gates are now in safe temporary storage. An updated condition assessment was completed with Historic England funding in 2014 and options to try and secure a sustainable long-term solution are being explored.

Contact: David Farrington 0191 269 1230



© Historic England

use,

1041329

Pillbox or defensible latrine, circa 1917. Rare survival as part of a World War I fort. Suffering from structural problems and lack of maintenance. A repair scheme has been drawn up with funding from Historic England, and discussions are underway about the next steps.

Contact: Rosie Brady 0191 269 1231

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

LIST ENTRY NUMBER:



© Northumberland Council

SITE NAME: Water tank, Fort House, A I 93 (east side), Hartley, Seaton Sluice DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: D (D)		
CONDITION: Poor OCCUPANCY: Part occupied/part in use	SITE NAME:	(east side), Hartley, Seaton
OCCUPANCY: Part occupied/part in use	DESIGNATION:	Listed Building grade II*
	CONDITION:	Poor
PRIORITY CATEGORY: D (D)	OCCUPANCY:	Part occupied/part in use
	PRIORITY CATEGORY:	D (D)
OWNER TYPE: Private	OWNER TYPE:	Private

1303566

Water tank incorporating former ablutions building, built circa 1917 and a rare survival of part of a World War I fort. Suffering from structural problems and lack of maintenance. A repair scheme has been drawn up with funding from Historic England, and discussions are underway about the next steps.

Two defended farmhouses dating from between 1575-1650 in the hamlet of Chesterwood. Both buildings were suffering from major structural problems but are now the subject of a repair programme which is nearing completion.

Contact: Rosie Brady 0191 269 1231

	T
L'ANDER S	是是

© Historic England

SITE NAME:	Bastles at Chesterwood, Haydon Bridge, Haydon
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II
CONDITION:	Good
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private

1006432 and 1042501;

1154494; 1154518

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Stublick Colliery beam engine house, Haydon
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1370425

The beam engine house is part of the Stublick Colliery site the finest group of early C 19 colliery buildings in the region. Although other grade II* buildings on the site are in fair condition, the engine house is in urgent need of repair. The ground around the colliery buildings was scheduled in November 2003.

© Historic England

SITE NAME:	Crawley Tower (with cottage inside), Crawley, Hedgeley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1057698

Remains of an early C14 tower house, with an C18 cottage built inside when the ruins were altered to form an eye-catcher on the Shawdon Estate. Constructed of massive squared stone; the cottage with a slate roof. The interior is now gutted and contains structural propping. The tower is vacant with no identified use, although the adjacent buildings form part of a working farm. A budget for project development work has been identified.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Hepple Tower, Hepple
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1371440

but the eastern wall collapsed many years ago. The interior walls are around eight feet thick and most of the tunnel vault remains. Now under threat from encroachment by vegetation and there are signs of stone and pointing decay. A repair scheme has been drawn up with Historic England funding and discussions are underway to agree the next steps.

C14 ruined tower. The south wall stands to almost 40 feet

Contact: Tom Gledhill 0191 269 1203

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	The Palace, medieval house and Tudor supply base, Holy Island
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1014571

Rare survival of a group of medieval buildings in a courtyard arrangement. The exterior north wall is suffering from localised areas of collapse. In an Area of Outstanding Natural Beauty and on the Heritage Coast. In 2014, The Palace was included in the Peregrini Landscape Partnership project with the aim of repairing the visible structures and removing the site from the Heritage at Risk Register.

Contact: Kate Wilson 0191 269 1221

2014			The said	
		M	#	
	///	11#1	4	1

© Historic England

SITE NAME:	Union Suspension Bridge (that part in England), Horncliffe
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1042214

Spanning the border of Scotland and England across the River Tweed, the bridge was built in 1820. It is Britain's oldest suspension bridge in road use. Some repairs have been undertaken but a further programme of investigative and remedial works is required to safeguard the structure in the long-term. Funding options are being explored.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Bastle, 100 metres south west of Ray Cottages, Kirkwhelpington
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)

Private

1011107

Ruined C16/C17 defended farmhouse, situated in the gardens of Ray Castle, with 1.4 metres thick stone walls standing to a maximum height of 2.2 metres. Very little mortar remains in the joints between the squared stonework. Historic England offered a Management Agreement grant towards the clearance of mature vegetation that was dislodging masonry.

Tilery built for the Kirkharle Estate c I 800. Masonry and the brick vaults are in a poor condition due to invasive vegetation and loss of fabric. Vegetation control would help

Contact: Kate Wilson 0191 269 1221

secure its long-term future.



© Historic England

SITE NAME:	Capheaton tilery, Mirlaw House, Kirkwhelpington
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1006418 Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Barmoor Castle, Barmoor, Lowick
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1156023

Country house of 1801 that incorporates earlier masonry. The building received grant aid towards repairs in 1986 but further deterioration has occurred. A grant was offered by Historic England in 2011 towards a package of project development works. That work, which included the preparation of a conservation plan and condition survey, is helping to inform discussions about the site's future.

Contact: David Farrington 0191 269 1230

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full ladar repair on in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Northumberland Council

	(- /
SITE NAME:	Pithead baths at Lynemouth Colliery, Lynemouth
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company

Pithead baths of 1938 by FG Frizzell in Modern Movement style. Vacant for over twenty years and subject to vandalism. There have been recent discussions with the new owner of the site about the repair and re-use of the structure.

Late C11 motte and bailey castle converted to a shell keep in C12. Five-sided keep of C13 includes C12 curtain wall, curtain wall structures and mid C12 chapel. It is now a roofless ruin but capable of consolidation. Grant offered for photographic recording (now complete). Historic England offered grants towards three phases of the repair programme, the first two of which are now complete.

1156081 Contact: Martin Lowe 0191 269 1233

Party -		
	Mil.	
-	A sellength	
12 40		Sales S
		No. of the
	March Countries and	
	The State of the Land	
		SELECTION OF

SITE NAME:	Mitford Castle, Mitford
DESIGNATION:	Scheduled Monument and Listed Buildings - 5 grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNED TYPE	Ci-l

OWNER TYPE: Commercial company

1017318 and 1370755;
LIST ENTRY NUMBER: 1042645; 1370756; 1042647;

1042646

Contact: Kate Wilson 0191 269 1221



© Historic England

© Historic England

SITE NAME:	Church of St Mary, Woodhorn, Newbiggin by the Sea
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority

1304471

Former parish church with surviving pre-Conquest elements. Significant rebuilding work took place throughout the C12 and C13 before a major rebuild was carried out in 1843-44 by B & J Green architects. The church closed as a place of worship in 1972 and was subsequently used as a museum and workspace for artists. Structural movement has been identified in some parts of the building and other repairs are required. Discussions are underway to help secure the church's repair and future use.

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME:	Cocklaw Tower, East Cocklaw, Wall
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

1006602 and 1156641

C14 tower containing wall paintings of probable C16 date. The tower is roofless, with self-seeded shrubs in the wall tops and over the first floor barrel-vaulting. The wall tops are perilous and there has been a partial collapse of the vaulting. The wall paintings show recent loss and are highly vulnerable.



© Historic England

SITE NAME:	Mausoleum, east of Seaton Delaval Hall, Seaton Delaval
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)

1154937

Mausoleum of 1766; the focal point of a walk to the east of the Hall, overlooking parkland to the south. The Hall was built 1718-29 by Vanbrugh, with early C18 landscaping incorporating earlier and later features. The mausoleum is roofless and subject to graffiti and vandalism. Urgent works were funded by Historic England in 1994, but further works are required to the building and its setting.

Contact: Chris Mayes 0191 269 1226

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full lader repair on in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Carrshield lead mines and ore works, Carrshield, West Allen
DESIGNATION:	Scheduled Monument and Listed Buildings - 5 grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

1015849 and 1155612:

1303252; 1042930; 1042931; 1042932 The remains of two lead mines and an ore works on the base and lower slopes of the West Allen valley at Carrshield. The site was used over three centuries, leaving a complex assortment of remains. The grade II lodging shop is the largest of its kind in the North Pennines but has severe structural damage and parts of the stone wall revetment have collapsed into the river. Exploratory works have identified options for the repair and consolidation of the revetment and work is progressing. Building repairs are anticipated for 2017 with funding from the Allen Valleys Landscape Partnership.

Contact: Tom Gledhill 0191 269 1203

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Simonburn Castle, Castle Lane, Simonburn
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1012414 and 1302543

C13 tower house with C18 Gothick style additions to create a folly. The basement vault has suffered some collapse and there is damaging vegetation growth. In need of urgent repair. A Management Agreement was established with the owner to clear some of the vegetation.



© Historic England

SITE NAME:	Sharpe's Folly, Rothbury, Tosson
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company

1155472

Folly, probably 1720s, by Archdeacon Sharpe, Rector of Rothbury. Ashlar round tower c30 feet high. Probably the earliest folly in the county, said to have been built partly to alleviate local unemployment and partly to satisfy the Archdeacon's taste for astronomy. Discussions are underway with the owner, Local Authority and Historic England to secure urgent repairs.



© Historic England

SITE NAME:	Church of St Michael, Alnham
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1303455

St Michael's has a nave with west bellcote, chancel, transepts and a south porch. It dates largely to the late C12/early C13, but there are Saxon stones at the northeast and south-east corners of the nave. The building was restored in 1870, having stood for many years as a dilapidated ruin. There is some internal water ingress due to problems with the stone-slated roofs and related roof details. Rainwater gutters and pipes also need overhauling. A grant has been offered by the Heritage Lottery Fund to allow a repair scheme to be drawn up.

Contact: Kate Wilson 0191 269 1221



SITE NAME:	Roman Catholic Church of St Robert, Oldgate, Morpeth
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1156182

Constructed around 1850, St Robert's has a soaring octagonal spire positioned over a south-west tower and porch. The porch allows access to an aisleless nave and chancel beyond. A later single-storey sacristy is attached to the chancel by a short linking passage. The walls are constructed of craggy sandstone and the Welsh slate roofs are supported on open timber roof trusses. Urgent structural repairs to the spire stonework were completed in 2015. A grant from the Heritage Lottery Fund has been offered for essential repairs to the roof coverings and stonework repairs to the tower.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise

New Entry is noted).

	ABBREVIATIONS	
	CA	Conservation Area
s	LB	Listed Building
١,	LPA	Local Planning Authority
	NP	National Park
	RPG	Registered Park and Garden
	SM	Scheduled Monument
	UA	Unitary Authority
	WHS	World Heritage Site



SITE NAME:	Church of St George, Prudhoe
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1044950

The original church was built in 1825. Cruciform in plan, the present building dates almost entirely from an extensive remodelling in 1886. The red tiled roof coverings have reached the end of their serviceable life due to corroded fixings and require replacement. Funding options for essential repairs are being explored.

Contact: Kate Wilson 0191 269 1221

© Historic England



	SITE NAME:	Church of St Cuthbert, Church Street, Haydon
	DESIGNATION:	Listed Place of Worship grade II*, CA
	CONDITION:	Poor
	PRIORITY CATEGORY:	C (C)
	OWNER TYPE:	Religious organisation
	LIST ENTRY NUMBER:	1154539

The church was erected in 1796 by the Greenwich Hospital Trustees, to whom the Derwentwater estates passed in the C18. It has an elegant west tower, narrower than the nave, which is topped by a pagoda-like roof. A north transept was added in 1869 to accommodate children from the Shaftoe Trust School. The chancel was enlarged, and other alterations made, in 1898. There is structural movement in the transept and rainwater ingress.

Contact: Kate Wilson 0191 269 1221

© Historic England



SITE NAME:	Church of St James, Middle Road, Shilbottle
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1041723

Built in 1884, and incorporating fragments from an earlier C12 church, St James is cruciform in plan with a central tower, south porch and north vestry. The tower roof is covered with felt and is allowing significant water ingress. Rainwater gutters and pipes also require overhauling. The Heritage Lottery Fund has offered a grant to enable a repair scheme to be drawn up.

Contact: Kate Wilson 0191 269 1221

© Historic England



SITE NAME:	Haydon Old Church, Old Haydon, Haydon
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1042512

Former parish church, still used for worship, with C12 chancel and C14 south chapel. Some Roman material has been used amongst the squared stonework and the font is a re-cut Roman altar. The roof has serious problems, with a heavy build-up of moss which is holding water and exacerbating the problems caused by water penetration through holes in the roof.

Contact: Kate Wilson 0191 269 1221

© Historic England



© Historic England

SITE NAME:	Church of St Aidan, Tarset
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1302858

Built in 1818 by HH Seward for the Commissioners of Greenwich Hospital, the church has an embattled west tower, continuous nave and chancel, and north vestry. A porch at the base of the tower provides access to a simple, well proportioned interior. High level stonework is deteriorating due to water ingress. Rainwater gutters and pipes are in poor condition and some roof details and junctions are in need of repair.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of Our Lady, A190, Seaton Delaval
DESIGNATION:	Listed Place of Worship grade I, RPG grade II*, CA
CONDITION:	Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1041317

Originally the private chapel of the Delaval family, the church has a short and tall nave, lower chancel and west porch. It dates from the early C12, but may incorporate earlier fabric. Structural movement is affecting two internal arches and the east wall and has been monitored since 1998. Following a specialist report in 2011, exploratory work is underway to determine the cause of the movement and potential repair solutions. This work has been made possible through grant support from the Heritage Lottery Fund and advice from Historic England.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Defended settlement, 1.05 kilometres north west	of North Farm, Add	derstone with Lucker
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006478
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Iron Age defended settlement and cultivation terra	ces 600 metres no	rth east of Brown's Law Cottage, Akeld
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019139
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Allen smelt mill, flue system and chimneys, Allenda	le	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016817
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Camp on Alnwick Moor, Alnwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006474
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Haggerston dovecote, Ancroft		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006570
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round barrow 520 metres WNW of Quarry Cott	age, Bamburgh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014503
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Defended settlement and Roman signal station 410	metres south of V	Vest Crindledikes, Bardon Mill
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1018536
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Rabbit - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Benthall round cairn, Beadnell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008430
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	St Ebba's chapel and monastic site, Beadnell		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008563
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Chester's Hill camps, Belford / Easington / Middleto	on	
esignation:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1006513
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth NEW ENTRY?: No		No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Huckhoe palisaded enclosure, defended settlement Bolam West Houses, Belsay	and Romano-Britis	sh settlement, 550 metres north east
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011838
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Springhill Roman camp, Berwick-upon-Tweed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003655
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Romano-British farmstead, 520 metres north east of Birtley Shields, Birtley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009676
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Romano-British settlement, 300 metres north of T	he Heugh, Birtley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010045
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Tinkler's Dene univallate hillfort, 400 metres north	east of Dancing H	all Farm, Callaly
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011095
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Defended settlement, 450 metres NNW of Ferney	Chesters, Caphea	ton
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011835
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Romano-British settlement and Iron Age defended settlement, 550 metres north east of Shaftoe Grange, Capheaton / Wallington Demesne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Simonside camp, Chatton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002907
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two cairn cemeteries west of Willie Law, Chatton	/ Chillingham	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006451
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hepburn Crags camp, Chillingham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006547
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- C Slow decay; no solution agreed.
- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 D Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION: CONDITION: PRINCIPAL VULNERABILITY: OWNER TYPE:	Scheduled Monument, LB grade II, WHS Unknown	LIST ENTRY NUMBER:	1006611
PRINCIPAL VULNERABILITY:	Unknown		
	-	TREND:	Unknown
OWNER TYPE:	Arable ploughing	NEW ENTRY?:	No
	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum between the track to Poin wall miles 22 and 23, Corbridge / Sandhoe / Wal		the field boundary east of milecastle 24
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010626
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum between the Fence Burr Corbridge / Whittington	and the track to P	Portgate Cottage in wall miles 21 and 22
DESIGNATION:	Scheduled Monument, LB grade II, WHS	LIST ENTRY NUMBER:	1010625
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	Yes
OWNER TYPE:	Private, multiple owners	CONTACT:	Mike Collins 0191 269 1212
SITE NAME:	Cornhill Castle, Cornhill-on-Tweed		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006508
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Enclosed settlement, 620 metres south east of Cor	nhill Castle, Cornh	ill-on-Tweed
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006409
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ridsdale ironworks, Corsenside		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006420
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Cresswell tower house, Cresswell		
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER:	1014509
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Tom Gledhill 0191 269 1203

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Heiferlaw defended settlement, 100 metres north	of Holywell, Denwi	ick
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014080
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Incised rocks, 500 metres north west of Doddingto	on Dean Wood, De	oddington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006555
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Roughting Linn camp, Doddington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006601
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two camps and cup and ring marked rocks on Doc	d Law, Doddington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002946
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Iron Age defended settlement in Camp Plantation,	350 metres north	west of North Charlton Mill, Eglingha
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017955
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Site south west of Thirlings, Ewart		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006436
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Haw Hill camp, Falstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006491
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Flooding	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

HERITAGE AT RISK 2016 / NO	RTH EAST / NORTHUMBERLAND (UA)		
SITE NAME:	Circular enclosure west of Second Linthaugh, Ford	I	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006430
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Flodden camp, Ford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006481
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Two incised rocks on Broom Ridge, Hunter's Moo	r, Ford	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006554
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Langley Barony lead mines, Haydon Bridge, Haydon	n	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006413
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum from Throckley to East Heddon-on-the-Wall	Town House, Hedo	don-on-the-Wall in wall mile 11,
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010616
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Mike Collins 0191 269 1212
ITE NAME:	Romano-British enclosed settlement, 800 metres r	orth west of East E	Bolton, Hedgeley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007446
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Hut circle settlement and field system, Romano-Br north east of Burntshield Haugh, Hexhamshire	itish settlement, hu	sh and lead ore works, 750 metres
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017959
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Medieval chapel and associated building on St Cuth	bert's Isle, Holy Isla	and
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014485
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Coastal erosion	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Nafferton castle and tower house, 750 metres east	t of Nafferton Farm	, Horsley
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018369
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Remains of medieval bridge, Chollerford, Humshau	ıgh	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006567
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn 790 metres west of Smithy Strip, Ilder	ton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016248
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Defended settlement 580 metres north west of Go	owanburn and asso	ciated medieval buildings, Kielder
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009672
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	Yes
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Castle Hill camp, Kilham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006470
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Newminster Abbey, Mitford Road, Morpeth		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1006563 and 1155952
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Camp in Oakwood, south east of Plenmeller village	e, Plenmeller with V	Vhitfield
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006484
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Ellsnook round barrow, 175 metres north east of	Heiferlaw Bridge, R	ennington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006564
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
RINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
TE NAME:	Cairn, 900 metres north east of Old Rothbury hillf	ort, Rothbury	
ESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
TE NAME:	Old Rothbury multivallate hillfort and cairnfield, Ro	othbury	
esignation:	Scheduled Monument	LIST ENTRY NUMBER:	1011616
ONDITION:	Extensive significant problems	TREND:	Improving
RINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
TE NAME:	Allensford blast furnace, Shotley Low Quarter		
ESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1006405
ONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sara Rushton 0191 269 1222
TE NAME:	The vallum between Oatens Bank, Harlow Hill, and	d Whittle Dene Wa	tercourse in wall mile 16, Stamfordh
ESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010621
ONDITION:	Extensive significant problems	TREND:	Unknown
RINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
WNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
TE NAME:	Medieval monastic sheep farm (bercaria), 550 met	res north-east of W	hittondean Farm, Whitton and Tosso
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011292
CONDITION:	Extensive significant problems	TREND:	Declining
RINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Two round cairn	Two round cairns, 590 metres and 610 metres east		nitton and Tosson
DESIGNATION:	Scheduled Monur	ment	LIST ENTRY NUMBER:	1017197
CONDITION:	Generally satisfac problems	tory but with significant localised	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth		NEW ENTRY?:	No
OWNER TYPE:	Private, multiple	Private, multiple owners		Kate Wilson 0191 269 1221
SITE NAME:	Low Chibburn m	edieval preceptory, C16 house an	d World War II pil	lbox, Widdrington Village
DESIGNATION:	Scheduled Monur	Scheduled Monument		1014679
CONDITION:	Generally unsatis	Generally unsatisfactory with major localised problems		Declining
PRINCIPAL VULNERABILITY:	Metal detecting -	unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Private		CONTACT:	Kate Wilson 0191 269 1221
	SITE NAME:	Seaton Delaval	Remains of an ea	arly C18 park and garden, partially restor
	DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, CA	Vanbrugh in 171	. House and landscape by Sir John 9. The approach avenue is deteriorating egeneration is concealing key landscape



© Historic England

SITE NAME:	Seaton Delaval
DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1001052

Remains of an early C18 park and garden, partially restored in the 1950s-60s. House and landscape by Sir John Vanbrugh in 1719. The approach avenue is deteriorating and woodland regeneration is concealing key landscape features, including earthworks and the Mausoleum. Ha-ha walls and corner bastions are being damaged by scrub and tree growth, with areas of partial collapse. The site was acquired by the National Trust in December 2009 and opened to visitors in May 2010. A Conservation Management Plan has been produced. The site was awarded a Heritage Lottery Fund grant in 2016.

Contact: Chris Mayes 0191 269 1226



© Historic England

SITE NAME:	Tillmouth Park, Cornhill-on- Tweed / Duddo
DESIGNATION:	Registered Park and Garden grade II*, 11 LBs, 2 SMs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners

1001053

Early and late C19 picturesque pleasure grounds and formal gardens. The picturesque walks alongside the River Till, along The Dean and to the 'eye-catcher', Twizel Castle, are masked by natural woodland regeneration. Several other heritage assets situated within the park and garden are in poor condition, including ha-ha walls, garden walls, an ornate Gothick bridge and the Henlaw Tunnel.

Contact: Chris Mayes 0191 269 1226

SITE NAME:	Amble, Morpeth, Amble By the Sea		
DESIGNATION:	Conservation Area, 18 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Low	CONTACT:	Liz Williams (LPA) 01670 620305
SITE NAME:	Berwick-upon-Tweed		
SITE NAME: DESIGNATION:	Berwick-upon-Tweed Conservation Area, 262 LBs, 4 SMs	NEW ENTRY?:	No
	'	NEW ENTRY?: TREND:	No Improving
DESIGNATION:	Conservation Area, 262 LBs, 4 SMs		

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Tweedmouth, Berwick-upon-Tweed		
DESIGNATION:	Conservation Area, 18 LBs, part in SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Liz Williams (LPA) 01670 620305

NORTHUMBERLAND (NP)



© Historic England

SITE NAME:	Hadrian's Wall from Cockmount Hill to Walltown, Greenhead, Northumberland (UA)
DESIGNATION:	Scheduled Monument and Listed Building grade I, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

Sections of unconsolidated Hadrian's Wall in Wall Miles 43, 44 and 45. Issues lie with a short section of the Wall above Walltown quarry and the remains of Wall turret 44b. Initial inspections suggest limited consolidation and capping works would address the remaining management issues, but agreement on the way forward (including funding) has yet to be reached.

1017535 and 1155916 Contact: Mike Collins 0191 269 1212 LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Bastle at Horneystead, 400 metres south west of The Ash, Wark, Northumberland (UA)
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

A defensive farmhouse of the type found only in the northern border counties of England. The walls stand up to 4.5 metres high but the first floor has collapsed on a barrel vault. The main cause for concern was a large tree growing out of the upper courses of the north wall, whose roots were displacing and dislodging original fabric. The tree was removed during 2009 but further consolidation works are required.

LIST ENTRY NUMBER: 1009674 Contact: Kate Wilson 0191 269 1221

SITE NAME:	Romano-British farmstead 900 metres north east Northumberland (UA)	of triangulation poir	nt on Gains Law, Akeld,
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1017381
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Unenclosed scooped settlement on the east slope Cottages, Akeld, Northumberland (UA)	of Harehope Hill, 7	750 metres south east of High Akeld
DESIGNATION:	Scheduled Monument, RB	LIST ENTRY NUMBER:	1014932
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Cairnfield, unenclosed hut circle settlement and a Alnham, Northumberland (UA)	rea of cord rig 190 r	metres north east of Pigdon's Leap,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020250
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Sara Rushton 0191 269 1222

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Three cross dykes on Middle Hill, Alwinton, Northumberland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007525	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Prehistoric field system and unenclosed hut circle settlement on eastern slopes of Hart Heugh, 550 metres south west of Earlehillhead, Earle, Northumberland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018441	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Roman period native enclosed settlement, 360 met (UA)	res south east of B	roadstruther, Earle, Northumberland	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016249	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Roman period native settlement on southeastern s Bridge, Earle, Northumberland (UA)	lope of Hart Heugh	n, 490 metres north west of Carey Burn	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016237	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Roman period native settlement, 750 metres north	west of Carey Bur	rn Bridge, Earle, Northumberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018440	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Two prehistoric enclosures, field clearance cairns a 600 metres south west of Wooler Common, Earle			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018442	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Haltwhistle Burn Roman temporary camps 2 and 3 Northumberland (UA)	and area of cord r	ig cultivation, Haltwhistle,	
SITE NAME: DESIGNATION:		and area of cord r	ig cultivation, Haltwhistle,	
	Northumberland (UA)		_	
DESIGNATION:	Northumberland (UA) Scheduled Monument, WHS Generally satisfactory but with significant localised	LIST ENTRY NUMBER:	1010946	

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 C Slow decay; no solution agreed.

- Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.

 Slow decay; solution agreed but for tyet implemented.

 Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial like) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems proble	Cross dyke, south of Campville, Harbottle, Northumberland (UA)		
PRINCIPAL VULNERABILITY: Plant growth NEW BYTEY: No OWNER TYPE: Government or agency CONTACT: Kate Wilson 0191 SITE NAME: Hadrian's Wall and associated features between the boundary east of turret 34a and the of milecastle 36 in wall miles 34, 35 and 36, Haydon / Simonburn / Bardon Mill, Northumb DESIGNATION: Scheduled Monument, WHS LET ENTRY NUMBER: 1010964 CONDITION: Generally satisfactory but with significant localised TRAND: Declining PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Kate Wilson 0191 STENAME: Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1011839 DECIDING PRINCIPAL VULNERABILITY: No OWNER TYPE: Private CONTACT: Kate Wilson 0191 STENAME: Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1011839 Declining Private CONTACT: Kate Wilson 0191 STENAME: Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESIGNATION: Generally unsatisfactory with major localised problems STENAME: Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DEDEGRATION: Scheduled Monument, WHS LET ENTRY NUMBER: 1010966 CONDITION: Generally satisfactory but with minor localised problems SPRINCIPAL VULNERABILITY: Visitor errosion - limited/localised NEW ENTRY: No OWNER TYPE: Scheduled Monument, WHS LET ENTRY NUMBER: 1010940 Generally satisfactory but with significant localised problems SPRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY: No OWNER TYPE: Scheduled Monument WHS LET ENTRY NUMBER: 1010940 TRENDAME: Scheduled Monument WHS LET ENTRY NUMBER: 1006404 DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1006404 DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1006404 DESIGNATION: Scheduled Monument LET ENTRY NUMBER: 1006404 DESIGNA			
OWNERTYPE: Government or agency CONTACT: Kate Wilson 0191 Hadrian's Wall and associated features between the boundary east of turret 34a and the of milecastle 36 in wall miles 34, 35 and 36, Haydon / Simonburn / Bardon Mill, Northumb DESCRATION: Scheduled Monument, WHS UST ENTRY NUMBER: 1010964 Generally satisfactory but with significant localised problems Animal burrowing - moderate NEW UNITEY: No DOWNER TYPE: Mixed, multiple owners CONTACT: Kate Wilson 0191 STEENAMS: Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESCRATION: Scheduled Monument Scheduled Monument Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPLA VULNERABILITY: No DOWNER TYPE: Private CONTACT: Kate Wilson 0191 Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESCRATION: Scheduled Monument, WHS UST ENTRY NUMBER: 1010966 DESCRATION: Scheduled Monument, WHS SET NAME: Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESCRATION: Scheduled Monument, WHS UST ENTRY NUMBER: 1010940 DESCRATION: Scheduled Monument, WHS SET ENAME: Scheduled Monument UST ENAME: Scheduled Monumen			
Hadrian's Wall and associated features between the boundary east of turret 34a and the of milecastle 36 in wall miles 34, 35 and 36, Haydon / Simonburn / Bardon Mill, Northumb DESIGNATION: Scheduled Monument, WHS Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY: No OWNER TYPE: Mixed, multiple owners CONTACT: Kate Wilson 0191 STE NAME: Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011839 Declining PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS UST ENTRY NUMBER: Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS UST ENTRY NUMBER: I 010966 Generally satisfactory but with minor localised PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY: No DOWNER TYPE: Mixed, multiple owners Scatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS UST ENAME: Scatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS UNROWNER TYPE: No DOWNER TYPE: C18 water mill at Grasslees, Hepple, Northumberland (UA) Declining PRINCIPAL VULNERABILITY: No Declining RENOLITION: Scheduled Monument STE NAME: Scheduled Monument UST ENTRY NUMBER: I 006404 TRENO. Declining Declining STE NAME: STE NAME: STE NAME: Scheduled Monument UST ENTRY			
of milecastle 36 in wall miles 34, 35 and 36, Haydon / Simonburn / Bardon Mill, Northumb DERGRATION: Scheduled Monument, WHS	269 22		
Generally satisfactory but with significant localised problems Animal burrowing - moderate New Entry: No OWNER TYPE: Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESCRIATION: Scheduled Monument Private CONTACT: Kate Wilson 0191 Step Name: Step Name: Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESCRIATION: Scheduled Monument, WHS Stable PRENCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY NUMBER: Mixed, multiple owners Scatsides I Roman temporary camp and section of the Stanegate Roman road from the way from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESCRIATION: Scheduled Monument, WHS Scheduled Monument	eld boundary wes erland (UA)		
PRINCIPAL VULNERABILITY: Animal burrowing - moderate NEW ENTRY?: No OWNER TYPE: Mixed, multiple owners Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESIGNATION: Scheduled Monument Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: No OWNER TYPE: No OWNER TYPE: Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS DESIGNATION: Scheduled Monument, WHS DESIGNATION: Scheduled Monument, WHS DESIGNATION: Wistor erosion - limited/localised PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised DESIGNATION: Scheduled Monument Mixed, multiple owners Scatsides I Roman temporary camp and section of the Stanegate Roman road from the war from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1010940 Unknown PRINCIPAL VULNERABILITY: No OWNER TYPE: Private CONTACT: Kate Wilson 0191 STENAME: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006404 TREND: Declining PRINCIPAL VULNERABILITY: Number: No OWNER TYPE: Private CONTACT: Kate Wilson 0191 STENAME: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument Declining PRINCIPAL VULNERABILITY: Number: No OWNER TYPE: Scheduled Monument Declining PRINCIPAL VULNERABILITY: Name: No OWNER TYPE: Scheduled Monument Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Scara Ru			
Mixed, multiple owners CONTACT: Kate Wilson 0191 Shelling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011839 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Plant growth NEW ENTRY: No OWNER TYPE: Private CONTACT: Kate Wilson 0191 Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS UST ENTRY NUMBER: 1010966 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY: No DOWNER TYPE Mixed, multiple owners CONTACT: Kate Wilson 0191 SETE NAME: Seatsides I Roman temporary camp and section of the Stanegate Roman road from the from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS UST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY: No CONTACT: Kate Wilson 0191 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: No CONTACT: Kate Wilson 0191 CONDITION: Generally satisfactory but with significant localised problems CONTACT: Kate Wilson 0191 C			
STEENAME Shieling, 500 metres south west of Spy Crags, Henshaw, Northumberland (UA) DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1011839 CONDITION: Generally unsatisfactory with major localised TREND: Declining Problems Private CONTACT: Kate Wilson 0191 STEENAME Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS UST ENTRY NUMBER: 1010966 CONDITION: Generally satisfactory but with minor localised TREND: Stable PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY: No DWNER TYPE: Mixed, multiple owners CONTACT: Kate Wilson 0191 STEENAME Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberlar DESIGNATION: Scheduled Monument, WHS UST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised TREND: Unknown PRINCIPAL VULNERABILITY: Scheduled Monument, WHS UST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised TREND: Unknown PRINCIPAL VULNERABILITY: No DOWNER TYPE: Private CONTACT: Kate Wilson 0191 STEENAME: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006404 Generally unsatisfactory with major localised TREND: Declining PRINCIPAL VULNERABILITY: No DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1006404 Generally unsatisfactory with major localised TREND: Declining PRINCIPAL VULNERABILITY: No DECINION: Generally unsatisfactory with major localised TREND: Declining PRINCIPAL VULNERABILITY: No DECINION: Generally unsatisfactory with major localised TREND: Declining PRINCIPAL VULNERABILITY: No Decining			
Designation: Scheduled Monument LIST ENTRY NUMBER: 1011339 CONDITION: Generally unsatisfactory with major localised problems Plant growth NEW ENTRY: No DOWNER TYPE: Private CONTACT: Kate Wilson 0191 SETE NAME: Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010966 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Visitor erosion - limited / localised DOWNER TYPE: Mixed, multiple owners CONTACT: Kate Wilson 0191 SETE NAME: Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY: No DOWNER TYPE: Private CONTACT: Kate Wilson 0191 SETE NAME: CI8 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006404 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No Declining PRINCIPAL VULNERABILITY: Natural erosion - moderate NEW ENTRY: No Declining PRINCIPAL VULNERABILITY: Natural erosion - moderate NEW ENTRY: No Declining	269 22		
Generally unsatisfactory with major localised problems Plant growth Plant growth Private			
PRINCIPAL VULNERABILITY: Plant growth Private Private CONTACT: Kate Wilson 0191 Addrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010966 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY?: No DESIGNATION: Seatsides I Roman temporary camp and section of the Stanegate Roman road from the water from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberlard (UA) CONDITION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Kate Wilson 0191 CONTACT: Kate Wilson 0191 TREND: Unknown DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006404 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No CONTACT: Kate Wilson 0191 TREND: Declining PRINCIPAL VULNERABILITY: No CONTACT: Scheduled Monument LIST ENTRY NUMBER: 1006404 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006404 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006404 TREND: Declining PRINCIPAL VULNERABILITY: No DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: No Declining PRINCIPAL VULNERABILITY: No DESIGNATION: Scheduled Monument Scheduled Monument LIST ENTRY NUMBER: No Scheduled Monument Scheduled Monument Scheduled Monument Scheduled Monument LIST ENTRY NUMBER: No Scheduled Monument Scheduled Mon			
Private CONTACT: Kate Wilson 0191 Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY?: No DWNER TYPE: Mixed, multiple owners CONTACT: Kate Wilson 0191 STEE NAME: Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No DOWNER TYPE: Private CONTACT: Kate Wilson 0191 STEE NAME: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: No CONDITION: Generally unsatisfactory with major localised TREND: Declining PRINCIPAL VULNERABILITY: No CONDITION: Generally unsatisfactory with major localised TREND: Declining PRINCIPAL VULNERABILITY: No Declining PRINCIPAL VULNERABILITY: No DOWNER TYPE: Government or agency CONTACT: Sara Rushton 019			
Hadrian's Wall and associated features between the field boundary west of turret 37a and Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010966 CONDITION: Generally satisfactory but with minor localised problems PRINCIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY?: No CONTACT: Kate Wilson 0191 STE NAME: Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No DOWNER TYPE: C18 water mill at Grasslees, Hepple, Northumberland (UA) Scheduled Monument LIST ENTRY NUMBER: 1006404 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No CONDITION: Generally unsatisfactory with major localised Problems PRINCIPAL VULNERABILITY: No CONDITION: Generally unsatisfactory with major localised Problems PRINCIPAL VULNERABILITY: No CONDITION: Generally unsatisfactory with major localised Problems PRINCIPAL VULNERABILITY: No CONTACT: Sara Rushton 019			
Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA) DESIGNATION: Scheduled Monument, WHS Generally satisfactory but with minor localised problems Visitor erosion - limited/localised DEVINICIPAL VULNERABILITY: Visitor erosion - limited/localised NEW ENTRY?: No CONTACT: Kate Wilson 0191 STE NAME: Seatsides I Roman temporary camp and section of the Stanegate Roman road from the water from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No DESIGNATION: CONTACT: Kate Wilson 0191 TREND: Unknown PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No CONTACT: Kate Wilson 0191 TREND: Declining PRINCIPAL VULNERABILITY: No CONDITION: Generally unsatisfactory with major localised problems NEW ENTRY: No CONTACT: Sara Rushton 019	269 22		
Generally satisfactory but with minor localised problems Visitor erosion - limited/localised NEW ENTRY?: No DWNER TYPE: Mixed, multiple owners Seatsides I Roman temporary camp and section of the Stanegate Roman road from the water from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS LIST ENTRY NUMBER: JORDITION: Generally satisfactory but with significant localised problems Stock erosion - moderate NEW ENTRY?: No DESIGNATION: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: JORGHOUSE CONTACT: Kate Wilson 0191 STEENAME: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: JORGHOUSE TREND: Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Generally unsatisfactory with major localised problems NEW ENTRY?: No Declining PRINCIPAL VULNERABILITY: No OWNER TYPE: Government or agency CONTACT: Sara Rushton 019	Hadrian's Wall and associated features between the field boundary west of turret 37a and the road to Steel Rigg car park in wall miles 37, 38 and 39, Henshaw / Bardon Mill, Northumberland (UA)		
problems Principal Vulnerability: Visitor erosion - limited/localised New entry?: No DWNER TYPE: Mixed, multiple owners Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate DESIGNATION: C18 water mill at Grasslees, Hepple, Northumberland (UA) SETENAME: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: No Declining PRINCIPAL VULNERABILITY: No CONTACT: Sara Rushton 019			
Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate Private CONTACT: Kate Wilson 0191 CONTACT: Kate Wilson 0191 CONTACT: Kate Wilson 0191 CONTACT: CONTACT			
Seatsides I Roman temporary camp and section of the Stanegate Roman road from the w from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland Designation: Scheduled Monument, WHS LIST ENTRY NUMBER: 1010940 CONDITION: Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No CONTACT: Kate Wilson 0191 TREND: CONTACT: Kate Wilson 0191 TREND: Declining PRINCIPAL VULNERABILITY: No CONTACT: Sara Rushton 019			
from Once Brewed to the south side of the B6318, Henshaw / Melkridge, Northumberland DESIGNATION: Scheduled Monument, WHS Generally satisfactory but with significant localised problems FRINCIPAL VULNERABILITY: Stock erosion - moderate Private C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems FRINCIPAL VULNERABILITY: No CONTACT: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - moderate New ENTRY?: No CONTACT: Sara Rushton 019	269 22		
Generally satisfactory but with significant localised problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No DEVINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No CONTACT: Kate Wilson 0191 SITE NAME: C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006404 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - moderate NEW ENTRY?: No DOWNER TYPE: Government or agency CONTACT: Sara Rushton 019			
problems PRINCIPAL VULNERABILITY: Stock erosion - moderate NEW ENTRY?: No CONTACT: Kate Wilson 0191 C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - moderate NEW ENTRY?: No CONTACT: Sara Rushton 019			
Private CI8 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - moderate Devented Wilson 0191 Kate Wilson 0191 LIST ENTRY NUMBER: 1006404 TREND: Declining NEW ENTRYP: No CONTACT: Sara Rushton 019			
C18 water mill at Grasslees, Hepple, Northumberland (UA) DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006404 Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - moderate Devenor Type: Government or agency CONTACT: Sara Rushton 019			
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1006404 CONDITION: Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - moderate Declining NEW ENTRY?: No CONTACT: Sara Rushton 019	269 22		
Generally unsatisfactory with major localised problems PRINCIPAL VULNERABILITY: Natural erosion - moderate Declining New Entry?: No CONTACT: Sara Rushton 019			
problems PRINCIPAL VULNERABILITY: Natural erosion - moderate New entry?: No CONTACT: Sara Rushton 019			
OWNER TYPE: Government or agency CONTACT: Sara Rushton 019			
5 ,			
Bastle 150 metres south west of Morrelhirst, Hollinghill, Northumberland (UA)	269 1222		
DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018994			
Generally unsatisfactory with major localised TREND: Declining problems			
PRINCIPAL VULNERABILITY: Natural erosion - moderate NEW ENTRY?: No			
OWNER TYPE: Private CONTACT: Sara Rushton 019	269 1222		

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

SITE NAME:	Hut circle 320 metres west of Threestoneburn House, Ilderton, Northumberland (UA)		
Designation:	Scheduled Monument	LIST ENTRY NUMBER:	1019924
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Sara Rushton 0191 269 1222
SITE NAME:	Promontory fort 330 metres south east of Middlet	on Dean, Ilderton,	Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019420
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn 850 metres, and two Romano-British settlement and field system 900 metres SSE of Mid	farmsteads, associa dleton Dean, Ildert	ted trackway, moated site, medieval on, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019923
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn cemetery 1000 metres north west of	Heddon Hill, Ilderto	on, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019920
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round cairn on the southern slope of Dod Hill, 80 (UA)	0 metres NNE of T	he Dod, Ilderton, Northumberland
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019868
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Settlements south east of Heddon Hill, Ilderton, N	orthumberland (UA	A)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006443
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Greaves Ash camp, Ingram, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006588
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Animal burrowing - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Reaveley Hill cairn cemetery, Ingram, Northumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006469
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Reaveley Hill settlement, Ingram, Northumberla	nd (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006468
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Settlement on south east slope of Ewe Hill, Ingra	ım, Northumberland	(UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002916
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Forestry	NEW ENTRY?:	Yes
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Unenclosed hut circle settlement, field system, c Linhope Spout, Ingram, Northumberland (UA)	airnfield and cord rig	cultivation immediately north west of
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020247
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Ingram Farm: prehistoric to post-medieval settle Northumberland (UA)	ment, agricultural and	funerary remains, Ingram / Alnham,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021382
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Tom Gledhill 0191 269 1203
ITE NAME:	Elsdonburn Roman period native settlements and	d medieval shieling, K	ilham, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014505
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Enclosed settlement and subsidiary enclosures I Kilham, Northumberland (UA)	60 metres north of Ri	ing Chesters defended settlement,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009527
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- deterioration or loss of labric; is solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

HERITAGE AT RISK 2016 / NOF	RTH EAST / NORTHUMBERLAND (NP)			
SITE NAME:	Northern ring cairn on Coldsmouth Hill, Kilham, Northumberland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009531	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222	
SITE NAME:	Southern ring cairn on Coldsmouth Hill, Kilham, Northumberland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009530	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Sara Rushton 0191 269 1222	
SITE NAME:	Hethpool tower house, Kirknewton, Northumberl	and (UA)		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018439	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Roman period native enclosed settlement 270 met	res ESE of Fleehope	e, Kirknewton, Northumberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014501	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Roman period native enclosed settlement and med Kirknewton, Northumberland (UA)	lieval sheiling 165 m	netres north east of Dunsdale,	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014680	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Natural erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Romano-British settlement 810 metres south east	of Whitehall, Kirkn	ewton, Northumberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019927	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Settlement north of White Law, Kirknewton, North	thumberland (UA)		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006456	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Settlement north west of Ell's Knowe, Kirknewton	, Northumberland	(UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008478
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Settlement on north east slope of Yeavering Bell, k	Kirknewton, North	umberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006459
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Settlement on north slope of Yeavering Bell, Kirkn	ewton, Northumbe	erland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006466
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Settlement on the east slope of The Bell, Kirknewt	on, Northumberlar	nd (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006465
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
ITE NAME:	Settlement, probably medieval, south west of Torle	eehouse, Kirknewto	on, Northumberland (UA)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006426
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Unenclosed settlement, part of a field system, Rommetres south east of Whitehall, Kirknewton, Nort		ate village and group of shielings, 470
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019929
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum between the field bound 34a in wall miles 32, 33 and 34, Newbrough / Simo		
DESIGNATION:	Scheduled Monument, LB grade I, WHS	LIST ENTRY NUMBER:	1010963
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Kate Wilson 0191 269 1221

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed.
 Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented.

 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but not yet implemented.

 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

SITE NAME:	Romano-British farmstead 850 metres south of Troughend, Otterburn, Northumberland (UA)			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009380	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sara Rushton 0191 269 1222	
SITE NAME:	Fishponds, 450 metres north east of Sewingshields,	Simonburn, North	numberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011081	
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221	
SITE NAME:	Walwick Fell Roman temporary camp, Warden, No	orthumberland (UA	A)	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1010935	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No	
OWNER TYPE:	Private	CONTACT:	Mike Collins 0191 269 1212	
SITE NAME:	Romano-British farmstead, 175 metres south of Co	ockpit Well, Whitto	on and Tosson, Northumberland (UA)	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009582	
CONDITION:	Extensive significant problems	TREND:	Declining	
PRINCIPAL VULNERABILITY:	Bracken	NEW ENTRY?:	No	
OWNER TYPE:	Commercial company	CONTACT:	Kate Wilson 0191 269 1221	

TEES VALLEY

DARLINGTON (UA)



Dovecote, 45 metres east of Manor House, Houghton Bank Lane, Houghton Le Side DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY C (C)

OWNER TYPE: Commercial company

© Historic England

1121194 LIST ENTRY NUMBER:

SITE NAME:

repairs, repointing and removal of vegetation from walls.

Dovecote, probably medieval. Disused and requires roof

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME: Church of All Saints, Sockburn Lane, Sockburn Scheduled Monument and Listed DESIGNATION: Building grade I CONDITION: OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Religious organisation

1002340 and 1185947

An important site containing the ruined remains of a pre-Conquest church. Repair works were completed in 2006, and again in 2010, with Historic England funding. Discussions are underway with a new owner about the site's future.

Contact: David Farrington 0191 269 1230

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA NP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Sockburn Hall, Sockburn Lane, Sockburn
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private

Country house of 1834 which has deteriorated due to a lack of maintenance over many years. Water ingress has led to the localised collapse of floors and ceilings, and there is general decay throughout. Historic England has funded holding repairs and a viability study. Discussions are underway with a new owner to secure the site's repair and re-use.

Contact: David Farrington 0191 269 1230

diction of the formation of the formation of the formation of the first of the formation of
-1130

SITE NAME: Church of St Hilda, Park Gate, Darlington DESIGNATION: Listed Place of Worship grade II CONDITION: Poor PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

1322955

1116156

Built (1887-88) in red brick in the Early English style by eminent C19 church architect JL Pearson. The stained glass and interior fittings were removed soon after closure in 1986. The church then suffered a fire before being acquired and re-used for worship by the Life and Light Mission. Roof coverings are reaching the end of their life and low level brickwork is in need of repair.

Contact: Kate Wilson 0191 269 1221

© Historic England

SITE NAME:	Small multivallate hillfort and tower mill on Shackle	eton Beacon Hill, H	eighington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016867
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Tom Gledhill 0191 269 1203
SITE NAME:	Northgate		
DESIGNATION:	Conservation Area, 14 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rosalind Kain (LPA) 01325 406326
SITE NAME:	Victoria Embankment		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rosalind Kain (LPA) 01325 406326
SITE NAME:	West End		
DESIGNATION:	Conservation Area, 39 LBs, part in RPG grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Rosalind Kain (LPA) 01325 406326

HARTLEPOOL (UA)



© Historic England

SITE NAME:	Church of St Mary, Durham Street, Hartlepool
DESIGNATION:	Listed Place of Worship grade II. CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1250263

Designed in 1850 by the architect JA Hansom, St Mary's church has a west tower (from which a spire was removed c1945) and a bowed apsidal chancel. The external limestone walls are displaying numerous problems, including multiple vertical fractures at the west end of the building, some pockets of deep erosion, open joints, internal powdering and inappropriate cement repairs which are failing. The cause of the cracking requires further investigation in order to establish a phased repair programme. There are some missing and slipped roofing slates and the gutters are partly blocked.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Church of St Hilda, High Street, Hartlepool Headland
DESIGNATION:	Listed Place of Worship grade I,

CONDITION: Poor PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1263355

Built around 1200 on the site of a C7 monastery, incorporating the remains of an early C12 church. There are many Saxon and medieval architectural fragments throughout the church, which has undergone several redesigns and was fully restored between 1925 and 1932. The church is on an exposed site near the sea and the parapets (and other masonry) are open-jointed. In addition to having a spalling roof, the tower has structural issues that are under investigation. The building has also been the subject of heritage crime.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Low Throston deserted medieval village		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006765
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Medieval farmstead and irregular open field system at High Burntoft Farm, Elwick		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1015207
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vehicle damage/erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Church Street, Hartlepool		
DESIGNATION:	Conservation Area, 17 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Sarah Scarr (LPA) 01429 523275
SITE NAME:	Headland, Hartlepool, Headland		
DESIGNATION:	Conservation Area, 35 LBs, 2 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Sarah Scarr (LPA) 01429 523275
SITE NAME:	Park, Hartlepool		
DESIGNATION:	Conservation Area, 10 LBs, RPG grade II	NEW ENTRY?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	High	CONTACT:	Sarah Scarr (LPA) 01429 523275
SITE NAME:	Seaton Carew, Hartlepool		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Sarah Scarr (LPA) 01429 523275
MIDDLESBROUGH (UA)			
SITE NAME:	Acklam Hall, Acklam		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Heather Nelson (LPA) 01642 729116

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Middlesbrough Historic Quarter		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Heather Nelson (LPA) 01642 729116

NORTH YORK MOORS (NP)

SITE NAME:	Pinchinthorpe Hall moated site and post medieval gardens, Guisborough, Redcar and Cleveland (UA)		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1013215
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Round barrow on Codhill Heights, 860 metres sout Cleveland (UA)	th east of Codhill F	arm, Guisborough, Redcar and
SITE NAME: DESIGNATION:		th east of Codhill F	arm, Guisborough, Redcar and
	Cleveland (UA)		.
DESIGNATION:	Cleveland (UA) Scheduled Monument Generally unsatisfactory with major localised	LIST ENTRY NUMBER:	1016574

REDCAR AND CLEVELAND (UA)



SITE NAME:	Kirkleatham Hall Stables, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority

Early-mid C18 bastion and adjoining ha-ha. The bastion is badly vandalised and robbed of much stonework. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. Some consolidation work, part-funded by Historic England, was carried out on the bastion during 2011/12 but further repairs are required and the ha-ha remains in a very poor condition.

Mid-C18 bastion. Badly vandalised and robbed of much stonework. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. Some urgent repairs, part-funded by Historic England, were carried out during 2011/12 but further works are required

© Historic England

LIST ENTRY NUMBER: 1329608

Contact: Kate Wilson 0191 269 1221



© Redcar and Cleveland Borough

SITE NAME:	Bastion, north west of Kirkleatham Hall Stables, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1160124

Contact: Kate Wilson 0191 269 1221

to complete the consolidation of the structure.



SITE NAME:	Kirkleatham Hall Stables, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Good
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority

Early C18 stable block. A conservation plan for structures on the Kirkleatham Hall estate was completed in 2008. The stable block was repaired, part-funded by Historic England grant aid, during 2011/12 and is now in good condition. However, further talks are required to identify a sustainable long-term use for the building.

© Historic England Archive LIST ENTRY NUMBER: | 160085 Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

OWNER TYPE:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:



© Redcar and Cleveland Borough Council

	(-)
SITE NAME:	Turner Mausoleum, Church of St Cuthbert, Kirkleatham Lane, Kirkleatham, Redcar
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation

1159896

Mausoleum, in memory of Marwood William Turner, attached to Church of St Cuthbert. 1739-40 by James Gibbs. The building has suffered from water penetration and rising damp, causing damage to the internal plasterwork and internal monuments. A grant from the Heritage Lottery Fund was offered in 2011 towards a package of urgent repairs; these are due to be completed in 2016.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221

的情况
《四月》 《四月》 《四月》 《四月》 《四月》 《四月》
1000 1000 1000 1000 1000 1000 1000 100
《新聞》
The second secon
THE RESERVE OF THE PARTY OF THE
AND THE RESERVE OF THE PARTY OF

© Historic England

SITE NAME:	Remains of Kilton Castle, Kilton Thorpe Lane, Kilton, Lockwood
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private

C12-C13 castle ruin occupying a rocky outcrop. The building is in a very bad condition, with vertical cracks in its walls and there is some regeneration of vegetation. There is only limited management by the Estate.

LIST ENTRY NUMBER: 1018946 and 1136489

© Redcar and Cleveland Borough Council

SITE NAME:	War Memorial, Saltburn by Sea, Glenside, Saltburn, Marske and New Marske
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (A)

Local authority

1387499

Arts and Crafts style memorial to the dead of World War I, with bronze sculpture by Sir William Reynolds-Stephens. Unveiled on 14 November 1920. The cross has open joints and cracking in its west arm. The surrounding paved area and retaining walls have suffered from subsidence and corrosion is affecting the heavily patinated bronze sculpture. A repair scheme is in progress and should be completed in 2016.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Cuthbert, Church Lane, Redcar
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation

1139628

Built in 1875 on an Anglo Saxon foundation, the church comprises a nave with north aisle and chancel. The north porch, vestry, organ chamber and oak shingled spire are later additions. The rainwater management system needs repair along with the roof coverings and there are deep pockets of erosion affecting the external stonework. The building is also vulnerable to heritage crime.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Eston Nab hill fort, palisaded settlement and beacon, Guisborough		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011273
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Lee McFarlane 0191 269 1239

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

cA gory is LB rwise, LPA NP RPG SM

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Manorial settlement, dovecote and fragment of field Marske and New Marske	d system, immediat	ely north of Marske Inn Farm, Saltburn,
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018948
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Valley Gardens, Saltburn, Saltburn, Marske and New Marske / Skelton and Brotton
DESIGNATION:	Registered Park and Garden grade II, 2 LBs, CA
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	Yes
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1001429

Public pleasure grounds developed from 1861 to designs principally by Joseph Newton. Paths and steps have subsided and tree and shrub growth has been allowed to develop unchecked, mainly due to the steeply sloping nature of the site. The Albert Memorial (grade II) and other structures around the site, including high-quality cast and wrought iron railings, have suffered from vandalism and unplanned management. Development of a private residence has divided the ownership of the site. The Saltburn war memorial (grade $\ensuremath{\mathsf{II}}^*$) is within the site and already included on the Heritage at Risk Register.

Contact: Chris Mayes 0191 269 1226

512616
512616
512616
512616
612616
612616
512616
512616
612616
6

STOCKTON-ON-TEES (UA)



© Historic England Archive

SITE NAME: Phosphate rock silo (No. 15), Haverton Hill, Former ICI, Billingham DESIGNATION: Listed Building grade II* CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company

1115821

Reinforced concrete silo of 1928/29. Parabolic crosssection with reinforced concrete arches, with ribs at the ends. Designed by Monnoyer British Construction Ltd, for the storage of phosphate rock imported for the production of fertilizer. This is the earliest surviving example of this type of silo in England. The owner is considering options for repair and re-use.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

I PA ΝP

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

LIST ENTRY NUMBER:



© Historic England Archive

Ruins of Church of St Thomas a SITE NAME: Becket, Durham Road, Grindon Scheduled Monument and Listed DESIGNATION: Building grade I CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A(A)OWNER TYPE:

1017321 and 1329821

Private

Ruins of late C12 church that was altered significantly in 1789. Now a roofless, part-collapsed ruin and consolidation of the remains is required.

Contact: Kate Wilson 0191 269 1221

TYNE AND WEAR

GATESHEAD



SITE NAME: Winlaton Mill ironworks, south east of Winlaton Mill village DESIGNATION: Scheduled Monument CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (New entry)

Local authority

Most of this large and complex site is protected as it is buried beneath the ground; however, there are important upstanding structures, including the remains of Crowley Dam and spillway. These features are at risk from extensive tree and scrub growth, which is causing damage to the stonework.

© Historic England

LIST ENTRY NUMBER: 1021272

LIST ENTRY NUMBER:

OWNER TYPE:

Contact: Sara Rushton 0191 269 1222



© Historic England

SITE NAME:	Dunston Staiths
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)

1005898 and 1248994

Built by the North Eastern Railway Company and opened in 1893. Closed in the 1970s after being the last working staiths on the River Tyne. Fire damage in 2003 resulted in 8% of the monument being lost and there was a further fire in July 2010. A conservation plan, condition survey and feasibility study have been produced to identify a future for the structure. The first phase of repair was completed in 2016 with funding from the Heritage Lottery Fund and Historic England. The next phase of repair is under discussion with Historic England and the Local Authority.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Ravensworth Castle (Nash House), Lamesley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1025151

Nash house of 1808 for Sir Thomas Liddell, completed by 1846 but now a ruin following extensive demolition in the 1950s. A sustainable future for all the historic structures on the site has been the subject of discussions over many years. Urgent repairs were completed by the owners in 2015 following a condition survey commissioned by the Local Authority using Historic England grant-aid. An outline scope of works and costings for repair have been produced and discussions continue with the owners about a scheme to consolidate the house as a ruin.

Contact: Mike Collins 0191 269 1212



© Historic England

SITE NAME:	Ravensworth Castle, Cross Lane, Lamesley
DESIGNATION:	Scheduled Monument and Listed Building grade II*, LB grade II, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Private

1016975 and 1025190

Medieval castle of which two C14 corner towers and part of its curtain wall survive in poor condition, as well as associated archaeological deposits. Urgent repairs were completed by the owners in 2015 following a condition survey commissioned by the Local Authority using Historic England grant-aid. An outline scope of works and costings for repair of the castle, alongside the other listed heritage assets on the site, have been prepared and discussions continue with the owners on consolidating the castle as a ruin.

Contact: Mike Collins 0191 269 1212

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

I PA ΝP RPG

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

Gibside Hall, B6314, Gibside Estate, Rowlands Gill,

Whickham

Scheduled Monument and Listed Building grade II*, RPG grade I,

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (B)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1017224 and 1299730

Large house/hall of 1603-20, enlarged C18 and altered early C19. Fell into disrepair in early C20 and now a roofless shell in poor condition. Set in early/mid C18 park. The house requires major stabilisation and consolidation works. Natural England has funded the preparation of a management plan and prioritised schedule of repair works.

Contact: Kate Wilson 0191 269 1221



© Historic England Archive

SITE NAME: Whinfield coking ovens, south east of Low Spen Farm, Whickham

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: F (B)

OWNER TYPE: Charity (heritage)

LIST ENTRY NUMBER: 1018226

Remains of what was originally a bank of 193 bee-hive coke ovens dating from the mid-C19. Part of an extensive former mining landscape that is now largely cleared and landscaped. The remaining ovens represent a rare example of intact bee-hive coke ovens. Initial repairs were carried out in 2003. This site has been included in the "Land of Oak and Iron" Landscape Partnership Scheme and repairs are due to be completed in 2016.

Contact: Sara Rushton 0191 269 1222



SITE NAME:	Church of St Paul, Scotland Head, Blaydon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NILIMBER	1025175

Built 1827-9 to designs by the architect Ignatius Bonomi, St Paul's is a hall church with the nave and chancel accommodated under a continuous low-pitched roof and a bold west tower. There is extensive decay and erosion to the external surface of the sandstone walls. Part of the south parapet has been dismantled and there is evidence of pronounced damp staining in the vicinity of rainwater pipes.

Contact: Kate Wilson 0191 269 1221

© Historic England

Coal mining remains at Dunston Hill		
Coar mining remains at Danston rim		
Scheduled Monument	LIST ENTRY NUMBER:	1018227
Generally satisfactory but with significant localised problems	TREND:	Declining
Road construction	NEW ENTRY?:	No
Private	CONTACT:	Kate Wilson 0191 269 1221
Site of Ravensworth coalmill, 600 metres north east	of Ravensworth C	Castle, Lamesley
Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1015922
Generally satisfactory but with significant localised problems	TREND:	Unknown
Scrub/tree growth	NEW ENTRY?:	No
Private	CONTACT:	Kate Wilson 0191 269 1221
Ravensworth, Lamesley		
Conservation Area, 11 LBs, 2 SMs	NEW ENTRY?:	No
Poor	TREND:	Deteriorating
Low	CONTACT:	Clare Richardson (LPA) 0191 433 3510
	Generally satisfactory but with significant localised problems Road construction Private Site of Ravensworth coalmill, 600 metres north east Scheduled Monument, part in CA Generally satisfactory but with significant localised problems Scrub/tree growth Private Ravensworth, Lamesley Conservation Area, 11 LBs, 2 SMs	Generally satisfactory but with significant localised problems Road construction Private Contact: Cont

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

NEWCASTLE UPON TYNE



© Historic England

Church of All Saints, Pilgrim Street, Newcastle upon Tyne

DESIGNATION: Listed Building grade I, CA

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

Local authority

LIST ENTRY NUMBER: | 106329

OWNER TYPE:

OWNER TYPE:

Former church, built between 1786-96 by David Stephenson to replace a medieval church on the same site. Classical style, with baroque tower. All Saints was closed by the Church of England in 1961 and the building was subsequently occupied as an urban studies centre and concert hall before being temporarily in use for worship by a different faith. Recent works have been undertaken to stem the ingress of rainwater; however, further repairs are required. The building has been a victim of heritage crime. Discussions are underway about its future.

Contact: Kate Wilson 0191 269 1221

Almshouses constructed in 1701 for keelmen and keelmen's widows. The building was last used as student accommodation but is now vacant and disused. It was a target for vandalism but the owner has improved security.

Options for re-use are being actively explored.



© Historic England

SITE NAME:	The Keelmen's Hospital, City Road, Newcastle upon Tyne
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)

Local authority

LIST ENTRY NUMBER: 1024902

Contact: Kate Wilson 0191 269 1221



© Historic England

© Historic England

SITE NAME:	5-13, Grey Street, Newcastle upon Tyne
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private

1139021

Four-storey shops and houses built circa 1835, probably by John Wardle for Richard Grainger. The property is now largely vacant and showing signs of a lack of maintenance; including extensive water-staining below the top cornice of the front elevation. Planning consent has been granted, subject to conditions, for conversion to hotel use.

Presbytery attached to St Michael's church, Westmorland Road, Newcastle upon Tyne

DESIGNATION: Listed Place of Worship grade II*

condition: Poor

LIST ENTRY NUMBER:

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1024743

A three-storey presbytery, attached to the south-east corner of St Michael's church, with a gabled front, stone walls and slated roofs. The building has not been actively used for some time. Gutters are choked with vegetation, there is some water ingress, and internal cracks adjacent to the end gable wall could indicate structural movement. Many of the external building elements are deteriorating and in need of a comprehensive programme of repairs. Discussions are underway to find a new use for the building. The attached church is also at risk.

Contact: Kate Wilson 0191 269 1221

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME: Woolsington Hall, Woolsington

DESIGNATION: Listed Building grade II*, RPG grade II

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: B (D)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1123737

A compact late C17 country house, with later additions. It has service buildings, all set in fine gardens and parkland. A planning application to convert the building to a five-star hotel and spa was approved by the Local Authority in 2015. The owners continue to pursue the implementation of that scheme despite the Hall being gutted by a fire in December 2015.

Contact: Martin Lowe 0191 269 1233

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Fundamental and first a good.
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

LIST ENTRY NUMBER:



© Historic England

SITE NAME:	Church of St Michael with St Lawrence, Avondale Road, Byker
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Fair
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Religious organisation

1024948

Parish church built 1862-63 by WL Moffat. North aisle and vestry added in 1936. The building has suffered from past problems of water ingress and heritage crime. A repair scheme was completed with grant funding awarded by the Heritage Lottery Fund in 2013 and the church is now dry and secure. While the building is essentially an empty shell, it is being increasingly used for worship and other community activities.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Life Transformation Church (former Church of St Paul), Havelock Place, High Elswick
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1024846

Former parish church of 1856-9 designed by John Dobson. Formally closed in 2006, the church lay vacant, and subject to heritage crime, until taken over by the Life Transformation Ministry in 2009. A grant was awarded by the Heritage Lottery Fund in 2012 which led to a phased repair programme being defined. A second grant was offered in 2013, again by the Heritage Lottery Fund, for the first phase of urgent repairs; these were completed in 2014. A further grant has been offered by the Heritage Lottery Fund to enable a second phase of urgent repairs to be undertaken.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Luke, Claremont Road, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Fair
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1355224

Completed in 1890 to designs by Oliver & Leeson, St Luke's has a short nave with south porch, paired transepts and a chancel with north vestry and south chapel. It is constructed of red brick with steeply pitched roofs of Welsh slate, stone window surrounds and a west belfry. A scheme of external repairs was completed in 2014. Proposals for the repair of the interior are being developed to enable the main body of the church to be brought back into use for worship. Whilst these proposals develop, the adjoining parish hall is temporarily being used for worship.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Christ Church (and hall attached), Shieldfield Green, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1024748

Parish church, 1859-61 by AB Higham. Squared sandstone with ashlar dressings and Welsh slate roofs. The roofs are coming to the end of their life and water ingress is damaging internal plaster work. The Heritage Lottery Fund offered a grant that allowed a first phase of roof repairs to be completed in 2015. Further grant funding is due to be sought for a second phase.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Thomas the Martyr, Barras Bridge, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
IST ENTRY NUMBER:	1024952

Built to a design by John Dobson in 1827-30, St Thomas' comprises a west tower with very tall bell openings, an aisled nave with galleries around three sides, and a shallow chancel with north and south porches. The nave and aisles are crowned by stone ribbed plaster vaults supported on slender piers. A grant from the Heritage Lottery Fund has been offered for repairs to the roof gutter on the north side of the nave.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 F. Under repair or in fair to good.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site



© Historic England

SITE NAME: Church of St Matthew, Summerhill Street, Newcastle upon Tyne

Listed Place of Worship grade DESIGNATION: II*, CA

CONDITION: Fair

PRIORITY CATEGORY: D (D) OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1024757

LIST ENTRY NUMBER:

Built in 1877 by the local architect RJ Johnson, with a striking west tower added in 1895 by Hicks & Charlewood. The church has sandstone walls and a roof of plain clay tiles. The interior is tall and spacious with double aisles on either side of the nave. Grant funding from the Heritage Lottery Fund enabled the completion of repairs to the nave and chancel roofs, and rainwater pipes, in 2014. A phased programme of work is being developed to address issues affecting the external stonework.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Michael, Westmorland Road, Newcastle upon Tyne
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1024743

Designed in 1889-91 by the Newcastle practice of Dunn, Hansom and Dunn, St Michael's has a striking octagonal crossing tower, much carved ornament, and a fine collection of internal fittings. There is some water ingress, particularly around the base of the crossing tower and to the north aisle. This is due, in part, to the difficulty of gaining access for maintenance. The slated roof covering to the south aisle is also in poor condition. Funding has been obtained from the Roof Repair Fund to enable a phase of repairs to be undertaken. The attached presbytery is also at risk.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Dewley Hill round barrow and associated features, 350 metres north west of Dewley Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018678
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Hadrian's Wall and vallum in wall mile 9, Blucher to	Dene House	
DESIGNATION:	Scheduled Monument, WHS	LIST ENTRY NUMBER:	1003790
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
CONDITION: PRINCIPAL VULNERABILITY:		TREND: NEW ENTRY?:	Declining Yes



© Historic England

SITE NAME:	St John's Cemetery, Newcastle upon Tyne
DESIGNATION:	Registered Park and Garden grade II, 4 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1000761

A burial board cemetery of 1857 where all three entrance lodge buildings are derelict. The twinned northern entrance lodges and ornate joining arch (all listed grade II) are subsiding, the latter permanently propped. The chapels (grade II) are unused and fenced off although in fair condition. Boundary walls are subsiding. Many monuments are in poor condition, including the Mather Tomb (grade II), which is also fenced-off to prevent further damage. Terraces and steps on Miser Hill are in poor condition and overgrown.

Contact: Chris Mayes 0191 269 1226

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park I PA ΝP RPG Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site



© Historic England

SITE NAME:	Westgate Hill Cemetery, Newcastle upon Tyne
DESIGNATION:	Registered Park and Garden grade II, 4 LBs, CA
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1001680

One of the earliest garden cemeteries in England (1829) and the earliest in the North East. Despite having lost its chapel, and the original layout being obscured by vegetation, the character of the site remains legible. The remaining monuments are of a style particular to early cemeteries and many have been damaged through weathering, vandalism and ivy growth. Invasive weeds and scrub, along with vandalism, anti-social behaviour and minimal management, risks the loss of further legibility and fabric. Liaison with the Council has developed a project to produce a conservation plan for the site.

Contact: Chris Mayes 0191 269 1226

NEWCASTLE UPON TYNE / GATESHEAD



© Historic England

SITE NAME:	Battle of Newburn Ford
DESIGNATION:	Registered Battlefield, 5 LBs, 2 CAs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Declining
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1000025

The Battle of Newburn Ford (1640) was the only battle of the Second Bishops' War. The Scottish Army took Newcastle by defeating the English at this river crossing. The Scottish campaign forced Charles I to raise an army against them and, after the loss of Newcastle, to pay them off. This expense meant Charles had to recall Parliament, which proved to be a critical step towards the English Civil War. The battlefield has been subject to piecemeal, peripheral development but an outline action plan has been agreed between Historic England, the local authorities and the Battlefields Trust.

Contact: Tom Gledhill 0191 269 1203

NORTH TYNESIDE

DESIGNATION: Conservation Area NEW ENTRY?: No	
CONDITION: Very bad TREND: Improving	
VULNERABILITY: Medium CONTACT: Ian McCaffery (LF	PA) 0191 6436334

SOUTH TYNESIDE



© Historic England

SITE NAME:	Detached chimney at Cleadon Pumping Station, off Sunniside Lane
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1416041

Large square chimney, detached from boiler house. Built in 1860-62 in Italianate style by Thomas Hawksley. A prominent local landmark and one of a series of pumping stations along the north east coast. A condition survey and schedule of repairs have been prepared with funding from Historic England. Discussions are underway about a first phase of work.

Contact: David Farrington 0191 269 1230



SITE NAME:	Marsden lime kilns, South Shields
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F(D)
OWNER TYPE:	Commercial company
LICT ENITDY NILIMBED	1005011

expected to be completed by the autumn of 2016.

Massive C19 industrial kilns, of two types, that were in poor condition and in urgent need of repair. Following completion of project development work, urgent repairs have begun, part-funded by Historic England, and are

© Historic England Archive LIST ENTRY NUMBER: 1005911 Contact: Tom Gledhill 0191 269 1203

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- solution agreed.

 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

 Full addresses in one in fairnesses decay.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS CA Conservation Area LB Listed Building LPA Local Planning Authority NP National Park RPG Registered Park and Garden SM Scheduled Monument UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:



0	Listopic	England

SITE NAME:	Church of St Aloysius, Bell Street, Hebburn
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1025193

Built in 1888, St Aloysius is a large church of red brick with slated roofs. It has an aisled nave, chancel, south porch and short double transepts to the north and south. The north transept has a Lady Chapel. The roof coverings are approaching the end of their serviceable life due to rusting nail fixings and there is some water penetration internally. The church has also suffered from heritage crime. A grant has been offered by the Heritage Lottery Fund for essential roofing works. Contact: Kate Wilson 0191 269 1221

SITE NAME: Christ Church, Grange Road West, Jarrow DESIGNATION: Listed Place of Worship grade II CONDITION: Very bad PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1025199

Parish church of 1868 by Johnson and Hicks in the Early English style. The interior contains a Norman-style font made of Frosterley marble and a Gothic-style altar composed of high quality woodwork. Remedial work to the tip of the tall broach spire has been completed; however, concerns remain about the condition of other parts of the tower.

Contact: Kate Wilson 0191 269 1221

© Historic England

SITE NAME:	Cleadon, South Tyneside		
DESIGNATION:	Conservation Area, 13 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lucy Routledge (LPA) 0191 424 7592
SITE NAME:	East Boldon, South Tyneside		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lucy Routledge (LPA) 0191 424 7592
SITE NAME:	Whitburn, South Tyneside		
DESIGNATION:	Conservation Area, 22 LBs	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Lucy Routledge (LPA) 0191 424 7592

SUNDERLAND



© Historic England

SITE NAME:	Old South Pier Lighthouse in Roker Cliff Park, Whitburn Road, Sunderland
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1218440

Lighthouse, originally built on the old South Pier in Roker in 1856 by the engineer Thomas Meik. Constructed of iron and steel, it was transferred to its current site in 1983. There is internal water ingress and some parts of the metal structure are starting to decay due to corrosion. A condition survey has been prepared and funding allocated by Sunderland City Council to enable repair works to be undertaken in 2016.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

Conservation Area Listed Building Local Planning Authority National Park LPA ΝP RPG Registered Park and Garden Scheduled Monument UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME: 'F' Pit Museum - colliery engine house, Albany Way (East side) Scheduled Monument and Listed DESIGNATION: Building grade II CONDITION: Poor OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: C (C)

Local authority

LIST ENTRY NUMBER: 1018224 and 1025422

OWNER TYPE:

"F" Pit was sunk in 1777 but the engine house wasn't built until 1926. The pit closed in 1968 and the site was cleared, apart from the engine house. Representing a fine example of the winding technology used in the north east coalfield, the building re-opened as a museum in 1976. The museum continues to open to limited, seasonal, hours. However, the future of the building is uncertain and there has been no progress in preparing a condition survey.

Contact: Kate Wilson 0191 269 1221



© Churches Conservation Trust

SITE NAME:	Church of Holy Trinity, Church Street East, Sunderland
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1208056

Former parish church with west tower, in the care of the Churches Conservation Trust since 1988. Built 1718-19, with a rounded eastern apse added in 1735. The building is starting to deteriorate and there is some structural movement, particularly at the east end. A substantial grant was awarded by the Heritage Lottery Fund in 2015 to repair the building and establish it as a new cultural venue ("The Canny Space"). Urgent temporary repairs were completed with Historic England funding in March 2016 to safeguard the building pending the implementation of The Canny Space project.

Contact: David Farrington 0191 269 1230



© Historic England

SITE NAME:	Fulwell Mill, Newcastle Road, Fulwell
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority

1207109

Tower windmill, circa 1821, restored in 1951, 1987 and again in 2000. The site has been closed since 2012 when parts of the sails and fantail were removed due to safety concerns. Further deterioration and water ingress led to the timber domed cap being replaced with a temporary flat roof in 2015. Discussions are well underway about a permanent repair scheme, the first stage of which is due to commence on site in late 2016. Plans are also being made to lease the site to a community organisation.

Contact: David Farrington 0191 269 1230



SITE NAME:	Doxford House, Warden Law Lane, Silksworth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1279879

Large house (previously known as Silksworth House), formerly used as a students' hall of residence. Mostly of the early C19 but with some earlier features. The property is vacant but has recently been acquired by a new owner who has made the building weathertight and secure. Work has started to implement the approved planning consent scheme which will see the building returned to a single residence.

Contact: Martin Lowe 0191 269 1233



© Historic England

SITE NAME:	Monkwearmouth Station Museum, with screen walls, footbridge and waiting room, Sunderland
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed multiple owners

1209029

Former railway station, built in 1848 with additions of 1879, now a museum. The site includes the main station building with pedimented portico and screen walls, an attached cast iron footbridge to the rear, and a waiting room and long screen wall to the west platform. There is a maintenance backlog, resulting in decay and some water ingress. A package of urgent repairs has recently been completed, and initial discussions have taken place to try and establish a maintenance regime for the site as a whole.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric: solution agreed but not yet implemented.
- Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park I PA ΝP Registered Park and Garden Scheduled Monument RPG Unitary Authority World Heritage Site



© Historic England

SITE NAME: Guru Gobind Singh Gurdwara Sikh Centre (Formerly Christ Church), Ryhope Road,

Sunderland

Listed Place of Worship grade II, DESIGNATION:

CONDITION: Poor

PRIORITY CATEGORY: C (C)

OWNER TYPE: Religious organisation

LIST ENTRY NUMBER: 1209657

LIST ENTRY NUMBER:

Formerly a parish church, built in 1862-64 by James Murray of Coventry. Closed by the Church of England, the building has been acquired by the Sikh community and continues as a place of worship. It contains high quality stained glass. A first phase of urgent repairs, including works to rainwater pipes and gutters, was completed in early 2014 with funding from the Heritage Lottery Fund. The spire remains in need of urgent repair.

Contact: Kate Wilson 0191 269 1221



© Historic England

SITE NAME:	Church of St Andrew, Park Avenue, Sunderland
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation

1207113

Church by Edward S Prior and his site architect A Randall Wells, 1906-7. The church has a big landmark tower at the east end, above the chancel, and a wide and broad nave. A highly innovative structure recognised as a rare artistic achievement. Recent repairs have been undertaken to window $\underline{\text{glazing}}$ with grant support from the Heritage Lottery Fund. Further Heritage Lottery Fund grant aid has been offered for repairs to the tower stonework.

Contact: Kate Wilson 0191 269 1221

SITE NAME:	Hylton Castle medieval fortified house, chapel, C17 and C18 country houses and associated gardens		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1017223
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Kate Wilson 0191 269 1221
SITE NAME:	Old Sunderland Riverside, Riverside location		
DESIGNATION:	Conservation Area, 11 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mark Taylor (LPA) 0191 5611515
SITE NAME:	Old Sunderland, East End of City to east of city centre		
DESIGNATION:	Conservation Area, 10 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mark Taylor (LPA) 0191 5611515

SUNDERLAND / GATESHEAD



© Gateshead Metropolitan Borough Council

SITE NAME:	Bowes Railway, track, Wagon Shop, Hauler Houses and associated sheds, structures and incline, Bowes Railway, Washington / Lamesley
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Charity (heritage)

1003723

Track and inclined track bed, sheds, hauler houses and associated workshops comprising part of the Bowes Railway, one of the earliest and best preserved examples of a rope haulage system. The site is vulnerable to vandalism. Since 2003, several repair schemes have been undertaken, all part-funded by Historic England. A specification is being drawn up to enable the repair of stone walling to the Engineering Shop at Springwell, part-funded by Historic England. A condition survey is also underway of the track bed and related structures between Blackfell and Blackham Hill hauler houses.

Contact: Kate Wilson 0191 269 1221

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric; no
- solution agreed. Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

LIST ENTRY NUMBER:

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

Last year's priority category is shown in brackets (otherwise. New Entry is noted).

I PA ΝP RPG

ABBREVIATIONS Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority World Heritage Site

This document is one in a series of publications produced as part of Historic England's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at HistoricEngland.org.uk/har

Heritage at Risk

Published October 2016

1 Waterhouse Square

138–142 Holborn

London EC1N 2ST

© Copyright Historic England 2016

Product code: 52037

