



ENGLISH HERITAGE

HERITAGE AT  
RISK  
REGISTER  
2012

SOUTH WEST

# Contents

<b>HERITAGE AT RISK</b>	<b>3</b>
Reducing the risks	7
Publications and guidance	10
<b>THE REGISTER</b>	<b>12</b>
Content and assessment criteria	12
Key to the entries	15
Heritage at risk entries by local planning authority	17
Bath and North East Somerset (UA)	19
Bournemouth (UA)	22
Bristol, City of (UA)	22
Cornwall (UA)	25
Devon	62
Dorset	131
Gloucestershire	173
Isles of Scilly (UA)	188
North Somerset (UA)	192
Plymouth, City of (UA)	193
Poole (UA)	197
Somerset	197
South Gloucestershire (UA)	213
Swindon (UA)	215
Torbay (UA)	218
Wiltshire (UA)	219



ENGLISH HERITAGE

# HERITAGE AT RISK

2012

WESLEYAN

SOUTH WEST

# HERITAGE AT RISK

Despite the challenges of recession, the number of sites on the Heritage at Risk Register continues to fall. Excluding listed places of worship, for which the survey is still incomplete, 1,150 assets have been removed for positive reasons since the Register was launched in 2008. The sites that remain at risk tend to be the more intractable ones where solutions are taking longer to implement.

While the overall number of buildings at risk has fallen, the average conservation deficit for each property has increased from £260k (1999) to £370k (2012). We are also seeing a steady increase in the proportion of buildings that are capable of beneficial re-use – those that have become redundant not because of any fundamental lack of potential, but simply as the temporary victims of the current economic climate.

The South West headlines for 2012 reveal a mixed picture. It is good news that 8 buildings at risk have been removed from the Register; less good that another 15 have had to be added. Similarly, while 2 conservation areas have been removed for positive reasons, 5 others have taken their place. There has been no net change in the number of scheduled monuments at risk – 45 have been secured but an equal number is now at risk. This year, every case solved has been replaced by at least one new future challenge.

In May, English Heritage set the target of removing 25% of the entries from the 2010 baseline Register for positive reasons by April 2015. This objective has since been embedded in the National Heritage Protection Plan so that resources can be focused on achieving this goal.

Partnerships will be crucial to success. An important new collaboration between English Heritage and the Architectural Heritage Fund is funding a number of Heritage at Risk Support Officers. Working on shared priorities, the South West Officer is now providing valuable advice to trusts who own buildings at risk. Funds have already been secured, for example, for the repair of Bridport Literary and Scientific Institute and Wolfeton Riding House, both in Dorset.

We need to nurture such relationships for the benefit of other asset types. Natural England's agri-environment schemes have long supported the conservation and enhancement of scheduled monuments – as well as designed landscapes and traditional farm buildings – in agricultural holdings. However, the programme ends in 2013, which means uncertainty about the future funding for such assets, most of which rely on public subsidy to remain in good condition.

We will continue to fund Monument Management Schemes which, with match-funding from local authorities, offer a cost-effective, locally led approach to tackling vulnerable scheduled monuments. But with 43% of England's scheduled monuments at risk lying in the South West, and with the 2015 target in mind, alternative and additional funding sources need to be identified as a priority.

Our cover story reminds us that places of worship in the South West are also facing many challenges, not least in small rural communities where repair costs can be a major financial burden or lead to proposals for closure. Seventeen churches and chapels have been added to this year's Register, but happily almost all have been offered Heritage Lottery Fund grants to help fund repairs.

We begin work towards meeting the 2015 target in testing times. With no immediate prospect of recovery in the South West's economy, developer-led solutions are unlikely to play a significant part in securing the future of threatened buildings in the short to medium term. However, English Heritage will foster links with the private sector wherever possible, and strengthen relationships with partners in the public and community and voluntary sectors to secure a sustainable future for our most vulnerable heritage assets.



**Andrew Vines**  
Planning and Conservation Director,  
South West

## LITTLE TRETHERY, CORNWALL

Cornwall's Nonconformist chapels are of national significance, but the number still being used for worship continues to decline. Built in 1868, this grade II\* Wesleyan wayside example is one of the most important of them all, but at risk of decay and eventual collapse without further help and funds. Rural chapels have experienced the highest levels of dereliction, loss and change, with small communities often struggling to maintain them. English Heritage, Cornwall Council and the Methodist Church have collaborated on the production of guidance to inform sensitive changes to these important buildings. © Eric Berry

## BUILDINGS AT RISK

- Nationally, 3.0% of grade I and II\* listed buildings are at risk. In the South West this falls to 2.2% (159 buildings).
- 8 buildings at risk were removed from the 2011 South West Register; but 15 have been added.

## PLACES OF WORSHIP AT RISK

- Of the 314 listed places of worship surveyed in the South West, 38 are at risk. 17 have been added this year.

## SCHEDULED MONUMENTS

- 3,286 (16.6%) of England's 19,759 scheduled monuments are at risk, of which 1,412 are in the South West.
- In the South West, 45 scheduled monuments have been removed from the 2011 Register for positive reasons, and 45 have been added.
- 11% of scheduled monuments (156) on the South West's baseline 2009 Register have been removed for positive reasons, compared to the national figure of 15.8%.
- Nationally, damage from arable cultivation is the greatest risk factor for scheduled monuments, accounting for 44% of those at risk. In the South West the proportion is 37%.

## REGISTERED PARKS AND GARDENS

- 99 (6.1%) of England's 1,617 registered parks and gardens are at risk, a decrease from 103 (6.4%) in 2011. In the South West, 18 (6.1%) of our 294 sites are at risk.
- Nationally, 5 sites were removed from the 2011 Register and 1 has been added. There has been no change in the South West.

## REGISTERED BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are at risk, 2 fewer than the 2008 baseline. None of the 8 registered battlefields in the South West are at risk.

## PROTECTED WRECK SITES

- Of the 46 protected wreck sites off England's coast, 4 are at risk. Of the 10 sites on the 2008 baseline, 9 have been removed. None of the 23 protected wreck sites off the coast of the South West are at risk.

## CONSERVATION AREAS

- We now have information on the condition of 7,976 of England's 9,770 conservation areas; 524 (6.6%) are at risk. Of the 1,125 conservation areas surveyed in the South West, 83 (7.4%) are at risk.
- 2 conservation areas were removed from the 2011 South West Register for positive reasons, but 5 have been added.



### SOUTHGATE STREET, GLOUCESTER

Although one of the main entrances into the city, the Southgate Street conservation area remains isolated and in decline. On the Heritage at Risk Register since 2009, it is now the subject of a Townscape Heritage Initiative scheme to help owners put their buildings into sound external repair.

© Gloucester City Council

**58%** OF  
BUILDINGS  
AT RISK ON THE 1999  
REGISTER HAVE BEEN  
**SAVED**

**83**  
CONSERVATION  
AREAS  
ARE AT RISK

**20.2%** OF  
SCHEDULED  
MONUMENTS  
ARE AT RISK

**£823k**  
IN GRANTS  
WAS OFFERED TO  
**47** SITES AT RISK

## PRIORITY HAR SITES

- Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth
- Birnbeck Pier, Weston-Super-Mare, North Somerset
- Carriage Works, 104 Stokes Croft, Bristol
- Cloth finishing works at Tone Mills, north range, Langford Budville, Somerset
- Former Saxon church to west of Priory House, Leonard Stanley, Stroud, Gloucestershire
- Grenville Battery 550yds (500m) SSW of Maker Farm, Maker-with-Rame, Cornwall
- Guns Mill Barn, Littledean, Gloucestershire
- Medieval moated site and Romano-British settlement at White Walls Wood, Easton Grey, Wiltshire
- The Mechanics Institute, Emlyn Square, Swindon
- Torbay Cinema, Torbay Road, Paignton, Torbay

## GRADE II PILOT PROJECTS

English Heritage is looking for people to take part in pilot projects that will explore options for expanding the Heritage at Risk programme to include all grade II listed buildings.

A maximum of 15 pilot projects are required to explore, cost and test various options for undertaking surveys of grade II listed buildings.


For more information and details on how to apply visit:

[www.english-heritage.org.uk/risk](http://www.english-heritage.org.uk/risk)

## FOR MORE INFORMATION CONTACT:

Principal Heritage at Risk Adviser; English Heritage South West, 29 Queen Square, Bristol, BS1 4ND.

Telephone: 0117 975 0700 Email: [southwest@english-heritage.org.uk](mailto:southwest@english-heritage.org.uk)



Find out what's at risk by searching or downloading the online Heritage at Risk Register at [www.english-heritage.org.uk/har](http://www.english-heritage.org.uk/har)

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181  
fax: 01793 414926 textphone: 01793 414878  
email: [customers@english-heritage.org.uk](mailto:customers@english-heritage.org.uk)

# Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. This will be challenging given the number of assets on the Register and the different kinds of risk they face.

To help address this challenge we have published our National Heritage at Risk Strategy which will be supported by nine local strategies. Key objectives of the strategy are to understand why assets are at risk and what most influences their removal from the Register and to find solutions for heritage at risk through partnership, stimulating economic regeneration and growth and maximising the benefit of our expertise and resources.

Whilst each asset type and individual site will require its own approach and solution, there are some general approaches that are relevant to all assets at risk. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. Advice and understanding are essential. Historic Environment Records, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

Maintenance of heritage assets is essential to prevent them becoming at risk, and those that are already at risk from decaying further and the cost of their repair and consolidation from escalating. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found. English Heritage has published guidance for owners on options for maintaining vacant buildings (*Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing*).

English Heritage provides on-line advice and guidance to local authorities, owners and managers of sites through the Historic Environment Local Management (HELM) website, [www.helm.org.uk](http://www.helm.org.uk)

## LISTED BUILDINGS

### Buildings at risk

English Heritage's role in securing the future of buildings at risk is primarily to provide practical advice, guidance and resources to local authorities, owners and developers. Our involvement in cases is determined by the importance of the building and the complexity of the issues. We can help with analysis of the issues, investigation of the feasibility of options and brokering solutions. Although buildings at risk will continue to be a priority for English Heritage repair grants, grant aid is limited in relation to demand. Grants from other public sources, notably the Heritage Lottery Fund, continue to be essential in helping secure the future of buildings at risk.

In very exceptional cases, English Heritage may acquire and repair a particularly important building at risk, where it is clear that the scale and complexity of problems are such that direct involvement is the best way of securing the building's long-term future.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action. Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices. Some local authorities have a successful track record, but generally these powers are under-used. It is essential that local authorities make best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, English Heritage has published revised guidance (*Stopping the Rot*) for local planning authorities on taking action to save historic buildings.

To help local authorities make more frequent and timely use of their statutory powers, English Heritage runs grant schemes to underwrite a significant proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.

Building preservation trusts can be the key to saving many buildings at risk. Some trusts cover geographical areas; others specialise in particular types of building or are

formed to save just one building. Determined individuals and trusts have saved numerous buildings at risk, working in partnership with other organisations such as local and national amenity societies, including SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society, The Twentieth Century Society, the Council for British Archaeology and the Ancient Monuments Society. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk officers to help not-for-profit organisations take building at risk projects forward.

### Places of worship at risk

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. It also means volunteers do not take unnecessary risks balancing on ladders.

The Repair Grants for Places of Worship scheme helped under-resourced congregations do urgent works to make buildings wind and watertight. From 2013 the Heritage Lottery Fund will fund a new scheme for places of worship. The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports the congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. *New Work in Historic Places of Worship* (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

## SCHEDULED MONUMENTS

The continuing success in reducing the number of monuments at risk, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term care on a regular basis. Over half of all scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship agri-environment scheme, administered on behalf of Defra. Continuing partnership with Defra and Natural England over the last year has seen the introduction of much more effective information sharing so that resources – whether Environmental Stewardship or English Heritage – can be more closely targeted where they will have the greatest impact. Over the next year we will also work more closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Continued progress is also reliant upon better understanding. As a result, as part of the National Heritage Protection Plan – which sets out English Heritage's commitment to safeguarding heritage for the period 2011 to 2015 – the Conservation of Scheduled Monuments in Cultivation project has begun across England. The project, which started with a questionnaire to all farmers and landowners with a scheduled monument that is being cultivated, will look at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible. Some causes of risk are neither so obvious nor dramatic in their effects however. Heritage at risk still shows that unmanaged tree, scrub and bracken growth is one of the most widespread causes of long term damage to both urban and rural monuments, even if the effects are not as visible or immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

In all cases, however – whether for rural or urban monuments – close co-operation with owners and land managers will remain the key to making further progress in ever more challenging circumstances.

## REGISTERED PARKS AND GARDENS

Inclusion on the *Register of Historic Parks and Gardens of Special Historic Interest* confers no additional statutory controls but the Government's new *National Planning Policy Framework* stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. Registered parks and gardens carry the same weight as listed buildings in the *National Planning Policy Framework* and substantial harm or loss can only be justified in exceptional cases.

English Heritage's landscape architects can help tailor plans and funding packages for individual landscape features as well as strategies for the whole site. We encourage the development of conservation management plans for registered historic parks and gardens, especially those in multiple ownership. We will continue to tackle the skills crisis facing historic parks and gardens through sector-wide initiatives.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: [www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens](http://www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens)

## REGISTERED BATTLEFIELDS

As with registered parks and gardens, this designation brings no additional statutory controls, but there is a presumption in favour of conservation of registered battlefields in the *National Planning Policy Framework*.

English Heritage will continue to work with owners to develop management plans for registered sites and, in appropriate cases, contribute towards the cost of management plans. We will develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage will also continue to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

## PROTECTED WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory

power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage ([maritime@english-heritage.org.uk](mailto:maritime@english-heritage.org.uk)) and from [www.helm.org.uk](http://www.helm.org.uk)

## CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after them is a responsibility shared by those of us who own homes and businesses in them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of our conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. However, this is extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: [www.english-heritage.org.uk/caring/get-involved/improving-your-neighbourhood](http://www.english-heritage.org.uk/caring/get-involved/improving-your-neighbourhood)

# Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

*Buildings at Risk: a New Strategy* (1998)

*Caring for Places of Worship 2010* (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

*Heritage at Risk 2010* – report (2010)

*Heritage at Risk: Conservation Areas* (2009)

*Heritage at Risk 2012* – national report and summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

*Heritage at Risk Register 2012* – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber can be downloaded from our website or viewed as an interactive database: [www.english-heritage.org.uk/risk](http://www.english-heritage.org.uk/risk)

*Monuments at Risk* (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, Yorkshire and the Humber

*The Monuments at Risk initiative 2003–08* (2010)

*Protected Wreck Sites at Risk: A Risk Management Handbook* (2007)

*Saving London: 20 Years of Heritage at Risk in the Capital* (2010)

*Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings* (2011)

*Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing* (2011)

## HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit [www.english-heritage.org.uk/risk](http://www.english-heritage.org.uk/risk) where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website [www.english-heritage.org.uk/heritageprotection](http://www.english-heritage.org.uk/heritageprotection)

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: <http://list.english-heritage.org.uk>

## CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: [www.english-heritage.org.uk/publications](http://www.english-heritage.org.uk/publications) or [www.english-heritage.org.uk/helm](http://www.english-heritage.org.uk/helm)

*Caring for Historic Graveyard and Cemetery Monuments* (2011)

*Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations* (2012)

*Caring for Places of Worship* (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

*Constructive Conservation in Practice* (2008)

*Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment* (2008)

*Creativity and Care: New Works in English Cathedrals* (2009)

*The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies* (2010)

*Enabling Development and the Conservation of Significant Places* (2008)

*Farming the Historic Landscape: Caring for Archaeological sites on Arable Land* (2004)

*Farming the Historic Landscape: Caring for Archaeological Sites in Grassland* (2004)

*Guidance on the Management of Conservation Areas* (2006)

*Guidance on Conservation Area Appraisals (2006)*

Guidance Notes and Application Forms for Grants to Local Authorities:

- *Grants to Local Authorities to Underwrite Urgent Works Notices (1998)*
- *Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)*
- *Grants for Historic Buildings, Monuments and Designed Landscapes (2004)*

*Heritage at Risk: Conservation Areas (2009)* – guidance for local authorities on conservation area management

*Heritage Works: the use of Historic Buildings in Regeneration (2006)*

*Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)*

*New Uses for Former Places of Worship (2010)*

*New Work in Historic Places of Worship (2012)*

*Options for the Disposal of Redundant Churches and Other Places of Worship (2010)*

*Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)*

*Pillars of the Community: the Transfer of Local Heritage Assets (2011)*

*Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)*

*Shared Interest: Celebrating Investment in the Historic Environment (2006)*

*Theft of Metal from Church Buildings (2011)*

*Valuing Places: Good Practice in Conservation Areas (2011)*

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department  
PO Box 569, Swindon SN2 2YP  
Telephone: 0870 333 1181  
Fax: 01793 414926  
Email: [customers@english-heritage.org.uk](mailto:customers@english-heritage.org.uk)

# THE REGISTER

## Content and criteria

### DESIGNATION

All the historic environment matters but there are some elements which warrant extra protection through the planning system. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces tight management controls. Some 1,617 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether a site is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge. While responding to threat-driven cases, we also seek to work strategically. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Conservation areas are designated locally by local planning authorities. They are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance.

### LISTED BUILDINGS

#### Definition

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat.

Listed buildings are graded I, II\* and II. Grade I and II\* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential

terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be both listed as buildings and scheduled as monuments.

### Criteria for inclusion on this Register

Buildings (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II\*, (or grade II in London) or be a structural scheduled monument. Buildings are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use). The condition of buildings on the Register ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good'. The Register also includes buildings that are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', or occasionally, 'unknown'; for many structural monuments, occupancy is not applicable.

Assessing vulnerability in the case of a building in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings are removed from the Register when they are fully repaired/consolidated, their future secured, and where appropriate, occupied or in use.

### Listed places of worship

Places of worship are the largest single group of non-domestic historic buildings still in use primarily for the purpose for which they were built. Their complex development over centuries is a testament to the changes in social, political and liturgical attitudes over time. This reflects the developing mission of congregations and means that they protect a wide range of fittings and furnishings of national and international importance. Their architectural, archaeological, aesthetic and historic significance is outstanding but so too is their value as the record of the endeavours and experiences of individuals and communities.

To date English Heritage has assessed a proportion of the 14,500 listed places of worship. In the coming years an increasing number of places of worship will be assessed to identify those that are at risk. Future registers will provide stronger evidence which will help us build upon our understanding of the challenges.

## Criteria for inclusion on this Register

Places of worship considered for inclusion on this Register must be listed grade I, II\* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Places of worship previously included on the Register may be in any condition category.

Once on the Register, all places of worship can move through the condition categories (e.g. from very bad to poor; to fair; even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

### Priority for action

Once a building is identified as at risk or vulnerable and included on the Register, priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a building which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority where a repair scheme is in progress and an end use has been secured.

## SCHEDULED MONUMENTS

### Definition

Scheduled monuments include archaeological sites and landscapes, and 19,759 examples have been designated because of their national importance. Scheduled monuments are not graded, and most have limited potential for beneficial use. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes. In particular, they can frequently be exposed to intense pressures beyond the reach of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

## Criteria for inclusion on this Register

Scheduled monuments included on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Monuments are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

## REGISTERED PARKS AND GARDENS

### Definition

There are 1,617 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest*. These registered landscapes are graded I, II\* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage *Register of Historic Parks and Gardens* brings no additional statutory controls, but there is a presumption in favour of conservation of the designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II\* and the Garden History Society on sites of all grades.

## Criteria for inclusion on this Register

The identification of registered parks and gardens at risk begins with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Landscapes assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Landscapes are removed from the Register once plans are put in place to address issues and positive progress is being made.

## REGISTERED BATTLEFIELDS

### Definition

English Heritage's *Register of Historic Battlefields* has identified 43 nationally significant sites ranging in date from 991 to 1685. These are places where people risked their lives fighting for a cause and where history was made. The outcome of these battles was influenced by where they were fought and traces of the events will have been left across the landscape. Battlefields are cherished for many reasons, as a commemoration of the event and those who died, as a resource for understanding the course of the battle, and for the light they can shed on the times in which the battle was fought. They are vulnerable to insensitive development and to poorly managed investigation such as large-scale metal-detecting. While this designation introduces no additional statutory controls, one of its primary objectives is to encourage policies and other mechanisms that ensure that change and development affecting battlefields is sensitive and appropriate.

### Criteria for inclusion on this Register

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

## PROTECTED WRECK SITES

### Definition

England's 46 protected wreck sites represent a tiny proportion of the 32,476 pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events, its cargo, flora and fauna or its role as a focus for the local community. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference.

Local authorities are able to react to foreshore infrastructure projects through the planning process, thereby securing the preservation of important remains in this intertidal zone.

### Criteria for inclusion on this Register

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

## CONSERVATION AREAS

### Definition

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently some 9,700 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

### Criteria for inclusion on this Register

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

# Key to the entries

## This Register includes the following heritage assets at risk:

- grade I and II\* listed buildings and structural scheduled monuments
- grade I, II\* and II listed places of worship
- scheduled monuments
- registered parks and gardens
- registered battlefields (if applicable)
- protected wreck sites (if applicable)
- conservation areas

## ORDER

Entries are grouped and ordered alphabetically first by County or Unitary Authority, and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

Sites that straddle more than one local planning authority are included under the lead authority.

Asset types are grouped within the relevant planning authority in the following order:

- listed buildings and structural scheduled monuments
- places of worship
- scheduled monuments
- registered parks and gardens
- conservation areas

Within each asset type, sites are ordered alphabetically by district for sites in National Parks, otherwise by parish and street/site name. Conservation areas are ordered by site name only.

## DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) Grade I, II\* or II
- Listed Place of Worship Grade I, II\* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) Grade I, II\* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to buildings at risk and registered parks and gardens at risk, including their location within a World Heritage Site (WHS), are also noted where applicable.

The National Heritage List for England reference number is noted for scheduled monuments.

## CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

## OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

## VULNERABILITY

Principal vulnerability is noted for scheduled monuments and may relate only to the part of the monument which is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub/tree growth
- visitor erosion.

For registered parks and gardens, registered battlefields, protected wreck sites and conservation areas, vulnerability is noted as high, medium or low.

## PRIORITY

For buildings at risk, the following priority categories are used as an indication of trend and as a means of prioritising action:

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2011 priority categories are given in brackets.

## TREND

Trend for scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

## OWNERSHIP

A principal ownership category is given for each entry, although many scheduled monuments, registered parks and gardens, and registered battlefields are in divided ownership. For registered parks and gardens, single or multiple ownership is noted.

## CONTACT

This is the member of the English Heritage regional team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

## ABBREVIATIONS

<b>CA</b>	Conservation Area
<b>EH</b>	English Heritage
<b>HLF</b>	Heritage Lottery Fund
<b>LPA</b>	Local Planning Authority
<b>LB</b>	Listed Building
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WHS</b>	World Heritage Site

# Heritage at risk entries by local planning authority

	Buildings at risk	Places of worship at risk	Scheduled monuments at risk	Registered parks and gardens at risk	Registered battlefields at risk	Protected wreck sites at risk	Conservation areas at risk
<b>BATH AND NORTH EAST SOMERSET (UA)</b>							
Bath and North East Somerset (UA)	4	2	8	0	0	0	10
<b>BOURNEMOUTH (UA)</b>							
Bournemouth (UA)	0	0	1	0	0	0	0
<b>BRISTOL, CITY OF (UA)</b>							
Bristol, City of (UA)	11	1	3	0	0	0	1
Bristol, City of (UA) / Bath and North East Somerset (UA)*	0	0	0	1	0	0	0
<b>CORNWALL (UA)</b>							
Cornwall (UA)	29	10	214	1	0	0	1
<b>DEVON</b>							
Dartmoor (NP)	1	0	248	0	0	0	1
East Devon	3	0	58	0	0	0	3
Exeter	1	1	1	0	0	0	3
Exmoor (NP)	0	2	12	0	0	0	0
Mid Devon	1	1	17	0	0	0	3
North Devon	2	0	14	0	0	0	1
South Hams	7	0	34	0	0	0	0
Teignbridge	2	1	9	3	0	0	3
Torridge	2	0	43	0	0	0	2
West Devon	5	3	8	0	0	0	4
<b>DORSET</b>							
Christchurch	0	0	2	0	0	0	0
East Dorset	3	0	41	1	0	0	0
North Dorset	3	2	46	0	0	0	3
Purbeck	1	0	64	0	0	0	6
West Dorset	10	2	108	1	0	0	23
Weymouth and Portland	4	0	4	0	0	0	1
<b>GLOUCESTERSHIRE</b>							
Cheltenham	0	0	0	0	0	0	0
Cotswold	6	2	38	1	0	0	0
Forest of Dean	5	3	11	0	0	0	0
Gloucester	7	0	0	0	0	0	1
Stroud	5	0	8	0	0	0	0
Tewkesbury	5	0	12	0	0	0	1
<b>ISLES OF SCILLY (UA)</b>							
Isles of Scilly (UA)	1	0	29	0	0	0	0
<b>NORTH SOMERSET (UA)</b>							
North Somerset (UA)	4	0	0	0	0	0	4
<b>PLYMOUTH, CITY OF (UA)</b>							
Plymouth, City of (UA)	12	0	12	0	0	0	1
<b>POOLE (UA)</b>							
Poole (UA)	0	0	1	0	0	0	5

<b>SOMERSET</b>							
Exmoor (NP)	0	0	17	0	0	0	0
Mendip	3	0	25	1	0	0	0
Sedgemoor	2	3	11	1	0	0	0
South Somerset	9	2	9	3	0	0	1
Taunton Deane	5	0	10	0	0	0	0
West Somerset	1	1	7	1	0	0	0
<b>SOUTH GLOUCESTERSHIRE (UA)</b>							
South Gloucestershire (UA)	6	1	5	1	0	0	2
<b>SWINDON (UA)</b>							
Swindon (UA)	2	1	15	0	0	0	0
<b>TORBAY (UA)</b>							
Torbay (UA)	3	0	3	2	0	0	2
<b>WILTSHIRE (UA)</b>							
Wiltshire (UA)	16	0	241	1	0	0	1
Wiltshire (UA) / New Forest (NP)	0	0	1	0	0	0	0
<b>TOTAL</b>	<b>181</b>	<b>38</b>	<b>1390</b>	<b>18</b>	<b>0</b>	<b>0</b>	<b>83</b>

\*Sites that cross local planning authority boundaries

## BATH AND NORTH EAST SOMERSET (UA)



SITE NAME: **King Edwards School,  
Broad Street,  
Bath**

DESIGNATION: Listed Building Grade II\*, WHS, CA

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNER TYPE: Company

School, 1752. A scheme for use as a hotel was submitted but withdrawn in 2006. Works to repair the roof have been successfully completed. The threat of decay has therefore diminished but the building remains vacant. Permission granted 2010 for hotel use.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Cleveland Baths,  
Hampton Row,  
Bath**

DESIGNATION: Listed Building Grade II\*, WHS, CA

CONDITION: Very bad


OCCUPANCY: Vacant

PRIORITY: D (D)

OWNER TYPE: Local authority

Dating from 1815, Cleveland Baths are believed to be the oldest surviving public outdoor swimming pools in England. A diminutive Georgian crescent houses the changing rooms and Caretakers Cottage. The Cleveland Pool Trust has recently completed a business plan, condition survey and scheme design with English Heritage grant aid and are now seeking capital funding for the works.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Victoria Bridge,  
Victoria Bridge Road,  
Bath**

DESIGNATION: Listed Building Grade II\*, WHS, CA

CONDITION: Poor


OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Local authority

Suspension bridge by Dredge c1836. Due to structural instability a temporary Mabey girder has been installed. The council has commissioned reports on the steps needed to repair the structure.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Hinton Priory,  
Hinton Charterhouse**

DESIGNATION: Listed Building Grade I, SM

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Early C13 Carthusian monastery, chapter house and refectory still standing. Later stables, coachhouse and garden buildings incorporate earlier material and follow original complex layout of cloister and cells. All structures in use except chapterhouse. Some parts in need of condition assessment.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Church of St Andrew,  
Aller**

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Poor

PRIORITY: F (B)

OWNER TYPE: Religious organisation

Very significant small church. Saxon origins with C12/C13, C15 and major restoration 1861-1862 by H John Norton. The church has recently undertaken patch repair to the nave roof which is suffering from nail sickness and this will need proper repair in the near future. The church was visited in 1997 and again in 2010 to assess the issue of cracking through tower parapet stonework and to the staircase turret. Repair of the tower stonework is ongoing.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Holy Trinity,  
Main Road,  
Cleeve**

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Very bad

PRIORITY: F (B)

OWNER TYPE: Religious organisation

1840 church by Manners of Bath. Large belfry openings have iron ferramenta bars running through central stone columns. The rusting of these bars has caused large vertical splits in the columns which have had to be strapped to stop pieces of stone falling. A Repair Grant for Places of Worship has been offered for repairs. Repair work to the Tower Belfry openings is ongoing.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

**D** Slow decay; solution agreed but not yet implemented.

**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

**F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

**CA** Conservation Area  
**LB** Listed Building  
**LPA** Local Planning Authority  
**NP** National Park  
**RPG** Registered Park and Garden  
**SM** Scheduled Monument  
**UA** Unitary Authority  
**WHS** World Heritage Site

SITE NAME: <b>Wansdyke: section 1230yds (1120m) eastwards from Burnt House Inn</b>			
DESIGNATION:	Scheduled Monument (No.1007003)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Gardening	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Camerton Romano-British town and associated Prehistoric and early medieval monuments, Camerton</b>			
DESIGNATION:	Scheduled Monument (No.1013881)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Roman road 720yds (660m) long, north of Abbey Farm, Hinton Charterhouse</b>			
DESIGNATION:	Scheduled Monument (No.1005421)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stantonbury camp and adjacent sections of Wansdyke, Marksbury</b>			
DESIGNATION:	Scheduled Monument (No.1002487)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Lansdown Roman camp, North Stoke</b>			
DESIGNATION:	Scheduled Monument (No.1005422)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Little Down camp, North Stoke</b>			
DESIGNATION:	Scheduled Monument (No.1004677)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Wansdyke: south east of Newbarn Farm, Norton Malreward</b>			
DESIGNATION:	Scheduled Monument (No.1003066)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Roman villa at Upper Hayes, Wellow</b>			
DESIGNATION:	Scheduled Monument (No.1007002)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Batheaston</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>Chew Magna</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>Corston</b>		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>Keynsham Dapps Hill, Keynsham</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	Deteriorating
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	Yes

SITE NAME:	<b>Keynsham High Street, Keynsham</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating significantly
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>Midsomer Norton and Welton</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>Paulton (including Paulton Basin)</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>Radstock (including Braysdown and Clandown)</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>South Stoke</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

SITE NAME:	<b>Wellow</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Ian Lund (LPA) 01225 477687	NEW ENTRY?:	No

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

**BOURNEMOUTH (UA)**

SITE NAME:	<b>Two round barrows 300yds (270m) north west of Double Dykes, Hengistbury Head, Bournemouth</b>		
DESIGNATION:	Scheduled Monument (No.1002397)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**BRISTOL, CITY OF (UA)**

SITE NAME:	<b>Lower Lodge to Ashton Court, Ashton Road, Bristol</b>
DESIGNATION:	Listed Building Grade II*, CA, RPG II
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	B (A)
OWNER TYPE:	Local authority

Picturesque Gothic style entrance lodge built 1805 by Henry Wood. Limestone ashlar, two storeys with wrought iron gates. Vacant with hole in main roof and signs of structural distress in ashlar. Doors and windows blocked on ground floor but upper storey open to weather. A scheme of repair and alteration has been agreed.


Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Mortimer House, Clifton Down Road, Bristol</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	D (C)
OWNER TYPE:	Private

Imposing mid C18 palladian suburban villa, until recently in hospital use, now vacant. Roofs are deteriorating and there has been significant water ingress. A scheme of repair and conversion has been granted consent.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Swing Bridge over North Entrance Lock, Cumberland Basin, Bristol</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Local authority

Wrought iron bridge c1844 by IK Brunel with tubular supporting members. Moved to current location in 1873. It has been redundant and decaying on dock since construction of Plimssoll Bridge in C20. English Heritage grant offered for repair of the bridge.


Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Church of St Michael and attached railings, St Michaels Hill, Bristol</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Religious organisation

Church, rebuilt in 1775-77 in a Gothick style, but retaining the mid C15 tower; the interior is divided in three aisles by classical colonnades and has some late C19 fittings. The church has been vacant for over six years. A scheme has been proposed for new denominational church use and negotiations are ongoing.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Carriage Works, 104 Stokes Croft, Bristol</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Private

Carriage works, 1862. A notable building in a manner recognised as particular to the city. Large and complex site including 4 Ashley Road (grade II) also in very bad condition. Local Planning Authority are proactively pursuing a solution for the site in parallel to an application that has been submitted for its redevelopment.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **The Trinity Centre,  
Holy Trinity Church,  
Trinity Road, Bristol**

DESIGNATION: Listed Building Grade II\*  
CONDITION: Poor  
OCCUPANCY: Occupied  
PRIORITY: D (D)  
OWNER TYPE: Local authority

Large perpendicular gothic revival Commissioners church circa 1829. Trinity Community Arts Ltd lease building for use as arts venue. English Heritage grant aided condition survey in 2008. Lead roof of south aisle is corroding. English Heritage grant offered in 2011 for repair of south aisle roof and feasibility study for whole building, which is underway.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Clifton Observatory,  
Clifton,  
Bristol**

DESIGNATION: Listed Building Grade II\*, CA  
CONDITION: Fair  
OCCUPANCY: Part occupied  
PRIORITY: F (F)  
OWNER TYPE: Private

Former windmill, now camera obscura. Built C18, camera obscura early C19. Interior winding stair leads up to obscura and down to a tunnel leading to Ghyston's Cave on the side of the Avon Gorge. Following extensive negotiations, a scheme of repair and conversion is advanced and consent has been given to restore the observatory dome in conjunction with restaurant use.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Stair turret (Holy Cross)  
Inns Court Vicarage,  
Inns Court Green, Knowle, Bristol**

DESIGNATION: Listed Building Grade II\*  
CONDITION: Fair  
OCCUPANCY: Vacant  
PRIORITY: D (D)  
OWNER TYPE: Religious organisation

C15 stair turret attached to C20 building. Situated in middle of a housing estate. The roof has recently been repaired but a long term use is still being sought for the building.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **28 Portland Square,  
St Paul, Bristol**

DESIGNATION: Listed Building Grade I, CA  
CONDITION: Poor  
OCCUPANCY: Vacant  
PRIORITY: C (C)  
OWNER TYPE: Company

One of a terrace of seven houses located in a largely complete Georgian square, c1789-1820. Limestone ashlar, brick stacks, slate mansard roofs, double-depth plan. Late Georgian style, four storeys with attic and basement. Consent for conversion to mixed use granted 2009 has not been implemented and ownership has subsequently changed.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **31 and 32 Portland Square,  
St Paul,  
Bristol**

DESIGNATION: Listed Building Grade I, CA  
CONDITION: Very bad  
OCCUPANCY: Vacant  
PRIORITY: D (D)  
OWNER TYPE: Private

Terraced houses, 1789-1820. Emergency repairs carried out with English Heritage grant aid. Wind and weathertight, but masonry continues to decay. There has been a partial collapse of the facade. Consent has been given for repair and residential conversion but has not been implemented.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Timber Lodge,  
Blaise Castle Estate,  
Henbury Road, Henbury**

DESIGNATION: Listed Building Grade II\*, CA, RPG II\*  
CONDITION: Poor  
OCCUPANCY: Vacant  
PRIORITY: C (C)  
OWNER TYPE: Local authority

Early C19 cottage ornée, finely detailed and of uncommon design. Repairs were grant-aided by English Heritage but the building has subsequently been vandalised. Roof now covered with metal sheeting. Options for use are being explored by Bristol City Council.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

**CA** Conservation Area  
**LB** Listed Building  
**LPA** Local Planning Authority  
**NP** National Park  
**RPG** Registered Park and Garden  
**SM** Scheduled Monument  
**UA** Unitary Authority  
**WHS** World Heritage Site



SITE NAME: **Church of St Paul,  
St Pauls Road,  
Bristol**

DESIGNATION: Listed Place of Worship Grade I

CONDITION: Poor

PRIORITY: B (New entry)

OWNER TYPE: Religious organisation

Church built in 1853 to designs by Manners and Gill, but rebuilt by Charles Hansom 14 years later after fire destroyed all but the tower and spire. The roofs are covered with even coursed slating probably Welsh, dating from the 1867 build. The roof coverings are all in poor condition with many slipped and deteriorating slates and frequent repairs are at present carried out by steeplejacks. The valley gutters have received many patch repairs to splits. The roof coverings are now all in need of replacement. A Repair Grant for Places of Worship was successfully applied for in 2011.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:

**Anti-aircraft gun site, Purdown, Bristol**

DESIGNATION:

Scheduled Monument (No.1004531)

CONDITION:

Generally unsatisfactory  
with major localised problems

PRINCIPAL VULNERABILITY:

Deterioration – in need of management

TREND:

Declining

OWNER TYPE:

Private

CONTACT:

Principal Heritage at Risk Adviser  
0117 975 0700

SITE NAME:

**Civil War earthworks on Brandon Hill, Bristol**

DESIGNATION:

Scheduled Monument (No.1006989)

CONDITION:

Generally unsatisfactory  
with major localised problems

PRINCIPAL VULNERABILITY:

Deterioration – in need of management

TREND:

Declining

OWNER TYPE:

Local authority

CONTACT:

Principal Heritage at Risk Adviser  
0117 975 0700

SITE NAME:

**Heavy Anti-aircraft battery 520m east of Holes Mouth, Bristol**

DESIGNATION:

Scheduled Monument (No.1021291)

CONDITION:

Generally unsatisfactory  
with major localised problems

PRINCIPAL VULNERABILITY:

Vandalism

TREND:

Declining

OWNER TYPE:

Local authority

CONTACT:

Principal Heritage at Risk Adviser  
0117 975 0700

## BRISTOL, CITY OF (UA) / BATH AND NORTH EAST SOMERSET (UA)



SITE NAME: **Brislington House,  
Bristol, Keynsham**

DESIGNATION: Registered Park and Garden Grade II\*,  
also CA, 5 LBs

CONDITION: Extensive significant problems

VULNERABILITY: High

TREND: Declining

OWNER TYPE: Mixed, multiple owners

One of the first and most influential asylum landscapes in Britain. Now subdivided between a sixth form college, private residential development, commercial sports facilities, industrial units and a management training centre. Despite this, some components of the designed landscape survive. Its designation is being re-evaluated by English Heritage. Part of the park is in Bath and North East Somerset Unitary Authority.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

## BRISTOL, CITY OF (UA)

SITE NAME:

**Stokes Croft**

DESIGNATION:

Conservation Area

CONDITION:

Very bad

VULNERABILITY:

Low

TREND:

Deteriorating

CONTACT:

Kingsley Fulbrook (LPA) 0117 922 2966

NEW ENTRY:

No

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories  
are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

## CORNWALL (UA)

	<p>SITE NAME: <b>Codda Farmhouse, Bolventor, Altarnun</b></p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: F (F)</p> <p>OWNER TYPE: Private</p>	<p>Farmhouse. C17 or earlier. Partly collapsed. Although some repairs to the habitable part of the house have been undertaken, the shippon and ancillary buildings are in poor condition. The temporary roof has been renewed and listed building consent granted for repair of the collapsing gable end and conversion of associated sheds to ancillary uses.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Scraesdon Fort, Antony</b></p> <p>DESIGNATION: Listed Building Grade II, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (F)</p> <p>OWNER TYPE: Government</p>	<p>Built 1868, used for military training purposes. Vegetation is kept under control to an agreed conservation management plan but works are still outstanding to stop water ingress to the range west of the entrance, and further repairs are required to the main gates and to metalwork throughout the site. In January 2012 the bridge was declared unsafe; there is a commitment to renew it to an historic design.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Tregantle Fort, Antony</b></p> <p>DESIGNATION: Listed Building Grade II, SM</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (F)</p> <p>OWNER TYPE: Government</p>	<p>Fort, built 1858-1865. The Keep is vacant, with no end use identified. The interior is in poor condition and is still drying out following repairs. New doors and windows have been fitted. Elsewhere in the fort, the barracks accommodation is no longer used and the interiors are deteriorating due to outstanding roof repairs. A section of the counterscarp wall has collapsed.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Barn about 40 metres south east of Tremaer, Maer, Bude Stratton</b></p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (C)</p> <p>OWNER TYPE: Private</p>	<p>Rare example of late medieval barn in Cornwall in a hamlet now dominated by a popular caravan site not far from Bude. Approximately one third of the historic roof of cruck type (rare in Cornwall) survived late C20 fire. Historic element not in use and in poor condition. Small cob-built rear wing roofless and collapsing. Remainder re-roofed in corrugated iron and last used as riding stables.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Rosewarne House (Gladys Holman House), Tehidy Road, Camborne</b></p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: A (New entry)</p> <p>OWNER TYPE: Private</p>	<p>Large early C19 H-plan granite town house in its own grounds. Latterly a residential home but vacant for some time. Lack of maintenance and vandalism have resulted in rapidly increasing deterioration. Repairs and a viable use are urgently needed.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Boiler house to winding engine house at King Edward Mine, Troon, Camborne</b></p> <p>DESIGNATION: Listed Building Grade II*, WHS</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: C (New entry)</p> <p>OWNER TYPE: Local authority</p>	<p>Boiler House to winding engine house, built 1904. Part of the King Edward Mine complex, the most complete surviving mine-head complex in the Cornish Mining World Heritage Site. One of the very few boiler houses for an engine house in the World Heritage Site with an original roof. The roof urgently needs replacing to match existing and repairs are required to the windows, doors and brick lintel.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Count House, blacksmiths' shop and miners' dry, Kings Edward Mine, Troon, Camborne</b>
DESIGNATION:	Listed Building Grade II*, WHS
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (New entry)
OWNER TYPE:	Local authority

Count house, blacksmiths' shop and miners' dry. Mainly built c1870. Part of the King Edward Mine complex, the most complete surviving mine-head complex in the Cornish Mining World Heritage Site.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Weighbridge stores, assay office and brass machining shop at King Edward Mine, Troon, Camborne</b>
DESIGNATION:	Listed Building Grade II*, WHS
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	C (New entry)
OWNER TYPE:	Local authority

Weighbridge stores, assay office and brass machining shop built in 1870s. Part of the King Edward Mine complex, the most complete surviving mine-head complex in the Cornish Mining World Heritage Site.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of St Rumon, Ruan Major, Grade Ruan</b>
DESIGNATION:	Listed Building Grade I
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Religious organisation

Medieval former parish church, now chapel of ease in picturesque churchyard. Roof removed shortly afterwards. The Diocese has undertaken consolidation to the low walls but not to the tower which has a tree growing out of it at high level.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>13 High Street, Launceston</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	A (A)
OWNER TYPE:	Company

Jettied and timber-framed corner house, prominent on town's market square. Roof structure is in very poor condition and upper level party wall also in very poor condition. Some of the structural work undertaken but condition of building remains serious.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Freemasons Hall, Quay Street, Lostwithiel</b>
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Good
OCCUPANCY:	Vacant
PRIORITY:	F (E)
OWNER TYPE:	Trust

C13 former hall of the Duchy Palace, a masonic hall since 1878. A building preservation trust has acquired the building; an options appraisal has been carried out and proposals for its re-use are being developed. English Heritage has offered grant for investigation and repairs which are due to be completed Autumn 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Treffry Viaduct, Luxulyan</b>
DESIGNATION:	Scheduled Monument, WHS
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	B (New entry)
OWNER TYPE:	Charity

Combined viaduct and aqueduct. Granite built ten-arched bridge with a span approximately 200 metres and which stands up to 27 metres above the valley floor. Water gushes from the leat within the structure. Leaks are evident at the abutments and at locations within the main spans of the structure. The main leaks have to be stopped to prevent progressive damage to the mortar joints in the masonry.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Maker Heights Barracks Block,  
Maker with Rame**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNER TYPE: Trust

Built in 1804-1808 as a barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. It is the most complete and unaltered small garrison barracks from this significant period. The two storey block was altered in the mid C19 when the formerly tile-hung first floor was rebuilt in brick.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Maker Heights Guard House,  
boundary wall and attached  
ancillary buildings, Maker with Rame**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNER TYPE: Trust

Built in 1804-1808 as Barracks for a line of earlier redoubts built to protect Devonport Dockyard in 1782. Altered in mid C19. Guard House in good condition and used as offices but several of other buildings are in poor to bad condition, in particular the Straw Store, Wash House and Caponier.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Boundary wall to Lanherne  
Carmelite Convent,  
Mawgan in Pydar**

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Religious organisation

C16 or C17 boundary park wall. Substantial loam bonded random rubble masonry wall almost 3ft thick standing up to 12ft in places. Neglected, heavily overgrown with ivy and partially collapsed in places. EH working with agent to encourage urgent remedial repairs but so far only fencing off and clearance of collapses taken place. Condition survey needed to understand and monitor decay and to prioritise repairs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Dry sand and green sand shop,  
Perran Foundry,  
Perran Wharf, Mylor**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: F (B)

OWNER TYPE: Private

Early to mid C19 mould and casting buildings. This is the main furnace building. Impressive and surprisingly intact. Urgent repairs carried out early 2005. Listed building consent and planning permission for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Engineers Shop,  
Perran Foundry,  
Perran Wharf, Mylor**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: F (B)

OWNER TYPE: Private

Engineers shop, boring mill and pattern shop circa early/mid C18. Listed building consent and planning permission for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **New Pattern Shop,  
Perran Foundry,  
Perran Wharf, Mylor**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: F (B)

OWNER TYPE: Private

Early C19 pattern shop. It is one of the most visually exciting buildings on site and despite serious problems retains most of its original structural fabric. Urgent repairs carried out early 2005. Permissions for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Warehouse (formerly listed as office), Perran Foundry, Perran Wharf, Mylor</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	F (B)
OWNER TYPE:	Private

Mid C19 warehouse serving the former iron foundry, subsequently used as offices. It forms part of the Perran Foundry site which was established in 1791. Urgent repairs were carried out early 2005. Permissions for repair and conversion granted 2008 and now starting to be implemented in a phased manner, with an expected completion date of 2016.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Trinity Methodist Chapel, Chywoone Hill, Newlyn, Penzance</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Religious organisation

Former Nonconformist Wesleyan chapel circa 1834, enlarged 1866. One of the best and most complete early C19 chapels in Cornwall. No longer used for religious worship. English Heritage grant for investigation and repairs offered 2010. Heritage Lottery Fund bid for multi-purpose community use under review.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Tolgus Calciner, New Portreath Road, Redruth</b>
DESIGNATION:	Listed Building Grade II, WHS, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	A (New entry)
OWNER TYPE:	Private

Remains of a calciner used in the production of arsenic. It has been vacant for many years and is vulnerable with a damaged main roof and a collapsed adjoining tin roofed extension. The main hipped slate roof of the building has been damaged through vandalism and there is an urgent need for weather proofing.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Sara's Foundry, Tolgus Place, Redruth</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Private

C19 and C20 iron foundry and engineering works, containing a large quantity of tools and associated machinery. Buildings continue to deteriorate and are now in a very vulnerable condition. Discussions are in train with Cornwall Council to identify an appropriate strategy to secure the building and prevent further deterioration.


Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Charlestown Methodist Church, Charlestown Road, St Austell</b>
DESIGNATION:	Listed Building Grade II*, WHS, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Private

Former Wesleyan chapel (1827) and attached schoolroom (mid C19). No longer used for worship. Building weathertight. Listed building consent granted for conversion of rear school block and stabilisation of chapel agreed.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Hockings House Bible Christian Chapel, St Cleer</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	B (B)
OWNER TYPE:	Private

Chapel dated 1846. Exceptionally well-preserved interior with gallery and good quality original fittings including leaders' pew. Now separated from the small Sunday school. Plans for modest conversion agreed.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Flanking walls and gateway to the bridge over moat about 8 metres east of Old Rectory, Old Rectory Drive, St Columb Major</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (New entry)
OWNER TYPE:	Private

Mid-C19, part of William White's layout for the Bishop's Palace which became a Rectory and latterly a hotel. Obscured and threatened by dense vegetation. White's wrought iron gate, referred to in the List is not at present hung.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Old Bishops Palace, Old Rectory Drive, St Columb Major</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (New entry)
OWNER TYPE:	Company

1851 by William White. Picturesque Gothic Revival country gentleman's rectory, a classic of the type. In very poor state of repair caused by lack of maintenance, vandalism, vegetation, inappropriate finishes and unlive-in state. Water ingress has resulted in dry rot and damage to historic fabric.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Calf House at Lithiack and stable adjacent to north, Port Eliot Estate, St Germans</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied
PRIORITY:	C (C)
OWNER TYPE:	Private

Late C18/early C19 Estate agricultural building. Attributed to Soane for the Port Eliot Estate. Low key use but condition remains very poor.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Porthmeor Pilchard Cellars and Studios, 13, 15 and 17 Back Road West, St Ives</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Occupied
PRIORITY:	F (F)
OWNER TYPE:	Trust

Built in the C19 and extended around 1900, the Studios were home to many important artists of the internationally known St Ives School. The net lofts below retain rare pilchard processing tanks. The building is still in use today, and the Trust who own the building have started an intensive programme of repairs with funding from the Heritage Lottery Fund, English Heritage and others.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Wesleyan Chapel, Porkellis, Wendron</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Private

Former Wesleyan Methodist chapel, built 1866. The congregation has moved into the Sunday school and the chapel was sold to a private buyer. New owner has addressed the most serious roof leaks and is negotiating potential for conversion to residential use with Cornwall County Council and English Heritage.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of All Saints, Pendarves Street, Tuckingmill, Camborne</b>
DESIGNATION:	Listed Place of Worship Grade II, WHS
CONDITION:	Poor
PRIORITY:	B (New entry)
OWNER TYPE:	Religious organisation

Church built for the new parish of Tuckingmill in 1845. The external walls are of mass wall construction with rubble infill, the external face of coursed red sandstone, with granite quoins, piers and dressings. The sandstone is suffering from severe erosion on all elevations, particularly on the south aisle walls and the middle stage to the tower. There have been recent high level losses with pieces of stone shearing off, causing safety concerns. The condition of the valley gutter is poor; with very many patch repairs. A Repair Grant for Places of Worship was successfully applied for in 2011.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: <b>Church of St David, Davidstow</b></p> <p>DESIGNATION: Listed Place of Worship Grade II*</p> <p>CONDITION: Poor</p> <p>PRIORITY: B (New entry)</p> <p>OWNER TYPE: Religious organisation</p>	<p>Typical Cornish three aisle church with a tall west tower mostly C15, but with an extensive late Victorian restoration. The roofs were all repaired about 15 years ago including the tower. The tower walls are now showing structural problems at high level and bits are falling from the bell opening louvres. A repair grant was offered in 2011.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Church of St Michael, Stratton Terrace, Falmouth</b></p> <p>DESIGNATION: Listed Place of Worship Grade II, CA</p> <p>CONDITION: Poor</p> <p>PRIORITY: F (B)</p> <p>OWNER TYPE: Religious organisation</p>	<p>A large suburban Anglican parish church fronting the estuary north of Falmouth. It was built in 1827 to the design of R Grouet and has remained substantially unaltered since. There are major roof leaks in several places that have caused internal decay. A Repair Grant for Places of Worship has been offered for the repairs which will be completed during 2012.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Church of St James, Jacobstow</b></p> <p>DESIGNATION: Listed Place of Worship Grade I</p> <p>CONDITION: Very bad</p> <p>PRIORITY: F (B)</p> <p>OWNER TYPE: Religious organisation</p>	<p>A three aisled church with a tall west tower in the centre of a tiny village. The tower roof and the north valley gutter are leaking, the latter very badly due to a temporary repair long overdue for replacement. A grant offer for repairs to the roofs and gutters has been made, and work will start in 2012.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Church of St Philip and St James, Maryfield, St Antony</b></p> <p>DESIGNATION: Listed Place of Worship Grade II*</p> <p>CONDITION: Very bad</p> <p>PRIORITY: F (B)</p> <p>OWNER TYPE: Religious organisation</p>	<p>A mid C19 church near to Antony House (National Trust) overlooking the estuary of the river Tamar in Cornwall. The stone spire has structural problems with damp ingress and loose pinnacles and spire apex. There is a very real danger of falls of stonework. A repair grant has been offered to restore the stonework. Repair work will be undertaken in 2012.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>St Buryan Church, St Buryan</b></p> <p>DESIGNATION: Listed Place of Worship Grade I, CA</p> <p>CONDITION: Very bad</p> <p>PRIORITY: F (B)</p> <p>OWNER TYPE: Religious organisation</p>	<p>A large three aisled church with a tall tower that is a famous maritime landmark. The valley gutters are leaking, causing active decay to the wall heads above the internal arcades. A repair grant has been offered to renew the valley gutters and repair the inner slate roof slopes, and repair works will start 2012.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Church of St Enoder, St Enoder</b></p> <p>DESIGNATION: Listed Place of Worship Grade I</p> <p>CONDITION: Poor</p> <p>PRIORITY: B (New entry)</p> <p>OWNER TYPE: Religious organisation</p>	<p>A large three aisled church near to the A30 in mid Cornwall. The six main large roof pitches need relaying because the C19 nails holding the slates on are rusting away. The valleys have split and although patched frequently, still let in water which is causing internal damage. A grant for repairs to the roof has been offered.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Church of St Ida,  
St Issey**

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor

PRIORITY: B (New entry)

OWNER TYPE: Religious organisation

The church has C14 and C15 origins evidenced in the north and south aisle arcades. Rebuilt in 1872 to designs by JP St Aubyn, following collapse of tower and part of the nave. The ring beams were inserted at two levels in the tower walls to address structural weaknesses probably when the bells were lowered in the 1950s. The damp environment of the tower and the inadequate cover to the concrete means the reinforcement is corroding and therefore presenting a structural weakness which will only deteriorate if left unrepaired. A repair grant was successfully applied for in 2011. Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Little Trethewey Methodist Chapel,  
Little Trethewey,  
St Levan**

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Very Bad

PRIORITY: A (New entry)

OWNER TYPE: Religious organisation

Built as Wesleyan Chapel in 1868. Small chapel with stuccoed Italianate front. Modest and complete interior with closed box pews. Raked seating under gallery, stand and communion rail in front of raised choir with organ and open benching. The church is in a bad condition with holes in the roof. The downpipes are blocked and external render is failing. Front gable is unstable and resulted in damage to the interior.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **St Stithians Church,  
Stithians**

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Very bad

PRIORITY: F (D)

OWNER TYPE: Religious organisation

A large three aisled church on the edge of a large former mining village. The tall granite west tower is exceptionally wet internally as it lets in and retains rainwater. The beam ends are starting to decay where they are embedded in the tower walls. A grant for the repair of the tower walls has been offered, and repairs will be completed during 2012.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Two hut circles 400m WSW of Furhouse, Advent**

DESIGNATION: Scheduled Monument (No.1004657)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Extensive vehicle damage/erosion

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Co-axial field system, hut circle settlements, cairnfield and land boundaries on Carne Down, Altarnun**

DESIGNATION: Scheduled Monument (No.1011726)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Moderate stock erosion

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Cross on Halvana Moor, Altarnun**

DESIGNATION: Scheduled Monument (No.1004399)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Forestry

TREND: Unknown

OWNER TYPE: Government or Agency

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Deserted medieval settlement and field system with incorporated prehistoric settlement and field system and post-medieval farmhouse north west of Tresibbet Farm, Altarnun**

DESIGNATION: Scheduled Monument (No.1007775)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Scrub/tree growth

TREND: Improving

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	<b>Nine Stones stone circle 1.03km NNW of Bowhayland Farm, Altarnun</b>		
DESIGNATION:	Scheduled Monument (No.1008631)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Platform cairn with rim bank and central cairn, and a secondary cairn, on the summit of Carne Down, Altarnun</b>		
DESIGNATION:	Scheduled Monument (No.1011781)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric coaxial field system, incorporated and adjacent hut circles, stone setting, linear boundaries and medieval settlement on Fox Tor and Treburland Farm, Altarnun</b>		
DESIGNATION:	Scheduled Monument (No.1008245)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric irregular field system and hut circle settlement with adjacent medieval regular field system and deserted settlement south east of Tresibbet Farm, Altarnun</b>		
DESIGNATION:	Scheduled Monument (No.1007776)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric stone alignment 1km SSE of Eastmoorgate, Altarnun</b>		
DESIGNATION:	Scheduled Monument (No.1012228)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two adjacent prehistoric coaxial field systems incorporating regular field systems, stone hut circles, cairns and medieval fields on East Moor and Ridge, Altarnun</b>		
DESIGNATION:	Scheduled Monument (No.1008439)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut circle group and enclosure north east of Carwen, Blisland</b>		
DESIGNATION:	Scheduled Monument (No.1004659)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Castle Pencaire hillfort, two rounds and a field system, Tregonning Hill, Breage</b>			
DESIGNATION:	Scheduled Monument (No.1007293)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Group of round barrows south east of Middle Taphouse, Broadoak</b>			
DESIGNATION:	Scheduled Monument (No.1004433)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Group of round barrows south of Penadlake, Broadoak</b>			
DESIGNATION:	Scheduled Monument (No.1004436)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow 310yds (280m) south of Kilmansag, Broadoak</b>			
DESIGNATION:	Scheduled Monument (No.1004434)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrows west of West Taphouse, Broadoak</b>			
DESIGNATION:	Scheduled Monument (No.1004617)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two round barrows north west of Middle Taphouse, Broadoak</b>			
DESIGNATION:	Scheduled Monument (No.1003077)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Okeltor 19th century arsenic, copper and tin mine, Calstock</b>			
DESIGNATION:	Scheduled Monument (No.1019440)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prince of Wales Mine at Harrowbarrow, Calstock</b>			
DESIGNATION:	Scheduled Monument (No.1021411)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Tamar Canal, Gunnislake, Calstock</b>		
DESIGNATION:	Scheduled Monument (No.1007302)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Carvannel cliff castle, Camborne</b>		
DESIGNATION:	Scheduled Monument (No.1004390)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of round barrows north of Grey Mare Lodge, Cardinham</b>		
DESIGNATION:	Scheduled Monument (No.1003080)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>St Bellarmin's Chapel, Cardinham</b>		
DESIGNATION:	Scheduled Monument (No.1004442)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Treznace Holy Well and chapel enclosure, Cardinham</b>		
DESIGNATION:	Scheduled Monument (No.1018494)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Carn Brea Castle, Carn Brea</b>		
DESIGNATION:	Scheduled Monument (No.1006704)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wheal Busy, Chacewater</b>		
DESIGNATION:	Scheduled Monument (No.1021392)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Melangoose camp, Colan</b>		
DESIGNATION:	Scheduled Monument (No.1004426)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round 300yds (270m) WSW of High Cross, Constantine</b>		
DESIGNATION:	Scheduled Monument (No.1004270)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Killibury Castle later Prehistoric hillfort, Egloshayle</b>		
DESIGNATION:	Scheduled Monument (No.1010439)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Tregeare camp, Egloskerry</b>		
DESIGNATION:	Scheduled Monument (No.1006711)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Jewish and Congregationalist cemeteries at Ponsharden, Falmouth</b>		
DESIGNATION:	Scheduled Monument (No.1020815)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow 120m south east of Parkwood Hill, Feock</b>		
DESIGNATION:	Scheduled Monument (No.1019087)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cliff castle west of Gunwalloe Church, Gunwalloe</b>		
DESIGNATION:	Scheduled Monument (No.1004265)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Rectangular camp south west of Trevarnon Round, Gwinear-Gwithian</b>		
DESIGNATION:	Scheduled Monument (No.1004468)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roseworthy Arsenic Works, 700m west of Cornhill Farm, Gwinear-Gwithian</b>		
DESIGNATION:	Scheduled Monument (No.1021418)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round near Lower Nanterrow, Gwinear-Gwithian</b>		
DESIGNATION:	Scheduled Monument (No.1007303)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Trevarnon Round, Gwithian, Gwinear-Gwithian</b>		
DESIGNATION:	Scheduled Monument (No.1006696)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Castle Kayle (earthwork), Phillack, Hayle</b>		
DESIGNATION:	Scheduled Monument (No.1006688)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>'Headon Barrow' near Headon Cross, Jacobstow</b>		
DESIGNATION:	Scheduled Monument (No.1005434)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round 200m north west of Penventinnie, Kenwyn</b>		
DESIGNATION:	Scheduled Monument (No.1016063)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp north east of Northcott Park Quarry, Kilkhampton</b>		
DESIGNATION:	Scheduled Monument (No.1004382)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
**2011 priority categories are given in brackets.**

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Group of four round barrows east of Bottaborough, Kilkhampton</b>			
DESIGNATION:	Scheduled Monument (No.1004402)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Five bowl barrows 480m and 510m north of Hendra Farm, Ladock</b>			
DESIGNATION:	Scheduled Monument (No.1019021)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round 390m south west of Trethurffe, Ladock</b>			
DESIGNATION:	Scheduled Monument (No.1020797)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round and annexe 720m WSW of Tregear, Ladock</b>			
DESIGNATION:	Scheduled Monument (No.1020179)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Neolithic settlement and hut circle on Helman Tor, Lanlivery</b>			
DESIGNATION:	Scheduled Monument (No.1007306)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Giants Hedge, Lerryn to Lanreath, Lanreath</b>			
DESIGNATION:	Scheduled Monument (No.1006681)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Mabel Barrow, Lansallos</b>			
DESIGNATION:	Scheduled Monument (No.1006683)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Earlier Prehistoric hillfort, two cairns, medieval pound and adjacent Prehistoric field systems, hut circles and transhumance huts on Stowe's Hill, Linkinhorne</b>	
DESIGNATION:	Scheduled Monument (No.1012352)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Early medieval transhumance hut 740m west of Blackcoombe Farm, Linkinhorne</b>	
DESIGNATION:	Scheduled Monument (No.1011899)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Medieval and post-medieval tin and copper mines with medieval field system on the middle and lower northern slopes of Caradon Hill, Linkinhorne</b>	
DESIGNATION:	Scheduled Monument (No.1020942)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Neolithic long cairn, Prehistoric regular and irregular aggregate field systems, linear boundaries and medieval enclosure 625m west of Blackcoombe Farm, Linkinhorne</b>	
DESIGNATION:	Scheduled Monument (No.1010221)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Prehistoric funerary cist 1.275km north west of Wardbrook Farm, Linkinhorne</b>	
DESIGNATION:	Scheduled Monument (No.1012043)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Flooding	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Prehistoric linear boundaries, cairn and enclosure 1.225km north west of Wardbrook Farm, Linkinhorne</b>	
DESIGNATION:	Scheduled Monument (No.1008982)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Prehistoric linear boundary and field system, medieval enclosure and tin miners' caches 1.06km north west of Wardbrook Farm, Linkinhorne</b>	
DESIGNATION:	Scheduled Monument (No.1015975)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Prehistoric round cairn on Caradon Hill, 310m west of Heather House, Linkinhorne</b>		
DESIGNATION:	Scheduled Monument (No.1020939)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric unenclosed hut circle settlement incorporating a medieval tin miners' cache and medieval shelter 1.285km north west of Wardbrook Farm, Linkinhorne</b>		
DESIGNATION:	Scheduled Monument (No.1008848)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 580m north west of Wardbrook Farm, Linkinhorne</b>		
DESIGNATION:	Scheduled Monument (No.1009737)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 775m north west of Wardbrook Farm, Linkinhorne</b>		
DESIGNATION:	Scheduled Monument (No.1010308)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn with central cist on Bearah Common, 1.106km north of Wardbrook Farm, Linkinhorne</b>		
DESIGNATION:	Scheduled Monument (No.1010411)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone hut circle 812m north west of Wardbrook Farm, Linkinhorne</b>		
DESIGNATION:	Scheduled Monument (No.1009739)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two adjacent transhumance huts on Caradon Hill, 450m north of East Caradon Farm, Linkinhorne</b>		
DESIGNATION:	Scheduled Monument (No.1011900)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Stone cross in the garden of Pendean House, Liskeard</b>		
DESIGNATION:	Scheduled Monument (No.1003046)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round 450yds (405m) north west of Lower Chellew Farm, Ludgvan</b>		
DESIGNATION:	Scheduled Monument (No.1004262)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Trencrom Castle, Ludgvan</b>		
DESIGNATION:	Scheduled Monument (No.1006721)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Innis Downs earthwork, Luxulyan</b>		
DESIGNATION:	Scheduled Monument (No.1006684)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Ancient village and fields at Boswarva Carn, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004466)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow 800yds (730m) WNW of Boswens Farm, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004286)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bosulow Trehylls (hut circles), Madron</b>		
DESIGNATION:	Scheduled Monument (No.1006697)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Chun Downs prehistoric landscape complex, incorporating Chun Cromlech, Chun Castle, and barrow 200yds (180m) south west of Chun Farm, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1007264)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Courtyard house 200yds (180m) NNE of Try Farm, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004352)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Courtyard house 300yds (270m) north west of Middle Carnaquidden, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004353)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Courtyard houses north east of Newmill, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004356)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut circles with associated field system 400yds (360m) south west of Little Higher Bosulow, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004316)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round 300yds (270m) north east of Newmill, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004627)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow 530yds (480m) north west of Nancothan Cottages, Madron</b>		
DESIGNATION:	Scheduled Monument (No.1004311)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Settlement 450yds (400m) north west of Middle Carnaquidden, Madron</b>			
DESIGNATION:	Scheduled Monument (No.1003100)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Cawsand Fort, Maker-with-Rame</b>			
DESIGNATION:	Scheduled Monument (No.1016102)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Earthwork redoubts Nos. 1, 2 and 3, Maker-with-Rame</b>			
DESIGNATION:	Scheduled Monument (No.1004254)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Grenville Battery 550yds (500m) SSW of Maker Farm, Maker-with-Rame</b>			
DESIGNATION:	Scheduled Monument (No.1003114)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Incomplete Palmerstonian fort 650yds (600m) west of Forder, Maker-with-Rame</b>			
DESIGNATION:	Scheduled Monument (No.1007299)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Mount Edgcumbe round barrow, Maker-with-Rame</b>			
DESIGNATION:	Scheduled Monument (No.1004496)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>No. 5 redoubt 450yds (410m) north west of Maker Farm, Maker-with-Rame</b>			
DESIGNATION:	Scheduled Monument (No.1004255)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Mawgan Cross early Christian memorial stone and wayside cross shaft, Mawgan-in-Meneage</b>		
DESIGNATION:	Scheduled Monument (No.1010852)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow 500yds (460m) west of Trevassack, Mawgan-in-Meneage</b>		
DESIGNATION:	Scheduled Monument (No.1004499)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hillfort at Blacketon Farm, Menheniot</b>		
DESIGNATION:	Scheduled Monument (No.1007296)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Inswork Chapel, Millbrook</b>		
DESIGNATION:	Scheduled Monument (No.1003095)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Croftoe British village, Morvah</b>		
DESIGNATION:	Scheduled Monument (No.1006740)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow on Bin Down, Morval</b>		
DESIGNATION:	Scheduled Monument (No.1006651)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Trelgue promontory camp and two barrows, Newquay</b>		
DESIGNATION:	Scheduled Monument (No.1006712)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Hut circle settlement 975m north east of Trewortha Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1009806)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Platform cairn 667m ENE of Trewortha Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1017846)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric co-axial and regular aggregate field systems with incorporated and adjacent hut circle settlements on Bastreet Downs, south of Bowda Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1011558)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 1.175km WSW of East Castick Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1010412)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 617m ENE of Trewortha Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1009780)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 800m WSW of Tolcarne Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1011507)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 910m WSW of Tolcarne Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1011508)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Round cairn with central cist 1.05km east of Trewortha Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1009735)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn with central cist 970m ENE of Trewortha Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1009734)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn with double orthostatic kerb and cist 497m south east of Trewortha Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1009688)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone hut circle 1.225km WSW of East Castick Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1010414)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three adjoining Prehistoric linear boundaries on Bearah Tor, 687m south west of Nodmans Bowda Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1010220)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three stone hut circles 1.06km north east of Trewortha Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1009807)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two stone hut circles and adjacent Prehistoric boundary wall 575m west of West Berriow Farm, North Hill</b>		
DESIGNATION:	Scheduled Monument (No.1010218)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Unenclosed hut circle settlement and adjacent Prehistoric linear boundary 800m SSE of Trewortha Farm, North Hill</b>			
DESIGNATION:	Scheduled Monument (No.1008958)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Unenclosed hut circle settlement with incorporated enclosure 1.5km north west of Wardbrook Farm, North Hill</b>			
DESIGNATION:	Scheduled Monument (No.1008954)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three barrows 550m ENE of Cansford, Otterham</b>			
DESIGNATION:	Scheduled Monument (No.1005463)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Roundago, hut circle and field system on Castallack Carn, Paul</b>			
DESIGNATION:	Scheduled Monument (No.1004654)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bake Rings later prehistoric-Roman round with attached enclosure and outwork, Pelynt</b>			
DESIGNATION:	Scheduled Monument (No.1017682)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Group of three round barrows north of Hendra, Pelynt</b>			
DESIGNATION:	Scheduled Monument (No.1004621)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hall Rings, Pelynt</b>			
DESIGNATION:	Scheduled Monument (No.1006682)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories  
are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Ten barrows south of Wilton Mill, Pelynt</b>			
DESIGNATION:	Scheduled Monument (No.1004465)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>St Piran's Oratory and associated early medieval cemetery, Perranzabuloe</b>			
DESIGNATION:	Scheduled Monument (No.1018955)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Flooding	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Clapper Bridge, Quethiock</b>			
DESIGNATION:	Scheduled Monument (No.1004482)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>The Tolgus arsenic works 80m south east of East Tolgus House, Redruth</b>			
DESIGNATION:	Scheduled Monument (No.1021240)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>D-Day landing craft maintenance site, 170m north of Saltash Pier, Saltash</b>			
DESIGNATION:	Scheduled Monument (No.1020053)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Field system on Boswens Common, Sancreed</b>			
DESIGNATION:	Scheduled Monument (No.1007268)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Goldherring British village, Sancreed</b>			
DESIGNATION:	Scheduled Monument (No.1004651)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Hut circle north of Botrea, Sancreed</b>		
DESIGNATION:	Scheduled Monument (No.1003072)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bolster Bank, St Agnes</b>		
DESIGNATION:	Scheduled Monument (No.1016444)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wheal Kitty 20th century tin processing works, St Agnes</b>		
DESIGNATION:	Scheduled Monument (No.1021164)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Promontory fort and Civil War battery, Little Dennis Head, St Anthony-in-Meneage</b>		
DESIGNATION:	Scheduled Monument (No.1004431)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Black Head promontory fort, St Austell Bay</b>		
DESIGNATION:	Scheduled Monument (No.1004391)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Deserted village of Garrow, St Breward</b>		
DESIGNATION:	Scheduled Monument (No.1021445)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric to post-medieval settlement, and religious and funerary remains on the middle and lower slopes west and south of Roughtor, St Breward</b>		
DESIGNATION:	Scheduled Monument (No.1019172)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Stannon Stone Circle, prehistoric field system, hut circle settlement, cairns, cist, linear boundaries and medieval building north of Dinnever Hill, St Breward</b>	
DESIGNATION:	Scheduled Monument (No.1007764)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Stone circle on Emblance Common, St Breward</b>	
DESIGNATION:	Scheduled Monument (No.1004459)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Camp 900yds (820m) south east of St Buryan village, St Buryan</b>	
DESIGNATION:	Scheduled Monument (No.1004483)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Round barrow 200yds (180m) north of the Merry Maidens, St Buryan</b>	
DESIGNATION:	Scheduled Monument (No.1004358)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Earlier Prehistoric hillfort, adjacent round cairn with incorporated shelter, and tor cairn on Tregarrick Tor, St Cleer</b>	
DESIGNATION:	Scheduled Monument (No.1009698)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Embanked platform cairn with central mound 375m north west of Trewalla Farm, St Cleer</b>	
DESIGNATION:	Scheduled Monument (No.1015976)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Kerbed platform cairn with kerbed central mound and outer bank 600m east of Trewalla Farm, St Cleer</b>	
DESIGNATION:	Scheduled Monument (No.1010323)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Platform cairn with central mound 760m ESE of Lambadla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1010327)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Platform cairn with central mound 900m ESE of Lambadla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1010328)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric cist, cairns and cairnfield on north east Smallacombe Downs, 570m north west of Smallacombe Tor, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1018630)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric enclosure 325m west of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1010434)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric enclosure and field system, two hut circles and parts of a medieval field system 350m south east of Sparretts Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1013216)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric enclosure containing a stone hut circle and parts of a medieval field system, 500m south east of Sparretts Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1013199)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric irregular and regular aggregate field systems with incorporated stone hut circles 750m ENE of Siblyback Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011315)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME:</b> Prehistoric irregular and regular aggregate field systems, enclosure, stone hut circles, cairnfield and kerbed boulder 750m ESE of Siblyback Farm, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010060)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Prehistoric regular aggregate field system with incorporated and adjacent stone hut circles and an adjacent enclosure 550m WSW of Trewalla Farm, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1009731)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Prehistoric to medieval settlements, field systems, enclosures and cairns, with post-medieval boundary and railway on north east Smallacoombe Down, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1018629)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Forestry	<b>TREND:</b>	Improving
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Prehistoric to post-medieval field systems, boundaries, settlements and railway at Smallacoombe Parks and north eastern Siblyback Moor, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1018631)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Forestry	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Round cairn 450m east of Sparretts Farm, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1009838)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Round cairn 472m SSW of Caradon Hill summit, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1011824)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Moderate vehicle damage/erosion	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Round cairn 480m SSW of Caradon Hill summit, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1011825)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Vandalism	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Round cairn 525m east of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1012041)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 527m SSW of Caradon Hill summit, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011840)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 557m SSW of Caradon Hill summit, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011844)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 725m ESE of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011992)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 740m SSW of Caradon Hill summit, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011774)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 800m ESE of Lambadla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1010326)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 812m ESE of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011991)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Round cairn 840m south east of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011995)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn and shelters 812m SSW of Caradon Hill summit, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011784)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Public utilities	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn with peripheral berm 402m SSW of Caradon Hill summit, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011822)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>South Caradon 19th century copper mine, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1020614)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle 425m south east of Sparretts Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1013211)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle 685m south east of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011907)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle 750m ESE of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011909)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Stone hut circle 800m ESE of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011989)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle centred 460m ESE of Sparretts Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1009839)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>The Tinnars' Dyke 160yds (150m) in length south of Hendergrove Wood, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1004364)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Tor cairn with adjacent sub-rectangular hut 650m SSW of Caradon Hill summit, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1011793)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two adjacent stone hut circles 265m WNW of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1009738)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two adjacent stone hut circles 290m west of Trewalla Farm, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1009703)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two cairns 550m and 587m ENE of Trewalla Farm and two adjacent small clearance cairns, St Cleer</b>			
DESIGNATION:	Scheduled Monument (No.1010311)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME:</b> Two platform cairns 750m and 785m east of Sparretts Farm, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010325)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Moderate vehicle damage/erosion	<b>TREND:</b>	Improving
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Two round cairns 455m and 475m north west of Trewalla Farm, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010324)	<b>CONDITION:</b>	Generally satisfactory but with minor localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Scrub/tree growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Two stone hut circles and an adjoining Prehistoric boundary wall 470m east of Trewalla Farm, St Cleer			
<b>DESIGNATION:</b>	Scheduled Monument (No.1012000)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Round 340m north west of Tresawle Farm, St Columb Major			
<b>DESIGNATION:</b>	Scheduled Monument (No.1020864)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Bury camp, St Dominick			
<b>DESIGNATION:</b>	Scheduled Monument (No.1004393)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Localised/limited stock erosion	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Westcott Cross, 480m south east of Westcott Lodge, St Dominick			
<b>DESIGNATION:</b>	Scheduled Monument (No.1018019)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Other	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Local authority	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Warren's Barrow, St Erme			
<b>DESIGNATION:</b>	Scheduled Monument (No.1016888)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Scrub/tree growth	<b>TREND:</b>	Improving
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

<b>CA</b>	Conservation Area
<b>LB</b>	Listed Building
<b>LPA</b>	Local Planning Authority
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WH</b>	World Heritage Site

SITE NAME: <b>Enclosures east of Gurlyn, St Erth</b>			
DESIGNATION:	Scheduled Monument (No.1007282)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Promontory fort north of village, St Gennys</b>			
DESIGNATION:	Scheduled Monument (No.1003097)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Gunpowder storage complex at Kennall Vale, St Gluvias</b>			
DESIGNATION:	Scheduled Monument (No.1020441)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Gunpowder works at Kennall Vale, St Gluvias</b>			
DESIGNATION:	Scheduled Monument (No.1020143)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Later prehistoric cliff castle, two prehistoric round barrows, medieval field system, and associated remains on Dodman Point, St Goran</b>			
DESIGNATION:	Scheduled Monument (No.1020865)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Camp 500yds (460m) west of Trenance, St Issey</b>			
DESIGNATION:	Scheduled Monument (No.1004235)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Tokenbury camp, St Ive</b>			
DESIGNATION:	Scheduled Monument (No.1004469)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Hut circles, Higher Bussow, St Ives</b>			
DESIGNATION:	Scheduled Monument (No.1006689)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Whitesand Bay (or Tregonhawke) battery, St John</b>			
DESIGNATION:	Scheduled Monument (No.1004664)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Chambered barrow 100yds (90m) east of Kerrow Farm, St Just</b>			
DESIGNATION:	Scheduled Monument (No.1004637)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Holed stones on Kenidjack Common, St Just</b>			
DESIGNATION:	Scheduled Monument (No.1006755)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circles 50yds (45m) west of Carnyorth Farm, St Just</b>			
DESIGNATION:	Scheduled Monument (No.1004277)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow 550yds (500m) north of Chycarne, St Just</b>			
DESIGNATION:	Scheduled Monument (No.1004245)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Standing stone 200yds (180m) west of Chycarne, St Just</b>			
DESIGNATION:	Scheduled Monument (No.1003116)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Two barrows on Carn Bean 300yds (270m) NNE of Higher Botallack, St Just</b>		
DESIGNATION:	Scheduled Monument (No.1004279)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two barrows on Woon Gumpus Common 700yds (640m) NNW of Boslow Farm, St Just</b>		
DESIGNATION:	Scheduled Monument (No.1004287)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Chapel enclosure 150yds (140m) south of Trelease Farm, St Keverne</b>		
DESIGNATION:	Scheduled Monument (No.1004334)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cliff castle at Winecove Point, St Merryn</b>		
DESIGNATION:	Scheduled Monument (No.1004234)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>St Constantine's chapel and holy well, St Merryn</b>		
DESIGNATION:	Scheduled Monument (No.1018569)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hobbs Hill tin mine, openwork and lodeback tinwork 530m east and 160m north east of Chyseger Farm, St Neot</b>		
DESIGNATION:	Scheduled Monument (No.1021410)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut circle village 330yds (300m) west of West Northwood Farm, St Neot</b>		
DESIGNATION:	Scheduled Monument (No.1004662)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Medieval homestead and fields on Redhill Downs, St Neot</b>			
DESIGNATION:	Scheduled Monument (No.1003074)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric field systems, enclosure, hut circles and rounds, with adjacent medieval settlement, longhouse and field system on Higher Langdon Farm, St Neot</b>			
DESIGNATION:	Scheduled Monument (No.1007475)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric settlements and field system with adjacent medieval settlement, field systems, boundaries and tin streamworks on the Brown Gelly Downs, St Neot</b>			
DESIGNATION:	Scheduled Monument (No.1007770)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 1.062km south west of Higher Langdon Farm, St Neot</b>			
DESIGNATION:	Scheduled Monument (No.1007476)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 1.17km south west of Higher Langdon Farm, St Neot</b>			
DESIGNATION:	Scheduled Monument (No.1007477)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bofarnel Downs round barrows, St Winnow</b>			
DESIGNATION:	Scheduled Monument (No.1004437)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Respryn Bridge, St Winnow</b>			
DESIGNATION:	Scheduled Monument (No.1006701)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Limited/localised vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Two round barrows north east of Fairy Cross, St Winnow</b>		
DESIGNATION:	Scheduled Monument (No.1004439)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Condolden Barrow, Tintagel</b>		
DESIGNATION:	Scheduled Monument (No.1004652)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Ballast Pond, Torpoint</b>		
DESIGNATION:	Scheduled Monument (No.1007261)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wheal Martyn china clay works, Treverbyn</b>		
DESIGNATION:	Scheduled Monument (No.1003265)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Carne Beacon round barrow 320m north of Carne Farm, Veyan</b>		
DESIGNATION:	Scheduled Monument (No.1019745)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Warbstow Bury camp, Warbstow</b>		
DESIGNATION:	Scheduled Monument (No.1006710)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Ancient village south of Carburrow Tor, Warleggan</b>		
DESIGNATION:	Scheduled Monument (No.1003073)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Grambla Roman camp, Wendron</b>		
DESIGNATION:	Scheduled Monument (No.1003078)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Trellill Well Chapel, near Helston, Wendron</b>		
DESIGNATION:	Scheduled Monument (No.1006743)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bosigran Castle 900yds (820m) west of Bosigran, Zennor</b>		
DESIGNATION:	Scheduled Monument (No.1003106)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Porthmeor ancient village, Zennor</b>		
DESIGNATION:	Scheduled Monument (No.1003071)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Treen Common barrows, Zennor</b>		
DESIGNATION:	Scheduled Monument (No.1004473)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Carclew, Mylor</b>	Mid C18 formal terraced and water gardens, together with an C18 landscape park. The main house burned down in 1934 and the site is now in divided ownership. Infill residential development has taken place in the park belts, substantial areas of woodland have been cleared and many individual parkland trees have been lost.
DESIGNATION:	Registered Park and Garden Grade II, also CA, 5 LBs	
CONDITION:	Extensive significant problems	
VULNERABILITY:	Medium	
TREND:	Stable	
OWNER TYPE:	Private, multiple owners	Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bodmin</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Alyson Cooper (LPA) 01872 323603	NEW ENTRY:	No

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

## DEVON

## DARTMOOR (NP)



SITE NAME: **Higher Sigford, Sweet's Sigford, Ilsington, Teignbridge**

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: D (D)

OWNER TYPE: Private

A rare example of a longhouse derivative in a farmstead context which has been used for agricultural storage in more recent years. Some internal and external stabilisation works have been carried out though further works are needed. Conditional consents for re-occupation of the house have been granted. New owner is negotiating the consent.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Medieval farmstead 340m south east of Cold East Cross, Ashburton, Teignbridge**

DESIGNATION: Scheduled Monument (No.1019604)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Taw River tin blowing mill, 840m south of Tawcroft, Belstone, West Devon**

DESIGNATION: Scheduled Monument (No.1019228)

CONDITION: Generally satisfactory but with minor localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Enclosure, two stone hut circles and an alignment of upright stones 780m north west of Little Links Tor, Bridestowe, West Devon**

DESIGNATION: Scheduled Monument (No.1007648)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Hut circles and a length of enclosure wall, forming part of a stone hut circle settlement 600m east of Nodden Gate, Bridestowe, West Devon**

DESIGNATION: Scheduled Monument (No.1008638)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Hut circles and fields on Buckland Common, Buckland in the Moor, Teignbridge**

DESIGNATION: Scheduled Monument (No.1004589)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Lizwell Bridge, Buckland in the Moor, Teignbridge**

DESIGNATION: Scheduled Monument (No.1003294)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Extensive natural erosion

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:** 2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Hut circles west of Higher Shapley, Chagford, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002651)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Agglomerated enclosure on the west side of the Erme Valley below Stalldown, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012740)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Blowing house north of Yealm Steps, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002628)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure on the west side of the Erme valley below Stalldown, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012767)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval settlement on Ford Waste, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002627)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The southern of three enclosures north of Ford Waste, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012700)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three unenclosed stone hut circles on the west side of the Erme Valley, north of Lower Piles, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012768)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Two hut circles on the south east slope of Stalldown, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012766)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Unenclosed stone hut settlement north east of Yadsworthy, Cornwood, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012771)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>A double stone hut circle and enclosure 280m south of Deadlake Foot, Dartmoor Forest, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1011569)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp 325yds (300m) south east of Archerton, Dartmoor Forest, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002636)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Coaxial fields, prehistoric settlement, two cairns and a stone alignment in Little Stannon Newtake, 900m south east of Stannon Tor, Dartmoor Forest, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021339)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut circle and field system north west of Saddle Bridge, Dartmoor Forest, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002601)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval settlement 470m east of Hartlyland, Dartmoor Forest, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021338)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Prehistoric enclosed settlement 740m north west of Hartland Tor, Dartmoor Forest, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021335)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two irregular aggregate field systems with associated settlements, part of a coaxial field system, boundary stones and historic fields on Riddon Ridge, Dartmoor Forest, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1018930)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure and hut circles east of Huntingdon Ford, Dean Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002536)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut circles and two enclosures on Dean Moor, near River Avon, Dean Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1003828)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prestonbury Castle (hillfort), Drewsteigton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1003861)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Chambered cairn 430m south of Buttern, Gidleigh, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021217)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Chambered cairn 830m south of Buttern, Gidleigh, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021216)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Coaxial field system, associated and later remains at Throwleigh Common and Kennon Hill, Gidleigh, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1018916)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Part of a coaxial field system, prehistoric settlements and cairns on Buttern Hill, Gidleigh, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021215)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone hut circle 380m north west of North Creaber, Gidleigh, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021220)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone hut circle and field system 580m north west of North Creaber, forming part of a coaxial field system on Buttern Hill, Gidleigh, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021219)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two stone hut circles and field system, 590m south of Buttern, forming part of a coaxial field system on Buttern Hill, Gidleigh, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021218)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Agglomerated enclosure with hut circles, south of Lower Piles, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1009578)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Blowing house at junction of Hook Lake and River Erme, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002605)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Blowing house north of Dry Lake, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002609)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairn in north east corner of Lower Piles, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1009575)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure and hut circles at Piles Corner, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1013108)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure with hut circles east of Addicombe, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1017609)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure with hut circles east of Addicombe, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012484)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure with hut circles in Higher Piles newtake, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1013110)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure with hut circles to the north east of Piles Copse, Harford, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1013106)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Hut circles and enclosure to south of Left Lake, Harford, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1004574)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circles in Erme Pound east of River Erme, Harford, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1002604)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone row, cairn and enclosures near Hook Lane, Erme Valley, Harford, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1002493)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Unenclosed stone hut settlement on the east side of the Erme Valley, north Harford Moor, Harford, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012747)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Unenclosed stone hut settlement with enclosures north of Piles Copse, Harford, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012765)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Eight cairns forming part of a cairn cemetery on Holne Ridge and a stone alignment immediately west of Horn's Cross, Holne, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1019273)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Enclosed prehistoric settlement and round cairn 880m south west of Venford Reservoir dam, Holne, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1020095)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Enclosed prehistoric settlement and three round cairns 870m south east of Horn's Cross, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020096)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four cairns 310m south of Horn's Cross forming part of a cairn cemetery on Holne Ridge, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019272)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four cairns on Holne Lee 1140m north west of Greatcombe, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019268)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Holne Chase Castle, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1003842)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval farmstead and field system, post-medieval tinworks, prehistoric settlements and cairns north and west of Gibby Coombe, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019591)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Part of the Dartmeet coaxial field system and other archaeological remains on Holne Moor west and north west of Venford Reservoir, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020487)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Partially enclosed stone hut circle settlement 350m south west of Horn's Cross, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019274)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Partially enclosed stone hut circle settlement 420m north west and 440m west of Horn's Cross, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020185)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Partially enclosed stone hut circle settlement 560m west of Horn's Cross, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019275)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Prehistoric fields and settlements north east of Venford Reservoir forming part of the Dartmeet coaxial field system, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020091)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Prehistoric fields, settlements and cairn south east of Venford Reservoir forming part of the Dartmeet coaxial field system, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020092)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Ringleshutes tinwork, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020098)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Stone hut circle and length of boundary walling 860m south west of Venford Reservoir dam, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020094)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Three stone hut circles 780m SSW of Venford Reservoir dam, Holne, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1020093)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Cairn 240m north of Crownley Parks, Ilsington, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1019588)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pound north east of Holwell Tor, Ilsington, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1002530)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Settlement on Smallacombe Rocks, Ilsington, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1002531)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Settlement west of Holwell Tor, Ilsington, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1002529)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two ring cairns 330m south east of Coldharbour Cross, Loddiswell, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014244)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle 530m ESE of Nodden Gate forming an outlying part of a stone hut circle settlement, Lydford, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1008639)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle 610m ESE of Nodden Gate forming an outlying part of a stone hut circle settlement, Lydford, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1008656)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Medieval strip field system, tinworks, part of a prehistoric settlement, a cairn and reave on Challacombe Down, Manaton, Teignbridge</b>	
DESIGNATION:	Scheduled Monument (No.1021393)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Medieval strip fields, tinworks, prehistoric settlements, and a cairn on the lower western slopes of Hamel Down, Manaton, Teignbridge</b>	
DESIGNATION:	Scheduled Monument (No.1021394)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Three hut circles at north end of Vogwell Down, Manaton, Teignbridge</b>	
DESIGNATION:	Scheduled Monument (No.1002595)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Four round barrows on Wigford Down, Meavy, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1002522)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Greenwell Girt socket stone 600m SSW of Lovaton hamlet, Meavy, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1008929)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Hut circle on Wigford Down, Meavy, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1002551)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Hut circles south east of Brisworthy, Meavy, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1004585)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Prehistoric enclosures on Dewerstone Hill, 500m south east of Dewerstone Cottage, Meavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1020241)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow north of Cadworthy Wood, Meavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1002552)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Settlement on Wigford Down south of Durance, Meavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1002523)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Settlement on Wigford Down, Meavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1002550)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three hut circles north west of Cadworthy, Meavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1003057)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three hut circles on south part of Wigford Down, Meavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1002549)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two hut circles south of Catstow Down, Meavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1002548)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Enclosure south west of Hingston Rocks, Moretonhampstead, Teignbridge</b>		
DESIGNATION:	Scheduled Monument (No.1002496)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wooston Castle, Moretonhampstead, Teignbridge</b>		
DESIGNATION:	Scheduled Monument (No.1003822)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four hut circles north of Bush Down, North Bovey, Teignbridge</b>		
DESIGNATION:	Scheduled Monument (No.1002646)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric settlement and field system 240m east of Challacombe Cross, North Bovey, Teignbridge</b>		
DESIGNATION:	Scheduled Monument (No.1020097)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two hut circles north west of Bush Down, North Bovey, Teignbridge</b>		
DESIGNATION:	Scheduled Monument (No.1003198)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairnfield 460m south east of Cox Tor, Peter Tavy, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1020005)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairnfield and two stone hut circles 490m and 550m south west of Cox Tor, Peter Tavy, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1020004)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Coaxial field system and prehistoric settlement 410m west of Cox Tor, Peter Tavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1020090)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Eluvial tin streamworks and prehistoric coaxial field system together with other archaeological remains on Whitchurch Common, Peter Tavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1020089)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric settlement 610m south west of Cox Tor, Peter Tavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1020002)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle and a short length of boundary wall forming part of an unenclosed stone hut circle settlement on the north east slope of Cox Tor, Peter Tavy, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1011432)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>A stone alignment, kerbed cairn, prehistoric settlement, four pillow mounds, a vermin trap and animal runs 720m south west of Great Trowlesworthy Tor, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1016147)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Agglomerated enclosure with hut circles south west of Ditsworthy Clam, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1009573)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>An enclosed settlement, length of reave, two vermin traps and a pillow mound 770m east of Trowlesworthy Warren House, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1015748)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>An unenclosed stone hut circle settlement 760m north east of Trowlesworthy Warren House, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1014656)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Barrow near Shaugh Cross, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1003824)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Cairn south of Mill Corner, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1013413)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Cairn with a cist east of Willings Walls Reave, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1012209)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Cairn with a cist, one of several on the western edge of Lee Moor, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1012051)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Cross Dyke reave, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1010811)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Double stone alignment with a terminal stone setting south of Great Trowlesworthy Tor, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1012114)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Eight pillow mounds and a vermin trap on the northern slope of Little Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1015758)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosed stone hut circle settlement and three round cairns on Giant's Hill, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019081)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure with hut circles west of Plym Steps, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012297)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hentor Warren boundary stone standing 200m south east of Hen Tor, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1015744)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut circles west of Saddlesborough, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002520)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval farmstead and field system, length of Willings Walls Reave, four round cairns, a ring cairn and pillow mounds at Willings Walls Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019083)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Multi-period remains at Hentor Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1019082)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012214)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>One of a number of cairns with cists south of Shavercombe Brook, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012172)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>One of three stone hut circles 500m SSE of Legis Tor, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012631)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pillow mound 100m south east of Great Trowlesworthy Tor, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014666)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pillow mound 160m south west of Great Trowlesworthy Tor, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014665)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pillow mound 270m south east of Ditsworthy Warren House forming part of Hentor Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014477)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pillow mound 530m ENE of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014462)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Pillow mound 610m SSW of Ditsworthy Warren House forming part of Willings Walls Warren, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1014469)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pillow mound 620m ESE of Legis Tor forming part of Willings Walls Warren, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1014457)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pillow mound 630m east of Legis Tor forming part of Willings Walls Warren, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1015742)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pillow mound 760m ENE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1014611)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pillow mound 790m NNE of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1014662)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pillow mound 840m north east of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1014658)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pillow mound 860m NNW of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>	
DESIGNATION:	Scheduled Monument (No.1014664)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Pillow mound 860m SSE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014616)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pillow mound and animal run 830m north east of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014657)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pound and hut circles north of Hawk's Tor, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1002516)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pounds and hut circles north of Saddlesborough, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1002517)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Rectangular building 420m north west of Hen Tor, forming an outlying part of Hentor Farm, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1020011)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn on Lee Moor 950m south east of Great Trowlesworthy Tor, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1015753)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle north east of Hentor Brook, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012175)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Stone hut circle north of Hentor Brook, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012083)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle settlement 600m ENE of Great Trowlesworthy Tor, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1018356)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three pillow mounds and a linear gully 200m north of Great Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014481)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two pillow mounds 640m ENE of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1015747)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two pillow mounds and a small area of tin streamwork 510m south west of Ditsworthy Warren House forming part of Willings Walls Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014467)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two pillow mounds and a small area of tin streamwork earthworks 770m north of Blackaton Cross, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1014663)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two round cairns 600m ENE of Great Trowlesworthy Tor, Shaugh Prior, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1018357)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Two stone hut circles and an enclosure 680m ENE of Trowlesworthy Warren House, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1014615)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two stone hut circles north of Spanish Lake, Lee Moor, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1013058)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Unenclosed stone hut circle settlement on the western edge of Lee Moor, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012116)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Vermin trap 350m south west of Great Trowlesworthy Tor forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1014475)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Vermin trap 520m SSW of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1014466)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Vermin trap 700m ENE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1014612)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Vermin trap 730m ENE of Trowlesworthy Warren House, forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1014613)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Vermin trap 800m south east of Trowlesworthy Warren House forming part of Trowlesworthy Warren, Shaugh Prior, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1014464)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Agglomerated enclosure with hut circles and later farmstead at Whittenknowles Rocks, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1010650)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairn east of Scout Hut, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1011993)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairn south west of Lower Hartor Tor, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1012293)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairn with a cist north of Drizzlecombe stone alignments, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1010654)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairn with cist north of Gutter Tor, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1012473)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1012251)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Enclosure north west of Gutter Tor, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1012032)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure with hut circles on Eastern Tor, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1010652)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure with hut circles south east of Eastern Tor, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1010651)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Part of Eylesbarrow Reave, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1011958)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Part of Eylesbarrow watershed reave, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1010669)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pillow mound 180m west of Legis Tor forming part of Legistor Warren, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1008714)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pillow mound 220m south west of Legis Tor forming part of Legistor Warren, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1008713)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Pillow mound 40m east of Legis Tor forming part of Legistor Warren, Sheepstor, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1008715)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric enclosed settlement 950m north east of Ditsworthy Warren House, Sheepstor, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1021058)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric settlement, three round cairns and a post-medieval rabbit warren at Legis Tor, Sheepstor, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1019876)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn east of Whittenknowles Rocks, 960m ENE of Gutter Tor, Sheepstor, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1021052)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three stone alignments, 15 cairns, a cist, a partially enclosed stone hut circle settlement and a small clapper bridge at Drizzle Combe, Sheepstor, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1014145)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two enclosures and a length of the Eylesbarrow watershed reave 800m WSW of Eylesbarrow, Sheepstor, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1013474)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Unenclosed stone hut settlement south west of Gutter Tor, Sheepstor, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1012239)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Vermin trap immediately south west of Legis Tor forming part of Legistor Warren, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1008716)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Warren at Sheeps Tor, 520m north of Chubstone Cottage, Sheepstor, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1021391)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Cist with a retaining kerb north west of Corringdon Ball, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1010180)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Enclosure and hut circle north of Old Hill, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1003200)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Enclosure with hut circles and rectangular pens, south of Bala Brook, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012775)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Enclosure with hut circles north of Bala Brook intake, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012776)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:	<b>Enclosure with hut circles north of Bala Brook intake, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012783)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Enclosures and hut circles at Petre's Pits Bottom, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1004557)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut circle and fields, Bishop's Mead, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002537)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hut enclosure north of Old Hill, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002664)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>One of several stone hut circles north of Corringdon Ball, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1010202)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Riders Rings (The Rings), South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002502)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three enclosed hut groups, Black Tor, Shipley Bridge, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1002505)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two conjoined huts between two enclosures north of Bala Brook intake, South Brent, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012778)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Two hut circles on the right bank of Red Brook, South Brent, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1013035)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>A prehistoric settlement complex, length of reave, tin streamwork and stamping mill on the western slopes of Cosdon Hill, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1015760)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>A warren, two stone hut circle settlements, cairnfields and cairns at Ivy Tor, ESE of Belstone, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1018925)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Agglomerate enclosure and 15 stone hut circles 560m west of Cawsand Beacon, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1010791)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Agglomerate enclosure and ten stone hut circles 500m west of Cawsand Beacon, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1010790)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>An agglomerated enclosed settlement 480m west of Stoneyhurst, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1017285)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Cairn cemetery and earthwork bank 340m south west of Blackaton Brook Ford, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1018906)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Cairnfield 760m west of Stoneyhurst, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1017287)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Partially enclosed stone hut circle settlement 650m south east of Tawcroft, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1015759)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two hut circles east of Foxes Holt, South Tawton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1002599)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Stone hut circle 140m north west of Higher Shilstone, Throwleigh, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1018917)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Chambered cairn in Cuckoo Ball newtake, Ugborough, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012284)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Enclosure with hut circles north of Scad Brook, Ugborough, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012485)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long cairn east of Butterdon Hill, Ugborough, South Hams</b>			
DESIGNATION:	Scheduled Monument (No.1012247)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Multiple stone alignment and associated cairns west of Glasscombe Upper Plantation, Ugborough, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1013031)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>One of a number of cairns at Black Pool, Ugborough, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012232)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>One of a number of cairns at Black Pool, Ugborough, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1012285)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone alignment and cairn south east of Western Beacon, Ugborough, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1017604)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>A length of the Great Western Reave, a prehistoric settlement, three cairns and two field systems on Walkhampton Common, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1019589)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>An agglomerate enclosure and seven stone hut circles 460m WSW of Raddick Hill summit, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1011171)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>An enclosed stone hut circle settlement and later tin working earthworks, 540m south east of Down Tor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1009088)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>An enclosure containing one stone hut circle 460m west of Cross Gate, Walkhampton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1009091)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>An enclosure, attached stone hut circle and length of reave 180m NNE of Leather Tor, Walkhampton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1011248)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>An enclosure, six stone hut circles, a length of reave and several prospecting pits 170m north east of Leather Tor, Walkhampton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1011247)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>An unenclosed stone hut circle settlement, an irregular aggregate field system, a length of reave and an enclosure on the south east slope of Leeden Tor, Walkhampton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1008671)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Cairn 550m south west of Raddick Hill summit forming part of a cairnfield, Walkhampton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1007416)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Cairn 560m south west of Raddick Hill summit forming part of a cairnfield, Walkhampton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1007415)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Eight stone hut circles and two enclosures forming part of an unenclosed settlement 580m south of Leeden Tor, Walkhampton, West Devon</b>			
DESIGNATION:	Scheduled Monument (No.1008661)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Eleven stone hut circles, a length of boundary wall and a field system forming part of an unenclosed settlement on the north east slope of Sharpitor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1007435)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosed settlement 380m south west of Raddick Hill summit, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1011173)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosed settlement 400m west of Raddick Hill summit, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1011172)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure and stone hut circle 320m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1007434)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure and stone hut circle 700m west of Sharpitor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1019590)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four stone hut circles and an enclosure 100m north east of Sharpitor summit, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1007419)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval settlement on Peek Hill, 240m and 280m north east of Lowery Tor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1020237)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Prehistoric coaxial field system and cairns, an historic enclosure and part of RAF Sharpitor, situated on and around Peek Hill, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1020238)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 340m ESE of Norsworthy Bridge, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1008651)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round cairn 650m WSW of Raddick Hill summit, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1007424)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Routrundle Pound, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002494)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone alignment, two round cairns and a length of Walkhampton Common reave lying in a valley between Sharpitor and Leeden Tor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1007433)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone hut circle 155m east of Sharpitor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1007421)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stone hut circle 240m south of Down Tor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1008641)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Stone hut circle 315m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1007436)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Stone hut circle 350m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1007437)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Stone hut circle 370m north east of Sharpitor forming part of a stone hut circle settlement, Walkhampton, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1007438)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Stone hut circle settlement 250m east of Cuckoo Rock, Walkhampton, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1021057)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Stone hut circle settlement, irregular aggregate field system, two long houses and a medieval and post-medieval field system 700m SSW of Black Tor, Walkhampton, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1011170)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Tinworks and other archaeological remains in the Meavy valley at Stanlake, Black Tor, Hart Tor and Cramber Tor, Walkhampton, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1020129)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Twelve cairns, a lynchet and a boundary bank forming part of a cairnfield 440m south west of Raddick Hill summit, Walkhampton, West Devon</b>	
DESIGNATION:	Scheduled Monument (No.1007425)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Two cairns and a boundary bank forming part of a cairnfield 440m south west of Raddick Hill summit, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1007426)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two stone hut circles 570m south west of Down Tor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1019572)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two stone hut circles, a reave, round cairn and shelter south east of Sharpitor, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1011167)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Unenclosed stone hut circle settlement 370m south west of Routrundle, Walkhampton, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1019565)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hembury Castle, West Buckfastleigh, South Hams</b>		
DESIGNATION:	Scheduled Monument (No.1003859)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure and stone hut circle 770m south of Cox Tor, Whitchurch, West Devon</b>		
DESIGNATION:	Scheduled Monument (No.1020006)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Deserted medieval settlement at Blackaton, 340m and 400m north east of Lower Blackaton, Widcombe-in-the-Moor, Teignbridge</b>		
DESIGNATION:	Scheduled Monument (No.1021396)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Enclosure and fields north of Yar Tor, Widecombe-in-the-Moor, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1003292)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Foale's Arrishes, huts and fields, Blackslade Down, Widecombe-in-the-Moor, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1003283)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut 700yds (640m) north west of Sharp Tor, Widecombe-in-the-Moor, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1003280)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circles east of Pritton, Widecombe-in-the-Moor, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1004575)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circles east of Southway, Widecombe-in-the-Moor, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1002621)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circles on Bonehill Down, Widecombe-in-the-Moor, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1002619)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circles on Hedge Down, Widecombe-in-the-Moor, Teignbridge</b>			
DESIGNATION:	Scheduled Monument (No.1002620)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Hut circles south east of Yar Tor, Widecombe-in-the-Moor, Teignbridge</b>	
DESIGNATION: Scheduled Monument (No.1003291)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: Plant growth	TREND: Declining
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Pound at Newbridge, Widecombe-in-the-Moor, Teignbridge</b>	
DESIGNATION: Scheduled Monument (No.1003295)	CONDITION: Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY: Plant growth	TREND: Stable
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two cairns on Cator Common, Widecombe-in-the-Moor, Teignbridge</b>	
DESIGNATION: Scheduled Monument (No.1003297)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY: Plant growth	TREND: Declining
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Yar Tor stone row and adjacent cist, Widecombe-in-the-Moor, Teignbridge</b>	
DESIGNATION: Scheduled Monument (No.1003288)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: Plant growth	TREND: Declining
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Horrabridge</b>	
DESIGNATION: Conservation Area	CONDITION: Poor
VULNERABILITY: Medium	TREND: Deteriorating
CONTACT: Keith McKay (LPA) 01626 832093	NEW ENTRY: No

## EAST DEVON



SITE NAME: **Dunkeswell Abbey, Dunkeswell**

DESIGNATION: Scheduled Monument

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Trust

Remains of Gatehouse. There is cracking to elevations and failure of mortar pointing. Remains of west range also showing cracking, mortar failure and instability. English Heritage is monitoring both the gatehouse and west range, and have offered a grant to the Trust which owns it.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Poltimore House, Poltimore**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Trust

Cl6 country house with later additions. Acquired by a trust with funding from English Heritage and the Local Planning Authority in 1997. Urgent works carried out in 1998 to make the building wind/weathertight. Emergency roof cover erected 2006. A feasibility study was undertaken with grant from Architectural Heritage Fund and English Heritage.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Tithe barn and stable block at Bishop's Court, Clyst St Mary, Sowton**

DESIGNATION: Listed Building Grade I

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Large mid C14 barn with arch-braced base-cruck roof of seven bays, and long early C16 range of stables. Currently unused and with a temporary corrugated roof. The owners undertook an English Heritage grant-aided feasibility study into potential uses, completed 2011.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Hembury Fort, Awliscombe**

DESIGNATION: Scheduled Monument (No.1018850)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Newenham Abbey, Axminster**

DESIGNATION: Scheduled Monument (No.1011671)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Deterioration – in need of management

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Hawkesdown Camp and associated outwork, Axmouth**

DESIGNATION: Scheduled Monument (No.1017775)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Forestry

TREND: Stable

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Bowl barrow 400m north east of Common Farm, Aylesbeare**

DESIGNATION: Scheduled Monument (No.1017770)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Bowl barrow 130m south east of St Mary's Church, Bicton**

DESIGNATION: Scheduled Monument (No.1018056)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Two bowl barrows on Woodbury Common, 640m and 625m east of Four Firs, Bicton**

DESIGNATION: Scheduled Monument (No.1018051)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub/tree growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Bowl barrow 210m north east of Starved Oak Cross, Brampford Speke</b>			
DESIGNATION:	Scheduled Monument (No.I010633)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 320m north east of Starved Oak Cross, Brampford Speke</b>			
DESIGNATION:	Scheduled Monument (No.I010632)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow in Long Plantation, 610m north east of Starved Oak Cross, Brampford Speke</b>			
DESIGNATION:	Scheduled Monument (No.I010636)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow in Long Plantation, 680m north east of Starved Oak Cross, Brampford Speke</b>			
DESIGNATION:	Scheduled Monument (No.I010634)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Berry Cliff Camp, Branscombe</b>			
DESIGNATION:	Scheduled Monument (No.I017772)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Cross ridge dyke extending north and south of The Three Horse Shoes Inn, Branscombe</b>			
DESIGNATION:	Scheduled Monument (No.I017771)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric field system on the cliffs above Littlecombe Shoot, Branscombe</b>			
DESIGNATION:	Scheduled Monument (No.I020710)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Dolbury hillfort, 320m north of Killerton House, Broad Clyst</b>			
DESIGNATION:	Scheduled Monument (No.I017192)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Ice house 210m north west of Killerton House, Broad Clyst</b>			
DESIGNATION:	Scheduled Monument (No.1017191)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Sections of two deer park pales and a deer park pond at Killerton Park, Broad Clyst</b>			
DESIGNATION:	Scheduled Monument (No.1017193)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows at Big Wood, 580m south west and 470m south of Moorland Cottage, Exmouth</b>			
DESIGNATION:	Scheduled Monument (No.1017949)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 20m north east of the B3174, forming part of a round barrow cemetery on Farway Hill, Farway</b>			
DESIGNATION:	Scheduled Monument (No.1010278)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 320m north west of Farway Castle, forming part of a dispersed barrow group on Farway Hill, Farway</b>			
DESIGNATION:	Scheduled Monument (No.1010267)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 340m north west of Farway Castle, forming part of a dispersed barrow group on Farway Hill, Farway</b>			
DESIGNATION:	Scheduled Monument (No.1010268)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>A bowl barrow 370m WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>			
DESIGNATION:	Scheduled Monument (No.1014249)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>A bowl barrow 420m NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>	
DESIGNATION:	Scheduled Monument (No.1014247)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>A bowl barrow 460m NNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>	
DESIGNATION:	Scheduled Monument (No.1014248)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>A bowl barrow 500m WNW of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>	
DESIGNATION:	Scheduled Monument (No.1014250)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>A bowl barrow 570m NNE of Putts Corner, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>	
DESIGNATION:	Scheduled Monument (No.1014254)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>A cairn 450m WNW of Putts Corner, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>	
DESIGNATION:	Scheduled Monument (No.1014255)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>A ring cairn and bowl barrow 540m NNE of Putts Corner, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>	
DESIGNATION:	Scheduled Monument (No.1014253)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>An enclosure and two bowl barrows 180m east of Putts Corner, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>	
DESIGNATION:	Scheduled Monument (No.1014252)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Two bowl barrows, 220m ESE of Putts Corner, forming part of a round barrow cemetery on Gittisham Hill, Gittisham</b>		
DESIGNATION:	Scheduled Monument (No.1014251)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Dumpdon Camp, Luppitt</b>		
DESIGNATION:	Scheduled Monument (No.1018851)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows on Lypstone Common, 500m west of Fryingpans, Lypstone</b>		
DESIGNATION:	Scheduled Monument (No.1020014)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Membury Castle, Membury</b>		
DESIGNATION:	Scheduled Monument (No.1017951)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Musbury Castle, Musbury</b>		
DESIGNATION:	Scheduled Monument (No.1016793)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cursus, long mortuary enclosure, ring ditch and other associated cropmarks 700m east of Netherexe Barton, Nether Exe</b>		
DESIGNATION:	Scheduled Monument (No.1014144)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows north of Green Lane, 430m and 330m west of Rewe Cross, Nether Exe</b>		
DESIGNATION:	Scheduled Monument (No.1016565)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow cemetery on Venn Ottery Hill, 660m south east of Happy Valley, Newton Popleford and Harpford</b>		
DESIGNATION:	Scheduled Monument (No.1017476)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>High Peak camp, Sidmouth, Otterton</b>		
DESIGNATION:	Scheduled Monument (No.1003887)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Belbury Castle, Ottery St Mary</b>		
DESIGNATION:	Scheduled Monument (No.1017774)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow in Lee's Plantation, East Hill, 560m east of Higher Rill Farm, Ottery St Mary</b>		
DESIGNATION:	Scheduled Monument (No.1017773)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Promontory fort on Seaton Down, Seaton</b>		
DESIGNATION:	Scheduled Monument (No.1017776)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Beacon on Shute Hill, 200m north east of Rowlands, Shute</b>		
DESIGNATION:	Scheduled Monument (No.1020312)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>A bowl barrow 120m south west of Ring-in-the-Mire, forming part of a round barrow cemetery on Gittisham Hill, Sidmouth</b>		
DESIGNATION:	Scheduled Monument (No.1014246)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows to the north west of Roncombe Gate Farm, forming part of a dispersed barrow group on Farway Hill, Sidmouth</b>		
DESIGNATION:	Scheduled Monument (No.1010271)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Stockland Great Castle, Stockland</b>		
DESIGNATION:	Scheduled Monument (No.1017952)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 470m east of Fortescue, Stoke Canon</b>		
DESIGNATION:	Scheduled Monument (No.1016564)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roman villa 300yds (270m) SSW of Holcombe Farm, Uplyme</b>		
DESIGNATION:	Scheduled Monument (No.1002558)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Trinity Beacon, Uplyme</b>		
DESIGNATION:	Scheduled Monument (No.1017950)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 280m NNE of Starved Oak Cross, Upton Pyne</b>		
DESIGNATION:	Scheduled Monument (No.1010638)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 300m SSE of Stevenstone Farm, Upton Pyne</b>		
DESIGNATION:	Scheduled Monument (No.1015973)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 350m NNE of Starved Oak Cross, Upton Pyne</b>		
DESIGNATION:	Scheduled Monument (No.1010639)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 450m SSE of Stevenstone Farm, Upton Pyne</b>		
DESIGNATION:	Scheduled Monument (No.1015974)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Earthwork enclosure 330yds (300m) south west of Three Horse Shoes Inn, Upton Pyne</b>		
DESIGNATION:	Scheduled Monument (No.1002645)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows, 350m south of Stevenstone Farm, Upton Pyne</b>		
DESIGNATION:	Scheduled Monument (No.1010631)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 310m south of Widworthy Barton, Widworthy</b>		
DESIGNATION:	Scheduled Monument (No.1017475)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Castle Hill, Widworthy</b>		
DESIGNATION:	Scheduled Monument (No.1017477)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four bowl barrows at Four Firs on Woodbury Common, Woodbury</b>		
DESIGNATION:	Scheduled Monument (No.1018052)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows on Colaton Raleigh Common, 500m north and 780m north east of Woodbury Castle, Woodbury</b>		
DESIGNATION:	Scheduled Monument (No.1018053)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows on Woodbury Common, both 330m east of Four Firs, Woodbury</b>		
DESIGNATION:	Scheduled Monument (No.1018050)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Albion Street/Windsor Square, Exmouth</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Stephen Guy (LPA) 01395 516551	NEW ENTRY?:	Yes

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Ottery St Mary</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Improving
CONTACT:	Stephen Guy (LPA) 01395 516551	NEW ENTRY?:	Yes

SITE NAME:	<b>Seaton</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Stephen Guy (LPA) 01395 516551	NEW ENTRY?:	Yes

## EXETER



SITE NAME: **The Devon and Exeter Institution,  
7 The Close,  
Exeter**

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Very bad

OCCUPANCY: Occupied

PRIORITY: A (New entry)

OWNER TYPE: Charity

CI5 Cannon's House, leased as town house from 1672. In 1813 the lease was given to the Devon and Exeter Institution who carried out extensive rebuilding. Since 2009 there has been on-going cracking to plaster ceilings in the two library ceiling roofs. Investigation has led to major structural deficiencies being revealed and ceilings being scaffolded. Structural repair urgently required. EH grant applied for:

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Church of St David,  
St David's Hill,  
Exeter**

DESIGNATION: Listed Place of Worship Grade I

CONDITION: Poor

PRIORITY: A (New entry)

OWNER TYPE: Religious organisation

This highly distinctive church is designed by a leading church architect, WD Caröe (1897-9) and is in a freely-treated Gothic style. There have been longstanding issues with the west end of the church, which is moving but has been secured with scaffolding to prevent further cracking. English Heritage has given specialist advice and is working with the church architect and engineer on possible solutions. The PCC are likely to apply for a Repair Grant for Places of Worship grant for the works.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Danes Castle, Exeter</b>		
DESIGNATION:	Scheduled Monument (No.1011673)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Unknown
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Alphin Brook, Exeter</b>		
DESIGNATION:	Conservation Area	CONDITION:	Optimal
VULNERABILITY:	Low	TREND:	Deteriorating significantly
CONTACT:	Katharine Metcalfe (LPA) 01392 265227	NEW ENTRY?:	No

SITE NAME:	<b>St David's, Exeter</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Katharine Metcalfe (LPA) 01392 265227	NEW ENTRY?:	No

SITE NAME:	<b>St Sidwells, Exeter</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Katharine Metcalfe (LPA) 01392 265227	NEW ENTRY?:	No

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

## EXMOOR (NP)



SITE NAME: **Church of St Thomas,  
Kentisbury,  
North Devon**

CI5/CI6 church with major CI9 interventions. Delabole slates to north nave, north aisle, chancel/vestry and south porch have joining fixings and all need to be re-roofed. A Repair Grant for Places of Worship was offered for repairs. Works due to start 2012.

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Very bad

PRIORITY: F (B)

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Christ Church,  
Parracombe,  
North Devon**

Church built 1878 by W Oliver. Roofs are well maintained but areas of weakness are developing and the roof is beginning to need some major work to address this. The tower is also in need of repair; particularly the south and west faces which are exposed to prevailing weather, strong winds and high rainfall. A Repair Grant for Places of Worship has been offered for roof repairs to north aisle, vestry and nave, as well as emergency works to tower:

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: Poor

PRIORITY: B (B)

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Doone's Houses, Brendon, North Devon**

DESIGNATION: Scheduled Monument (No.1003886)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Two round barrows on Cheriton Ridge, Brendon, North Devon**

DESIGNATION: Scheduled Monument (No.1002583)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Five barrows and an enclosure on Challacombe Common, Challacombe, North Devon**

DESIGNATION: Scheduled Monument (No.1002634)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Round barrow on East Anstey Common, East Anstey, North Devon**

DESIGNATION: Scheduled Monument (No.1002569)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Earthwork defences of Countisbury Castle promontory fort, Lynton and Lynmouth, North Devon**

DESIGNATION: Scheduled Monument (No.1020807)

CONDITION: Generally satisfactory  
but with significant localised problems

PRINCIPAL VULNERABILITY: Plant growth

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

- CA** Conservation Area  
**LB** Listed Building  
**LPA** Local Planning Authority  
**NP** National Park  
**RPG** Registered Park and Garden  
**SM** Scheduled Monument  
**UA** Unitary Authority  
**WHS** World Heritage Site

SITE NAME:	<b>Roborough Castle, Lynton and Lynmouth, North Devon</b>		
DESIGNATION:	Scheduled Monument (No.1003281)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited natural erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow south east of Down Linhay, Lynton and Lynmouth, North Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002545)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two round barrows and cairn cemetery, Ikkerton Ridge, Lynton and Lynmouth, North Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002566)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two round barrows near Warcombe Water, Lynton and Lynmouth, North Devon</b>		
DESIGNATION:	Scheduled Monument (No.1003299)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Beacon Castle, South Down, Martinhoe, North Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002540)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Voley Castle, Parracombe, North Devon</b>		
DESIGNATION:	Scheduled Monument (No.1003885)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Trentishoe barrows, round cairns, Trentishoe, North Devon</b>		
DESIGNATION:	Scheduled Monument (No.1002556)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

## MID DEVON



SITE NAME: **The Walronds,  
6 Fore Street,  
Cullompton**

DESIGNATION: Listed Building Grade I, CA

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNER TYPE: Trust

A large early C17 mansion in the centre of Cullompton. The owner, Cullompton Walronds Preservation Trust, has obtained Stage I Heritage Lottery Fund funding and grant aid for project development was provided by English Heritage and the Local Authority. Emergency repairs have been undertaken. The building is now scaffolded and works will start on full repair 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Prescott Baptist Chapel,  
Culmstock**

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Poor

PRIORITY: C (C)

OWNER TYPE: Religious organisation

This simple, unspoilt C18 church is in an isolated rural location with two other Baptist Churches within a five mile radius and closer to centres of population. Its physical problems are putting historic fabric at risk in respect of windows and could rapidly escalate into more serious repair problems if not remedied.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Roman fort 300m north east of Cudmore Farm, Bampton**

DESIGNATION: Scheduled Monument (No.1011251)

CONDITION: Unknown

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 140m south east of Burston Cross, Bow**

DESIGNATION: Scheduled Monument (No.1015471)

CONDITION: Unknown

PRINCIPAL VULNERABILITY: Moderate stock erosion

TREND: Unknown

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 220m south west of Hampson Cottage, Bow**

DESIGNATION: Scheduled Monument (No.1015474)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 80m south west of Hampson Cottage, Bow**

DESIGNATION: Scheduled Monument (No.1016189)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Ring ditch 150m north of Natson Farm, Bow**

DESIGNATION: Scheduled Monument (No.1015477)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Two bowl barrows 180m south west of Hampson Cottage, Bow**

DESIGNATION: Scheduled Monument (No.1015475)

CONDITION: Unknown

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Unknown

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	<b>Two bowl barrows 250m north of Natson Farm, Bow</b>		
DESIGNATION:	Scheduled Monument (No.1015476)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Canonsleigh Abbey, Bursescombe</b>		
DESIGNATION:	Scheduled Monument (No.1003830)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Copplestone Cross, CREDITON Hamlets</b>		
DESIGNATION:	Scheduled Monument (No.1013728)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Posbury camp, Castle Down, CREDITON Hamlets</b>		
DESIGNATION:	Scheduled Monument (No.1003826)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Romano-British villa, Downes, near CREDITON, CREDITON Hamlets</b>		
DESIGNATION:	Scheduled Monument (No.1002668)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two Roman forts and two Roman camps at St Andrew's Hill, Cullompton</b>		
DESIGNATION:	Scheduled Monument (No.1019543)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Raddon Hill: a Neolithic causewayed enclosure and later hillfort, Shobrooke</b>		
DESIGNATION:	Scheduled Monument (No.1016259)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows 250m south east of Gibbet Moor Cross, Templeton</b>		
DESIGNATION:	Scheduled Monument (No.1017134)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 260m north west of Putson Cross, Tiverton</b>		
DESIGNATION:	Scheduled Monument (No.1017132)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Eggesford Castle, 640m north east of Eggesford House, Wembworthy</b>		
DESIGNATION:	Scheduled Monument (No.1016208)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 130m north east of Burston Cross, Zeal Monachorum</b>		
DESIGNATION:	Scheduled Monument (No.1015152)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bow</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sue Warren (LPA) 01884 234 264	NEW ENTRY:	No

SITE NAME:	<b>Cullompton</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Sue Warren (LPA) 01884 234 264	NEW ENTRY:	No

SITE NAME:	<b>Tiverton</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sue Warren (LPA) 01884 234 264	NEW ENTRY:	No

## NORTH DEVON



SITE NAME: **Hall House,  
Bishops Tawton**

Built circa 1846-50 by Philip Hardwick, with a rear range by RD Gould. The house lies within an estate containing several other listed structures within the vicinity. The main range is generally fair, but the rear range is in very poor condition, though roof is now weathertight.

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Trust

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Broomham Farmhouse,  
Kings Nympton**

Early C16 Longhouse with later additions. The roof has been re-thatched with English Heritage grant aid. Some recent improvements have permitted the family to return to the house, but further structural work still required.

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Two bowl barrows 170m west and 200m south west of Berry Down Cross, forming part of a round barrow cemetery on Berry Down, Berrynarbor</b>		
DESIGNATION:	Scheduled Monument (No.1019261)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow cemetery 210m south west of Hillcrest, Centery Lane, Bittadon</b>		
DESIGNATION:	Scheduled Monument (No.1019252)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows 170m and 270m east of Friendship Farm, Bratton Fleming</b>		
DESIGNATION:	Scheduled Monument (No.1017130)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 280m north east of Beacon Moor Cross, forming part of a round barrow cemetery, Chulmleigh</b>		
DESIGNATION:	Scheduled Monument (No.1015153)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 330m east of Beacon Moor Cross, forming part of a round barrow cemetery, Chulmleigh</b>		
DESIGNATION:	Scheduled Monument (No.1015154)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp in East Kidland Wood, Knowstone</b>		
DESIGNATION:	Scheduled Monument (No.1004588)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four bowl barrows 560m south east of New Moor Cross, Knowstone</b>		
DESIGNATION:	Scheduled Monument (No.1017135)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Castle Roborough, Loxhore</b>		
DESIGNATION:	Scheduled Monument (No.1002543)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Bowl barrow 320m east of New Moor Cross, Molland</b>		
DESIGNATION:	Scheduled Monument (No.1017136)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hillfort 400m north west of Woodhouse, Queen's Nympton</b>		
DESIGNATION:	Scheduled Monument (No.1015463)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows 100m east of Catkill Cross, Rose Ash</b>		
DESIGNATION:	Scheduled Monument (No.1015145)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp south of Birch Ham Wood, Stoke Rivers</b>		
DESIGNATION:	Scheduled Monument (No.1002533)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 300m north west of Witheridge Moor Cross (west), Witheridge</b>		
DESIGNATION:	Scheduled Monument (No.1016652)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 610m south east of Elworthy Cross, Witheridge</b>		
DESIGNATION:	Scheduled Monument (No.1016651)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Ilfracombe</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	James Bate (LPA) 01271 388 352	NEW ENTRY:	No

## SOUTH HAMS



SITE NAME:	<b>Deer Park wall at Berry Pomeroy Castle, Berry Pomeroy</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Medieval deer park wall, extended in the C16. Neglected, heavily overgrown with ivy and partially collapsed in places, particularly in the woods where it has no use as a boundary. The Estate has prepared a condition survey in order to understand and monitor mechanisms of decay and to prioritise repairs, some of which will qualify for agri-environment grant aid.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Warleigh House, Tamerton Foliot, Bickleigh</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Company

Medieval site. The present C16 house incorporates late medieval roof structures and was remodelled in the mid C18 and again, importantly, by John Foulston of Plymouth from 1825-31. For sale. Urgent Works Notice outstanding and conditional listed building consent agreed for reinstatement of significant features.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Yarde Farmhouse, Malborough</b>
DESIGNATION:	Listed Building Grade I
CONDITION:	Fair
OCCUPANCY:	Part occupied
PRIORITY:	F (F)
OWNER TYPE:	Private

Late C16 evolved manor house. The house, its detached kitchen and also the early C18 chamber block are now wind and weathertight externally. The greatest area of uncertainty remains the interior of the lodging range and the important painted hangings whose conservation and future display are not resolved.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Pridhamsleigh Farmhouse, Ashburton, Staverton</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Private

C16 and C17 Farmhouse. Subdivided into Pridhamsleigh Manor and Pridhamsleigh Farmhouse. Farmhouse only is at risk. Part of the Farmhouse has suffered collapse. At risk from exposure and neglect. Listed building consent granted for repairs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>39 The High Street, Totnes</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Private

Fine C17 plasterwork and interior threatened by poor condition of roof and opening up of floor on the second floor. Ground floor is a shop. Upper floors are unoccupied and in need of repair and new services. Owner has discussed proposals for repair and alteration with the Local Planning Authority and English Heritage.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Garden wall, steps and gatepiers south of Langdon Court Hotel, Langdon, Wembury</b>
DESIGNATION:	Listed Building Grade II*, RPG II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Late C17 to early C18 formal terraced garden, the layout little altered since the early C18. Terraces extend south from the house on rising ground, with central axial path and connecting steps. Enclosed by walls to the east, south and west. The northern (larger) terrace has C17 gate piers and gates in the east and west walls and a central pool. The present owner has instigated a programme of repair.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Pair of garden houses south of Langdon Court Hotel, Langdon, Wembury</b>
DESIGNATION:	Listed Building Grade II*, RPG II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Early C18 gazebos standing at the junction of the northern and southern terraces in the late C17 to early C18 formal terraced garden to the south of the house. The walls, steps and gate piers of the terraced garden are also at risk. Recently reroofed but derelict. Negotiations are underway to restore them as annexes of the hotel.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Hilltop enclosure known as Maristow Camp, 240m east of Middle Park House, Bickleigh</b>			
DESIGNATION:	Scheduled Monument (No.1019784)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long barrow and two bowl barrows, 200m south east of Chapelcombe, Bigbury</b>			
DESIGNATION:	Scheduled Monument (No.1019239)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Iron Age hillfort known as Wasteberry Camp, medieval deer park and post-medieval warren, 800m north west of Lyneham House, Brixton</b>			
DESIGNATION:	Scheduled Monument (No.1020160)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two round barrows on Ridding Down, Cornwood</b>			
DESIGNATION:	Scheduled Monument (No.1002586)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Levelling	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Deer park north and north west of Dartington Hall, Dartington</b>			
DESIGNATION:	Scheduled Monument (No.1020870)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hilltop enclosure and woodbanks in Chacegrove Wood, 540m north west of Dartington Hall, Dartington</b>			
DESIGNATION:	Scheduled Monument (No.1020553)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hilltop enclosures in North Wood, 780m NNW of Old Parsonage Farm, Dartington</b>			
DESIGNATION:	Scheduled Monument (No.1020381)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Four bowl barrows at Bickleigh Brake 540m south west of Bickleigh, forming part of a linear round barrow cemetery, Halwell and Moreleigh</b>		
DESIGNATION:	Scheduled Monument (No.1019238)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hillfort and two bowl barrows at Halwell Camp, Halwell and Moreleigh</b>		
DESIGNATION:	Scheduled Monument (No.1019237)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval churchyard cross, 6m south east of the porch of St Andrew's Church, Harberton</b>		
DESIGNATION:	Scheduled Monument (No.1019234)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 470m south of Borough Farm, Holbeton</b>		
DESIGNATION:	Scheduled Monument (No.1019316)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows 140m west of Borough Farm, Holbeton</b>		
DESIGNATION:	Scheduled Monument (No.1019317)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>D-Day landing craft maintenance site on the River Dart immediately to the south of Lower Noss Point, Kingswear</b>		
DESIGNATION:	Scheduled Monument (No.1021076)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Gomerock Tower, Kingswear</b>		
DESIGNATION:	Scheduled Monument (No.1003852)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

<b>SITE NAME: Coaxial field system, hut circles and medieval farm buildings at Starehole Bottom, Malborough</b>			
DESIGNATION:	Scheduled Monument (No.1020577)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Field systems, hut circles and four beacons, 510m south of Middle Soar, Malborough</b>			
DESIGNATION:	Scheduled Monument (No.1020574)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Hilltop enclosure 380m east of Middle Soar, Malborough</b>			
DESIGNATION:	Scheduled Monument (No.1019533)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Medieval farmstead, boundary work and earthwork enclosures 350m south east of Middle Soar, Malborough</b>			
DESIGNATION:	Scheduled Monument (No.1020575)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Two hut circles and associated field systems and enclosure at Mousehill Brake, Malborough</b>			
DESIGNATION:	Scheduled Monument (No.1020573)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Two bowl barrows at Beacon Hill, 120m south of The Beacon, Marlton</b>			
DESIGNATION:	Scheduled Monument (No.1020164)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Two prehistoric hilltop enclosures, a ditch system and four bowl barrows, 300m north of Barton Pines Inn, Marlton</b>			
DESIGNATION:	Scheduled Monument (No.1020162)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Iron Age promontory fort known as Oldaport Camp, Modbury</b>			
DESIGNATION:	Scheduled Monument (No.1020234)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Fort Charles, Salcombe</b>			
DESIGNATION:	Scheduled Monument (No.1020165)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Barrow cemetery on western slope of Crownhill Down, Shaugh Prior</b>			
DESIGNATION:	Scheduled Monument (No.1003201)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Deer park and rabbit warren at Newnham Park, Sparkwell</b>			
DESIGNATION:	Scheduled Monument (No.1020169)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circle 1000yds (915m) east of Coleland Bridge, Sparkwell</b>			
DESIGNATION:	Scheduled Monument (No.1002596)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Post-medieval deer park, medieval fishpond, 18th century triumphal arch and a 19th century lead mine, ore works and smelt mill at Boringdon Park, Sparkwell</b>			
DESIGNATION:	Scheduled Monument (No.1020565)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Woodbury Camp, Stoke Fleming</b>			
DESIGNATION:	Scheduled Monument (No.1019783)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hillfort known as Slapton Castle, Stokenham</b>			
DESIGNATION:	Scheduled Monument (No.1019236)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Roman settlement site at Bantham Ham, Thurlestone</b>		
DESIGNATION:	Scheduled Monument (No.1019322)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hilltop enclosure at Yellowberries Copse, 430m west of Higher Turtley, Ugborough</b>		
DESIGNATION:	Scheduled Monument (No.1019325)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Fort Bovisand, Wembury</b>		
DESIGNATION:	Scheduled Monument (No.1002584)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Watch House battery and ditch, Wembury</b>		
DESIGNATION:	Scheduled Monument (No.1002585)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Subsidence	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>World War II Heavy Anti-aircraft gunsite, 100m west of Princes Cottages, Wembury</b>		
DESIGNATION:	Scheduled Monument (No.1021147)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## TEIGNBRIDGE



SITE NAME: **Former stables to Stover House, Stover, Kingsteignton**

DESIGNATION: Listed Building Grade II\*, RPG II

CONDITION: Very bad


OCCUPANCY: Vacant

PRIORITY: C (New entry)

OWNER TYPE: Company

Built as stables, 1779. The stables were stripped out when they were superseded by a new larger stable block in 1843 and converted to a magnificent backdrop to newly laid out gardens for the 11th Duke of Somerset. It is a key feature of the Stover's grade II designed landscape. Now in very bad condition due to spread and distortion of single ashlar front, rusting cramps, and water and vegetation damage.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **The Belvedere, Powderham**

DESIGNATION: Listed Building Grade II\*, RPG II\*

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Gothick Belvedere, 1771-1774, situated 600m north west of Powderham Castle on the north east fringe of Powderham Old Plantation within the CI8 park. Damaged by fire after the war and now a roofless shell. English Heritage grant has been offered towards repairs and a first phase of repairs has been completed. With no prospect of a further phase being funded in the immediate future, the building remains at risk.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **St Michael the Archangel,  
Den Promenade,  
Teignmouth**

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: Poor

PRIORITY: F (B)

OWNER TYPE: Religious organisation

Multi-phase Norman style church. Current Repair Grant for Places of Worship for repairs to valley gutters which have been leaking for several years. Roof covering replaced in recent past with concrete tiles and there is concern as to increased load this has applied to the roof structure. This will be assessed as part of the grant. Stonework tracery of windows is deteriorating. Cracking of ceilings internally is extensive and may indicate expansion of structural timbers as a result of water ingress and decay. Repair works to the valley gutters and associated works are ongoing.  
Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Earthwork (possibly civil war) on Bovey Heath, Bovey Tracey**

DESIGNATION: Scheduled Monument (No.1002657)

CONDITION: Generally satisfactory  
but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive vehicle damage/erosion

TREND: Declining

OWNER TYPE: Local authority

CONTACT: Principal Heritage at Risk Adviser  
0117 975 0700

SITE NAME: **Bishop's Palace, Chudleigh**

DESIGNATION: Scheduled Monument (No.1008679)

CONDITION: Generally satisfactory  
but with significant localised problems

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
0117 975 0700

SITE NAME: **Cow Cave, Chudleigh Rocks, Chudleigh**

DESIGNATION: Scheduled Monument (No.1010726)

CONDITION: Generally satisfactory  
but with significant localised problems

PRINCIPAL VULNERABILITY: Vandalism

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
0117 975 0700

SITE NAME: **Milber Down camp, Coffinswell**

DESIGNATION: Scheduled Monument (No.1003178)

CONDITION: Generally satisfactory  
but with significant localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
0117 975 0700

SITE NAME: **Cotley Castle, Dunsford**

DESIGNATION: Scheduled Monument (No.1003180)

CONDITION: Generally unsatisfactory  
with major localised problems

PRINCIPAL VULNERABILITY: Forestry

TREND: Improving

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
0117 975 0700

SITE NAME: **Earthwork enclosure south of Blackall's Copse, Exminster**

DESIGNATION: Scheduled Monument (No.1004579)

CONDITION: Generally unsatisfactory  
with major localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
0117 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Linear round barrow cemetery at Castle Park, Alphington, Exminster</b>		
DESIGNATION:	Scheduled Monument (No.1012347)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Kingskerswell Manor House, Kingskerswell</b>		
DESIGNATION:	Scheduled Monument (No.1020875)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric field system and settlements on Kerswell Down and Whilborough Common, Kingskerswell</b>		
DESIGNATION:	Scheduled Monument (No.1021377)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Oxton House, Kenton</b>
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Declining
OWNER TYPE:	Private, multiple owners

In the mid C19 the picturesque grounds comprised lawns, parterres, shrubberies, parkland and a lake. In the C20, the property was occupied by a school before being divided into apartments. The pleasure grounds are neglected and much of the park is ploughed, with considerable loss of parkland planting.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Mamhead Park, Mamhead/Kenton</b>
DESIGNATION:	Registered Park and Garden Grade II*, also 16 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
OWNER TYPE:	Private, multiple owners

Mamhead contains the remnants of a 'Capability' Brown park overlooking the Exe estuary. Extensive loss of parkland trees, inappropriate land management and subdivision with new boundaries. Historic mixed plantations now largely converted to conifer. Main house currently (May 2012) on the market.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stover Park, Teigngrace</b>
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Mixed, multiple owners

Formerly a seat of the dukes of Somerset. Late C18 gardens, pleasure grounds and park. Now in divided ownership. Large area of the park now run by the County Council as a country park, another part is an actively worked quarry and the remainder is in use by a school. Setting also under threat with pressure for hotel, retail, residential and industrial development associated with A38 trunk road. Natural England is currently exploring opportunities through Environmental Stewardship for more informed management of the park.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bovey Tracey, Pottery Road</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Maureen Pearce (LPA) 01626 215705	NEW ENTRY:	No

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Chudleigh</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Maureen Pearce (LPA) 01626 215705	NEW ENTRY?:	No

SITE NAME:	<b>Dawlish</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Maureen Pearce (LPA) 01626 215705	NEW ENTRY?:	No

## TORRIDGE



SITE NAME:	<b>Richmond Dock, Appledore</b>	Dry dock, 1856. It is said to be the largest dry dock in the Bristol Channel at the time it was built. Now re-occupied and in use. The condition of the gates remains critical.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Fair	
OCCUPANCY:	Occupied	
PRIORITY:	C (C)	
OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Winsford Hospital, Halwill Junction, Halwill</b>	Winsford centre built as a cottage hospital in 1899, designed by Charles Voysey and founded by a local landowner. The NHS closed the hospital in 1998 when it was bought by the Winsford Trust. Since then, it has been run as a day centre and community resource. English Heritage grant aid led to the production of a conservation management plan, options appraisal and a costed condition survey.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Fair	
OCCUPANCY:	Part occupied	
PRIORITY:	C (C)	
OWNER TYPE:	Trust	Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cairn 20m east of Tibbett's Lookout, Lundy</b>		
DESIGNATION:	Scheduled Monument (No.1016015)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Chapel remains, cemetery and prehistoric settlement on Beacon Hill, Lundy</b>		
DESIGNATION:	Scheduled Monument (No.1016040)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Granite quarry on East Sidelands, Lundy</b>		
DESIGNATION:	Scheduled Monument (No.1016041)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Hut circle and small enclosure 270m north west of The Old Lighthouse, Lundy</b>			
DESIGNATION:	Scheduled Monument (No.1016014)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long house and enclosure 160m north of Widow's Tenement, Lundy</b>			
DESIGNATION:	Scheduled Monument (No.1018547)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Quarry infirmary and surgery, 220m north west of Quarterwall Cottages, Lundy</b>			
DESIGNATION:	Scheduled Monument (No.1016026)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Ruined cottages and well 190m north west of Quarterwall Cottages, Lundy</b>			
DESIGNATION:	Scheduled Monument (No.1016027)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Standing stone 100m north east of The Old Lighthouse, Lundy</b>			
DESIGNATION:	Scheduled Monument (No.1015928)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>The Widow's Tenement medieval settlement and prehistoric settlement sites, Lundy</b>			
DESIGNATION:	Scheduled Monument (No.1017646)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Iron Age enclosure and Roman marching camp, Alverdiscott</b>			
DESIGNATION:	Scheduled Monument (No.1004558)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 250m north east of Oak Cottage, forming part of a round barrow cemetery, Ashwater</b>			
DESIGNATION:	Scheduled Monument (No.1020079)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Bowl barrow 540m south east of Sandymoor Cross, forming part of a round barrow cemetery, Ashwater</b>	
DESIGNATION:	Scheduled Monument (No.1020080)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 770m south east of Sandymoor Cross, forming part of a round barrow cemetery, Ashwater</b>	
DESIGNATION:	Scheduled Monument (No.1020081)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Hillfort known as Castle Hill Settlement, 350m south of Woolleigh Bridge, Beaford</b>	
DESIGNATION:	Scheduled Monument (No.1021417)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 420m north west of Dural Cross, Bradworthy</b>	
DESIGNATION:	Scheduled Monument (No.1016643)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 280m south west of Upcott Cross, Broadwoodwidge</b>	
DESIGNATION:	Scheduled Monument (No.1019546)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Thorn Barrow 520m south east of Coop, in Highermoor Plantations, Broadwoodwidge</b>	
DESIGNATION:	Scheduled Monument (No.1017144)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 130m north of Wrangworthy Cross, forming part of a round barrow cemetery, Buckland Brewer</b>	
DESIGNATION:	Scheduled Monument (No.1018527)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Three bowl barrows 250m west of Bower, Bulkworthy</b>	
DESIGNATION:	Scheduled Monument (No.1020340)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Two bowl barrows 690m and 760m south west of Leworthy, Clawton</b>	
DESIGNATION:	Scheduled Monument (No.1017974)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Clovelly Dykes hillfort, Clovelly</b>	
DESIGNATION:	Scheduled Monument (No.1018522)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Four bowl barrows 110m and 360m west of Wrangworthy Cross forming part of a round barrow cemetery, East Putford</b>	
DESIGNATION:	Scheduled Monument (No.1018526)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Three fishponds at Winslade, East Putford</b>	
DESIGNATION:	Scheduled Monument (No.1017979)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Two bowl barrows 600m and 750m west of Wrangworthy cross forming part of a round barrow cemetery, East Putford</b>	
DESIGNATION:	Scheduled Monument (No.1018515)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Two bowl barrows one immediately north and one 100m south of Commonmoor Cottage forming part of a round barrow cemetery, East Putford</b>	
DESIGNATION:	Scheduled Monument (No.1018516)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Rothern Bridge, Frithelstock</b>	
DESIGNATION:	Scheduled Monument (No.1020702)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Round barrow on south east of Darracott Moor, Great Torrington</b>		
DESIGNATION:	Scheduled Monument (No.1012444)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hender Barrow, Halwill</b>		
DESIGNATION:	Scheduled Monument (No.1019727)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 300m south east of Gorvin, Hartland</b>		
DESIGNATION:	Scheduled Monument (No.1016645)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 520m west of Higher Welsford, Hartland</b>		
DESIGNATION:	Scheduled Monument (No.1017138)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 580m north west of Gorvin, Hartland</b>		
DESIGNATION:	Scheduled Monument (No.1016648)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Embury Beacon camp, Hartland</b>		
DESIGNATION:	Scheduled Monument (No.1003845)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows and one bell barrow on Bursdon Moor situated 670m north east of Lutsford Cross, Hartland</b>		
DESIGNATION:	Scheduled Monument (No.1019257)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows 400m north west of Gorvin, Hartland</b>		
DESIGNATION:	Scheduled Monument (No.1016647)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow on Ugworthy Moor 510m south of West Ugworthy House, Holsworthy Hamlets</b>		
DESIGNATION:	Scheduled Monument (No.1017977)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Berry Castle hillfort in Huntshaw Wood, Huntshaw</b>		
DESIGNATION:	Scheduled Monument (No.1016225)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 60m west of St James's Church, Luffincott</b>		
DESIGNATION:	Scheduled Monument (No.1020476)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Moated site at Grange Farm, Merton</b>		
DESIGNATION:	Scheduled Monument (No.1017867)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cross ridge dyke on Godborough Castle earthwork north west of Turner's Wood, Northam</b>		
DESIGNATION:	Scheduled Monument (No.1002640)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hallsannery limekiln, Northam</b>		
DESIGNATION:	Scheduled Monument (No.1004578)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Northcott Wood camp, Northcott</b>		
DESIGNATION:	Scheduled Monument (No.1003863)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 685m NNE of Moorfield, Peters Marland</b>		
DESIGNATION:	Scheduled Monument (No.1017963)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Beacon on Belland Moor 770m north east of Belland, Tetcott</b>		
DESIGNATION:	Scheduled Monument (No.1020609)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bideford</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Sarah Chappell (LPA) 01237 428742	NEW ENTRY?:	No

SITE NAME:	<b>Northam</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Sarah Chappell (LPA) 01237 428742	NEW ENTRY?:	No

## WEST DEVON



SITE NAME: **Gawton Mine complex, Gulworthy**

Former copper and arsenic mine and processing complex comprising a full range of buildings from cooperage to engine houses. Structures are at risk from a lack of maintenance.

DESIGNATION: Scheduled Monument, WHS

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Kelly House, Kelly**

CI8 house. Serious maintenance issues. Roof in need of renewal, rear medieval wing partly propped. Main house weathertight and maintenance gradually being addressed.

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Stable block north of Kelly House, Kelly**

Stables, 1740. Partly used, part collapsed.

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Lower Sessland Farm including cob walls adjoining to north west and south west, Sessland Lane, South Tawton**

Late medieval thatched farmhouse with later additions including CI7 hall bay and parlour wing. Further CI7 addition to north west has been used as a separate cottage and is now vacant and in very poor condition with severe water penetration and decay of thatch and roof timbers. Temporary protection was erected in 2006 following an Urgent Works Notice. Owner negotiating over repairs.

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: Part occupied

PRIORITY: A (A)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 0117 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Guildhall and police station, Abbey Place, Guildhall Square, Tavistock**

DESIGNATION: Listed Building Grade II\*, WHS, CA  
 CONDITION: Poor  
 OCCUPANCY: Vacant  
 PRIORITY: B (New entry)  
 OWNER TYPE: Trust

Completed 1848, incorporating medieval fabric in part. Court use ended 1997 and police station now relocated. The first known example of a combined police station and magistrates court. Roof is in very poor condition and fabric in general urgently needs attention. Devon Historic Trust has prepared an options appraisal which identifies repair needs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Church of St Peter, Lamerton**

DESIGNATION: Listed Place of Worship Grade II\*  
 CONDITION: Poor  
 PRIORITY: B (New entry)  
 OWNER TYPE: Religious organisation

Early C15 church, restored 1870s. Very soon after this the church suffered a major fire which destroyed almost everything except for the external walls and the tower. Rebuilding work was completed in 1880 following the C15 design including the barrel-vaulted roof. The main area of concern is the tower, which suffers from permanent dampness. The condition of the stonework at the top of the tower also gives cause for concern. A Repair Grant for Places of Worship was successfully applied for in 2011.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Church of St Andrew, South Tawton**

DESIGNATION: Listed Place of Worship Grade I  
 CONDITION: Very bad  
 PRIORITY: B (New entry)  
 OWNER TYPE: Religious organisation

The church is mostly C15 and was restored and vestry added in 1881. Good interior with fine bosses to roofs. There are major leaks in the north and south aisles and both roofs require renewal. A grant was offered in 2011 towards repair to roofs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Church of Our Lady and St Mary Magdalene, Callington Road, Tavistock**

DESIGNATION: Listed Place of Worship Grade II\*, WHS, CA  
 CONDITION: Poor  
 PRIORITY: F (B)  
 OWNER TYPE: Religious organisation

Built 1825-67 by Henry Clutton for the Duke of Norfolk. The church has previously been at risk of closure, although it has recently increased its congregation. The church has had English Heritage funding to investigate structural cracking and its cause. A scheme for repair has been agreed and works are ongoing with grant aid applied for in 2010.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:

**Round barrow cemetery and beacon at Heathfield, 650m west of Moorlands, Brentor**

DESIGNATION:	Scheduled Monument (No.1020075)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:

**Motte with two baileys and a multivallate hillfort at Burley Wood, Bridestowe**

DESIGNATION:	Scheduled Monument (No.1018519)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
 2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Iron Age defended settlement in Dunterue Wood, 570m south of Castle Head, Dunterton</b>		
DESIGNATION:	Scheduled Monument (No.1020273)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 620m north of Higher Eworthy, Germansweek</b>		
DESIGNATION:	Scheduled Monument (No.1017971)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Gawton arsenic mine and flue, Gulworthy</b>		
DESIGNATION:	Scheduled Monument (No.1002667)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Morwellham Quay: transport infrastructure, part of the water control system and a manganese mill, Gulworthy</b>		
DESIGNATION:	Scheduled Monument (No.1021461)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roman forts, marching camps and associated monuments, North Tawton</b>		
DESIGNATION:	Scheduled Monument (No.1021151)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Guide post at Place Cross, Okehampton Hamlets</b>		
DESIGNATION:	Scheduled Monument (No.1020069)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bere Alston</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Laura Batham (LPA) 01822 813600	NEW ENTRY:	No

SITE NAME:	<b>Hatherleigh</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813600	NEW ENTRY:	No

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>North Tawton</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813600	NEW ENTRY:	No

SITE NAME:	<b>Okehampton</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Laura Batham (LPA) 01822 813600	NEW ENTRY:	No

**DORSET****CHRISTCHURCH**

SITE NAME:	<b>Bowl barrow on East Parley Common 610m south west of Fir Grove Farm, Hurn</b>		
DESIGNATION:	Scheduled Monument (No.1016092)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows at Gibbet Firs, 950m south west and 1080m south west of Palmers Ford Works, Hurn</b>		
DESIGNATION:	Scheduled Monument (No.1016091)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**EAST DORSET**

SITE NAME: **Grotto 250 metres south west of St Giles House, Wimborne St Giles**

DESIGNATION: Listed Building Grade II\*, RPG II\*  
CONDITION: Very bad  
OCCUPANCY: N/A  
PRIORITY: C (C)  
OWNER TYPE: Private

Grotto, c1751-53, located 250 metres to the south-east of the house, at the east end of a winding channel of water running westwards for 300 metres to the northern extremity of the lake (which lies 150 metres to the south of the house). One of several garden buildings situated in the C17 and C18 landscape. The Grotto is identified as a priority in the Parkland Plan produced as part of Higher Level Stewardship.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **St Giles House, Wimborne St Giles**

DESIGNATION: Listed Building Grade I, RPG II\*  
CONDITION: Fair  
OCCUPANCY: Part occupied  
PRIORITY: E (C)  
OWNER TYPE: Private

Country house. C17, C18 and C19, situated in a C17 and C18 park. Owner's family have lived in the Dower House since the Second World War when the main house was requisitioned and subsequently used as a school. The south wing of the house has been repaired and the owner and his family are now living in it. There is ongoing repair to the roof and brickwork to the main house.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Remains of medieval buildings, Witchampton**

DESIGNATION: Scheduled Monument  
CONDITION: Poor  
OCCUPANCY: N/A  
PRIORITY: C (C)  
OWNER TYPE: Private

On the southern side of the village of Witchampton lie the ruins of a substantial domestic medieval building. It was used as an agricultural building in C19 but has since fallen into a state of disrepair. Scrub/vegetation clearance work has taken place in the past, but has since regenerated.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Length of deer park bank and ditch at Alderholt, Alderholt</b>		
DESIGNATION:	Scheduled Monument (No.1002394)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Section of Roman Road 150m south of Park Farm Cottages, Colehill</b>		
DESIGNATION:	Scheduled Monument (No.1018028)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrows in and near St Giles Park, Edmondsham</b>		
DESIGNATION:	Scheduled Monument (No.1002782)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow 500m north east of Beacon Farm, Ferndown Town</b>		
DESIGNATION:	Scheduled Monument (No.1015995)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow known as Belle Vue Barrow, and a bowl barrow 250m north east of Hillamsland, Ferndown Town</b>		
DESIGNATION:	Scheduled Monument (No.1015994)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 250m west of Ferndown Upper School, Ferndown Town</b>		
DESIGNATION:	Scheduled Monument (No.1015791)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration – in need of management	TREND:	Declining
OWNER TYPE:	Utility	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow near Burtts Harley, Gussage All Saints</b>		
DESIGNATION:	Scheduled Monument (No.1002787)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrows in and near The Drive Plantation, Gussage All Saints</b>		
DESIGNATION:	Scheduled Monument (No.1002788)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME: Part of Ackling Dyke (Roman road), including Roman road on Oakley Down, Gussage All Saints</b>			
DESIGNATION:	Scheduled Monument (No.1003309)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Barrow on Parsonage Hill, Gussage St Michael</b>			
DESIGNATION:	Scheduled Monument (No.1002783)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Earthworks on Gussage Down, Gussage St Michael</b>			
DESIGNATION:	Scheduled Monument (No.1002740)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Long mound 1500yds (1370m) east of Higher Farm, Gussage St Michael</b>			
DESIGNATION:	Scheduled Monument (No.1002784)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Round barrows near Thickthorn Farm, Gussage St Michael</b>			
DESIGNATION:	Scheduled Monument (No.1002816)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Two barrows near Ackling Dyke, Gussage St Michael</b>			
DESIGNATION:	Scheduled Monument (No.1002786)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Two long barrows on Gussage Hill, Gussage St Michael</b>			
DESIGNATION:	Scheduled Monument (No.1002707)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Two round barrows on Gussage Down, Gussage St Michael</b>			
DESIGNATION:	Scheduled Monument (No.1002741)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Round barrow north west of High Lea Farm, Hinton Martell</b>			
DESIGNATION:	Scheduled Monument (No.1004552)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow on Summerlug Hill 250m south of Mannington Farm, Holt</b>			
DESIGNATION:	Scheduled Monument (No.1018199)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bull Barrow on Holt Heath, Holt</b>			
DESIGNATION:	Scheduled Monument (No.1018198)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow cemetery and a cross dyke on Horton Common 800m south of Bridge Farm, Horton</b>			
DESIGNATION:	Scheduled Monument (No.1018411)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 250m north west of Veiny Cheese Pond, Long Cichel</b>			
DESIGNATION:	Scheduled Monument (No.1015191)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Disc barrow and a bowl barrow 640m south west of Veiny Cheese Pond, Long Cichel</b>			
DESIGNATION:	Scheduled Monument (No.1020444)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows 165m west of Veiny Cheese Pond, Long Cichel</b>			
DESIGNATION:	Scheduled Monument (No.1015785)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bradford Barrow, Pamphill</b>			
DESIGNATION:	Scheduled Monument (No.1002713)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>A linear earthwork north east of West Woodyates Manor: part of the 'Bokerley Line', Pentridge</b>		
DESIGNATION:	Scheduled Monument (No.1012138)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow west of village, Pentridge</b>		
DESIGNATION:	Scheduled Monument (No.1002794)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrows in Salisbury Plantation, Pentridge</b>		
DESIGNATION:	Scheduled Monument (No.1002817)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Celtic fields on Pentridge Down, Pentridge</b>		
DESIGNATION:	Scheduled Monument (No.1002796)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrows and group of round barrows on Bokerly Down, Pentridge</b>		
DESIGNATION:	Scheduled Monument (No.1002722)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Part of Dorset Cursus, Pentridge</b>		
DESIGNATION:	Scheduled Monument (No.1003222)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roman fort at Crab Farm, Shapwick</b>		
DESIGNATION:	Scheduled Monument (No.1002372)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp in Mistlebury Wood, Sixpenny Handley</b>		
DESIGNATION:	Scheduled Monument (No.1002455)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Enclosure south of Humby's Stock Coppice, Sixpenny Handley</b>		
DESIGNATION:	Scheduled Monument (No.1005575)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows in Avon Heath Country Park, two 620m and one 700m north west of Matcham's House, St Leonards and St Ives</b>		
DESIGNATION:	Scheduled Monument (No.1016095)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stephen's Castle, a bowl barrow 720m east of Eastworth Farm, Verwood</b>		
DESIGNATION:	Scheduled Monument (No.1021148)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Improving
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Parley Barrow, a bowl barrow on the corner of Ellesfield Drive and Druid's Close, West Parley</b>		
DESIGNATION:	Scheduled Monument (No.1015792)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow 30yds (27m) east of Dorset Cursus, Wimborne St Giles</b>		
DESIGNATION:	Scheduled Monument (No.1002793)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Parts of Dorset Cursus on Bottlebush Down, Wimborne St Giles</b>		
DESIGNATION:	Scheduled Monument (No.1002799)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two round barrows south of Cranborne Farm, Wimborne St Giles</b>		
DESIGNATION:	Scheduled Monument (No.1002459)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of henge monuments, an associated group of round barrows, a Saxon cemetery, and a Norman church at Knowlton, Woodlands</b>		
DESIGNATION:	Scheduled Monument (No.1020580)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Round barrow cemetery south of New Barn Farm, associated with the Knowlton Circles, Woodlands</b>		
DESIGNATION:	Scheduled Monument (No.1020582)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>St Giles' House, Wimborne St. Giles/Edmondsham/Gussage All Saints</b>
DESIGNATION:	Registered Park and Garden Grade II*, also part in CA, 7 LBs, 12 SMs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Improving
OWNER TYPE:	Private, single owner

Extensive C18 landscape park and pleasure grounds with follies, a grotto, a serpentine lake and a striking beech avenue. The main house and the shell grotto are also at risk. The structural elements of the park design survive in moderate condition. In 2010, Natural England's Environmental Stewardship scheme grant-aided a plan for the park and a comprehensive programme of restoration has commenced. Encouragingly, a start has also been made on repairing St Giles House.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

## NORTH DORSET



SITE NAME:	<b>Sturminster Newton Castle, Sturminster Newton</b>
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Ruins of C14 stone built manor house within Sturminster Newton Castle, a probable Iron Age promontory fort overlooking the River Stour. Upstanding remains in very precarious position and considerable amount of consolidation work is urgently required to avoid significant areas of collapse. EH architectural survey team has recorded the structure. Recent change of ownership. EH in discussions with new owners.


Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Barn and outbuilding range, Tarrant Abbey Farm, Tarrant Crawford</b>
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

C15 barn with C18 outbuildings and alterations. No longer in agricultural use. Works have been undertaken to support the structure.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Manor Farm barn, Winterborne Clenston</b>
DESIGNATION:	Listed Building Grade I, SM
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Huge late C16 tithe barn part used for storage. The hammerbeam roof may have been reused from a monastic building at Milton Abbey. Partial roof collapse resulted in English Heritage funding the erection of scaffolding as a temporary roof support.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Church of St Peter and St Paul, Market Place, Blandford Forum</b>
DESIGNATION:	Listed Place of Worship Grade I
CONDITION:	Poor
PRIORITY:	C (New entry)
OWNER TYPE:	Religious organisation

This grade I church is a notable example of Georgian church architecture outside London. It was rebuilt after fire in 1732-1739 to designs by John and William Bastard. The external stonework is in poor condition and there is water ingress to the interior causing damage to the plaster work. The cupola is in very poor condition and held in place with a temporary supporting structure.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **St Mary Magdalen,  
Fifehead Magdalen**

A small C14 parish church on the edge of the village, with C17 or C18 north chapel. The church was extensively restored in 1904. Repairs have been undertaken to the south chancel roof, but the fixings to the stone tiles on the remaining roofs appear to be progressively failing. A Repair Grant for Places of Worship has been offered for roof repairs. Works due to start in 2012.

DESIGNATION: Listed Place of Worship Grade II, CA

CONDITION: Poor

PRIORITY: F (B)

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Linear boundary 870m south west of Spring Farm, Ashmore**

DESIGNATION: Scheduled Monument (No.1020729)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Linear boundary and section of Roman road, 550m south east of Ashmore Farm, Ashmore**

DESIGNATION: Scheduled Monument (No.1020728)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **St Leonard's Chapel, Blandford Forum**

DESIGNATION: Scheduled Monument (No.1002726)

CONDITION: Generally satisfactory  
but with significant localised problems

PRINCIPAL VULNERABILITY: Deterioration – in need of management

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Field system in Old Park, Bryanston**

DESIGNATION: Scheduled Monument (No.1002427)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 1020m south east of Charisworth Cottages, Charlton Marshall**

DESIGNATION: Scheduled Monument (No.1014846)

CONDITION: Generally unsatisfactory  
with major localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 350m south of Gorcombe Farm, Charlton Marshall**

DESIGNATION: Scheduled Monument (No.1014848)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 500m south west of Gorcombe Farm, Charlton Marshall**

DESIGNATION: Scheduled Monument (No.1014847)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

**CA** Conservation Area  
**LB** Listed Building  
**LPA** Local Planning Authority  
**NP** National Park  
**RPG** Registered Park and Garden  
**SM** Scheduled Monument  
**UA** Unitary Authority  
**WHS** World Heritage Site

SITE NAME: <b>Bowl barrow 650m south west of Gorcombe Farm, Charlton Marshall</b>			
DESIGNATION:	Scheduled Monument (No.I014849)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long barrow 360m SSW of Chettle House, Chettle</b>			
DESIGNATION:	Scheduled Monument (No.I013792)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Causewayed camp on Hambledon Hill, Child Okeford</b>			
DESIGNATION:	Scheduled Monument (No.I002767)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Longbury long barrow 600m north west of Slaughtergate Farm, Gillingham</b>			
DESIGNATION:	Scheduled Monument (No.I013680)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow known as Folly Barrow, Iwerne Minster</b>			
DESIGNATION:	Scheduled Monument (No.I020030)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows 350m south west of Keeper's Lodge south east of Bareden Down, Iwerne Minster</b>			
DESIGNATION:	Scheduled Monument (No.I013745)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 480m south east of West End Barn, Milborne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.I014855)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 70m south east of West End Barn, Milborne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.I014854)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Stable Barrow 230m NNE of Frogmore Farm, Milborne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1014761)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three bowl barrows 380m west of West End Barn, Milborne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1015031)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three bowl barrows on Milborne Down 520m and 585m north east of obelisk on Weatherby Castle hillfort, Milborne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1019364)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows and two ring ditches 450m north west of Haywards Farm, Milborne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1019365)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Weatherby Castle, an Iron Age hillfort 1020m north west of Ashley Barn Farm, Milborne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1019360)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Enclosure south of Pimperne Down, Pimperne</b>			
DESIGNATION:	Scheduled Monument (No.1002860)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Site of St John's Church, Shaftesbury</b>			
DESIGNATION:	Scheduled Monument (No.1005580)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Crawford Castle (or Spetisbury Rings), Spetisbury</b>			
DESIGNATION:	Scheduled Monument (No.1004563)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Chapel west of Manor Farm, Stourton Caundle</b>			
DESIGNATION:	Scheduled Monument (No.1002857)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Slight univallate hillfort 850m north east of Busseys Stool Farm, Tarrant Gunville</b>			
DESIGNATION:	Scheduled Monument (No.1020611)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 200m south east of Pimperne Long Barrow, Tarrant Hinton</b>			
DESIGNATION:	Scheduled Monument (No.1013794)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric habitation site between north and south Hinton Downs, Tarrant Hinton</b>			
DESIGNATION:	Scheduled Monument (No.1003235)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Roman villa on Little Barton Hill, Tarrant Hinton</b>			
DESIGNATION:	Scheduled Monument (No.1002424)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 350m south west of Buzbury Rings, Tarrant Keyneston</b>			
DESIGNATION:	Scheduled Monument (No.1013789)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Buzbury Rings, Tarrant Keyneston</b>			
DESIGNATION:	Scheduled Monument (No.1002718)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Roman enclosure on Keyneston Down, Tarrant Keyneston</b>			
DESIGNATION:	Scheduled Monument (No.1002373)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME: Bowl barrow 600m south of Plantation Farm, Tarrant Launceston</b>			
DESIGNATION:	Scheduled Monument (No.1015190)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow on The Cliff 680m east of Luton Farm, Tarrant Rawston</b>			
DESIGNATION:	Scheduled Monument (No.1015187)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow on The Cliff 680m NNW of Smith's Cottages, Tarrant Rawston</b>			
DESIGNATION:	Scheduled Monument (No.1015186)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Long barrow and two bowl barrows 140m north west of Dormy House, Tarrant Rawston</b>			
DESIGNATION:	Scheduled Monument (No.1014572)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 850m ESE of Hill Farm, Tarrant Rushton</b>			
DESIGNATION:	Scheduled Monument (No.1015182)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 150m north east of Dunbury, Winterborne Houghton</b>			
DESIGNATION:	Scheduled Monument (No.1014758)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 800m north west of North Barn Farm on Houghton North Down, Winterborne Houghton</b>			
DESIGNATION:	Scheduled Monument (No.1013748)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Bowl barrow 500m south of West Down Barn, Winterborne Kingston</b>		
DESIGNATION:	Scheduled Monument (No.1020986)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 900m north west of Pond Down Buildings, Winterborne Stickland</b>		
DESIGNATION:	Scheduled Monument (No.1013749)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Rowbarrow, 500m north west of Hedge End Farm, Winterborne Stickland</b>		
DESIGNATION:	Scheduled Monument (No.1013747)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 120m south of the southern extent of Horse Close Plantation, Winterborne Whitechurch</b>		
DESIGNATION:	Scheduled Monument (No.1015387)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 25m south of Whitechurch Hill Barn, Winterborne Whitechurch</b>		
DESIGNATION:	Scheduled Monument (No.1013788)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Milling House, West Farm, Winterborne Whitechurch</b>		
DESIGNATION:	Scheduled Monument (No.1002396)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 550m north west of Bulbarrow Farm, Woolland</b>		
DESIGNATION:	Scheduled Monument (No.1013786)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bul Barrow, 750m east of Rawlsbury Camp, Woolland</b>		
DESIGNATION:	Scheduled Monument (No.1013787)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Blandford Forum</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Kevin Morris (LPA) 01258 484 276	NEW ENTRY?:	No

SITE NAME:	<b>Gillingham</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Kevin Morris (LPA) 01258 484 276	NEW ENTRY?:	No

SITE NAME:	<b>Milton Abbas</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Kevin Morris (LPA) 01258 484 276	NEW ENTRY?:	No

## PURBECK



SITE NAME:	<b>North Lodges, Lulworth Castle, Coombe Keynes</b>	Gate lodges and gateway to Lulworth Castle, 1785. Repairs have been undertaken by the estate, but a longer term plan for the buildings needs to be conceived.
DESIGNATION:	Listed Building Grade II*, SM	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	C (C)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow in Throop Clump, 450m west of Heatherdown, Affpuddle</b>		
DESIGNATION:	Scheduled Monument (No.1020734)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Double Barrow, a bowl barrow in Kite Hill Plantation 250m south east of Roger's Hill Cottages, Affpuddle</b>		
DESIGNATION:	Scheduled Monument (No.1015900)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Worgret Heath, 320m north west of High Tor, Arne</b>		
DESIGNATION:	Scheduled Monument (No.1018190)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME: Bell barrow on Blackhill Clump 470m north of Mintern's Ferry, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015899)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 190m north west of Bere Down Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015376)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 515m south of the southern extent of Horse Close Plantation, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015386)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 590m north east of Bere Down Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015378)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 610m east of Bere Heath Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015365)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 790m north east of Haywards Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015330)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow on Warren Heath, 350m south west of Warren House, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I019367)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Four bowl barrows 240m east of Oak Cottage, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015369)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

<b>SITE NAME: Four bowl barrows 600m east and 650m north east of Haywards Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015331)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Group of six bowl barrows, forming a round barrow cemetery on Black Hill, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015897)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Long barrow on Bere Down, 1100m north east of Roke Barn, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015329)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: The End Barrow, a bowl barrow 320m south west of White House, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I017462)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Three bowl barrows 230m south west of Haywards Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015333)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Three bowl barrows 650m south west of Bere Down Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I018193)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Two bell barrows and a bowl barrow, 200m north east of Haywards Farm, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015332)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Two bowl barrows both 350m north east of Spring Garden Barn, Bere Regis</b>			
DESIGNATION:	Scheduled Monument (No.I015898)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Two bowl barrows on South Heath, 900m SSE of The Bungalow, Bere Regis</b>		
DESIGNATION:	Scheduled Monument (No.1017694)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 800m NNW of West Morden Farm, Bloxworth</b>		
DESIGNATION:	Scheduled Monument (No.1015367)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Bloxworth Down, 740m south of Marsh Farm, Bloxworth</b>		
DESIGNATION:	Scheduled Monument (No.1017626)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow cemetery on Bloxworth Down, Bloxworth</b>		
DESIGNATION:	Scheduled Monument (No.1017624)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows on Bloxworth Down, 800m west of Botany Bay Barn, Bloxworth</b>		
DESIGNATION:	Scheduled Monument (No.1017625)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 200m south east of Hill Barn: one of a group of three barrows, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1008178)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 470m south east of Down Barn: an outlier of the Chaldon Down barrow group, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1008146)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 550m south of Chaldon Down Buildings: part of the Chaldon Down round barrow cemetery, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1008520)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 650m south of Chaldon Down Buildings: part of the Chaldon Down round barrow cemetery, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1008523)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 660m south of Chaldon Down Buildings: part of the Chaldon Down round barrow cemetery, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1008521)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Round Pound, an enclosure on Chaldon Down, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1018436)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows 200m south east of Hill Barn: two of a group of three barrows, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1008162)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wardstone Barrow: a bowl barrow on the Dorset coastal ridge 300m south of Chideock Farm, Chaldon Herring</b>		
DESIGNATION:	Scheduled Monument (No.1008676)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Crech Barrow hill, Church Knowle</b>		
DESIGNATION:	Scheduled Monument (No.1014830)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Rings: a ringwork and bailey and a Civil War battery 400m south west of Corfe Castle, Corfe Castle</b>		
DESIGNATION:	Scheduled Monument (No.1011479)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME:</b> Three bowl barrows in Holme Lane Plantation, 200m south west of Squirrel's Cottages, East Holme			
<b>DESIGNATION:</b>	Scheduled Monument (No.1016728)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b> Flower's Barrow: a small multivallate hillfort and associated outwork on Rings Hill, East Lulworth			
<b>DESIGNATION:</b>	Scheduled Monument (No.1008141)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Coastal erosion	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Other	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b> Two barrows known as 'Water Barrows' 650m WNW of Whiteway Farm: part of a round barrow cemetery to the south east of East Lulworth, East Lulworth			
<b>DESIGNATION:</b>	Scheduled Monument (No.1008144)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Extensive animal burrowing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Government or Agency	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b> Bowl barrow 60m north east of Hethfelton Farm, East Stoke			
<b>DESIGNATION:</b>	Scheduled Monument (No.1018192)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Scrub/tree growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b> Bowl barrow on Farm Heath, 470m south east of Hill Cottages, East Stoke			
<b>DESIGNATION:</b>	Scheduled Monument (No.1016272)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Scrub/tree growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b> Bowl barrow on Farm Heath, 480m south east of Hill Cottages, East Stoke			
<b>DESIGNATION:</b>	Scheduled Monument (No.1016271)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Extensive animal burrowing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b> Round barrow cemetery on West Holme Heath, 850m north west of Hurst Mill, East Stoke			
<b>DESIGNATION:</b>	Scheduled Monument (No.1007691)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Other	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Government or Agency	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Section of Battery Bank on Binnegar Plain, 830m north east of Stokeford Farm, East Stoke</b>		
DESIGNATION:	Scheduled Monument (No.1018189)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Section of Battery Bank on South Heath, East Stoke</b>		
DESIGNATION:	Scheduled Monument (No.1016273)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows on South Heath, 290m and 370m east of Binnegar Hall, East Stoke</b>		
DESIGNATION:	Scheduled Monument (No.1016276)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Alum works, other multi-period industrial remains and an associated group of jetties and breakwaters, Kimmeridge Bay, Kimmeridge</b>		
DESIGNATION:	Scheduled Monument (No.1017307)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow in Morden Park 350m south west of Hunting Bridge, Morden</b>		
DESIGNATION:	Scheduled Monument (No.1016281)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows 760m north east of Miller's Farm, Morden</b>		
DESIGNATION:	Scheduled Monument (No.1016283)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Obelisk on Fir Hill, Moreton</b>		
DESIGNATION:	Scheduled Monument (No.1002425)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Group of three bell barrows and a bowl barrow on Godlingston Heath, Studland</b>		
DESIGNATION:	Scheduled Monument (No.1014291)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow in Piddle Wood, 530m north east of Gate Barn, Turners Puddle</b>		
DESIGNATION:	Scheduled Monument (No.1015901)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow cemetery on Povington Heath 550m north east of Whiteway Farm, Tyneham</b>		
DESIGNATION:	Scheduled Monument (No.1008026)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Thorn Barrow: a bowl barrow on East Holme Range, 650m north east of Whiteway Farm, Tyneham</b>		
DESIGNATION:	Scheduled Monument (No.1009610)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Decoy pond and associated overnight shelter on Decoy Heath, Wareham St Martin</b>		
DESIGNATION:	Scheduled Monument (No.1016916)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Light Anti-aircraft battery on Holton Heath, 210m west of Sandford House, Wareham St Martin</b>		
DESIGNATION:	Scheduled Monument (No.1019153)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Royal Naval Cordite Factory at Holton Heath, Wareham St Martin</b>		
DESIGNATION:	Scheduled Monument (No.1019151)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>Bindon Hill camp, West Lulworth</b>	
DESIGNATION:	Scheduled Monument (No.I002705)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 370m east of Belhuish Farm: one of a group of barrows to the west of Burngate Wood, West Lulworth</b>	
DESIGNATION:	Scheduled Monument (No.I008220)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 400m ENE of Belhuish Farm: one of a group of barrows to the west of Burngate Wood, West Lulworth</b>	
DESIGNATION:	Scheduled Monument (No.I012050)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 650m south east of Belhuish Farm: one of a group of barrows to the west of Burngate Wood, West Lulworth</b>	
DESIGNATION:	Scheduled Monument (No.I008455)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Drove Hill round barrows, Winfrith Newburgh</b>	
DESIGNATION:	Scheduled Monument (No.I002765)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bindon Abbey (site), Wool</b>	
DESIGNATION:	Scheduled Monument (No.I002703)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 300m south east of Hyford Cottage, Wool</b>	
DESIGNATION:	Scheduled Monument (No.I015894)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 380m north west of Hyford Cottage, Wool</b>		
DESIGNATION:	Scheduled Monument (No.1015895)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Emmett's Hill, Worth Matravers</b>		
DESIGNATION:	Scheduled Monument (No.1017268)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Acton</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Benjamin Webb (LPA) 01929 556 561	NEW ENTRY:	No

SITE NAME:	<b>Chaldon Herring</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Benjamin Webb (LPA) 01929 556 561	NEW ENTRY:	No


SITE NAME:	<b>East Lulworth</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Benjamin Webb (LPA) 01929 556 561	NEW ENTRY:	No

SITE NAME:	<b>Kimmeridge</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Benjamin Webb (LPA) 01929 556 561	NEW ENTRY:	No

SITE NAME:	<b>Wareham and Stoborough</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Benjamin Webb (LPA) 01929 556 561	NEW ENTRY:	No

SITE NAME:	<b>West Lulworth</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Benjamin Webb (LPA) 01929 556 561	NEW ENTRY:	No

## WEST DORSET



SITE NAME:	<b>Literary and Scientific Institute, East Street, Bridport</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Local authority

Founded 1835 as Mechanics Institute and reconstituted 1855 as Literary and Scientific Institute. A local trust is carrying out project development work grant aided by English Heritage which includes a condition survey and a feasibility study exploring the viability of using the building for community purposes.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: <b>Messrs Norman goods warehouse, Station Road, West Bay, Bridport</b></p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: E (E)</p> <p>OWNER TYPE: Private</p>	<p>CI8, possibly older. Former bonded stores. Vacant. Owner has identified potential end use and is in discussion with Local Planning Authority and English Heritage.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>The Riding School, Wolfeton Manor, Wolfeton, Charminster</b></p> <p>DESIGNATION: Listed Building Grade II*, CA</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: E (D)</p> <p>OWNER TYPE: Trust</p>	<p>One of the oldest surviving riding schools in England, late CI6. Currently used as a barn. In Trust ownership. First phase of major repairs started early 2012, grant aided by English Heritage.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Marshwood Castle, Marshwood</b></p> <p>DESIGNATION: Listed Building Grade I, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: N/A</p> <p>PRIORITY: C (C)</p> <p>OWNER TYPE: Private</p>	<p>The site comprises a rectangular earthwork enclosure with a moat (partly filled). There are substantial remains of the internal ramparts and the motte. These masonry structures require consolidation and careful ongoing management.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Remains of Old Parish Church of St Mary Magdalene, North Wootton</b></p> <p>DESIGNATION: Listed Building Grade II*, SM</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: N/A</p> <p>PRIORITY: D (D)</p> <p>OWNER TYPE: Private</p>	<p>West tower of former parish church. Early CI5. The nave and chancel were demolished circa 1883 when the CI9 church was built. Ivy which encased the structure was removed in 2011 and a condition survey and proposals for its consolidation are underway in discussion with English Heritage.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Cart shed and stables 10 metres south of Waddon House, Portesham</b></p> <p>DESIGNATION: Listed Building Grade II*</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Vacant</p> <p>PRIORITY: D (D)</p> <p>OWNER TYPE: Private</p>	<p>Former stables and cart shed, dated 1702. Currently disused with roof temporarily protected. Application for repair and conversion to holiday let use has been approved. Roof has been made temporarily weathertight and intended to be re-thatched shortly.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p>SITE NAME: <b>Sherborne House, Newland, Sherborne</b></p> <p>DESIGNATION: Listed Building Grade I, CA</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Part occupied</p> <p>PRIORITY: F (D)</p> <p>OWNER TYPE: Local authority</p>	<p>House circa 1720. Former girls' school. An application for planning permission for gallery/office use has been approved and proposed new development at the rear is subject to a section 106 agreement, securing repairs to Sherborne House. Work commenced on site in early 2012 and repairs to the house are now proceeding.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Tithe Barn, Church Lane, Sydling St Nicholas</b>
DESIGNATION:	Listed Building Grade II*, SM
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (New entry)
OWNER TYPE:	Private

Impressive CI6 barn. It has an interesting constructional history and is part of an important complex of historic buildings. Its gradual deterioration has recently shown signs of accelerating with the loss of an area of roof covering. Approval of planning permission for change of use to community events has been granted and works in connection with scheduled monument consent still under discussion.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Stable Block immediately south east of Little Toller Farm, Toller Fratrum</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Private

Mid CI6 stable building, forming part of a working farm but currently disused. The thatch is in a very degraded state leading to partial collapse of the roof and rear wall structure at end of 2011. The building is now scaffolded with a temporary roof structure whilst the local authority and English Heritage is discussing the need for urgent repairs with the owner and exploring possible sources of grant aid.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Former Methodist Chapel, Dorchester Road, Tolpuddle</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Methodist church, circa 1818, and the meeting place of the Tolpuddle Martyrs. Discussions are ongoing between West Dorset District Council and the owner, who has indicated a willingness to sell the site, to find an appropriate use for the building.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Parish Church of St Lawrence, Folke</b>
DESIGNATION:	Listed Place of Worship Grade I
CONDITION:	Very bad
PRIORITY:	F (B)
OWNER TYPE:	Religious organisation

Church built 1628, restored 1875. High castellated parapets with stone tile and Welsh slate roofs. Very good Jacobean interior. Stone tile nave roofs failing and all four abutments of slate aisle roofs have temporary sheeting in place as also failing. A Repair Grant for Places of Worship has been offered for roof repairs. Works due to start in 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of St Mary, Mosterton</b>
DESIGNATION:	Listed Place of Worship Grade II
CONDITION:	Very bad
PRIORITY:	B (New entry)
OWNER TYPE:	Religious organisation

Parish church built in 1833 by Edmund Pearce on a new site. The historic nave roof has been replaced with an asbestos sheet roof finish with a suspended ceiling and is in poor condition. The stonework to the diminutive west tower is also in poor condition, particularly to the south side. This is due to extensive cement pointing and patch repairs which are failing. A Repair Grant for Places of Worship has been offered for repairs to the tower.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Barrow east of Burnt House Bottom, Alton Pancras</b>	
DESIGNATION:	Scheduled Monument (No. I002862)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Earthwork 80yds (70m) long north west of Coombe Bottom, Askerswell</b>	
DESIGNATION:	Scheduled Monument (No. I002734)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Group of three round barrows west of Two Gates, Askerswell</b>		
DESIGNATION:	Scheduled Monument (No.1002736)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow north west of Coombe Bottom, Askerswell</b>		
DESIGNATION:	Scheduled Monument (No.1003061)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Beaminstor Down 530m south east of East Axnoller Farm, Beaminstor</b>		
DESIGNATION:	Scheduled Monument (No.1015049)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Beaminstor Down 770m north east of Higher Meerhay Farm, Beaminstor</b>		
DESIGNATION:	Scheduled Monument (No.1015050)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow east of Red Barn, Bradford Peverell</b>		
DESIGNATION:	Scheduled Monument (No.1002815)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow near Higher Skippet Farm, Bradford Peverell</b>		
DESIGNATION:	Scheduled Monument (No.1002819)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow in Highfield Plantation and two bowl barrows immediately north west of Forty Acre Plantation, Bradford Peverell</b>		
DESIGNATION:	Scheduled Monument (No.1019415)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 380m west of Whitfield Farm, Bradford Peverell</b>		
DESIGNATION:	Scheduled Monument (No.1019639)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Discontinuous surviving sections of Roman aqueduct, Bradford Peverell</b>			
DESIGNATION:	Scheduled Monument (No.1002730)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Group of barrows in Seven Barrow Plantation, Bradford Peverell</b>			
DESIGNATION:	Scheduled Monument (No.1002812)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long barrow and four bowl barrows 500m north west of Whitfield Farm, Bradford Peverell</b>			
DESIGNATION:	Scheduled Monument (No.1019416)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Culliford Tree long barrow and group of round barrows, Broadmayne</b>			
DESIGNATION:	Scheduled Monument (No.1003304)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Oval barrow and three bowl barrows 250m and 330m south of Whitcombe Barn, Broadmayne</b>			
DESIGNATION:	Scheduled Monument (No.1019414)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows on Lord's Down 580m south east of Crawthorne Farm, Burleston</b>			
DESIGNATION:	Scheduled Monument (No.1017277)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow on Wood Hill 310m north east of Cowden, Charminster</b>			
DESIGNATION:	Scheduled Monument (No.1019395)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow east of Forston Farm, Charminster</b>			
DESIGNATION:	Scheduled Monument (No.1002851)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Earthwork and ancient fields south east of Lyscombe Bottom, Cheselbourne</b>			
DESIGNATION:	Scheduled Monument (No.1002456)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Group of round barrows north east of Hog Leaze, Cheselbourne</b>			
DESIGNATION:	Scheduled Monument (No.1002877)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow on Cheselbourne West Down, Cheselbourne</b>			
DESIGNATION:	Scheduled Monument (No.1002878)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 360m south of Compton Barn, Compton Valence</b>			
DESIGNATION:	Scheduled Monument (No.1019741)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Settlement south east of Soaper's Hill Plantation, Compton Valence</b>			
DESIGNATION:	Scheduled Monument (No.1003234)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 450m east of Dennet's Bottom Barn, Dewlish</b>			
DESIGNATION:	Scheduled Monument (No.1015427)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 550m WNW of West End Barn, Dewlish</b>			
DESIGNATION:	Scheduled Monument (No.1015032)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Earthwork east of Stake Farm, East Chelborough</b>			
DESIGNATION:	Scheduled Monument (No.1002845)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Bell barrow and five bowl barrows 1000m south east of Kingston Russell Farm, part of the Black Down round barrow cemetery, Kingston Russell</b>		
DESIGNATION:	Scheduled Monument (No.1011693)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 550m north east of Pitcombe Farm, part of the Black Down round barrow cemetery, Kingston Russell</b>		
DESIGNATION:	Scheduled Monument (No.1011694)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 810m NNE of Whatcombe House, forming part of the round barrow cemetery on the south western part of Black Down, Kingston Russell</b>		
DESIGNATION:	Scheduled Monument (No.1013845)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Lime kiln 800ft (245m) north west of Langton Cross, Langton Herring</b>		
DESIGNATION:	Scheduled Monument (No.1002387)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 165m NNW of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.1013260)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 200m south of Winterbourne Poor Lot forming part of the Winterbourne Poor Lot round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.1013254)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 265m north west of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.1013261)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 300m WNW of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I013262)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 340m north west of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I013264)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 355m north west of White Hill Barn, forming part of the White Hill round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I013263)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 500m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I013250)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 600m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I013249)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 600m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I013253)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Black Down, 870m north west of the Hardy Monument, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I019030)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four bowl barrows 500m west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.I013252)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Three bowl barrows 300m south west of Well Bottom Wood, forming part of the Pitcombe Down round barrow cemetery, Littlebredy</b>		
DESIGNATION:	Scheduled Monument (No.1013251)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow 650yds (600m) north of North Barn Farm, Long Bredy</b>		
DESIGNATION:	Scheduled Monument (No.1002798)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow 700yds (640m) south west of North Barn Farm, Long Bredy</b>		
DESIGNATION:	Scheduled Monument (No.1002800)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Farm Hill 620m west of Minterne Parva Farm, Minterne Magna</b>		
DESIGNATION:	Scheduled Monument (No.1015046)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 230m north east of Great Strode House, Netherbury</b>		
DESIGNATION:	Scheduled Monument (No.1016372)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval settlement at West Ringstead, Osmington</b>		
DESIGNATION:	Scheduled Monument (No.1019393)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four barrows on Moigns Down, Owermoigne</b>		
DESIGNATION:	Scheduled Monument (No.1002774)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow south west of Bourne Farm, Piddlehinton</b>		
DESIGNATION:	Scheduled Monument (No.1004550)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories  
are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Two barrows on Little Puddle Hill, Piddlehinton</b>			
DESIGNATION:	Scheduled Monument (No.1003224)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two barrows west of Little Piddle Down, Piddlehinton</b>			
DESIGNATION:	Scheduled Monument (No.1002805)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Barrow on College Down, Piddletrenthide</b>			
DESIGNATION:	Scheduled Monument (No.1002842)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow on Plush Hill 600m ESE of Lower Farm, Plush, Piddletrenthide</b>			
DESIGNATION:	Scheduled Monument (No.1015037)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow on Plush Hill 740m ESE of Lower Farm, Plush, Piddletrenthide</b>			
DESIGNATION:	Scheduled Monument (No.1015038)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow on Pond Eweleaze 500m north east of Dole's Ash Farm, Piddletrenthide</b>			
DESIGNATION:	Scheduled Monument (No.1015035)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow on Hog Leaze, Piddletrenthide</b>			
DESIGNATION:	Scheduled Monument (No.1003238)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow on Black Down, 80m south east of the Hardy Monument, Portesham</b>			
DESIGNATION:	Scheduled Monument (No.1017374)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Group of round barrows on Shorn Hill and Bronkham Hill, Portesham</b>			
DESIGNATION:	Scheduled Monument (No.1002699)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow north east of Friar Waddon, Portesham</b>			
DESIGNATION:	Scheduled Monument (No.1002488)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows on Black Down immediately east of the Hardy Monument, Portesham</b>			
DESIGNATION:	Scheduled Monument (No.1016729)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two round barrows on Ridgeway, Portesham</b>			
DESIGNATION:	Scheduled Monument (No.1002758)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Barrow near east boundary of parish, Powerstock</b>			
DESIGNATION:	Scheduled Monument (No.1002809)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Group of barrows east of Northdown Barn, Poxwell</b>			
DESIGNATION:	Scheduled Monument (No.1002770)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow west of Druce Higher Barn, Puddletown</b>			
DESIGNATION:	Scheduled Monument (No.1002874)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Three round barrows on Puddletown Down, Puddletown</b>			
DESIGNATION:	Scheduled Monument (No.1002450)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two round barrows south west of Well House Cottage, Puddletown</b>			
DESIGNATION:	Scheduled Monument (No.1002875)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 400m north east of Look Farm, Puncknowle</b>			
DESIGNATION:	Scheduled Monument (No.1016370)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bell barrow 70m west of Fidler's Green, Stinsford</b>			
DESIGNATION:	Scheduled Monument (No.1017262)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Roman fort on Waddon Hill, Stoke Abbott</b>			
DESIGNATION:	Scheduled Monument (No.1002410)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow north east of Hog Hill Barn, Stratton</b>			
DESIGNATION:	Scheduled Monument (No.1003237)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow north west of Jackman's Cross, Stratton</b>			
DESIGNATION:	Scheduled Monument (No.1002470)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Round barrow on Stratton Down, Stratton</b>		
DESIGNATION:	Scheduled Monument (No.1002871)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Eype Down 275m east of Frogmore Farm, Symondsburry</b>		
DESIGNATION:	Scheduled Monument (No.1016100)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Holditch Court Tower, Thorncombe</b>		
DESIGNATION:	Scheduled Monument (No.1002835)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four bowl barrows 710m north, 750m north west and 950m north west of Clyffe House, Tolpuddle</b>		
DESIGNATION:	Scheduled Monument (No.1016378)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow near Eggardon, West Compton</b>		
DESIGNATION:	Scheduled Monument (No.1004567)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Dyke south east of Eggardon Hill camp, West Compton</b>		
DESIGNATION:	Scheduled Monument (No.1002404)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Whitcombe Hill 500m north of Whitcombe Farm, West Stafford</b>		
DESIGNATION:	Scheduled Monument (No.1017282)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure on Mount Pleasant Hill, West Stafford</b>		
DESIGNATION:	Scheduled Monument (No.1002463)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Two bowl barrows on Frome Hill 520m west of Frome Farm, West Stafford</b>		
DESIGNATION:	Scheduled Monument (No.1019875)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bowl barrows 530m and 350m north east of Whitcombe Barn, Whitcombe</b>		
DESIGNATION:	Scheduled Monument (No.1019413)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two round barrows north of Came Farm, Winterborne Came</b>		
DESIGNATION:	Scheduled Monument (No.1002828)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow immediately north west of Maiden Castle, Winterborne Monkton</b>		
DESIGNATION:	Scheduled Monument (No.1015779)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow, three bell barrows, fancy barrow and a linear earthwork 800m north of Maiden Castle, Winterborne Monkton</b>		
DESIGNATION:	Scheduled Monument (No.1015783)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow cemetery immediately south east of Maiden Castle, Winterborne Monkton</b>		
DESIGNATION:	Scheduled Monument (No.1015778)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Settlement remains north of Maiden Castle, Winterborne Monkton</b>		
DESIGNATION:	Scheduled Monument (No.1002409)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of barrows south of Goldsmith's Plantation, Winterborne St Martin</b>		
DESIGNATION:	Scheduled Monument (No.1002810)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Group of round barrows near Eweleaze Barn, Winterborne St Martin</b>			
DESIGNATION:	Scheduled Monument (No.1002756)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Group of round barrows on and to east of Great Hill, Winterborne St Martin</b>			
DESIGNATION:	Scheduled Monument (No.1004564)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow north of Ridgeway, Winterborne St Martin</b>			
DESIGNATION:	Scheduled Monument (No.1002759)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrows on Four Barrow Hill, Winterborne St Martin</b>			
DESIGNATION:	Scheduled Monument (No.1002755)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrows on Grove Hill, Winterborne St Martin</b>			
DESIGNATION:	Scheduled Monument (No.1002757)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three barrows south of Hart Hill Plantation, Winterborne St Martin</b>			
DESIGNATION:	Scheduled Monument (No.1002814)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two barrows at Rew, Winterborne St Martin</b>			
DESIGNATION:	Scheduled Monument (No.1002811)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bell barrow 100m south of Winterbourne Poor Lot, part of the Winterbourne Poor Lot round barrow cemetery, Winterbourne Abbas</b>			
DESIGNATION:	Scheduled Monument (No.1012027)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Bowl barrow 400m north east of Manor Farm, part of the Pound Hill round barrow cemetery, Winterbourne Abbas</b>		
DESIGNATION:	Scheduled Monument (No.1011692)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 450m north east of Manor Farm, part of the Pound Hill round barrow cemetery, Winterbourne Abbas</b>		
DESIGNATION:	Scheduled Monument (No.1011691)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of barrows near Big Wood, Winterbourne Abbas</b>		
DESIGNATION:	Scheduled Monument (No.1002696)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Triple barrow and bowl barrow forming part of a barrow cemetery and part of an associated field system 250m north east of Winterbourne Poor Lot, Winterbourne Abbas</b>		
DESIGNATION:	Scheduled Monument (No.1012030)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bell barrows 15m north of Well Bottom Wood, part of the Poor Lot round barrow cemetery, Winterbourne Abbas</b>		
DESIGNATION:	Scheduled Monument (No.1012029)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four round barrows north west of Blagdon Barn, Winterbourne Steepleton</b>		
DESIGNATION:	Scheduled Monument (No.1002750)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow on Pound Hill, Winterbourne Steepleton</b>		
DESIGNATION:	Scheduled Monument (No.1002687)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Round barrow on Pound Hill, Winterbourne Steepleton</b>		
DESIGNATION:	Scheduled Monument (No.1002870)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow south west of village, Winterbourne Steepleton</b>		
DESIGNATION:	Scheduled Monument (No.1002751)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrows on Sheep Down, Winterbourne Steepleton</b>		
DESIGNATION:	Scheduled Monument (No.1003306)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three round barrows east of Smitten Corner, Winterbourne Steepleton</b>		
DESIGNATION:	Scheduled Monument (No.1003308)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two round barrows on North Hill, Winterbourne Steepleton</b>		
DESIGNATION:	Scheduled Monument (No.1002865)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 1km south west of Manor Farm, Wraxall</b>		
DESIGNATION:	Scheduled Monument (No.1015051)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Kingston Maurward, Stinsford</b>	Designed landscape surrounding early C18 house. Later landscape phases include formal Edwardian gardens, now open to the public. House forms nucleus of expanding college. Many post-war and more recent buildings, with impacts on view lines and appreciation of designed landscape. Natural England has grant aided a plan for the park (completed 2011) which may help to guide future restoration and management.
DESIGNATION:	Registered Park and Garden Grade II*, also part in CA, 8 LBs, 1 SM	
CONDITION:	Generally satisfactory but with minor localised problems	
VULNERABILITY:	Medium	
TREND:	Improving	
OWNER TYPE:	Corporate, single owner	
		Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bothenhampton</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY:	No

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bradford Abbas</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Deteriorating
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Bradpole</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Broadwindsor</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Cattistock</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Charminster</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Charmouth</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Chickerell</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Chideock and Seatown</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Dorchester</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Frampton</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Herrison</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Litton Cheney</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Maiden Newton and Higher Frome Vauchurch</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Owermoigne</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Piddlethrenthide</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Portesham</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	Improving
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Puddletown</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Shipton Gorge</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Symondsburry</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>West Knighton</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Whitchurch Canonicorum</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

SITE NAME:	<b>Winterbourne Abbas</b>		
DESIGNATION:	Conservation Area	CONDITION:	At risk
VULNERABILITY:	Unknown	TREND:	No significant change
CONTACT:	Kim Sankey (LPA) 01305 251010	NEW ENTRY?:	No

## WEYMOUTH AND PORTLAND



SITE NAME: **Rufus Castle,  
Church Ope Road,  
Easton, Portland**

Present structure probably late C15, on site of earlier building captured in 1142 by Earl Robert of Gloucester. Ruinous and in need of conservative repair and consolidation. Scheme of repair and urgent works carried out in 2010 with English Heritage grant.

DESIGNATION: Listed Building Grade I, SM


CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: D (D)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Church of St Peter,  
Grove Road,  
Grove, Portland**

Former robust Romanesque church, 1872. Built by convict labour from Portland's prison and later transferred to the parish. No longer used for worship, and in poor condition.

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Sandsfoot Castle,  
Weymouth**

The castle is one of a pair built by Henry VIII to protect the Portland Anchorage, the other being Portland Castle. It is a scheduled monument and grade I listed. The castle is built on soft clays that even with the protection of the Portland Breakwaters suffer from ongoing erosion and instability. Works of consolidation and repair are nearing completion under scheduled monument consent and with HLF grant aid.

DESIGNATION: Listed Building Grade I, SM

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: F (F)

OWNER TYPE: Local authority

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Maiden Street Methodist Church,  
Maiden Street,  
Weymouth**

Former church. Fire in January 2002 left the church a gutted, roofless ruin. Subsequent health and safety works completely cleared the interior. Consent has been granted but not implemented for conversion/reconstruction to a mixed residential and commercial use. The new owners submitted an application for restoration of part of the building.

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: D (D)

OWNER TYPE: Religious organisation

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Battery 200yds (180m) east of the Naval cemetery, Portland</b>		
DESIGNATION:	Scheduled Monument (No.1002412)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>RAF Portland, site of Rotor early warning radar station, Portland</b>		
DESIGNATION:	Scheduled Monument (No.1021302)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Verne Citadel, Portland</b>		
DESIGNATION:	Scheduled Monument (No.1002411)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of round barrows on Ridgeway, Weymouth and Portland</b>		
DESIGNATION:	Scheduled Monument (No.1002760)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Lodmoor Hill</b>		
DESIGNATION:	Conservation Area	CONDITION:	Fair
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Colin Ellis (LPA) 01305 838334	NEW ENTRY:	No

**GLOUCESTERSHIRE****COTSWOLD**

SITE NAME:	<b>Barrington Park, Barrington</b>	Country house built circa 1736-38, extended late C19. Full repair of the house is nearing completion.
DESIGNATION:	Listed Building Grade I, CA, RPG II	
CONDITION:	Fair	
OCCUPANCY:	Vacant	
PRIORITY:	F (F)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Dovecote, Barrington Park, Barrington</b>	CI8 domed dovecote with Ionic portico on east side, located approximately 500 metres north west of the house in open parkland. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are completed.
DESIGNATION:	Listed Building Grade II*, CA, RPG II	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY:	F (F)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Gothick Seat (Temple), Barrington Park, Barrington</b>	Mid C18 garden temple, situated 100 metres to south west of the house in the gardens. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are completed.
DESIGNATION:	Listed Building Grade II*, CA, RPG II	
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY:	F (F)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Roman Doric Temple, Barrington Park, Barrington</b>
DESIGNATION:	Listed Building Grade II*, CA, RPG II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	F (F)
OWNER TYPE:	Private

Mid C18 garden temple located in the C18 gardens of Barrington Park. Emergency works to arrest further decay have been undertaken and full repairs will start when the house repairs are completed.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Elizabeth Pengree Memorial, The Square, Blockley</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Unknown

Commemorative monument (1770s) decaying on one side and the railings are in poor condition. Basic maintenance has been undertaken, but no significant repairs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Alfreds Hall, Cirencester Park, Cirencester</b>
DESIGNATION:	Listed Building Grade II*, CA, RPG I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Folly, begun 1721, designed by Lord Bathurst with Alexander Pope's advice, completed 1732. Probably the earliest C18 mock Gothic castle; part former house, part banqueting house and part mock ruin. Located in Oakley Wood, with rides radiating from it through the wood.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of St Mary the Virgin, Cowley</b>
DESIGNATION:	Listed Place of Worship Grade II*, CA
CONDITION:	Very bad
PRIORITY:	F (B)
OWNER TYPE:	Religious organisation

A small Cotswold stone church in a Cotswold village. The Cotswold stone slates are decaying badly having long reached the end of their life. A repair grant has been offered for the replacement of the stone slate roof coverings which will be renewed during 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of St Edward, Hawling</b>
DESIGNATION:	Listed Place of Worship Grade II*
CONDITION:	Very bad
PRIORITY:	F (B)
OWNER TYPE:	Religious organisation

A small Cotswold stone church in a Cotswold village. The stone tile roofs are falling apart and the gutters are leaking. A Repair Grant for Places of Worship has been offered for the renewal of the stone tile roofs and the repair of the rainwater goods, which will be completed in 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Two bowl barrows 690m and 790m north of The Manor Farm, Avening</b>	
DESIGNATION:	Scheduled Monument (No.I017337)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Perrott's Brook dykes, Bagendon</b>	
DESIGNATION:	Scheduled Monument (No.I003436)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Bowl barrow 800m north east of Beverston Castle Farm, Beverstone</b>			
DESIGNATION:	Scheduled Monument (No.1008197)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long barrow 800m north east of Oldwalls Farm, Bibury</b>			
DESIGNATION:	Scheduled Monument (No.1018163)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Wayside cross socket stone 125m NNW of Kilkenny Cottages, Bibury</b>			
DESIGNATION:	Scheduled Monument (No.1014414)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>West Barrow: a long barrow 200m west of Leighterton School, Boxwell with Leighterton</b>			
DESIGNATION:	Scheduled Monument (No.1013590)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Localised/limited animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round barrow north of Chedworth Roman villa, Chedworth</b>			
DESIGNATION:	Scheduled Monument (No.1003346)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Digging	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Settlement south east of Chesterton Farm, Cirencester</b>			
DESIGNATION:	Scheduled Monument (No.1003444)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Crickley Hill camp, Coberley</b>			
DESIGNATION:	Scheduled Monument (No.1003586)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows, known as Crippet's Wood round barrows, 560m and 590m north east of Dryhill Farm, Coberley</b>			
DESIGNATION:	Scheduled Monument (No.1017041)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Norbury Camp hillfort, Colesbourne</b>		
DESIGNATION:	Scheduled Monument (No.1018167)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Condicote bowl barrow, Condicote</b>		
DESIGNATION:	Scheduled Monument (No.1016080)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Tump Barn bowl barrow, Didmarton</b>		
DESIGNATION:	Scheduled Monument (No.1016077)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp at Upper Dowdeswell, Dowdeswell</b>		
DESIGNATION:	Scheduled Monument (No.1003321)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hillfort 320m north east of Castle Barn Farm, Dowdeswell</b>		
DESIGNATION:	Scheduled Monument (No.1018170)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Lineover long barrow, 530m south west of Castle Barn Farm, Dowdeswell</b>		
DESIGNATION:	Scheduled Monument (No.1018166)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow 750m north east of Eastleachdowns Farm, Eastleach</b>		
DESIGNATION:	Scheduled Monument (No.1016506)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow in Three Ash Belt, 460m north east of Westwood Farm, Edgeworth</b>		
DESIGNATION:	Scheduled Monument (No.1016840)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Settlement site south of Claydon Cottages, Fairford</b>		
DESIGNATION:	Scheduled Monument (No.1003443)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Mineral extraction / related subsidence	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow 300m west of Church Farm, Guiting Power</b>		
DESIGNATION:	Scheduled Monument (No.1017338)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Icomb camp, Icomb</b>		
DESIGNATION:	Scheduled Monument (No.1003342)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 450m west of Lasborough, Kingscote</b>		
DESIGNATION:	Scheduled Monument (No.1009159)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Chessalls Roman town, Kingscote</b>		
DESIGNATION:	Scheduled Monument (No.1018607)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roman villa 600yds (550m) north east of Great Lemhill Farm, Lechlade</b>		
DESIGNATION:	Scheduled Monument (No.1003420)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Chessels Roman site, Lower Slaughter</b>		
DESIGNATION:	Scheduled Monument (No.1003466)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>New Court Ground Roman villa (south of new buildings), Naunton</b>		
DESIGNATION:	Scheduled Monument (No.1003340)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Summerhill prehistoric site, Naunton</b>			
DESIGNATION:	Scheduled Monument (No.1003339)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow in Inlands Plantation, 650m south of Hazleton Manor Farm, Rodmarton</b>			
DESIGNATION:	Scheduled Monument (No.1008788)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows 180m south east of Haresdown Barn, Rodmarton</b>			
DESIGNATION:	Scheduled Monument (No.1008796)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 120m north of Home Farm, Sherborne</b>			
DESIGNATION:	Scheduled Monument (No.1017082)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>South Cerney castle, South Cerney</b>			
DESIGNATION:	Scheduled Monument (No.1003422)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows 260m north of Chalk Hill Cottage; part of the Cow Common round barrow cemetery, Swell</b>			
DESIGNATION:	Scheduled Monument (No.1008194)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows 80m north of Arch Hollow, Swell</b>			
DESIGNATION:	Scheduled Monument (No.1008621)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 990m south east of Bemborough Farm: part of the Bemborough Farm round barrow cemetery, Temple Guiting</b>			
DESIGNATION:	Scheduled Monument (No.1020654)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Earthwork north of Lyne's Barn, Temple Guiting</b>	
DESIGNATION: Scheduled Monument (No.1003328)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: No known threat	TREND: Declining
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 335m south east of Broadfield Farm, Tetbury Upton</b>	
DESIGNATION: Scheduled Monument (No.1016838)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: Extensive animal burrowing	TREND: Declining
OWNER TYPE: Other	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Four bowl barrows forming part of a round barrow cemetery, and a long barrow 550m NNE of Eyford Hill Farm, Upper Slaughter</b>	
DESIGNATION: Scheduled Monument (No.1020987)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY: Arable ploughing	TREND: Declining
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Syreford Farm bowl barrow, 450m south west of Oxpens, Whittington</b>	
DESIGNATION: Scheduled Monument (No.1018155)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY: Arable clipping	TREND: Declining
OWNER TYPE: Private	CONTACT: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: <b>Hatherop Castle, Hatherop/Quenington</b>
DESIGNATION: Registered Park and Garden Grade II, also part in CA, 2 LBs, 1 SM
CONDITION: Generally unsatisfactory with major localised problems
VULNERABILITY: Medium
TREND: Stable
OWNER TYPE: Mixed, multiple owners

Hatherop is thought to have been landscaped by 'Capability' Brown's contemporary Richard Woods and then reworked extensively in the C19. The main house is occupied by a school with an adjacent area of new build. The wider parkland, in separate ownership, is neglected: many parkland trees have gone, clumps and ornamental woodland are over-mature and decaying, and sections of park wall and estate railings are in very poor condition.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

## FOREST OF DEAN



SITE NAME: <b>Blakeney United Reformed Church, Cinderford Road, Blakeney, Awre</b>
DESIGNATION: Listed Building Grade II*, CA
CONDITION: Fair
OCCUPANCY: N/A
PRIORITY: F (F)
OWNER TYPE: Private

Former non-conformist chapel, dated 1849. Remarkably complete and architecturally distinctive example of its type. Stonework repairs required. Other repairs ongoing.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: <b>Guns Mill Barn, Littledean</b>
DESIGNATION: Listed Building Grade II*, SM
CONDITION: Very bad
OCCUPANCY: Vacant
PRIORITY: A (A)
OWNER TYPE: Private

Formerly a blast furnace and later a paper mill, built 1682. Now unused and in perilous condition, despite some emergency holding repairs. A meeting with the owner autumn 2011 was very positive and the options for the future of the site are opening up. Development grant aid is being organised to assist the determination of the future of the building.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Lydney Docks and Harbour,  
Naas Lane,  
Lydney**

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Government

The docks and harbour date from about 1810 to 1821 and were once the main commercial port serving industry in the district. Outer basin now repaired with surrounding area used for recreation, however the Inner Basin is still in poor condition.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Tithe Barn, Highleadon Court,  
Rudford and Highleadon**

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

CI5 or early CI6 Tithe barn built for the Abbey of St Peter, Gloucester. The roof is sound, but the framing and infill panels are deteriorating. Used for agricultural storage. Some maintenance undertaken.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **St James Church,  
Lancaut,  
Tidenham**

DESIGNATION: Listed Building Grade II, SM

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: F (F)

OWNER TYPE: Trust

Small CI2 chapel with later medieval extension to west. Unroofed rubble-built structure with slow deterioration of stonework and internal plasterwork. A condition survey funded by English Heritage highlighted the works needed to halt further deterioration and with a recommendation for the wall heads to be soft-capped.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Church of St John the Evangelist,  
Boxbush Road,  
Coleford**

DESIGNATION: Listed Place of Worship Grade II

CONDITION: Poor

PRIORITY: B (B)

OWNER TYPE: Religious organisation

A late Victorian Anglican parish church overlooking the centre of Coleford, the last phase of which was completed in 1907. The roof has been partly repaired but the remainder is leaking badly, which has damaged the interior of the church. A Repair Grant for Places of Worship was successfully applied for in 2010 for roof repairs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Church of St Edward the Confessor,  
Kempley**

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Poor

PRIORITY: B (New entry)

OWNER TYPE: Religious organisation

The church was built in 1903 to the designs of the architect Randall Wells, in the Arts and Crafts style. The valley gutter needs urgent replacement to prevent rainwater from entering the church. Problems of dampness are also evident at low level. The perimeter channel has many cracks and open joints, including next to the walls, where water seeps through and keeps the feet of the walls wet. Horizontal cracks have appeared in all four buttresses. The church successfully applied for a Repair Grant for Places of Worship in 2011.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Church of St Mary,  
Church Street,  
Newent**

DESIGNATION: Listed Place of Worship Grade I, CA

CONDITION: Poor

PRIORITY: F (A)

OWNER TYPE: Religious organisation

A large church in the centre of Newent. The stonework of the tower is heavily eroded, increasingly badly the higher it gets. The stone parapets are in the worst condition and feel insecure. Past deathwatch beetle attack in the tower and the nave lintels needs to be independently investigated and a control strategy established. The church has successfully applied for a grant for repair work and which will start 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Whitecliff Iron Works, Coleford</b>		
DESIGNATION:	Scheduled Monument (No.1021420)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Symonds Yat promontory fort, English Bicknor</b>		
DESIGNATION:	Scheduled Monument (No.1016760)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Soudley camp, Lower Soudley, Ruspidge and Soudley</b>		
DESIGNATION:	Scheduled Monument (No.1005564)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Offa's Dyke: section 240m north east of Buttington Farm, Tidenham</b>		
DESIGNATION:	Scheduled Monument (No.1020643)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Offa's Dyke: section in Boatwood Plantation, 320m south west of Chase Farm, Tidenham</b>		
DESIGNATION:	Scheduled Monument (No.1020606)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Offa's Dyke: section in Caswell Wood, 280m west of Beeches Farm, Tidenham</b>		
DESIGNATION:	Scheduled Monument (No.1020601)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Offa's Dyke: section in Chapelhouse Wood, 240m west of the Recreation Ground, Tidenham</b>		
DESIGNATION:	Scheduled Monument (No.1020639)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Offa's Dyke: section in Passage Grove, 660m west of Sheepcot, Tidenham</b>		
DESIGNATION:	Scheduled Monument (No.1020603)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Offa's Dyke: section in Shorncliff Wood including the Devil's Pulpit, 790m south west of Sheepcot, Tidenham</b>		
DESIGNATION:	Scheduled Monument (No.1020604)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Offa's Dyke: section in Worgan's Wood, 800m west of Chase Farm, Tidenham</b>		
DESIGNATION:	Scheduled Monument (No.1020605)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roman villa 600yds (550m) south west of Woolaston station, Woolaston</b>		
DESIGNATION:	Scheduled Monument (No.1004860)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## GLOUCESTER



SITE NAME: **Tanner's Hall,  
north of city centre,  
Gouda Way, Gloucester**

DESIGNATION: Scheduled Monument  
CONDITION: Very bad  
OCCUPANCY: N/A  
PRIORITY: B (B)  
OWNER TYPE: Private

This is a rare survival of a C13 merchant's house, later converted to a tannery and Tanner's Hall. Surrounding buildings have been removed for the inner relief road. Scheduled monument consent has been granted for a scheme to repair and consolidate the Hall within an encasing new development.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Llanthony Priory, range between  
Outer and Inner Courts,  
Llanthony Road, Gloucester**

DESIGNATION: Listed Building Grade I, SM  
CONDITION: Very bad  
OCCUPANCY: Vacant  
PRIORITY: C (B)  
OWNER TYPE: Trust

Remains of the range between the Outer and Inner Courts of the Augustinian Priory of Llanthony Secunda. Late C14 and early C16. Vacant buildings subject to vandalism. Timber frame decaying; brick and stonework eroded. Works were carried out in March 2012 to make the Priory Lodgings wind and weather proof and to eradicate dry rot. Funding is now being sought by the trustees for some structural repairs.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Llanthony Priory, remains of precinct  
wall north of Inner Gatehouse,  
Llanthony Road, Gloucester**

DESIGNATION: Listed Building Grade I, SM  
CONDITION: Poor  
OCCUPANCY: N/A  
PRIORITY: C (C)  
OWNER TYPE: Trust

Stone and brick wall on the west and north sides of the Outer Court of the former Augustinian Priory. Built in the C15, it was rebuilt or extended in the C17 and C18. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



**SITE NAME:** Llanthony Priory, remains of precinct wall south of Outer Gatehouse, Llanthony Road, Gloucester

**DESIGNATION:** Listed Building Grade I, SM

**CONDITION:** Very bad

**OCCUPANCY:** N/A

**PRIORITY:** C (C)

**OWNER TYPE:** Trust

Early C16 brick wall. Badly eroded especially at low level. Two brick piers constructed 1995 to support wall to provide support in event that condition of wall deteriorates, but these have now rotated away from back of wall. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



**SITE NAME:** Llanthony Priory, remains of range on south side of Inner Court, Llanthony Road, Gloucester

**DESIGNATION:** Listed Building Grade I, SM

**CONDITION:** Very bad

**OCCUPANCY:** N/A

**PRIORITY:** C (B)

**OWNER TYPE:** Trust

Remains of the range on the south side of the Inner Court of the Augustinian Priory of Llanthony Secunda. Early C16. Subject to vandalism. The Llanthony Priory Trust is looking to raise funds and investigate suitable future uses for the site.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



**SITE NAME:** The Fleece Hotel, 19 Westgate Street, Gloucester

**DESIGNATION:** Listed Building Grade I, CA

**CONDITION:** Poor

**OCCUPANCY:** Vacant

**PRIORITY:** C (C)

**OWNER TYPE:** Local authority

C15 timber-framed range most recently occupied as the Fleece Hotel. The building has been vacant for sometime. It is in poor repair, with some internal decay. A series of opening up works were carried out early summer 2010 to provide more information on the condition. Ownership has passed to Gloucester City Council who are undertaking emergency repairs and considering longer term solutions.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



**SITE NAME:** Old Judges House, 26 Westgate Street, Gloucester

**DESIGNATION:** Listed Building Grade I, CA

**CONDITION:** Poor

**OCCUPANCY:** Vacant

**PRIORITY:** C (New entry)

**OWNER TYPE:** Company

Late C15 timber framed merchant house, greatly enlarged and remodelled in late C16/early C17. Refronted and altered internally c1815. Operated as seed merchant for c100 years until 1989, then partly occupied as bookshop, but vacant for last two years. Whilst some repairs being undertaken, there are many areas which require attention relating to general decay, water ingress and previous use of cement for repairs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:

**Southgate Street**

<b>DESIGNATION:</b>	Conservation Area	<b>CONDITION:</b>	Very bad
<b>VULNERABILITY:</b>	Low	<b>TREND:</b>	Improving
<b>CONTACT:</b>	Charlotte Lewis (LPA) 01452 396855	<b>NEW ENTRY:</b>	No

**STROUD**



**SITE NAME:** St Marys House, London Road, Chalford

**DESIGNATION:** Listed Building Grade II\*, CA

**CONDITION:** Poor

**OCCUPANCY:** Part occupied

**PRIORITY:** A (A)

**OWNER TYPE:** Private

Former mill owner's house and weavers' cottages, late C16 and late C17. Roof in exceptionally poor condition and is covered with tarpaulin.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



**SITE NAME:** Main building at Stanley Mills, Ryeford, Kings Stanley

**DESIGNATION:** Listed Building Grade I, CA

**CONDITION:** Fair

**OCCUPANCY:** Part occupied

**PRIORITY:** E (E)

**OWNER TYPE:** Company

Woollen mill, 1813. Ancillary building (grade II) is in poor condition and part occupied. Roof repaired with English Heritage grant. A proposal for repair and conservation has been granted consent.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



SITE NAME:	<b>Former Saxon church to west of Priory House, Leonard Stanley</b>
DESIGNATION:	Listed Building Grade II*, SM, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Private

Former Saxon and medieval chapel within core of former priory of St Leonard. Later converted to agricultural use including dovecotes and forge. Threshing floor in situ. Currently used for vehicle/equipment storage. English Heritage Grant aid has been offered and accepted. This is currently enabling the repair works to be assessed and organised.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Brownhill Court, Wick Street, Painswick</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Private

Early to mid C18 country house converted into flats, which are now vacant. The house has been the subject of a closing order and parts are now in a dangerous condition. The house has been inherited by a new owner; no works yet undertaken.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Woodchester Mansion, Woodchester</b>
DESIGNATION:	Listed Building Grade II*, RPG II
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Trust

Mansion c1854-68 incorporating a magnificent private chapel. The Woodchester Mansion Trust was formed in 1989 to do a continuous programme of conservation and display of the uncompleted gothic-style masterpiece. In 1991 a protective scaffold was built to cover the leaking roof of the chapel. The scaffold is now decaying and unsafe. Repairs are immediately needed to the scaffold or, ideally, the roof underneath.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Two bowl barrows, known as Climperwell round barrows, 310m south west of Climperwell Farm, Cranham</b>	
DESIGNATION:	Scheduled Monument (No. I017074)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>The Mount moated site, Haresfield</b>	
DESIGNATION:	Scheduled Monument (No. I020655)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Tresham Farbarrow round barrows, Hillesley and Tresham</b>	
DESIGNATION:	Scheduled Monument (No. I002115)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Bowl barrow 450m south east of Upper Hyde Farm, Minchinhampton</b>	
DESIGNATION:	Scheduled Monument (No. I008626)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND: Declining
OWNER TYPE:	Other	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Gatcombe long barrow, 400m east of Gatcombe Farm, Minchinhampton</b>		
DESIGNATION:	Scheduled Monument (No.1008623)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>West Hill Romano-Celtic temple, Uley</b>		
DESIGNATION:	Scheduled Monument (No.1002076)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 720m south east of Longwood Farm, Woodchester</b>		
DESIGNATION:	Scheduled Monument (No.1017084)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 330m north of Symonds' Hall Farm, Wotton-under-Edge</b>		
DESIGNATION:	Scheduled Monument (No.1017083)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## TEWKESBURY

SITE NAME:	<b>Dovecote approx 75 metres south east of Manor Farm, Fiddington, Ashchurch</b>	Dovecote, 1637. Pointing eroded particularly on the north face. Occasional missing roof tiles, although some roofing works have commenced.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY:	E (C)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Dovecote 3 metres north of Bridge House, Bentham, Badgeworth</b>	Dovecote, C17. Movement of structural timbers on south east and north east walls has caused joints to pull apart, leading to brick panels falling out. Wattle and daub panels are also fragmenting. Some timber decay on west side. Cement repairs to roof.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY:	C (C)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Malthouse to the rear of, 23 Barton Street, Tewkesbury</b>	Workshop, former malthouse. C17. Building has been unoccupied for some time and although discussions have been held with the owner, no applications have yet been forthcoming.
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	C (C)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site



SITE NAME: **88 Church Street,  
Tewkesbury**

Late C15 town house, altered C16 and C19, with shop under: Building only partly occupied and in poor condition with broken windows on second floor.

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Poor

OCCUPANCY: Part occupied

PRIORITY: C (C)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Toddington House,  
Church Lane,  
Toddington**

Manor house, 1820-35, set in C19 formal gardens, on the east side of a late C18 landscape park. The house has been mothballed for more than 15 years, but has recently been purchased by a new owner who has installed a temporary roof and is engaging in an extensive programme of urgent works and repairs in consultation with the Local Planning Authority and English Heritage.

DESIGNATION: Listed Building Grade I, RPG II

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Nottingham Hill camp, Gotherington**

DESIGNATION: Scheduled Monument (No.1004864)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Great Witcombe Romano-British villa, Great Witcombe**

DESIGNATION: Scheduled Monument (No.1014826)

CONDITION: Generally unsatisfactory  
with major localised problems

PRINCIPAL VULNERABILITY: Deterioration - in need of management

TREND: Declining

OWNER TYPE: Government or Agency

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 690m south west of Roel Farm, Hawling**

DESIGNATION: Scheduled Monument (No.1017076)

CONDITION: Generally satisfactory  
but with significant localised problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Bowl barrow 760m south of Roel Farm, Hawling**

DESIGNATION: Scheduled Monument (No.1017077)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Two bowl barrows known as Hawling Downs round barrows,  
610m north east of Slade Barn Farm, Hawling**

DESIGNATION: Scheduled Monument (No.1017037)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WH** World Heritage Site

SITE NAME:	<b>Hailes Abbey and ringwork, Stanway</b>		
DESIGNATION:	Scheduled Monument (No.1018070)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hailes Wood camp, Hailes, Stanway</b>		
DESIGNATION:	Scheduled Monument (No.1004843)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Milhampost Roman site, Stanway</b>		
DESIGNATION:	Scheduled Monument (No.1004844)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wadfield Roman villa, Sudeley</b>		
DESIGNATION:	Scheduled Monument (No.1004846)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Moat House moated site, Uckington</b>		
DESIGNATION:	Scheduled Monument (No.1016835)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Deserted medieval village, Walton Cardiff</b>		
DESIGNATION:	Scheduled Monument (No.1002071)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Romano-British villa 170m south west of Winchcombe School, Greet Road, Winchcombe</b>		
DESIGNATION:	Scheduled Monument (No.1021449)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Woodmancote</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	High	TREND:	No significant change
CONTACT:	Siân Hughes (LPA) 01684 272060	NEW ENTRY:	Yes

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories  
are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

## ISLES OF SCILLY (UA)



SITE NAME: **Post medieval cottages, Samson**

Fossilised C18/C19 landscape. The remains of the buildings are at risk from natural weathering, vegetation and erosion caused by visitors. A management plan has been devised and initial phase of consolidation grant-aided by English Heritage is now complete. The result of the consolidation trials are being studied to inform a wider programme of repair.

DESIGNATION: Scheduled Monument, CA

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Trust

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Civil War battery on The Green, Bryher**

DESIGNATION: Scheduled Monument (No.1010176)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Moderate vehicle damage/erosion

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Gig shed on the north coast of Great Porth, Bryher**

DESIGNATION: Scheduled Monument (No.1016173)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Dumping

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Prehistoric enclosure south east of The Brow, Bryher**

DESIGNATION: Scheduled Monument (No.1015649)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Prehistoric field system and post-medieval quay in Great Porth, Bryher**

DESIGNATION: Scheduled Monument (No.1014987)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Coastal erosion

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Prehistoric field system and Romano-British cist in Green Bay, Bryher**

DESIGNATION: Scheduled Monument (No.1014989)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Collapse

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: **Prehistoric hut circle south of The Brow, Bryher**

DESIGNATION: Scheduled Monument (No.1014990)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Other

TREND: Declining

OWNER TYPE: Other

CONTACT: Principal Heritage at Risk Adviser 0117 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Prehistoric linear boundary and cairns south west of The Bar, Bryher</b>		
DESIGNATION:	Scheduled Monument (No.1016170)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric linear boundary SSE of The Island, Bryher</b>		
DESIGNATION:	Scheduled Monument (No.1014991)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Platform cairn on Cruther's Neck, St Martin's</b>		
DESIGNATION:	Scheduled Monument (No.1013806)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric cairn cemetery and field system on Tinkler's Hill, St Martin's</b>		
DESIGNATION:	Scheduled Monument (No.1018109)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric house platform settlement south west of English Island Carn, St Martin's</b>		
DESIGNATION:	Scheduled Monument (No.1018115)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric settlement and Romano-British shrine on Nornour, St Martin's</b>		
DESIGNATION:	Scheduled Monument (No.1015674)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric to Romano-British ritual, funerary and settlement remains on Par Beach, St Martin's</b>		
DESIGNATION:	Scheduled Monument (No.1018116)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Ennor Castle, Old Town, St Mary's</b>			
DESIGNATION:	Scheduled Monument (No.1014994)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Hut circle settlement in Pendrathen, St Mary's</b>			
DESIGNATION:	Scheduled Monument (No.1015663)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Iron Age to Romano-British fogou on northern Peninnis Head, 170m south of Carn Gwavel Farm, St Mary's</b>			
DESIGNATION:	Scheduled Monument (No.1020142)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Unknown
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Kerbed platform cairn on Helvear Hill, 210m ENE of Helvear Farm, St Mary's</b>			
DESIGNATION:	Scheduled Monument (No.1010168)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Post-medieval breastwork, curtain wall and associated defensive structures on the periphery of The Garrison, St Mary's</b>			
DESIGNATION:	Scheduled Monument (No.1018370)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Prehistoric settlement, Romano-British cist cemetery and Civil War battery in northern Toll's Porth, St Mary's</b>			
DESIGNATION:	Scheduled Monument (No.1015664)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Round cairn 137m east of Helvear Farm, St Mary's</b>			
DESIGNATION:	Scheduled Monument (No.1010167)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>The Giant's Castle cliff castle, St Mary's</b>		
DESIGNATION:	Scheduled Monument (No.1011935)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Old Quay, Old Town Bay, St Mary's</b>		
DESIGNATION:	Scheduled Monument (No.1015656)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>World War II pillbox between Thomas' Porth and Porthaloo, St Mary's</b>		
DESIGNATION:	Scheduled Monument (No.1016517)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>World War II pillbox west of Porth Hellick, 90m north of Drum Rock, St Mary's</b>		
DESIGNATION:	Scheduled Monument (No.1016516)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Post-medieval animal-driven crushing mill 270m south west of Blockhouse Cottage, Tresco</b>		
DESIGNATION:	Scheduled Monument (No.1016186)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric field system and settlement in Bathinghouse Porth, Tresco</b>		
DESIGNATION:	Scheduled Monument (No.1016423)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric field system and settlement north of Appletree Point, Tresco</b>		
DESIGNATION:	Scheduled Monument (No.1016182)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Coastal erosion	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Prehistoric round cairn 255m south west of Blockhouse Cottages, Tresco</b>		
DESIGNATION:	Scheduled Monument (No.1016187)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>St Nicholas' Priory, Tresco</b>		
DESIGNATION:	Scheduled Monument (No.1016184)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## NORTH SOMERSET (UA)



SITE NAME:	<b>Ashton Court, Long Ashton</b>
DESIGNATION:	Listed Building Grade I, RPG II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Local authority

Large country house dating from C15, C17, C18 and C19. House partly used but large part remains derelict and subject to slow but ongoing decay. The house has been the subject of negotiations between owners, Local Planning Authority, English Heritage and other interested parties for many years. English Heritage grant offered 2011 for project development works being carried out in 2012.


Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Elms Colliery, Nailsea</b>
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Local authority

One of the most complete examples of a late C18 colliery remaining in England. There are three standing structures and further exposed archaeological remains. All buildings are unroofed, derelict and subject to neglect and vandalism. Wall top consolidation completed.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Birnbeck Pier, Weston Super Mare</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied
PRIORITY:	A (A)
OWNER TYPE:	Company

Main pier which connects Birnbeck Island to the mainland below the Prince Consort Gardens. Dated 1862, opened 1867. Disused apart from the lifeboat station on the island. Negotiations ongoing between local planning authority, owner, English Heritage and other interested parties about repair of pier and development of island. Trial repairs have been grant-aided by EH to help establish likely total repair costs.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Orangery at Tyntesfield, Tyntesfield, Wraxall</b>
DESIGNATION:	Listed Building Grade II*, RPG II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	F (F)
OWNER TYPE:	Charity

Orangery (1897). Tyntesfield House and estate was acquired in 2002 by the National Trust with funding from the Heritage Lottery Fund. The Trust is in the process of drawing up a strategy for the various elements. A temporary roof has been installed. An application for listed building consent was approved in 2010. Repairs are underway.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Birnbeck, Weston-Super-Mare</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Marianna Porter (LPA) 01934 426 250	NEW ENTRY:	No

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Boulevard/Montpelier</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Marianna Porter (LPA) 01934 426 250	NEW ENTRY?:	No

SITE NAME:	<b>Clevedon Triangle</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Marianna Porter (LPA) 01934 426 250	NEW ENTRY?:	No

SITE NAME:	<b>Melrose/Grove Park, Weston-Super-Mare</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Marianna Porter (LPA) 01934 426 250	NEW ENTRY?:	No

## PLYMOUTH, CITY OF (UA)



SITE NAME: **Agaton Fort, Plymouth**

Heavy Goods Vehicle testing centre is located within a modern building in the Fort. Some ancillary buildings are vacant but have been subject to remedial repairs.

DESIGNATION: Scheduled Monument  
CONDITION: Fair  
OCCUPANCY: Part occupied  
PRIORITY: C (C)  
OWNER TYPE: Government

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **The coastal fortifications of Drakes Island, Plymouth**

The Island incorporates numerous defences/military monuments from 1549-C20. It was held for Parliament during the Civil War and used for defence purposes until 1958. More recently it was used as an outdoor pursuits centre. All buildings and structures are thought to be in a poor state. A planning application for regeneration as hotel conversion has been drawn up in consultation with EH and submitted to LPA.

DESIGNATION: Listed Building Grade II, SM  
CONDITION: Poor  
OCCUPANCY: Vacant  
PRIORITY: C (C)  
OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Boringdon Arch, Plymbridge Road, Plymouth**

Designed by Robert Adam and built in 1783, it is believed the arch was built as a triumphal arch and eye-catcher to be viewed from Saltram House. Its repair was included in a Section 106 agreement associated with consent for adjacent golf course, but work on the arch is yet to start.

DESIGNATION: Listed Building Grade II\*, SM  
CONDITION: Poor  
OCCUPANCY: N/A  
PRIORITY: D (D)  
OWNER TYPE: Private

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Melville, Royal William Victualling Yard, Plymouth**

The Melville building was constructed circa 1826-32 as stores and offices for the Victualling Board to the design of Sir John Rennie Jnr and forms part of the impressive Royal William Yard. Whilst the majority of the Yard has been successfully developed, with a combination of public and private finance, a sustainable future of Melville has yet to be secured.

DESIGNATION: Listed Building Grade I, CA  
CONDITION: Poor  
OCCUPANCY: Part occupied  
PRIORITY: C (New entry)  
OWNER TYPE: Local authority

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

	<p><b>SITE NAME:</b> Old Cooperage, Royal William Yard, Plymouth</p> <p><b>DESIGNATION:</b> Listed Building Grade I, CA</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> C (New entry)</p> <p><b>OWNER TYPE:</b> Local authority</p>	<p>The Cooperage was built circa 1826-32 for the Victualling Board, to the design of Sir John Rennie Jnr and forms part of the impressive Royal William Yard. Whilst the majority of the Yard has been successfully developed, with a combination of public and private finance, a sustainable future of the Cooperage has yet to be secured.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Woodland Fort, Crownhill Road, Crownhill, Plymouth</p> <p><b>DESIGNATION:</b> Scheduled Monument</p> <p><b>CONDITION:</b> Very bad</p> <p><b>OCCUPANCY:</b> Part occupied</p> <p><b>PRIORITY:</b> C (C)</p> <p><b>OWNER TYPE:</b> Local authority</p>	<p>Palmerston Fort, built 1863-1869. Part of barrack block in use as social club, but the rest is empty. Remedial repairs have been undertaken and some of the heavy vegetation has recently been cleared. Site is prone to vandalism and rubbish dumping. English Heritage and Plymouth City Council are considering the results of a joint funded study to look at regeneration and conservation options.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Oddfellows Hall, Ker Street, Devonport, Plymouth</p> <p><b>DESIGNATION:</b> Listed Building Grade I</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Occupied</p> <p><b>PRIORITY:</b> C (C)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Hall by John Foulston, 1823, in the Egyptian style. Part of a group with the Guildhall and Devonport Column. Egyptian columns flank a central, recessed porch. Currently used as a social club and in poor repair. English Heritage has previously grant-aided a feasibility study and emergency repairs to the roof.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Efford Fort and Emplacement, Military Road, Efford, Plymouth</p> <p><b>DESIGNATION:</b> Scheduled Monument</p> <p><b>CONDITION:</b> Very bad</p> <p><b>OCCUPANCY:</b> Part occupied</p> <p><b>PRIORITY:</b> A (A)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Palmerston Fort built 1863-1869. Partially occupied as parade ground is used for storage, but all buildings are vacant. Buildings are suffering from extreme neglect and decay and heavy vegetation growth. Extensive water penetration and structural problems are apparent. No solution agreed at present.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> South Saw Mills, South Yard, HM Naval Base, Plymouth</p> <p><b>DESIGNATION:</b> Listed Building Grade II*</p> <p><b>CONDITION:</b> Fair</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> E (E)</p> <p><b>OWNER TYPE:</b> Government</p>	<p>Sawmill of 1856-59. The saw mills ceased to be used as such in 1987 but the ground floor remained in light industrial use and for storage until 1997. An options report was issued in 2010, but the building remains vacant with no identifiable use.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> South Smithery, South Yard, HM Naval Base, Plymouth</p> <p><b>DESIGNATION:</b> Listed Building Grade II*</p> <p><b>CONDITION:</b> Very bad</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> A (A)</p> <p><b>OWNER TYPE:</b> Government</p>	<p>Dockyard smithery built 1771, modified in the C19 and reconstructed circa 1897. It remained in use until 1987 when structural faults were discovered. There is continued deterioration of the roof, masonry and interiors. An options report was issued in 2010, but a repair strategy has not been put in place.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

<b>CA</b>	Conservation Area
<b>LB</b>	Listed Building
<b>LPA</b>	Local Planning Authority
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WHS</b>	World Heritage Site



SITE NAME: **Amphitheatre in grounds of Saltram House, Merafield Road, Plympton, Plymouth**

DESIGNATION: Listed Building Grade II\*, RPG II\*

CONDITION: Fair

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Charity

Late CI8 screen wall fronting rock-cut grottos overlooking the River Plym. Surrounding rock faces have become unstable and are subject to collapse. Repair of the amphitheatre has been identified as a key objective in a draft landscape masterplan for the Saltram area.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Academy Theatre and Great Western Hotel (Palace Theatre), Union Street, Stonehouse, Plymouth**

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

Former variety theatre and hotel, 1898. Building gradually deteriorating. A significant building in a major regeneration area. English Heritage has offered grant aid in the past, which was not taken up. Temporary repairs undertaken in 1997. Currently in very bad condition with water penetration causing internal floors to become dangerous.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Austin Fort and section of military road, Plymouth**

DESIGNATION: Scheduled Monument (No.1021380)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Scrub/tree growth

TREND: Stable

OWNER TYPE: Local authority

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Efford Fort and Efford Emplacement, Plymouth**

DESIGNATION: Scheduled Monument (No.1021135)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Deterioration - in need of management

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Egg Buckland keep, Plymouth**

DESIGNATION: Scheduled Monument (No.1020543)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Development requiring planning permission

TREND: Unknown

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Fort Stamford, Plymouth**

DESIGNATION: Scheduled Monument (No.1002544)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Permitted development

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Knowle Battery, Plymouth**

DESIGNATION: Scheduled Monument (No.1002614)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Rain entry

TREND: Unknown

OWNER TYPE: Local authority

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	<b>Laira Battery, Plymouth</b>		
DESIGNATION:	Scheduled Monument (No.1021134)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Laira Emplacement, immediately south west of Laira Battery, Plymouth</b>		
DESIGNATION:	Scheduled Monument (No.1020686)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Plympton Castle, Plymouth</b>		
DESIGNATION:	Scheduled Monument (No.1003865)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Plympton Priory, Plymouth</b>		
DESIGNATION:	Scheduled Monument (No.1017594)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stonehouse Manor wall, Plymouth</b>		
DESIGNATION:	Scheduled Monument (No.1003850)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The coastal fortifications of Drake's Island, Plymouth</b>		
DESIGNATION:	Scheduled Monument (No.1010910)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Woodland fort, Plymouth</b>		
DESIGNATION:	Scheduled Monument (No.1002615)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Improving
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Union Street</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Medium	TREND:	No significant change
CONTACT:	Mike Daniells (LPA) 01752 304 397	NEW ENTRY:	No

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

**POOLE (UA)**

SITE NAME:	<b>Round barrow cemetery on Barrow Hill 150m south west of Brookvale Farm, Poole</b>		
DESIGNATION:	Scheduled Monument (No.1018029)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Branksome Park, Canford Cliffs</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Nigel Jacobs (LPA) 01202 633 328	NEW ENTRY:	No

SITE NAME:	<b>Evening Hill, Canford Heath, Poole</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating significantly
CONTACT:	Nigel Jacobs (LPA) 01202 633 328	NEW ENTRY:	No

SITE NAME:	<b>Haven Road, Canford Cliffs, Poole</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Nigel Jacobs (LPA) 01202 633 328	NEW ENTRY:	No

SITE NAME:	<b>High Street, Town Centre, Poole</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving
CONTACT:	Nigel Jacobs (LPA) 01202 633 328	NEW ENTRY:	No

SITE NAME:	<b>Sandbanks, Canford Cliffs, Poole</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Low	TREND:	Deteriorating
CONTACT:	Nigel Jacobs (LPA) 01202 633 328	NEW ENTRY:	No

**SOMERSET****EXMOOR (NP)**

SITE NAME:	<b>Barlinch Priory, Brompton Regis, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1006213)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Carnarvon New Pit iron mine and section of mineral railway trackbed, 300m south west of Heather House, Brompton Regis, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1021352)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Later prehistoric defended enclosure, Long Wood, Carhampton, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1008255)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Other	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Mounsey Castle, Dulverton, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1021357)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Post-medieval pottery kiln 360m NNE of the Castle, Dunster, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1020409)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Cow Castle, Exmoor, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1002955)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long Chains Combe North: a stone setting 120m WNW of the sheepfold, Exmoor, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1014280)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Iron Age defended settlement above Sweetworthy (eastern of two), Luccombe, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1008471)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Iron Age defended settlement above Sweetworthy (western of two), Luccombe, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1008472)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME:</b> Sweetworthy deserted medieval settlement, Luccombe, West Somerset			
<b>DESIGNATION:</b>	Scheduled Monument (No.1008469)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Berry Castle, Iron Age enclosure in Berry Castle Wood, Porlock, West Somerset			
<b>DESIGNATION:</b>	Scheduled Monument (No.1006204)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Scrub/tree growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Local authority	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Stone circle, Porlock Common, Porlock, West Somerset			
<b>DESIGNATION:</b>	Scheduled Monument (No.1006189)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Other	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Allerford New Bridge, Selworthy, West Somerset			
<b>DESIGNATION:</b>	Scheduled Monument (No.1006197)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Moderate vehicle damage/erosion	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Local authority	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Allerford packhorse bridge, immediately north of Cross Lane Farm, Selworthy, West Somerset			
<b>DESIGNATION:</b>	Scheduled Monument (No.1020776)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Other	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Bury Castle, an Iron Age defended settlement, Selworthy, West Somerset			
<b>DESIGNATION:</b>	Scheduled Monument (No.1008808)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Scrub/tree growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Staddon Hill camp, Winsford, West Somerset			
<b>DESIGNATION:</b>	Scheduled Monument (No.1021359)	<b>CONDITION:</b>	Generally satisfactory but with minor localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

<b>CA</b>	Conservation Area
<b>LB</b>	Listed Building
<b>LPA</b>	Local Planning Authority
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WHS</b>	World Heritage Site

SITE NAME:	<b>Brightworthy Barrows on Withypool Common, Withypool and Hawkridge, West Somerset</b>		
DESIGNATION:	Scheduled Monument (No.1021264)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## MENDIP



SITE NAME:	<b>Kilmersdon Lodges, Kilmersdon</b>	Pair of lodges, gate piers and gates, associated with Ammerdown House, 1788-94, and situated on the edge of late C18 to early C19 park. The lodges were ruinous when listed in the 1960s and their potential for reuse is limited by their size. A feasibility study has been undertaken but the scale of the project indicated was prohibitive. Discussions have commenced with estate owners but no solution yet agreed.
DESIGNATION:	Listed Building Grade II*, RPG II*	
CONDITION:	Very bad	
OCCUPANCY:	Vacant	
PRIORITY:	A (A)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Former Anglo-Bavarian Brewery, Commercial Road, Shepton Mallet</b>	Brewery, now warehouses, built 1864. Whilst partly occupied at ground floor level, most of the building has been vacant for many years. A feasibility study has been undertaken which has identified a substantial conservation deficit. A partial collapse has now been repaired.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	Part occupied	
PRIORITY:	A (A)	
OWNER TYPE:	Company	Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Outbuilding about 30 metres west of Higher Southtown Farm, Southtown Lane, West Pennard</b>	Early C17 timber-framed brewhouse, later cottage, now part calf shed/hay store. In poor condition due to lack of maintenance and beneficial use for many years. English Heritage is in discussion with the owner and SPAB regarding possible partnership repair scheme. Emergency clearance and stabilisation works to the building have recently been undertaken by Mendip Council.
DESIGNATION:	Listed Building Grade II*	
CONDITION:	Poor	
OCCUPANCY:	Vacant	
PRIORITY:	C (C)	
OWNER TYPE:	Private	Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrows south west of Cleeve's Plantation, Chewton Mendip</b>		
DESIGNATION:	Scheduled Monument (No.1003027)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 300m north east of Whitnell Corner, Emborough</b>		
DESIGNATION:	Scheduled Monument (No.1011670)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Drying house at The Coach House, Willow Vale, Frome</b>		
DESIGNATION:	Scheduled Monument (No.1016955)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Glastonbury lake village, Godney</b>			
DESIGNATION:	Scheduled Monument (No.1006156)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Vobster Breach colliery, 890m ENE of Tweed Farm, Leigh-on-Mendip</b>			
DESIGNATION:	Scheduled Monument (No.1014867)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Lake villages north west of Oxenpill, Meare</b>			
DESIGNATION:	Scheduled Monument (No.1006160)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Section of the Abbot's Way trackway, 500m WSW of Honeygar Farm, Meare</b>			
DESIGNATION:	Scheduled Monument (No.1014432)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Sections of the Sweet Track and Post Track, 240m south west of Sunnyside Farm, Meare</b>			
DESIGNATION:	Scheduled Monument (No.1014440)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Sections of the Sweet Track and Post Track, 250m ESE of Station House, Meare</b>			
DESIGNATION:	Scheduled Monument (No.1014831)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Timber trackway site, 700m west of Honeygar Farm, Meare</b>			
DESIGNATION:	Scheduled Monument (No.1014434)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Fussell's Lower Works: an iron edge tool works, 210m south east of Wadbury, Mells</b>			
DESIGNATION:	Scheduled Monument (No.1019796)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Whatley Combe Roman villa, Nunney</b>		
DESIGNATION:	Scheduled Monument (No.1006188)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 180m south west of Yoxter Farm, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1011532)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 250m north east of King Down Farm, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1011530)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 260m east of Templedown Farm, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1011534)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 300m south west of Moor View, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1009773)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 70m north east of King Down Farm, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1011531)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 800m south of Townsend Farm, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1009740)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Linear barrow cemetery comprising six bowl barrows 510m south west of Townsend Farm, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1009744)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>World War II bombing decoy complex, anti-aircraft obstructions and Beacon Batch round barrow cemetery on Black Down, Priddy</b>		
DESIGNATION:	Scheduled Monument (No.1020995)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive visitor erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 900m south west of Bristol Plain Farm: part of a group of round barrows south and south west of Bristol Plain Farm, Rodney Stoke</b>		
DESIGNATION:	Scheduled Monument (No.1008784)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Romano-British settlement on Stoke Moor, Rodney Stoke</b>		
DESIGNATION:	Scheduled Monument (No.1011125)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hillfort on Roddenbury Hill, Selwood</b>		
DESIGNATION:	Scheduled Monument (No.1008804)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of round barrows 750m north west of Ivy Cottage, St Cuthbert Out</b>		
DESIGNATION:	Scheduled Monument (No.1020494)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Marston Moat, Trudoxhill</b>		
DESIGNATION:	Scheduled Monument (No.1016302)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Babington House, Kilmersdon/Mells</b>	Landscape of lakes, gardens and parkland surrounding Regency villa. Much recent development in association with use of main house as club-hotel. New build and ancillary development including car park and conversion of kitchen garden ranges. However, there are some encouraging signs e.g. cultivation of walled garden along traditional principles.
DESIGNATION:	Registered Park and Garden Grade II, also 7 LBs	
CONDITION:	Generally satisfactory but with significant localised problems	
VULNERABILITY:	Medium	
TREND:	Stable	
OWNER TYPE:	Mixed, multiple owners	
		Contact: Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

## SEDGEMOOR



SITE NAME:	<b>Castle House, Queen Street, Bridgwater</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Trust

House in early Tudor Revival style, built for William Ackerman in 1851. The building is in a precarious condition. Owned by SAVE Building Preservation Trust. English Heritage has grant-aided scaffolding and project development work. Repairs to roof of rear range are being undertaken with English Heritage grant. SAVE are pursuing a long term future for the building with a local trust.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Westonzoyland Pumping Station, Westonzoyland</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Trust

A former pumping station (early C19) now preserved by the Westonzoyland Engine Trust. The first pumping station to be built to lift floodwater from the Somerset Levels and moors, and the only one to survive with the steam engine still working and the buildings intact. Much work has been done but the buildings are still in need of repair.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of St Congar, Church Lane, Badgworth</b>
DESIGNATION:	Listed Place of Worship Grade II
CONDITION:	Poor
PRIORITY:	B (New entry)
OWNER TYPE:	Religious organisation

The nave and north aisle are mostly C14. Tower dates from the C15. The north aisle is of interest for its good proportions and also the attractive C17/18 thrown lime render external finish to the north elevation. The walls are constructed of lias coursed rubble with dressings of limestone. The surface of the exposed walling in all areas of the church is eroded and spalled but no area more so than the tower which requires urgent attention to prevent further deterioration. A Repair Grant for Places of Worship was successfully applied for in 2011 for repairs.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Church of St Mary, Fore Street, North Petherton</b>
DESIGNATION:	Listed Place of Worship Grade I
CONDITION:	Very bad
PRIORITY:	B (New entry)
OWNER TYPE:	Religious organisation

The church was mostly built in the late C14 and early C15 including the tower, in Perpendicular style. The tower is acknowledged to be one of the finest in the country. Inside the tower at the height of the nave is a fine fan vault, unusual for a village church. The north aisle parapet is leaning at mid point and needs to be taken down and rebuilt. Roofs to the south aisle are in very poor condition allowing rainwater to enter the church and jeopardise timber structure and finishes. The church successfully applied for a Repair Grant for Places of Worship for works to the roof in 2011.



SITE NAME:	<b>Church of St Michael, North Lane, Othery</b>
DESIGNATION:	Listed Place of Worship Grade I
CONDITION:	Very bad
PRIORITY:	B (New entry)
OWNER TYPE:	Religious organisation

Church is C13 with C14, C15 and C16 phases but it was much restored in 1846-47. However, high quality of medieval work remains, especially the tower. High level stonework on the tower, including the carved statues is at risk and requires stabilising and conserving. A grant was offered in 2011 towards the repair of the tower.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Bronze Age and Iron Age trackways 600m north east of Northbrook Farm, Ashcott</b>		
DESIGNATION:	Scheduled Monument (No.1014444)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01 17 975 0700

## PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

## ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Chandos Glass Cone, at the junction of Northgate and Valetta Place, Bridgwater</b>		
DESIGNATION:	Scheduled Monument (No.1019899)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Horsely medieval settlement immediately north of Board's Farm, Bridgwater Without</b>		
DESIGNATION:	Scheduled Monument (No.1020438)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Ruborough Camp large univallate hillfort, Broomfield</b>		
DESIGNATION:	Scheduled Monument (No.1007670)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Timber trackways 850m east of Catcott Burtle Farm, Burtle</b>		
DESIGNATION:	Scheduled Monument (No.1014433)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>World War II anti-aircraft rocket battery and bombing decoy control building 265m north east of Ashridge Farm, Cheddar</b>		
DESIGNATION:	Scheduled Monument (No.1020994)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Permitted development	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Dead Woman's Ditch cross-dyke, Robin Upright's Hill, Over Stowey</b>		
DESIGNATION:	Scheduled Monument (No.1008254)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bronze Age and Iron Age timber trackways, 700m north west of Coppice Gate Farm, Shapwick</b>		
DESIGNATION:	Scheduled Monument (No.1014431)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Sections of the Sweet Track, the Post Track and associated remains 500m north east of Moorgate Farm, Shapwick</b>		
DESIGNATION:	Scheduled Monument (No.1014438)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric timber trackways, 670m SSE of Parchey Bridge, Stawell</b>		
DESIGNATION:	Scheduled Monument (No.1014430)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Alstone lake settlement site, West Huntspill</b>		
DESIGNATION:	Scheduled Monument (No.1012311)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Halswell Park, Goathurst/Broomfield</b>
DESIGNATION:	Registered Park and Garden Grade II, also 17 LBs
CONDITION:	Extensive significant problems
VULNERABILITY:	Medium
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

An C18 landscape park. Local preservation trusts have instigated the restoration and maintenance of two important garden buildings. Other structures are still at risk. The main house is in use as a commercial venue. The majority of the park is under intensive cultivation. The centrepiece of the design, Mill Wood, is largely denuded of trees and the structures within it are in a very poor state of repair.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

## SOUTH SOMERSET



SITE NAME:	<b>The Grotto at Jordans, NGR ST 3388 1601, Ashill</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY:	E (C)
OWNER TYPE:	Private

Early C19 grotto within a designed landscape whose principle house was demolished in the mid C20. The building has been subject to vandalism and although now rethatched, elements are still in need of repair.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Cosenes monument, Church of All Saints, Church Street, Castle Cary</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	A (A)
OWNER TYPE:	Religious organisation

Late C16 monument. Rusting iron cramps have caused serious damage and threaten further loss of stone.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Top mill building, Higher Flax Mills, Torbay Road, Castle Cary</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	F (D)
OWNER TYPE:	Private

This mid C19 former mill has been empty for several years. The building has now been sold and an application for conversion to one live/work unit has now been approved. Work implementing permission is underway but not yet complete.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

	<p><b>SITE NAME:</b> Waterloo House and Manor Court House, 7A, 7B, 9, 11, 13 and 13A Fore Street, Chard, Chard Town</p> <p><b>DESIGNATION:</b> Listed Building Grade I</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Part occupied</p> <p><b>PRIORITY:</b> C (C)</p> <p><b>OWNER TYPE:</b> Company</p>	<p>Late C16/early C17 group of shops/offices, houses and flats with two prominent projecting two and three storey porches. No. 9, which contains important internal features is vacant and in a deteriorating condition. A recent planning appeal refused subdivision to smaller units and the local authority is considering commissioning a feasibility study with English Heritage grant aid.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Madedy Mill, East Street, Martock</p> <p><b>DESIGNATION:</b> Listed Building Grade II*</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Part occupied</p> <p><b>PRIORITY:</b> C (C)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Water mill with medieval origins, although current buildings are largely C17. The building is situated on a working farm, is under-used and is suffering from lack of maintenance. Viable new uses and/or funding opportunities need to be investigated to obtain adequate funding for repairs. English Heritage funded condition survey has been completed, identifying urgent repairs.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Pranker chest tomb in churchyard 7m south east of south door, St John the Evangelist, Bathwell Lane, Milborne Port</p> <p><b>DESIGNATION:</b> Listed Building Grade II*, CA</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> N/A</p> <p><b>PRIORITY:</b> B (B)</p> <p><b>OWNER TYPE:</b> Religious organisation</p>	<p>Early C17 chest tomb. Subsidence at the northern end is causing structural instability. Rusting iron cramps threaten further damage. Surface deterioration of the south panel threatens further loss of the inscription. A grant offer has been made by South Somerset District Council and a repair scheme is expected to be implemented in 2012.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Secular college at Parsonage Farm, Stoke Sub Hamdon</p> <p><b>DESIGNATION:</b> Listed Building Grade II, SM, CA</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> C (C)</p> <p><b>OWNER TYPE:</b> Charity</p>	<p>Attached to this chantry college is a group of medieval and C16 farm buildings most of which are in poor condition and unroofed.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Two monuments in churchyard, approx 6 and 8 metres S of S transept, St Mary the Virgin, East Stoke, Stoke Sub Hamdon</p> <p><b>DESIGNATION:</b> Listed Building Grade II*, CA</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> N/A</p> <p><b>PRIORITY:</b> A (A)</p> <p><b>OWNER TYPE:</b> Religious organisation</p>	<p>Mid C17 monument. Subsidence has resulted in rising damp threatening the inscriptions, through increased salt crystallisation in the ledger slabs.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> The former Ropewalk, 75 metres north east of Millbrook House, High Street, West Coker</p> <p><b>DESIGNATION:</b> Listed Building Grade II*</p> <p><b>CONDITION:</b> Fair</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> E (E)</p> <p><b>OWNER TYPE:</b> Trust</p>	<p>Former twine works, now store and workshop. Late C19 with C20 alterations and extensions. English Heritage grant aided urgent repairs have been undertaken and supporting scaffolding has been erected. In 2011 the lease was taken over by the Coker Rope and Sail Trust and a Challenge Fund grant was awarded.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

<b>CA</b>	Conservation Area
<b>LB</b>	Listed Building
<b>LPA</b>	Local Planning Authority
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WHS</b>	World Heritage Site



SITE NAME: **Church of St Mary,  
Mudford**

DESIGNATION: Listed Place of Worship Grade I

CONDITION: Very bad

PRIORITY: B (New entry)

OWNER TYPE: Religious organisation

A medieval church in a village which is on the outskirts of Yeovil. Most of the fabric appears to date from the C15 or C16. The condition of the high level stonework is the subject of a successful Repair Grant for Places of Worship application. With this element repaired, the church will be put into good condition and the risk removed.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **St Peter and St Paul,  
Church Street,  
Wincanton**

DESIGNATION: Listed Place of Worship Grade II\*, CA

CONDITION: Poor

PRIORITY: F (B)

OWNER TYPE: Religious organisation

Large town centre church. The tower is all that remains of a medieval church. Major enlargement and rebuilding in 1735 and 1887-89. English Heritage grant-aided work to south east roofs in recent past. All other roofs are showing signs of age and there will need to be a rolling repair programme to these. A grant was offered in 2010 for works to northern nave. Repair works to roofing are ongoing.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Roman house south of Fair View House, Curry Rivel**

DESIGNATION: Scheduled Monument (No.1006185)

PRINCIPAL VULNERABILITY: Arable ploughing

OWNER TYPE: Private

CONDITION: Extensive significant problems

TREND: Declining

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Roman villa north of Dunnock's Lane, East Coker**

DESIGNATION: Scheduled Monument (No.1003029)

PRINCIPAL VULNERABILITY: Development requiring planning permission

OWNER TYPE: Private

CONDITION: Generally satisfactory  
but with minor localised problems

TREND: Declining

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Low Ham Roman villa, High Ham**

DESIGNATION: Scheduled Monument (No.1006192)

PRINCIPAL VULNERABILITY: Extensive animal burrowing

OWNER TYPE: Private

CONDITION: Generally unsatisfactory  
with major localised problems

TREND: Declining

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Northover House, late Roman cemetery, Ilchester**

DESIGNATION: Scheduled Monument (No.1006128)

PRINCIPAL VULNERABILITY: Scrub/tree growth

OWNER TYPE: Local authority

CONDITION: Generally unsatisfactory  
with major localised problems

TREND: Declining

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

SITE NAME: **Pill Bridge, Ilchester**

DESIGNATION: Scheduled Monument (No.1006214)

PRINCIPAL VULNERABILITY: Deterioration - in need of management

OWNER TYPE: Local authority

CONDITION: Generally satisfactory  
but with significant localised problems

TREND: Declining

CONTACT: Principal Heritage at Risk Adviser  
01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Roman villa north of Stowey Hill, Pitney</b>			
DESIGNATION:	Scheduled Monument (No.1006183)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Melbury Roman villa, Somerton</b>			
DESIGNATION:	Scheduled Monument (No.1002954)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Large multivallate hillfort and associated earthworks at South Cadbury, South Cadbury</b>			
DESIGNATION:	Scheduled Monument (No.1011980)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Chessels Roman villa, West Coker</b>			
DESIGNATION:	Scheduled Monument (No.1006186)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: <b>Redlynch Park, Bruton/Shepton Montague</b>	
DESIGNATION:	Registered Park and Garden Grade II, also 9 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Stable
OWNER TYPE:	Private, multiple owners

Formerly the principal seat of the earls of Ilchester, Redlynch is a large landscape park near Wincanton. The main house has gone and the stables and ancillary buildings are now in multiple ownership. The majority of the parkland planting has disappeared, boundary walls and estate railings are in poor repair and there are ongoing development pressures. More positively, a C18 Gothic gatehouse, The Towers, has been repaired and is no longer at risk.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: <b>Cricket House, Cricket St. Thomas/Winsham</b>	
DESIGNATION:	Registered Park and Garden Grade II*, also 8 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Stable
OWNER TYPE:	Mixed, multiple owners

C18 landscape park and pleasure grounds surrounding listed mansion, partly by Soane. Pressure for development from large hotel and farm diversification. However, encouragingly, parts of the park are being restored through Natural England's Environmental Stewardship scheme.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: <b>Hazlegrove House, Queen Camel/Sparkford</b>	
DESIGNATION:	Registered Park and Garden Grade II, also 3 LBs
CONDITION:	Generally satisfactory but with minor localised problems
VULNERABILITY:	Medium
TREND:	Stable
OWNER TYPE:	Mixed, multiple owners

C18 landscape park with formal garden in front of house. Avenues and veteran parkland trees survive, with some replanting. Main house in use as a school. Area close to house subject to development for a range of school facilities. Sports pitches encroaching into parkland. Park bisected by main road in 1980s, severing lodge from drive.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Misterton</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Adron Duckworth (LPA) 01935 462 595	NEW ENTRY:	No

## TAUNTON DEANE



SITE NAME: **Sandhill Park,  
Bishops Lydeard**

DESIGNATION: Listed Building Grade II\*  
CONDITION: Fair  
OCCUPANCY: Vacant  
PRIORITY: B (D)  
OWNER TYPE: Private

Country house c1720. An application for conversion of the house to apartments and construction of enabling development in its grounds is still under discussion. A fire in 2011 caused serious damage to the roof structure and top floor. The building has now been scaffolded with a temporary roof structure while discussions on its repair continue.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Gatehouse at Cothelstone Manor,  
Cothelstone**

DESIGNATION: Listed Building Grade I, CA, RPG II  
CONDITION: Poor  
OCCUPANCY: N/A  
PRIORITY: D (D)  
OWNER TYPE: Private

A mid C16 gatehouse. Part of a much larger estate. Consent has been granted for use as holiday let with associated repairs, but this has not been implemented. However, the Vivat Trust are investigating leasing the building for a similar purpose.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Cloth finishing works at Tone Mills,  
north range,  
Langford Budville**

DESIGNATION: Listed Building Grade II\*  
CONDITION: Poor  
OCCUPANCY: N/A  
PRIORITY: B (A)  
OWNER TYPE: Private

A near-complete example of a C19 cloth dyeing and finishing works which developed between c1830 and c1920. An application for new development on the adjoining grease works site has been approved and will provide funding for the conversion and repair of some of the buildings to enable their reuse for cloth making purposes.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Castle House,  
The Castle,  
Castle Green, Taunton**

DESIGNATION: Listed Building Grade I, SM, CA  
CONDITION: Poor  
OCCUPANCY: Vacant  
PRIORITY: C (C)  
OWNER TYPE: Trust

C17 house, within castle courtyard but in separate occupation, incorporating medieval fabric. Its former use as workshop and administrative building for the museum has ceased and it is now vacant. The building has been leased by Somerset Building Preservation Trust who have prepared a scheme for its reuse for educational and holiday let purposes and have raised funding. The castle is not at risk.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Tonedale Mills (west complex),  
Wellington**

DESIGNATION: Listed Building Grade II\*  
CONDITION: Poor  
OCCUPANCY: Part occupied  
PRIORITY: A (A)  
OWNER TYPE: Private

Western complex of an integrated multi-component wool textile factory, now largely disused. Consent granted for mixed use redevelopment of the complex. Works halted on site in 2008 and owners went into receivership leaving some buildings in a very vulnerable condition. Site has been sold. Discussions underway with new owners. Consent for a revised flood alleviation scheme will be required from Environment Agency.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Two crosses in St Mary's churchyard, Bishop's Lydeard</b>		
DESIGNATION:	Scheduled Monument (No.1016708)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 01 17 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Two groups of World War II pillboxes in the north eastern and north western sectors of the former airfield of RAF Culmhead, Trickey Warren, Churchstanton</b>		
DESIGNATION:	Scheduled Monument (No.1019846)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two World War II air traffic control buildings, 620m west and 560m WSW of Whitewall Corner, on the former airfield of RAF Culmhead, Trickey Warren, Churchstanton</b>		
DESIGNATION:	Scheduled Monument (No.1019845)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>World War II fighter pens and other airfield remains and defences of the former airfield of RAF Culmhead, at Trickey Warren Farm, Churchstanton</b>		
DESIGNATION:	Scheduled Monument (No.1020492)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow and folly ruins on Cothelstone Hill, 1km north east of St Agnes' Well, Cothelstone</b>		
DESIGNATION:	Scheduled Monument (No.1015086)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow at the west end of Cothelstone Hill, 825m NNE of St Agnes' Well, Cothelstone</b>		
DESIGNATION:	Scheduled Monument (No.1015085)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Cothelstone Hill, 1.07km north east of St Agnes' Well, Cothelstone</b>		
DESIGNATION:	Scheduled Monument (No.1015087)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Cothelstone Hill, 885m NNE of St Agnes' Well, Cothelstone</b>		
DESIGNATION:	Scheduled Monument (No.1015950)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Metal detecting	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Norton Camp large univallate hillfort, Norton Fitzwarren</b>		
DESIGNATION:	Scheduled Monument (No.1008467)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp south of Manor Farm, Wiveliscombe</b>		
DESIGNATION:	Scheduled Monument (No.1006167)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## WEST SOMERSET



SITE NAME: **Remains of Chantry at Kilve, Sea Lane, Kilve**

DESIGNATION: Listed Building Grade II\*, SM

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: A (A)

OWNER TYPE: Private

Early C14, with later medieval additions. Formerly believed to be remains of collegiate dwelling of chantry priests. An English Heritage survey has shown that the ruins are part of an important manorial complex. English Heritage funded emergency repairs were undertaken 2010, with more works undertaken 2011. EH has funded a conservation plan which includes options for reuse. Some works will be progressing in 2012.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME: **Church of the Blessed Virgin Mary, Brompton Ralph**

DESIGNATION: Listed Place of Worship Grade II\*

CONDITION: Very bad

PRIORITY: B (New entry)

OWNER TYPE: Religious organisation

Church dates from C15 but has undergone many changes. It was largely rebuilt in the C18 and the tower restored. North aisle added in 1841 and further restoration in 1881. All roofs, covered with common slate, are leaking and require repair. A grant was offered in 2011 towards the repair of the roofs.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Clatworthy hillfort, Clatworthy</b>		
DESIGNATION:	Scheduled Monument (No.1006149)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four cairns on Hurley Beacon, Crowcombe</b>		
DESIGNATION:	Scheduled Monument (No.1017218)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow and cairn cemetery on Black Hill, 490m north west of Crowcombe Park Gate, Holford</b>		
DESIGNATION:	Scheduled Monument (No.1019381)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Dowsborough hillfort and associated round barrow, Holford</b>		
DESIGNATION:	Scheduled Monument (No.1010494)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Entrenchment on Heydon Hill, Huish Champflower</b>		
DESIGNATION:	Scheduled Monument (No.1006173)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four medieval fish weirs 500m east of the Harbour, Minehead</b>		
DESIGNATION:	Scheduled Monument (No.1020017)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stringston churchyard cross, Stringston</b>		
DESIGNATION:	Scheduled Monument (No.1006171)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>St Audries (House), West Quantoxhead</b>	<p>CI9 gardens and pleasure grounds, surrounding a CI9 mansion, together with parkland developed from the mid CI8 and improved in the mid CI9. St Audries has had a succession of institutional uses; derelict former school buildings remain in the walled garden. The parkland is mostly cultivated and few parkland trees survive. Currently, St Audries house and gardens are in use as a wedding venue.</p> <p>Contact: Principal Heritage at Risk Adviser 0117 975 0700</p>
DESIGNATION:	Registered Park and Garden Grade II, also 16 LBs	
CONDITION:	Generally unsatisfactory with major localised problems	
VULNERABILITY:	Medium	
TREND:	Stable	
OWNER TYPE:	Mixed, multiple owners	

## SOUTH GLOUCESTERSHIRE (UA)



SITE NAME:	<b>Monument to Lord Robert Edward Somerset, Hawkesbury</b>	<p>A tall tapering stone tower ashlar monument by Lewis Vulliamy dated 1846. Repairs needed at high-level to cast iron balcony and stonework.</p> <p>Contact: Principal Heritage at Risk Adviser 0117 975 0700</p>
DESIGNATION:	Listed Building Grade II*, CA	
CONDITION:	Poor	
OCCUPANCY:	N/A	
PRIORITY:	C (C)	
OWNER TYPE:	Private	

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Ragged Castle or Keeper's Lodge, Badminton Park, Hawkesbury</b>
DESIGNATION:	Listed Building Grade II*, RPG I
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Private

Folly Castle. Set on motte at end of a main drive from Badminton House. Circa 1750 by Thomas Wright of Durham. Largely hidden by trees. Shell of structure is in poor condition. Interior has been lost. The council is in discussion with the owners regarding the repair and stabilisation of the walls. There has been clearance of vegetation on and around the structure.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Whitfields Tabernacle, Park Road, Kingswood</b>
DESIGNATION:	Listed Building Grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Private

Former chapel, built in 1741. The building has been redundant for many years and a fire has placed the building in an even more vulnerable position. The owners have recently withdrawn their application for redevelopment of the site and revised schemes are under discussion.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Brandy Bottom Colliery, Pucklechurch</b>
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	D (D)
OWNER TYPE:	Company

A former C19 steam-powered colliery built on the site of C18 colliery. The Avon Industrial Buildings Trust have commissioned an historical study of the site to inform future work. They are currently undertaking vegetation clearance and minor repairs to stabilise the structures.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Coach House and stables north east of Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY:	E (E)
OWNER TYPE:	Private

Coach house and stables, built 1722 in a mannered provincial baroque. The building has recently changed hands and an extensive repair programme has been agreed and is ongoing. The building is under a temporary roof.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Oxwick Farmhouse, Oxwick Lane, Yate, Wickwar</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	C (C)
OWNER TYPE:	Private

Farmhouse dated 1722, in flamboyant artisan mannerist/baroque style. Part occupied. Vacant part has serious decay of floor structures and in areas is unsafe, but emergency repairs have commenced. Discussions over full repair are ongoing.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of St James the Great, Church Road, Westerleigh</b>
DESIGNATION:	Listed Place of Worship Grade I
CONDITION:	Very bad
PRIORITY:	F (B)
OWNER TYPE:	Religious organisation

Large church with distinctive tall tower at the edge of the village of Westerleigh. The roofs are covered with a local sandstone slate, many slates are slipped or missing. It is especially bad over the porch which now has a tarpaulin cover. The north valley gutter is a temporary repair; now leaking, that imperils the nave and aisle roofs. A Repair Grant for Places of Worship for repair of the roofs has been offered and repairs will be undertaken in 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Round barrow on Barrow Hill, Bitton</b>	
DESIGNATION:	Scheduled Monument (No. I004521)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

**PRIORITY (FOR BUILDINGS)**

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

- D Slow decay; solution agreed but not yet implemented.
- E Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**


- CA Conservation Area
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

SITE NAME:	<b>Roman villa at Cromhall north west of Tapwell Bridge, Cromhall</b>		
DESIGNATION:	Scheduled Monument (No.1003045)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Starveall long barrow, Hawkesbury</b>		
DESIGNATION:	Scheduled Monument (No.1002473)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Hillfort and associated Romano-British occupation at Little Abbey, Alveston, Thornbury</b>		
DESIGNATION:	Scheduled Monument (No.1010803)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wickwar Roman small town 680m WNW of Hall End Farm, Wickwar</b>		
DESIGNATION:	Scheduled Monument (No.1021404)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Stoke Park, Stoke Gifford</b>
DESIGNATION:	Registered Park and Garden Grade II, also CA, 11 LBs, 1 SM
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	Medium
TREND:	Improving
OWNER TYPE:	Mixed, multiple owners

Dramatic location on a hill overlooking the city of Bristol. Mid C18 park laid out around crenellated Dower House. Park embellished by monuments and eye-catchers. Now bisected by the M32 motorway. Setting compromised by dense residential development. Park under pressure from heavy and occasionally anti-social use. Future now appears more settled following acquisition by Bristol City Council in 2010.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Warmley, Siston</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Rebecca Anthony (LPA) 01454 863 465	NEW ENTRY:	No

SITE NAME:	<b>Whitfield Tabernacle</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Unknown
CONTACT:	Rebecca Anthony (LPA) 01454 863 465	NEW ENTRY:	No

## SWINDON (UA)



SITE NAME:	<b>The Mechanics Institute, Emlyn Square, Swindon</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	C (A)
OWNER TYPE:	Company

Mechanics Institute, 1853-1855; now vacant. Outstanding example at heart of railway village. The council served an urgent works notice on the owner in 2009 and implemented works in 2010 to secure the building. The shell of the building has been stabilised.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RP&G	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	<b>Chain Test House, Rodbourne Road, Swindon</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	D (D)
OWNER TYPE:	Company

A rare example of a railway chain testing house, 1873. Building currently vacant and in poor condition. Now part of application for mixed use development.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME:	<b>Church of St Mary, Church Lane, Lydiard Tregoze</b>
DESIGNATION:	Listed Place of Worship Grade I
CONDITION:	Very bad
PRIORITY:	F (B)
OWNER TYPE:	Religious organisation

Church dates from C13, with C15, C17 and C19 phases. Restored C20. Exceptional interior with high quality monuments, wall and ceiling paintings from C13-C19. Roof to St John's Chapel is leaking and has a damaged painted ceiling. Rainwater goods and drainage throughout building are defective and damaging medieval wall paintings. A Repair Grant for Places of Worship has been offered for roof repairs. Works due to start in 2012.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Bowl barrow 280m north of Downs Barn, Bishopstone</b>	
DESIGNATION:	Scheduled Monument (No.I010419)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Bowl barrow on Hinton Downs, Bishopstone</b>	
DESIGNATION:	Scheduled Monument (No.I010461)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Bowl barrow 1km west of Sheppard's Farm Dairy, Chiseldon</b>	
DESIGNATION:	Scheduled Monument (No.I012439)	CONDITION: Extensive significant problems
PRINCIPAL VULNERABILITY:	Moderate animal burrowing	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Disc barrow on Burderop Down, 1km north east of Upper Herdwick Farm, Chiseldon</b>	
DESIGNATION:	Scheduled Monument (No.I010457)	CONDITION: Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME:	<b>Field system and earthwork enclosure on Burderop Down, Chiseldon</b>	
DESIGNATION:	Scheduled Monument (No.I016383)	CONDITION: Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND: Declining
OWNER TYPE:	Private	CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.  
**B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.  
**C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.  
**E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Site of Roman town, west of Wanborough House, Covingham</b>			
DESIGNATION:	Scheduled Monument (No.1004684)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Four Highworth circles 150m north east of Pickett's Copse, Highworth</b>			
DESIGNATION:	Scheduled Monument (No.1016386)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Highworth circle 520m north west of North Leaze Farm, Highworth</b>			
DESIGNATION:	Scheduled Monument (No.1016382)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three Highworth circles 600m east of North Leaze Farm, Highworth</b>			
DESIGNATION:	Scheduled Monument (No.1018221)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 700m south west of Liddington Warren Farm, Liddington</b>			
DESIGNATION:	Scheduled Monument (No.1009634)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Liddington Castle, Liddington</b>			
DESIGNATION:	Scheduled Monument (No.1016312)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long barrow 700m north of Liddington Warren Farm, Liddington</b>			
DESIGNATION:	Scheduled Monument (No.1009631)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Remains of Holy Rood Church, The Lawn, Old Town, Swindon</b>			
DESIGNATION:	Scheduled Monument (No.1018057)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 150m north of Half Moon Wood, Wanborough</b>		
DESIGNATION:	Scheduled Monument (No.1011811)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 850m north west of North Farm, Wanborough</b>		
DESIGNATION:	Scheduled Monument (No.1016381)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

## TORBAY (UA)



SITE NAME:	<b>Lupton House (Gramercy Hall School), Brixham</b>
DESIGNATION:	Listed Building Grade II*, RPG II*
CONDITION:	Poor
OCCUPANCY:	Part occupied
PRIORITY:	D (D)
OWNER TYPE:	Trust

C18 and C19 country house remodelled by G Wightwick c1840, with extensive ancillary buildings and fine Italianate Garden. Altered after a fire in 1928. In use as school from mid C20 to 2004. A charitable trust have acquired the House and are undertaking holding repairs. English Heritage have grant aided works to the garden structures, whilst plans for the repair and re-use of the House are discussed.


Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Torbay Cinema, Torbay Road, Paignton</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant
PRIORITY:	C (C)
OWNER TYPE:	Company

Cinema, licensed in 1912. An extremely well preserved example of an early purpose-built cinema. The building closed in the late 1980s and the Devon Historic Buildings Trust, in conjunction with the National Trust, are in discussion with the current owner about the re-use of the building.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Ilsham Manor Oratory, Ilsham Road, Ilsham, Torquay</b>
DESIGNATION:	Listed Building Grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	A (A)
OWNER TYPE:	Educational Body

Redundant oratory, part of the demolished medieval Ilsham Manor. Neglected and in poor condition, the chapel has no current use.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Ashhole Cavern, Torbay</b>		
DESIGNATION:	Scheduled Monument (No.1019133)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Prehistoric field system at Walls Hill, Torbay</b>		
DESIGNATION:	Scheduled Monument (No.1019134)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Moderate visitor erosion	TREND:	Declining
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>St Michael's Chapel, Chapel Hill, Torbay</b>		
DESIGNATION:	Scheduled Monument (No.1019131)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Stable
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Oldway Mansion</b>
DESIGNATION:	Registered Park and Garden Grade II, also 12 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	High
TREND:	Stable
OWNER TYPE:	Local Authority, single owner

Formal gardens laid out to complement a grand house inspired by the palace of Versailles. Built by the Singer sewing machine dynasty, the property has been in local authority ownership for many years. The grounds have been steadily rationalised and simplified. Permission has been granted (spring 2012) for mixed use development, including a hotel and housing. The consented scheme incorporates some landscape restoration.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Princess Gardens and Royal Terrace Gardens</b>
DESIGNATION:	Registered Park and Garden Grade II, also part in CA, 4 LBs
CONDITION:	Generally satisfactory but with significant localised problems
VULNERABILITY:	Medium
TREND:	Stable
OWNER TYPE:	Local Authority, single owner

Important formal Victorian seaside park with later phases and additions. Ongoing structural problems relating to seafront location. Proposals for major development on Princess Gardens appear to have been shelved. After a long period when it was closed to the public, Rock Walk has been subject to a major programme of rock stabilisation and redesign, and reopened.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Brixham Town</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	No significant change
CONTACT:	Hal Bishop (LPA) 01803 207787	NEW ENTRY:	No

SITE NAME:	<b>Torquay Harbour</b>		
DESIGNATION:	Conservation Area	CONDITION:	Very bad
VULNERABILITY:	Low	TREND:	Improving significantly
CONTACT:	Hal Bishop (LPA) 01803 207787	NEW ENTRY:	No

## WILTSHIRE (UA)



SITE NAME:	<b>Gay's Cave and Diamond (Amesbury Abbey), Amesbury</b>
DESIGNATION:	Listed Building Grade II*, WHS, CA, RPG II*
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY:	C (C)
OWNER TYPE:	Private

Gay's Cave or Seat, circa 1734-38, with gateway and wrought iron gates, attributed to Henry Flitcroft, and situated on the axis of Amesbury Abbey and tumulus beyond the River Avon. Some of the shrubbery has been cleared; however, the Diamond pattern paths are overgrown and unrecognisable. One gate has been removed from the Grotto and it is suffering from vandalism and neglect.

Contact: Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Rudloe Manor, Box</b>
DESIGNATION:	Listed Building Grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant
PRIORITY:	B (B)
OWNER TYPE:	Company

Late C17 manor house surrounded by ancillary buildings including a grade II listed barn. The house was part of a larger MOD site which was vacated in 1998. The house has remained vacant. The current owners have consent for a residential scheme with enabling development. Work expected to start 2012.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

	<p><b>SITE NAME:</b> Buildings to the rear of the Lansdowne Hotel, The Strand, Calne</p> <p><b>DESIGNATION:</b> Listed Building Grade II*, CA</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> C (C)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Former coach house, stable and brewhouse to rear of Lansdowne Arms Hotel. Buildings range from mid C17 to mid C19. Condition of roofs and coverings are continuing to degenerate leading to further internal decay. Urgent Works Notices have previously been complied with; however, the condition of these buildings continues to decline. The property has new owners who have indicated an intent to use the buildings.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Former hangars at Yatesbury Airfield, Cherhill, Compton Bassett</p> <p><b>DESIGNATION:</b> Listed Building Grade II*, CA</p> <p><b>CONDITION:</b> Good</p> <p><b>OCCUPANCY:</b> Part occupied</p> <p><b>PRIORITY:</b> E (A)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Two aircraft hangars, built circa 1917 as part of a training centre. Two hangars from the first years of military flying. One hangar has been repaired, though there is no current end use. Consent has been granted to demolish the second hangar.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Devizes Castle, Devizes</p> <p><b>DESIGNATION:</b> Listed Building Grade I, SM</p> <p><b>CONDITION:</b> Very bad</p> <p><b>OCCUPANCY:</b> N/A</p> <p><b>PRIORITY:</b> A (A)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Grade I house, 1842, sited on top of a Norman motte and encircling moat. Site included on the register because of the precarious condition of the motte, though the Victorian house is occupied and in fair condition.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Former Law Courts and County Police Station, Northgate Street, Devizes</p> <p><b>DESIGNATION:</b> Listed Building Grade II*, CA</p> <p><b>CONDITION:</b> Very bad</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> D (C)</p> <p><b>OWNER TYPE:</b> Company</p>	<p>Law courts and police station, 1835. Wind and weathertight. Interior has been gutted. Several schemes have been granted consent, including residential use and a nightclub, but none have been implemented. Planning permission and listed building consent granted in 2012 for a new residential scheme.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Stable block to Tottenham House, Great Bedwyn</p> <p><b>DESIGNATION:</b> Listed Building Grade II*, RPG II*</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> B (B)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Impressive stable block of 1818, by Thomas Cundy, located 150 metres north-north-west of Tottenham House. Consent for conversion to residential use granted early 1990s but not implemented. Consent has been granted for conversion into a spa, in association with a hotel in the main house. The condition of the building is declining.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>
	<p><b>SITE NAME:</b> Tottenham House, Great Bedwyn</p> <p><b>DESIGNATION:</b> Listed Building Grade I, RPG II*</p> <p><b>CONDITION:</b> Poor</p> <p><b>OCCUPANCY:</b> Vacant</p> <p><b>PRIORITY:</b> B (B)</p> <p><b>OWNER TYPE:</b> Private</p>	<p>Country house, 1825, by Thomas Cundy, situated in park, developed from C15 to C17 and landscaped by Lancelot 'Capability' Brown in the 1760s. Previously used as a preparatory school (from the 1950s). The consent for conversion to an hotel has yet to be implemented. However, the fabric is vulnerable to the elements and continues to decline.</p> <p>Contact: Principal Heritage at Risk Adviser 01 17 975 0700</p>

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Early wing at Brook Hall, Brokerswood, Heywood**

DESIGNATION: Listed Building Grade I

CONDITION: Poor

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

An important C15 lodging range, attached to the grade II listed house which contains some medieval remnants. Continued decay of building since support scaffolding erected in 2002. Local Planning Authority served second Urgent Works Notice March 2012 to extend support scaffold and protect openings. Discussions for reuse ongoing.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Chapel at Knowle House, Little Bedwyn**

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Early C15 former chapel in curtilage of a listed house. In poor condition and needs some work and repair.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **93 and 94 Bradenstoke, Lyneham**

DESIGNATION: Listed Building Grade II\*, CA

CONDITION: Fair

OCCUPANCY: Vacant

PRIORITY: E (E)

OWNER TYPE: Private

Timber-framed building, C15 to C16, upgraded to II\* in 2002. Last known use as a private residence but is now unoccupied. The council is monitoring the condition. Listed building consent was granted in 2010 for some repair works.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Medieval undercroft at Bradenstoke Priory, Bradenstoke, Lyneham**

DESIGNATION: Scheduled Monument

CONDITION: Poor


OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

C14 undercroft to priory. The building above removed in 1920s to the United States of America by Randolph Hearst. The undercroft has been propped with grant aid from English Heritage, to prevent collapse. There has been recent clearance of scrub and re-pointing. Gradual improvement but more to do to stabilise overall.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **The Red House at Eastwell Manor, Eastwell Road, Potterne**

DESIGNATION: Listed Building Grade II\*

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Red brick garden building, built circa 1700. One of several buildings on this site that are presently disused and in a decaying condition. An Enforcement Notice has been served in respect of unauthorised alterations. An appeal was lodged by the owner but was rejected by the planning inspector.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Littlecote Roman Villa, Ramsbury**

DESIGNATION: Scheduled Monument

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Company

Roman Villa, C1 to C4 AD. The owners have erected a new permanent cover over the mosaic. English Heritage is working with the owners over a long term management plan for the site including its future repair.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME: **Chapel, immediately north of Pythouse, Pythouse Park, West Tisbury**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: Vacant

PRIORITY: A (A)

OWNER TYPE: Private

Former private chapel to country house circa 1827. Built by John Bennett of Pythouse for his wife nee Lucy Lambert of Boyton. The chapel is derelict and overgrown and the stonework has been vandalised. The building is now scaffolded. Some of the vegetation has been removed and a repair schedule is being prepared.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700



SITE NAME: **Phipps Mausoleum, Westbury Cemetery, Bratton Road, Westbury**

DESIGNATION: Listed Building Grade II\*

CONDITION: Very bad

OCCUPANCY: N/A

PRIORITY: C (C)

OWNER TYPE: Private

Late 19th century privately owned mausoleum, within a local authority municipal cemetery.

Contact: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Banjo enclosure 480m south west of Cheldene, Aldbourne**

DESIGNATION: Scheduled Monument (No.1017363)

CONDITION: Extensive significant problems

PRINCIPAL VULNERABILITY: Arable ploughing

TREND: Unknown

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Lewisham Castle, Aldbourne**

DESIGNATION: Scheduled Monument (No.1017364)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Unknown

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Bowl barrow 800m south east of Tanhill Penning, All Cannings**

DESIGNATION: Scheduled Monument (No.1013023)

CONDITION: Generally unsatisfactory with major localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Unknown

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Two bowl barrows 400m south of Tanhill Penning, All Cannings**

DESIGNATION: Scheduled Monument (No.1013024)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Arable clipping

TREND: Unknown

OWNER TYPE: Government or Agency

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

SITE NAME: **Earth Burgh (or Eorth Burh) north west of New Town Farm, Alton**

DESIGNATION: Scheduled Monument (No.1004717)

CONDITION: Generally satisfactory but with significant localised problems

PRINCIPAL VULNERABILITY: Extensive animal burrowing

TREND: Declining

OWNER TYPE: Private

CONTACT: Principal Heritage at Risk Adviser 01 17 975 0700

#### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

#### ABBREVIATIONS

**CA** Conservation Area  
**LB** Listed Building  
**LPA** Local Planning Authority  
**NP** National Park  
**RPG** Registered Park and Garden  
**SM** Scheduled Monument  
**UA** Unitary Authority  
**WH** World Heritage Site

SITE NAME:	<b>Two Saxon boundary stones 450yds (410m) west of New Town, Alton</b>		
DESIGNATION:	Scheduled Monument (No.1005646)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Other	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wermere pond, Alvediston</b>		
DESIGNATION:	Scheduled Monument (No.1004774)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>A bell barrow and two bowl barrows east of The Avenue on Countess Farm: part of a linear round barrow cemetery, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1010331)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Scrub/tree growth	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow 550m east of New Barn, Earl's Farm Down, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1009872)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 170m south east of Strangways on Countess Farm, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1009145)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 400m SSE of Strangways on Countess Farm, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1021348)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 60m west of A345 on Countess Farm, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1009141)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Henge monument 400m south of Stonehenge Cottages, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1012376)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Linear boundary earthwork 250m west of Stockport, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1015689)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Linear boundary earthwork on Amesbury Down west of Stock Bottom, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1015218)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pond barrow 400m south east of Strangways, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1009136)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pond barrow 480m west of Olddown Barn on Amesbury Down, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1015027)	CONDITION:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three bell barrows 300m north east of New Barn, Earl's Farm Down, Amesbury</b>		
DESIGNATION:	Scheduled Monument (No.1009572)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Settlement east of Ashtonfield (Cotswold Community), Ashton Keynes</b>		
DESIGNATION:	Scheduled Monument (No.1004691)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Local authority	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>A henge, four Bronze Age barrows and part of a Roman road 500m south west of Fox Covert, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1007491)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Beckhampton round barrow cemetery 150m north east of the 'Waggon and Horses', Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1008221)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Bell barrow forming part of a round barrow cemetery 400m north east of West Kennett Farm on Overton Hill, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1008099)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 200m south of Green Street and 1100m east of the Avebury henge monument, forming part of a round barrow cemetery on Avebury Down, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1008110)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 50m south of The Sanctuary on Overton Hill, forming part of the Seven Barrow Hill round barrow cemetery, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1007489)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 770m south west of the junction of the Ridgeway and Green Street, forming part of a round barrow cemetery on Avebury Down, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1008107)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 900m SSE of Green Bank, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1014029)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow forming part of a Bronze Age cemetery 400m north east of West Kennett Farm on Overton Hill, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1008100)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow immediately west of the Ridgeway, 400m north east of its junction with Green Street, Avebury</b>		
DESIGNATION:	Scheduled Monument (No.1008500)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:		<b>Earthwork enclosure 950m SSE of Manor Farm, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1014031)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Group of six round barrows forming part of a Bronze Age cemetery 400m north east of West Kennett Farm, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1008102)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Vandalism	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pair of round barrows 400m west of the Ridgeway, forming part of a round barrow cemetery situated on Avebury Down, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1008075)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Pair of round barrows forming part of the Bronze Age round barrow cemetery 400m north east of West Kennett Farm, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1008101)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Remains of 'Falkner's Circle', a Neolithic stone circle 180m east of the West Kennet Avenue, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1008109)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Round barrow cemetery 400m south of Avebury henge monument on Waden Hill, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1008216)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>Ten barrows forming part of Fox Covert round barrow cemetery, West Down, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1008293)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:		<b>West Kennet Avenue and an earthwork bank east of West Kennett Farm, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1015547)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:		<b>West Kennett Farm palisaded enclosures, Avebury</b>	
DESIGNATION:	Scheduled Monument (No.1015157)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Grovely Ditch, Barford St Martin</b>	
DESIGNATION:	Scheduled Monument (No.1005584)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Berwick Coombe Ditch, Berwick St John</b>	
DESIGNATION:	Scheduled Monument (No.1005587)	CONDITION:	Generally satisfactory but with minor localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow west of Rotherley Wood, 750m WNW of Park Cottage, Berwick St John</b>	
DESIGNATION:	Scheduled Monument (No.1020464)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Winkelbury Hill earthworks, Berwick St John</b>	
DESIGNATION:	Scheduled Monument (No.1005585)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Winkelbury Hill round barrows, Berwick St John</b>	
DESIGNATION:	Scheduled Monument (No.1003002)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bell barrow situated between Bishop's Cannings Down and Easton Down, Bishops Cannings</b>	
DESIGNATION:	Scheduled Monument (No.1013229)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
SITE NAME:		<b>Bowl barrow 1070m NNW of Baltic Farm forming part of a barrow cemetery on North Down, Bishops Cannings</b>	
DESIGNATION:	Scheduled Monument (No.1013772)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 150m east of the wireless station on Morgan's Hill, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1014040)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 300m east of Furze Knoll, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1013068)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 550m north east of Baltic Farm, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1012629)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 840m north east of Baltic Farm, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1013066)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 950m SSW of Beckhampton Plantation, forming part of a round barrow cemetery on Horton Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1012983)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow at east end of Morgan's Hill, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1013070)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow situated 500m SSW of Shepherds' Shore, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1013756)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Eleven round barrows 1000m north of Baltic Farm forming part of a barrow cemetery, and a probable enclosed Iron Age farmstead on North Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1013773)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Enclosed Iron Age farmstead 450m south of Down Barn on Bishop's Cannings Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I013230)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Four bowl barrows forming part of a cemetery 270m east of long barrow on Roughridge Hill, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I014027)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of small enclosures on Horton Down, 910m north east of Easton Down long barrow, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I014561)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Group of three bowl barrows 250m north east of Shepherds' Shore, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I013232)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Kitchen Barrow: a long barrow on Kitchen Barrow Hill, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I012519)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Linear earthworks forming part of a field system on Bishop's Cannings Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I013233)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow 650m WSW of Shepherds' Shore, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I014030)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow on Easton Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.I013366)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Long barrow on Horton Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1013141)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roundway Hill Farm round barrows, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1004773)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Saucer barrow 600m west of Beckhampton Buildings, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1012193)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Saucer barrow on North Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1012627)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Square enclosure 350m north of Wansdyke on Bishop's Cannings Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1013231)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two saucer barrows and a pair of bowl barrows 750m SSW of Beckhampton Plantation, forming part of a round barrow cemetery on Horton Down, Bishops Cannings</b>		
DESIGNATION:	Scheduled Monument (No.1012982)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Crouchston Down Barn round barrow, Bishopstone</b>		
DESIGNATION:	Scheduled Monument (No.1004772)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Knighton Roman road (stretching from Reddish Gore to reservoir), Bishopstone</b>		
DESIGNATION:	Scheduled Monument (No.1003728)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME:</b> Bowl barrow 85m north of Bishopstrow House, Bishopstrow			
<b>DESIGNATION:</b>	Scheduled Monument (No.1019507)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Extensive animal burrowing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Enclosure and linear earthworks between Bishopstrow Down and South Down Sleight, Bishopstrow			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010283)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Extensive vehicle damage/erosion	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Government or Agency	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Woodminton Down round barrow, Bower Chalke			
<b>DESIGNATION:</b>	Scheduled Monument (No.1003729)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Corton long barrow, Boyton			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010518)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Scrub/tree growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Long barrow 250m east of Boyton Field Barn, Boyton			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010520)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable clipping	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Scrubbed Oak enclosure and linear boundary earthwork, Boyton			
<b>DESIGNATION:</b>	Scheduled Monument (No.1017713)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Plant growth	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Bowl barrow on Cold Kitchen Hill, 740m north east of Seagram's Barn, Brixton Deverill			
<b>DESIGNATION:</b>	Scheduled Monument (No.1016908)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Bowl barrow on Cold Kitchen Hill, 910m north east of Seagram's Barn, Brixton Deverill			
<b>DESIGNATION:</b>	Scheduled Monument (No.1016909)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

<b>CA</b>	Conservation Area
<b>LB</b>	Listed Building
<b>LPA</b>	Local Planning Authority
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WHS</b>	World Heritage Site

SITE NAME:	<b>Long barrow on Pertwood Down, 1400m north west of Lower Pertwood, Brixton Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1010463)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Knowle Hill round barrow, Broad Chalke</b>		
DESIGNATION:	Scheduled Monument (No.1003033)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow 860yds (786m) south east of Knighton Hill Buildings, Broad Chalke</b>		
DESIGNATION:	Scheduled Monument (No.1004771)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Roman road in Spye Park, Bromham</b>		
DESIGNATION:	Scheduled Monument (No.1003010)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow 770m north west of New Barn, Bulford</b>		
DESIGNATION:	Scheduled Monument (No.1015216)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow: one of a group of round barrows south of Bulford, Bulford</b>		
DESIGNATION:	Scheduled Monument (No.1009564)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow: one of a group of round barrows south of Bulford, Bulford</b>		
DESIGNATION:	Scheduled Monument (No.1009605)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow: one of a group of round barrows south of Bulford, Bulford</b>		
DESIGNATION:	Scheduled Monument (No.1009545)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow: one of a group of round barrows south of Bulford, Bulford</b>		
DESIGNATION:	Scheduled Monument (No.1009602)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow: one of a group of round barrows south of Bulford, Bulford</b>		
DESIGNATION:	Scheduled Monument (No.1009604)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Nuthills Roman villa, Calne Without</b>		
DESIGNATION:	Scheduled Monument (No.1004723)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow 240m south west of Green Barrow Farm, Castle Combe</b>		
DESIGNATION:	Scheduled Monument (No.1018419)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 190m north east of Nolands Farm, Yatesbury, Cherhill</b>		
DESIGNATION:	Scheduled Monument (No.1015808)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 350m north east of White Horse Plantation, Cherhill</b>		
DESIGNATION:	Scheduled Monument (No.1010134)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 700m south east of Field Barn, Chicklade</b>		
DESIGNATION:	Scheduled Monument (No.1015937)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Fussell's long barrow, Clarendon Park</b>			
DESIGNATION:	Scheduled Monument (No.1005611)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl Barrow, part of the round barrow cemetery south of Codford Down, Codford</b>			
DESIGNATION:	Scheduled Monument (No.1016557)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Three bowl barrows in Colerne Park, 450m north of Keeper's Cottage, Colerne</b>			
DESIGNATION:	Scheduled Monument (No.1010758)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow on Wick Down, Collingbourne Ducis</b>			
DESIGNATION:	Scheduled Monument (No.1012510)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 650m east of Summer Down Farm, Collingbourne Kingston</b>			
DESIGNATION:	Scheduled Monument (No.1012544)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Crowdown Clump earthwork (Godsbury), Collingbourne Kingston</b>			
DESIGNATION:	Scheduled Monument (No.1004759)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Two bowl barrows 400m south of Summer Down Farm, Collingbourne Kingston</b>			
DESIGNATION:	Scheduled Monument (No.1012518)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 430m north west of Northdown Barn, Coombe Bissett</b>		
DESIGNATION:	Scheduled Monument (No.I017705)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Little Toyd Down, 650m south west of Grims Lodge Farm, Coombe Bissett</b>		
DESIGNATION:	Scheduled Monument (No.I015704)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Moated site and surrounding earthwork enclosure, 100m south of Chelworth Farm, Cricklade</b>		
DESIGNATION:	Scheduled Monument (No.I013353)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Dumping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow on Ashmore Down, 775m north of Ashgrove Cottages, Donhead St Mary</b>		
DESIGNATION:	Scheduled Monument (No.I015938)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Clearbury Down round barrow, Downton</b>		
DESIGNATION:	Scheduled Monument (No.I003003)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow 600yds (550m) south east of Vanity, Downton</b>		
DESIGNATION:	Scheduled Monument (No.I003004)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Wick Down round barrow, Downton</b>		
DESIGNATION:	Scheduled Monument (No.I004776)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Ogbury camp, Durnford</b>		
DESIGNATION:	Scheduled Monument (No.I005677)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories  
are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Nine round barrows forming a round barrow cemetery 400m north of the eastern end of The Cursus, Durrington</b>		
DESIGNATION:	Scheduled Monument (No.I009067)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Improving
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 120m west of East Kennett long barrow forming part of a cemetery, East Kennett</b>		
DESIGNATION:	Scheduled Monument (No.I014035)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 200m east of East Kennett long barrow forming part of a barrow cemetery, East Kennett</b>		
DESIGNATION:	Scheduled Monument (No.I014036)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 200m north of East Kennett long barrow forming part of a cemetery, East Kennett</b>		
DESIGNATION:	Scheduled Monument (No.I014038)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Easton Clump settlement, Easton</b>		
DESIGNATION:	Scheduled Monument (No.I004761)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow on Easton Down, Easton</b>		
DESIGNATION:	Scheduled Monument (No.I005693)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval moated site and Romano-British settlement at White Walls Wood, Easton Grey</b>		
DESIGNATION:	Scheduled Monument (No.I013354)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive vehicle damage/erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow on Fifield Down 700yds (640m) ESE of North Barn, Ebbesborne Wake</b>		
DESIGNATION:	Scheduled Monument (No.I003744)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories  
are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Edington Priory (site of), Edington</b>		
DESIGNATION:	Scheduled Monument (No.1004709)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Collapse	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow, Tinhead Hill, Edington</b>		
DESIGNATION:	Scheduled Monument (No.1009783)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive natural erosion	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow Clump, bowl barrow, east of Ablington, Figheldean</b>		
DESIGNATION:	Scheduled Monument (No.1009697)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Three round barrows west of Netheravon Aerodrome, Fittleton</b>		
DESIGNATION:	Scheduled Monument (No.1010192)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 540m north of Woodbine Barn, Fonthill Bishop</b>		
DESIGNATION:	Scheduled Monument (No.1015943)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 100m north of Great Botley Copse, Grafton</b>		
DESIGNATION:	Scheduled Monument (No.1012301)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Great Botley Copse long barrow, and disc barrow near it, Grafton</b>		
DESIGNATION:	Scheduled Monument (No.1005692)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>North Hill round barrows, Grafton</b>		
DESIGNATION:	Scheduled Monument (No.1004746)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Romano-British kilns 150yds (135m) SSW of Tottenham House, Great Bedwyn</b>		
DESIGNATION:	Scheduled Monument (No.1004706)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Development requiring planning permission	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Grovely Castle and earthworks north of Grovely Wood, Great Wishford</b>		
DESIGNATION:	Scheduled Monument (No.1005604)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 340m east of Holly Bush Farm, Grittleton</b>		
DESIGNATION:	Scheduled Monument (No.1018418)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval settlement immediately north west of Upper Littlecott Farm, Hilmarton</b>		
DESIGNATION:	Scheduled Monument (No.1018420)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow 250m NNE of the sports ground: one of a group of round barrows north west of Idmiston Down, Idmiston</b>		
DESIGNATION:	Scheduled Monument (No.1013971)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow, bowl barrow and section of hollow way 600m NNW of Long Orchard, Idmiston</b>		
DESIGNATION:	Scheduled Monument (No.1013983)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME: <b>Bell barrow, three bowl barrows and gas testing trenches on Idmiston Down, Idmiston</b>			
DESIGNATION:	Scheduled Monument (No.1014818)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 260m SSE of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston</b>			
DESIGNATION:	Scheduled Monument (No.1014096)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 440m SSW of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston</b>			
DESIGNATION:	Scheduled Monument (No.1014094)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 530m SSW of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston</b>			
DESIGNATION:	Scheduled Monument (No.1014092)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 535m SSW of the southern corner of Moll Harris's Clump: one of a group of round barrows on Porton Down, Idmiston</b>			
DESIGNATION:	Scheduled Monument (No.1014093)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bronze Age enclosure and two bowl barrows 520m north east of Moll Harris's Clump on Idmiston Down, Idmiston</b>			
DESIGNATION:	Scheduled Monument (No.1014819)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Long barrow 140m WSW of the Battery Hill triangulation point, Idmiston</b>			
DESIGNATION:	Scheduled Monument (No.1014089)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Saucer barrow 400m north east of the sports ground: one of a group of round barrows north west of Idmiston Down, Idmiston</b>		
DESIGNATION:	Scheduled Monument (No.1013970)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two bowl barrows 265m south of the southern corner of Moll Harris's Clump: part of a group of round barrows on Porton Down, Idmiston</b>		
DESIGNATION:	Scheduled Monument (No.1014095)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two disc barrows and two bowl barrows 900m north of Moll Harris's Clump on Idmiston Down, Idmiston</b>		
DESIGNATION:	Scheduled Monument (No.1015557)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow north east of Mere Down Farm, Kingston Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1003005)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 140m west of Cleeve, Kingston Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1015805)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 1480m east of Keysley Farm, Kingston Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1019738)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 200m south west of Keysley Farm, Kingston Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1010405)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 670m SSE of Kingston Dairy, Kingston Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1016903)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME: Bowl barrow 700m south west of Keysley Farm, Kingston Deverill</b>			
DESIGNATION:	Scheduled Monument (No.1010406)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow 735m SSE of Kingston Dairy, Kingston Deverill</b>			
DESIGNATION:	Scheduled Monument (No.1019605)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow east of Court Hill Plantation, Kingston Deverill</b>			
DESIGNATION:	Scheduled Monument (No.1010403)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Bowl barrow on Keysley Down, 250m west of the A350 Warminster-Shaftesbury Road, Kingston Deverill</b>			
DESIGNATION:	Scheduled Monument (No.1013877)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Romano-Celtic temple 300m south west of Keysley Farm, Kingston Deverill</b>			
DESIGNATION:	Scheduled Monument (No.1016907)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: The Park round barrow, Kingston Deverill</b>			
DESIGNATION:	Scheduled Monument (No.1005595)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Moated site and fishponds south east of Rowden Farm, Lacock</b>			
DESIGNATION:	Scheduled Monument (No.1013876)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Plant growth	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME: Settlement south east of Latton, Latton</b>			
DESIGNATION:	Scheduled Monument (No.1004690)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Settlement west of Latton, Latton</b>		
DESIGNATION:	Scheduled Monument (No.1004689)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Mineral extraction / related subsidence	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Medieval pottery kilns, Milford Farm, Laverstock</b>		
DESIGNATION:	Scheduled Monument (No.1003252)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow on Rook Hill, 200m west of Pertwood Wood, Longbridge Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1010470)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow south west of Parsonage Down, Longbridge Deverill</b>		
DESIGNATION:	Scheduled Monument (No.1005622)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow 600m north of Hebden Farm, Luckington</b>		
DESIGNATION:	Scheduled Monument (No.1010395)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Enclosure on the summit of Rodmead Hill, Maiden Bradley with Yarnfield</b>		
DESIGNATION:	Scheduled Monument (No.1017704)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two saucer barrows 775m south east of Rodmead Farm, Maiden Bradley with Yarnfield</b>		
DESIGNATION:	Scheduled Monument (No.1017697)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bohune Down round barrow, Manningford</b>		
DESIGNATION:	Scheduled Monument (No.1003036)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME:	<b>Two bowl barrows north of Rowbury Lane, Market Lavington</b>		
DESIGNATION:	Scheduled Monument (No.1012191)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 190m north east of Burton Farm, Mere</b>		
DESIGNATION:	Scheduled Monument (No.1017711)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Unknown
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 760m north west of The Down House, Mere</b>		
DESIGNATION:	Scheduled Monument (No.1016300)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pond Bottom round barrow, Mere</b>		
DESIGNATION:	Scheduled Monument (No.1005620)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two round barrows in Chaddenwick Furze, Mere</b>		
DESIGNATION:	Scheduled Monument (No.1015945)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Improving
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Black Field Roman site, Mildenhall</b>		
DESIGNATION:	Scheduled Monument (No.1004726)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 800m south east of Ogbourne St Andrew Farm, Mildenhall</b>		
DESIGNATION:	Scheduled Monument (No.1012296)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Camp on Forest Hill, Mildenhall</b>		
DESIGNATION:	Scheduled Monument (No.1004697)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME:</b> Bowl barrow: one of three round barrows west of The Belt, Milston			
<b>DESIGNATION:</b>	Scheduled Monument (No.1009636)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Extensive animal burrowing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Government or Agency	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Bowl barrow 200m north east of Everleigh Ashes, Milton Lilbourne			
<b>DESIGNATION:</b>	Scheduled Monument (No.1009543)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable clipping	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Roman tile and brick kiln site 1000yds (900m) west of Tidling Corner, Minety			
<b>DESIGNATION:</b>	Scheduled Monument (No.1004702)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Bowl barrow 900m north of Down Farm, Nettleton			
<b>DESIGNATION:</b>	Scheduled Monument (No.1018391)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Long barrow 400m north west of Fox Covert, Nettleton			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010396)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Long barrow 500m north of Lugbury Farm, Nettleton			
<b>DESIGNATION:</b>	Scheduled Monument (No.1010397)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Early medieval settlement, palace, church and Bronze Age ring ditches 340m east of Cowage Farm, Norton			
<b>DESIGNATION:</b>	Scheduled Monument (No.1018389)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

<b>SITE NAME:</b> Bowl barrow: one of a group of dispersed barrows south east of Norton Plantation, Norton Bavant			
<b>DESIGNATION:</b>	Scheduled Monument (No.1009830)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Government or Agency	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

<b>CA</b>	Conservation Area
<b>LB</b>	Listed Building
<b>LPA</b>	Local Planning Authority
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WHS</b>	World Heritage Site

<b>SITE NAME: Round barrow on the south side of Cotley Hill, Norton Bavant</b>			
DESIGNATION:	Scheduled Monument (No.1009835)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Barrow on Coombe Down, 1070yds (980m) north east of Upper Poughcombe, Ogbourne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1005670)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Barrow on Smeathe's Ridge, Ogbourne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1005679)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Bell barrow 200m north of Rockley Plantation, Ogbourne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1012195)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Bowl barrow 375m east of Wick Bottom Barn, Ogbourne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1015814)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Bowl barrow 630m north east of Wick Bottom Barn, Ogbourne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1015803)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Bowl barrow and a saucer barrow 200m north of Rockley Plantation, Ogbourne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1012197)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME: Ogbourne Maizey Down round barrow, Ogbourne St Andrew</b>			
DESIGNATION:	Scheduled Monument (No.1004762)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Round barrow 750yds (690m) south east of Smeathe's Plantation, Ogbourne St Andrew</b>		
DESIGNATION:	Scheduled Monument (No.1004733)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow SSE of Greenland Camp, Orcheston</b>		
DESIGNATION:	Scheduled Monument (No.1010023)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow cemetery 320m south east of Down Farm, Pewsey</b>		
DESIGNATION:	Scheduled Monument (No.1016779)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>The Spectacles, Pewsey</b>		
DESIGNATION:	Scheduled Monument (No.1005638)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Long barrow, Winterbourne, Pitton and Farley</b>		
DESIGNATION:	Scheduled Monument (No.1005623)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Moated site 300m north-east of Potterne Park Farm, Potterne</b>		
DESIGNATION:	Scheduled Monument (No.1012152)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow 350m south west of Barbury Barn, Preshute</b>		
DESIGNATION:	Scheduled Monument (No.1012190)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 300m east of Ivy House Farm, Preshute</b>		
DESIGNATION:	Scheduled Monument (No.1012294)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

<b>SITE NAME:</b>		<b>Group of round barrows on Rough Hill, Preshute</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1003034)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b>		<b>Preshute Down field system, Preshute</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1004763)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b>		<b>Sharpridge field system, Preshute</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1004764)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b>		<b>Membury Camp (part in West Berkshire (UA)), Ramsbury</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1002994)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable clipping	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b>		<b>Bowl barrow 450m north of Cross Drovers, Shalbourne</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1012274)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b>		<b>Long barrow on Smay Down, 300m east of The Hassock, Shalbourne</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1010467)	<b>CONDITION:</b>	Extensive significant problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable ploughing	<b>TREND:</b>	Unknown
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b>		<b>Wansdyke: Daniel's Lane section, Shalbourne</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1005594)	<b>CONDITION:</b>	Generally unsatisfactory with major localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable clipping	<b>TREND:</b>	Declining
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700
<b>SITE NAME:</b>		<b>Newton Barrow, South Newton</b>	
<b>DESIGNATION:</b>	Scheduled Monument (No.1005687)	<b>CONDITION:</b>	Generally satisfactory but with significant localised problems
<b>PRINCIPAL VULNERABILITY:</b>	Arable clipping	<b>TREND:</b>	Stable
<b>OWNER TYPE:</b>	Private	<b>CONTACT:</b>	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

<b>CA</b>	Conservation Area
<b>LB</b>	Listed Building
<b>LPA</b>	Local Planning Authority
<b>NP</b>	National Park
<b>RPG</b>	Registered Park and Garden
<b>SM</b>	Scheduled Monument
<b>UA</b>	Unitary Authority
<b>WHS</b>	World Heritage Site

SITE NAME:	<b>Earthwork enclosure on Milk Hill, Stanton St Bernard</b>		
DESIGNATION:	Scheduled Monument (No.1004735)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Stapleford Castle, Stapleford</b>		
DESIGNATION:	Scheduled Monument (No.1005686)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow north of 'The Spectacles', Steeple Langford</b>		
DESIGNATION:	Scheduled Monument (No.1004742)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 240m east of The Penning, Steeple Langford</b>		
DESIGNATION:	Scheduled Monument (No.1015025)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Deptford Down round barrow, Steeple Langford</b>		
DESIGNATION:	Scheduled Monument (No.1005615)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>East Castle, Steeple Langford</b>		
DESIGNATION:	Scheduled Monument (No.1005599)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Little Langford round barrow, north of Upper Farm Down, Steeple Langford</b>		
DESIGNATION:	Scheduled Monument (No.1005605)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Round barrow 230yds (210m) north west of New Field Plantation, Steeple Langford</b>		
DESIGNATION:	Scheduled Monument (No.1004725)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Orchard Castle, Stourton with Gasper</b>		
DESIGNATION:	Scheduled Monument (No.1005639)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow 350m north of Haydon Farm, Sutton Veny</b>		
DESIGNATION:	Scheduled Monument (No.1010517)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bell barrow on Parsonage Down, 1.3km south east of Lord's Hill Farm, Sutton Veny</b>		
DESIGNATION:	Scheduled Monument (No.1016677)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Littlecombe Down, Sutton Veny</b>		
DESIGNATION:	Scheduled Monument (No.1005683)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pair of bowl barrows 1050m NNW of Pertwood Wood, Sutton Veny</b>		
DESIGNATION:	Scheduled Monument (No.1019739)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Fosbury camp, Tidcombe and Fosbury</b>		
DESIGNATION:	Scheduled Monument (No.1005682)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Localised/limited stock erosion	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow south east of Sidbury Hill, Tidworth</b>		
DESIGNATION:	Scheduled Monument (No.1010022)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Castle Ditches camp, Tisbury</b>		
DESIGNATION:	Scheduled Monument (No.1005701)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Romano-British villa complex 330m north west of Queen Court Farm, Tockenham</b>		
DESIGNATION:	Scheduled Monument (No.1017015)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow on Woodley Down 675m NNE of Ashmore Farm, Tollard Royal</b>		
DESIGNATION:	Scheduled Monument (No.1020465)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Casterley Camp and associated monuments, Upavon</b>		
DESIGNATION:	Scheduled Monument (No.1010074)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Two saucer barrows 250m west of John's Planting, Upton Lovell</b>		
DESIGNATION:	Scheduled Monument (No.1007564)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 500m south of Upton Scudamore, Upton Scudamore</b>		
DESIGNATION:	Scheduled Monument (No.1010398)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Barrow 1/4 mile (400m) north west of Willoughby Hedge, West Knoyle</b>		
DESIGNATION:	Scheduled Monument (No.1005666)	CONDITION:	Generally satisfactory but with significant localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow in The Belt, 350m north east of Hill Barn, West Overton</b>		
DESIGNATION:	Scheduled Monument (No.1019901)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 100m north of Rox Hill Clump, Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.1013813)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 250m south of Westfield Farm buildings,Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I010835)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 350m south west of Normanton Gorse,Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I013812)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 400m west of Normanton Gorse,Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I010831)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 450m east of The Diamond south of the A303,Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I011709)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 50m south west of Rox Hill Clump,Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I010836)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow south of the A303 and north west of Normanton Gorse,Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I010832)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pond barrow south of the A303 and 400m west of Normanton Gorse containing the 'Wilsford Shaft', Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I010833)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Seven bowl barrows and a pond barrow forming a round barrow cemetery 200m north of The Diamond on Wilsford Down,Wilsford cum Lake</b>		
DESIGNATION:	Scheduled Monument (No.I010834)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WH	World Heritage Site

SITE NAME: <b>Horse Barrow, Winterbourne</b>			
DESIGNATION:	Scheduled Monument (No.1005610)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 350m north west of Greenland Farm, Winterbourne Stoke</b>			
DESIGNATION:	Scheduled Monument (No.1010892)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 830m south west of Greenlands Bungalow, east of Shrewton, Winterbourne Stoke</b>			
DESIGNATION:	Scheduled Monument (No.1015217)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bronze Age enclosure and bowl barrow 100m west of Longbarrow Cross Roads on Winterbourne Stoke Down, Winterbourne Stoke</b>			
DESIGNATION:	Scheduled Monument (No.1011048)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Disc barrow and pond barrow 350m NNW of Greenland Farm, Winterbourne Stoke</b>			
DESIGNATION:	Scheduled Monument (No.1010891)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Unknown
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bell barrow and bowl barrow 500m NNW of Long Orchard, Winterslow</b>			
DESIGNATION:	Scheduled Monument (No.1013984)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Bowl barrow 750m NNE of Easton Down Farm, Winterslow</b>			
DESIGNATION:	Scheduled Monument (No.1013986)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Extensive animal burrowing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME: <b>Heale Hill round barrows and earthworks, Woodford</b>			
DESIGNATION:	Scheduled Monument (No.1005609)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Arable clipping	TREND:	Stable
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

**PRIORITY (FOR BUILDINGS)**

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

**ABBREVIATIONS**

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	<b>Bowl barrow 175m west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers</b>		
DESIGNATION:	Scheduled Monument (No.1013352)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Bowl barrow 275m west of Square Copse: part of the Square Copse barrow cemetery, Wootton Rivers</b>		
DESIGNATION:	Scheduled Monument (No.1013364)	CONDITION:	Extensive significant problems
PRINCIPAL VULNERABILITY:	Arable ploughing	TREND:	Declining
OWNER TYPE:	Government or Agency	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700



SITE NAME:	<b>Tottenham House and Savernake Forest, Burbage and Savernake, Savernake/Burbage/Great Bedwyn/Little Bedwyn/Mildenhall</b>
DESIGNATION:	Registered Park and Garden Grade II*, also 20 LBs, 7 SMs
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
OWNER TYPE:	Mixed, multiple owners

Extensive landscape of rides linking Savernake Forest with ornamental parkland and pleasure grounds around the house. Exemplifies the work of Burlington, Brown, Cundy and others. Main house has planning permission for hotel development, including building over Brown's walled garden and laying out a golf course in the park. Forestry Commission manages Savernake Forest on a long lease.

Contact: Principal Heritage at Risk Adviser 0117 975 0700

SITE NAME:	<b>Pewsey - Wilcot Road</b>		
DESIGNATION:	Conservation Area	CONDITION:	Poor
VULNERABILITY:	Medium	TREND:	Deteriorating
CONTACT:	Helen Garside (LPA) 01380 724911	NEW ENTRY:	No

## WILTSHIRE (UA) / NEW FOREST (NP)

SITE NAME:	<b>Barrows in Bath Hole and Bury Hill Plantations, Redlynch</b>		
DESIGNATION:	Scheduled Monument (No.1004754)	CONDITION:	Generally unsatisfactory with major localised problems
PRINCIPAL VULNERABILITY:	Forestry	TREND:	Declining
OWNER TYPE:	Private	CONTACT:	Principal Heritage at Risk Adviser 0117 975 0700

### PRIORITY (FOR BUILDINGS)

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair; but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

**NOTE:**  
2011 priority categories are given in brackets.

### ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



## ENGLISH HERITAGE

This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at [www.english-heritage.org.uk/risk](http://www.english-heritage.org.uk/risk)

### HERITAGE AT RISK

Published September 2012 by English Heritage  
1 Waterhouse Square, 138-142 Holborn,  
London EC1N 2ST