



ENGLISH HERITAGE

HERITAGE AT
RISK
REGISTER
2013

YORKSHIRE

Contents

| | |
|--|-------|
| HERITAGE AT RISK | III |
| THE REGISTER | VII |
| Content and criteria | VII |
| Criteria for inclusion on the Register | VIII |
| Reducing the risks | X |
| Publications and guidance | XIII |
| Key to the entries | XV |
| Entries on the Register by local planning authority | XVIII |
| <i>Cumbria</i> | I |
| Yorkshire Dales (NP) | I |
| East Riding of Yorkshire (UA) | I |
| Kingston upon Hull, City of (UA) | 26 |
| North East Lincolnshire (UA) | 27 |
| North Lincolnshire (UA) | 28 |
| <i>North Yorkshire</i> | 31 |
| Craven | 31 |
| Hambleton | 32 |
| Harrogate | 35 |
| North York Moors (NP) | 40 |
| Richmondshire | 55 |
| Ryedale | 58 |
| Scarborough | 77 |
| Selby | 80 |
| Yorkshire Dales (NP) | 85 |
| <i>South Yorkshire</i> | 87 |
| Barnsley | 87 |
| Doncaster | 90 |
| Peak District (NP) | 94 |
| Rotherham | 94 |
| Sheffield | 98 |
| <i>West Yorkshire</i> | 101 |
| Bradford | 101 |
| Calderdale | 106 |
| Kirklees | 110 |
| Leeds | 115 |
| Wakefield | 121 |
| York (UA) | 124 |




ENGLISH HERITAGE

HERITAGE AT RISK

2013

YORKSHIRE



HERITAGE AT RISK

Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results. Each of our nine local offices now hosts a dedicated Heritage at Risk team, delivering national expertise locally.

The good news is that we are on target to save 25% (1,137) of the sites that were on the Register in 2010 by 2015. From the historic battlefield at Towton to ancient barrows on the Wolds, this success is down to good partnerships with owners, developers, the Heritage Lottery Fund, Natural England, councils and local groups. It will be increasingly important to build on these partnerships to achieve the overall aim of reducing the number of sites on the Register. **Trevor Mitchell**, Planning and Conservation Director, Yorkshire

This year we have made great progress, removing over 120 assets from the Heritage at Risk Register, including 96 scheduled monuments, many of which have received funding through Natural England Stewardship Schemes. We have also removed two of our top ten priority sites. Our approach continues to focus on Yorkshire's most distinctive heritage.

The Ancient Landscapes of the Wolds and Moors

These landscapes contain some of England's most important but least appreciated prehistoric sites. Working with the North York Moors National Park, the Coast Wolds and Wetlands Leadership Partnerships and Natural England, we are addressing the threat of arable cultivation to the area's many barrows, dykes and boundary features.

The Industrial Remains of the Dales

Lead mining has shaped the landscape of the Dales since Roman times and our successful partnership with the National Park has secured characteristic remains as evidence for future generations. Successes include the removal of Sargill Lead Mine, now monitored by a team of volunteers and the repair of the chimney and flues associated with lead smelting on Grassington Moor.

South Yorkshire Metal Trades

Real progress has been made securing this important industrial legacy. In Sheffield, grants of over £260k for Green Lane Works and Eagle Works will aid the repair and reuse of these important landmarks in the Kelham Island Conservation Area, as part of a £13m mixed-use scheme, supported by the Homes and Communities Agency. Next year we will focus our attention on Leah's Yard, a key courtyard site in the


heart of Sheffield, while our work with the East Peak Innovation Partnership should see improvements to Rockley Blast Furnace and Engine House near Barnsley.

The Textile Industry of the West Riding

It continues to be difficult to secure regeneration of large mill complexes in the current economic climate. However, there is some progress with smaller sites and associated townscapes. We have offered a grant of £92k to the social housing provider Accent Foundation to support the residential conversion of the former St Catherine's Nurses Home in Manningham. We have also helped to scope the outstanding repair needs at nearby Lister Mills. In Haworth, a combination of initiatives has improved the conservation area sufficiently for us to remove it from the Register, although there is more to be done to ensure that the village is a truly world-class visitor destination.

South Yorkshire Designed Landscapes

Dedication and perseverance pays off. For some years we have been investing alongside the Heritage Lottery Fund and others in the amazing grade I landscape at Wentworth Castle, securing many of its fine follies. And finally, 10 years after it featured on the BBC Restoration programme, the £3.7m repair of the beautiful Victorian Conservatory is now complete.



Tammy Whitaker,
Principal Adviser, Heritage at Risk

GREEN LANE WORKS, SHEFFIELD, SOUTH YORKSHIRE

The imposing entrance to Green Lane Works, described as "the most spectacular survival of factory architecture in Sheffield." The site was home to successive metal manufacturing firms making everything from razor blades to agricultural machinery and motor parts. But once production ceased the condition of the building deteriorated and the grade II* gateway was added to the Register this year. But the future looks promising. The site is set to be restored as part of a £13m eco-friendly mixed-use development, incorporating housing, commercial and leisure space by award winning Leeds based developer Citu.

BUILDINGS AND STRUCTURES

- Nationally, 4.1% of grade I and II* listed buildings (excluding places of worship) are on the Register. In Yorkshire the percentage is 6.0% (96 buildings).
- 8 building or structure entries have been removed from the 2012 Yorkshire Register because their futures have been secured, but 11 have been added.

PLACES OF WORSHIP

- Of the 519 listed places of worship assessed in Yorkshire, 71 are on the Register.
- 14 places of worship have been removed from the 2012 Register following repair work.

ARCHAEOLOGY

- 3,265 (16.5%) of England's 19,792 scheduled monuments are on the Register, of which 597 are in Yorkshire.
- 96 archaeology entries have been removed from the 2012 Register for positive reasons and 4 have been added.
- 25.6% of archaeology entries (185) on Yorkshire's baseline 2009 Register have been removed for positive reasons, compared to the national figure of 21.1%.
- Nationally, damage from arable cultivation is the greatest risk factor, accounting for 43% of those on the Register. In Yorkshire the proportion is 57%.

PARKS AND GARDENS

- 100 (6.2%) of England's 1,624 registered parks and gardens are on the Register. In Yorkshire, 14 are on the Register, an increase of 1 on last year.

BATTLEFIELDS

- Of the 43 registered battlefields in England, 6 are on the Register. Of the 7 registered battlefields in Yorkshire, 3 are on the Register. 1 entry has been removed from the 2012 Register.

WRECK SITES

- Of the 46 protected wreck sites around England's coast, 4 are on the Register. Yorkshire's single protected wreck site is not on the Register.

CONSERVATION AREAS

- 8,179 of England's 9,839 conservation areas have been surveyed by local authorities. 510 (6.2%) are on the Register. Of the 853 conservation areas surveyed in Yorkshire, 55 (6.4%) are on the Register.
- 3 conservation areas have been removed from the 2012 Yorkshire Register for positive reasons, but 5 have been added.



LEAD CUPOLA, FLUE AND CHIMNEY, GRASSINGTON MOOR, NORTH YORKSHIRE

The surviving remains of a lead processing plant stand high on Grassington Moor. On the Register since 1999, the ruins of this extraordinary system of flues, semi-sunken arched tunnels, condensing chambers, and chimney have now been repaired and removed from the Register with grant aid from English Heritage.

61% OF BUILDINGS AND STRUCTURES ON THE 1999 REGISTER HAVE BEEN **SAVED**

55 CONSERVATION AREAS ARE ON THE REGISTER

22.8% OF SCHEDULED MONUMENTS ARE ON THE REGISTER

£1.1m IN GRANTS WAS OFFERED TO **23** SITES ON THE REGISTER

Heritage assets are assessed based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

PRIORITY HAR SITES

- Barden Church, Barden, Yorkshire Dales National Park
- Birdsall Estate (incl. 16 scheduled monuments at risk), Birdsall Wold, Ryedale, North Yorkshire
- First Leeds White Cloth Hall, 98-101 (consec) Kirkgate, Leeds, West Yorkshire
- Grassington Moor (multi-period lead mines and processing works and 20th century barytes mill), Grassington, Yorkshire Dales National Park
- Keld Heads lead smeltnill and mine complex, Wensley, Richmondshire, North Yorkshire
- Kirklees Park Farm buildings (incl. Double aisled barn to north west of Kirklees Priory Gatehouse, Home Farm (Building No. 6), Kirklees Priory Gatehouse, L-shaped Aisled Barn, and the Malthouse) Brighouse, Calderdale, West Yorkshire
- Leah's Yard, 20-22 Cambridge Street, Sheffield, South Yorkshire
- Rockley Blast Furnace and Engine House, Bamsley, South Yorkshire
- Whortlon Castle (gatehouse and ruins of undercroft), Castle Bank, Whortlon, North York Moors National Park
- Wressle Castle, Brighton Road, Wressle, East Riding of Yorkshire

FOR MORE INFORMATION CONTACT:

Principal Heritage
at Risk Adviser
English Heritage
Yorkshire
37 Tanner Row
York
YO1 6WP

Telephone: 01904 601 901

Email: yorkshire@english-heritage.org.uk



HAWORTH CONSERVATION AREA, WEST YORKSHIRE

BACKGROUND AND HISTORY:

At one time entire families in the Pennine village of Haworth were employed as weavers and wool combers, producing fine quality worsted yarn and cloth. Today, it is best known for its famous association with the Bronte family. It is a remote and picturesque village, based on the side of a steep hill, with the lonely and desolate moors, made famous by Emily Bronte's *Wuthering Heights*, rising behind. The historic village is a product of the 19th century when its location on the trans-Pennine turnpike road meant that it served a large area,

hosting a range of shops and services including booksellers, grocers, tailors, drapers, surgeons and an apothecary and wine merchant. The Brontes added their mark founding the National School in 1832.

IS IT AT RISK?

This thriving tourism destination was added to the Heritage at Risk Register in 2010, when fears that poor maintenance and piecemeal changes were eroding the character of the village. Local residents and businesses have been working with English Heritage and Bradford Council to reverse the decline and ensure Haworth retains its reputation as an international tourism destination. Small improvements like the

reinstatement of original features including windows in the old school room (left, before and after) and shop fronts on Main Street, repair of the cobbled streets and repairs to the roof of St Michael and All Angels Church where Patrick Bronte was curate have all helped to restore the character of the village.

WHAT'S THE CURRENT SITUATION?

The work by residents, businesses, the local authority and English Heritage has helped Haworth to turn a corner, but there is still much to do. We've identified a series of further actions such as tackling the plethora of signage blighting Main Street and encouraging owners to follow our lead on building repairs so that Haworth continues to strengthen its identity as an iconic Yorkshire village showcasing Yorkshire's heritage to visitors from all over the world.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har

If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

THE REGISTER

Content and criteria

DESIGNATION

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (<http://list.english-heritage.org.uk>). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing emerged from the post-blitz 1940s Planning Acts, and is now applied to about half a million buildings ranging from palaces to street lamps. Almost 20,000 archaeological sites are scheduled, which introduces management controls. Some 1,624 designed landscapes are registered, as are 43 battlefields, and 46 wreck sites are protected.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a never-ending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special. A change in legislation, part of the Enterprise and Regulatory Reform Act, makes this possible.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

A listed building is a building (or structure) that has been designated as being of 'special architectural or historic interest'. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat. There are over 376,000 listing entries on the National Heritage List for England.

Listed buildings are graded I, II* and II. Grade I and II* are particularly important buildings of outstanding interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

Entries on the statutory list of buildings of special architectural or historic interest may comprise a number of separate buildings. Formal residential terraces are the most obvious example. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,792 examples have been designated because of their national importance. (Scheduled monuments are not graded). They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

REGISTERED PARKS AND GARDENS

There are 1,624 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest*. These registered landscapes are graded I, II* or II, and include private gardens, public parks and other green spaces, country estates and cemeteries. They are valued for their design, diversity and historical importance and in contrast to the number of listed buildings and scheduled monuments, registered parks and gardens is a very small group of assets.

Inclusion on the English Heritage *Register of Historic Parks and Gardens* brings no additional statutory controls, but there is a presumption in favour of conservation of the

designated site. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades. The setting of designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

English Heritage's *Register of Historic Battlefields* was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1185): almost half date from the period of the the civil wars in the mid-17th century. These are cherished for their memory, and for the respect owing to those who were killed, and whose remains still lie in the field.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological records. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy. Battlefields are not graded.

PROTECTED WRECK SITES

England's 46 protected wreck sites represent a tiny proportion of the 33,000 odd pre-1945 wrecks and recorded casualties that are known to lie in the territorial sea. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of special architectural or historic interest the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently over 9,800 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on the Register

RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

BUILDINGS AND STRUCTURES

Buildings or structures (not in use as a public place of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from 'very bad' to 'poor', 'fair' and (occasionally) 'good' reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in 'very bad' or 'poor' condition it is added to the Register. Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

English Heritage has assessed a proportion of the 14,800 listed places of worship. We are working with the respective denominations to assess the remaining places of worship. Those that are identified as at risk will be included on the Register.

ARCHAEOLOGY

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

BATTLEFIELDS

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure – for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metal-detecting. One major impact or a combination of several factors can be enough to raise the risk at a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to the inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends, identifying those that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, as being defined as at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

English Heritage is committed to securing a year-on-year reduction in the number of heritage sites at risk as part of our National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Whilst this is a challenge given the number of entries on the Register and the different kinds of risk they face, good progress is being made.

To help address this challenge we have created dedicated Heritage at Risk teams in each local office. We have published our National Heritage at Risk Strategy which is supported by nine local strategies. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all at risk assets. Resolving cases requires working in close partnership with owners, local planning authorities and other relevant organisations and partners. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including on new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: www.english-heritage.org.uk or the Historic Environment Local Management (HELM) website: www.helm.org.uk

Historic Environment Records, and local heritage at risk registers maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services, the inclusion of information about condition can help improve the protection, conservation and management of heritage assets.

BUILDINGS AND STRUCTURES

English Heritage's role in securing the future of buildings and structures that are on the Register is primarily to provide practical advice, guidance and resources to local authorities, owners and developers.

Our local Heritage at Risk teams can help with analysis of the issues, investigating the feasibility of options and brokering solutions. We can advise on sources of grant aid and, where possible and appropriate, the provision of English Heritage's own grants. Our national advisers and specialists in structural engineering, quantity surveying, development economics and law provide support for local teams on particularly difficult cases. We work closely with grant providers, notably the Heritage Lottery Fund and Natural England as these are essential in helping secure the future of buildings or structures on the Register. In very exceptional cases, English Heritage may acquire and repair a particularly important building or structure, where it is clear that this is the only way of securing its long-term future. More information on funding can be found on the HELM website and at www.english-heritage.org.uk/professional/funding

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings. A local register, often compiled with the help of voluntary groups can identify the scale of the problem, promote monitoring and help prioritise resources and action. A range of enforcement powers are available for local authorities to tackle listed buildings at risk but declining resources in local authorities means that these powers are often under-used. In a bid to help, English Heritage now has a legal adviser dedicated to heritage at risk. We can also provide grant aid to underwrite some of the costs involved in serving Urgent Works Notices and Repairs Notices on historic buildings and we hope that this, together with our published guidance (*Stopping the Rot*) will encourage local authorities to take action to save historic buildings.

Building preservation trusts (BPTs) offer a tried and tested way of saving many buildings at risk. In 2012 English Heritage joined forces with the Architectural Heritage Fund to employ four Heritage at Risk Officers to help not-for-profit organisations take forward building at risk projects. We also provide support for an Industrial Heritage Support Officer based at Ironbridge to work with similar groups running industrial sites. These officers aim to provide a supportive network offering guidance on the establishment of new BPTs, access to funding, training, information and links to associated groups. Case studies and our guidance on the transfer of heritage assets to community and voluntary organisations can be found at www.helm.org.uk/guidance-library/pillars-of-the-community-the-transfer-of-local-authority-heritage-assets

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as it stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

This year the Heritage Lottery Fund has started funding the new Grants for Places of Worship scheme, the main focus of which is fabric repairs but now also includes small changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. *New Work in Historic Places of Worship* (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offer advice and encouragement to congregations. Projects to effect repairs, develop necessary new facilities, provide community facilities, and welcome visitors are all transforming buildings that were once thought to be unfit for purpose.

ARCHAEOLOGY

The continuing success in reducing the number of archaeological sites on the Register, even in difficult economic times, demonstrates the value which owners and land managers place upon the monuments in their care, and more and more are addressing their long-term

management on a regular basis. Many scheduled monuments are now on land subject to an agreement under Natural England's Environmental Stewardship schemes, administered on behalf of Defra. Continuing partnership with Defra and Natural England has resulted in much more effective information sharing which we use in analysing, updating and publishing so that resources – whether Environmental Stewardship or English Heritage – can be more closely targeted where they will have the greatest impact. We have agreed a joint target with Natural England to specifically reduce the number of scheduled monuments on the 2010 Register by 25% by 2015. We also continue to work closely with the Heritage Lottery Fund to help identify those important monuments deserving of grant aid for major stabilisation or repair work.

Nationally, damage from arable cultivation is still the greatest risk factor to archaeological entries on the Register. To help address this, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project, a national survey which looks at ways in which further damage can be avoided whilst enabling cultivation to continue wherever possible will begin reporting in the autumn. Some causes of risk are neither so obvious nor dramatic in their effects however. Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites, even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the *Register of Historic Parks and Gardens of Special Historic Interest* in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's *National Planning Policy Framework* (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the *Register of Historic Parks and Gardens of Special Historic Interest* and that substantial harm or loss of such features can only be justified in exceptional cases.

Most historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take many years to identify and implement solutions to reduce the risks to parks and gardens.

To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Our landscape architects can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/advice-by-topic/parks-and-gardens

BATTLEFIELDS

As with registered parks and gardens, the *Register of Historic Battlefields* brings no additional statutory controls to registered battlefields, but the *National Planning Policy Framework* makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II*, grade I and II* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' appreciation of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered sites.

WRECK SITES

At the strategic level, the major sources of risk to designated wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans.

Risks to protected wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation

requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@english-heritage.org.uk) and from www.helm.org.uk

CONSERVATION AREAS

The risks to conservation areas are difficult to address as they cover large areas of land: they include the spaces between buildings and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage the spaces between the buildings or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved as well, either individually or through groups. Some local groups have helped to prepare character Appraisals and Management Plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/get-involved/improving-your-neighbourhood/

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010 (2010) – a report on the condition of England's listed places of worship and the needs of the congregations

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2013 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2013 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit www.english-heritage.org.uk/risk where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: <http://list.english-heritage.org.uk>

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/heritageprotection

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications or www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for History Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004)

Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance Notes and Application Forms for Grants to Local Authorities:

- *Grants to Local Authorities to Underwrite Urgent Works Notices* (1998)
- *Acquisition Grants to Local Authorities to Underwrite Repairs Notices* (1998)
- *Grants for Historic Buildings, Monuments and Designed Landscapes* (2004)

Heritage at Risk: Conservation Areas (2009) – guidance for local authorities on conservation area management

Heritage Crime Prevention: A guide for Owners, Tenants and managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010)

Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the Transfer of Local Heritage Assets (2011)

Scheduled Monument Consent: a Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department
PO Box 569, Swindon SN2 2YP
Telephone: 0870 333 1181
Fax: 01793 414926
Email: customers@english-heritage.org.uk

Key to the entries

This Register includes the following risk assessment types:

- Buildings and structures
 - grade I and II* listed buildings and structural scheduled monuments
- Places of worship
 - grade I, II* and II listed buildings
- Archaeology
 - scheduled monuments – earthworks and buried archaeology
- Parks and gardens
- Battlefields
- Conservation areas

ORDER

Entries are grouped and ordered alphabetically, first by County† (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough). A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

†The metropolitan counties of South Yorkshire and West Yorkshire are used to group the entries. North Yorkshire is the only two tier planning authority in the region.

Note: since January 2013 the East Midlands team has absorbed responsibility for heritage at risk in North Lincolnshire (UA) and North East Lincolnshire (UA) alongside other planning advisory work. Entries are included on the Yorkshire Register in order to maintain consistency of statistical trends.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings and structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas which are ordered by site name only).

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are included.

CONDITION

For buildings (including places of worship) at risk, condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments), parks and gardens and battlefields) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (is noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY / USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy, or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub/tree growth
- visitor erosion.

For parks and gardens, battlefields and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For **buildings and structures and places of worship** the following priority categories are used as an indication of trend and as a means of prioritising action:

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2012 priority categories are given in brackets, otherwise 'New entry' is noted.

For **battlefields** the following priority categories are used as a means of prioritising action:

- A** No action/strategy identified or agreed (where trend is declining or unknown)
- B** Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C** No action/strategy identified or agreed (where trend is stable or improving)
- D** Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E** Monitoring as appropriate (any trend)
- F** Action implemented/strategy underway/ scheme in progress (any trend)

TREND

Trend for archaeology entries, parks and gardens and battlefields may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the local Heritage at Risk Principal who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| EH | English Heritage |
| HLF | Heritage Lottery Fund |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |

Entries on the Register by local planning authority

| Local Planning Authority | Building and structure entries | Place of worship entries | Archaeology entries | Park and garden entries | Battlefield entries | Wreck site entries | Conservation area entries |
|--|--------------------------------|--------------------------|---------------------|-------------------------|---------------------|--------------------|---------------------------|
| CUMBRIA | | | | | | | |
| Yorkshire Dales (NP) | 1 | 0 | 0 | 0 | 0 | 0 | 1 |
| EAST RIDING OF YORKSHIRE (UA) | | | | | | | |
| East Riding of Yorkshire (UA) | 8 | 6 | 166 | 2 | 1 | 0 | 2 |
| KINGSTON UPON HULL, CITY OF (UA) | | | | | | | |
| Kingston upon Hull, City of (UA) | 0 | 2 | 0 | 0 | 0 | 0 | 2 |
| NORTH EAST LINCOLNSHIRE (UA) | | | | | | | |
| North East Lincolnshire (UA) | 2 | 0 | 2 | 0 | 0 | 0 | 7 |
| NORTH LINCOLNSHIRE (UA) | | | | | | | |
| North Lincolnshire (UA) | 2 | 2 | 13 | 0 | 0 | 0 | 2 |
| NORTH YORKSHIRE | | | | | | | |
| Craven | 1 | 2 | 0 | 0 | 0 | 0 | 0 |
| Hambleton | 5 | 0 | 18 | 0 | 0 | 0 | 0 |
| Harrogate | 9 | 0 | 14 | 3 | 1 | 0 | 0 |
| North York Moors (NP) | 5 | 0 | 93 | 0 | 0 | 0 | 0 |
| Richmondshire | 6 | 0 | 13 | 0 | 0 | 0 | 0 |
| Ryedale | 11 | 1 | 120 | 2 | 0 | 0 | 0 |
| Scarborough | 0 | 2 | 22 | 1 | 0 | 0 | 1 |
| Selby | 4 | 2 | 22 | 0 | 0 | 0 | 0 |
| Yorkshire Dales (NP) | 4 | 1 | 9 | 0 | 0 | 0 | 1 |
| SOUTH YORKSHIRE | | | | | | | |
| Barnsley | 4 | 3 | 8 | 0 | 0 | 0 | 1 |
| Doncaster | 2 | 5 | 15 | 0 | 0 | 0 | 6 |
| Peak District (NP) | 0 | 0 | 3 | 0 | 0 | 0 | 0 |
| Rotherham | 5 | 3 | 12 | 0 | 0 | 0 | 4 |
| Sheffield | 5 | 3 | 6 | 2 | 0 | 0 | 3 |
| WEST YORKSHIRE | | | | | | | |
| Bradford | 5 | 7 | 10 | 1 | 0 | 0 | 11 |
| Bradford / Kirklees / Leeds [†] | 0 | 0 | 0 | 0 | 1 | 0 | 0 |
| Calderdale | 9 | 4 | 5 | 0 | 0 | 0 | 3 |
| Kirklees | 7 | 14 | 4 | 0 | 0 | 0 | 4 |
| Leeds | 11 | 6 | 8 | 2 | 0 | 0 | 5 |
| Peak District (NP) | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Wakefield | 5 | 7 | 6 | 0 | 0 | 0 | 0 |
| Wakefield / Barnsley / Kirklees [†] | 0 | 0 | 0 | 1 | 0 | 0 | 0 |
| YORK (UA) | | | | | | | |
| York (UA) | 0 | 1 | 0 | 0 | 0 | 0 | 2 |
| TOTAL | 111 | 71 | 569 | 14 | 3 | 0 | 55 |

[†]Sites that cross local planning authority boundaries

CUMBRIA

YORKSHIRE DALES (NP)



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | High Hall Farmhouse including cartshed, Dent, South Lakeland |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |

C17 farmhouse once owned by Richard Trotter who led the Dent "statesmen" to purchase the manor of Dent from the crown in 1670. Partially derelict and collapsing.

LIST ENTRY NUMBER: 1383893

Contact: Tammy Whitaker 01904 601880

| | | | |
|----------------|--|-------------|---------------------------------|
| SITE NAME: | Farfield Mill (Sedbergh), Sedbergh, South Lakeland | NEW ENTRY?: | No |
| DESIGNATION: | Conservation Area, 2 LBs | TREND: | Deteriorating |
| CONDITION: | Very bad | CONTACT: | Robert White (LPA) 01969 652360 |
| VULNERABILITY: | Low | | |

EAST RIDING OF YORKSHIRE (UA)



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Flamborough Castle, Tower Street, Flamborough |
| DESIGNATION: | Scheduled Monument and Listed Building grade II, LB grade II, CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |

Mid C14 castle comprised of earthworks and upstanding remains within a pasture field in the centre of the village. The upstanding elements consist of an unconsolidated former undercroft which is made of decaying chalk blocks.

LIST ENTRY NUMBER: 1014896 and 1083401

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Elmswell Old Hall, Elmswell Lane, Garton |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |

House, 1634 with later alterations. Once the home of Henry Best, important C17 agricultural diarist. Isolated and abandoned. Urgent works have been carried out but these have not arrested decay. The whole building is roofless. An application to restore the house to a dwelling was made by the Spitalfield Trust.

LIST ENTRY NUMBER: 1083792

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Gates, gate piers, flanking walls and abutments, Londesborough |
| DESIGNATION: | Listed Building grade I, RPG grade II*, CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |

Gateway, 1660-70, probably by Robert Hooke, forming the principal entrance to Londesborough Park. The caps of the gate piers are deteriorating and trees are growing from the joints. The ball finials have fallen.

LIST ENTRY NUMBER: 1310607

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Paull Holme Tower, Thorngumbald Road, Paull |
| DESIGNATION: | Scheduled Monument and Listed Building grade I |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1007875 and 1366242 |

Mid C15 three storey brick tower house in a scheduled moated site, originally part of a larger manorial complex. A unique survival for this region. Restored and re-roofed in 1871; roofless since the early C20 and suffering from long-term neglect. An options appraisal has been carried out.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Adlingfleet Medieval Rectory, Church Lane, Adlingfleet, Twin Rivers |
| DESIGNATION: | Scheduled Monument and Listed Building grade II*, CA |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1016933 and 1346748 |

Part of a C13 dwelling of the wealthy rector and King's councillor, John le Franceys. Re-used as farm buildings in the C18. A unique survival of a stone-built medieval dwelling in this area. English Heritage and Leader Grant offered.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Outbuildings to Watton Abbey, Church Lane, Watton |
| DESIGNATION: | Scheduled Monument and Listed Building grade II*, LB grade I |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1007751 and 1083773 |

Gilbertine priory buildings, now outbuildings. C16 with later additions and alterations. The structure is derelict and ruinous. A feasibility study has been carried out and funding identified for repair, including possible re-roofing.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Haltemprice Priory Farmhouse, Abbey Lane, Willerby |
| DESIGNATION: | Scheduled Monument and Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1019825 and 1103364 |

Fragmentary remains of a farmhouse dating largely from the C17-C19, incorporating sections of re-used medieval and C16 fabric. In a very advanced state of decay. Proposals for repair and residential re-use are in preparation.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Wressle Castle, Brighton Road, Wressle |
| DESIGNATION: | Scheduled Monument and Listed Building grade I, 2 LBs |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | F (A) |
| OWNER TYPE: | Other not for profit group |
| LIST ENTRY NUMBER: | 1005210 and 1083170 |

Very impressive and important surviving range of a major late C14 castle built for the Percy family and occupied by them during the period when they were at the height of their power as the leading family in northern England. Repaired and consolidated as a roofless ruin in the C19; some repairs in 1970-80s. Grant offered and accepted for repair and survey work has commenced.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Andrew, Main Street, Bainton |
| DESIGNATION: | Listed Place of Worship grade I, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1083830 |

Fine medieval church, C12-C14, restored by Fowler of Louth. Roof and stonework in poor repair, structural movement in east wall. Grant offered in December 2011 under Repair Grants for Places of Worship for repair and work is underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|-------------------------------------|
| SITE NAME: | Church of St Mary, Driffield |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1083376 |

C12 church with C15 west tower, restored by Temple Moore in 1889. Tower roof and stonework in poor condition, some structural movement, glazing and drainage issues. Grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880




© English Heritage

| | |
|--------------------|--------------------------------------|
| SITE NAME: | Church of St Martin, Fangfoss |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1083833 |

Church with C12 origins, partially rebuilt in 1849-50 by Chantrell. Masonry and drainage in poor condition, localised issues with roofs, glazing and internal finishes. Grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Augustine, Church Lane, Hedon |
| DESIGNATION: | Listed Place of Worship grade I, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1346568 |

Magnificent medieval church, C13-C15. The noble central tower dominates the town. A programme of repairs over the years has addressed many issues, but parts of the building are still in poor repair, including the north transept and nave aisles.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Mary, Church Lane, Watton |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (F) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1083772 |

C16 church, largely brick. The roofs have recently been recovered and the parapets repaired. Grant offered in December 2011 under Repair Grants for Places of Worship and repairs underway to the windows and brickwork.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



| | |
|--------------------|--|
| SITE NAME: | Church of St Mary, Main Street, Welwick |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1366256 |

Parish church with elements dating to the C13. Roofs and rainwater goods in poor condition. Grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

© English Heritage

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Bewick Hall moated site, Aldbrough | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1007848 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |
| SITE NAME: | Rectilinear enclosures, Barmby Moor | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1005209 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |
| SITE NAME: | Four round barrows 780m north east of Littlewood Lodge, Bishop Burton | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1007563 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 900m north east of Littlewood Lodge, Bishop Burton | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1007440 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 1000m north east of Littlewood Lodge, Bishop Burton | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1007572 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |
| SITE NAME: | Three round barrows 800m north east of Littlewood Lodge, Bishop Burton | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1007573 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Five round barrows 700m north east of Littlewood Lodge, Bishop Burton / Newbald | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007401 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 250m south of Callis Wold Farm, Bishop Wilton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008366 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 300m south west of Callis Wold Farm, Bishop Wilton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008368 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 400m north east of Wold Farm, Bishop Wilton Wold, Bishop Wilton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008344 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow south east of Cot Nab Farm, Bishop Wilton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009386 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Site of Archbishop's moated palace and fishponds, Hall Garth, Bishop Wilton | | |
| DESIGNATION: | Scheduled Monument, part in CA | LIST ENTRY NUMBER: | 1009383 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Romano-British villa at Cockle Pits, near Brantingham, Brantingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014736 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Dumping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow, 500m south of Buckton Barn, Bridlington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013624 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow, 500m SSW of Buckton Barn, Bridlington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013623 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site at North Park Farm, Burstwick | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008047 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Wharram Hill embankment cross, Burton Agnes | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005199 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Site revealed by aerial photography north west of Argam Cottages, Burton Fleming | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005211 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 200m west of Crest Cottages, Carnaby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007733 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Iron Age square barrow cemetery on Haisthorpe Moor, 750m WNW of Demming Farm, Carnaby / Burton Agnes | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013706 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site and two fishponds 80m south west of Parkhouse Farm, Cherry Burton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007842 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 300m south west of High Gardham Farm, Cherry Burton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007726 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 430m north west of High Gardham Farm, Cherry Burton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012121 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 430m north west of High Gardham Farm, Cherry Burton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007727 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 700m west of High Gardham Farm, Cherry Burton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007728 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Seven round barrows 530m west of High Gardham Farm, Cherry Burton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012187 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows 600m north west of High Gardham Farm, Cherry Burton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008785 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 700m north east of Collingwood Farm, Cottam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007861 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Linear earthwork north east of Collingwood Farm, Cottam / Sledmere | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007862 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Baynard Castle, Cottingham | | |
| DESIGNATION: | Scheduled Monument, LB grade II, CA | LIST ENTRY NUMBER: | 1019823 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Money Hill round barrow, Dalton Holme | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007923 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Site of deserted village of Grimston, East Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021241 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Coastal erosion | NEW ENTRY?: | No |
| OWNER TYPE: | Utility | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Motte and bailey castle, fishpond and moated site north and east of Aughton church, Ellerton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007973 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bolton Old Hall moated site, Fangfoss | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008045 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 150m NNE of Towthorpe High Barn, Fimber | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013702 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow, 150m south east of Towthorpe Reservoir, Fimber | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013703 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Settlement at Blealands Nook, Fimber / Sledmere / Wetwang | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005205 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 350m south east of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007852 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 400m south west of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007856 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 420m south west of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007857 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 440m south west of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007854 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 450m south west of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007853 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 500m south east of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008810 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 500m south of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009394 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 700m south of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007850 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 700m south of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007855 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 750m south of Low Farm, Garton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007851 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Linear earthwork running from the head of Warren Dale towards Sledmere Field Farm and associated settlement site, Garton / Sledmere / Wetwang | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007736 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 230m south west of Enthorpe House, Goodmanham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012835 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 550m north east of Goodmanham Wold Farm, Goodmanham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008933 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 550m south west of Enthorpe House, Goodmanham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008923 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 700m south west of Enthorpe House, Goodmanham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008922 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 1000m north east of Goodmanham Wold Farm, Goodmanham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008934 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 730m NNW of Goodmanham Wold Farm, Goodmanham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007328 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Twelve bowl barrows 800m north of Goodmanham Wold Farm, Goodmanham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007642 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Romano-British villa east of Sandy Lane, 800m north west of Harpham Grange, Harpham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013628 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Park Closes moated lodge, 130m south west of Park Farm, Holme upon Spalding Moor | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015111 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 230m south west of High Barn Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013464 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 400m NNW of East Greenwick Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014727 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 780m north east of Watermanhole Reservoir, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013864 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Pasture, 350m north east of Pasture Dale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013868 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow on Huggate Pasture, 450m NNE of Pasture Dale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013867 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Pasture, 500m north of Pasture Dale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013866 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 400m NNW of Watermanhole Reservoir, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013861 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 460m WNW of western corner of Horsedale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013858 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 480m north of Watermanhole Reservoir, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013862 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 500m NNW of Horsedale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013854 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 580m north west of Horsedale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013857 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 600m NNW of Horsedale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013853 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow on Huggate Wold, 600m west of Horsedale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013859 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 700m NNW of Watermanhole Reservoir, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013863 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 700m north west of Horsedale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013856 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow on Huggate Wold, 840m ENE of Watermanhole Reservoir, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013860 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 240m south west of High Barn Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012491 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 320m south west of High Barn Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012479 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 360m south west of High Barn Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012493 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 380m south west of High Barn Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012505 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 390m south west of High Barn Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012489 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of a single and double linear boundary dyke in Horse Dale, and the junctions of Holm Dale and Harper Dale, north west of Northfield Farm, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015566 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of linear boundary dyke south of Middleham Plantation and Harper Dale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015569 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Sections of linear boundary dyke in Cow Dale Plantation, Rabbit Dale and Oxland Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015570 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two bowl barrows on Huggate Wold, 600m north west of Horsedale Plantation, Huggate | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013855 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Shaw Fosse moated site, Humbleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007847 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Nunnery Hill and adjacent earthworks, Little Kelk, Kelk | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005202 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Gallows Hill round barrow, Kilham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016737 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Iron Age barrow cemetery, Kilham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005208 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 250m north east of Painsthorpe Wold Cottages, Kirby Underdale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008417 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 350m south east of Fordham Farm, Kirby Underdale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013165 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 500m south east of Painsthorpe Wold Cottages, Kirby Underdale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008347 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 600m north east of Painsthorpe Wold Cottages, Kirby Underdale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008408 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 850m north east of Wayrham Farm, Kirby Underdale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008351 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 900m north east of Wayrham Farm, Kirby Underdale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008362 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow south east of South Wold Farm, Kirby Underdale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009384 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Moated site at Metham Hall Farm, Laxton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007972 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site 100m north of Parkhouse Farm, Leconfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008292 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site 310m north east of Scarborough church, Leconfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015818 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site 550m south east of Scarborough Hall, Leconfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016250 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site of Leconfield Castle, Leconfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007949 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hayholme moated site, Leven | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008043 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hall Garth motte and bailey, Lockington | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1021289 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Barf Hill moated site, Lockington / Beswick | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007717 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Cleaving Hall moated site, Londesborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007817 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 100m north east of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013672 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 110m east of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012091 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 200m south east of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012092 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 320m north east of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012090 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 400m south of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012100 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 450m north east of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014256 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 450m north of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012089 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 550m north of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012088 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Nine round barrows south east of Arras Cottages, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005228 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Six bowl barrows 300m north east of High Wold Farm, Market Weighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007501 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Four bowl barrows 450m south east of High Wold Farm, Market Weighton / Sancton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012103 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Iron Age barrow group north east of Middleton on the Wolds, Middleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003597 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 340m south east of Watermanhole Reservoir, Millington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013865 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Dane's Graves, Nafferton / Kilham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005230 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Dumping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Five round barrows 750m south east of Newbald Lodge, Newbald | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007325 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 400m south west of Newbald Lodge, Newbald | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011654 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 550m south east of Newbald Lodge, Newbald | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007320 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 600m south east of Newbald Lodge, Newbald | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007321 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 620m south east of Newbald Lodge, Newbald | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007323 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 700m north east of Littlewood Lodge, Newbald | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007353 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 610m east of Blanch Farm, North Dalton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013460 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 620m ESE of Blanch Farm, North Dalton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013461 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 600m ESE of Blanch Farm, North Dalton / Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013463 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Paull Point Battery, coastal artillery battery and Submarine Mining Establishment, Paull | | |
| DESIGNATION: | Scheduled Monument, LB grade II, part in CA | LIST ENTRY NUMBER: | 1020425 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Coastal erosion | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Paull Holme moated site and tower, Paull | | |
| DESIGNATION: | Scheduled Monument and Listed Building grade I | LIST ENTRY NUMBER: | 1007875 and 1366242 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Earthwork on the Sheepwalk stretching north from Wold Gate for 530yds (480m), Rudston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005223 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|----------------------------------|--------------------|-----------------------------|
| SITE NAME: | Roman villa site, Rudston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005222 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Rudston Beacon and round barrows to east, Rudston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005231 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 550m south of High Wold Farm, Sancton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012102 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Moated monastic grange 300m south west of Winsetts Farm, Skeffling | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015309 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Hallgarth medieval hall and moat, Skipsea | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013705 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Royal Observer Corps underground monitoring post and World War II visual spotting post, 200m north of Southfield House, Skipsea | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021192 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Skipsea Castle: 11th century motte and bailey castle and inland harbour, Skipsea | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011212 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Moated site, fishponds and associated earthworks at Manor House, Skirpenbeck | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015614 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 1300m east of Life Hill, Sledmere | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007858 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 1400m east of Life Hill, Sledmere | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007859 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 1650m east of Life Hill, Sledmere | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007860 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Kings Manor moated site, 450m south of Little London, Snaith and Cowick | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015307 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Stone Creek Heavy Anti-aircraft gunsite, at Sunk Island Clough, Sunk Island | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1020187 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Moated site at St Lois Farm, Sutton upon Derwent | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007818 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Willy Howe round barrow, Thwing / Burton Fleming | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008040 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Hall Garth moated site, associated drainage channels and fishpond, Twin Rivers | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013190 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 170m north west of Farberry Garth Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013471 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 210m south east of Blanch Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013456 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 290m south east of Blanch Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013457 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 500m east of Blanch Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013459 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 560m NNW of Farberry Garth Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013467 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 720m NNW of Farberry Garth Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013466 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 760m NNE of Farberry Garth Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013465 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 100m south west of Cobdale Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011895 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 400m north west of Cobdale Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012508 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 450m north east of Blanch Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011906 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 520m south of Warren Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011890 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 915m north east of Dalton Gates Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011911 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 930m north east of Dalton Gates Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011910 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--------------------------------------|--------------------|-----------------------------|
| SITE NAME: | Round barrow on Thirty Acres, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011908 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Section of linear boundary dyke between Sylvan Dale and Warren Farm, north west of Coldwold Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016191 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Two bowl barrows 300m south east of Blanch Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013458 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Two bowl barrows 500m north west of Farberry Garth Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013470 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Two round barrows 820m north east of Dalton Gates Farm, Warter | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011912 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS


| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Haltemprice Augustinian priory, Willerby | | |
| DESIGNATION: | Scheduled Monument and Listed Building grade II* | LIST ENTRY NUMBER: | 1019825 and 1103364 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 580m west of High Fordon Farm, Wold Newton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007743 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 600m west of High Fordon Farm, Wold Newton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007742 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Hall Garth moated site south of Beverley Minster, Woodmansey / Beverley | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1008122 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Thwaite Hall, Cottingham | Grounds of a villa developed mainly in the 1870s/80s, but modified in the mid C20 to provide accommodation for the University College of Hull. Grounds partly developed as a botanical garden. Problems with flood damage in 2007 and drainage problems are affecting mature planting and lawns around the lake. |
| DESIGNATION: | Registered Park and Garden grade II, CA | |
| CONDITION: | Generally satisfactory but with significant localised problems | |
| VULNERABILITY: | High | |
| TREND: | Declining | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1000137 | Contact: Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|---|
| SITE NAME: | Londesborough Park, Londesborough | Gardens laid out in the late C17 wholly or partly by Robert Hooke for the first Lord Burlington, with alterations and additions by the third Lord Burlington in the early to mid C18. Park with avenues of early C18 date with earlier origins. Kitchen garden of 1730-5 with cascades and entrances aligned with parkland avenues. Extensive parkland requiring more detailed study of historic development of the planting design, key avenues and vistas. Structures in walled garden in state of deterioration. |
| DESIGNATION: | Registered Park and Garden grade II*, 4 LBs, part in CA | |
| CONDITION: | Generally satisfactory but with significant localised problems | |
| VULNERABILITY: | High | |
| TREND: | Declining | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Private, multiple owners | |
| LIST ENTRY NUMBER: | 1000924 | Contact: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© Battlefields Trust

| | |
|--------------------|--|
| SITE NAME: | Battle of Stamford Bridge, Stamford Bridge |
| DESIGNATION: | Registered Battlefield |
| CONDITION: | Generally satisfactory but with minor localised problems |
| VULNERABILITY: | High |
| TREND: | Declining |
| PRIORITY CATEGORY: | A |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1000035 |

Three weeks before the Battle of Hastings (1066) King Harold defeated a Norwegian army at this crossing point on the River Derwent. The modern settlement of Stamford Bridge grew markedly in the later C20 and little of the battlefield remains undeveloped.

Contact: Tammy Whitaker 01904 601880

| | | | |
|----------------|--------------------------------------|-------------|-----------------------------------|
| SITE NAME: | Bridlington Quay, Bridlington | NEW ENTRY?: | No |
| DESIGNATION: | Conservation Area, 19 LBs | TREND: | Improving |
| CONDITION: | Very bad | CONTACT: | Malte Klockner (LPA) 01482 393725 |
| VULNERABILITY: | Low | | |

| | | | |
|----------------|--|-------------|-----------------------------------|
| SITE NAME: | Goole, East Riding of Yorkshire | NEW ENTRY?: | No |
| DESIGNATION: | Conservation Area | TREND: | Deteriorating significantly |
| CONDITION: | Very bad | CONTACT: | Malte Klockner (LPA) 01482 393725 |
| VULNERABILITY: | Low | | |

KINGSTON UPON HULL, CITY OF (UA)



© PCC

| | |
|--------------------|------------------------------------|
| SITE NAME: | St Albans Church, Hall Road |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1382106 |

Parish church dating to 1938, completed 1954. Constructed from orange brick under a pantile roof. Interior has flat concrete arches. Tower repaired with grant offered in March 2007 under Repair Grants for Places of Worship. Aisle roofs are in need of recovering. Grant offered in March 2012 for first phase of roof repair under Repair Grants for Places of Worship and repairs underway. Grant offered in March 2013 for second phase of roof repair under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Charles Borromeo, Jarratt Street, Kingston Upon Hull |
| DESIGNATION: | Listed Place of Worship grade II*, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1197723 |

Built to the designs of John Earle in 1829, altered and enlarged by JJ Scholes in 1835 and further enlarged between 1894 and 1900 by Smith, Brodrick and Lowther. Roofs and rainwater goods are in poor condition which has led to water ingress that has damaged internal plasterwork and decorations. Some windows and stucco also in poor condition.

Contact: Tammy Whitaker 01904 601880

| | | | |
|----------------|----------------------------|-------------|----------------------------------|
| SITE NAME: | Beverley Road, Hull | NEW ENTRY?: | No |
| DESIGNATION: | Conservation Area, 12 LBs | TREND: | Deteriorating |
| CONDITION: | Poor | CONTACT: | Philip Hampel (LPA) 01482 612343 |
| VULNERABILITY: | Medium | | |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|--------------------------------|-------------|----------------------------------|
| SITE NAME: | St Andrew's Dock, Hull | | |
| DESIGNATION: | Conservation Area, LB grade II | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating significantly |
| VULNERABILITY: | Medium | CONTACT: | Philip Hampel (LPA) 01482 612343 |

NORTH EAST LINCOLNSHIRE (UA)

© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | The Grimsby Ice Factory, Gorton Street, Grimsby | 1900 ice works with extension factory of 1907-8 and later alterations. Closed in 1990. It is thought that this is the earliest surviving ice factory in Britain, and the sole survivor from this period to retain its machinery. Window damage. Roof is now deteriorating rapidly. |
| DESIGNATION: | Listed Building grade II* | |
| CONDITION: | Very bad | |
| OCCUPANCY: | Vacant/not in use | |
| PRIORITY CATEGORY: | A (A) | |
| OWNER TYPE: | Commercial company | |
| LIST ENTRY NUMBER: | 1379842 | |



© English Heritage Archive

| | | |
|--------------------|--|---|
| SITE NAME: | Church of Saint Margaret, Barton Street, Hawerby cum Beesby | Former parish church. C12, C13 and C17 with mid C19 restorations. Empty and disused since closed in 1978. Longstanding proposals for conversion to studio/gallery have not been implemented. Suffering from neglect, with localised collapses of walling. Grant offered and project development phase underway. |
| DESIGNATION: | Listed Building grade II* | |
| CONDITION: | Very bad | |
| OCCUPANCY: | Vacant/not in use | |
| PRIORITY CATEGORY: | F (A) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1310283 | |

| | | | |
|--------------------------|--|--------------------|---------------------------|
| SITE NAME: | Civil War earthwork fort 350m north east of Walk Farm, Irby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007735 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

| | | | |
|--------------------------|---|--------------------|---------------------------|
| SITE NAME: | Premonstratensian priory chapel 170m south west of Priory Farm, West Ravendale | | |
| DESIGNATION: | Scheduled Monument, LB grade II | LIST ENTRY NUMBER: | 1019867 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

| | | | |
|----------------|------------------------------|-------------|------------------------------------|
| SITE NAME: | Central Area, Grimsby | | |
| DESIGNATION: | Conservation Area, 23 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving |
| VULNERABILITY: | Medium | CONTACT: | Elizabeth Mayle (LPA) 01472 324252 |

| | | | |
|----------------|---------------------------------------|-------------|------------------------------------|
| SITE NAME: | Central Sea Front, Cleethorpes | | |
| DESIGNATION: | Conservation Area, 11 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving |
| VULNERABILITY: | Medium | CONTACT: | Elizabeth Mayle (LPA) 01472 324252 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|--|-------------|------------------------------------|
| SITE NAME: | Great Coates, Grimsby, Great Coates | | |
| DESIGNATION: | Conservation Area, 9 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | No significant change |
| VULNERABILITY: | Medium | CONTACT: | Elizabeth Mayle (LPA) 01472 324252 |
| <hr/> | | | |
| SITE NAME: | Holme Hill, Grimsby | | |
| DESIGNATION: | Conservation Area, 8 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating significantly |
| VULNERABILITY: | Medium | CONTACT: | Elizabeth Mayle (LPA) 01472 324252 |
| <hr/> | | | |
| SITE NAME: | Laceby | | |
| DESIGNATION: | Conservation Area, 3 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | No significant change |
| VULNERABILITY: | Medium | CONTACT: | Elizabeth Mayle (LPA) 01472 324252 |
| <hr/> | | | |
| SITE NAME: | Waltham | | |
| DESIGNATION: | Conservation Area, 2 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Elizabeth Mayle (LPA) 01472 324252 |
| <hr/> | | | |
| SITE NAME: | Wellow, Grimsby | | |
| DESIGNATION: | Conservation Area, 26 LBs, RPG grade II | NEW ENTRY?: | Yes |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Elizabeth Mayle (LPA) 01472 324252 |

NORTH LINCOLNSHIRE (UA)



© English Heritage Archive

| | | |
|--------------------|---|--|
| SITE NAME: | Hibaldstow Mill and walls to mill pond and wheel race, Ings Lane, Hibaldstow | Combined wind and watermill, 1802, by James Middleton of Hibaldstow. Some repairs undertaken, but further work required to both exterior and interior. |
| DESIGNATION: | Scheduled Monument and Listed Buildings - I grade II*; I grade II | |
| CONDITION: | Fair | |
| OCCUPANCY: | Part occupied/part in use | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1008528 and 1083709; 1162093 | Contact: Ben Robinson 01480 412107 |



© English Heritage Archive

| | | |
|--------------------|--|--|
| SITE NAME: | Manor Farmhouse, East Halton Road, North Killingholme | Medieval, C17-C19 manor house on a scheduled moated site. Exceptional multi-period survival for this region. The roof was repaired in 1980, but little has been done since and the interior is propped with scaffolding. A feasibility study has been completed. |
| DESIGNATION: | Listed Building grade II*, SM | |
| CONDITION: | Very bad | |
| OCCUPANCY: | Vacant/not in use | |
| PRIORITY CATEGORY: | B (B) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1346854 | Contact: Ben Robinson 01480 412107 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



| | |
|--------------------|--|
| SITE NAME: | Church of St Martin, Church Street, Owston Ferry |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1083261 |

Medieval church with early C19 north aisle. Roofs and drainage in poor condition. Grant offered in December 2010 under Repair Grants for Places of Worship and repairs underway.

Contact: Ben Robinson 01480 412107

© English Heritage



| | |
|--------------------|---|
| SITE NAME: | Church of All Saints, Church Lane, Saxby All Saints |
| DESIGNATION: | Listed Place of Worship grade II, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1103702 |

Late C13 church rebuilt in 1845-9 by George Gilbert Scott in the early Decorated style with tower rebuilt by Neville in 1873. Roofs, rainwater goods and high-level masonry in poor condition. Grant offered in March 2013 under Repair Grants for Places of Worship.

Contact: Ben Robinson 01480 412107

© English Heritage

| | | | |
|--------------------------|---|--------------------|---------------------------|
| SITE NAME: | Heavy Anti-aircraft gunsite 220m east of West Marsh Cottage, Barrow upon Humber | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020024 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Deterioration - in need of management | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

| | | | |
|--------------------------|--|--------------------|---------------------------|
| SITE NAME: | Moated site 285m east of Castlethorpe House, Broughton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016429 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

| | | | |
|--------------------------|--|--------------------|---------------------------|
| SITE NAME: | Yarborough Camp large univallate hillfort, Croxton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016427 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

| | | | |
|--------------------------|----------------------------------|--------------------|---------------------------|
| SITE NAME: | Money Field Roman site, Dragonby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005224 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

| | | | |
|--------------------------|--|--------------------|---------------------------|
| SITE NAME: | Romano-British settlement near Staniwells Farm, Hibaldstow | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005221 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|---------------------------|
| SITE NAME: | Roman settlement, Kirmington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005206 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |
| SITE NAME: | Romano-British villa at Mount Pleasant Farm, Kirton in Lindsey | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013627 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |
| SITE NAME: | Moated site and fishpond 200m south east of Melton Hall, Melton Ross | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007747 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |
| SITE NAME: | North Garth moated site and associated enclosures, North Killingholme | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007815 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |
| SITE NAME: | Kinaird motte and bailey castle, Owston Ferry | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017556 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |
| SITE NAME: | Old Winterringham Roman settlement, Winterringham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005243 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |
| SITE NAME: | Howe Hill bowl barrow, Wootton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009346 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|---------------------------|
| SITE NAME: | Roman site 400yds (370m) north east of Worlaby Church, Worlaby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005233 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Ben Robinson 01480 412107 |

| | | | |
|----------------|---------------------------|-------------|-----------------------------------|
| SITE NAME: | Crowle | | |
| DESIGNATION: | Conservation Area, 14 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving |
| VULNERABILITY: | Low | CONTACT: | Ian Goldthorpe (LPA) 01724 297396 |

| | | | |
|----------------|---------------------------|-------------|-----------------------------------|
| SITE NAME: | Winterton | | |
| DESIGNATION: | Conservation Area, 25 LBs | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Ian Goldthorpe (LPA) 01724 297396 |

NORTH YORKSHIRE

CRAVEN



© English Heritage Archive

| | |
|--------------------|---------------------------------------|
| SITE NAME: | Dale End Mills, Dale End, Lothersdale |
| DESIGNATION: | Scheduled Monument, 2 LBs, CA |
| CONDITION: | Poor |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1004071 |

C19 mill, including disused waterwheel (1861), pit and enclosing building. The mill-wheel is the largest in England and is in poor condition. The mill roofs are deteriorating. The base of the stack is also in need of remedial work. Discussions are underway with the owner to find a solution for the complex. The condition of the chimney, wheel and building have been assessed.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St James, Church Avenue, Clapham cum Newby |
| DESIGNATION: | Listed Place of Worship grade II, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1132398 |

Parish church dating to 1814 with C15 tower and c1900 alterations. Parapets are in poor condition and water ingress has damaged internal finishes. Grant offered in March 2013 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Mary the Virgin, Church Street, Long Preston |
| DESIGNATION: | Listed Place of Worship grade I, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1157818 |

Late C14/early C15 parish church with C19 and C20 alterations. Chancel restored 1867-68 by Healey of Bradford. Windows by Capronnier of Brussels. Glazing in poor condition and localised roof and masonry issues. Grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

HAMBLETON



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | The Coach House, Rounton Grange, East Rounton |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | F (A) |
| OWNER TYPE: | Other not for profit group |
| LIST ENTRY NUMBER: | 1150672 |

Coach house, built in 1875. Now used as a combined home and workshop. One range is in fair condition, the rest is in a state of collapse. Permission has been granted, subject to a Planning Agreement, to convert the premises into four dwellings and it is proposed that work will start in 2013.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Landmoth Hall, Landmoth-cum-Catto |
| DESIGNATION: | Scheduled Monument |
| CONDITION: | Very bad |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | B (B) |
| OWNER TYPE: | Other not for profit group |
| LIST ENTRY NUMBER: | 1013350 |

Part of the east wing of a medieval manor house. Now in an unstable condition. 20/06/2013 has now been accepted for a 'midi bar project' and the owners will be invited to apply for a grant to consolidate the ruins.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | West Lodge, Thornton Stud, Newsham Road, Newsham with Breckenbrough |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1150821 |

Late C18 lodge and entrance gateway. Some roof repairs have been undertaken.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Snape Castle, Snape with Thorp |
| DESIGNATION: | Scheduled Monument and Listed Building grade I, RPG grade II, part in CA |
| CONDITION: | Very bad |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | B (B) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1004908 and 1190147 |

Castle dated to circa 1430, with additions and alterations in the C16 and C18. It is comprised of extensive ruins, including some vaulted rooms and two towers. The rear ranges are in a poor condition. The upper parts of the towers are particularly unstable. Much repointing is required elsewhere. The front ranges are divided into two dwellings.

Contact: Tammy Whitaker 01904 601880



© Hambleton District Council

| | |
|--------------------|--|
| SITE NAME: | Stables at Harlsey Castle Farmhouse, West Harlsey |
| DESIGNATION: | Scheduled Monument and Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Occupied/in use |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1004183 and 1188946 |

Remains of medieval castle keep; in use as farm buildings.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Medieval moated grange 160m south east of The Grange, Balk | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015920 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 150m south of Warren House, Brandsby-cum-Stearsby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013601 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 300m east of Warren House, Brandsby-cum-Stearsby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013600 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 300m west of Quarry House, Brandsby-cum-Stearsby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013602 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 450m north east of Hagg Farm, Brandsby-cum-Stearsby / Dalby-cum-Skewsby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013592 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site immediately south of Danby Wiske church, Danby Wiske with Lazenby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020346 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Gardening | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Deighton moated site, Deighton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004099 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Lime kilns 400m south west of Furlands, Kewick / Borrowby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021190 |
| CONDITION: | Unknown | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Deterioration - in need of management | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of cross ridge dyke and earthworks in Roman Plantation, Oulston Moor, Oulston | | |
| DESIGNATION: | Scheduled Monument, part in RPG grade II | LIST ENTRY NUMBER: | 1013438 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | A moated site 100m east of St Mary Magdalene's Church, Thirsk | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1008179 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow known as Gospel Hill, 80m south west of Pasture House, Thornton Watlass | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018922 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Maiden Bower and Cock Lodge: a motte and bailey castle, moated site, windmill mound and associated linear outwork, Topcliffe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011612 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Three round barrows at Three Hills 500m north east of Camp House, West Tanfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015764 |
| CONDITION: | Extensive significant problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Earth circles, cursus, pit alignments and burial sites near Nosterfield and Thornborough, including Centre Hill round barrow, West Tanfield / East Tanfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004912 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Four round barrows on Yearsley Moor 200m south west of High Lions' Lodge, Yearsley | | |
| DESIGNATION: | Scheduled Monument, RPG grade II | LIST ENTRY NUMBER: | 1013446 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Yearsley Moor 330m SSW of High Lions' Lodge, Yearsley | | |
| DESIGNATION: | Scheduled Monument, RPG grade II | LIST ENTRY NUMBER: | 1013448 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Yearsley Moor 400m south west of High Lions' Lodge, Yearsley | | |
| DESIGNATION: | Scheduled Monument, RPG grade II | LIST ENTRY NUMBER: | 1013447 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows on Yearsley Moor 550m south west of High Lions' Lodge, Yearsley | | |
| DESIGNATION: | Scheduled Monument, RPG grade II | LIST ENTRY NUMBER: | 1013449 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

HARROGATE

| | | | |
|--|--------------------|---|---|
|  | SITE NAME: | Chapel of St Mary attached to the mansion, Allerton Park, Allerton Mauleverer with Hopperton | <p>Former Roman Catholic chapel, circa 1807, attached to the grade I house. The house stands on a promontory in the eastern section of the C18 park, with mid C19 terraces to the north. Much of the interior of the chapel has been stripped out for dry rot treatment. English Heritage has grant-aided repairs to the roof, windows and internal floor, which when complete will allow the chapel to be given a use. Further repairs are proposed to the internal plasterwork.</p> |
| | DESIGNATION: | Listed Building grade II*, RPG grade II | |
| | CONDITION: | Fair | |
| | OCCUPANCY: | Vacant/not in use | |
| | PRIORITY CATEGORY: | F (C) | |
| | OWNER TYPE: | Charity (heritage) | |
| | LIST ENTRY NUMBER: | 1149995 | |
|  | SITE NAME: | Church of St Mary, Harlow Terrace, Harrogate | <p>Former church built circa 1916 by Sir Walter Tapper. Deterioration of the stone has occurred from an early date. There is evidence that the mineral felt to the aisle roofs is leaking. It is now proposed to convert the church into a luxury day spa, with minimal internal subdivision. English Heritage have offered grant towards project development.</p> |
| | DESIGNATION: | Listed Building grade II*, CA | |
| | CONDITION: | Poor | |
| | OCCUPANCY: | Vacant/not in use | |
| | PRIORITY CATEGORY: | F (F) | |
| | OWNER TYPE: | Commercial company | |
| | LIST ENTRY NUMBER: | 1149482 | |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© Harrogate Borough Council

| | |
|--------------------|--|
| SITE NAME: | Coach house and bee hives approx 10 metres to north of Nutwith Cote, Grewelthorpe Road, Burton-on-Yore |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1132066 |

Coach house with bee hives. Mid C18 and C16. The rear hall of the coach house is settling and the end return of the bee hives is failing. There are structural cracks to the right hand return and rear, and some of the copings are missing from the rear gable. Pointing is failing to cut stone on facades leaving some stone loose.

Contact: Tammy Whitaker 01904 601880



© Harrogate Borough Council

| | |
|--------------------|--|
| SITE NAME: | Outbuilding approx 20m to north of Nutwith Cote, Grewelthorpe Road, Burton-on-Yore |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1316886 |

Early C18 outbuilding/store. The building has been vacant for some time. Emergency re-roofing in corrugated asbestos was carried out many years ago. Building is slowly decaying, with open joints and defective rainwater goods. The corrugated asbestos roof appears to be failing at the ridge and at one of the gables.

Contact: Tammy Whitaker 01904 601880



© Harrogate Borough Council

| | |
|--------------------|--|
| SITE NAME: | Temple of Victory with railed enclosure, Allerton Park, Flaxby |
| DESIGNATION: | Listed Building grade II*, RPG grade II |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Charity (heritage) |
| LIST ENTRY NUMBER: | 1315590 |

Summerhouse or view point, 1790, situated on a knoll in the park, to north west of the house. Re-roofed, cornice repaired and building made secure over 15 years ago with grant aid from English Heritage and Harrogate Borough Council. Repairs needed to stonework below cornice level and to steps and railings, and interior needs re-instating. Extensive views from the Temple over the park and surrounding landscape.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | The Old Hall, Middleton Quernhow |
| DESIGNATION: | Scheduled Monument and Listed Building grade II |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | D (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1005473 and 1150058 |

Gable wall and part of the south wall of an early C17 house. Many open joints are visible and part of chimney stack appears to be unstable.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Harrogate Borough Council

| | |
|--------------------|---|
| SITE NAME: | Orangery with flanking walls, botheys and pavilion (Ripley Castle), Ripley |
| DESIGNATION: | Listed Building grade II*, RPG grade II, CA |
| CONDITION: | Poor |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1315394 |

Classical Orangery in walled garden with flanking pavilions, circa 1785 by William Belwood. One surviving glasshouse circa 1840, now repaired. Botheys, in poor condition, to rear. East Pavilion recently repaired and some emergency repairs to Orangery. The balustrade has been dismantled and the cornice has been temporarily supported to prevent collapse.

Contact: Tammy Whitaker 01904 601880



© Harrogate Borough Council

| | |
|--------------------|---------------------------------|
| SITE NAME: | Butterton Bridge, Sawley |
| DESIGNATION: | Scheduled Monument |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1004202 |

Medieval bridge, now crossed by a public footpath. The structure is overgrown and decaying and there is danger of structural collapse. The bridge is now under new ownership.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Dob Park Lodge, Dob Park Lane, Weston |
| DESIGNATION: | Scheduled Monument |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1015630 |

Ruins of a C17 park lodge, now roofless structure three storeys high. Scheduled as an Ancient Monument in 1997. English Heritage has grant-aided emergency works. An archaeological assessment and feasibility study have been produced in an effort to find a sustainable use for the building.

Contact: Tammy Whitaker 01904 601880

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Cairnfield, enclosures, boulder walling, hollow way and carved rocks towards edge of Snowden Carr centred at 370m south east of Crag House, Askwith | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014304 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Rock with complex carving south west of a wall junction, 265m SSW of Far High Westcliff, Bewerley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014969 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Stone alignment west of Boroughbridge known as the Devil's Arrows, including three standing stones and the setting for a fourth, Boroughbridge | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014705 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Improving |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Henge monument 300m north of Nunwick, Hutton Conyers | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012724 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Hutton Hall (site of), Hutton Conyers | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004074 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Stock erosion - localised/limited | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 150m east of Burtree Hill, Hutton Conyers | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013396 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 300m WNW of Low Barn, Hutton Conyers | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013395 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow at Moor House, Hutton Conyers | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009784 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow in Harland's Plantation, Hutton Conyers | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009785 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Motte and bailey castle, known as Mowbray Castle, east of Kirkby Malzeard, Kirkby Malzeard | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012994 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Rougemont Castle ringwork and bailey and associated fishponds and outwork, Kirkby Overblow / Weeton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1010026 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Medieval monastic fishponds immediately east of Park House, Markington with Wallerthwaite | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018691 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Moated site 50m north west of Red House, Moor Monkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020887 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Moated site 50m north east of North Rigton School, North Rigton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017716 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Stock erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Allerton Park, Allerton Mauleverer with Hopperton / Flaxby |
| DESIGNATION: | Registered Park and Garden grade II, 19 LBs |
| CONDITION: | Generally unsatisfactory with major localised problems |
| VULNERABILITY: | Medium |
| TREND: | Declining |
| NEW ENTRY?: | No |
| OWNER TYPE: | Private, multiple owners |
| LIST ENTRY NUMBER: | 1000402 |

Mid C19 terraced gardens which provide the setting for a country house, surrounded by parkland which was enlarged in the 1720s and reworked in the 1770s. C20 woodland planting has significantly changed the character of the historic landscape and a number of listed structures are in poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Plumpton Rocks, Plumpton |
| DESIGNATION: | Registered Park and Garden grade II*, 12 LBs, CA |
| CONDITION: | Generally satisfactory but with significant localised problems |
| VULNERABILITY: | Medium |
| TREND: | Declining |
| NEW ENTRY?: | No |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1000535 |

Mid C18 pleasure grounds laid out with advice from John Carr as the grounds for a country house built within a pre-existing park of C16 origin. Painted by JMW Turner in 1798. Landscape designed around an artificial lake contained by dam, probably designed by John Carr. Lake surrounded by picturesque sandstone outcrops frequently surmounted by trees. Progressive silting of lake and regeneration of trees and shrubs is severely compromising the historic views within the site and the relationships of planting, rocks and lake. Natural England Higher Level Stewardship agreement in place.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Swinton Castle, Swinton with Warthermarske |
| DESIGNATION: | Registered Park and Garden grade II*, 6 LBs |
| CONDITION: | Generally satisfactory but with significant localised problems |
| VULNERABILITY: | Medium |
| TREND: | Declining |
| NEW ENTRY?: | No |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1001074 |

Gardens and extensive pleasure grounds with grottos, rustic bridges and rockwork laid out from 1796 to c1820 under the direction of Adam Mickle the second and others for Sir William Danby, incorporating lakes and landscaping of c1760. The park probably has C17 or earlier origins. Significant proportion of the tree cover has reached maturity and beyond, some structures in poor condition and water bodies in Quarry Gill woods heavily silted.

Contact: Tammy Whitaker 01904 601880



© Battlefields Trust

| | |
|--------------------|--|
| SITE NAME: | Battle of Boroughbridge, Boroughbridge / Langthorpe / Milby |
| DESIGNATION: | Registered Battlefield, 2 LBs, part in CA |
| CONDITION: | Generally satisfactory but with significant localised problems |
| VULNERABILITY: | Medium |
| TREND: | Stable |
| PRIORITY CATEGORY: | C |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1000003 |

Thomas Earl of Lancaster's 1322 revolt against Edward II ended with defeat as his army attempted to retreat north and cross the River Ure. Much of the battlefield lies under modern Boroughbridge; further expansion is possible north of the river.

Contact: Tammy Whitaker 01904 601880

NORTH YORK MOORS (NP)




© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Ruins of Whorlton Castle Undercroft, Castle Bank, Whorlton, Hambleton |
| DESIGNATION: | Scheduled Monument and Listed Buildings - 2 grade I; 1 grade II*, part in CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1007641 and 1151332; 1294328; 1189310 |

C14 castle. Parts of two vaulted chambers remain. English Heritage grant has been offered towards project development for a scheme to convert the adjacent gatehouse into holiday accommodation. If this goes ahead the undercroft will be repaired as part of the scheme.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Whorlton Castle Gatehouse, Castle Bank, Whorlton, Hambleton |
| DESIGNATION: | Scheduled Monument and Listed Buildings - 2 grade I; 1 grade II*, part in CA |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1007641 and 1151332; 1294328; 1189310 |

Shell remains of a late C14 gatehouse, which was altered in the C16. Conservation plan complete. Possible conversion to holiday accommodation being considered and English Heritage grant has been offered towards project development.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Ionic Temple, Duncombe Park Estate, Helmsley, Ryedale |
| DESIGNATION: | Listed Building grade I, RPG grade I |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1149311 |

Decorative temple, circa 1730, attributed to Vanbrugh, situated at the north end of the approximately 800 metres long, grass East Terrace, approximately 120 metres east of the house. The column shafts are badly decayed. Grant has been offered for repair and a scheme is in preparation.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Tuscan Temple, Duncombe Park Estate, Helmsley, Ryedale |
| DESIGNATION: | Listed Building grade I, RPG grade I |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1295364 |

Decorative temple circa 1730 in the Palladian style situated at the south end of the East Terrace. The column shafts are badly decayed and internal plasterwork in poor repair. A repair scheme is in preparation and funding has been identified.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Ayton Castle, Castle Rise, West Ayton, Scarborough |
| DESIGNATION: | Scheduled Monument and Listed Building grade I, part in CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | F (C) |
| OWNER TYPE: | Local authority |
| LIST ENTRY NUMBER: | 1015410 and 1148147 |

Pele tower, late C14. The upper storeys are ruinous, but the undercroft still has a vaulted roof. Subject to weathering. Grant has been offered for a second phase of work which will complete the repair of the castle.

Contact: Tammy Whitaker 01904 601880

SITE NAME: **Group of round barrows on Bilsdale Moor 1/2 mile (800m) north west of Fangdale Beck, Bilsdale Midcable, Hambleton**

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004148 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Other | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

SITE NAME: **Round barrow 550m east of Cam House, Bilsdale Midcable, Hambleton**

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012488 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Other | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Pit alignment forming part of the Cleave Dyke system 1000m north west of Dialstone Farm, Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1010345 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Pit alignment, part of the Cleave Dyke prehistoric boundary system and round barrow 450m south east of High Paradise, Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015576 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Ravensthorpe manor house (site of), Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004083 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Animal burrowing - localised/limited | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 400m south east of Hill Fort Windypit, Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1010341 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 500m south east of Hill Fort Windypit, Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1010342 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 600m north east of South Woods, Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013085 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 650m east of South Woods, Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1010343 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 350m west of Green Bank, Carlton, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008856 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 300m south east of Faceby Plantation, Faceby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012731 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Ayton Banks alum works, Great Ayton, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020347 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 200m south of Green Bank, Great Busby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008854 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Section of the Cleave Dyke system known as Hesketh Dike and Silver Hill round barrow, Hawnby / Old Byland and Scawton / Boltby, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015575 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 480m east of Yorkshire Gliding Club, Kilburn High and Low, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014564 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 600m north west of Garbutt Farm, Sutton-under-Whitstonecliffe, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018550 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 200m north west of Scarth Nick, Whorlton, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008862 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 500m west of Red Way Head, Whorlton, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012728 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow at northern edge of Snotterdale Plantation, Whorlton, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012736 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows 275m south of Scarth Wood, Whorlton, Hambleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011917 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Oxmoor and Givendale Dikes: prehistoric linear boundaries and associated features, Allerston / Eberston and Yedingham, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020834 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Beadlam Rigg, 490m west of Stone Ruckles round barrow, Beadlam, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019516 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow at Crook Staff Hill, Bransdale, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009360 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Other | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow at Blanket Head, 350m north west of Broad Head Farm, Eberston and Yedingham, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020698 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Blakey Howe round barrow, Farndale East / Rosedale West Side, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018983 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Pike Howe round cairn, Farndale East / Rosedale West Side, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018986 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Cairnfield 200m east of Hazelshaw House, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008860 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Cairnfield 500m north east of Bumper Castle, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009358 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Other | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 11m east of Hazel Head Wood, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008585 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 150m north east of Silver Hill Farm, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016052 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 500m east of Silver Hill Farm, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016066 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 500m north west of Lower Locker Farm, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009371 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 550m south east of High Cote Farm, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013223 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows at Sour Milk Hills, Hawnby, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008442 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Other | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Douthwaite pillow mounds, Hutton-le-Hole, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016024 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Four round barrows one 400m and three 540m east of Grouse Hall, Hutton-le-Hole, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016023 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows, 245m and 340m north west of Barmoor Lodge, Hutton-le-Hole, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016022 |
| CONDITION: | Unknown | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 400m north east of Low Pasture Farm, Lockton, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021097 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 430m north west of Crossdale Head, Lockton, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021098 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Cross dyke centred 480m south of Fox and Rabbit Farm, Lockton / Thornton-le-Dale, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021170 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Potato Nab round barrow 1020m south west of Penny Holme, Nawton, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019592 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 350m south of Long Plain Farm, Old Byland and Scawton, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009793 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow on Scawton Moor, 620m north west of High Lodge, Old Byland and Scawton, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019824 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Four round barrows 875m north west of High Blansby, Pickering, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020818 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 440m north of Blansby Park Farm, Pickering, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020817 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Cairn cemetery north east of Birk Nab Farm, Pockley, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004088 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Linear boundary earthwork 370m east of Oscar Park Farm, Rievaulx, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019340 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Shunner Howe round barrow, Rosedale East Side / Egton / Glaisdale / Hartoft, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018763 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Pry Rigg round barrows, Sproxton, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004086 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two sections of Roman road on Flamborough Rigg, Stape, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004104 |
| CONDITION: | Unknown | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Forestry | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Rabbit type 570m south east of Pexton Moor Farm, Thornton-le-Dale, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020675 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 520m north west of St Hilda's Church, Ellerburn, Thornton-le-Dale, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020693 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 650m north west of St Hilda's Church, Ellerburn, Thornton-le-Dale, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020694 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Warrening enclosure 975m north east of High Paper Mill Farm, Thornton-le-Dale, Ryedale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020680 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Late prehistoric enclosed settlement and field system on Borrowby Moor, 360m south of Moor House Farm, Borrowby, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016957 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow in Wykeham Forest, 440m east of Jenny Thrush Spring, Brompton, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019356 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow known as Hunter Howe, Cloughton, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019770 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Maw Rigg, 1.6km south west of High Langdale End, Darncombe-cum-Langdale End, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019970 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 520m north west of Keepers Cottage, East Ayton, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008482 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow in Raincliffe Woods, 420m north of Osborne Lodge, East Ayton, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021235 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow in Newton Mulgrave Woods, 740m south of Newton Brow, Ellerby, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016571 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Forestry | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | High Bride Stones, Eskdaleside cum Ugglebarnby, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004892 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Fyling medieval deer park wall section, Fylingdales, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015542 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 510m north east of Cook House, Fylingdales, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019698 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Site of Stoupe Brow alum works, 210m south east of Stoupe Bank Farm, Fylingdales, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018145 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Coastal erosion | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Allan Tofts cairnfield, field system, burial cairns and prehistoric rock art, immediately south of Morton Close, Goathland, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021301 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow in Springwood Heights Plantation, 220m north west of Springwood Cottage, Hackness, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019620 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Reasty Hill Top, 550m WSW of Breckenhurst, Hackness, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019561 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | Yes |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 150m south of Thirley Beck Farm, Harwood Dale, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019774 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow in Harwood Dale Forest known as Penny Howe, Harwood Dale, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019678 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round cairn on Cowgate Rigg, 790m south west of Teydale Farm, Harwood Dale, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020226 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round cairn on Cowgate Rigg, 870m north of Brooklands Farm, Harwood Dale, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019769 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Moated site at Low Laithes Farm, Whitby Laithes, Hawsker-cum-Stainsacre, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020402 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Stock erosion - localised/limited | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Saltwick Nab alum quarries, Hawsker-cum-Stainsacre, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017779 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Coastal erosion | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow and 20th century Royal Observer Corps post on Beacon Hill, known as the site of Hinderwell Beacon, Hinderwell, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016956 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow in School Belt, 1050m north west of Jenny Spring, Hutton Buscel, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017167 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | The Moor Dikes and Cradlegrip Dike prehistoric linear boundaries and other prehistoric remains in Wykeham Forest, Hutton Buscel / West Ayton, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017164 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Linear earthwork to the north west of the junction of the A171 and the road leading to Fylingthorpe, LCPs of Fylingdales and Hawsker-cum-Stainsacre, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011961 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 580m north east of Howdale Farm, LCPs of Fylingdales and Hawsker-cum-Stainsacre, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019705 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | The Latter Gate Hills tumuli; the northern of the two, 200m ESE from the junction of the A171 and the road leading to Fylingthorpe, LCPs of Fylingdales and Hawsker-cum-Stainsacre, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011973 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Medieval dyke known as Green Dike, LCPs of Fylingdales and Hawsker-cum-Stainsacre / Stainton Dale, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020116 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Alum works at Kettleless, Lythe, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018144 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Coastal erosion | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Brockrigg, 400m east of Brockrigg Farm, Lythe, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016539 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Cow Hill, 410m south west of Scratch Alley, Lythe, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016538 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 330m south west of Newton Brow, Newton Mulgrave, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016961 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 920m south west of Silpho Brow Farm, Silpho, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019626 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Prehistoric linear boundary and associated features including a medieval monastic grange, north, east and south east of Moorsome Farm, Snainton / Brompton, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020836 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 370m south east of Rudda Cottages, Stainton Dale, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020106 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Square barrow in Broxa Forest, 285m west of Swarth Howe, Suffield-cum-Everley, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019888 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Bracken | NEW ENTRY?: | Yes |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Square barrow in Broxa Forest, 580m south east of Whisperdales, Suffield-cum-Everley, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019560 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | Yes |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Square barrow in Broxa Forest, 720m south west of Surgate Brow Farm, Suffield-cum-Everley, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019562 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | Yes |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | The Thieves' Dikes: prehistoric linear boundaries and associated features, Suffield-cum-Everley / Silpho, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019627 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Ugthorpe Moor known as Loose Howe, 130m south west of Day Well House, Ugthorpe, Scarborough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016543 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

RICHMONDSHIRE



© English Heritage Archive

SITE NAME: **The Old Gatehouse (occupied part), Jervaulx Park, East Witton**

DESIGNATION: Listed Building grade I, SM

CONDITION: Very bad

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1318555

The house, known as the Old Gatehouse, was probably constructed from re-used medieval masonry in the C19, on medieval foundations. Part of the building is occupied and being repaired but the western end is ruinous and in need of repair. This entry relates to the occupied part of the Gatehouse.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

SITE NAME: **The Old Gatehouse (unoccupied part), Jervaulx Park, East Witton**

DESIGNATION: Scheduled Monument and Listed Buildings - I grade I; I grade II, LB grade I

CONDITION: Very bad

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1020493 and 1130961; 1130962

The house, known as the Old Gatehouse, was probably constructed from re-used medieval masonry in the C19, on medieval foundations. Part of the building is occupied and being repaired but the western end is ruinous and in need of repair. This entry relates to the non-occupied ruins of the Gatehouse.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME: **Keld Heads lead smelting mill and mine complex, Preston-under-Scar, Preston-under-Scar / Wensley**

DESIGNATION: Scheduled Monument and Listed Buildings - 2 grade II

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: D (D)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1014763 and 1179229; 1130869

The mine complex displays a wide range of features associated with lead exploitation and processing. The site has been mined since the C12 but the present complex dates from C18 and C19. Scrub clearance was undertaken by North Yorkshire County Council volunteers in 2005 to assist with the preparation of survey documents. Options appraisal complete.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

SITE NAME: **Ravensworth Castle and park wall, The Green, Ravensworth**

DESIGNATION: Scheduled Monument and Listed Building grade I, part in LB grade II

CONDITION: Poor

OCCUPANCY: N/A

PRIORITY CATEGORY: A (A)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1013087 and 1166522

Late C14, small roofless keep/gate tower and ruins of ancillary buildings together with impressive water defences later adapted to form water gardens. Much repointing and consolidation needed to all parts of the building. Significant parts of the standing remains, including the gate tower, are now at risk. A detailed record of the standing fabric has been completed.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



| | |
|--------------------|---------------------------------|
| SITE NAME: | Old Grandstand, Richmond |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1131277 |

A rare example of an C18 racecourse grandstand. The racecourse was closed in the late C19 and the Grandstand became derelict. It was partially demolished c1960. Ruins cleared and stonework sorted c1995. A conservation plan for the building has been completed with the support of English Heritage. The Racecourse is now a conservation area.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | St Martins Priory Ruins, A6136, St. Martin's |
| DESIGNATION: | Scheduled Monument and Listed Building grade I |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1012995 and 1131548 |

The ruins of a small medieval monastic house, of C12 (possibly earlier) and C15. Part of a church, small gate tower and the ruined walls of other buildings also remain. Extensive consolidation and repointing work is required.

Contact: Tammy Whitaker 01904 601880

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Section of Scots Dyke linear boundary 600m south east of Park House, Aldbrough | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013305 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Section of Scots Dyke linear boundary 150m ENE of Olliver, Aske | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013780 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | St Giles medieval hospital, post-medieval farmstead and Iron Age occupation site immediately north of St Giles Farm, Brough with St. Giles | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021210 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Natural erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Cataractonium Roman forts and town, Brough with St. Giles / Catterick / Brompton-on-Swale | | |
| DESIGNATION: | Scheduled Monument, LB grade II | LIST ENTRY NUMBER: | 1021181 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Medieval settlement of Dalton upon Tees and associated field system, Dalton-on-Tees | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019724 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Permitted development | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two moated sites, the site of a dovecote and further associated features 120m north west and 180m north of The Old Hall, East Layton / Forcett and Carkin | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021039 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Medieval village of Hunton and field system, Hunton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018380 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Permitted development | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of Scots Dike linear boundary north west of High Merrybent, Melsonby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014799 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of Scots Dyke linear boundary east of Langdale Rush, Melsonby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014240 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | William's Hill, Middleham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004907 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Stock erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of Scots Dyke linear boundary and portion of field system 100m east of Whitefields Farm, Richmond / Easby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013777 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Improving |
| PRINCIPAL VULNERABILITY: | Permitted development | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Section of the Scots Dyke linear boundary 225m south of St Martin's Priory, St. Martin's | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018143 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Dumping | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Stanwick Late Iron Age oppidum, Iron Age and medieval settlement, early Christian church and sculpture and post-medieval emparkment, Stanwick St. John / Aldbrough / Forcett and Carkin / Melsonby | | |
| DESIGNATION: | Scheduled Monument, 5 LBs, part in RPG grade II | LIST ENTRY NUMBER: | 1016199 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

RYEDALE



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Lime Kilns, A170, Allerston |
| DESIGNATION: | Scheduled Monument and Listed Building grade II |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1021084 and 1206153 |

Bank of four lime kilns circa 1800. For Sir George Osbaldeston. Situated in woodland. These are in a poor state of repair. Some parts are starting to collapse. Section 17 Management Agreement works to remove damaging trees completed.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Yedingham Priory, Ebberston and Yedingham |
| DESIGNATION: | Scheduled Monument and Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1003684 and 1149556 |

Former priory, C12-C13. Little standing structure survives except for part of the precinct wall and part of the refectory, which has been incorporated into a cottage and barn. The masonry is cracking and bulging in places.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Wall of cascade approximately 100 metres north of Ebberston Hall, A170, Ebberston and Yedingham |
| DESIGNATION: | Listed Building grade II*, RPG grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1315781 |

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale approximately 50 metres to the north of the Hall by Colen Campbell. Forms the lowest cascade of the two in the water garden.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Wall of cascade approximately 50 metres north of Ebberston Hall, A170, Ebberston and Yedingham |
| DESIGNATION: | Listed Building grade II*, RPG grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1206196 |

Stepped cascade within a water garden of circa 1718, situated in the narrow valley of Kirk Dale circa 50 metres to the north of the Hall by Colen Campbell. Forms the upper cascade of the two in the water garden. In need of consolidation and restoration.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | The Stray, Castle Howard, Henderskelfe |
| DESIGNATION: | Listed Building grade I, RPG grade I |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1316058 |

Castellated walls, four metres high, with square and round interval towers stretching for one mile to either side of the main drive, immediately south of the pyramid gate. Built to the designs of Sir John Vanbrugh c1723 as a landscape feature. Eastern half repaired with the support of Natural England, but repairs are still required to the western half. Grant has been offered for project development.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|---|
| SITE NAME: | The Mausoleum and bastion wall with gates and railings, Kirk Hill, Castle Howard Estate, Henderskelfe |
| DESIGNATION: | Listed Building grade I, RPG grade I |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1149010 |

Mausoleum by Hawksmoor, 1729-42, modelled on the tomb of Metella. Situated on a bluff circa 1.2 kilometres east of the mansion and visible from the Temple Terrace and the Temple of the Four Winds (1724-28 by Vanbrugh), both south east of the mansion. The columns were repaired with a grant in the 1980s. The entablature and bastions continue to decay. Much of the damage is due to rusting cramps. The staircase balustrade is collapsing.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | The Pyramid, St Annes Hill, Castle Howard Estate, Henderskelfe |
| DESIGNATION: | Listed Building grade I, RPG grade I |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | F (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1148971 |

Commemorative monument of 1728 by Hawksmoor, situated on a knoll and dominating views to the south from the Broad Walk and South Parterre. Decaying stone pyramid suffering from cramp damage. Five of the eight piers at the corners have been repaired with the support of a grant and grant has recently been offered for the repair of the remaining piers and the Pyramid. Set in late C17/early C18 park, one of the most historically significant landscapes in the country.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Walls to walled garden with gates and corner piers, Castle Howard Estate, Henderskelfe |
| DESIGNATION: | Listed Building grade I, RPG grade I |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | D (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1296425 |

Walls to the walled garden, early C18 by Sir John Vanburgh. The brick walls are in fair condition but the limestone piers are decaying, largely due to corrosion of iron cramps. They are in need of extensive repair.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|---|
| SITE NAME: | Screen wall, north west of Malton Lodge, Old Maltongate, Malton |
| DESIGNATION: | Listed Building grade II*, SM, CA |
| CONDITION: | Very bad |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1219922 |

Courtyard wall circa 1604 of 'An extraordinary relic of a great Prodigy house of considerable national importance' (list description). Very heavily decayed and potentially unstable.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Sheriff Hutton Castle, Main Street, Sheriff Hutton |
| DESIGNATION: | Scheduled Monument and Listed Building grade II*, part in CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Other not for profit group |
| LIST ENTRY NUMBER: | 1019593 and 1149592 |

Ruinous castle begun in 1382 by John, Lord Neville, with C15 gatehouse inserted. Vulnerable to weathering. A condition survey was funded by English Heritage and Phase I repairs, also funded by English Heritage are complete. Emergency works to south west tower are complete. The castle is in a relatively stable condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Slingsby Castle, Slingsby |
| DESIGNATION: | Scheduled Monument and Listed Building grade II, part in LB grade II, part in CA |
| CONDITION: | Very bad |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1004178 and 1149761 |

C16 Great House built on the site of a medieval castle. Ruinous but surviving up to the eaves in height. In need of urgent consolidation; site is deteriorating as a result of natural erosion and some vandalism.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Nicholas, Main Street, Ganton |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1149689 |

C14 church incorporating C13 chancel and transept arches. C15 tower and south porch. Chancel partly rebuilt during restoration of 1843. The roofs are in good order, but there is severe decay of some of the stonework, potentially leading to loss of historic fabric. Grant offered in December 2011 under Repair Grants for Places of Worship and work is underway.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Acklam Wold barrow group: a bowl barrow 300m north west of Acklam Wold House, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011541 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Acklam Wold barrow group: a bowl barrow 300m south east of Acklam Wold House, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011570 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Acklam Wold barrow group: a bowl barrow 300m south west of Acklam Wold House, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009928 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Acklam Wold barrow group: a bowl barrow 450m south of Acklam Wold House, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011574 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Acklam Wold barrow group: a bowl barrow 450m south west of Acklam Wold House, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011573 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Acklam Wold barrow group: a bowl barrow on Wooing Nab, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011539 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Acklam Wold barrow group: a pair of bell barrows and a bowl barrow 200m south west of Acklam Wold House, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011547 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Acklam Wold barrow group: two bowl barrows on Wooing Nab, Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011537 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Acklam Wold barrow group: a bowl barrow 220m north west of Acklam Wold House, Acklam / Leavening | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011543 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 250m NNE of Easthorpe Cottages, Amotherby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014566 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 310m NNE of Easthorpe Lodge, Amotherby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014565 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 330m north of Easthorpe Lodge, Amotherby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014567 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 360m north of Easthorpe Lodge, Amotherby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014568 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 380m NNW of Easthorpe Lodge, Amotherby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014569 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Iron Age settlement, Barton-le-Street | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003666 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Pockley Gates round barrow 600m west of Beadlam Grange, Beadlam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019341 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, 250m north west of Vessey Pasture Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007571 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, 250m south east of Vessey Pasture Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007569 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, 300m north east of Vessey Pasture Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007570 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, 425m east of Aldro Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007512 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, 475m north west of Vessey Pasture Farm, incorporating part of a linear boundary, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007575 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, 580m east of Aldro Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007514 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, 750m east of Aldro Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007468 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, between Birdsall Dale and Vessey Pasture Dale, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007443 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, between Birdsall Dale and Vessey Pasture Dale, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007442 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | A bowl barrow on Birdsall Wold, between Birdsall Dale and Vessey Pasture Dale, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007439 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Three bowl barrows on Birdsall Wold, 400m north west of Vessey Pasture Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007574 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Two bowl barrows on Birdsall Wold, 850m east of Aldro Farm, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007403 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Two bowl barrows on Birdsall Wold, between Birdsall Dale and Vessey Pasture Dale, Birdsall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007441 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Aldro earthworks: a linear boundary, two cross-dykes and nine round barrows on Birdsall Wold, Birdsall / Leavening / Thixendale / Acklam | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007500 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Hedon Howe tumulus, Burythorpe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005487 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Roman site south west of Kennythorpe, Burythorpe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004070 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bossall Hall: a quadrangular castle, Buttercrambe with Bossall | | |
| DESIGNATION: | Scheduled Monument, LB grade II | LIST ENTRY NUMBER: | 1008016 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Cawthorne medieval settlement remains 150m north east of West Cawthorne, Cropton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018951 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Stock erosion - localised/limited | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 350m north west of Hen Flatts, Cropton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018408 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 550m north of High Nova Farm, Cropton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015440 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Long barrow 630m north west of Scamridge Farm, Ebberston and Yedingham / Allerston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020832 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Foston medieval settlement and moated monastic grange, Foston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019388 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Stock erosion - localised/limited | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Boythorpe settlement site, Foxholes | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004059 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Romano-British settlement, Foxholes | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004046 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Settlement site at Butterwick, Foxholes | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004047 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 250m ENE of High Baxtonhowe, Fryton / Hovingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013682 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 450m south west of Coney Hill Farm, Gilling East | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014082 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 500m SSW of Coney Hill Farm, Gilling East | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014083 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 530m NNW of Maidensworth Farm, Grimstone | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013599 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Grimston Moor 350m north east of Black Gill Plantation, Grimstone | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013444 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Improving |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 300m north of Rye House Farm, Helmsley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019596 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 420m north of Rye House Farm, Helmsley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019595 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | East Heselton Brow barrow group: a bowl barrow 750m east of Manor Wold Farm, Heselton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011580 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | East Heselton Brow barrow group: a bowl barrow 1,100m east of Manor Wold Farm, Heselton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011578 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | East Heselton Brow barrow group: a bowl barrow 1,300m east of Manor Wold Farm, Heselton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011579 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Heselton Brow barrow group: a bowl barrow 230m north east of Wold Barn, Heselton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011585 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | New Bield round barrow and ringwork, Heselton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004105 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 100m north west of Moor House Farm, Hovingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014709 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 250m west of Calf Close Wood, Hovingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013552 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Forestry | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 350m south west of Moor House Farm, Hovingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013545 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 400m ESE of Theaker Waster's Spring, Hovingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013553 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Forestry | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 500m NNW of Moor House Farm, Hovingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013547 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Forestry | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow 700m north of Moor House Farm, Hovingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013546 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Forestry | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Medieval moated site 150m south east of Low Hutton Post Office, Huttons Ambo | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1014384 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Improving |
| PRINCIPAL VULNERABILITY: | Stock erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Two round barrows 1/2 mile (800m) north east of Duggleby High Barn, Kirby Grindalythe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004165 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Moated site known as Vivers Hill Castle, 300m north east of the parish church, Kirkbymoorside | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015811 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Stock erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Starfits round barrow, 450m north east of Starfits House, Kirkbymoorside | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015810 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman villa, Langton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004884 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Esh's round barrow: a long barrow and later bowl barrow 400m north of Cross Thorns Barn, Luttons | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011576 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Long barrow 650m south east of Cross Thorns Barn, Luttons | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011575 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 1/4 mile (400m) north west of Broom House, Luttons | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004114 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Three bowl barrows 200m west of Belle Vue Farm, Luttons | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011514 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Middleton Heights round barrow, Middleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003258 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Black Howe round barrow, Newton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019777 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Beacon Hill ringwork siege castle and Royal Observer Corps post, Pickering | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1019091 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 140m west of Haugh Rigg, Pickering | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020230 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 280m south west of Haugh Rigg, Pickering | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019781 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 400m north east of Haugh Rigg, Pickering | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019778 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 570m south of Saintoft Grange, Pickering | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020115 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 600m SSW of Saintoft Grange, Pickering | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020114 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Iron Age barrow cemetery, East Field, Rillington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004072 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Moated site and ridge and furrow cultivation 230m south east of Manor Farm, Scackleton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015491 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Stock erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Knapton Brow, Scampston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004109 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Part of Leppington medieval village, a moated site and site of the former parish church of St Helen, Scrayingham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011515 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 1/2 mile (800m) NNE of Settrington House, Settrington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004159 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 1/4 mile (400m) south west of Many Thorns Farm, Settrington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004160 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow north east of Lawson's Wold Barn, Sherburn | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003140 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Three round barrows south of Prodham's Wold Farm, Sherburn | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004089 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Aldro earthworks: a bowl barrow and part of a cross-dyke on Birdsall Wold, 500m north west of Brown Moor Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007483 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Aldro earthworks: a bowl barrow on Birdsall Wold, 500m north west of Brown Moor Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007484 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Aldro earthworks: a bowl barrow on Hanging Grimston Wold 400m north west of Stone Sleights Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007496 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Aldro earthworks: a cross-dyke on Birdsall Wold, 200m west of Brown Moor Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007485 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Barrow near Middle Plantation, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004171 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Barrow west of Bradeham Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004170 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Hanging Grimston barrow group: a bowl barrow 300m east of Stone Sleights Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007906 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Hanging Grimston barrow group: a bowl barrow 450m north east of Wold Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007982 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Hanging Grimston barrow group: a bowl barrow 650m south west of Thixendale Grange, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008481 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hanging Grimston barrow group: a long barrow 400m east of Wold Farm, incorporating part of a prehistoric linear boundary, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007922 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hanging Grimston barrow group: four bowl barrows and part of a cross dyke 600m SSW of Thixendale Grange, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008484 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hanging Grimston barrow group: four bowl barrows on Uncleby Stoop, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008474 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hanging Grimston barrow group: three bowl barrows 350m north east of Wold Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007977 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hanging Grimston barrow group: three bowl barrows 600m south west of Thixendale Grange, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008483 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow north of manor house, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004128 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow south east of Gill's Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004537 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrows south of Gill's Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004149 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrows south west of Riggs Farm, Thixendale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004554 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow east of Weaverthorpe Ling, Weaverthorpe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004098 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow north west of Mount Spaniel, Weaverthorpe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003141 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of linear earthwork in Pasture Plantation, Weaverthorpe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007864 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows south east of Pasture Farm, Weaverthorpe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004166 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrows on Wharram Percy Wold, Wharram | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004127 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 700m north west of High Fordon Farm, Willerby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007746 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Bowl barrow 800m west of High Fordon Farm, Willerby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007744 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 1100m west of High Fordon Farm, Willerby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1007745 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Prior Moor round barrow, Willerby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004106 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow south east of Willerby Wold House, Willerby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004112 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow west of Willerby Wold House, Willerby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004107 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows, Staxton Brow, Willerby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004090 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Wilton Hall moated site 250m south of Manor Farm, Wilton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1021269 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 1/4 mile (400m) south east of Newton South Wold Farm, Wintringham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003136 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow 330yds (300m) NNW of Ladyhills, Wintringham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003135 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow north east of Wintringham South Wold Farm, Wintringham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004163 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Round barrow west of Newlands Lane, Wintringham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004538 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Three round barrows on West Heselton Wold, Wintringham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004110 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Eberston Hall, Eberston and Yedingham | Gardens with water features c1718 integral to the design of Eberston Hall and views of the wider landscape from it. Stepped cascade water features (listed grade II*) in need of consolidation and repair, trees in parkland to south over-mature. |
| DESIGNATION: | Registered Park and Garden grade II*, 5 LBs, 2 SMs | |
| CONDITION: | Generally satisfactory but with significant localised problems | |
| VULNERABILITY: | Low | |
| TREND: | Declining | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1001062 | |



© English Heritage

| | | |
|--------------------|--|---|
| SITE NAME: | Castle Howard, Henderskelfe / Huttons Ambo / Slingsby / Welburn / Bulmer / Coneysthorpe | Gardens, pleasure grounds and park with a mixture of geometric and less formal features developed c1698-1738 by Charles Howard, third Earl of Carlisle and Sir John Vanbrugh (1664-1726) possibly with some advice from Stephen Switzer (1682-1745). Key buildings and structures in the landscape are in need of consolidation and repair; sections of the grand approach avenues have over-mature trees in need of replacement. |
| DESIGNATION: | Registered Park and Garden grade I, 65 LBs, 2 SMs | |
| CONDITION: | Generally satisfactory but with significant localised problems | |
| VULNERABILITY: | Low | |
| TREND: | Declining | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1001059 | |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

SCARBOROUGH



| | |
|--------------------|--|
| SITE NAME: | Church of St Martin, Main Street, Seamer |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (F) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1316472 |

Substantial C12 church with later medieval alterations. Nave roof recovered and nave south wall repairs almost completed with grant offered in December 2009 under Repair Grants for Places of Worship. Further stonework repairs are required, particularly to the chancel.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|--|
| SITE NAME: | Church of St John the Evangelist, Baxtergate, Whitby |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (F) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1244949 |

Early Victorian church with three parallel roofs. Main roofs re-slatted with grant offered in March 2010 under Repair Grants for Places of Worship. Further grant offered in March 2013 for urgent repairs to lower roofs and stonework under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

© English Heritage

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Round barrow 460m south of Oliver's Mount Farm | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1021233 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Three barrows at Seamer Beacon and the ruins of Baron Albert's Tower | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1008486 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: No |
| OWNER TYPE: | Local authority | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Bowl barrow 700m north of Betton Farm, East Ayton | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1008128 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Bowl barrow 920m north of Betton Farm, East Ayton | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1008129 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Bowl barrow 950m north of Betton Farm, East Ayton | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1008130 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Roman signal station, Carr Naze, Filey | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004187 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Coastal erosion | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Elf Howe round barrow, Folkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004091 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Flixton Wold, Folkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004113 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Flotmanby Brow, Folkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004096 |
| CONDITION: | Unknown | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Flotmanby Wold, Folkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004095 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow south of Long Plantation, Folkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004539 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Sharpe Howes, round barrows, Folkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004182 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two round barrows north west of Danebury Manor, Folkton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004092 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow south of Grange Farm, Hunmanby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004093 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Group of circular and rectangular enclosures, near Cansdale Whin, Hunmanby / Wold Newton / Burton Fleming | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004065 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow 60m west of Beacon Farm, Irton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008476 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 150m north of Moor House Farm, Seamer | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008133 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 450m north west of Moor House Farm, Seamer | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008519 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 550m NNW of Moor House Farm, Seamer | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008136 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bowl barrow 800m north west of Moor House Farm, Seamer | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008137 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Section of linear earthwork on Seamer Moor Hill, Seamer | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008135 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Star Carr Early Mesolithic settlement site, 960m NNW of Woodhouse Farm, Seamer | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1401425 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Valley Gardens and South Cliff Gardens | Public gardens, comprising a series of seaside walks and gardens with features from the mid C19 to the 1930s including contributions from George Knowles, William Skipsey, Sir Joseph Paxton, HW Smith and Alfred Shuttleworth. Deterioration of the wider park combined with cliff erosion is resulting in the loss of sections of the path systems and park integrity. |
| DESIGNATION: | Registered Park and Garden grade II, 5 LBs | |
| CONDITION: | Generally satisfactory but with significant localised problems | |
| VULNERABILITY: | Medium | |
| TREND: | Declining | |
| NEW ENTRY?: | Yes | |
| OWNER TYPE: | Local authority | |
| LIST ENTRY NUMBER: | 1001528 | Contact: Tammy Whitaker 01904 601880 |

| | | | |
|----------------|--|-------------|--------------------------------|
| SITE NAME: | Dean Road / Manor Road Cemetery | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving significantly |
| VULNERABILITY: | Medium | CONTACT: | Derek Green (LPA) 01723 232468 |

SELBY



© English Heritage

| | | |
|--------------------|---|--|
| SITE NAME: | Chapel to Huddleston Hall (now barn), west of house, Laith Staid Lane, Huddleston with Newthorpe | Former chapel with C15 origins, C16 rebuilding to the east and later alterations. The building is disused and the roof coverings are in poor repair, resulting in water ingress to the interior. |
| DESIGNATION: | Listed Building grade II* | |
| CONDITION: | Poor | |
| OCCUPANCY: | Vacant/not in use | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1167970 | |



© English Heritage

| | | |
|--------------------|---|--|
| SITE NAME: | Huddleston Hall, Laith Staid Lane, Huddleston with Newthorpe | Late C16 manor house, now used as a farmhouse. The roofs are in poor condition resulting in water ingress to the interior, and there is some decaying stonework. A full repairs programme planned but work has not yet been carried out. |
| DESIGNATION: | Listed Building grade II* | |
| CONDITION: | Poor | |
| OCCUPANCY: | Part occupied/part in use | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1167923 | |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | | |
|--------------------|---|---|
| SITE NAME: | Stables to Huddleston Hall, south east of house, Laith Staid Lane, Huddleston with Newthorpe | Stables of the late C16 with C19 additions and alterations. The roof coverings have some missing tiles. |
| DESIGNATION: | Listed Building grade II* | |
| CONDITION: | Fair | |
| OCCUPANCY: | Part occupied/part in use | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1167953 | Contact: Tammy Whitaker 01904 601880 |



© Selby District Council

| | | |
|--------------------|---|---|
| SITE NAME: | Abbot's Staith Buildings, Water Lane, Selby | C15 or early C16, two storey, 'H' shaped plan warehouse built for Selby Abbey. Mainly of magnesium limestone ashlar with some brick. The roof is modern, the building is in poor condition and the roof is deteriorating. |
| DESIGNATION: | Scheduled Monument and Listed Building grade II*, 2 LBs | |
| CONDITION: | Poor | |
| OCCUPANCY: | Part occupied/part in use | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1004181 and 1167663 | Contact: Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|---|---|
| SITE NAME: | Church of All Saints, Church Hill, Sherburn in Elmet | Medieval parish church, C12-C16 with east end restored by Anthony Salvin in 1857. Magnesian limestone masonry is very badly eroded to clerestories, east and west windows and spiral stair to the belfry. Localised defects to glazing, rainwater goods and south aisle roof. |
| DESIGNATION: | Listed Place of Worship grade I | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | C (New entry) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | 1148444 | Contact: Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Church of St Martin, Park Lane, Womersley | Medieval church predominantly of the C13 and C14, notable for a decorative scheme added by Bodley in the C19. Roofs and rainwater goods in poor condition. Some stonework, most notably at the east and west ends, is very eroded. Grant offered in December 2012 under Repair Grants for Places of Worship. |
| DESIGNATION: | Listed Place of Worship grade I | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | D (New entry) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | 1174486 | Contact: Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | St Andrew's College and moat, 440m north east of College Farm, Acaster Selby | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017457 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Animal burrowing - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Brocket Hall moated site, Appleton Roebuck | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008228 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Mote Hill: a moated site, two fishponds and part of an adjacent field system 500m west of Nun Appleton Hall, Appleton Roebuck | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008229 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Parkshaw moated site, 170m north west of Wood Farm, Balne | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016025 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Catterton Hall moated site and adjacent building platform, Catterton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017456 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Castle Hill moated site, 350m south of St Peter and St Paul's Church, Drax | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017455 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Kelfield moated site and fishpond, 180m north of Kelfield Church, Kelfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017459 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Scurff Hall moated site, Newland | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017485 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Toulston medieval village, manor house site and early garden earthworks, Newton Kyme cum Toulston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017922 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Permitted development | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Two Roman forts, two Roman camps, vicus, Iron Age enclosure, Bronze Age barrows and Neolithic henge monument west of Newton Kyme, Newton Kyme cum Toulston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017693 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | York prebendary manor moated site, 300m north west of Hawthorn Farm, Riccall | | |
| DESIGNATION: | Scheduled Monument, 2 LBs | LIST ENTRY NUMBER: | 1018212 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Paradise Lodge moated site and grange of the Prior of Bolton, Ryther cum Ossendyke | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008225 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Thorpe Hall moated monastic grange, Selby | | |
| DESIGNATION: | Scheduled Monument, LB grade II | LIST ENTRY NUMBER: | 1017460 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Unknown |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Danes Hills square barrow cemetery on Crook Moor, Skipwith | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016619 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moated site and fishpond 140m south of St Helen's Church, Skipwith | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015543 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Improving |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Round barrow on Skipwith Common, 800m south east of Adamson Farm, Skipwith | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018604 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Skipwith Common, 810m south of Skipwith Church, Skipwith | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018601 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round barrow on Skipwith Common, 830m south east of Adamson Farm, Skipwith | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018605 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Danes Hills square barrow cemetery, 300m south of Adamson Farm, Skipwith / Riccall | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018603 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Steeton Hall medieval magnate's residence and manorial centre, South Milford | | |
| DESIGNATION: | Scheduled Monument, 3 LBs | LIST ENTRY NUMBER: | 1015504 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Permitted development | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Steeton medieval village, moated site and fishponds, Steeton | | |
| DESIGNATION: | Scheduled Monument, 2 LBs | LIST ENTRY NUMBER: | 1017555 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Whitley Thorpe moated Templar grange site, 600m north west of Fulham House, Whitley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017458 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

YORKSHIRE DALES (NP)



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Henry Simpson's Barn, Appletreewick, Craven |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Charity (non-heritage) |
| LIST ENTRY NUMBER: | 1249282 |

Barn built in 1737 for Lord Burlington. Of a high level of embellishment and craftsmanship, unusual for the date. The roof was partly stripped in 1995 and the roof timbers are consequently in poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Barden Church, B6160, Barden, Craven |
| DESIGNATION: | Listed Building grade I, SM |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1131761 |

C16 former chapel. The interior is derelict and there is some water penetration and damage, despite past repairs to the roof. An options appraisal has been undertaken with the Estate and Yorkshire Dales National Park Authority and grant has been offered for project development.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Lodge Hall, Ingman Lodge Road, Selside, Horton in Ribblesdale, Craven |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Occupied/in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1289489 |

Farmhouse dated 1687. Structural cracks to main (east) front and bulge on north side. Roof reported to leak badly with attendant decay. Integral part of a working farm.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|---|
| SITE NAME: | Nappa Hall, Askrigg, Richmondshire |
| DESIGNATION: | Listed Building grade I |
| CONDITION: | Poor |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | F (F) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1157398 |

A fortified Manor House built in 1459 for James Metcalf. A wing was added in C17. Most of the medieval portion has not been occupied for some years. There has recently been a change in ownership and some repairs have been carried out. However, the floors in the west tower are still in a rotten and dangerous state and the roof coverings over the great hall and the south east wing are in very poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Margaret, Gruel Street, Hawes, Richmondshire |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1166758 |

1851 church with fine later furnishings. Roofs in poor condition, extensive repointing required, glazing poor. Two phases of grant offered in March 2012 and March 2013 under Repair Grants for Places of Worship. First phase of repair and works underway; second phase in project development.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Kinsey Cave, Giggleswick Scar, Giggleswick, Craven | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1010295 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Multi-period lead mines and processing works and 20th century barytes mill on Grassington Moor, Grassington / Hebden, Craven | | |
| DESIGNATION: | Scheduled Monument and Listed Building grade II | LIST ENTRY NUMBER: | 1018333 and 1166878 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Stable |
| PRINCIPAL VULNERABILITY: | Dumping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Meal Bank Quarry Hoffmann kiln, quarry and lime works, Ingleton, Craven | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020889 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Large univallate hillfort on Ingleborough Hill, Ingleton / Clapham cum Newby, Craven | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1008876 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Bolton Parks Lead Mine and ore works, Castle Bolton with East and West Bolton, Richmondshire | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018712 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Marrick ore hearth lead smelting, Marrick, Richmondshire | | |
| DESIGNATION: | Scheduled Monument, 2 LBs | LIST ENTRY NUMBER: | 1015824 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Improving |
| PRINCIPAL VULNERABILITY: | Dumping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Gunnarside Gill lead mines and ore works, Melbecks, Richmondshire | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015830 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Beldi Hill Low Level lead mine and ore works, Muker, Richmondshire | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1015408 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | West Stonesdale lead mine and ore works, Muker, Richmondshire | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1015407 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|----------------|--|-------------|---------------------------------|
| SITE NAME: | Swaledale and Arkengarthdale barns and walls, Muker / Reeth, Fremington and Healaugh / Arkengarthdale / Grinton / Marrick / Melbecks, Richmondshire | | |
| DESIGNATION: | Conservation Area, 135 LBs, 9 SMs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Robert White (LPA) 01969 652360 |

SOUTH YORKSHIRE

BARNSELY



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Grimethorpe Hall, Brierley Road, Brierley |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Commercial company |

LIST ENTRY NUMBER: 1151202

House, circa 1670, altered in C18, C19 and C20, which requires extensive repairs. Although standing in an amply sized site, the surrounding area is residential. The setting has been eroded by construction of housing to the west. Consent was granted for conversion to a restaurant in 2005, but the scheme failed.

Contact: Tammy Whitaker 01904 601880



© Stephen Elliott, Purcell Miller Tritton

| | |
|--------------------|---|
| SITE NAME: | Gun Room, Wentworth Castle, Stainborough |
| DESIGNATION: | Listed Building grade II*, RPG grade I, CA |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | E (E) |
| OWNER TYPE: | Charity (heritage) |

LIST ENTRY NUMBER: 1151066

Probably built as a banqueting house or a bath-house, it was used as a gun room in the C19. The interior has exceptionally fine plasterwork. Repairs to the walls and roof were carried out in 2006-07, but a further phase of conservation is required to the interior which is in very poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Dovecote at Glebe Farm, Tankersley |
| DESIGNATION: | Scheduled Monument and Listed Building grade II |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Private |

LIST ENTRY NUMBER: 1016549 and 1151075

Stone built dovecote and cart shed, built in 1735 as part of the Glebe Farm for Richard Goodwin, Rector 1715-52. A particularly good example, complete with full interior and a rare set of spiked protective grilles over the dove holes. In a state of serious disrepair with a temporary roof structure in place. Potential for low key use, ancillary to residential. Project development grant underway.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--------------------------------------|
| SITE NAME: | Low Forge, Wortley / Hunshelf |
| DESIGNATION: | Scheduled Monument |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | D (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1020626 |

Roofless remains of an early C18 water-powered iron forge, including waterwheel and tilt-hammer, associated wheelraces, forge and bloomery building; in need of repair.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Peter including attached wall and gateway to south west, Brinckman Street |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1314984 |

Church and attached wall and gateway, 1893-1910 by Temple Moore. In generally good order; nave appears to have been re-slatted. Slates to chancel roof appear to be in poor condition and there is salting brickwork to the Lady Chapel.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Bull House Chapel, Manchester Road, Penistone |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1314708 |

Non-conformist chapel, previously Presbyterian and Methodist, dated to 1692. Simple, single-storey rectangular plan and constructed from coursed stone with a stone slate roof. The chapel lies in an isolated position outside the town, adjacent to the manor. The roof and ceiling are in poor condition. Grant offered in March 2012 under Repair Grants for Places of Worship and work is underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Helen, High Street, Thurnscoe |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1151168 |

Victorian church with Georgian tower, the rest rebuilt in 1887. Clay tiled roofs to nave and south east corner are in poor condition, although regularly repaired. Eroded stonework to porch.

Contact: Tammy Whitaker 01904 601880

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | East Gawber Hall colliery fanhouse, 800m north east of Croft Farm | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017748 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Elsecar Colliery Newcomen engine | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1004790 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Heavy anti-aircraft gunsite 330m south east of Lowfield Farm | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1019872 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Rockley blast furnace | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004820 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Rockley engine house | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004821 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Dumping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Wortley Top Forge, Hunshelf / Thurgoland | | |
| DESIGNATION: | Scheduled Monument, 3 LBs | LIST ENTRY NUMBER: | 1018262 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Flooding | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Romano-British settlements at Finkle Street, Wortley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004801 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Water powered bloomery, iron forge and rolling mill at Low Forge, Wortley / Hunshelf | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1020626 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|----------------|-------------------------------|-------------|--------------------------------|
| SITE NAME: | Elsecar | | |
| DESIGNATION: | Conservation Area, 19 LBs, SM | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving significantly |
| VULNERABILITY: | Low | CONTACT: | Tony Wiles (LPA) 01226 772 576 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

DONCASTER



© English Heritage

| | |
|--------------------|------------------------------------|
| SITE NAME: | Moat Hall ruins, Braithwell |
| DESIGNATION: | Scheduled Monument, LB grade II |
| CONDITION: | Very bad |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1012461 |

Ruins of medieval monastic grange and post-medieval dwelling, consisting of arched doorway and low walls, in poor repair.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Stable to Hickleton Hall including the Stable Cottage and attached walls and gate piers, Hickleton Hall, Hickleton |
| DESIGNATION: | Listed Building grade II*, RPG grade II, CA |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | F (E) |
| OWNER TYPE: | Charity (non-heritage) |
| LIST ENTRY NUMBER: | 1151659 |

Mid C18 stable block, now store and house with attached walls and gate piers. Possibly by James Paine, who designed Hickleton Hall, 1745-48, for Godfrey Wentworth. The stable block stands to the north of the Hall, which occupies an elevated position towards the north end of the registered site. Repairs have been carried out to the roofs and the building is now in fair condition, but disused.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---------------------------------------|
| SITE NAME: | Christ Church, Thorne Road |
| DESIGNATION: | Listed Place of Worship grade II*, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (C) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1286309 |

A Gothic style church dating to 1827/9. It is constructed from limestone ashlar with a slate roof and copper spire. It has a four-stage south tower. Closed in 1989, it was bought by Reachout Christian Fellowship in 1994. Ten years later and at significant cost, it opened again for worship. Grant-aided remedial roof works and repairs to falling internal ceiling plaster are underway following a grant offer in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Peter, Warmsworth Road |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1096038 |

Known as 'The White Church'. Consecrated in 1942 and mentioned in a wartime broadcast from Berlin by the notorious 'Lord Haw Haw'. Windows in poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St George, Church Lane, Doncaster |
| DESIGNATION: | Listed Place of Worship grade I, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1151447 |

Major Victorian church, replacing the medieval parish church which was destroyed by fire. Several phases of repair undertaken, but further work required to stonework, including central tower. Grant offered in December 2011 under Repair Grants for Places of Worship and works underway.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.


ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© PCC

| | | |
|--------------------|--|---|
| SITE NAME: | Church of St Lawrence, Station Road, Hatfield | Norman church. C12 origin, C13 arcades, the rest mostly C15. Tower in poor condition. |
| DESIGNATION: | Listed Place of Worship grade I, CA | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | I 192628 | |



© PCC

| | | |
|--------------------|---|---|
| SITE NAME: | Church of St Mary, Main Street, Sprotbrough and Cusworth | Medieval church, significant decay to medieval oak roofs. Grants offered in December 2011 and December 2012 for two phases of roof repair under Repair Grants for Places of Worship. First phase complete: second phase underway. |
| DESIGNATION: | Listed Place of Worship grade I, CA | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | F (D) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | I 192663 | |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Castle Hills motte and bailey castle, Langthwaite, Adwick le Street | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: I 013654 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - extensive | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Moat Hills moated site, Bentley | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: I 013655 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Site of St Helen's Chapel, Barnburgh | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: I 004799 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Manor Holt moated site, Bawtry | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: I 012453 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Moat Hall moated site and site of external ancillary buildings, Braithwell | | |
| DESIGNATION: | Scheduled Monument, LB grade II | LIST ENTRY NUMBER: | 1012461 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Improving |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman fort at Robin Hood's Well, Burghwallis | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1002930 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman potteries 300yds (270m) north east of Rossington Bridge, Cantley / Rossington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004787 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Other | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Edlington Wood Roman settlement, Edlington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004824 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Metal detecting - unlicensed | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Moat Hill moated site, Fenwick | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011920 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Castle Hill, Hampole | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004794 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Icehouse 720m south east of Bath House Farm, High Melton | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1020715 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------------|
| SITE NAME: | Earthworks on Sutton Common, Norton | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004816 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Rossington Roman fort, Rossington | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004823 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Thorpe in Balne moated site, chapel and fishpond, Thorpe in Balne | | |
| DESIGNATION: | Scheduled Monument, LB grade II* | LIST ENTRY NUMBER: | 1012111 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Drainage/dewatering | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Tickhill Castle, Tickhill | | |
| DESIGNATION: | Scheduled Monument, CA | LIST ENTRY NUMBER: | 1004828 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: | No |
| OWNER TYPE: | Other | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Hatfield High Street, Hatfield | | |
| DESIGNATION: | Conservation Area, 11 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | No significant change |
| VULNERABILITY: | Medium | CONTACT: | Malcolm Thomas (LPA) 01302 735199 |
| SITE NAME: | Marr | | |
| DESIGNATION: | Conservation Area, 6 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | High | CONTACT: | Malcolm Thomas (LPA) 01302 735199 |
| SITE NAME: | St George's, Doncaster | | |
| DESIGNATION: | Conservation Area, 2 LBs, SM | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | No significant change |
| VULNERABILITY: | Medium | CONTACT: | Malcolm Thomas (LPA) 01302 735199 |
| SITE NAME: | Thorne Central, Thorne | | |
| DESIGNATION: | Conservation Area, 15 LBs, SM | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Malcolm Thomas (LPA) 01302 735199 |
| SITE NAME: | Thorne Road, Doncaster | | |
| DESIGNATION: | Conservation Area, LB grade II | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Malcolm Thomas (LPA) 01302 735199 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|---------------------------|-------------|-----------------------------------|
| SITE NAME: | Woodlands | | |
| DESIGNATION: | Conservation Area, 26 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Malcolm Thomas (LPA) 01302 735199 |

PEAK DISTRICT (NP)

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Bailey Hill motte and bailey castle, High Bradfield, Bradfield, Sheffield | | |
| DESIGNATION: | Scheduled Monument, part in CA | LIST ENTRY NUMBER: | 1013217 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Castle Hill motte and bailey castle, High Bradfield, Bradfield, Sheffield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017612 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Animal burrowing - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Cowell Flat prehistoric field system, 350m south east of Mortimer House, Bradfield, Sheffield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017833 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

ROTHERHAM

© Rotherham Metropolitan Borough Council

| | |
|--------------------|--|
| SITE NAME: | 25 and 27, High Street, Rotherham |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1132712 |

Known as The Three Cranes. Late medieval house. Signs of structural decay, faulty rainwater goods.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Keppels Column, Admirals Crest, Thorpe Common |
| DESIGNATION: | Listed Building grade II*, RPG grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Local authority |
| LIST ENTRY NUMBER: | 1314632 |

Monumental column built 1773-80. Now on the edge of Wentworth Woodhouse Estate. The building is closed to the public, although emergency repairs have been carried out to the viewing platform and stairwell. There are significant structural cracks and stonework erosion. The internal staircase is unsafe.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Thorpe Salvin Old Hall (ruins of), Ladyfield Road, Thorpe Salvin |
| DESIGNATION: | Scheduled Monument and Listed Buildings - 2 grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1004788 and 1286372; 1314668 |

Gatehouse and imposing three storey south facade of mid C16 stone-built mansion built by Henry Sanford (died 1582) standing in an open courtyard. Grant has been offered for a condition survey.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Camellia House, Wentworth Woodhouse, Wentworth |
| DESIGNATION: | Listed Building grade II*, RPG grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1286162 |

Early C19 conservatory incorporating mid C18 section to rear, situated approx 400 metres south west of the house in the C18 and C19 gardens. Built as part of the Wentworth Estate. Set within park remodelled by Humphry Repton in the early 1790s. The condition of the Camellia House has deteriorated, in part due to vandalism and the roof and glazing are in poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Stable block and riding school, Wentworth Woodhouse, Wentworth |
| DESIGNATION: | Listed Building grade I, RPG grade II* |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | E (E) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1203779 |

Stable block and riding school, 1760s, situated approximately 300 metres north west of the house.

Contact: Tammy Whitaker 01904 601880




© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of All Saints, Church Street, Wath Upon Dearne |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1132786 |

Church with north arcades and lower part of tower dating to C12. Nave and chancel rebuilt and added to in C13 and C14 and tower heightened in C14 or C15. Roofs, high-level masonry and rainwater goods in poor condition. Grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880



© PCC

| | |
|--------------------|---|
| SITE NAME: | Church of St Leonard, Doncaster Road, Thrybergh |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1132783 |

Medieval church with fine monuments. Roofs in poor condition. Two phases of grant offered in December 2010 and December 2012 under Repair Grants for Places of Worship for repair. First phase almost complete and second phase in project development.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



| | | |
|--------------------|---|--|
| SITE NAME: | Church of St Peter and St Paul, Todwick | Medieval church with C11 nave, C14 chancel and C15 tower with C18 and C19 alterations. Tower parapets and pinnacles in poor condition. |
| DESIGNATION: | Listed Place of Worship grade II* | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | 1151903 | Contact: Tammy Whitaker 01904 601880 |

© PCC

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Kimberworth motte and bailey castle | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1013469 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Dumping | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Roman Ridge: section 110yds (100m) long, 450yds (410m) NNE of Kimberworth Park Farm | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1004835 |
| CONDITION: | Generally satisfactory but with minor localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Roman Ridge: section 300yds (270m) long north of Birchwood (east of Chemical Cottages) | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1004813 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Roman Ridge: section 400yds (370m) long from Hill Top Lane to Little Common Lane | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1004808 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - moderate | NEW ENTRY?: No |
| OWNER TYPE: | Local authority | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Roman Ridge: section 400yds (370m) long in Wath Wood | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1004811 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - moderate | NEW ENTRY?: No |
| OWNER TYPE: | Local authority | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Roman Ridge: south east of Hill Top (section 700yds (660m) long, Meadowhall Road to Hill Top) | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1004807 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Deterioration - in need of management | NEW ENTRY?: No |
| OWNER TYPE: | Local authority | CONTACT: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|----------------------------------|
| SITE NAME: | Swinton Pottery (The Rockingham Works), 310m and 120m north west of Keeper's Cottage | | |
| DESIGNATION: | Scheduled Monument, LB grade II* | LIST ENTRY NUMBER: | 1020067 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Natural erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman Ridge (Roman road): section 135yds (120m) long, east of Hooper House, Brampton Bierlow | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004830 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman Ridge: section 300yds (270m) long on Birchcliff Bank, Brampton Bierlow | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004809 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman Ridge: section 400yds (370m) long south of Abdy Farm, Brampton Bierlow | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004810 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman Ridge: section 330yds (300m) long, south of Dog Kennel Pond, Wentworth Park, Wentworth | | |
| DESIGNATION: | Scheduled Monument, RPG grade II* | LIST ENTRY NUMBER: | 1004833 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Roman Ridge: section 500yds (460m) long, north of Dog Kennel Pond, Wentworth Park, Wentworth | | |
| DESIGNATION: | Scheduled Monument, RPG grade II* | LIST ENTRY NUMBER: | 1004832 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Stock erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Doncaster Road, Rotherham Town Centre | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Jonathan Bell (LPA) 01709 823811 |
| SITE NAME: | Greasborough, Rotherham Urban | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving |
| VULNERABILITY: | Low | CONTACT: | Jonathan Bell (LPA) 01709 823811 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|------------------------------|-------------|----------------------------------|
| SITE NAME: | Rotherham Town Centre | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving |
| VULNERABILITY: | Low | CONTACT: | Jonathan Bell (LPA) 01709 823811 |

| | | | |
|----------------|-------------------------------|-------------|----------------------------------|
| SITE NAME: | Wales, Rotherham South | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jonathan Bell (LPA) 01709 823811 |

SHEFFIELD



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Entrance Gateway to Green Lane Works, Green Lane |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (New entry) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1255044 |

Imposing entrance gateway, dated 1860, incorporating a tripartite triumphal arch flanked by relief panels depicting "Art" and "Industry" and topped with a pediment and cupola with clock stage and lantern. Rear masonry range, roofs and rainwater goods are in very poor condition and water ingress has caused internal timbers to decay. Grant application submitted for funding towards investigative works and urgent repairs.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Gateway and adjoining walls at garden entrance to Oakes Park, Norton |
| DESIGNATION: | Listed Building grade II*, RPG grade II |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1271161 |

Early C18 and early C19 gateway with ornamental iron gates leading to C18 gardens. The gates are rusty and the gate piers are in poor condition. The park is also at risk.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Leah's Yard, 20-22, Cambridge Street, Sheffield |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Local authority |
| LIST ENTRY NUMBER: | 1247012 |

Mid C19 cutlery/silversmithing works, with late C19 alterations. General decay, some fire damage. Use for shops and food/drink use agreed and included in "New Retail Quarter" proposals. The scope of urgent repairs has been agreed.

Contact: Tammy Whitaker 01904 601880



| | |
|--------------------|---|
| SITE NAME: | Nonconformist Chapel, General Cemetery, Cemetery Road, Sheffield |
| DESIGNATION: | Listed Building grade II*, RPG grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Charity (heritage) |
| LIST ENTRY NUMBER: | 1247073 |

Cemetery chapel built in circa 1836. Lead has been stolen from the roof and not reinstated, risking further structural deterioration. Fundraising is in progress to restore the building and open it to the public.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© English Heritage

| | | |
|--------------------|--|---|
| SITE NAME: | Loxley United Reformed Church, Loxley Road, Bradfield | Former church, 1787. Closed in 1994. Recently suffered from further vandalism, condition deteriorating. |
| DESIGNATION: | Listed Building grade II* | |
| CONDITION: | Poor | |
| OCCUPANCY: | Vacant/not in use | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1314565 | Contact: Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Seventh Day Adventist Church adjoining school and boundary wall, Andover Street | Victorian chapel, now Seventh Day Adventist Church. Roofs and rainwater goods in poor condition. |
| DESIGNATION: | Listed Place of Worship grade II | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | C (C) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | 1246453 | Contact: Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Church of St Mary, Howard Road, Sheffield | Parish church in the Gothic Revival style dating to 1869, with vestry added in 1928. Roof coverings and rainwater goods are in poor condition and water ingress has damaged internal finishes. Some glazing is in poor condition. Grant offered in March 2013 under Repair Grants for Places of Worship. |
| DESIGNATION: | Listed Place of Worship grade II | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | D (New entry) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | 1270449 | Contact: Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Church of St Paul, Wordsworth Avenue, Sheffield | 1960s church by Basil Spence. Repairs carried out to body of church, but extensive repair needed to the concrete cloisters which extend from the front of the church. Some grant-aided repairs offered in March 2009 under Repair Grants for Places of Worship have been completed. Further phases are required. |
| DESIGNATION: | Listed Place of Worship grade II* | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | B (B) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | 1376605 | Contact: Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Roman Ridge: section 600yds (550m) long between Jenkin Lane (now Road) and Tylers Street | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004806 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Little Matlock rolling mill immediately south and east of Olive Terrace, Bradfield | | |
| DESIGNATION: | Scheduled Monument, LB grade II* | LIST ENTRY NUMBER: | 1019857 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Other | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Handlands Romano-British settlement, 460m south west of Woodseats Farm, Ecclesfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017835 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Willow Garth moated site and fishpond, Ecclesfield, Ecclesfield | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012477 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Mousehole Forge, Malin Bridge | | |
| DESIGNATION: | Scheduled Monument, LB grade II | LIST ENTRY NUMBER: | 1004804 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Iron Age and Roman quern workings on Wharncliffe Rocks, Stocksbridge | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1004802 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Government or agency | CONTACT: | Tammy Whitaker 01904 601880 |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Oakes Park, Sheffield |
| DESIGNATION: | Registered Park and Garden grade II, 9 LBs |
| CONDITION: | Extensive significant problems |
| VULNERABILITY: | High |
| TREND: | Declining |
| NEW ENTRY?: | No |
| OWNER TYPE: | Mixed, multiple owners |
| LIST ENTRY NUMBER: | 1001160 |

Gardens and pleasure grounds with early to mid C18 origins, an early C19 terrace and parkland probably of early C19 date. Park and gardens compromised by multiple use, condition of park is poor and listed structures in very poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Sheffield General Cemetery |
| DESIGNATION: | Registered Park and Garden grade II*, 9 LBs |
| CONDITION: | Generally unsatisfactory with major localised problems |
| VULNERABILITY: | High |
| TREND: | Declining |
| NEW ENTRY?: | No |
| OWNER TYPE: | Local authority, multiple owners |
| LIST ENTRY NUMBER: | 1001391 |

Cemetery of 1836 designed by Sheffield architect Samuel Worth (fl.1830) with a chapel, catacombs and a cemetery office, and a layout which makes dramatic use of a quarried hillside site. An extension of 1846 for Anglican burials, laid out by Robert Marnock (1800-89). The cemetery retains both its Anglican and Non-conformist chapels (listed grade II*) the latter a building at risk. Site managed by The Friends of Sheffield General Cemetery.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|----------------------|-------------|----------------------------------|
| SITE NAME: | Kelham Island | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving |
| VULNERABILITY: | Low | CONTACT: | John Stonard (LPA) 0114 273 4472 |

| | | | |
|----------------|-----------------------------------|-------------|----------------------------------|
| SITE NAME: | Sheffield General Cemetery | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | John Stonard (LPA) 0114 273 4472 |

| | | | |
|----------------|--------------------|-------------|----------------------------------|
| SITE NAME: | Well Meadow | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | John Stonard (LPA) 0114 273 4472 |

WEST YORKSHIRE

BRADFORD



© English Heritage Archive

SITE NAME: **Manningham Mill (ancillary buildings and boiler house), Heaton Street, Heaton, Bradford**

DESIGNATION: Listed Building grade II*, CA

CONDITION: Fair

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: C (C)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1314426

Silk mill, with boiler house, chimney and warehouse. Built in 1873. Scheme of residential and office conversion complete. Mill no longer a risk but ancillary buildings and boiler house are. Condition surveys of at risk buildings have been commissioned with English Heritage grant aid.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME: **Leventhorpe Hall, 1289 and 1291, Thornton Road, Lower Grange, Bradford**

DESIGNATION: Listed Building grade II*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: D (D)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1133692

Late C17 house with C19 additions. Windows are broken, the roof is sagging with missing slates. The east wall is failing. The site in general has substantially deteriorated but not the Hall. Residential scheme has consent for the whole site, but work has stalled.

Contact: Tammy Whitaker 01904 601880



© English Heritage

SITE NAME: **New Hall, Rooley Lane, Newhall**

DESIGNATION: Listed Building grade II*

CONDITION: Poor

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: C (New entry)

OWNER TYPE: Charity (non-heritage)

LIST ENTRY NUMBER: 1314521

A fine C17 hall, built by the Richardson Family of Bierley Hall. Of gritstone with excellent detailing. New Hall was formerly the club house of West Bowling Golf Club, which has now been redeveloped for commercial use. The Hall is empty and deteriorating.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Mill Building at Low Mills, Low Mill Lane, Keighley |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1200162 |

Late C18. Early cotton mill, adjacent to supermarket and car park. Application approved for residential use but little progress on site as yet.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Waterloo Mill, Howden Road, Silsden |
| DESIGNATION: | Listed Building grade II*, CA |
| CONDITION: | Poor |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | D (F) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1266636 |

Main four storey mill is in fair condition and in use. The Chimney was extensively repaired in 2005. The engine house, which retains its engine, is in poor repair, with cracking to the concrete roof and some water penetration.

Contact: Tammy Whitaker 01904 601880



© PCC

| | |
|--------------------|---|
| SITE NAME: | Church of All Saints, Little Horton Lane |
| DESIGNATION: | Listed Place of Worship grade II*, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1207967 |

Noble Victorian church with prominent south east tower and spire. Previous phases of repair complete, but some high-level stonework is in poor repair. Grant offered in December 2011 for repairs under Repair Grants for Places of Worship and works are underway.

Contact: Tammy Whitaker 01904 601880



© PCC

| | |
|--------------------|--|
| SITE NAME: | Church of St Paul, St Paul's Avenue |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1133732 |

Small Gothic church dating to 1838 and constructed from sandstone with ashlar dressings. Grant offered in March 2011 under Repair Grants for Places of Worship for repairs to the tower, spire and rainwater goods and repairs are underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Bradford Synagogue (Reform), Bowland Street, Bradford |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1227613 |

Synagogue of 1880-1 in the Islamic revival style by Francis and Thomas Healey. Principal elevation of gold and red banded ashlar with bracketed eaves and ornate pierced parapet. Central raised panel with Hebrew inscription beneath cresting incorporating the Star of David. Roof coverings and rainwater goods in poor condition, water ingress is causing damage to timbers, masonry and finishes.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Stephen, Donisthorpe Street, Bradford |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1133174 |

Victorian city church. The roofs are in poor condition, leading to extensive water penetration and timber decay. Two phases of grant offered in March 2012 and March 2013 under Repair Grants for Places of Worship and works are underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | St Michael and All Angels, Church Street, Haworth, Keighley |
| DESIGNATION: | Listed Place of Worship grade II*, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1283403 |

Large Victorian church with C16 tower. Roof coverings and rainwater goods to north elevation in poor condition, internal wall paintings also in poor condition. Repairs to roof coverings to south elevation almost completed with grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Paul, Kirkgate, Shipley |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1133546 |

Commissioners' Church of 1823-25 designed in the Perpendicular style by John Oates of Halifax. Roofs, rainwater goods, high-level masonry and glazing in poor condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St James, Thornton Road, Thornton |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1133695 |

Large Victorian church with Morris glass. Slate roofs in poor condition. Two phases of grant offered in March 2011 and March 2013 under Repair Grants for Places of Worship for repairs. First phase almost complete and second phase in project development.

Contact: Tammy Whitaker 01904 601880

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Cup and ring marked rock north of Pennythorn Hill, Baildon | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012684 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Cup-marked rock on slight bank north east of Glovershaw quarry, Baildon | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009724 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Enclosed settlement known as 'Soldier's Trench' including a cup-marked rock, Baildon | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1009718 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Round cairn and curving bank on Pennythorn Hill, Baildon | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012683 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Twelve Apostles stone circle, Burley Moor, Burley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1011763 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Late prehistoric enclosed settlement known as Catstones Ring on Catstones Hill, Cullingworth | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018240 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Cairn 330m north of Woodhead on Harden Moor, Harden | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018239 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Cairnfield, carved rocks and associated curved bank at north west end of Green Crag Slack, east of Gill Head Reservoir, Ilkley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013872 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Cup and Ring marked rock known as the Hanging Stone Rock, Ilkley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012008 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Enclosure with carved rocks and disturbed cairn known as Green Crag Enclosure, Ilkley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1012840 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|---|
| SITE NAME: | Whinburn, Keighley | Gardens and pleasure grounds partly laid out c1897 with additional formal landscaping and features dating from 1912 to 1938, with some design work in the latter period by TH Mawson and Son. Formerly owned by Bradford City Council, now in private ownership and lay vacant for a number of years suffering decay and vandalism. New owners in process of repairing house and grounds. |
| DESIGNATION: | Registered Park and Garden grade II, 3 LBs | |
| CONDITION: | Generally satisfactory but with minor localised problems | |
| VULNERABILITY: | Low | |
| TREND: | Unknown | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Private | |
| LIST ENTRY NUMBER: | 1001643 | Contact: Tammy Whitaker 01904 601880 |

| | | | |
|----------------|---------------------------------------|-------------|--------------------------------|
| SITE NAME: | Apsley Crescent, Manningham, Bradford | | |
| DESIGNATION: | Conservation Area, 15 LBs | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|---|-------------|--------------------------------|
| SITE NAME: | Devonshire Park and Cliffe Castle, Keighley | | |
| DESIGNATION: | Conservation Area, 10 LBs | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|---------------------------|-------------|--------------------------------|
| SITE NAME: | Great Horton | | |
| DESIGNATION: | Conservation Area, 42 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|--------------------------|-------------|--------------------------------|
| SITE NAME: | Heaton Estates | | |
| DESIGNATION: | Conservation Area, 8 LBs | NEW ENTRY?: | Yes |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|---------------------------|-------------|--------------------------------|
| SITE NAME: | Idle and The Green | | |
| DESIGNATION: | Conservation Area, 34 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|---------------------------------------|-------------|--------------------------------|
| SITE NAME: | Little Horton Lane, Bradford, Trident | | |
| DESIGNATION: | Conservation Area, 60 LBs | NEW ENTRY?: | Yes |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|---|-------------|--------------------------------|
| SITE NAME: | North Park Road | | |
| DESIGNATION: | Conservation Area, 12 LBs, RPG grade II | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|---|-------------|--------------------------------|
| SITE NAME: | Southfield Square, Manningham, Bradford | | |
| DESIGNATION: | Conservation Area, 6 LBs | NEW ENTRY?: | Yes |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|---------------------------|-------------|--------------------------------|
| SITE NAME: | St Paul | | |
| DESIGNATION: | Conservation Area, 18 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|--------------------------|-------------|--------------------------------|
| SITE NAME: | The Goitside, Bradford | | |
| DESIGNATION: | Conservation Area, 5 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

| | | | |
|----------------|---------------------------|-------------|--------------------------------|
| SITE NAME: | Thornton | | |
| DESIGNATION: | Conservation Area, 52 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Jon Ackroyd (LPA) 01274 433952 |

BRADFORD / KIRKLEES / LEEDS



© Battlefields Trust

| | |
|--------------------|--|
| SITE NAME: | Battle of Adwalton Moor, Drighlington |
| DESIGNATION: | Registered Battlefield, LB grade II |
| CONDITION: | Generally satisfactory but with significant localised problems |
| VULNERABILITY: | Medium |
| TREND: | Declining |
| PRIORITY CATEGORY: | A |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1000000 |

The 1643 battle during the English Civil War on moorland outside Bradford in which some 14,000 men fought, gave control of the north of England to the Royalists. The battlefield faces various development pressures, notably from an industrial zone at its west end.

Contact: Tammy Whitaker 01904 601880

CALDERDALE



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Double aisled barn to north west of Kirklees Priory Gatehouse, Kirklees Park, Brighouse |
| DESIGNATION: | Listed Building grade I |
| CONDITION: | Fair |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1133848 |

Aisled barn. One of the farm buildings of the Priory (now gone), with a C15 timber frame, which was later stone-clad. Whole complex continuing to decay. North east corner of stables and north threshing porch appear unstable. A report on development options is under consideration by the owners.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Home Farm Building No. 6, Kirklees Park, Brighouse |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1133805 |

Early C17 cowhouse, two cell house, possibly slaughter house. Gable wall partially collapsed and unstable.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Kirklees Priory Gatehouse, Kirklees Park, Brighouse |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1314039 |

Gatehouse to the Priory (now gone). Early C16, part timber-framed. Holding repairs in place, but beginning to fail. Feasibility and consent for office or dwelling recently obtained. Timber decay ongoing, so that work is becoming urgently necessary.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | L-shaped aisled barn, Kirklees Park, Brighouse |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1133808 |

Aisled barn, early C16, encased in stone during the early to mid C17. Part of a little used farm complex. Area of roof missing to north and some timber decay to frame.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Malthouse, Kirklees Park, Brighouse |
| DESIGNATION: | Listed Building grade I |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1133809 |

Malthouse, late C17. It forms part of a little used farm complex. Building appears to be in a stable condition.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Former lock-up, 121, Keighley Road, Ilkington, Halifax |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Local authority |
| LIST ENTRY NUMBER: | 1314017 |

Located on the north side of the A629 Halifax - Keighley Road, the lock-up is a small two storey building of coursed sandstone walls and stone slate roof dated 1823. The building is vacant. The roof covering and roof drainage is in very poor condition. Community asset transfer to a local preservation group is being considered.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--------------------------------------|
| SITE NAME: | Scout Hall, Lee Lane, Halifax |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (B) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1203783 |

Late C17 house. Part repaired with English Heritage grant, part derelict. Repair and reuse under discussion with Conservation Officer at Calderdale.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Broad Bottom Old Hall, Mytholmroyd, Hebden Royd |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Fair |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1279330 |

Late medieval timber-framed open hall encased in stone in the mid C16. Watertight but vacant for some years. Vulnerable to decay without a sustaining use.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Barn to north west of Greenwood Lee, Widdop Road, Heptonstall |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1265719 |

Late C16 aisled barn. Major failure of roof structure and loss of roof covering.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Christ Church, Wharfe Street, Sowerby Bridge |
| DESIGNATION: | Listed Place of Worship grade II, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1313761 |

Fine early C19 town church with prominent west tower. Lower parts of the church repaired with grant offered in March 2008 under Repair Grants for Places of Worship. Tower roof and parapets poor; grant-aided repairs are underway following an offer in March 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St James, Church Lane, Hebden Royd |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1229139 |

Early C19 Gothic church, with additions by Richard Norman-Shaw. The roof covering and rainwater goods are in poor condition, with consequential damage to the interior.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Hope Baptist Church, New Road, Hebden Bridge, Hebden Royd |
| DESIGNATION: | Listed Place of Worship grade II, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (F) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I230080 |

1857 classical chapel and Sunday school. Extensive repairs carried out to roofs but rainwater goods still poor and high level pointing required. Grant offered in March 2012 under Repair Grants for Places of Worship and works are underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Michael and All Angels, Burnley Road, Todmorden |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I133755 |

A Gothic/Tudor Revival church dating to 1902 with embattled west tower and octagonal spire. The building is constructed from hammer-dressed stone with ashlar dressings. Roofs, rainwater goods and masonry of north aisle, porch, clergy vestry and chancel are in poor condition with dry rot present in these areas. Tower and spire are also in poor condition. Grant offered in March 2013 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Camp at Kirklees Park | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: I005806 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Mill gas plant, Shaw Lodge Mills | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: I005783 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Ventilation chimney and furnace house 260m south of Park Farm | |
| DESIGNATION: | Scheduled Monument, part in RPG grade II | LIST ENTRY NUMBER: I017655 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Collapse | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Blackstone Edge Roman road (see also Rochdale, Greater Manchester), Ripponden | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: I005819 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - extensive | NEW ENTRY?: No |
| OWNER TYPE: | Utility | CONTACT: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|---|--------------------|-------------------------------|
| SITE NAME: | Cairfield on Ringstone Edge Moor, 240m south west of Clay House, Ripponden | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018560 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| <hr/> | | | |
| SITE NAME: | Akroydon | | |
| DESIGNATION: | Conservation Area, 27 LBs | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Kate Peach (LPA) 01422 392268 |
| <hr/> | | | |
| SITE NAME: | Elland | | |
| DESIGNATION: | Conservation Area, 19 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Kate Peach (LPA) 01422 392268 |
| <hr/> | | | |
| SITE NAME: | Todmorden | | |
| DESIGNATION: | Conservation Area, 47 LBs | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Kate Peach (LPA) 01422 392268 |

KIRKLEES



SITE NAME: **Milnsbridge House, 2-6, Dowker Street, Huddersfield**

DESIGNATION: Listed Building grade II*

CONDITION: Fair

OCCUPANCY: Part occupied/part in use

PRIORITY CATEGORY: E (E)

OWNER TYPE: Private

LIST ENTRY NUMBER: 1290158

Mid C18 house now in engineering use. Pediments conceal modern flat roof. Scheme approved for residential conversion but works not yet commenced.

Contact: Tammy Whitaker 01904 601880

© Kirklees Metropolitan Borough Council



SITE NAME: **Boiler house, engine house, rope race, water tower and powerhouse at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield**

DESIGNATION: Listed Building grade II*

CONDITION: Very bad

OCCUPANCY: Vacant/not in use

PRIORITY CATEGORY: A (New entry)

OWNER TYPE: Commercial company

LIST ENTRY NUMBER: 1271263

An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.

Contact: Tammy Whitaker 01904 601880

© English Heritage

| | | | |
|--|--|--|---|
| PRIORITY CATEGORIES | | | ABBREVIATIONS |
| <p>A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.</p> <p>B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.</p> <p>C Slow decay; no solution agreed.</p> | <p>D Slow decay; solution agreed but not yet implemented.</p> <p>E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).</p> | <p>F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.</p> | <p>CA Conservation Area</p> <p>LB Listed Building</p> <p>LPA Local Planning Authority</p> <p>NP National Park</p> <p>RPG Registered Park and Garden</p> <p>SM Scheduled Monument</p> <p>UA Unitary Authority</p> <p>WHS World Heritage Site</p> |
| <p>NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.</p> | | | |

| | | |
|--|--|---|
|  | <p>SITE NAME: Mill Dam at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield</p> <p>DESIGNATION: Listed Building grade II*</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant/not in use</p> <p>PRIORITY CATEGORY: A (New entry)</p> <p>OWNER TYPE: Commercial company</p> <p>LIST ENTRY NUMBER: 1271264</p> | <p>An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.</p> <p>Contact: Tammy Whitaker 01904 601880</p> |
|  | <p>SITE NAME: North Range at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield</p> <p>DESIGNATION: Listed Building grade II*</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant/not in use</p> <p>PRIORITY CATEGORY: A (A)</p> <p>OWNER TYPE: Commercial company</p> <p>LIST ENTRY NUMBER: 1216965</p> | <p>An early C19 mill complex with some later C19 alterations. Buildings include former scribbling, carding, and fulling mill, office, warehouse workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.</p> <p>Contact: Tammy Whitaker 01904 601880</p> |
|  | <p>SITE NAME: Offices and workshop ranges at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield</p> <p>DESIGNATION: Listed Building grade II*</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant/not in use</p> <p>PRIORITY CATEGORY: A (New entry)</p> <p>OWNER TYPE: Commercial company</p> <p>LIST ENTRY NUMBER: 1217132</p> | <p>An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.</p> <p>Contact: Tammy Whitaker 01904 601880</p> |
|  | <p>SITE NAME: West Block at Westwood Mills, Lowestwood Lane, Linthwaite, Huddersfield</p> <p>DESIGNATION: Listed Building grade II*</p> <p>CONDITION: Very bad</p> <p>OCCUPANCY: Vacant/not in use</p> <p>PRIORITY CATEGORY: A (New entry)</p> <p>OWNER TYPE: Commercial company</p> <p>LIST ENTRY NUMBER: 1216966</p> | <p>An early C19 mill complex, with some later C19 alterations. Buildings include former scribbling, carding and fulling mill, office, warehouse, workshops, boiler and engine house. Interiors and roofs stripped for refurbishment. Part lacks roof covering.</p> <p>Contact: Tammy Whitaker 01904 601880</p> |
|  | <p>SITE NAME: Hopton Congregational Church, Calder Road, Mirfield</p> <p>DESIGNATION: Listed Building grade II*</p> <p>CONDITION: Fair</p> <p>OCCUPANCY: Vacant/not in use</p> <p>PRIORITY CATEGORY: C (C)</p> <p>OWNER TYPE: Private</p> <p>LIST ENTRY NUMBER: 1134675</p> | <p>Former church and attached school buildings to rear dated 1829. Largely unaltered and retaining box pews in the body of the church and original windows throughout. Water penetration has resulted in patches of timber decay and a failing roof truss. Planning Permission granted for enabling development subject to a Section 106 agreement over phasing of repair work to the church. Some repairs to roof already carried out.</p> <p>Contact: Tammy Whitaker 01904 601880</p> |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



| | |
|--------------------|--|
| SITE NAME: | Christ Church, Church Lane, Batley and Liversedge |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1313710 |

1812-16 by Thomas Taylor of Leeds. Gothic in style with west tower. Tower roofs are in poor repair. Grant offered in March 2012 under Repair Grants for Places of Worship and works underway.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|--|
| SITE NAME: | Parish Church of St Peter, Kirkgate, Birstall |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1134648 |

One of the earliest churches to occupy the present site of St Peter's was built circa 1100. The present church was essentially rebuilt in the 1860s. Grant offered in December 2010 under Repair Grants for Places of Worship for roof and masonry repairs, and works are underway.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|--|
| SITE NAME: | Church of St Mary, Spen Lane, Cleckheaton |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1184613 |

1850-51 by Dobson of Leeds, Gothic in style with north west tower. Tower in poor repair. Chancel and south transept roofs are leaking. Grant offered in March 2012 under Repair Grants for Places of Worship and works underway.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|---|
| SITE NAME: | Church of St Michael and All Angels, Church Street, Dewsbury |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1200754 |

Fine medieval tower, chancel and side chapels. Nave and aisles by GE Street. The Savile Chapel, built in 1477 contains fine glass of the same date. This rare medieval survival of glass is now threatened and needs to be displayed within a controlled environment if it is to survive. Grant offered in December 2011 under Repair Grants for Places of Worship for this purpose and also to carry out a programme of urgent conservation works to restore important C17 and C18 funerary monuments, all of which have suffered damage from water ingress; works are now underway.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|--|
| SITE NAME: | Church of St Michael, Church Street, Denby Dale |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1135290 |

Church in the Perpendicular style. South wall probably early medieval, the rest early C15 with slightly later tower and chapel of 1632. Tower roof, rainwater goods and south porch in poor condition. Grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

© English Heritage

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© PCC

| | |
|--------------------|--|
| SITE NAME: | Church of St Aidan, Radcliffe Street, Skelmanthorpe, Denby Dale |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 135306 |

St Aidan's was opened on September 28 1895. Urgent repairs have been carried out to the bellcote and chimney. Further roof repairs will be required in the future.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of the Holy Spirit, Bath Road, Heckmondwike |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 379826 |

Roman Catholic church, 1914-15, with minor late C20 alterations. Byzantine revival style. Grant offered in March 2011 under Repair Grants for Places of Worship for roof and window repairs and works are underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Peter, Kirkgate, Huddersfield |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 134977 |

The present church is the third to have stood on the site and was built in 1836. The internal plaster work and the roofs have been repaired with grant offers in December 2010 under Repair Grants for Places of Worship. A further grant offered in December 2012 under Repair Grants for Places of Worship towards stonework repairs and work is underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Thomas, Manchester Road, Huddersfield |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 134950 |

Church of 1857-59 by Sir George Gilbert Scott with impressive south west tower and spire. Roofs and tower masonry in poor condition. Grant offered in December 2011 under Repair Grants for Places of Worship and works underway for roof repairs.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | The Apostolic Church, Mountjoy Road, Huddersfield |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 228182 |

Small mid-C19 Apostolic Church constructed from ashlar to facade, with rock-cut stone elsewhere and rusticated quoins. Simple rectangular plan with four-bay facade. In poor condition.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St John, St John's Road, Huddersfield |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (B) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1217625 |

Fine Victorian church by William Butterfield. West tower and spire. Structural movement in south wall. Two phases of grant offered in December 2011 and December 2012 under Repair Grants for Places of Worship and works underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Shelley Methodist Church, Shelley Far Bank, Kirkburton |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1183949 |

1785-86 classical chapel with stone slate roof. Roofs in poor repair. Grant offered in March 2012 under Repair Grants for Places of Worship and repair works are underway.

Contact: Tammy Whitaker 01904 601880




© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Bartholomew, Greens End Road, Meltham |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1313662 |

Georgian church with early Victorian tower and late Victorian chancel. The tower stonework is in poor condition and the interior damp. The roof coverings are failing. Grant offered in March 2012 under Repair Grants for Places of Worship for tower repair. Further phases of repair will be necessary.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Mary, Church Lane, Mirfield |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1134677 |

Large Victorian church dating from 1871, designed in the Early English style by Sir George Gilbert Scott. High-level tower masonry and tower roof covering are in poor condition, rainwater goods are also in poor condition. These defects are allowing water into the building, which is damaging the fabric and finishes of the church.

Contact: Tammy Whitaker 01904 601880

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Emley Day Holes, 200m east of Churchill Farm, Denby Dale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1017656 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Late prehistoric enclosed settlement on Castle Hill, 550m north of Broadstone Lodge, Denby Dale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018554 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|------------------------------|
| SITE NAME: | Medieval ironstone pits south of Bentley Grange, Denby Dale | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005786 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Crosland Lower Hall moated site, Meltham | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1013896 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Development requiring planning permission | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |
| SITE NAME: | Birkby, Huddersfield | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | High | CONTACT: | Anne Ross (LPA) 01484 222066 |
| SITE NAME: | Dewsbury | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Anne Ross (LPA) 01484 222066 |
| SITE NAME: | Edgerton, Huddersfield | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Anne Ross (LPA) 01484 222066 |
| SITE NAME: | Holmfirth | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | No significant change |
| VULNERABILITY: | High | CONTACT: | Anne Ross (LPA) 01484 222066 |

LEEDS



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Rothwell Castle, Church Street (off) |
| DESIGNATION: | Scheduled Monument, CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1005792 |

Ruined chapel to medieval manor complex. C14. Masonry needs to be consolidated. The site is part of an active Local Heritage Initiative scheme to investigate its surroundings.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



| | |
|--------------------|--|
| SITE NAME: | Stank Hall quasi-manorial site, Dewsbury Road |
| DESIGNATION: | Scheduled Monument and Listed Building grade II*, CA |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Local authority |
| LIST ENTRY NUMBER: | 1002985 and 1375339 |

Remains of a major yeoman farm of sub-manorial type, with surviving barn of C15 of eight bays. Southern-most bays rebuilt in stone mid C17. Roof slates missing. Temporary roof now put in place.

Contact: Tammy Whitaker 01904 601880



| | |
|--------------------|--|
| SITE NAME: | Temple Works gate lodge, Marshall Street, Holbeck |
| DESIGNATION: | Listed Building grade II*, CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1375166 |

Small derelict gate lodge to spinning, water, steam and flax mill of 1836-40 designed by Bonomi in the Egyptian style. Walls stable, but lacks a roof.

Contact: Tammy Whitaker 01904 601880

© English Heritage Archive



| | |
|--------------------|---|
| SITE NAME: | Ledston Hall, Hall Lane, Ledston |
| DESIGNATION: | Listed Building grade I, RPG grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Part occupied/part in use |
| PRIORITY CATEGORY: | D (E) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1237569 |

Country house now partly subdivided into flats, situated in late C17/C18 walled gardens with terraces to south and west, grass terraces to the east and an early C18 park to the north. Five periods of building starting in c1200 with chapel and kitchen. Landscape condition is generally fair to good. A conservation plan and strategic plan have been completed for the estate and discussions are ongoing about future long-term uses. A programme of priority repairs has been identified.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|--|
| SITE NAME: | First Leeds White Cloth Hall, 98-101 (consecutive), Kirkgate, Leeds |
| DESIGNATION: | Listed Building grade II*, CA |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1375042 |

An exceptionally rare example of an early C18 arcaded cloth hall, built in 1711. The building is derelict and deteriorating, the west wing was subjected to emergency demolition in 2010. Part of generally dilapidated block along Kirkgate, which has been included in a Heritage Lottery Fund Townscape Heritage Initiative programme.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|---|
| SITE NAME: | Temple Mill, Marshall Street, Holbeck, Leeds |
| DESIGNATION: | Listed Building grade I, CA |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1375162 |

Brick-vaulted former spinning shed by Bonomi, Egyptian facade, 1836-40. Brick-vaulted roof with circular rooflights. Failure of tie bar has caused collapse of two front bays. Other bays vulnerable to similar failure. Proposals for structural repair have been developed and are under discussion.

Contact: Tammy Whitaker 01904 601880

© English Heritage

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |




© English Heritage Archive

| | |
|--------------------|---|
| SITE NAME: | Hunslet Mill, Goodman Street, Hunslet, Leeds |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1256253 |

Flax mill of 1838 with later infill in south block. Housing development agreed, but not yet underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | St Marys Convent Church (Mount Saint Mary), Church Road, Richmond Hill, Leeds |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Commercial company |
| LIST ENTRY NUMBER: | 1255558 |

Former Roman Catholic Church, 1852, by Joseph Hansom. Chancel and transepts by EW Pugin, 1866. Gothic style. Presbytery roof slates are partly missing, the windows are boarded and broken and the interior of the church has been stripped. Surveyed following concern of the Council for public safety. Holding works have been undertaken. Housing development has received consent.

Contact: Tammy Whitaker 01904 601880



© English Heritage Archive

| | |
|--------------------|--|
| SITE NAME: | Memorial to Queen Victoria, Woodhouse Lane, Woodhouse Moor, Leeds |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Local authority |
| LIST ENTRY NUMBER: | 1255642 |

1903 by Sir George Frampton. Portland stone base supporting an enthroned bronze statue of Queen Victoria. The base is flanked by bronzes of "Peace" and "Industry". The figure of Industry is severely damaged and now in store. The remaining bronzes are corroding. Formerly located in front of the Town Hall.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Gazebo north of Clumpcliffe Farmhouse, Methley Lane, Methley, Rothwell |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (B) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1135669 |

Hunting lodge dated 1708 on rainwater heads. Total collapse of the front elevation. Temporary cover on the flanking roofs has failed. Residential conversion being discussed.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Thorpe Hall, Middleton Lane, Thorpe on the Hill |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1135039 |

Former farmhouse, 1735. Unitary Development Plan proposes employment land use allocation (offices). Some windows broken and gutters failed. Ceiling collapsed in one room. Roof holed.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of the Epiphany, Beech Lane |
| DESIGNATION: | Listed Place of Worship grade I |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1255904 |

Grade I listed 1930s art deco church. Roofs and windows in poor condition. Phase one grant offered in December 2010 under Repair Grants for Places of Worship and work is underway. Grant offered in December 2012 under Repair Grants for Places of Worship and investigative work for phase two is in progress.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Stephen, Morris Lane |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1375210 |

Original church dates to 1829. A new spire was erected in the 1830s after a lightning strike. Grant offered in March 2011 under Repair Grants for Places of Worship for chancel roof repairs and works are underway.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Wilfrid, Selby Road |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1256092 |

Significant 1930s Expressionist church. Roof in very poor structural condition. One phase of repair complete with grant offered in December 2010 under Repair Grants for Places of Worship for roof repairs which are complete. A further grant offered in March 2011 and March 2012 for further work.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Mark, St Mark's Road |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1256144 |

Early C19 Commissioners' Church with fine west tower. Grant offered in March 2010 under Repair Grants for Places of Worship for roof repairs which are complete. A further grant offered in March 2012 for tower, vestry roof and aisle stonework.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Paul, Whitehall Road, Morley |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1313446 |

Church in the Gothic Revival style dating to 1876-78 with sanctuary remodelled c1928 by Sir Charles Nicholson. Roofs and windows in poor condition. Grant offered in March 2013 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



| | |
|--------------------|--|
| SITE NAME: | Church of St Andrew, Haw Lane, Yeadon and Guiseley |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | 1313171 |

Church by Thomas and Francis Healey dating to 1890-91 in the Arts and Crafts Perpendicular style. Distinctive octagonal bell turret with wooden traceried bellcote and ogival cap. Roofs, rainwater goods and some glazing in poor condition. Bell turret also in poor condition. Water ingress has caused internal rot and damage to finishes. Grant offered in March 2013 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

© English Heritage

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Cairn west of Craven Hall Hill | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1010355 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Medieval farmstead in Ireland Wood, 150m north east of Cookridge Hospital | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1018553 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - extensive | NEW ENTRY?: No |
| OWNER TYPE: | Other | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Stone hut circle settlement in Clayton Wood on the south west side of Iveson Drive | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1018814 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: No |
| OWNER TYPE: | Local authority | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Stone hut circle settlement in Iveson Wood | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1018815 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Visitor erosion - extensive | NEW ENTRY?: No |
| OWNER TYPE: | Local authority | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Linear earthwork, part of the Aberford Dyke system, extending 770m east from Humphrey Dale Cottage, Aberford / Stutton with Hazlewood | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1016953 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Linear earthworks known as Woodhouse Moor Rein and South Dyke, part of the Aberford Dyke system, Lotherton cum Aberford / Saxton with Scarthingwell | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1016954 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable clipping | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Howley Hall: a 16th century country house and gardens, Morley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1016323 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Scrub/tree growth | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Settlement site revealed by aerial photography near Moat House, Walton / Wighill | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1003801 |
| CONDITION: | Extensive significant problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Oulton Hall | Park and pleasure grounds laid out in 1809-10 in part to designs by Humphry Repton, with mid C19 additions by WA Nesfield. Chequered C20 history and now split as a hotel and golf course. De Vere hotel group restored the main building. The garden layout survives in part but golf course and new development predominate. |
| DESIGNATION: | Registered Park and Garden grade II, 2 LBs, part in CA | |
| CONDITION: | Generally satisfactory but with significant localised problems | |
| VULNERABILITY: | Low | |
| TREND: | Stable | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Mixed, multiple owners | |
| LIST ENTRY NUMBER: | 1000413 | Contact: Tammy Whitaker 01904 601880 |



© English Heritage

| | | |
|--------------------|--|---|
| SITE NAME: | High Royds Hospital, Aireborough | The grounds of an echelon-style psychiatric hospital, opened in 1888, including airing courts, sports grounds, woodland and parkland. Hospital under conversion to residential use including extensive new build within the grounds. Historic landscape now significantly compromised and peripheral areas neglected. |
| DESIGNATION: | Registered Park and Garden grade II, LB grade II | |
| CONDITION: | Extensive significant problems | |
| VULNERABILITY: | High | |
| TREND: | Declining | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Mixed, multiple owners | |
| LIST ENTRY NUMBER: | 1001469 | Contact: Tammy Whitaker 01904 601880 |

| | | | |
|----------------|-----------------------------|-------------|-------------------------------|
| SITE NAME: | Buslingthorpe, Leeds | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | High | CONTACT: | Phil Ward (LPA) 0113 247 8146 |

| | | | |
|----------------|---------------------------|-------------|-------------------------------|
| SITE NAME: | Chapelton, Leeds | | |
| DESIGNATION: | Conservation Area, 10 LBs | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Improving significantly |
| VULNERABILITY: | Low | CONTACT: | Phil Ward (LPA) 0113 247 8146 |

| | | | |
|----------------|---|-------------|-------------------------------|
| SITE NAME: | Headingley Hill, Hyde Park and Woodhouse Moor, Leeds | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | Yes |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Low | CONTACT: | Phil Ward (LPA) 0113 247 8146 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|-----------------------|-------------|-------------------------------|
| SITE NAME: | Holbeck, Leeds | | |
| DESIGNATION: | Conservation Area | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | No significant change |
| VULNERABILITY: | Medium | CONTACT: | Phil Ward (LPA) 0113 247 8146 |

| | | | |
|----------------|------------------------------|-------------|-------------------------------|
| SITE NAME: | Stank Hall, Leeds | | |
| DESIGNATION: | Conservation Area, 3 LBs, SM | NEW ENTRY?: | No |
| CONDITION: | Very bad | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Phil Ward (LPA) 0113 247 8146 |

WAKEFIELD



© English Heritage

| | |
|--------------------|---------------------------------------|
| SITE NAME: | Crown Court House, Wood Street |
| DESIGNATION: | Listed Building grade II*, CA |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | A (New entry) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1258996 |

Built in 1810 in neo-Greek style with extensions of 1849-50. Two storeys, sandstone ashlar with banded rustication to all walls. Tetrastyle Doric pedimented portico with eight side steps to stylobate. Central door flanked by sash windows with glazing bars. Plain parapets to one-storey side wings. Set back two-storey left section has three pairs of windows and an entablature and blocking course continuous with return of main block. Unoccupied, grave condition. Roofs in very poor condition. No solution agreed.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Malt House approx 15 metres south west of Blacker Hall Farmhouse, Crigglestone Branch Road, Chevet |
| DESIGNATION: | Listed Building grade II* |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | B (A) |
| OWNER TYPE: | Private |
| LIST ENTRY NUMBER: | 1135604 |

Rare early-mid C17 malt house located approx 15 metres south west of Blacker Hall Farmhouse. Impressive group value. Recent partial collapse of front wall, roof covering missing, roof timbers collapsing. Imminent danger of total collapse. English Heritage grant offered 2011 for project development work with a view to longer term solution.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--------------------------------------|
| SITE NAME: | Pontefract Castle, Pontefract |
| DESIGNATION: | Scheduled Monument, CA |
| CONDITION: | Poor |
| OCCUPANCY: | N/A |
| PRIORITY CATEGORY: | B (B) |
| OWNER TYPE: | Local authority |
| LIST ENTRY NUMBER: | 1010127 |

Substantial ruins comprising motte, bailey and Saxon cemetery. The fabric of the ruins needs substantial consolidation. A condition survey has been prepared. Grant has been awarded for the first three phases of repair. Emergency works complete.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | The Hermitage, Southgate, Pontefract |
| DESIGNATION: | Listed Building grade I |
| CONDITION: | Poor |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | F (A) |
| OWNER TYPE: | Health authority |
| LIST ENTRY NUMBER: | 1135427 |

The Hermitage consists of two below ground chambers hewn out of sandstone. The deeper chamber dates from 1386 and consists of a short corridor which leads to a spiral stair which descends to a well. The second chamber, known as the Oratory, is later and consists of a spiral stair which leads to a cell with altar and fireplace. At risk due to flooding. Following completion of a Hydrological Survey a solution to flooding has been identified and is being implemented.

Contact: Tammy Whitaker 01904 601880

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



| | |
|--------------------|--|
| SITE NAME: | Church in Bretton Park, Park Lane, West Bretton |
| DESIGNATION: | Listed Building grade II*, RPG grade II |
| CONDITION: | Very bad |
| OCCUPANCY: | Vacant/not in use |
| PRIORITY CATEGORY: | F (New entry) |
| OWNER TYPE: | Charity (non-heritage) |
| LIST ENTRY NUMBER: | I 135462 |

Church built in 1744 by Sir William Wentworth for his own estate. Ashlar with stone slate roof. In poor condition with water ingress due to condition of roof and rainwater goods. Subject of English Heritage grant with repairs starting Summer 2013.

Contact: Tammy Whitaker 01904 601880



| | |
|--------------------|--|
| SITE NAME: | Quaker Meeting House, Pontefract Road, Ackworth |
| DESIGNATION: | Listed Place of Worship grade II*, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (C) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 135475 |

A two storey building in classical style constructed in 1847 from sandstone ashlar with a slate roof. It is currently in use as part of a school. Low level stonework is badly eroding. Two windows are broken. Roof in poor repair.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|---|
| SITE NAME: | Church of St Mary, New Road, Badsworth |
| DESIGNATION: | Listed Place of Worship grade I, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 052219 |

Medieval village church with fine west tower. The sandstone of the south elevation is much eroded. Grant offered in December 2011 under Repair Grants for Places of Worship for repair and works underway.

Contact: Tammy Whitaker 01904 601880

© English Heritage




| | |
|--------------------|--|
| SITE NAME: | Church of St John, Jackson Lane, Darrington |
| DESIGNATION: | Listed Place of Worship grade II, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | C (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 135502 |

Rock-faced magnesian limestone church dating to 1878 in C12 northern French style to designs of Sir Arthur Blomfield. Roofs, masonry and windows are in poor condition.

Contact: Tammy Whitaker 01904 601880

© English Heritage



| | |
|--------------------|--|
| SITE NAME: | Church of All Saints, Ackton Lane, Featherstone |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (New entry) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 288962 |

Late medieval church in the Perpendicular style restored in the late C19 and re-ordered in the late 1990s. Roofs, masonry and rainwater goods are in poor condition. Grant offered in December 2012 under Repair Grants for Places of Worship.

Contact: Tammy Whitaker 01904 601880

© English Heritage

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of the Holy Trinity, Church Street, Ossett |
| DESIGNATION: | Listed Place of Worship grade II* |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 184049 |

Impressive Victorian church with central tower and spire. Mostly in good repair but stonework and glazing to the west and east elevations is in poor condition. Work to repair the west end is complete with a grant offered in December 2010 under Repair Grants for Places of Worship and grant offered in December 2012 under Repair Grants for Places of Worship for repair works to the east end.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|---|
| SITE NAME: | Church of St Giles, Market Place, Pontefract |
| DESIGNATION: | Listed Place of Worship grade II*, CA |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | D (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 135461 |

Medieval and Georgian town church. North aisle roof and stonework to north and south elevations in poor condition. Grant offered in December 2011 under Repair Grants for Places of Worship for repair of masonry to south elevation and repair works in progress. Further phases required.

Contact: Tammy Whitaker 01904 601880



© English Heritage

| | |
|--------------------|--|
| SITE NAME: | Church of St Paul, St Paul's Drive, Wakefield |
| DESIGNATION: | Listed Place of Worship grade II |
| CONDITION: | Poor |
| PRIORITY CATEGORY: | F (D) |
| OWNER TYPE: | Religious organisation |
| LIST ENTRY NUMBER: | I 273436 |

Church of 1823-25 by Atkinson of York, with west tower. Roof in poor condition. Grant offered in March 2012 under Repair Grants for Places of Worship for repair and works are underway.

Contact: Tammy Whitaker 01904 601880

| | | |
|--------------------------|---|--------------------------------------|
| SITE NAME: | Earthwork west of Ferrybridge, Knottingley | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: 1005789 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Arable ploughing | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Ferrybridge near Knottingley, Brotherton | |
| DESIGNATION: | Scheduled Monument, 2 LBs | LIST ENTRY NUMBER: 1005799 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: No |
| OWNER TYPE: | Local authority | CONTACT: Tammy Whitaker 01904 601880 |

| | | |
|--------------------------|--|--------------------------------------|
| SITE NAME: | Newland Preceptory, Newland with Woodhouse Moor / Normanton | |
| DESIGNATION: | Scheduled Monument, 2 LBs | LIST ENTRY NUMBER: 1012153 |
| CONDITION: | Extensive significant problems | TREND: Declining |
| PRINCIPAL VULNERABILITY: | Development requiring planning permission | NEW ENTRY?: No |
| OWNER TYPE: | Private | CONTACT: Tammy Whitaker 01904 601880 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Sharlston Common coal and ironstone workings, Sharlston | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018399 |
| CONDITION: | Generally satisfactory but with significant localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vehicle damage/erosion - moderate | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|---|--------------------|-----------------------------|
| SITE NAME: | Site of post-medieval tannery, Felkirk, South Hiendley | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1005775 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Vandalism | NEW ENTRY?: | No |
| OWNER TYPE: | Private | CONTACT: | Tammy Whitaker 01904 601880 |

| | | | |
|--------------------------|--|--------------------|-----------------------------|
| SITE NAME: | Prehistoric enclosed settlement known as South Kirkby Camp, South Kirkby and Moorthorpe | | |
| DESIGNATION: | Scheduled Monument | LIST ENTRY NUMBER: | 1018818 |
| CONDITION: | Generally unsatisfactory with major localised problems | TREND: | Declining |
| PRINCIPAL VULNERABILITY: | Plant growth | NEW ENTRY?: | No |
| OWNER TYPE: | Local authority | CONTACT: | Tammy Whitaker 01904 601880 |

WAKEFIELD / BARNESLEY / KIRKLEES

© English Heritage

| | | |
|--------------------|--|---|
| SITE NAME: | Bretton Hall, West Bretton / Denby Dale / High Hoyland | Pleasure grounds of late C18 and early C19, parkland of C18 with earlier origins. Associations with Richard Woods and Robert Marnock. Part of parkland accommodates Yorkshire Sculpture Park, part country park. Hall is owned by Wakefield Council who is negotiating with potential purchaser of the Hall for hotel use. First phase of conservation and repair works now complete including the restoration of dramatic views across the lakes. Repairs ongoing to church in grounds under English Heritage grant aid. |
| DESIGNATION: | Registered Park and Garden grade II, 23 LBs, part in CA | |
| CONDITION: | Generally satisfactory but with significant localised problems | |
| VULNERABILITY: | Medium | |
| TREND: | Improving | |
| NEW ENTRY?: | No | |
| OWNER TYPE: | Mixed, multiple owners | |
| LIST ENTRY NUMBER: | 1001217 | Contact: Tammy Whitaker 01904 601880 |

YORK (UA)

© English Heritage

| | | |
|--------------------|--|--|
| SITE NAME: | Church of St Mary, Jackson's Walk, Askham Richard | Late C12 church with earlier origins, restored in 1879. Bell turret, high-level stonework and glazing in poor condition. Grant offered in December 2012 under Repair Grants for Places of Worship. |
| DESIGNATION: | Listed Place of Worship grade II*, CA | |
| CONDITION: | Poor | |
| PRIORITY CATEGORY: | D (New entry) | |
| OWNER TYPE: | Religious organisation | |
| LIST ENTRY NUMBER: | 1316686 | Contact: Tammy Whitaker 01904 601880 |

| | | | |
|----------------|--|-------------|---------------------------------|
| SITE NAME: | Strensall, York, Strensall with Towthorpe | | |
| DESIGNATION: | Conservation Area, 7 LBs | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | Deteriorating |
| VULNERABILITY: | Medium | CONTACT: | Janine Riley (LPA) 01904 551305 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |

| | | | |
|----------------|--|-------------|---------------------------------|
| SITE NAME: | The Racecourse and Terry's Factory, York | | |
| DESIGNATION: | Conservation Area, 9 LBs | NEW ENTRY?: | No |
| CONDITION: | Poor | TREND: | No significant change |
| VULNERABILITY: | High | CONTACT: | Janine Riley (LPA) 01904 551305 |

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

| | |
|-----|----------------------------|
| CA | Conservation Area |
| LB | Listed Building |
| LPA | Local Planning Authority |
| NP | National Park |
| RPG | Registered Park and Garden |
| SM | Scheduled Monument |
| UA | Unitary Authority |
| WHS | World Heritage Site |



ENGLISH HERITAGE

This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2013 by English Heritage
1 Waterhouse Square, 138-142 Holborn,
London EC1N 2ST

© Copyright English Heritage 2013

If you require an alternative accessible version of this document (for instance in audio, Braille or large print) please contact our Customer

Services Department:

Telephone: 0870 333 1181

Fax: 01793 414926

Textphone: 0800 015 0516

E-mail: customers@english-heritage.org.uk