

Heritage at **Risk**



Historic England

West Midlands Register 2017

Contents

Heritage at Risk	III
The Register	VII
Content and criteria	VII
Criteria for inclusion on the Register	IX
Reducing the risks	XI
Key statistics	XIV
Publications and guidance	XV
Key to the entries	XVII
Entries on the Register by local planning authority	XIX
Herefordshire, County of (UA)	I
Shropshire (UA)	13
<i>Staffordshire</i>	28
East Staffordshire	28
Lichfield	29
Newcastle-under-Lyme	30
Peak District (NP)	31
South Staffordshire	31
Stafford	32
Staffordshire Moorlands	33
Tamworth	35
Stoke-on-Trent, City of (UA)	35
Telford and Wrekin (UA)	38
<i>Warwickshire</i>	39
North Warwickshire	39
Nuneaton and Bedworth	42
Rugby	42
Stratford-on-Avon	44
Warwick	47
<i>West Midlands</i>	50
Birmingham	50
Coventry	54
Dudley	57
Sandwell	59
Walsall	60
Wolverhampton, City of	61
<i>Worcestershire</i>	63
Bromsgrove	63
Malvern Hills	64
Redditch	67
Worcester	67
Wychavon	68
Wyre Forest	71

Heritage at Risk





Our West Midlands Heritage at Risk team continues to work hard to reduce the number of heritage assets on the Register. This year the figure has been brought down to 416, which is 7.8% of the national total of 5,290. While we work to decrease the overall numbers we do, unfortunately, have to add individual sites each year and recognise the challenge posed by a number of long-standing cases. We look to identify opportunities to focus resources on these tough cases. This year we have grant-aided some £1.5m of conservation repairs, Management Agreements and capacity building, covering a wide range of sites. We are particularly pleased to have jointly funded a Places of Worship Support Officer with the Roman Catholic Archdiocese of Birmingham; the first Catholic Diocesan Places of Worship Support Officer in England.

Veryan Heal Planning Director, West Midlands



The 2017 Heritage at Risk Register for the West Midlands reflects the hard work of the local team, our partner organisations and owners of our locally designated heritage. We continue to follow the national trend and have reduced the overall

number of heritage assets on the West Midlands Register.

In last year's published Register we identified a number of priority sites for the regional team and we are encouraged with the progress made. Snodhill and Clifford castles have received significant grant aid and will be removed from the Register in the coming year. Conservation work is due to start at 31 High Street, Droitwich. Bedlam Furnace, in the Ironbridge Gorge World Heritage Site, has been removed from the Register.

We have also made significant progress on a number of long-standing cases. Pitchford Hall, Shropshire, has new owners and we are working closely with them as they carry out extensive conservation work. We are exploring options with the City of Stoke-on-Trent to tackle the issues at Price and Kensington Teapot Works and Chatterley Whitfield Colliery. The city walls of Hereford and the town walls of Shrewsbury have been removed from the Register. We have negotiated with

Birmingham City Council to keep Moseley Road Baths open until April 2018 and we are working with the City Council, the Moseley Road Baths Action Group, the Friends of Moseley Road Baths and The National Trust to explore potential options for the future use of the building. Curzon Street Station, Birmingham, is another major building where we expect to see significant works commence in the coming year.


Using our grant aid, the Heritage at Risk team also develops and implements solutions for heritage at risk through Management Agreements. This approach provides owners with the support needed to achieve positive change in the management of archaeological sites at risk. In 2016/17 this funding has resulted in the removal of Nadbury Camp, Warmington, the moated sites at Baxterley and Moorgreen Farm, Alvechurch and the Roman Settlement at Bays Meadow, Droitwich Spa from our Register.

Regionally, there are 101 places of worship on the Register. This is an increase of one in the overall number, which doesn't reflect the fact that we have worked to remove 15 from the Register in the last year. Even with the dedication and hard work of congregations, volunteers and the Historic England funding for Places of Worship Support Officers, these numbers illustrate the pressures on this particular aspect of our heritage.

Rhodri Evans Principal Adviser, Heritage at Risk

Cover image: The Toll House, Stratford-upon-Avon, is a grade I listed building on Clopton Bridge. Built in 1814, it had sat empty for many years. With grant aid from Historic England and the Heritage Lottery Fund urgent conservation work has been carried out to the roof and stonework. Employing skilled craftsmen, the Stratford Historic Building Trust has breathed new life into the building. The Toll House has been transformed from an empty, dilapidated building with an unclear future into a modern office space. The project demonstrates how heritage conservation can be at the heart of supporting local communities, businesses and jobs.

Designated assets on the 2017 **West Midlands Register**



There are **416** assets on the **West Midlands Register**, **17** fewer than in 2016

Curzon Street Station **Birmingham**



Curzon Street Station, the original terminus of the London to Birmingham railway, was built in 1838 and has been unused for over a decade. It has become isolated on the eastern side of the city, a proud and intriguing relic of Birmingham's 19th century civic pride, welcoming visitors to the city as their trains come

into Birmingham New Street Station.

Considering the origins of the building at the cutting edge of railway technology, it is fitting that Curzon Street Station will be given a new lease of life as part of the developments that will see HS2 arrive in Birmingham.

While building works begin on the new HS2 station, Curzon Street Station will come back to life as a shared office building. In a wide ranging partnership HS2 Ltd will

lease the building from the City Council, and will share its use with Birmingham City University and Historic England, who will occupy one floor as its West Midlands Regional Office. Historic England looks forward to being part of the medium term future of the building.

This new plan will ensure that the grade I listed building will come back into use while the wider area is redeveloped. The project will provide a striking example of how heritage conservation can play an integral part in major redevelopment projects by providing a short term solution while demonstrating a long term sustainable use.

An application for listed building consent has been submitted to Birmingham City Council and it is hoped that the building will be back in use by the end of 2018.

The Nag's Head Engine House **Pontesford, Shropshire**

The Nag's Head Engine House is the oldest and only surviving example of a group of early pumping engines built in the village of Pontesford. They were constructed to exploit the local coal field to facilitate the lead smelting industry which, in the late 18th century, was centred on this small Shropshire village. The Nag's Head is the only remaining engine house to survive demolition or significant alteration

The Engine House is rectangular on plan, measures 6.3m x 4.7m and was originally covered by a pitched roof where the ridge was 9.5m above ground level. The walls are constructed in squared buff coloured rubble. Apart from the large stone base used to secure the engine cylinder, nothing remains of the steam engine and its component parts. The Engine House became disused in the middle of the 19th century.

A scheme to consolidate the masonry remains was carried out this year with grant aid from Historic England and facilitated by the Stiperstones & Corndon Hill



Country Landscapes Partnership. The works included rebuilding part of one demolished wall to ensure structural stability, stone renewal, repointing and soft capping of exposed wall heads. The works were concluded in April 2017 and the structure removed from the Heritage at Risk Register.

Caring for Conservation Areas

This year we are celebrating the 50th anniversary of conservation areas. These come in all forms, from the quintessential English village to the urban heartland. They are united by a common theme – they are special places full of character and history, much loved by those who live and work in them. Because of their unique character they are also engines for economic regeneration and this is the key to tackling risk in many conservation areas.

This year we have added more conservation areas to the Register than have been removed. But it's also the year we launched Heritage Action Zones, many of which include conservation areas at risk where we will unlock economic potential with our partners over the coming years.

For more information contact:

Rhodri Evans, Historic England West Midlands
The Axis, 10 Holliday Street,
Birmingham, B1 1TG
Telephone: 0121 625 6870
Email: west.midlands@HistoricEngland.org.uk
Twitter: @HE_WestMids

For a different format of this document contact our customer services department on:
Telephone: 0370 333 0608 Textphone: 0800 015 0516
Email: customers@HistoricEngland.org.uk
Product code: 52077

Find out what's at risk by searching or downloading the online Heritage at Risk Register at:
HistoricEngland.org.uk/har

THE REGISTER

Content and criteria

LISTING

Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the [National Heritage List for England](#) (NHLE), an online searchable database of listed assets. Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the system of statutory protection of heritage assets. Listing, which is applied to buildings, emerged from the post-Blitz 1940s Planning Acts. There are now nearly 400,000 assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

Historic England, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Digital, Culture, Media and Sport who makes the decisions on whether an asset is listed. Understanding and appreciation develop constantly, which makes keeping the listing database up-to-date a never-ending challenge.

While still responding to threat-driven cases, our approach is now more strategic, based around thematic and area-based projects. Recent developments have seen a greater striving for openness and transparency in the process of listing a site, and better communication of what makes something special.

In June 2016 Historic England launched [Enriching the List](#), a crowdsourcing initiative opening up the entries on the National Heritage List to contributions by users. Anyone can register as a volunteer and submit extra information about one of the assets on the List or submit photographs to illustrate it. This additional content will then be available for anyone to view with (but separate from) the official List Entry.

Alongside the nationally listed assets found on the National Heritage List for England are locally listed assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

Listing is the most commonly encountered type of statutory protection of heritage assets. A listed building (or structure) is one that has been granted protection as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of very high quality and under threat. Listing is mandatory: if special interest is believed to be present, then the Department for Digital, Culture, Media and Sport has a duty to add the building to the List.

Listed buildings are graded I, II* and II. Grade I buildings are of outstanding interest, and II* are particularly important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II. There are over 377,000 entries on the NHLE of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory List.

Structures can occasionally have dual List entries (be both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. Nearly 20,000 examples have been listed because of their national importance. Scheduled monuments are not graded. They cover human activity from the Paleolithic era, such as cave sites, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record. The later 20th century saw unprecedented changes to the landscape. As a result, some types of historic sites that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside.

Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and, often most seriously of all, wholly natural processes such as scrub growth, animal burrowing and coastal erosion. Scheduling is discretionary, and many archaeological sites of potential importance are not scheduled. Instead, they are managed through the planning system and other regimes.

REGISTERED PARKS AND GARDENS

There are over 1,600 landscapes on the current Historic England Register of Historic Parks and Gardens of Special Historic Interest. These registered landscapes are graded I, II* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the Historic England Register of Historic Parks and Gardens brings no statutory controls, but there is a clear presumption in favour of upholding their significance in government planning guidance, so they do gain protection. Local authorities are required to consult Historic England on applications affecting sites registered as grade I or II*, and the Gardens Trust on sites of all grades. The setting of other listed heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

Historic England's Register of Historic Battlefields was set up in 1995, and is our youngest category of listing. Its aim is to protect and promote those sites where history was made through military engagement which can be securely identified on the ground. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where often thousands were killed, deserve our recognition and respect. Recently, additions have been made to the Register of Historic Battlefields for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in government planning policy.

PROTECTED WRECK SITES

There are over 50 protected wreck sites in England, which represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to list a restricted area around a vessel to protect it or its contents from unauthorised interference, and Historic England administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are listed by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For 50 years, ever since the 1967 Civic Amenities Act, conservation areas have proved a highly effective mechanism for managing change on an area-wide basis.

There are currently nearly 10,000 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity.

Criteria for inclusion on the Register

RISK ASSESSMENTS

Heritage assets included on the Register are risk assessed according to the nature of the site rather than the type of listing. Building or structure assessments are used for secular listed buildings and structural scheduled monuments, typically masonry remains. Archaeology assessments are used for scheduled earthworks and below-ground remains. Thus a scheduled monument may appear on the Register in either or both the building and structure and the archaeology sections, depending upon what puts it at risk. Listed buildings that are in use as places of worship are assessed using the places of worship assessment. Registered parks and gardens, conservation areas, battlefields and protected wreck sites have their own assessments because they each have their own particular characteristics and factors that may put them at risk.

BUILDINGS AND STRUCTURES

To be considered for inclusion on the Register, buildings or structures must be:

- listed on the National Heritage List for England;
- a grade I or II* listed building;
- a grade II listed building in London;
- a structural scheduled monument with upstanding remains;
- in secular (non-worship) use.

Buildings or structures are assessed on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is assessed as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category, for example: ruins, walls, gates, headstones or boundary stones.

Condition is assessed as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register is typically very bad or poor, but can be fair or, very occasionally, good. This reflects the fact that some buildings or structures are vulnerable because they are empty, underused or face redundancy without a new use to secure their future. Assessing vulnerability in the case of

buildings in fair condition necessarily involves judgement and discretion. A few buildings remain on the Register in good condition, having been repaired or mothballed, but still awaiting a new use or occupancy.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured either through occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

To be considered for inclusion on the Register, places of worship must be listed grade I, grade II* or grade II on the National Heritage List for England, and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If a place of worship is in very bad or poor condition, it is added to the Register. This includes places of worship which are generally in fair or good condition but have major problems with one key element, like the tower.

Historic England has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register. This means that there are some places of worship in good condition on the Register but with outstanding issues still to be resolved at the time when they were assessed.

ARCHAEOLOGY

To be considered for inclusion on the Register, archaeological sites must be listed as scheduled monuments and included on the National Heritage List for England.

Archaeology assessments cover scheduled earthworks and buried archaeology. The risk assessment is based on their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from 'extensive significant problems' to 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address the identified issues, and a significant reduction in the level of risk has been demonstrated.

PARKS AND GARDENS

To be considered for inclusion on the Register, parks and gardens must be listed as grade I, grade II* or grade II and included on the National Heritage List for England. Parks and gardens are assessed in terms of condition and vulnerability. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed and divided ownership leads to the loss of their cohesive historic design.

Park and garden entries are removed from the Register once steps have been taken to address issues and positive progress is being made.

BATTLEFIELDS

To be considered for inclusion on the Register, battlefields must be listed and included on the National Heritage List for England. Battlefields deemed to be at risk of loss of cultural significance are included on the Register.

The principal risks and threats are:

- development pressure e.g. encroachment of buildings;
- pressures of particular use within the site e.g. arable cultivation;
- damage e.g. unregulated metal detecting.

Battlefields are removed from the Register either when damaging activities cease/are managed, or when threats recede due to effective planning.

WRECK SITES

To be considered for inclusion on the Register, wrecks must be listed and included on the National Heritage List for England. Wreck sites are assessed based on their current condition, vulnerability and the way they are being managed.

Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained. In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

Historic England has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and not expected to change significantly in the next three years, are defined as being at risk.

The approach taken to assess conservation areas at risk has been refined since the first survey in 2008/2009. The information provides a detailed assessment of each conservation area. An overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

One of the primary aims of the [Historic England Corporate Plan 2017-2020](#) is protecting places through Heritage at Risk grants and advice, thereby reducing the risk to heritage assets. In order to achieve this aim we are working to:

- better understand the nature and extent of risk
- encourage others to save and re-use heritage at risk
- build the capacity of the sector to deliver solutions for heritage at risk
- provide advice and grant aid to help remove sites from the Register.

Dedicated Heritage at Risk teams in our nine regional offices are tasked with achieving this aim.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Finding solutions for heritage at risk requires working in close partnership with owners, local planning authorities and a wide variety of other organisations. The provision of clear advice is essential to further understanding of heritage at risk.

Maintenance and occupation or use (where appropriate) are essential in preventing heritage from becoming at risk. Maintenance of assets already at risk can prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

The Heritage at Risk Register helps us understand what factors lead to heritage assets becoming at risk, what action is most likely to influence their condition and where resources can be focused to best effect. Historic Environment Records and local heritage at risk registers, maintained by local authorities, are additional repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of assets.

Historic England provides a wide range of published guidance on reducing the risks, including: finding partners, funding, new uses for heritage assets, and enforcing urgent works and repairs. These are available to download from our website, www.historicengland.org.uk. Key publications and guidance are listed on pages XV-XVI.

BUILDINGS AND STRUCTURES

Our nine regional teams can help owners, developers and Local Authorities better understand buildings and

structures at risk, and advise on necessary repairs. They can help commission specialist surveys, help with feasibility studies and with brokering solutions. In particularly difficult cases, they can draw on the expertise of Historic England's national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law.

Historic England can help with access to funding. We have two principal grant streams ourselves: Repair Grants for Heritage at Risk and Section 17 Management Agreements, which are smaller grants for scheduled monuments. More information on funding can be found on the [Historic England](#) website. The support of other grant providers, including the Heritage Lottery Fund, the Architectural Heritage Fund and Natural England, is also critical.

We know how useful our own Register is in managing risk, prioritising action and engaging partners. We are therefore working with local authorities to encourage them to develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers; '[Stopping the Rot](#)' is our published guidance on this. Our legal team can provide training and support for local authorities considering enforcement action. In certain circumstances we can also provide [grant aid](#) to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the [Architectural Heritage Fund](#) and fund their regional support officers to work across the country. They help BPTs and other not-for-profit organisations to access funding, carry out feasibility studies and develop solutions for buildings at risk. The [Heritage Network Trust](#) also provides information about support officers and BPTs. Guidance and case studies are available on the [Historic England](#) website.

PLACES OF WORSHIP

Historic places of worship are cared for by thousands of volunteers throughout the country. Sometimes these treasured buildings will require major repairs. However, regular maintenance will help prevent minor problems developing into unnecessary crises. Keeping drains and gutters clear is essential: the overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable. In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such cooperation enables them to get good quality work carried out at

reasonable prices by firms that understand historic buildings. The practical resources created by the [Maintenance Cooperatives Project](#) run by the Society for the Protection of Ancient Buildings are still available from their website. These are a great starting point for local groups wanting to work together to do basic, regular maintenance safely.

The Heritage Lottery Fund welcomes applications from places of worship seeking to do repairs, develop facilities or welcome more visitors. Grants of up to £100k are available from Our Heritage and over £100k from the Heritage Grants programme but congregations are free to apply to any of the [Heritage Lottery Fund programmes](#).

The Government's [Listed Places of Worship scheme](#), enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

Historic England supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. Our [advice web pages](#) help congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by Historic England, offers direct advice and encouragement to congregations. Projects to achieve repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

ARCHAEOLOGY

The continued excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites.

The large majority of the 19,853 scheduled monuments in England are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agri-environment grant schemes to best effect. This has been especially important under the Countryside Stewardship Scheme, where our advice has resulted in the removal of 32 sites from being at risk this year. Historic England, Natural England and local authority curators have collaborated on developing a web portal for the scheme which provides local advice to support farmers and landowner applications. Our work in partnership with Natural England on

agri-environment schemes has removed 801 scheduled monuments from the Register since 2009. We also continue to work closely with local trusts, volunteers and the Heritage Lottery Fund to identify the nationally important monuments for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register, affecting 38% of archaeological entries on it. The Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for all sites affected by arable cultivation on the Register. It provides bespoke recommendations for each monument, enabling cultivation to continue where it does not present a risk. It will also be an important tool for advising owners on the longer term management of their monuments as the existing ten year Environmental Stewardship agreements expire.

Although great progress has been made, analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth remains one of the most widespread causes of long-term damage to both urban and rural archaeological sites - even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key. The delivery of this will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the Register of Historic Parks and Gardens of Special Historic Interest in England in itself brings no additional statutory powers, instead it is used in the development control process to provide a valuable tool for the protection of the sites it includes. The Government's National Planning Policy Framework (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation.

The NPPF states that great weight must be given to the conservation of sites included on the Register of Historic Parks and Gardens of Special Historic Interest and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or held in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities.

Registered parks and gardens are typically large, complex heritage assets, many of them in multiple ownership. It can take years to identify and implement proposals to improve their condition and trajectory. To help reduce the risks, Historic England encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

BATTLEFIELDS

As with registered parks and gardens, the Register of Historic Battlefields brings no additional statutory controls to registered battlefields, but the NPPF makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II*, registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

Historic England continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal detecting.

Historic England also continues to encourage greater access to battlefields and the improvement of their amenity value and visitors' understanding of the impact these dramatic historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their

national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although Historic England has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close cooperation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long term survival. Practical advice on the management of historic wreck sites, whether at the coast edge or under water, is available from [Historic England](#).

CONSERVATION AREAS

Looking after conservation areas is a responsibility shared by those of us who live, work or do business in them, as well as those of us whose job it is to manage them or make decisions about their future.

The reasons conservation areas become at risk are difficult to address as they can cover large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and approaches to management.

Local authorities complete the Conservation Areas Survey, providing us with an understanding of what is particularly affecting the character and appearance of conservation areas, what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. Local authorities across the country continue to see their resources reduced, and this is making their task more difficult to deliver. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues.

Key statistics

BUILDINGS AND STRUCTURES

- Nationally, 840 (3.8%) of grade I and II* listed buildings (excluding places of worship) are on the Register. In the West Midlands the percentage is 4.4% (85 listed secular buildings).
- 8 building or structure entries have been removed from the 2016 West Midlands Register because their futures have been secured, and 2 have been added.
- 62.4% of buildings or structures (118) on the West Midlands baseline 1999 Register have been removed because their futures have been secured, compared with the national figure of 62.4%.

PLACES OF WORSHIP

- Nationally, 6.3% of listed places of worship are on the Register. In the West Midlands, 6.9% (101) are on the Register.
- 15 places of worship have been removed from the West Midlands Register following repair work, and 16 have been added.

ARCHAEOLOGY

- 2,480 (12.5%) of England's 19,855 scheduled monuments are on the Register. 165 (11.7%) of the 1,408 scheduled monuments in the West Midlands are on the Register.
- 11 archaeology entries have been removed from the 2016 West Midlands Register for positive reasons, and 2 have been added.
- 50.8% of archaeology entries (132) on the West Midlands baseline 2009 Register have been removed for positive reasons, compared with the national figure of 45.7%.

- Nationally, damage from arable cultivation is the greatest cause of risk affecting 38.3% of archaeological entries on the Register. In the West Midlands the proportion is 34.1%.

PARKS AND GARDENS

- 96 (5.8%) of England's 1,652 registered parks and gardens are on the Register. Of the 154 registered parks and gardens in the West Midlands, 8 (5.2%) are on the Register.
- No park and garden entries were added or removed from the 2016 West Midlands Register.

BATTLEFIELDS

- Of the 46 registered battlefields in England, 4 (8.7%) are on the Register. Of the 6 registered battlefields in the West Midlands, none are on the Register.

WRECK SITES

- Of the 52 protected wreck sites around England's coast, 4 (7.7%) are on the Register. There are no protected wreck sites in the West Midlands.

CONSERVATION AREAS

- 8,494 of England's 9,868 conservation areas have been surveyed by local authorities and 512 (6.0%) are on the Register. Of the 798 conservation areas in the West Midlands, 726 have been surveyed and 57 (7.9%) are on the Register.
- 3 conservation areas have been removed from the 2016 West Midlands Register for positive reasons and 4 have been added.

HISTORIC ENGLAND FUNDING

- £1.51 million in grant was spent on 32 entries on the West Midlands Register during 2016/17.

Risk assessments of heritage assets are based on the nature of the site. Buildings and structures include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

Publications and guidance

Historic England has produced the following publications relating to heritage at risk, including:

[Assessment of Heritage at Risk from Environmental Threat: Key Message](#) (2013)

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – [Historic England Research News 21](#), available online

[Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers](#) (2013)

[Heritage at Risk 2010 – Report](#) (2010)

[Heritage at Risk: Conservation Areas](#) (2009)

[Heritage at Risk 2017 – national summary leaflet](#) and [regional summary leaflets](#) for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire.

[Heritage at Risk Online Register](#) – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database.

[How to Assess the Condition of Historic Buildings](#) – an online introduction to assessing condition.

[Monuments at Risk \(2008\)](#) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire.

[Protected Wreck Sites at Risk: A Risk Management Handbook](#) (2008)

[Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings](#) (2016)

[Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing](#) (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit [Heritage at Risk](#) where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the [National Heritage List for England](#) online database. Further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites can be viewed at the same address.

GUIDANCE NOTES AND APPLICATION FORMS FOR GRANTS

[Historic England Grant Schemes](#) – online overview of all our current grant schemes, including the Repair Grants for Heritage at Risk scheme.

[Grants to Local Authorities to Underwrite Urgent Works Notices](#)

[Acquisition Grants to Local Authorities to Underwrite Repairs Notices](#)

[Repair Grants for Heritage at Risk](#)

CONSERVATION ADVICE AND GUIDANCE

The following publications are among the numerous guidance documents available for free on our website – [Historic England Advice](#).

[Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations](#) (2012)

[Conservation Area Designation, Appraisal and Management](#) (2016)

[Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment](#) (2008)

[Conservation and Management of War Memorial Landscapes](#) (2016)

[The Conservation, Repair and Management of War Memorials](#) (2015)

[Guidance on Constructive Conservation](#)

[Guidance on Improving Streets and Public Spaces](#)

[Guidance on Looking after Historic Buildings](#)

[Guidance on Looking after Historic Cemeteries and Burial Grounds](#)

[Guidance on Looking after Historic Parks, Gardens and Landscapes](#)

[Guidance on Looking after Places of Worship](#)

[Guidance on Protecting the Rural Historic Environment](#)

[Guidance on Tackling Heritage Crime](#)

[Heritage Works: a Toolkit of Best Practice in Heritage Regeneration](#) (2017)

[Latest Advice and Guidance](#) – this page highlights our most recent advice and guidance on a wide range of heritage-related topics.

[Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers](#) (2017)

[Metal Theft from Historic Buildings. Prevention, Response and Recovery](#) (2017)

[Practical Building Conservation](#) – revised ten-part series: *Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing, Glass & Glazing; Metals; Mortars, Renders & Plasters; Stone; Timber* (2012–2015)

[Pillars of the Community: the Transfer of Local Authority Heritage Assets](#) (2015)

[Post-War Public Art: Protection, Care and Conservation](#) (2016)

[Scheduled Monument Consents: A Guide for Owners and Occupiers](#) (2014)

[The Disposal of Heritage Assets: Guidance Note for Government Departments and Non Departmental Public Bodies](#) (2010)

[The Installation of Telecommunications Equipment, Including Broadband and Mobile, in Churches and Other Listed Places of Worship](#) (2017)

Key to the entries

The Register includes the following risk assessment types:

- Building or structure
(grade I and II* listed buildings, grade II listed buildings in London and structural scheduled monuments)
- Place of worship
(grade I, II* and II listed buildings)
- Archaeology
(scheduled monuments – earthworks and buried archaeology)
- Park and garden
(Registered parks and gardens)
- Battlefield
(Registered battlefields)
- Wreck site
(Protected wreck sites)
- Conservation area
(Conservation areas)

Details are given here for all risk assessment types even if entries are not present in the Regional Register.

ORDER

Entries are grouped and ordered alphabetically, first by County (dark grey bands) or Unitary Authority (light grey bands), and then by Local Planning Authority (National Park/Unitary Authority/District or Borough).

A blank band denotes the end of a county and the beginning of a unitary authority.

Sites that straddle more than one local planning authority are included under the lead authority.

Within each planning authority, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Parks and gardens
- Battlefields
- Wreck sites
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by parish, locality and street/site name (except for conservation areas and protected wreck sites which are ordered by site name only).

LISTING

The principal listing type is noted for each entry and includes:

- Listed Building (LB) grade I or II*
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Registered Battlefield (RB)
- Protected Wreck Site (PWS)
- Conservation Area (CA)

Other listing types that apply to a given site, including location within a World Heritage Site (WHS), are also noted.

If an entry is a dual list entry (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is a dual list entry with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site has dual list entries, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments), parks and gardens, battlefields and wreck sites) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established)

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration – in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens, battlefields, wreck sites and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented

For battlefields and wreck sites the following priority categories are used as a means of prioritising action:

- A No action/strategy identified or agreed (where trend is declining or unknown)
- B Action/strategy agreed but not yet implemented (where trend is declining or unknown)
- C No action/strategy identified or agreed (where trend is stable or improving)
- D Action/strategy agreed but not yet implemented (where trend is stable or improving)
- E Monitoring as appropriate (any trend)
- F Action implemented/strategy underway/scheme in progress (any trend)

Previous year priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries, parks and gardens, battlefields and wreck sites may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the Historic England local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

ABBREVIATIONS

CA	Conservation Area
HE	Historic England
HLF	Heritage Lottery Fund
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
PWS	Protected Wreck Site
RB	Registered Battlefield
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
HEREFORDSHIRE, COUNTY OF (UA)							
Herefordshire, County of (UA)	15	27	21	1	0	0	2
SHROPSHIRE (UA)							
Shropshire (UA)	25	21	42	0	0	0	1
STAFFORDSHIRE							
Cannock Chase	0	0	0	0	0	0	0
East Staffordshire	1	1	2	0	0	0	2
Lichfield	3	1	3	0	0	0	1
Newcastle-under-Lyme	3	0	1	0	0	0	0
Peak District (NP)	1	0	2	0	0	0	0
South Staffordshire	1	0	2	0	0	0	0
Stafford	2	0	3	0	0	0	3
Staffordshire Moorlands	6	2	2	0	0	0	2
Tamworth	1	0	0	0	0	0	0
STOKE-ON-TRENT, CITY OF (UA)							
Stoke-on-Trent, City of (UA)	6	3	0	0	0	0	5
TELFORD AND WREKIN (UA)							
Telford and Wrekin (UA)	2	2	5	0	0	0	0
WARWICKSHIRE							
North Warwickshire	9	1	5	0	0	0	0
Nuneaton and Bedworth	2	0	0	0	0	0	0
Rugby	0	0	9	1	0	0	0
Stratford-on-Avon	3	7	10	0	0	0	2
Warwick	3	2	7	2	0	0	0
WEST MIDLANDS							
Birmingham	10	6	1	0	0	0	9
Coventry	6	2	2	0	0	0	3
Dudley	1	5	2	0	0	0	4
Sandwell	2	0	2	0	0	0	2
Solihull	0	0	0	0	0	0	0
Walsall	0	2	0	0	0	0	6
Walsall / Sandwell [†]	0	0	0	1	0	0	0
Wolverhampton, City of	1	4	0	0	0	0	9
WORCESTERSHIRE							
Bromsgrove	1	4	0	1	0	0	1
Malvern Hills	3	5	3	1	0	0	1
Redditch	0	0	2	0	0	0	0
Worcester	2	1	0	0	0	0	1
Wychavon	5	5	6	1	0	0	0
Wyre Forest	3	0	0	0	0	0	3
TOTAL	117	101	132	8	0	0	57

[†] Sites that cross local planning authority boundaries

HEREFORDSHIRE, COUNTY OF (UA)



© Historic England

SITE NAME:	Gatehouse buildings at Wigmore Abbey, Grange, Adforton
DESIGNATION:	Scheduled Monument and Listed Building grade I, 2 LBs
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005359 and 1179921

The remains of a late C12 and C14 abbey. The Gatehouse comprises two buildings, one is without a roof and in very poor condition. Survey work to inform conservation is required. Structural assessment by Historic England in 2011 indicated that elements of collapse were likely, some collapse of the outer skin of stonework has since taken place.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Ruined Church of St Mary, Avenbury
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005356 and 1349633

A ruined C12 church. The tower stands to full height, the roof survived to the mid C20 but has fallen in. The walls of the nave and chancel are half collapsed and survive only to a few feet in places. Fragments of decorated interior plaster survive. Vegetation clearance has been carried out by the owners under a Historic England Management Agreement. The walls are generally stable but are highly exposed.

Contact: Bill Klempere 0121 625 6847



© Historic England

SITE NAME:	Belmont House, Clehonger
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1167079

Late C18 country house by James Wyatt, extended and remodelled by EW Pugin c1860. Some holding repairs have been carried out and the building is watertight. There are some areas of weathering and deterioration. Resolution lies in finding and funding an appropriate and sustainable solution for the building, this should be encouraged through the planning process.

Contact: Sarah Lewis 0121 625 6846



© Historic England

SITE NAME:	Clifford Castle, Clifford
DESIGNATION:	Scheduled Monument and Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001774 and 1167903

Ruins of a late C13 Marcher castle. A repair scheme has been developed with a Historic England Repair Grant for repairs to the motte and gatehouse following earlier fencing and propping to some of the remains in 2013. Vegetation clearance and masonry consolidation works are now ongoing and due to complete in the second half of 2017.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Craswall Priory ruins, Craswall
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	E (D)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1014536 and 1342128

The remains of one of only three Grandmontine houses in England dating from 1220 to 1225. The severely exposed position has contributed to the priory's decline. An Historic England Management Agreement previously addressed management of vegetation and urgent repairs to the piscina. Further consolidation and the repair of exposed and deteriorating architectural details have been undertaken within a new Natural England stewardship scheme. Much of the fabric remains vulnerable and a future phase of repairs is planned.

Contact: Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Huntington Castle, Huntington
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1002939 and 1157544

Castle remains C13 or earlier. The motte and inner bailey are surrounded by a ditch and outer bailey. Traces of a curtain wall and C13 semi circular tower have survived in a fair condition although they were very overgrown. Work to control vegetation is being carried out by the owner and a new access track has been created. Unstable stonework needs consolidating following unsuccessful attempts to secure funding for the site via environmental stewardship schemes.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Lyonshall Castle, Lyonshall
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1001720 and 1301287

C13 keep enclosed by inner bailey and outer enclosures. The owners are undertaking maintenance of the earthworks in accordance with Historic England advice. Much vegetation control has been carried out. A survey was carried out to inform masonry repair and consolidation. The first phase of which was completed in late 2016, facilitated by an Historic England Management Agreement. A second phase is planned for the keep and remaining sections at risk.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Outbuilding east of Marstow Court (formerly listed as the Granary at Marstow), Marstow
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1214715

Reputedly associated with manor of the Knights Hospitallers who held lands in Marstow and probably originally a house, C15. Built of sandstone rubble under a Welsh slate roof with C18 and C19 alterations. The building is now in agricultural use. The stonework and pointing are generally in poor condition, there are slipped and missing roof slates and the windows and doors are in poor condition. A scheme for conversion was approved several years ago, but works are yet to take place.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Barn and attached cowhouse built onto Glibes Farmhouse, Michaelchurch Escley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1223446

A four bay barn with an extra bay for a cow house, and further loft bay linking to farmhouse which has collapsed. Probably C18 in date. A temporary metal sheet roof protects the building which is unused and in need of comprehensive repair. The owner has no proposals for the repair of the building, and its future is uncertain.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Glibes Farmhouse, Michaelchurch Escley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1223549

A remote farmhouse probably C17 with C18 alterations. The walls are of thin coursed rubble stone. The roof was of stone tiles but has been temporarily replaced in metal sheet. The building is unoccupied and in need of comprehensive repair. A programme of urgent works including repair of the temporary roof and rebuilding of fallen masonry has improved its condition but the chimney stacks are deteriorating and further long term repairs are necessary.

Contact: Rhodri Evans 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Urishay Castle, Peterchurch
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014547 and 1099487

Remains of C12 motte castle, a ruined C17 house and a partly ruined C16 chapel. The chapel is stable and in good condition, the C17 house is not. Without a roof the masonry is disintegrating. Lintels are failing and in danger of collapse. An assessment of the structure to establish the survival of medieval fabric and development of a strategy are required.

Contact: Bill Klemperer 0121 625 6847



© Historic England

SITE NAME:	Snodhill Castle, Snodhill, Peterchurch
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1015168 and 1172756

Snodhill Castle was a key element in the Norman line of defence through the English and Welsh Marches. Ownership of the site has now transferred to the Snodhill Castle Preservation Trust. A Historic England Repair Grant has been awarded for recording and consolidation of the remains including the motte, gatehouse and bastion walls. A further Historic England Management Agreement is also in place to tackle the wider scrub issues and erect fencing. Both grant aided projects are now on site with vegetation clearance and masonry consolidation due to be completed during the second half of 2017.

Contact: Sarah Lewis 0121 625 6846



© Historic England

SITE NAME:	Court Farmhouse, Preston Wynne
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1099380

A former hall house dating from the C14 which retains a spere truss and cruck truss of high architectural quality. This building is now used for storage with residential accommodation in the later C17 house which was added to the south end. Grant aid achieved essential stabilisation and roofing works but the condition of the building continues to decline.

Contact: Sarah Lewis 0121 625 6846



© Historic England

SITE NAME:	Post-Medieval house at Willey Court, Willey
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1017251

This monument includes the buried, earthwork and upstanding remains of the post-medieval house and gardens at Willey Court. The owners are in negotiations with Historic England to determine an appropriate strategy for consolidation and management of the site, following on from previous successful agreements. Countryside Stewardship was being considered to facilitate repairs to the remaining stonework but the site is not eligible for the current Natural England scheme.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Church of St Andrew, Wolverlow
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1217197

Early C12 church restored in 1863 by Kempson. Of stone construction under a clay tile roof with timber framed tower and shingle spire. The church has not been used for worship since 2006 and sits in an isolated location. Rainwater goods are absent and the roof has slipped and broken tiles. A sale has now been agreed by The Church Commissioners and a proposal for re-use as a dwelling has been approved but not implemented.

Contact: Sarah Lewis 0121 625 6846

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, Abbey Dore, Abbey Dore
DESIGNATION:	Listed Place of Worship grade I, SM
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099794

Large parish church created in c1634 from the derelict Abbey church of the dissolved Cistercian Dore Abbey. The c1220 transepts crossing and chancel remain with a C17 tower inserted on the south east angle of the crossing. There are repair issues with the roof and drainage from this tower as well as the sandstone ashlar walling. The sandstone slates of all the main roofs have been renewed except the north transept chapel roof which still has the original slates. These have failed and are leaking and need urgent re-slating.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, Birley, Birley with Upper Hill
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081970

Small parish church in a large level churchyard in the middle of a scattered village. C12 and C13 nave and chancel and late C14 south chapel. The west tower is c1200. Heritage Lottery Fund and Historic England Repair Grant for Places of Worship funded repairs in 2004 have remedied tower roof problems and the stonework to the chancel and vestry. However the sandstone rubble stonework is still poor on the tower and south chapel gable.

Contact: Chris Miners 0121 625 6835




© Historic England

SITE NAME:	Church of St Michael, Brampton Abbots, Brampton Abbots
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099258

A small rural C15 parish church. The sandstone roof slates over the nave and chancel are in a poor condition with water ingress causing falls of ceiling plaster. The building is currently closed for worship. However, the Churches Conservation Trust Regeneration Group is working with the Brampton Abbots Regeneration Group to develop new uses for the building, alongside worship. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2016 and project development is underway.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Barnabas, Brampton Bryan
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1179943

Small rural parish church notable for its construction during the Civil War Commonwealth. Still Gothic in style it incorporates a double hammerbeam trusses roof which creates a large hall space to house the traditional church spaces of nave and chancel. The tiled roof has come to the end of its life and urgent repairs are needed to limit the harm to the roof structure.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Chapel at Brockhampton Park, Brockhampton
DESIGNATION:	Listed Place of Worship grade II*, RPG grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1349630

Tiny chapel in the grounds of Brockhampton Park. Built in 1798 by Byfield in the Gothic Revival style of a nave and west tower. Grey sandstone ashlar with battlemented parapets on the 'show' sides but coursed rubble and conventional eaves to the north. Structurally deflected slate roof. The ashlar stone mouldings are heavily eroded.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Peter, Bromyard, Bromyard and Winslow
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1307758

Large medieval civic church in the centre of Bromyard. The 2006 and 2011 Quinquennial Inspections identified stonework and roof repairs as necessary. The roof valleys and slate roof have now been repaired with a Listed Places of Worship Roof Repairs Grant in 2016. A leaking flat roof to the vestry still needs repair.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St James, Cradley, Cradley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1082298

Large parish church of sandstone with tiled roofs. Large west tower, six bay nave and lower chancel mostly C14 with north aisle added in 1869. The tower needs roof and masonry repair. The north aisle floor has structural faults due to timber decay. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2016 and the project is being developed.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Mary, Craswall
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1078203

Small rural parish church. Continuous nave and chancel with belfry and south entrance porch. Sandstone slate roofs with Welsh slate to the north pitch. Sandstone rubble walls partly rendered with sandstone ashlar window tracery. Timber boarded belfry. The walls have severe open jointing, structural cracking and the render is falling. The roof slates are failing. The rainwater goods have part fallen.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Michael, Croft Park, Croft and Yarpole
DESIGNATION:	Listed Place of Worship grade I, RPG grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1166506

Small parish church set next to Croft Castle on a National Trust site. Small sandstone rubble nave and chancel with a slate roof mostly from a 1515 rebuilding. The west end was remodelled in late C17 with an ogee capped cupola. The cupola leadwork has fallen off and been neatly replaced with a temporary felt covering. However, the felt has a short lifespan and urgent replacement of the lead is still required.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Chapel of St Silas, Bollingham, Eardisley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1157325

Small chapel of three bays, and a nave and chancel. Rebuilt between 1865 and 1867 with the addition of south porch and bellcote. The nave roof is C14 and the roof is covered with sandstone slates. These are heavily overgrown with moss and ferns, decaying the slates. Holes have appeared in the slates covering both roof pitches. The interior is netted to catch falls of plaster from the roof lining.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St John the Baptist, Upper Road, Eastnor, Eastnor
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I266756

Large parish church. Rebuilt by GG Scott in 1852, with the exception of the C14 west tower, C13 arcade and C12 south doorway. Generally sandstone ashlar in the C13 style and with tiled roofs. The sandstone ashlar of the tower is in poor condition with cracking, erosion and open jointing.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Giles, Goodrich, Goodrich
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I157263

Grade II* parish church in the centre of a small village. C13 core, a mid to late C14 slim west tower with a tall spire, north aisle, south porch and chancel. Altered and restored in the late C19 with addition of the organ chamber. Major damp ingress problems which need urgent repairs to prevent further deterioration of the external stonework and the internal decay of the timber floors. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2016 and repair work is underway.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St John the Baptist, Grendon Bishop, Grendon Bishop
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I307407

Parish church built in the 1780s which now looks Victorian in character. The church has severe damp problems and slipped tiles are allowing water into the chancel.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Dubricius, Hentland, Hentland
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I288593

Small rural parish church with C11 vestiges, and a C13 and C14 nave and chancel. Restored by JP Seddon in 1853 with C19 vestry and porch. The late C14 tower has structural cracking on the west side. Internal plaster has fallen in the nave and from the chancel west end roof. The sandstone rubble walls are heavily eroded. The sandstone slate roof pitches and the plain clay tiled pitches have slipped or are missing slates and tiles. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2016 and project development is underway.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, St Peter's Square, Hereford, Hereford
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I196883

Large urban parish church in the city centre of Hereford. A C13 tower and four bay arcade, chancel and south chapel, all dating to c1300. Extensively rebuilt by Thomas Nicholson between 1880 and 1885. The valley between the nave and north aisle leaks and the south pitch slate roof needs urgent renewal.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, Hope under Dinmore, Hope under Dinmore
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1301623

Small but lengthy parish church on a hillside setting next to the A49. Heavily restored by Kempson in 1877 and 1896, with the small west tower and north chapel still retaining C12 and C13 fabric. The north chapel gable has structural movement and the cast iron gutters are cracked, rusting and leaking. The tower sandstone rubble is heavily eroded.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Andrew and St Mary, How Caple, How Caple
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1166452

Parish church in a hillside setting overlooking the River Wye. C14 chancel with a later low pitched roof. The tower, nave and chancel date to between 1693 and 1695, and the windows are C19. The rainwater goods are undersized and failing. The ashlar stonework of the tower is delaminating and falling. The parapet stonework of the tower is structurally unsound next to the tower access door.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Mary, Kings Pyon, King's Pyon
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1179970

Rural parish church set on an elevated tump. Sandstone walls with both tiled and stone slate roofs. Cruciform in plan, including a C12 nave, C13 south transept, C14 chancel and tower and a C19 north transept and porch. The main problems are subsidence in the north transept, damp in the south walls, deteriorated stone window mullions, and the lead roof over the organ chamber. A Heritage Lottery Fund Grant for Places of Worship was awarded for the repairs in 2015 and project development has been completed.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St James, Kinnersley
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1157630

Sandstone parish church predominantly of the C13 and C14. Noted for a late C19 decorative scheme by GF Bodley. The church is in regular use but the roofs, particularly to the north, are heavily overgrown with mosses and fern growth. The interior showed significant signs of damp, possibly associated with the poor condition of the roof. This is affecting much of the C19 decoration.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Matthew, Marstow
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1288414

Small Victorian rural parish church of nave chancel and porch. Sandstone and limestone dressings. The stone work of the south and east walls is decaying badly. A Heritage Lottery Fund Grant for Places of Worship was awarded for the repairs in 2017.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St James, Ocle Pychard
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1276199

Rural parish church. Coursed rubble walled continuous nave and chancel and partly integral west tower with a leaded broach spire. C19 decorative clay tile roof slopes are in very poor condition and need reroofing. The rainwater goods are inadequate and in poor condition, as are the surface water drains. There are low level open joints to the external walls and some damage to dressed stonework.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter, Pipe and Lyde, Pipe and Lyde
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1172739

Small parish church set at the end of a village and facing the A49. Late C12 nave and C14 chancel largely rebuilt by F Kempson in 1874 who also added the broach spire to the C13 tower. The roof needs repair and work is also needed to the tower. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship was awarded in 2012 to enable repairs but works are yet to begin.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Andrew, Pixley, Pixley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1098989

Small single cell rural parish church in a farmyard setting. C13 core with C14 chancel and roof. The integral bellcote is C19 with C17 windows. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship aided project repaired the roof, bellcote and rainwater system. However, structural instability needs repair in the north east corner, as well as the timber framed entrance porch.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of the Holy Trinity, Preston Wynne
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1302088

Small isolated parish church. C18 single cell nave/chancel with west tower. Coursed and dressed sandstone walls with plain clay tile roofs. The east, south and tower walls require repairs, including bedding copings, pointing, grouting and repair to stone work. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2016 and project development is underway.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Mary, Staunton on Wye, Staunton on Wye
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1166457

Large rural parish church high in a hillside village overlooking the River Wye. The nave has a C12 core, the west tower is C13 and the chancel and porch date from C18. The hipped tiled roof has holes and the nave sandstone slate roof has slipped slates. The gutter on the north side has failed. The internal plaster is damp affected and part fallen. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2016 and is being developed.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, Stoke Edith, Stoke Edith
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099825

Large parish church, rebuilt by the Foleys of Stoke Edith Park in 1740 in the Palladian style by Henry Flitcroft. The C14 tower with truncated spire was retained. The roof leaks, causing rot in the nave beam and falls in the ornate plasterwork. The ashlar stone facings are eroding severely. A few stones have fallen from the tower and spire.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Peter and St Paul, Church Road, Weobley, Weobley
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1301343

Large parish church at the edge of the village of Weobley. C13 nave and flanking aisles with C14 chancel extension and north west tower. There is currently no solution to the problem of flaking sandstone ashlar on the tower and spire, however it is being managed by high level metal guards and ground level fencing.

Contact: Chris Miners 0121 625 6835

SITE NAME:	Dinedor Camp, Dinedor	LIST ENTRY NUMBER:	1001758
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	Yes
PRINCIPAL VULNERABILITY:	Scrub/tree growth	CONTACT:	Bill Klemperer 0121 625 6847
OWNER TYPE:	Other not for profit group		

SITE NAME:	Blackfriars Friary, preaching cross and cemetery, and hospital and chapel of St John in Hereford, Hereford	LIST ENTRY NUMBER:	1010797
DESIGNATION:	Scheduled Monument, 3 LBs, part in CA	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	Yes
PRINCIPAL VULNERABILITY:	Natural erosion - localised/limited	CONTACT:	Bill Klemperer 0121 625 6847
OWNER TYPE:	Local authority		

SITE NAME:	Promontory fort on Dorstone Hill, Dorstone	LIST ENTRY NUMBER:	1014544
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Scrub/tree growth	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Private		

SITE NAME:	Roman settlement, Ford and Stoke Prior / Humber	LIST ENTRY NUMBER:	1005322
DESIGNATION:	Scheduled Monument	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Arable ploughing	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Private		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Moated site 360m north of Joanshill Farm, Fownhope / Mordiford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019853
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Unknown	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Bowl barrow 460 metres south of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014103
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Ring ditches and rectilinear enclosures east of Tupsley, Hampton Bishop		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005348
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Row Ditch (entrenchment), Hereford		
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001780
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Bowl barrow 490 metres south east of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014112
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Huntington Castle, Huntington		
DESIGNATION:	Scheduled Monument and Listed Building grade II	LIST ENTRY NUMBER:	1002939 and 1157544
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Bowl barrow 550 metres south east of Milton Cross, Pembridge		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1014895
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Kingsland Castle, Kingsland		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1007318
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Offa's Dyke: section north west of Holme Marsh extending 615 yards (560 metres) to the railway, Lyonshall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001735
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	North Herefordshire Rowe Ditch, Pembridge / Staunton on Arrow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005382
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Shell keep castle and associated fishponds at Snodhill, Peterchurch		
DESIGNATION:	Scheduled Monument and Listed Building grade II*	LIST ENTRY NUMBER:	1015168 and 1172756
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Sarah Lewis 0121 625 6846
SITE NAME:	Sutton Walls (camp), Sutton / Marden		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001747
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Dumping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Roman fort at Coppice House, Tedstone Wafer		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005363
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Wall Hills Camp, Thornbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001748
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Motte and bailey, west of St Mary's Church, Walterstone		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001778
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Roman town of Ariconium, Weston under Penyard		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005364
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Offa's Dyke: Upperton Farm, two sections extending 195 yards (180 metres) and 370 yards (340 metres) south from Yazor, Yazor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001736
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827



© Historic England

SITE NAME:	Shobdon	Early C18 formal gardens (much modified) and mid-C18 landscape park, part of which is open to the public. Although some garden buildings survive, their context is much altered; commercial fruit growing, a caravan park, a chicken farm, commercial forestry and intensive agriculture characterise the historic park. Recent improvements include new estate railings and repairs to historic walls.
DESIGNATION:	Registered Park and Garden grade II, 10 LBs, 3 SMs	
CONDITION:	Extensive significant problems	
VULNERABILITY:	Medium	
TREND:	Stable	
NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000894	Contact: Kim Auston 0117 975 0696

SITE NAME:	Kington		
DESIGNATION:	Conservation Area, 124 LBs, SM	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Matthew Knight (LPA) 01432 260321

SITE NAME:	Ross-on-Wye, Ross-on-Wye / Bridstow		
DESIGNATION:	Conservation Area, 153 LBs, 4 SMs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Matthew Knight (LPA) 01432 260321

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SHROPSHIRE (UA)



© Historic England Archive

SITE NAME:	Wattlesborough Castle (uninhabited parts), Alberbury with Cardeston
DESIGNATION:	Scheduled Monument and Listed Building grade I, part in LB grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1006285 and 1366883

Remains of a large square tower of castle with fine quality detailing, now without roof. Probably late C13 for Sir Robert Corbet. The wall heads are particularly vulnerable, some blocks of masonry have fallen from high level. The owner is considering consolidation and re-roofing for domestic use.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Alberbury Castle, Alberbury, Alberbury with Cardeston
DESIGNATION:	Scheduled Monument and Listed Building grade II, 2 LBs, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1020662 and 1175344

Remains of tower keep from C13 castle. Rapidly eroding with rampant ivy cover and mortar erosion and undermined masonry. A survey was commissioned by Historic England as a basis for designing a programme of urgent repair works for discussion with the owner. Natural England funding may be available via an existing Stewardship scheme.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Barn to west of Hall Farmhouse, Aston Eyre
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1053205

Used as a barn for many years, this building is in fact a medieval hall with a solar wing and dates from the C15. Consent has been given for conversion back to residential use. The owner is carrying out repairs and has undertaken a detailed recording of the stonework. Structural repairs have been carried out. Further works to the roof, windows and doors are planned.

Contact: Steven McLeish 0121 625 6884



© Historic England

SITE NAME:	48 Mill Street, Bridgnorth
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1177762

This three storey building, c1675, forms part of a commercial premises used as an antique centre. The oldest building fronting the road was in poor condition but extensive repairs have been completed with the benefit of funding from Historic England. Some repairs to the return elevation of the building range immediately behind the front remain outstanding. The front range of the property is still vacant, but the owners have plans for re-use. The building will no longer be at risk when it is once more re-occupied.

Contact: John Tiernan 0121 625 6839



© Historic England Archive

SITE NAME:	Rockley Farmhouse, Chirbury with Brompton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1054405

Early C17 farmhouse with mid C20 alterations. The farmhouse is run-down but watertight. It is in need of basic repair and maintenance work.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Trinity Hospital, Hospital Lane, Clun
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (non-heritage)
LIST ENTRY NUMBER:	I054455

Known as The Hospital of the Holy and Undivided Trinity, these almshouses were founded in 1607 by Henry Howard, Earl of Northampton and built in 1618. A Warden's house and chapel were added in the second half of the C19. Parts of the perimeter wall, which incorporates a mortuary, are in very poor condition and some sections have collapsed. Large parts of the wall are colonised by vegetation and saplings which threatens further instability and loss of integrity. A Historic England Repair Grant for project development to quantify the repair works was accepted in 2016.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Old Hall and attached garden wall, Old Marton, Ellesmere Rural
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	I307787

Large farmhouse, mid to late C16 with later additions and alterations. Timber framed with painted brick and rendered infill. The owner has repaired the roof and repairs to the timber frame and infill panels have commenced. The adjoining C18 garden wall, of red brick with moulded stone coping, has partially collapsed.

Contact: Steven McLeish 0121 625 6884




© Historic England

SITE NAME:	Ludlow town walls, Ludlow
DESIGNATION:	Scheduled Monument and Listed Buildings - 8 grade II, 2 CAs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	I006278 and I219038; I289747; I291656; I202827; I202825; I202826; I219077; I282007

Medieval town walls in multiple ownership. Historic England has helped to fund a town walls management plan and the repair of substantial sections in local authority ownership. A Town Walls Trust has been established to promote the protection and care of the walls. A major section of wall below the parish church collapsed in spring 2013, Historic England has advised the Town Council on repairs. Other small collapses have taken place on the east and west sections. Issues relating to ownership and liability remain to be resolved which has delayed repair works being planned and implemented.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Remains of Lea Castle at Lower Lea Farm, Lea, Lydham
DESIGNATION:	Scheduled Monument and Listed Building grade II, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	I021064 and I054509

This monument consists of fragmentary remains of a C12 castle surviving in the middle of a working farm. This was formerly a castle of the Bishops of Hereford. A Victorian house abuts the castle remains which are heavily overgrown. There is an urgent need to reduce ivy growth, to be followed by repair and consolidation of the masonry. An application for Historic England grant aid was encouraged more than three years ago but nothing has been submitted to date.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Charllotte Furnace, Neenton
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	I004785

C17 blast furnace for the manufacture of pig iron from ironstone, using charcoal as fuel. A relic of the long extinct local iron industry. There are structural problems and areas of unconsolidated masonry in need of long term repair. Temporary propping has been carried out and Historic England Management Agreements have been used to control vegetation but a longer term repair solution is needed.

Contact: Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Pentre Isaf, Oswestry
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1054276

Pentre Isaf is a farm complex with an attractive courtyard of outbuildings. The grade II* stone farmhouse is C17 but hides within it a C15 timber framed hall. The owner is making good progress with a comprehensive programme of repairs.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Pitchford Hall, Pitchford
DESIGNATION:	Listed Building grade I, RPG grade II
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1177907

A large timber framed country house built c1560-70 for Adam Ottley but with an earlier C14 or C15 core. This is an outstanding example of a timber framed building. Shropshire Council had undertaken a condition survey in preparation for enforcement action. The property has now been sold and the new owners are embarking on a project of repairs with the aim of restoring part of the building as a family home and to convert further wings as holiday accommodation.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Brogyntyn Hall, Brogyntyn Park, Selattyn and Gobowen
DESIGNATION:	Listed Building grade II*, RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1367373

An elegant county house, mainly C18 extended in the C19; most of the interior is of this date. The property stands at the centre of the grade II park with pleasure grounds, a walled garden, lodges, cottages and model farm. Last used as offices the property has been out of use for over a decade. Planning permission for an enabling development of housing in the grounds has been permitted to secure the repair of the hall subject to a Section 106 agreement. Repairs to the hall have commenced and the building is currently scaffolded.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Ditherington Flax Mill: Cross Building, Shrewsbury
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1428700

Originally built in c1799, the cross building was rebuilt in c1812 after a fire. It comprises four storeys. The cast iron frame represents the rapid development of the use of this material for fire-proofing in the first decade of the C19. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. Funding has been secured for the first phase and works are underway; this building will be repaired in a later phase of works,

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Ditherington Flax Mill: Apprentice House, Shrewsbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1254855

Former apprentice house for the Flax Mill c1812, now mothballed. Historic England is working in partnership with the local authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. Work has commenced on the first phase of works, and this building will form a part of a later phase.

Contact: Nick Molyneux 0121 625 6857

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Ditherington Flax Mill: Flax Warehouse, Shrewsbury
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1428731

Built c1810 as part of the mill's expansion, it comprises nine bays, four storeys and an attic. The cast iron frame represents the rapid development of the use of this material in the first decade of the C19. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. Funding has been secured for the first phase and works are underway; this building will be repaired in a later phase.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Ditherington Flax Mill: Spinning Mill, Shrewsbury
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (B)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1270576

Former flax mill with five storeys, built in 1797 as the first iron frame structure in the world. Converted to maltings in 1897. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. A masterplan for the site was approved in 2010. Funding has been secured for the first phase of works and the building is now being repaired.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Ditherington Flax Mill: Stove House and Dye House, Shrewsbury
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Government or agency
LIST ENTRY NUMBER:	1270566

Former drying stove house and dye house of flax mill, now disused. These buildings are an early and significant component of the flax mill complex. Historic England is working in partnership with the local authority. Outline planning approval was secured for the whole site in 2010, and this will form the basis of the masterplan and future redevelopment proposals. Funding has been secured and the first phase of repairs is underway; this building will be tackled in a later phase.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Hawkstone Windmill, Hawkstone Park, Weston-under-Redcastle
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1264219

Late C18 windmill located just outside the registered park at Hawkstone Hall which was designed by William Emes in the mid C18. The windmill sits above the Hawk Lake in the part of the park which is now a golf course and benefits from extensive views. The building is boarded up; internal machinery and floor structures have largely collapsed though principal floor beams survive. A temporary roof erected in 1996 has saved the building but its condition is deteriorating.

Contact: Jez Bretherton 0121 625 6855



© Historic England Archive

SITE NAME:	Red Castle, Hawkstone Park, Weston-under-Redcastle
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1020850 and 1237180; 1264271

The standing remains of a C12/C13 medieval castle in a largely restored C18 landscape. Recent research suggests that the remains were significantly adapted as part of the designed landscape which includes the adjacent Hawkstone Follies. The masonry is in vulnerable condition and deteriorating. Invasive vegetation needs to be brought under control. A management plan for the site has been completed and its recommendations will be implemented as appropriate.

Contact: Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	The Old Rectory, Claypit Street, Whitchurch Urban
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1056008

An elegant Georgian rectory of 1749 which was used as a listening station during World War II. Urgent works were undertaken to make the roof watertight and halt structural movement but the service wing remains in very poor condition and property boundaries are an issue. Section 106 contributions have been secured for the repair of the building. The owner has undertaken urgent works, cleared debris from the building and is exploring options for re-use.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Cheney Longville Castle, Cheney Longville, Wistanstow
DESIGNATION:	Listed Building grade II*, SM, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1269816

A fortified manor house complex dating from 1677 set around a courtyard. The north wing is in use as a farmhouse and in fair condition but the rest of the buildings around the courtyard are only partially in use and are in a vulnerable condition. Long term plans for a mixed use conversion to holiday accommodation and heritage interpretation have not yet been implemented. Emergency repairs have been carried out with Historic England grants and roof repairs completed under a Natural England stewardship scheme.

Contact: Jez Bretherton 0121 625 6855



© Historic England

SITE NAME:	Hargreaves Farmhouse, Winnington, Wollaston
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1051173

Timber framed farmhouse dating from early C17 with C19 additions including a stone extension. The property has been unoccupied for over 20 years and is very dilapidated. The roof has holes, many infill panels are missing and parts of the frame have collapsed. The erection of scaffolding has provided support and a temporary roof so that the structure is protected and dry. The property is currently for sale.

Contact: Steven McLeish 0121 625 6884



© Historic England

SITE NAME:	Snailbeach New Smeltmill, Worthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1017764 and 1307989; 1055031

The monument comprises a smelt mill and slag mill built in 1862 for the Snailbeach Mining Company. The slag mill has been stabilised but standing remains of the smelt mill furnaces are in very poor condition due to invasive uncontrolled vegetation. Extensive vegetation clearance and emergency propping has been carried out under an Historic England Management Agreement.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Candle House, Snailbeach Lead Mine, Worthen with Shelve
DESIGNATION:	Scheduled Monument and Listed Buildings - 10 grade II, LB grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014866 and 1261135; 1055011; 1055012; 1176609; 1176636; 1176648; 1176660; 1366969; 1367007; 1055013

This building is part of the scheduled site of the Snailbeach Lead Mine and was where miners collected their candles before going underground. It dates from the early C19 and is constructed from coursed rubble with brick dressings under the remains of a Welsh slate roof. The walls are substantially intact, but the roof has collapsed and the building is derelict. Subject to the owner's agreement, it is hoped that the building may be acquired by the Shropshire Mines Trust and reunited with the other mining structures which have already been restored with grant aid.

Contact: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Church of St Margaret, Acton Scott
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383212

Although a medieval church consisting of a nave with a lower chancel and a west tower, subsequent additions have included an C18 south porch and a C19 north chapel built for the Stackhouse family of Acton Scott Hall. This addition has a fine Gothic plaster ceiling with ornate rib vaulting and square bosses but is at risk due to the poor condition of the hipped slate roof above it. The chancel slate roof covering is also failing, the rainwater goods to both roofs require repair and the surface water drainage system needs modification, if not complete renewal.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary, Bitterley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383652

Late C13 church consisting of a nave, chancel and west tower, heavily restored by Thomas Nicholson between 1880-88. He added the timber south porch and the timber framed top stage of the tower and its short broad shingled spire. All of the roofs, cast iron rainwater goods and spire coverings are failing and require renewal. The surface water drainage system is largely ineffective and also needs to be replaced. Limited high level masonry repairs are also required. An application to the Heritage Lottery Fund Grants for Places of Worship scheme was unsuccessful in 2017.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary, Cleeton St Mary, Bitterley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383665

This church was built in 1876-8 and designed by Thomas Nicholson. It consists of a chancel with a lean-to north vestry and a nave with a tower built into its west end. Recent repairs to the north slope of the chancel and an assortment of construction defects have confirmed that the original roof coverings are failing and require stripping and relaying. All roofs are of the same date and so should be considered equally suspect. Cast iron rainwater goods require overhauling, if not complete renewal, as does the existing surface water drainage installation.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Parish Church (dedication unknown), Boraston
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383416

This C12 church was mostly rebuilt between 1884 and 1887 by Henry Curzon at the expense of Lord Northwick of Burford House. Built as a chapel of Burford, it consists of a nave with a west tower and shingled spire, a south porch and an apsidal chancel. Differential settlement has occurred at the east end of the church and is thought to be the result of ineffective surface water drainage. Parts of the plain clay tile roof coverings need attention and the oak shingle covering to the spire requires renewal.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Collegiate Church of St Mary Magdalene, Bridgnorth
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1374848

The church of St Mary Magdalene was built in 1084-6. The original chancel survives as does the north west corner of the C11 nave but this was subsequently rebuilt in 1714 when the west tower was also added. Both were designed in a decorated Gothic style as were the south aisle and porch which were added in 1857. The crown of the tower roof is defective and parts of the roof structure are rotten: timber repairs and re-roofing is required and makes the case for parapet gutter renewal. Extensive masonry repairs are also required to the tower pinnacles, parapet and bell stage.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St George, Church Street, Clun
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I367257

The C12 church of St George consists of a nave with same height chancel, north and south aisles, a north porch and a west tower of several stages. The body of the church sustained damage during the Civil War and was virtually reconstructed by GE Street in 1877. Roofs re-laid in the C19 are now failing and recently sustained storm damage has created a greater urgency to address roof repairs. An application to the Listed Places of Worship Roof Repair Fund to relay the south side roof slopes to the aisle, nave and chancel was made in 2016 but was unsuccessful.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Peter, Coreley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I383711

This church has a C13 unbuttressed west tower with a later shingled broach spire. Both the nave and lower chancel were rebuilt in C18 in brickwork on the former medieval footprint. Roofs are steeply pitched with plain clay tiles which appear to be almost time-expired, along with most of the rainwater goods. Ineffective drainage and/or roof leaks are responsible for the deteriorating condition of the vestry plasterwork.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Giles, Farlow
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I188651

The church of St Giles was built in 1857-8 and consists of a nave with a west end bellcote and a lower chancel with a north side vestry and a south side porch. With the exception of the south slope of the nave, all other roof slopes are failing and will require relaying in the near future. Plaster infill ceiling panels to the exposed roof structures are potentially unstable and their renewal should be considered as part of a comprehensive re-roofing scheme. Rainwater goods require increased capacity, together with a new surface water drainage system.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary, Highley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I188722

Although the nave and lower chancel of this church are Norman in origin, the addition of the west tower and other later alterations and insertions suggest that most of the existing building fabric dates from C15 and later. The church was restored in 1881 by Poultney Smith but the tiles covering the tower roof, the lead lined parapet gutter and areas of the tower staircase masonry are now either failing and/or require assorted repairs to address significant defects. An application to the Heritage Lottery Fund Grants for Places of Worship scheme was unsuccessful in 2017.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St John the Baptist, Church Street, Ightfield
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I366502

The C15 church of St John the Baptist consists of a nave with a west tower and a south porch, a north aisle and a chancel. Designed in Perpendicular Gothic with crenellated parapets, multi-stepped buttresses and decorative finials, it is constructed in grey ashlar stone and has steeply pitched roofs covered in plain clay tiles. The tower roof coverings and parapet gutter linings are time-expired and require complete renewal. Assorted high level masonry repairs to the tower are also needed. The existing surface water drainage installation is ineffective and requires complete renewal.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of the Holy Trinity, Minsterley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1055228

Built as a chapel of Westbury between 1688-9, the church consists of a nave and chancel in one with a west end bellcote and a south porch. The use of classical and baroque elements, the extensive use of brickwork, raking buttresses without offsets and a steeply pitched tiled roof, creates an attractive if unusual composition. The use of Portland cement based mortar in conjunction with soft red bricks and Grinshill ashlar is causing the masonry to decay at an accelerated rate. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2016.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Bartholomew, Moreton Corbet and Lee Brockhurst
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1307235

This C13 church consists of a nave and west tower, a chancel, south aisle and squire's pew. The church has steeply pitched plain clay tile roofs and walls of fine yellow grey Grinshill ashlar. Although most of the roofs are in good order following repair works completed in 2013, the tower roof covering requires complete renewal as does the south slope of the south aisle and squire's pew. Extensive repointing of the tower walls and other areas of low level walling is required. Structural movement at the west end of the aisle requires monitoring as well as a new surface water drainage system.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St John the Baptist, Nash
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383565

This C13 church with a nave and chancel under one continuous roof and west tower was built in a single phase of works. Built as a chapel of Burford, it was given a broached spire in the C14 and a north aisle in 1865. The nave roof structure also dates from C19. Sections of the plaster infill panels between the rafters have started to become detached and fall to the floor without warning. The nave, chancel and north aisle roofs are all affected. Parts of the north aisle timber floor have failed due to damp conditions and the spire timber cladding requires renewal.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Abbey Church of the Holy Cross, Abbey Foregate, Shrewsbury
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1246392

The parish church of the Holy Cross was formed by the nave and west tower of the former Benedictine Abbey Church. C17 and C19 additions explain the present configuration and appearance of the church which was constructed in red sandstone. There are assorted defects associated with the variable quality of some of the particular building stones used. Parts of the chancel and transept parapets are in urgent need of repair and renewal. The church has been awarded a Heritage Lottery Fund Grant for Places of Worship to address these defects and repair works are due to start in 2017.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Michael and All Angels, Smethcott
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1177711

This isolated C12 church was largely rebuilt between 1849 and 1850 by JP Harrison in a decorated style and incorporates medieval walling and some C12 features. The church consists of a chancel and a nave with a south porch and a west end bellcote. The roofs are covered by plain clay tiles interspersed with courses of scalloped tiles which are all now in need of re-laying. Rainwater goods are defective and in need of complete renewal. A new surface water drainage installation is also required. A grant application to the Heritage Lottery Fund is due to be made in 2017.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Mary, Stottesdon
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1189978

The church of St Mary consists of a nave with aisles, a west tower and a chancel. Although there are fragments of Saxon masonry within the west wall of the nave, the tower and aisles are C12. The church as seen today was largely completed by C14 and was restored in C19 by Thomas Blashill. The tile roof coverings date from C19 and require re-laying if not renewal along with the rainwater goods. Assorted high level masonry repairs are also required as is a new surface water drainage system. An unsuccessful application was made to the Heritage Lottery Fund Grants for Places of Worship in 2017.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Bartholomew, Newport Road, Tong
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1053606

The church of St Bartholomew dates from the early C15 and consists of a nave with aisles, a crossing tower with spire, transepts, a chancel, vestry, south east chapel and a south porch. The Perpendicular Gothic exterior remains largely unaltered with buttressed walls and crenelated parapets decorated with crocketed pinnacles. The spire crown stone is cracked due to corroding ferrous metal and parts of the tower parapet are displaced. Rust jacking has also caused damage to assorted window mullions and transoms. A Heritage Lottery Grant for Places of Worship was awarded in 2016.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Lucia, Upton Magna
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1267600

This C12 church has a chancel and a nave with a west tower and a south porch. Some of the original masonry survives in the chancel but the church was substantially rebuilt and enriched by the architect GE Street between 1860-1. The condition of the plaster infill ceiling panels to the nave and north aisle roofs is fragile and hazardous to those who use the church. There is water ingress at the nave roof abutment to the tower and defective drainage is responsible for damp walls at a low level. An application to the Heritage Lottery Fund Grants for Places of Worship scheme has been submitted.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Michael, Wheathill
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383760

This church consists of a short C12 nave with an asymmetrical west tower of similar date aligned with the north wall, a C14 chancel and a C16 porch. Walls are constructed in coursed and squared rubble reflecting the local geology and roofs are steeply pitched and covered with red plain clay tiles. The nave north wall has raking buttresses installed in the C19 to address structural deficiencies. Extensive cracking to both nave and tower walls suggest inadequate bonding of the external facework and the presence of core voids. The extent and scope of repairs has yet to be agreed.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Loughton Parish Church, Wheathill
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1383759

This church was built in 1622 at the expense of Bonham Norton of Church Stretton to replace a C13 chapel. Constructed in rubble stone with steeply pitched roofs covered by plain clay tiles, it consists of a nave with a west bellcote and a lower chancel. It was subsequently restored in 1904 when the south porch and north vestry were added. This was possibly the last occasion when all roofs were last re-laid and accounts for their poor condition. Rainwater goods are also failing and a new modified surface water drainage system is required.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St John the Baptist, Boot Street, Whittington
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1367372

The earliest part of this red brick church is the west tower built in 1747; the neoclassical nave was designed by Thomas Harrison and built in 1805-6 and the pyramid roof added to the tower in 1894. The Early English chancel with south organ chamber and north chapel was added in 1861. Whilst proposed minor repairs to the north west corner of the nave roof should resolve issues of on-going water ingress, all of the cast iron rainwater goods are time-expired and need to be replaced. The surface water drainage system is also largely ineffective and complete renewal should be anticipated.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Little Shrawardine motte and bailey castle, Alberbury with Cardeston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019198
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Natural erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855

SITE NAME:	Ringwork 540 metres north of Lane Farm, Alberbury with Cardeston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019831
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855

SITE NAME:	Standing cross in the churchyard of St Michael and All Angels' Church, Alberbury with Cardeston		
DESIGNATION:	Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER:	1020663
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Bill Klemperer 0121 625 6847

SITE NAME:	Stanwardine moated site and associated fishpond, Baschurch		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017240
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855

SITE NAME:	Lower Cleeton moat, a moat and fishponds 380 metres south east of Cleeton Court, Bitterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1010496
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855

SITE NAME:	White Ladies (St Leonard's) Priory, Boscobel		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1015290
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow 450 metres north west of Felton Farm, Bromfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1007712
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Roman camp north of Bromfield Farm, Bromfield		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006273
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Castle Tump, a motte castle and causeway, 150 metres west of Teme Bridge, Burford		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008392
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Motte and bailey castle 150 metres north east of Wilmington, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012864
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Offa's Dyke: section 2/3 mile (1170 metres) long, north from southern boundary of Rownal Covert, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1003013
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Other not for profit group	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section one mile 750 yards (2290 metres) from Dudston Covert to a point 300 yards (274 metres) north of Lack Brook - Also in Powys: Wales, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003797
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: two sections running 400 yards (370 metres) south of Camlad Stream - Also in Powys: Wales, Chirbury with Brompton		
DESIGNATION:	Scheduled Monument, part in SM	LIST ENTRY NUMBER:	1006259
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Motte castle 80 metres north east of Home Farm, Church Stretton		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1008396
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Norton Camp: a large multivallate hillfort, Culmington / Craven Arms		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021073
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	The Mount motte and bailey castle, 120 metres north east of Hill House Farm, Diddlebury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012856
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Moated site and associated ridge and furrow cultivation remains, 145 metres south of St Mary Magdalene's Church, Hadnall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019650
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Offa's Dyke: section 90 metres south of Brynorgan, Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020905
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Offa's Dyke: section 890 metres north west and 320 metres west of Little Selley, Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020903
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Motte and bailey castle 100 metres west of Holy Trinity Church, Lydham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013486
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Nickless moat, Milson		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009552
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Callow Hill Camp: a small multivallate hillfort, Minsterley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019828
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Roman villa at Linley Hall, More		
DESIGNATION:	Scheduled Monument, part in RPG grade II	LIST ENTRY NUMBER:	1006253
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Offa's Dyke: section 175 metres east of Cefn Bronydd, Newcastle on Clun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020899
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Small enclosed settlement on Fron, 340 metres west of St John's Church, Newcastle on Clun		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021069
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Offa's Dyke: section 400 metres south west of Springhill Farm, Newcastle on Clun / Clun / Llanfair Waterdine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020901
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Roman villa 150 yards (140 metres) south east of Lea Hall, Pontesbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006246
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Wat's Dyke, 420m long section, 190m west of the junction between Preeshenlle Lane and St Martin's Road, Selattyn and Gobowen		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020617
CONDITION:	Generally satisfactory but with minor localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Roman camps south west of Stoneyford Cottages, Shifnal		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006249
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Roman fort 300 metres east of Drayton Lodge Farm, Shifnal		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020283
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Uxacona Roman site (see also Telford and Wrekin Unitary Authority), Shifnal / St. Georges and Priorslee / Lilleshall and Donnington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003811
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827
SITE NAME:	Roman military site at Rhyn Park, St. Martin's		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1003716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Camp Ring motte and bailey castle, enclosure, fishpond and ridge and furrow 400 metres east of Culmington Farm, Stanton Lacy		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012855
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Medieval fishpond reservoir north east of Haughmond Abbey and south west of the hamlet of Haughton, Uffington / Upton Magna		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002953
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Robury Ring: a small enclosed settlement on Wentnor Prolley Moor, Wentnor		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021072
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Hawcocks Mount ringwork castle 200 metres north east of Hawcocks Farm, Westbury		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013494
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Red Castle: an enclosure castle in Hawkstone Park, Weston-under-Redcastle		
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, RPG grade I	LIST ENTRY NUMBER:	1020850 and 1237180; 1264271
CONDITION:	Extensive significant problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Upper Barn moat, Wistanstow		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012455
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Bowl barrow 120 metres south west of Dorrington Cottage, Pipe Gate, Woore		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016829
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Bowl barrow at The Napp, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017347
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855
SITE NAME:	Snailbeach New Smeltmill, 350 metres north east of Green Acres, Worthen with Shelve		
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II	LIST ENTRY NUMBER:	1017764 and 1307989; 1055031
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Whitchurch, Whitchurch Urban		
DESIGNATION:	Conservation Area, 92 LBs, SM	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andy Wigley (LPA) 01743 254605

SITE NAME:	Two bowl barrows 290 metres north of Upper House Farm, Worthen with Shelve		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016666
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855

STAFFORDSHIRE

EAST STAFFORDSHIRE



© Historic England

SITE NAME:	Sinai Park, Burton on Trent, Branston
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1038484

Mid C17 timber framed house, one wing of which was repaired some years ago. The remainder is in very poor condition and continues to deteriorate. It is in critical condition with areas of partial collapse but no agreed plans for its repair. The owners have employed consultants to undertake an initial options appraisal, and are in discussion with the Heritage Lottery Fund with regard to bringing forward a scheme for its restoration.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Church of St Michael and All Angels, Tatenhill
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1038433

The church dates from the C13 and consists of a tall nave and chancel, a south porch and a west tower. It is constructed in buff/red sandstone and has steeply pitched roofs covered in red plain clay tiles. Notwithstanding assorted alterations and changes made throughout its history - the tower is a C15 addition - the church was restored towards the end of the C19 by GF Bodley when the existing roofs were retiled. These are now time expired and renewal is urgently required: a Heritage Lottery Fund Grants for Places of Worship application has been made and a decision is due in September 2017.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Enclosures and cursus 300 yards (270 metres) south east of Efflinch, Barton-under-Needwood		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006073
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Bill Klemperer 0121 625 6847

SITE NAME:	Timber circle, hengi-form monument and part of a pit alignment at Catholme, Barton-under-Needwood		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019109
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Mineral extraction/related subsidence	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Bill Klemperer 0121 625 6847

SITE NAME:	Clarence Street/Anglesey Road, Burton upon Trent, Anglesey		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Ben Williscroft (LPA) 01283 508624

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	George Street, Burton, Burton upon Trent, Burton		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Ben Williscroft (LPA) 01283 508624

LICHFIELD

© Historic England

SITE NAME:	Manor House, Hamstall Ridware
DESIGNATION:	Scheduled Monument, 3 LBs, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1006119

Porch, walls and gatehouse to timber framed C15 country house, substantially altered in C16 and C18 with brick hall, tower and courtyard walls. The tower remains as a prominent garden folly with considerable structural issues. The house is still in use, but the tower is derelict and in very bad condition. The owner is working with Historic England to manage vegetation and a detailed recording survey has been completed. Further structural assessment of the site is needed.

Contact: Jez Bretherton 0121 625 6855



© Historic England

SITE NAME:	Angel Croft Hotel, front railings and gates, Beacon Street, Lichfield
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1187354

A fine three storey hotel, built c1750 in brick with ashlar dressings. The railings and gates are included in its listing and are also in poor condition. The building has been empty for some time. Permission was granted for conversion to apartments with an agreement to secure the repair of the gates and railings. We are hopeful that works will commence on site later in 2017.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Church Tower north of Church of St John, St Johns Hill, Shenstone
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1038830

This is a C13 derelict church tower with later alterations. There are no current plans for future use of the tower. Local Planning Authority Building Inspectors have visited in the past and the structure was considered stable at the time. A Historic England Architect visited approximately five years ago and advised on the removal of ivy. Previous proposals to agree a repair scheme between interested parties have not come to fruition.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St John the Baptist, Edingale
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1188243

The church of St John the Baptist has C13 origins and consists of a nave with a west tower and a chancel with a north side organ chamber. Several phases of past repairs, remodelling and rebuilding are clearly evident but works to renew roof coverings, high level stonework and rainwater goods are urgently required. A Listed Places of Worship Roof Repairs Grant awarded in June 2016 has facilitated the renewal of the tower, nave and chancel roof coverings, parapet gutter linings, rainwater goods and new surface water drainage but extensive high level masonry repairs remain outstanding.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Site of round barrow near River Tame, Alrewas		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006090
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Charity (heritage)	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Air photographic site south west of Elford, Fisherwick		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006100
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Causewayed enclosure, Fradley and Streethay		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002964
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Fazeley and Bonehill, Fazeley / Drayton Bassett		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Claire Hines (LPA) 01543 308188

NEWCASTLE-UNDER-LYME



© Historic England

SITE NAME:	Model farm complex south west of Betley Old Hall, Main Street, Betley
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1188395

Early C19 model farm including a range of cowhouses, a granary, cartshed, stables and watermill. The owner is currently repairing the buildings for agricultural and storage use. Repairs to the granary have been completed and the front range and vaults have been stabilised. Repairs are ongoing to the bottom yard range. Possible alternative uses for the buildings are being discussed with the Local Planning Authority.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Heighley Castle, Heighley Lane, Madeley
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1011070 and 1353703

Remains of a medieval castle dating mainly from the early C13. Only fragments of walling survive due to it being partly demolished in the Civil War. The castle is heavily overgrown with masonry eroding and is generally in a very poor condition. An Historic England Management Agreement has been undertaken by the owner for vegetation clearance prior to undertaking a condition survey and masonry consolidation which are ongoing.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Gatehouse, walls and bollards to Maer Hall, Maer
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1027834

Late C18 gatehouse, walls and bollards forming the approach to Maer Hall. The Hall is set in an early C19 park by John Webb. The property is associated with the Wedgwood and Darwin families. The condition of the gatehouse continues to deteriorate with repairs to the roof, gables and stonework required. Stabilising works have taken place and further negotiations are underway regarding more permanent repairs.

Contact: Julie Taylor 0121 625 6848

SITE NAME:	Heighley Castle, Madeley	LIST ENTRY NUMBER:	1011070 and 1353703
DESIGNATION:	Scheduled Monument and Listed Building grade II	TREND:	Improving
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Scrub/tree growth	CONTACT:	John Tiernan 0121 625 6839
OWNER TYPE:	Private		

PEAK DISTRICT (NP)



© Historic England

SITE NAME:	Critchlow Monument, Sheen, Staffordshire Moorlands
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374551

Chest tomb and railings to the Critchlow Family, c1853 with large aedicular Gothic stone chest and spike headed wrought iron railing surround. The north face of the tomb has suffered two fragment losses to the blind arcading panels at the west and east end. The surrounding railings on all four sides have deteriorated where they fix into the stone base, in some cases to a point of complete loss, potentially jeopardising the long term stability of the monument. Historic England has contacted the Churchwardens to discuss possible repairs.

Contact: Aimee Henderson 0121 625 6854

SITE NAME:	Bowl barrow 450 metres east of Stanshope, Alstonefield, Staffordshire Moorlands	LIST ENTRY NUMBER:	1010798
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Animal burrowing - Badger - extensive	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Private		

SITE NAME:	Copper mines on Ecton Hill, Wetton, Staffordshire Moorlands	LIST ENTRY NUMBER:	1021175
DESIGNATION:	Scheduled Monument	TREND:	Improving
CONDITION:	Generally satisfactory but with minor localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Scrub/tree growth	CONTACT:	Rhodri Evans 0121 625 6886
OWNER TYPE:	Mixed, multiple owners		

SOUTH STAFFORDSHIRE



© Historic England

SITE NAME:	Stable Court at Four Ashes Hall, Four Ashes, Enville
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1277027

Stable court incorporating extensive farm outbuilding ranges at Four Ashes Hall dating from the mid to late C18 with C20 alterations. One range has virtually collapsed and the roofs are in a very bad state. A programme of urgent repairs to the main frontage of the building was completed in 2006 with Historic England funding, but the rest of the building remains in very poor condition. An Historic England Repair Grant to develop a repairs project was accepted in 2016 and is expected to be complete in 2017.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman fort west of Eaton House, Brewood and Coven		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006098
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Roman camp, Kinvaston, Penkridge / Lapley, Stretton and Wheaton Aston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006104
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854

STAFFORD



© Historic England

SITE NAME:	Engine House and Boiler House at Mill Meece Pumping Station, Standon	Former pumping station built around 1914 for the Staffordshire Potteries Waterworks Company. It now operates as a museum. The building was designed by William Campbell and constructed by Thomas Godwin and Son. The engine house and boiler house form part of an exceptionally complete pumping station site in which the integrated process of water pumping is still readable. Repairs are in progress to address the remaining issue of asbestos and enable the steam engines to be used once more. Roof repairs are needed.
DESIGNATION:	Listed Building grade II*	
CONDITION:	Poor	
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (B)	
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1039047	

Contact: Aimee Henderson 0121 625 6854



© Historic England Archive

SITE NAME:	Remains of Trentham Hall, the Grand Entrance and Orangery, Park Drive, Trentham Gardens, Swynnerton	The remains of a country house dated between 1833 and 1842 by Sir Charles Barry and an orangery of 1808, all situated in a C18 to C19 park by Lancelot Brown. Emergency repairs have been carried out and the adjacent Italian gardens have been successfully restored. However, several heritage assets on the site are still in need of urgent repair and viable new uses.
DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1190243	

Contact: Julie Taylor 0121 625 6848

SITE NAME:	Moated site in Reynold's Orchard, Eccleshall		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011051
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - extensive	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Jez Bretherton 0121 625 6855

SITE NAME:	Multivallate hillfort at Bury Bank, Stone Rural		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1008548
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Bowl barrow north of Hargreaves Wood, Swynnerton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1009315
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Foregate and St Georges		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	Medium	CONTACT:	Penny McKnight (LPA) 01785 619337

SITE NAME:	Trentham, Swynnerton		
DESIGNATION:	Conservation Area, 30 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Penny McKnight (LPA) 01785 619337

SITE NAME:	Walk Mill, Eccleshall		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Penny McKnight (LPA) 01785 619337

STAFFORDSHIRE MOORLANDS



© Historic England

SITE NAME:	Biddulph Old Hall, Biddulph
DESIGNATION:	Scheduled Monument, part in LB grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014688

Substantial remains of a mansion constructed in the 1580s for Francis Biddulph. It came under siege by the Parliamentarians in 1643 when the east range was destroyed and the house fired. The tower and rest of the remains are in need of consolidation. Works were partially completed with the aid of Historic England funding but have stalled for some years now.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Prospect Tower and attached wing, Knypersley, Biddulph
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1037810

Built in 1828 by John Bateman as a gamekeeper's house and eye catcher on the Knypersley Hall estate landscape, this three storey octagonal tower constructed in red sandstone has been disused for more 25 years and is in a poor state of repair. The reoccupation of the building is limited by the presence of bats. An options appraisal for the reuse of the building was completed in March 2017 and its recommendations are due to be taken forward and developed.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Hales Hall, Oakamoor Road, Cheadle
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1204735

Baroque style, small country house built in 1712 for Mrs Grosvenor the granddaughter of Sir Matthew Hale, Lord Chief Justice of England (1670 to 1676). The condition of the house has deteriorated, with water ingress from the roof being of particular concern. Hales Hall has recently been purchased by the adjacent land owner, who intends to use the Hall as bar facilities for the camp site. Roof repairs are currently underway.

Contact: Julie Taylor 0121 625 6848

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England Archive

SITE NAME:	Alton Towers and attached garden walls and gatehouse, Alton Park, Farley
DESIGNATION:	Listed Building grade II*, RPG grade I
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1374685

Country house, walls and gatehouse, c1810, set in early C19 valley gardens. Derelict when listed. A complete condition survey was undertaken and emergency work completed. A conservation management plan for the whole site has been prepared and phased programme of small works is ongoing. However, no overall solution for the whole site at present.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Sharpecliffe Hall, Ipstones
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374611

A large country house dated 1673 but restored and enlarged in C19. It may hide earlier fabric. Some repairs have been undertaken in recent years but essential roof repairs to the wings are still needed.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	The Gazebo west of Whitehough, Ipstones
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1374612

An early C18 gazebo in the grounds of the C17 farmhouse at Whitehough. Some repairs were undertaken in the 1990s with grant assistance from Historic England. However, further repair works are now required to the roof, stonework and joinery to complete the restoration.

Contact: Julie Taylor 0121 625 6848



© Historic England

SITE NAME:	Church of St Chad, A 53, Longsdon
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1037805

Designed by Gerald Horsley and built in 1903, this church consists of a west tower with spire, nave, north aisle and chancel and was inspired by Norman Shaw's All Saints at Leek. A Listed Places of Worship Roof Repair Grant awarded in 2016 has facilitated the reroofing of the vestry, the repair of defective rainwater goods and the installation of a new surface water drainage system. The nave/chancel and north aisle roofs are still in urgent need of renewal and the masonry to the spire broaches requires repointing following the previous removal of self seeded saplings.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary, Waterhouses
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1286588

Built in 1839 and consists of a nave with a west end timber bellcote, a south porch and a short chancel with a north east vestry. The church has grey limestone rubble walls with buff gritstone dressings and roofs covered with blue plain clay tiles. The nave roof covering is practically time expired and needs to be stripped and re-laid: most of the roof tiles appear to be sound and should be capable of reuse. Timber repairs to the roof and ceiling structures should also be anticipated. A decision on a Heritage Lottery Fund Grants for Places of Worship application is expected in September 2017.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Paynsley Hall moated site and outer enclosure, Draycott in the Moors		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1011050
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - localised/limited	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Dieu-la-Cres Abbey (remains of), Leek		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1006107
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Alton and Farley, Staffordshire Moorlands		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395400

SITE NAME:	Cheadle		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Gill Bayliss (LPA) 01538 395400

TAMWORTH



© Historic England

SITE NAME:	Deanery wall, Lower Gungate, Tamworth
DESIGNATION:	Scheduled Monument and Listed Buildings - 2 grade II, 3 LBs, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Unknown

LIST ENTRY NUMBER: 1006059 and 1197033; 1207833

A C14 masonry wall which was part of St Editha's Deanery. An Historic England engineer has inspected the three surviving sections of wall, parts of which are in urgent need of maintenance and repair. The removal of plant growth, repointing and resetting of stones to wall tops are all required. As a boundary wall, the ownership is uncertain, and liability for repair unclear.

Contact: Aimee Henderson 0121 625 6854

STOKE-ON-TRENT, CITY OF (UA)



© Historic England

SITE NAME:	Former Wedgwood Institute (Public Library), Queen Street, Burslem
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)

LIST ENTRY NUMBER: 1195840

An art school, gallery and library built in 1869 and constructed in brick and terracotta with a richly ornamented facade. The Institute has been transferred to the UK Historic Buildings Preservation Trust who is now in the process of bringing the building back into use as an enterprise hub and centre for start-up businesses. The first phase of repair work was completed in autumn 2016. Subject to funding, the second phase of work to enlarge and refurbish the Institute is due to start in autumn 2018 with completion anticipated in April 2020.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Bethesda Methodist Chapel, Albion Street, Hanley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1195821

A former Methodist chapel built in the C19 with intact interiors known as "the Cathedral of the Potteries". The Historic Chapels Trust has completed external repairs with the help of grants from Historic England and the Heritage Lottery Fund. Further repairs have also been undertaken to some of the outbuildings. The Friends group has undertaken repairs to the stained glass. The Trust is looking at options for increased use of the building.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Bottle oven and factory, Price and Kensington Teapot Works, Newcastle Street, Longport
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1290799

An early C19 pottery complex with a bottle oven that has been repaired and only one range now occupied. A fire in the three storey range has resulted in the demolition of walls above the second floor and the removal of the roof structure. Theft of slates and tiles from the roofs of many of the other buildings means that the complex is exposed and highly vulnerable. The site is rapidly deteriorating. Urgent works are required to stabilise the buildings while a new use is sought.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Chatterley Whitfield Colliery, Biddulph Road, Stoke-on-Trent
DESIGNATION:	Scheduled Monument, 6 LBs
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1015947

Large redundant C19/C20 colliery in need of major repair and regeneration. The site includes 15 scheduled structures and 5 listed buildings. A heritage based regeneration programme has been started based on a masterplan but a long term solution still needs to be agreed. Progress with the re-use of buildings and reclamation works has been slow however. Discussions on private sector engagement and longer term proposals are ongoing.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Chatterley Whitfield: pithead baths complex (18-21), Biddulph Road, Stoke-on-Trent
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1260223

Originally opened in the 1860s, Chatterley Whitfield became the first mine in Britain to draw more than a million tons of coal in a year in 1937. The pithead baths and canteen were erected at this time and are of special interest as an example of large scale provision for miners in the early C20. On the closure of the mine, the buildings were used to accommodate a museum which has since closed. The whole colliery site is now vacant and these buildings are in very poor condition.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Mausoleum, Stone Road, Trentham
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	N/A
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1210451

A mausoleum built for the Dukes of Sutherland around 1808 and set opposite one of the entrances to Trentham Park. A package of urgent roof repairs was carried out with funding from Historic England and the local planning authority. Further repairs to doors and the rear window have also been completed. The fabric is now generally sound, but the building remains at risk until responsibility for future upkeep is clearly established.

Contact: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Church of St John the Baptist, Cross Hill, Burslem
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1291065

This church was largely rebuilt in 1717 but retains its medieval tower. Non-breathable paint on the nave external walls is trapping moisture causing significant levels of damp internally and the deterioration of the outer brick face. Outbreaks of dry rot have occurred in the past and reroofing with inappropriate and heavy concrete tiles on the hipped nave roof is leading to structural problems. The building has multiple fabric defects and has been the victim of heritage crime. Protracted negotiations to lease this place of worship to the New Testament Church of God have yet to be concluded.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	All Saints Church, Leek Road, Hanley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1245925

This Arts and Crafts Gothic church was designed by Gerald Horsley in 1910. Built with red brick buttressed walls and sandstone dressings, it has steeply pitched roofs that have plain clay and replacement concrete tiles. Failed abutment flashings at the east end of the church and defective rainwater goods threaten the integrity of this largely unaltered building. A scheme to create an enclosed place of worship within the unheated church is now proposed. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2015 and repair work is anticipated to start on site in 2017.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mark, Broad Street, Stoke-on-Trent
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1220134

This Commissioners' church was built c1830 and consists of a nave with galleries and a west tower; the chancel was added in 1868. The buttressed tower is tall and remarkably decorative for a building where economy would have been a primary consideration. The clock stage to the tower is subdivided by blind pointed panels with engaged shafts secured by ferrous metal fixings and several of these have failed and fallen to the ground. Panelled plaster ceilings above the galleries have had emergency holding repairs initiated which are connected to defective roof coverings and parapet gutter linings.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Caldon Canal, Stoke-on-Trent	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Medium	CONTACT: Jane Corfield (LPA) 01782 236680

SITE NAME:	Longton Town Centre, Longton	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Medium	CONTACT: Jane Corfield (LPA) 01782 236680

SITE NAME:	Newcastle Street, Middleport	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Poor	TREND: No significant change
VULNERABILITY:	High	CONTACT: Jane Corfield (LPA) 01782 236680

SITE NAME:	Stoke Town, Stoke	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?: No
CONDITION:	Very bad	TREND: No significant change
VULNERABILITY:	Medium	CONTACT: Jane Corfield (LPA) 01782 236680

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Trent & Mersey Canal, Stoke-on-Trent		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Jane Corfield (LPA) 01782 236680

TELFORD AND WREKIN (UA)

© Historic England

SITE NAME:	Site of pumping engine at Muxton Bridge colliery, Lilleshall and Donnington
DESIGNATION:	Scheduled Monument
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1018468

The monument is situated in Granville Country Park near Telford. The condition of the engine house is deteriorating with loose joints in the brickwork causing bricks to become dislodged. Remedial action has been agreed in principle but a timetable for implementation of repairs has not yet been agreed with Telford and Wrekin Council.

Contact: Bill Klemperer 0121 625 6847



© Historic England Archive

SITE NAME:	Charlton Castle, Wrockwardine
DESIGNATION:	Scheduled Monument
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019649

A medieval moated site which is very overgrown and has several uprooted trees damaging the earthworks. There are some elements of standing masonry exposed. The site needs an assessment of condition and the development of an appropriate management regime. There is potential to fund this through an Historic England Management Agreement.

Contact: Jez Bretherton 0121 625 6855



© Historic England

SITE NAME:	Church of St Peter, Church Road, Oakengates
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1033297

The church of St Peter was designed by Francis Halley of Shifnal and built between 1825 and 1827 to replace a C12 chapel which consisted of the present nave and west tower to which the chancel was added in 1903. The church is constructed in brindle brickwork with stone dressings and has slate covered roofs. Concealed ferrous metal dowels have disrupted the masonry to the tower bell lights which has resulted in sections of masonry shearing off. The vestry has settled and rotated away from the chancel wall. All of the roofs require re-laying and the rainwater goods overhauling and repairing.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Peter, Wrockwardine
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1030939

This C12 cruciform church has a nave and chancel, transepts and a crossing tower with later medieval chapels added to the north and south sides of the chancel. Much altered with prominent structural reinforcement in the form of angle buttresses to the tower and by subsequent restoration and repair schemes, assorted works are now urgently required to address defective tiled roof coverings, rainwater goods and high level stonework. A Heritage Lottery Fund Grant for Places of Worship for high level masonry repairs to the crossing tower was awarded in 2015, with work due to complete in 2017.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Enclosed Iron Age farmstead immediately adjacent to The Croft, Pave Lane, Chetwynd Aston and Woodcote		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020275
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Roman camp on Red Hill, Lilleshall and Donnington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006269
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Jez Bretherton 0121 625 6855

SITE NAME:	Canal aqueduct over River Tern, Rodington		
DESIGNATION:	Scheduled Monument, LB grade I	LIST ENTRY NUMBER:	1006275
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Uxacona Roman site (See also Shropshire Unitary Authority), Shifnal / St. Georges and Priorslee / Lilleshall and Donnington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1006272
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Alison MacDonald 0121 625 6827

SITE NAME:	Moated site and a fishpond 160 metres and 280 metres south of The Farm, Charlton, Wrockwardine		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019649
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Plant growth	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855

WARWICKSHIRE

NORTH WARWICKSHIRE



© Historic England

SITE NAME:	Beech House, 19 Market Street, Atherstone
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Commercial company

LIST ENTRY NUMBER: 1185175

A fine town house in the Queen Anne style dated 1708. The interiors are largely unaltered and most of the original features are intact. The property has been vacant for several years and is slowly decaying. A scheme for the repair and refurbishment of the building has been agreed following discussions between the owner and the Local Planning Authority. It is hoped that works will commence in the second half of 2017.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Grendon Bridge, Grendon / Polesworth
DESIGNATION:	Scheduled Monument and Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private

LIST ENTRY NUMBER: 1005756 and 1186247

Stone bridge, probably C15 constructed in sandstone. Now in poor condition with parts of the parapet missing. A condition survey is needed to assess the scale of repairs. Discussions are ongoing with the owners about a possible Historic England Management Agreement.

Contact: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Hartshill Castle, Castle Road, Hartshill
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1011197 and 1034748

C13 castle ruins. Steady decay of surviving masonry due to erosion, structural problems and vandalism. The owner has set up a trust to look after the castle. Vegetation clearance and emergency repairs were carried out some time ago. Discussions are ongoing with the owner for a condition survey prior to masonry repairs.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Kingsbury Hall , Kingsbury
DESIGNATION:	Scheduled Monument and Listed Buildings - 1 grade II*; 1 grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1019978 and 1116550; 1034721

A manor house of c1500 with late C16 and C18 rebuilding and early C19 wing. A scheme for the residential conversion of the building has commenced. Final repairs and reuse have yet to be achieved.

Contact: Rhodri Evans 0121 625 6886



© Historic England

SITE NAME:	Maxstoke Priory, Church Road, Maxstoke
DESIGNATION:	Scheduled Monument and Listed Buildings - 6 grade II*, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1011195 and 1034822; 1034823; 1365129; 1034821; 1116038; 1320105

Substantial remains of an early C14 Augustinian monastery including infirmary, precinct walls and outer gatehouse with attached barn and farmhouse. The buildings are steadily decaying, the precinct wall is in very poor condition and the infirmary structure is propped. Natural England previously funded some repairs under a Higher Level Stewardship scheme. Historic England is now working with the owners to review the condition of the walls, gatehouse, and other sections, looking to address their condition.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Merevale Abbey, a Cistercian monastery, associated water control features and industrial remains, Merevale
DESIGNATION:	Scheduled Monument, 6 LBs, part in RPG grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1014682

Mid C12 Cistercian monastery retaining several visible fragments of major monastic buildings but also earthwork and buried remains which illustrate the development of the monastery. Stonework in the refectory is eroding and needs addressing through a condition assessment to inform conservation. The Estate is working with Historic England to address the site.

Contact: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Stables range north east of Middleton Hall, Middleton
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1365197

Originally stables and lodging block c1570. Timber framed with brick infill panels. Consists of a four bay main range with a two bay cross wing at the north end and a two storey gabled porch to the left of the centre. Courtyard of farm buildings to rear. The structure is in need of stabilisation. The building is vacant and a condition survey has been undertaken.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Moat, footbridge and gatepiers to Shustoke Hall Farmhouse, Moat House Lane, Shustoke
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1226189

Homestead moat, footbridge and gate piers c1686, with late C18 service wing which is in poor condition. Substantial sections of overgrown walls and buttresses were previously leaning outwards and required rebuilding. Much of this work has been carried out, most recently the Estate has rebuilt the brick upper parapet to the south arm. Progress has been made since 2013 with repointing to the moat walls, but further work is needed to remove the site from the Register.

Contact: Aimee Henderson 0121 625 6854



© Historic England Archive

SITE NAME:	Alvecote priory and dovecote, Shuttington
DESIGNATION:	Scheduled Monument, 2 LBs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1020623

The listed and scheduled remains of a C12 Benedictine Monastery; the primary structure on site represents the C14 remodelling of the building and has been subject to heritage crime and natural deterioration. An associated medieval dovecote is also affected by issues with its roof covering and water penetration. Historic England is encouraging the Local Authority to establish a management plan for the site and carry out repairs to the standing remains of the priory and dovecote.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Church of St Mary, Sheepy Road, Atherstone
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1365164

Large imposing church constructed in two parts with a central tower. Chancel may date from C12 as an independent chapel, and then remodelled c1383 when the nave was added. Older parts are built in rubble. Nave and aisles were rebuilt in 1849 in rubble granite, wagon roof with moulded braces and purlins. The octagonal tower was part of the original chapel, although of a later period, C13/C14, but was remodelled. The roof, rainwater goods and high level masonry are in poor condition. Repair works funded by a Heritage Lottery Fund Grant for Places of Worship will begin in summer 2017.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Oldbury Camp univallate hillfort, Hartshill	LIST ENTRY NUMBER:	1018855
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Scrub/tree growth	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Utility		

SITE NAME:	Roman Camp, Mancetter	LIST ENTRY NUMBER:	1005736
DESIGNATION:	Scheduled Monument, part in CA	TREND:	Unknown
CONDITION:	Unknown	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Other	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Mixed, multiple owners		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Manduesedum Roman villa and settlement with associated industrial complex, Mancetter / Witherley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1017585
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Merevale Abbey, a Cistercian monastery, associated water control features and industrial remains, Merevale		
DESIGNATION:	Scheduled Monument, 6 LBs, part in RPG grade II*	LIST ENTRY NUMBER:	1014682
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Alvecote priory and dovecote, Shuttington		
DESIGNATION:	Scheduled Monument, 2 LBs	LIST ENTRY NUMBER:	1020623
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Aimee Henderson 0121 625 6854

NUNEATON AND BEDWORTH



© Historic England

SITE NAME:	Park Farmhouse, Arbury Park, Nuneaton
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1365048

Late C15 farmhouse with C16 and C17 alterations, to the north west of Arbury Park. Following a building survey, works were carried out to support and protect the structure while schemes and options for future use were considered and discussed by the Estate with Historic England. Temporary measures have subsequently begun to fail and the Estate is now looking to undertake further urgent action to protect the building, particularly its vulnerable timber frame, from further deterioration.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	The Tea House, Arbury Park, Nuneaton
DESIGNATION:	Listed Building grade II*, RPG grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1299615

Mid C18 summerhouse located c500 metres east north east of Arbury Hall. The Tea House is situated on the north east shore of a small lake on the eastern edge of the C18 park. The roof has collapsed and it is in a very bad state of repair and continues to deteriorate. Action is needed urgently to halt decay and save what is left of the building. There are currently no plans to repair the structure.

Contact: Aimee Henderson 0121 625 6854

RUGBY

SITE NAME:	Brandon Castle, Brandon and Bretford		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1011371
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Barrow cemetery 400 metres north east of Bretford, Brandon and Bretford / King's Newnham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005722
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Prehistoric pit alignment and associated features on Lawford Heath, adjacent to the northernmost Blue Boar Farm, Church Lawford / Thurlaston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1020937
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Bowl barrow 470 metres south west of Coton House, Churchover		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016883
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Tripontium Roman Station, Churchover		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005759
CONDITION:	Unknown	TREND:	Declining
PRINCIPAL VULNERABILITY:	Metal detecting - unlicensed	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Prehistoric circular earthworks, King's Newnham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005717
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Bowl barrow on Lammas Hill, Wolston		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016885
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Arable clipping	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Bowl barrow 490 metres north west of Abbey Farm, Wolvey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016845
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
SITE NAME:	Bowl barrow 900 metres north of Copston Farm, Wolvey		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1016846
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Ryton House, Ryton-on-Dunsmore
DESIGNATION:	Registered Park and Garden grade II, LB grade II
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001343

Small Regency landscape surrounding the shell of a grade II listed Regency villa. Late C20 extensions to the villa extend over the gardens. Longstanding lack of regular maintenance has left the boundary belt, historic drive, shrubberies and lakes in poor condition. The setting is compromised by roads and residential development. Its future is uncertain.

Contact: Kim Auston 0117 975 0696

STRATFORD-ON-AVON




© Historic England

SITE NAME:	St Nicholas' Church, Ettington Park, Ettington
DESIGNATION:	Scheduled Monument, LB grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005744

The ruined chapel of St Nicholas is the family mausoleum of the Shirley family. It has suffered from natural erosion and other threats including birds nesting in the tower, structural decay of standing masonry and other issues associated with rainwater goods and cementitious repairs. The owners are in discussions with Historic England about repairs and management options.

Contact: Aimee Henderson 0121 625 6854



© Historic England

SITE NAME:	Toll House, Clopton Bridge, Stratford-upon-Avon
DESIGNATION:	Listed Building grade I, SM
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1204167

Former toll house built in 1814 on the C15 Clopton Bridge in the centre of Stratford-upon-Avon. The building had not been used for many years, with roof and stonework in poor condition. In 2015 Stratford Historic Buildings Trust was awarded grant aid by Historic England and the Heritage Lottery Fund for repairs and conversion to office use. The works are due to be completed in September 2017.

Contact: Cristina Gardiner 0121 625 6850




© Historic England

SITE NAME:	Umberslade Baptist Chapel, Spring Lane, Tanworth-in-Arden
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1382428

Exceptionally fine Nonconformist estate chapel of 1877 by George Ingall for GF Muntz of Umberslade Park. The chapel has not been used as a place of worship for many years and has been acquired by the Historic Chapels Trust. Roof repairs have been carried out and the building is drying out, a condition survey has been completed and a management plan with options for use is planned.

Contact: Steven McLeish 0121 625 6884



© Historic England

SITE NAME:	Roman Catholic Church of St Peter Paul and Elizabeth, Coughton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1355381

In 1851-3 the Throckmorton family built a substantial church and presbytery on the edge of their estate, from designs by Charles Hansom. The Throckmorton family has been at Coughton Court since C15, and the house was a Catholic recusant centre from the 1570s. The terracotta tiled roof appears to be at the end of its life with several tiles dislodged and damp showing internally. Poor cementitious repairs, some recent, may further erode and damage the limestone. Historic England has met with the owner who is keen to rectify the situation.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site



© Historic England

SITE NAME:	Church of St Botolph, Church Lane, Farnborough
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1299775

The church is set close to Farnborough Hall. It is in poor condition; the roof shows slipped slates, the gutters have vegetation growing in them and some have become detached. Stonework at high level is also in bad condition.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Giles, Church Lane, Gaydon
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184784

Small ironstone ashlar church with moulded cornices, designed by Squirrill of Leamington and dating from 1852. The church is modest in size but in poor condition externally due to the friability of the Horton Stone. Some parts of the church appear in poor structural condition especially on the east gable. There are large cracks in the masonry and the one on the south west corner is particularly bad. The gutters are also in bad condition.

Contact: Cristina Gardiner 0121 625 6850




© Historic England

SITE NAME:	Church of St Peter, Warwick Road, Kineton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1381924

The prominently located Church of St Peter, Kineton dates from the C13, with alterations from the C14, C15 and C18. It was remodelled and repaired in 1873-89 but the soft local iron stone has not lasted well. A Heritage Lottery Fund and Historic England Repair Grant for Places of Worship awarded in 2012 has repaired the high level and tower's stonework which was extremely poor. Further repairs are needed to poor stonework on the nave's elevations and to rainwater items.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Peter, Tysoe Road, Radway
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1184627

Small parish church built in 1866 to replace a medieval church which was located in a different part of the village of Radway, at the base of the Edge Hill battlefield site. The church was built in Gothic Revival style and has a three bay chancel, nave and aisles. It is built in local Hornton ironstone and regularly coursed with terracotta plain tiled roofs. The tower has four stages with string courses, a moulded cornice and a broach spire. The roof, which is still original, is in very poor condition because of poor detailing despite maintenance. The condition of the rainwater goods is poor.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Michael, Church Hill, Warmington
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1355583

This church dates from the late C12 with additions in the C13 and a mid C14 north aisle, chancel, vestry and west tower. The church was restored in 1850 and 1876 by Sir GG Scott. It is constructed in coursed local ironstone with ashlar stone tower, spire and dressing with a terracotta tiles roof. The roof to the nave is in extremely poor condition and a large number of tiles have slipped. Water leaking into the interior is affecting the supporting timber structure. The gutters and flashings are also in poor condition.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



SITE NAME:	Church of St Peter, Wormleighton
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1299347

This church has C12 and C13 origins, although the aisles were largely rebuilt in the C14 together with the chancel. The east and south walls were rebuilt in the C18. Constructed in squared rubble and coursed ironstone with slate roofs. The tower and north and south aisle roofs are in very poor condition and drainage from the tower is inadequate and unsightly. The church was awarded a Heritage Lottery Fund Grant for Places of Worship in 2014. Repairs started in 2016 and are to be completed in 2017.

Contact: Cristina Gardiner 0121 625 6850

© Historic England

SITE NAME:	Oversley Castle, Alcester	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005750
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Commercial company	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Castle Hill Motte, Brailes	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1018858
CONDITION:	Generally satisfactory but with significant localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?: No
OWNER TYPE:	Commercial company	CONTACT: Jez Bretherton 0121 625 6855

SITE NAME:	Double ditched enclosure east of Thornton Farm, Ettington	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1002990
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Enclosures north of Old Pasture Farm, Hampton Lucy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005714
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Site of building and enclosure 460 metres east of Hatton Rock Farm, Hampton Lucy	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005741
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Commercial company, multiple owners	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Medieval settlement remains at Hodnell Manor, Hodnell and Wills Pastures	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1020421
CONDITION:	Generally satisfactory but with minor localised problems	TREND: Improving
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Rectangular Earthwork on Nebsworth, Ilmington		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005734
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Animal burrowing - Rabbit - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Multivallate hillfort on Meon Hill, Quinton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1011372
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Jez Bretherton 0121 625 6855

SITE NAME:	Enclosures 1200 metres north of Salford Priors, Salford Priors		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005721
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Enclosures 550 metres east of King's Mead, Wellesbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005716
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Other	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854

SITE NAME:	Lower Shuckburgh		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	No significant change
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326

SITE NAME:	Southam		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Clare Eynon (LPA) 01789 260326

WARWICK



© Historic England

SITE NAME:	Hunningham Bridge, Hunningham / Weston under Wetherley	Hunningham Bridge is a mid C17 structure of sandstone ashlar spanning the river Leam and is currently in use as a public highway. The structure has now had extensive repairs following two incidents in 2015 which resulted in two demolished sections of the parapet. Unfortunately the bridge has been hit again since these repairs were completed. The bridge remains at risk until traffic management systems can be reviewed and installed at the site to protect the bridge from further incidents.
DESIGNATION:	Scheduled Monument, 2 LBs	
CONDITION:	Good	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1005770	Contact: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England Archive

SITE NAME:	Remains of Old Castle Bridge, Mill Street, Warwick
DESIGNATION:	Scheduled Monument and Listed Building grade II*, RPG grade I
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1005772 and 1035499

Late medieval bridge. Ownership of the remains is split three ways. Earlier proposals for stabilisation were very costly and beyond available resources. It has been proposed that ownership should be transferred to a trust who would co-ordinate restoration and funding package but this has not progressed. A fresh survey of condition and repair costs has been suggested to move things forward.

Contact: Aimee Henderson 0121 625 6854



© Historic England Archive

SITE NAME:	Masters House, Warwick
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1364850

The Leper Hospital of St Michael was founded in the C12. The Master's House survives and is a timber framed building of C15 date built upon C12 foundations. The timber frame and roof are in very poor condition and there are general structural problems throughout the building which has been propped to prevent collapse and covered in tarpaulins. Following the compilation of a repairs specification and cost plan to inform decision making, a viability appraisal by the West Midlands Building Preservation Trust to develop the Master's House and surrounding site for social housing is now underway.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St Mary including Beauchamp Chapel, Warwick
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	D (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1035500

St. Mary's is a Grade I parish church which was founded as Collegiate Church in 1123. The nave, aisles, transept and tower were rebuilt by Sir W Wilson after the great fire of 1694, although the chancel, dating from the C14 remained. The Beauchamp Chapel, built in 1442-63, also escaped the fire and is an excellent example of Perpendicular design. The Church has remarkable stained glass windows, fan vaulted ceilings and stone carvings. St Mary has undergone much repair in recent years but the stonework is soft Arden stone and the tower requires urgent repair as it suffers from falling masonry.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Michael, Rugby Road, Weston under Wetherley
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1325524

Parish church in red sandstone ashlar situated in an elevated position with evidence of a C12 church in the north and south walls of the chancel. The red sandstone stonework is in extremely poor condition at all levels with delamination, open joints and hollow sections, erosion, cracking and inappropriate repairs. Some structural cracks are present. Deformation on the south elevation appears stable.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Roman settlement at Glasshouse Wood, Ashow / Kenilworth	
DESIGNATION:	Scheduled Monument, part in RPG grade II*	LIST ENTRY NUMBER: 1005723
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Digging	NEW ENTRY?: No
OWNER TYPE:	Mixed, multiple owners	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Circular ditches enclosures south west of Wiggerland Wood Farm, Bishop's Tachbrook	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1003740
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Guy's Cave hermitage and other rock cut chambers at Guy's Cliffe, Leek Wootton and Guy's Cliffe		
DESIGNATION:	Scheduled Monument, LB grade II*, RPG grade II	LIST ENTRY NUMBER:	1019129
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Religious organisation	CONTACT:	Neil Rimmington 0121 625 6856
<hr/>			
SITE NAME:	Wedgnoek Park pale, dam, two watermill sites, bridge and hollow way 200 metres north east of Goodrest Farm, Leek Wootton and Guy's Cliffe		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1013159
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Stock erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
<hr/>			
SITE NAME:	Enclosures 410 metres north east of Sherbourne parish church, Sherbourne		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005711
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Aimee Henderson 0121 625 6854
<hr/>			
SITE NAME:	Warwick Castle (uninhabited parts), Warwick		
DESIGNATION:	Scheduled Monument, RPG grade I	LIST ENTRY NUMBER:	1005757
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Neil Rimmington 0121 625 6856
<hr/>			
SITE NAME:	Enclosures and drove road 90 metres south of Manor House Farm, Wasperton		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005712
CONDITION:	Unknown	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Aimee Henderson 0121 625 6854
<hr/>			
	SITE NAME:	Stoneleigh Abbey, Stoneleigh / Ashow	Complex multi-phase landscape, incorporating medieval deer park and work by Repton, Nesfield and Percy Cane. Deer park now a golf course. Business park and residential enclaves built within historic landscape. Impressive programme of restoration of cascades, bridges and other water features through Natural England's Environmental Stewardship scheme, with a further phase of work under way. Other parts of the historic estate remain vulnerable.
	DESIGNATION:	Registered Park and Garden grade II*, 30 LBs, 2 SMs, part in CA	
	CONDITION:	Generally satisfactory but with significant localised problems	
	VULNERABILITY:	High	
	TREND:	Improving	
	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	
LIST ENTRY NUMBER:	1000377	Contact: Kim Auston 0117 975 0696	

© Historic England

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Guy's Cliffe, Warwick / Leek Wootton and Guy's Cliffe / Old Milverton
DESIGNATION:	Registered Park and Garden grade II, 9 LBs, SM
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001602

Picturesque landscape either side of the River Avon. Main house is a ruinous shell. Chapel now a Masonic temple. Derelict gardens periodically cleared by volunteers. Most of the park has been ploughed and the majority of parkland trees lost. Previous risk of the local planning authority allocating intrusive urban expansion has now receded.

Contact: Kim Auston 0117 975 0696

WEST MIDLANDS

BIRMINGHAM



© Historic England

SITE NAME:	British Rail Goods Office (Curzon Street Station), Birmingham
DESIGNATION:	Listed Building grade I
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1343086

Original terminus of the London to Birmingham railway by Philip Hardwick. Built in 1838 in the Ionic style. The building is owned by the City Council and has been vacant for over 10 years. Repairs to the roof have been undertaken, but water ingress is still a problem and there have been stonework falls from the cornice. Potential for redevelopment in association with HS2 exists; the building is included in the Birmingham Curzon HS2 Masterplan in the 'Visit' quarter. A planning application has been approved for its re-use as offices and as part of HS2.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Grand Hotel, Colmore Row, Birmingham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	F (F)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1391246

A large Victorian hotel, shops and offices dating from 1875. Following a major refurbishment the building is watertight and the shops and offices are occupied. The hotel remains vacant and requires very substantial investment. The decorative plaster ceiling in the Grosvenor Suite which contributes much to the significance of the building is in very poor condition. Plans are in place for its repair as it will be a key part of the hotel.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Methodist Central Hall, Corporation Street, Birmingham
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1075607

A substantial building constructed in 1903-4 by E and JA Harper in red brick and terracotta. The ground floor is in various retail uses, some vacant, the upper floors are vacant. Planning approval and Listed Building Consent was previously granted for conversion to mixed office/residential use, but this was not implemented and has now expired. Birmingham City Council negotiated with the owner to undo unauthorised works, but the building continues to deteriorate with extensive vegetation at upper levels.

Contact: Katriona Byrne 0121 625 6858

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	The Red Lion Public House, Soho Road, Birmingham
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1276278

Public house, built 1901-2 by James & Lister Lea for the Holt Brewery Company. Built of red brick with terracotta facade, the building is of unusual richness and completeness with interior detailing comparable with best surviving examples nationally. Leaking roofs and windows and ingress of pigeons have caused significant problems. A new owner undertook urgent works, including repairs to roof, and gained Listed Building Consent for re-use as a public house restaurant. It was sold again in 2016 and the new owner is seeking permission for a cafe, restaurant and media centre.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Perrott's Folly, Waterworks Road, Edgbaston
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Other not for profit group
LIST ENTRY NUMBER:	1076123

Built in 1758 by John Perrott as a folly adjacent to his house (long demolished). A six storey structure with circular stair tower attached. Adjoining waterworks tower said to be inspiration for Tolkien's 'The Two Towers'. Urgent repairs to address immediate structural problems have been completed. A business plan for long-term future use and completion of repairs is necessary.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	303 Icknield Street, Hockley
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	B (A)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1291556

Built 1883, by Martin and Chamberlain, in brick and terracotta with tiled roof as the master's house to the Icknield Street School. Now derelict and in poor repair with risk of rapid deterioration. The upper storey windows and door are now boarded up and remained vacant for some years. In July 2017 the lessees contacted the Local Authority and Historic England to suggest ways to repair Icknield Street School. The plan is for 303 to house an on-site caretaker who will look after both assets. A Listed Building Consent application for the repairs of the property will be submitted in 2017.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Horseshoe shaped former stables and stores (City of Birmingham Engineers Depot), 23 Shepcote Street, Ladywood
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1220997

Former stables, originally a Corporation Depot built in 1873, the design was the winning competition entry by WH Ward. All four buildings are in poor condition. The Roundhouse is mainly vacant and clearly deteriorating. The Canal and River Trust is working with the National Trust on a mixed use scheme for re-use with a visitor centre and canal related activities. The project has been awarded a Heritage Lottery Fund grant and is in the development stage.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Public Baths, Moseley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1076274

Municipal baths with lavish terracotta decoration and complete interiors. The baths were opened in 1907 as an addition to the Free Library (1895) forming an impressive group of public buildings. Threat of closure is pending and the building continues to deteriorate. Historic England provided grant aid in 2016 for the Moseley Road Baths Action Group to undertake an options appraisal. A Moseley Road Baths Coalition group has been formed, which includes the National Trust. The condition survey and the costs of repair are being updated in 2017 by Birmingham City Council.

Contact: Rhodri Evans 0121 625 6886

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Former School of Art, 496-500 Moseley Road, Moseley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343102

Moseley School of Art was designed by Bidlake and built in 1899. It was bought from the Council in the 1980s by the Moseley Muslim Community Association (MMCA). The building is now suffering from neglect; spalling stonework and leaking roofs are problems. Historic England and the Architectural Heritage Fund have worked with the MMCA to take a project for more intensive use forward and a stage one Heritage Lottery Fund grant has been awarded.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	100 Sampson Road, Sparkhill
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1076179

Built in 1901 as the vicarage to St Agatha's Church in Sparkbrook and designed in an Arts and Crafts style by local Birmingham architect, WH Bidlake. Formerly converted to flats by a housing association, the building is now in private ownership but has been subject to heritage crime and is now suffering from dry rot and isolated structural issues. Localised repairs have been carried out, but more needs to be done; meanwhile it continues to exhibit a lack of maintenance with missing tiles, decaying windows and other issues.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Edward Road Baptist Church, Edward Road, Birmingham
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343405

This is a good example of the Birmingham Terracotta School's work which combines Romanesque and Perpendicular details. There is evidence of damp at high level, the roof needs attention, the gutters need cleaning and the joints to brick and terracotta blocks are badly eroded.

Contact: Cristina Gardiner 0121 625 6850




© Historic England

SITE NAME:	Parish Church of St Aidan, Herbert Road B10, Birmingham
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343050

Designed by TF Proud in 1893, this church is a striking example of local red bricks and buff terracotta, designed in the Perpendicular style with a lofty nave and clearstory windows. Two further bays and the apsidal baptistery were added in 1898. The nave north roof is in poor condition with many slipped tiles. Rainwater goods are also in poor condition. The church building also suffers from dampness and the base of some of the columns show the presence of salt efflorescence.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St George, Westbourne Crescent, Edgbaston, Birmingham
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	F (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1211414

Constructed in three separate phases to the design of JJ Scoles (1836-38), Charles Edge (1855-7) and JA Chatwin (1884-5) in a light coloured Alvechurch sandstone and a slate roof. The two southern aisles were part of the original first phase and the chancel north east vestry and tower were added to these in the second phase. The current large nave and chancel replaced the former south aisle. The high level stonework is in poor condition and in need of urgent repairs because of expanding iron fixings. A Grant for Places of Worship is currently addressing repairs and will be completed by Autmn.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Alban the Martyr, Conybere Street, Highgate
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1290539

Large church designed by JL Pearson in 1879-81 in the Early English style constructed in red brick with sandstone ashlar. The terracotta tiled roof has passed the point of repair and needs to be replaced urgently. The C20 extensions are also in poor condition and in need of repair. Rainwater goods need attention and there is work to be done to the perimeter of the apse because the external ground level is higher than the internal level.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Icknield Street School, Icknield Street, Hockley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Local authority, multiple owners
LIST ENTRY NUMBER:	1076315

School designed in 1883 by Martin and Chamberlain. The building is occupied as a Hindu temple for the purpose of worship and community use. The roof to the fire-damaged area has been repaired, but more comprehensive repair of the building is needed. Rainwater goods are in poor shape, resulting in rainwater entry affecting both roof and walls. Negotiations between the owners and the Council to determine how the building can be protected are taking place.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Bishop Latimer Memorial Church of All Saints, Handsworth New Road, Winson Green
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1343061

A very large brick church designed by Bidlake and erected in 1903, with important interior. The church is now occupied by the Seventh Day Adventist Church under a lease from the Church of England. Since 2015 it has carried out some repairs. Historic England provided a Repair Grant for the development phase in 2015 to prepare drawings and specifications. A further Historic England Repair Grant was accepted in 2016 and repairs are due to complete in 2017.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Kent's Moat	LIST ENTRY NUMBER:	1020538
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally satisfactory but with significant localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Local authority		

SITE NAME:	Austin Village	NEW ENTRY?:	Yes
DESIGNATION:	Conservation Area	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		

SITE NAME:	Barnsley Road	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 4 LBs	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
LB Listed Building
LPA Local Planning Authority
NP National Park
RPG Registered Park and Garden
SM Scheduled Monument
UA Unitary Authority
WHS World Heritage Site

SITE NAME:	Digbeth / Deritend	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 12 LBs	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Low		
SITE NAME:	Four Oaks	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 28 LBs	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		
SITE NAME:	Ideal Village, Bordesley Green	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		
SITE NAME:	Lozells and Soho Hill	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 38 LBs	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	High		
SITE NAME:	School Road	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 2 LBs	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Low		
SITE NAME:	Steelhouse	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 8 LBs	TREND:	Unknown
CONDITION:	Very bad	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		
SITE NAME:	Warwick Bar	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 7 LBs	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Simon Delahunty-Forrest (LPA) 0121 464 8258
VULNERABILITY:	Medium		

COVENTRY



© Historic England

SITE NAME:	Cook Street Gate
DESIGNATION:	Scheduled Monument, LB grade I, part in RPG grade II, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1005908

The construction of this gate began in the early C14 and was completed later that century following a licence to crenellate in 1363. Inappropriate historic repairs, vulnerability to vehicle damage and stone erosion are all issues. The gatehouse is due to be transferred from Coventry City Council to Historic Coventry Trust as part of a heritage partnership to address the repair and re-use of heritage assets that are no longer of strategic value to the City Council. An Historic England Repair Grant was accepted in 2016 to address assorted external building fabric repairs.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England Archive

SITE NAME:	Coventry City Walls
DESIGNATION:	Scheduled Monument, 2 LBs, part in RPG grade II, 2 CAs
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	D (B)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1002979

The remains of Coventry City walls include several lengths of C14 city defences. Historic England funded a conservation management plan for the walls in 2010 which the City Council is now in the process of implementing. An Historic England Repair Grant was accepted in 2016 to address assorted building fabric repairs to both Swanswell and Cook Street gatehouses and the connecting length of wall between them: project development works are due to take place this year with repair works planned for 2018.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Basement on site of Old Star Inn, Earl Street, Coventry
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1115642

Late medieval cellar of an inn now incorporated in the Civic Centre. Significant erosion of the sandstone took place as a result of water damage. The stone vault was temporarily propped in 2008 and damaged stonework repaired. Since then the stone structure has been steadily drying out. The next phase of work will be to replace the eroded ribs on the vault.

Contact: Steven McLeish 0121 625 6884




© Historic England

SITE NAME:	The Charterhouse, London Road
DESIGNATION:	Listed Building grade I and Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Charity (heritage)
LIST ENTRY NUMBER:	1076621 and 1005901

Founded as a Carthusian Monastery dedicated to St Anne, the surviving building is a mixture of stone, brick and timber frame construction incorporating centuries of change and adaptation. Exceptional and vulnerable wall paintings survive from the C15 and C16. The clay tile roof is in poor condition and there is evidence of water damage within the building. Now in the ownership of the Historic Coventry Trust, the building is part of a major regeneration project supported by a Heritage Lottery Fund grant.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Nonconformist Chapel to the Cemetery, London Road, Coventry
DESIGNATION:	Listed Building grade II*, RPG grade I, CA
CONDITION:	Fair
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1076624

Cemetery chapel 1846-47, probably by GH Stokes, at southern end of the mid C19 cemetery, landscaped by Joseph Paxton in an informal style. The building remains without a use and in a vulnerable condition. The Historic Coventry Trust has plans for the cemetery to become part of a Heritage Park, their options appraisal completed as part of these plans has identified potential for re-use of the chapel as an office. The Trust is in negotiations with the City Council regarding asset transfer for the cemetery and the chapel. An application to the Heritage Lottery Fund is proposed.

Contact: John Tiernan 0121 625 6839



© Coventry HER 2014

SITE NAME:	Numbers 36 and 37 and archway in between (Whitefriars Gate), Much Park Street
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1087114

This C14 postern gatehouse of the Carmelite Friary is built of sandstone and tile with later repairs in brickwork. The building was subject to heritage crime in 2008 and later repaired: it has remained vacant since then and is slowly deteriorating. Inappropriate window coverings, erosion of sandstone and mortar joints, continuing threat of heritage crime and rotting timbers in the ceiling of the archway are all issues to be addressed. The Historic Coventry Trust plans to re-use the building and is to apply for a Heritage Enterprise grant from the Heritage Lottery Fund.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Church of St Mark and boundary walls to Stoney Stanton Lane and Bird Street
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I 104904

The church of St Mark was built in 1869 and consists of a clerestoried nave with aisles, a chancel, north porch and south vestry: a tall bellcote is located at the west end of the north aisle. A church hall extension was added to the south side in 1962. Following closure in 1973, the church was internally remodelled and converted to a hospital outpatient's department. Now relicensed for public worship, it has a catalogue of building fabric defects that require urgent attention including reroofing works, the renewal of rainwater goods, drainage and assorted high level masonry repairs.

Contact: John Tiernan 0121 625 6839



© Historic England

SITE NAME:	Church of St John the Baptist, Fleet Street, Coventry
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I 342889

The Church of St John the Baptist is located at the head of Spon Street in the city centre. Built in the mid C14, it was a collegiate church and is largely Perpendicular in appearance with a crossing tower, transepts, clerestories to nave and chancel and aisles. Changes of plan are visible in several places together with alterations to the fabric. The red sandstone used in its construction is of variable quality and its repair is an on-going issue, in particular, the condition of the nave clerestory. Transept roof coverings will shortly require renewal due to material failure.

Contact: John Tiernan 0121 625 6839

SITE NAME:	Allesley Castle	LIST ENTRY NUMBER:	I 005907
DESIGNATION:	Scheduled Monument	TREND:	Declining
CONDITION:	Generally unsatisfactory with major localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Local authority		

SITE NAME:	Priory ruins	LIST ENTRY NUMBER:	I 005902
DESIGNATION:	Scheduled Monument, 2 LBs, CA	TREND:	Declining
CONDITION:	Generally satisfactory but with minor localised problems	NEW ENTRY?:	No
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	CONTACT:	Aimee Henderson 0121 625 6854
OWNER TYPE:	Local authority		

SITE NAME:	Lady Herbert's Garden, Coventry	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 8 LBs, RPG grade II, 2 SMs	TREND:	Deteriorating significantly
CONDITION:	Very bad	CONTACT:	Chris Patrick (LPA) 02476831271
VULNERABILITY:	Low		

SITE NAME:	London Road, Coventry	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade I, SM	TREND:	Improving
CONDITION:	Very bad	CONTACT:	Chris Patrick (LPA) 02476831271
VULNERABILITY:	Low		

SITE NAME:	Naul's End, Coventry	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 2 LBs	TREND:	Deteriorating
CONDITION:	Poor	CONTACT:	Chris Patrick (LPA) 02476831271
VULNERABILITY:	Low		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

DUDLEY



© Historic England

SITE NAME:	Triangular Crane, Bumble Hole Boat Yard, Dudley
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	I005884

C19 triangular boat crane, in very poor condition. Historic England funded a report on the condition and repair of the monument in 1997. An application for Historic England funding was made but later withdrawn as no match funding was available for the repairs. The crane collapsed in 2002 and sections of structure remained stored in the yard. A joint initiative between Historic England, Canal and River Trust and the Black Country Museum is currently investigating repair/reinstatement of the structure.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St John, Leys Road, Brockmoor
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I229092

A good example of a neo-Norman Commissioners' Church built in 1844-5 by Thomas Smith. Built in dark brick with yellow dressings it has sandstone carved faces to the kneelers, stone coped shallow pitched gables and a Welsh slate roof. The church is in poor condition. The gutters and downpipes are in poor condition. The brickwork shows open joints as do the sandstone copings to the gables. The church applied for a Heritage Lottery Fund Grant for Places of Worship and was awarded a Development Grant in June 2016.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Edmund, Castle Street, Dudley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I287455

Situated in the centre of Dudley, this is a red brick church built in the Palladian style in the 1720s. Shallow tile roofs slope to parapets finished with stone dressings which are also a distinctive feature of the round headed windows and the tower. Vegetation growing out of the tower is impacting on high level stonework and is a significant cause for concern. A Heritage Lottery Fund Grant for Places of Worship was awarded in 2015. Stage 1 of the grant has been completed and works are expected to start in 2018.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Parish Church of St Thomas, High Street, Dudley
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I075998

Large Georgian church built in Perpendicular style designed by William Brooks from 1815 to 1818. The current church is a replacement of a medieval chapel, the remains of which are visible in the crypt. The church was awarded a Heritage Lottery Fund Grants for Places of Worship in 2014 for high level stonework which is shaling away in large sections and these repairs have been completed although there are more repairs needed to the pinnacles and parapet walls.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St James the Great, Salop Street, Dudley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I270305

A Commissioners' Church of the mid C19, designed by William Bourner. Sister church to St John the Evangelist, Kate's Hill. The church is built of limestone with ashlar stone dressings. Emergency roof repairs carried out in 2015 have revealed extensive significant problems with the roof of the nave.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.


- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Former Church of St John the Evangelist, St Johns Road, Dudley
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	B (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	I393300

St John's the Evangelist (Kate's Hill) was designed in the Gothic lancet style by William Bourner and is the sister church to St James, Eve Hill, also in Dudley. The church opened in 1849. Due to poor fabric condition and the costs of repairs, the church closed in 2002. The formal process of closure was undertaken and completed and the church has been leased to a building preservation group which is active in carrying out daily maintenance whilst seeking sources of funding for its repair. However the church is still being used for worship on a regular basis.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	The Redhouse, Whitehouse and Newhouse glassworks	
DESIGNATION:	Scheduled Monument, LB grade II*, CA	LIST ENTRY NUMBER: I021378
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Mixed, multiple owners	CONTACT: Rhodri Evans 0121 625 6886

SITE NAME:	Wychbury Camp (see also Bromsgrove, Worcestershire), Hagley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: I005900
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Brierley Hill High Street	
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Low	CONTACT: Jayne Pilkington, CMIFA, IHBC (LPA) 01384 814168

SITE NAME:	Stourbridge Branch Canal (Canal Street)	
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Low	CONTACT: Jayne Pilkington, CMIFA, IHBC (LPA) 01384 814168

SITE NAME:	Wollaston	
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Deteriorating
VULNERABILITY:	Medium	CONTACT: Jayne Pilkington, CMIFA, IHBC (LPA) 01384 814168

SITE NAME:	Wordsley Church	
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?: No
CONDITION:	Poor	TREND: Deteriorating
VULNERABILITY:	Medium	CONTACT: Jayne Pilkington, CMIFA, IHBC (LPA) 01384 814168

PRIORITY CATEGORIES


- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SANDWELL



© Historic England Archive

SITE NAME:	Soho Foundry, Foundry Lane, Smethwick
DESIGNATION:	Listed Building grade II*, SM
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1268451

Foundry built in 1795: the world's first integrated steam engine manufactory, established by Boulton & Watt. Historic England and the Local Authority grant aided a temporary roof to stabilise the structure in 2009. Discussions continue with the owners and the Local Authority to ensure maintenance of the temporary roof and to find a new use.

Contact: Nick Molyneux 0121 625 6857



© Historic England

SITE NAME:	Waterloo Hotel, Shireland Road, Smethwick
DESIGNATION:	Listed Building grade II*
CONDITION:	Fair
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	E (E)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1261644

The Waterloo Hotel was built in 1907 by Wood and Kendrick for local brewers, Mitchells & Butler, in the baroque style with terracotta dressings. This is a near complete example of an Edwardian showpiece pub and commercial hotel, which retains many interior features including the ornately tiled basement grill room. The upper floors have been converted into flats and are partially occupied. Discussions are underway with potential users for the ground floor and basement grill room.

Contact: Sarah Lewis 0121 625 6846

SITE NAME:	Chances Glassworks, Smethwick	
DESIGNATION:	Scheduled Monument, 5 LBs	LIST ENTRY NUMBER: 1021387
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Commercial company, multiple owners	CONTACT: Rhodri Evans 0121 625 6886

SITE NAME:	Engine Arm Aqueduct, Warley	
DESIGNATION:	Scheduled Monument, LB grade II*	LIST ENTRY NUMBER: 1005904
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Improving
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Utility	CONTACT: Cristina Gardiner 0121 625 6850

SITE NAME:	High Street, West Bromwich, Black Country	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Very bad	TREND: No significant change
VULNERABILITY:	Low	CONTACT: Mark Stretton (LPA) 0121 569 4033

SITE NAME:	Market Place, Wednesbury, Black Country	
DESIGNATION:	Conservation Area	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Low	CONTACT: Mark Stretton (LPA) 0121 569 4033

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

WALSALL



© Historic England

SITE NAME:	Church of St Matthew, Church Hill, Walsall
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1116151

St Matthew's was rebuilt in the 1820s by Francis Goodwin. Its soaring spire is a local landmark and its Bath stone facades stand out in the street scene. The style of the church is predominantly Perpendicular, but C13 remains survive in the crypt. High level repairs are needed all over this complex building. A Heritage Lottery Fund and Historic England Repair Grants for Places of Worship enabled repairs to the north aisle and east end to be completed in 2015. Other sections of the church are also in need of repair.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Life and Light Mission Church (former Trinity Methodist Church), Union Street, Willenhall
DESIGNATION:	Listed Place of Worship grade II, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1077170

Built as a Methodist church in the 1860s, this large rendered church is in the Classical style, with round headed windows and pilasters, making it prominent on the street frontage. The render is loose in many areas allowing water to enter the building.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Bloxwich High Street	NEW ENTRY?:	No
DESIGNATION:	Conservation Area	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	John Somers (LPA) 01922 655537
VULNERABILITY:	Low		

SITE NAME:	Bradford Street, Walsall	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 5 LBs	TREND:	Deteriorating
CONDITION:	Very bad	CONTACT:	John Somers (LPA) 01922 655537
VULNERABILITY:	Medium		

SITE NAME:	Bridge Street, Walsall	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 12 LBs	TREND:	Improving
CONDITION:	Very bad	CONTACT:	John Somers (LPA) 01922 655537
VULNERABILITY:	Low		

SITE NAME:	Caldmore Green, Walsall	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, LB grade II	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	John Somers (LPA) 01922 655537
VULNERABILITY:	Low		

SITE NAME:	Church Hill, Walsall	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 17 LBs, RPG grade II	TREND:	Improving
CONDITION:	Very bad	CONTACT:	John Somers (LPA) 01922 655537
VULNERABILITY:	Low		

SITE NAME:	Elmore Green, Bloxwich	NEW ENTRY?:	No
DESIGNATION:	Conservation Area, 3 LBs, SM	TREND:	No significant change
CONDITION:	Very bad	CONTACT:	John Somers (LPA) 01922 655537
VULNERABILITY:	Low		

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

WALSALL / SANDWELL



© Historic England

SITE NAME:	Great Barr Hall, Walsall
DESIGNATION:	Registered Park and Garden grade II, 3 LBs, part in CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1001202

Parkland and pleasure grounds, partly by Humphry Repton and John Nash. Much of historic park was built over as a hospital in C20, in turn replaced by a modern housing estate circa 2005. Due to longstanding lack of regular maintenance, the pleasure grounds and planting around the lakes are completely overgrown. The remaining area of the park is also in poor condition, and the banks of the lakes are being eroded around the outfalls and spillways. The hall is dilapidated and at risk. Proposals for enabling development remain under consideration by the Local Authority.

Contact: Kim Auston 0117 975 0696

WOLVERHAMPTON, CITY OF



© Historic England

SITE NAME:	The Greyhound and Punchbowl Inn (formerly Stoke Heath Manor House), High Street, Bilston
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1201819

Mid-C16 manor house, restored in the 1930s. Of timber framed construction, strengthened with concrete skin in the 1930s. Now suffering complex structural problems to the supporting concrete frame requiring a long term solution. An Historic England engineer has prepared a preliminary report. A more detailed structural survey and investigation needs to be carried out to establish the most appropriate method of repair.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Church of St Leonard, Church Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1282492

This church was built in 1825 to designs by Francis Goodwin, and restored in the 1880s by Ewan Christian. It is in the neoclassical style, finished in render with elegant round headed windows and a fine octagonal tower. The interior has decorative plaster ceilings and balconies. Leaking parapet gutters are affecting the render externally and the plaster internally.

Contact: Cristina Gardiner 0121 625 6850




© Historic England

SITE NAME:	Church of St Martin and attached cloister and vicarage, Dixon Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1282500

Church, cloister and vicarage built 1938-9 by Lavender and Twentyman. Brick Modernist church with pantile roofs, coped gables and parapets. The elevations are plain except for the statue of St Martin by Donald Potter on the west facade above the entrance. The interior is remarkably intact. The church was originally lined with asbestos, which is still in place. The roof and gutters are in need of repair so that leaks do not disturb the asbestos below. Previous water ingress meant the building was closed until the source of the leaks was repaired. Subsequently a comprehensive repair is needed.

Contact: Cristina Gardiner 0121 625 6850



© Historic England

SITE NAME:	Catholic Church of St Mary and St John, Snow Hill, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	F (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1208140

Roman Catholic church built 1851-5 by Charles Hansom and extended 1879-80. Built in ashlar stone with a slate roof, it has an apsidal chancel and French Gothic treatment. It has a rich interior with fine fittings and is a good example of a mid-Victorian Roman Catholic church. High level stonework is very poor, causing a hazard and the gutters and rain water pipes are also in need of repair. A Heritage Lottery Fund Grant for Places of Worship was accepted in 2015.

Contact: Cristina Gardiner 0121 625 6850

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA Conservation Area
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site



SITE NAME:	Church of St Luke, Upper Villiers Street, Wolverhampton
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Very bad
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1293038

Gothic Revival church by GT Robinson of Leamington built in polychromatic brickwork in 1860. The church is large and its soaring, decorated spire is a local landmark in the Blakenhall area. Dry rot was addressed some years ago, however many other issues remain for this very large building.

Contact: Cristina Gardiner 0121 625 6850

© Historic England

SITE NAME:	Bilston Canal Corridor		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Jon Beesley (LPA) 01902 555622

SITE NAME:	Bilston Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Jon Beesley (LPA) 01902 555622

SITE NAME:	Bushbury Hill		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jon Beesley (LPA) 01902 555622

SITE NAME:	Cleveland Road		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Jon Beesley (LPA) 01902 555622

SITE NAME:	Park		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jon Beesley (LPA) 01902 555622

SITE NAME:	Springfield Brewery		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving significantly
VULNERABILITY:	High	CONTACT:	Jon Beesley (LPA) 01902 555622

SITE NAME:	The Oaks (Merridale Road)		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Jon Beesley (LPA) 01902 555622

SITE NAME:	Union Mill		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	High	CONTACT:	Jon Beesley (LPA) 01902 555622

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Worcester Street		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Jon Beesley (LPA) 01902 555622

WORCESTERSHIRE**BROMSGROVE**

© Historic England

SITE NAME:	Temple of Theseus, Hagley Hall, Hagley
DESIGNATION:	Listed Building grade I, RPG grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1348599

Doric temple of 1758 designed by James 'Athenian' Stewart. It stands in a Grade I registered landscape park 800 metres north of Hagley Hall. It is separated from the rest of the estate by the A456; this relatively isolated location has rendered it vulnerable to vandalism so security fencing has been erected. Discussions continue with the owner on a strategy to secure the future of the building. A new visitor centre on the estate gained planning permission in 2014 but works have not started yet.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Church of St Laurence, Bear Hill, Alvechurch, Alvechurch
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100225

Large parish church. Mostly rebuilt between 1860 and 1861 by W Butterfield retaining only a C15 tower which was remodelled in 1676. Badly eroded sandstone is affected by damp, especially on the north side and in the tower. Rainwater goods are in poor condition and the leaded windows are also deteriorating. The church was awarded a Heritage Lottery Fund Grant for Places of Worship in February 2017 to fund repairs which is currently in development.

Contact: Chris Miners 0121 625 6835




© Historic England

SITE NAME:	Christ Church, Catshill, Catshill and North Marlbrook
DESIGNATION:	Listed Place of Worship grade II
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1099541

Large suburban parish church. Nave and west tower built in 1838 by Harvey Eginton and the east end of chancel and flanking chapels rebuilt by J A Chatwin in 1887, mostly in the Early English style. Red sandstone ashlar with slate roofs. The sandstone is heavily eroded with harmful vegetation growth. Many leaks have sprung from the failing parapet gutters.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Michael, Hanbury Road, Stoke
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100179

Large rural parish church. Nave with flanking aisles, chancel with four-stage south tower and north chapel. C12 core with C13 additions and C19 rebuilding of north and west walls, and additions of entrance porch and vestry. Mostly sandstone ashlar walls with plain tile roofs. The tower has structural problems with missing stonework on the south east corner and the shingled spire has bird damage holes. A Heritage Lottery Fund Grant for Places of Worship has been applied for and a decision is due in September 2017.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Church of St Bartholomew, Church Lane, Tardebigge, Tutnall and Cobley
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1100167

Parish church. Nave, west tower and spire with Baroque bell stage from 1777 by Francis Hiorn. The chancel was added in 1880. The sandstone ashlar is heavily eroded. The downpipes have leaked and seriously degraded the stone behind them.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Hewell Grange, Tutnall and Cobley / Bentley Pauncefoot
DESIGNATION:	Registered Park and Garden grade II*, 20 LBs, CA
CONDITION:	Extensive significant problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000886

Multi-phase landscape, including work influenced by 'Capability' Brown and Humphry Repton. Another major period of activity took place towards the end of C19 when the current house was built. Post-war development by the Prison Service has had a major impact on the legibility of the design. A management plan and partnership with the County Gardens Trust has led to renewed interest in and care for the designed landscape, including restoration of a bridge and the commissioning of a Statement of Significance for the earlier, ruined mansion at the heart of the landscape.

Contact: Kim Auston 0117 975 0696

SITE NAME:	Bromsgrove Town Centre, Centred on the High Street/Worcester Road,	
DESIGNATION:	Conservation Area, 53 LBs	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Low	CONTACT: Mary Worsfold (LPA) 01527 881329

MALVERN HILLS



© Historic England

SITE NAME:	Stone Farmhouse and attached Hop Kiln, Bromyard Road, Broadwas
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1082977

An attractive C15 timber framed farmhouse which originated as a cruck framed hall house and was enlarged in the C16 and C19; there is a late C19 brick hop kiln attached on the rear gable. The building has a high quality medieval roof and timber framing. The condition of the hop kiln roof is very bad. The house roof tiling is very bad in places and the timber framing has frame members missing from the south gable and is in poor external condition elsewhere.

Contact: Katriona Byrne 0121 625 6858



© Historic England

SITE NAME:	Mythe Bridge (that part in Civil Parish of Bushley), Tewkesbury Road, Bushley
DESIGNATION:	Listed Building grade II*
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1238445

Road bridge over the River Severn. Built 1823-26 by Thomas Telford. Cast iron bridge of six segmental arched lattice beams, latticed roadway beam with latticed ironwork filling the spandrels. Each abutment has inner and outer sandstone piers separated by six brick arched tunnel vaults with cast iron colonettes. The ironwork of the balustrades is rusting at the connections. The sandstone piers, especially above the roadway level, are severely fractured and eroded, and some have been covered in excessive and harmful ivy growth. Also included in the South West Heritage at Risk Register.

Contact: John Ette 0117 975 0687

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Chapel and Cloister at the Convent of the Holy Name, Ranelagh Road, Malvern
DESIGNATION:	Listed Building grade II*, CA
CONDITION:	Poor
OCCUPANCY:	Vacant/not in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Commercial company
LIST ENTRY NUMBER:	1082736

Former chapel designed by Comper & Bucknell in 1891-3 which forms part of a complex of buildings associated with the former Convent of the Holy Name. The building has been redundant for some years following the closure of the convent. The site is subject to applications for residential redevelopment, however the chapel is suffering from blocked gutters and poor roofs. The future of the chapel will be an integral part of any successful proposals for the redevelopment of the area.

Contact: Steven McLeish 0121 625 6884



© Historic England Archive

SITE NAME:	Church of St John, Mamble
DESIGNATION:	Listed Place of Worship grade I
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081406

The Blount Chapel on the north side of the chancel has been roofless for a long while. The bricks are starting to show severe effervescence (crystalline deposits on the bricks) at high level possibly as a result of the rebuilding of the brick and tile coping of the wall head. Harmful ivy growth is a problem on the north side of this chapel.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Bartholomew, Bayton, Bayton
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1081471

Small rural parish church in exposed hilltop location. Mainly C12 core of the nave and the chancel masonry. C15 nave roof. West tower 1817. Roof tiling failing and water ingress beginning to take its toll on the internal plasterwork. Chronic damp problem at low level resulting in stone erosion and the wood block flooring is adversely affected. Considerable masonry erosion around some windows and cement mortar pointing over lime is causing masonry erosion elsewhere. Heritage Lottery Fund Grant for Places of Worship awarded in 2014. Roof repairs near completion but tower repairs still needed.

Contact: Chris Miners 0121 625 6835



© Historic England Archive

SITE NAME:	Church of St Mary, Church End, Hanley Castle
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Poor
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1349232

Large rural parish church. Largely C14 nave and north aisle with C17 rebuilt tower and east end. Interior is from the 1858 restoration. The tiled roofs of the nave and south porches need renewal. The sandstone ashlar needs localised repair.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Priory Church of St Mary and St Michael, Church Street, Malvern
DESIGNATION:	Listed Place of Worship grade I, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1082794

Large medieval priory church which dominates the centre of Malvern. Overall in fair condition but there is a major problem with the medieval stained glass which needs urgent repair. Other problems are the high level stonework of the tower and the high level masonry of the windows on the south side.

Contact: Chris Miners 0121 625 6835

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



SITE NAME:	Church of St James, Norton, Norton Juxta Kempsey
DESIGNATION:	Listed Place of Worship grade II*
CONDITION:	Poor
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1242858

Rural parish church. The nave and chancel are Norman, the lower parts of the west tower are C14. Restored in 1874-75 with a modern church hall added on the north side. The lias stonework on the south west diagonal buttress of the tower has fallen and further stone falls present a danger to the public.

Contact: Chris Miners 0121 625 6835

© Historic England

SITE NAME:	Enclosure 110 yards (100 metres) north of St Bartholomew's Church, Grimley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005296
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Religious organisation	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Enclosure west of Church Farm, Grimley	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005315
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Religious organisation	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Moated site at Earl's Court, Rushwick	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1017229
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?: No
OWNER TYPE:	Other not for profit group	CONTACT: Aimee Henderson 0121 625 6854



SITE NAME:	Witley Court, Great Witley / Hillhampton / Little Witley
DESIGNATION:	Registered Park and Garden grade II*, 18 LBs, SM
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Declining
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000901

Pre-eminent C19 landscape in multiple ownership. Parts of the registered park and garden are well cared for but there are concerns about intrusive development in the park and a loss of parkland trees. The park is lacking in a Conservation Management Plan to inform future land management and potential development.

Contact: Kim Auston 0117 975 0696

© Historic England

SITE NAME:	Tenbury Wells, Tenbury	
DESIGNATION:	Conservation Area, 55 LBs, part in SM	NEW ENTRY?: No
CONDITION:	Very bad	TREND: Improving
VULNERABILITY:	Medium	CONTACT: Nicky Wardroper (LPA) 01684 862257

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

REDDITCH

SITE NAME:	Park Wood Camp, Ipsley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005334
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Neil Rimmington 0121 625 6856

SITE NAME:	Feckenham manorial moated site, Feckenham		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018361
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Visitor erosion - moderate	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Aimee Henderson 0121 625 6854

WORCESTER



© Historic England

SITE NAME:	City walls: section extending 130 feet (40 metres) from the back of No. 27 New Street to Windsor Row
DESIGNATION:	Scheduled Monument, CA
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1005282

Single section of the medieval city walls. A variety of repair and maintenance has taken place along the city walls in the past. A conservation management plan for the medieval defences has also been completed. Sections of the wall have been repaired with Historic England grant aid. The section which remains at risk is affected by damaging plant growth, it extends 40 metres from the back of number 27 New Street to Windsor Row.

Contact: Aimee Henderson 0121 625 6854




© Historic England

SITE NAME:	Edgar Tower entrance to the Cathedral Close
DESIGNATION:	Scheduled Monument, LB grade I, CA
CONDITION:	Poor
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	B (B)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1005306

Gatehouse at the east side of the College Green part of the Worcester Cathedral Precincts. The monument survives as a gatehouse tower that was rebuilt between 1300 and 1335, remodelled in 1369 and restored during the late 19th century. The gatehouse is constructed from coursed red sandstone with a concealed tile roof. It is rectangular in plan with octagonal embattled towers at each corner. There have been falls of sandstone and structural instability in the towers. The south side is under repair. An application for Historic England grant aid has been submitted for repairs to the north side.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Church of St Helen, Fish Street, Worcester
DESIGNATION:	Listed Place of Worship grade II*, CA
CONDITION:	Very bad
PRIORITY CATEGORY:	D (D)
OWNER TYPE:	Religious organisation
LIST ENTRY NUMBER:	1389795

Although its foundation predates that of the Anglo Saxon Diocese of c675, the church of St Helen dates primarily from C15 and consists of a nave and chancel with aisles, a south porch and a west tower. Several campaigns of repair and alteration were carried out in C19 which accounts for its existing Decorated Gothic exterior. The presence of iron metal cramps in conjunction with the red sandstone used for rebuilding is causing accelerated deterioration and failure of the facework. A Heritage Lottery Fund Grant for Places of Worship to assist with funding repair work was awarded in 2016.

Contact: John Tiernan 0121 625 6839

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

SITE NAME:	Lowesmoor, Worcester		
DESIGNATION:	Conservation Area, 15 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	James Dinn (LPA) 01905 721132

WYCHAVON

© Historic England

SITE NAME:	31 High Street, Droitwich Spa
DESIGNATION:	Listed Building grade II*, SM, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	D (C)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1296659

The solar wing of a C14 timber framed town house. The front range is rendered but incorporates exceptional timber work in the roof and ceiling structures. C17 extensions to the rear are in very bad condition with structural failure to the timber frame and walls. Failed rainwater goods and a roof in poor condition are letting water into the structure and rotting the frame. The building is only partly occupied. A scheme to convert and upgrade for use as an office, retail units and a residential unit has been approved. An Historic England Repair Grant was accepted in 2017 to undertake repairs.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	The Almonry, Merstow Green, Evesham
DESIGNATION:	Listed Building grade I, CA
CONDITION:	Very bad
OCCUPANCY:	Occupied/in use
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1302722

The building is run as a museum, but is in bad condition due to the clear signs of structural instability of the timber frame. Much of the stone slate roofing is nearing the end of its life and the timber frame has developed weaknesses and rot, particularly at sole plate level. The museum is currently looking to apply for a Heritage Lottery Fund grant, supporting repairs to the building and rejuvenation of the exhibits it holds.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Abbot Chyryton wall, Boat Lane, Evesham
DESIGNATION:	Scheduled Monument and Listed Building grade II
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1005501 and 1350435

Part of the outer precinct wall of Evesham Abbey, built by Abbot William de Chyryton between 1317 and 1344, which originally extended from the river to the Abbey. Previous grant aided consolidation has partially failed due to vandalism. Some parts of wall still in very bad condition, and wall footings are diminishing. Discussions are ongoing with associated parties to agree a long term solution.

Contact: Neil Rimmington 0121 625 6856



© Historic England

SITE NAME:	Abbot Reginalds Wall, Evesham Abbey, Evesham
DESIGNATION:	Scheduled Monument and Listed Buildings - I grade I; I grade II*, CA
CONDITION:	Very bad
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (C)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1005298 and 1081349; 1081350

Abbot Reginalds wall forms part of the main ecclesiastical complex of Evesham Abbey, fragments of which still survive. The rebuilding of the collapsed section and repairs to adjoining wall have been completed with grant aid. Sections of wall are still in poor condition and in need of an overall repair strategy. This is potentially going to be addressed through a Heritage Lottery Fund bid, currently underway, administered by the Evesham Abbey Trust.

Contact: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
C Slow decay; no solution agreed.

- D** Slow decay; solution agreed but not yet implemented.
E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
 Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

	<p>SITE NAME: Westwood House, Westwood</p> <p>DESIGNATION: Listed Building grade I, RPG grade II</p> <p>CONDITION: Poor</p> <p>OCCUPANCY: Part occupied/part in use</p> <p>PRIORITY CATEGORY: C (C)</p> <p>OWNER TYPE: Private, multiple owners</p> <p>LIST ENTRY NUMBER: 1173950</p>	<p>A grand hunting lodge from 1612 now converted to apartments. Square core with added diagonal wings of three and four storeys. Brick with sandstone dressings and very ornate slate covered roofs. There are now growing problems with the wall structure, windows and roof.</p> <p>Contact: Chris Miners 0121 625 6835</p>
	<p>SITE NAME: Church of St James, Bredicot, Bredicot</p> <p>DESIGNATION: Listed Place of Worship grade II</p> <p>CONDITION: Poor</p> <p>PRIORITY CATEGORY: A (A)</p> <p>OWNER TYPE: Religious organisation</p> <p>LIST ENTRY NUMBER: 1117084</p>	<p>Tiny church in the old rectory garden with three-bay nave/chancel, south porch and bellcote. Walls are rubble with ashlar stone dressings and tiled roof. Restored in 1843 by Perkins. The sandstone of the window masonry is heavily eroded and falling apart.</p> <p>Contact: Chris Miners 0121 625 6835</p>
	<p>SITE NAME: Church of St John the Baptist, Church Walk, Crowle, Crowle</p> <p>DESIGNATION: Listed Place of Worship grade II*, CA</p> <p>CONDITION: Poor</p> <p>PRIORITY CATEGORY: C (C)</p> <p>OWNER TYPE: Religious organisation</p> <p>LIST ENTRY NUMBER: 1081275</p>	<p>The original medieval church was demolished and rebuilt in the 1880s to designs by Frederick Preedy in the Decorated style with a tall west tower. The church is constructed from lias limestone rubble with ashlar stone dressings under a plain clay tile roof with decorative ridges. The roof and rainwater goods are in poor condition and minor repairs are required to the stonework. A Heritage Lottery Fund Repair Grant for Places of Worship was offered in February 2013 but not accepted, and therefore no work has resulted.</p> <p>Contact: Chris Miners 0121 625 6835</p>
	<p>SITE NAME: Church of St Nicholas, Dormston</p> <p>DESIGNATION: Listed Place of Worship grade I</p> <p>CONDITION: Poor</p> <p>PRIORITY CATEGORY: C (New entry)</p> <p>OWNER TYPE: Religious organisation</p> <p>LIST ENTRY NUMBER: 1116851</p>	<p>Small rural medieval parish church. Simple nave and chancel with a timber framed west tower that received a Heritage Lottery Fund and Historic England Repair Grant for Places of Worship in 2011. Persistent high levels of damp at low level in the nave and north chancel walls is now an urgent problem.</p> <p>Contact: Chris Miners 0121 625 6835</p>
	<p>SITE NAME: Church of St Andrew, St Andrew's Street, Droitwich Spa, Droitwich Spa</p> <p>DESIGNATION: Listed Place of Worship grade I, CA</p> <p>CONDITION: Poor</p> <p>PRIORITY CATEGORY: C (C)</p> <p>OWNER TYPE: Religious organisation</p> <p>LIST ENTRY NUMBER: 1167974</p>	<p>Large parish church in the centre of Droitwich. Sandstone ashlar with roofs of mixed materials. Nave and chancel flanked by tall aisles, with a truncated integral north tower set in the north range. A parish centre is attached on the south side. Tiled roof and the rainwater system of the north east chapel are leaking, causing decay in the C15 ceiling below. Other roofs and high level walls were repaired with a Heritage Lottery Fund and Historic England Repair Grant of Places of Worship 11 years ago.</p> <p>Contact: Chris Miners 0121 625 6835</p>

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site



© Historic England

SITE NAME:	Church of St Michael, Main Street, South Littleton, South Littleton	Small parish church with a c1200 nave, C14 chancel and north transept, and C15 west tower and south porch. Roofs, porch and chancel severely restored by Preedy in 1883. Lias coursed rubble with limestone ashlar dressings and clay tiled roof. Repairs to the stonework on the north side and the top of the tower have been completed. Work at the lower levels of the tower still remains to be completed.
DESIGNATION:	Listed Place of Worship grade II*, CA	
CONDITION:	Poor	
PRIORITY CATEGORY:	D (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1081303	

Contact: Chris Miners 0121 625 6835

SITE NAME:	Settlement site NNE of Fernhill Farm, Charlton	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005287
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Enclosures north east of Fernhill Farm, Charlton / Crophorne	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005286
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Evesham Abbey (remains of), Evesham	
DESIGNATION:	Scheduled Monument, 4 LBs, CA	LIST ENTRY NUMBER: 1005297
CONDITION:	Generally unsatisfactory with major localised problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Local authority	CONTACT: Neil Rimmington 0121 625 6856

SITE NAME:	Settlement site north of Spring Hill, Fladbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005352
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private, multiple owners	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Moated site 120 metres south east of Huntingdrop Farm, Hanbury	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1017311
CONDITION:	Extensive significant problems	TREND: Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

SITE NAME:	Double ditched enclosure north east of Wick village, Wick	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER: 1005310
CONDITION:	Unknown	TREND: Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?: No
OWNER TYPE:	Private	CONTACT: Aimee Henderson 0121 625 6854

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site



© Historic England

SITE NAME:	Westwood Park, Westwood / Hampton Lovett
DESIGNATION:	Registered Park and Garden grade II, 11 LBs
CONDITION:	Generally unsatisfactory with major localised problems
VULNERABILITY:	High
TREND:	Stable
NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners
LIST ENTRY NUMBER:	1000899

Gardens and pleasure grounds mostly late C19 and early C20. The vast majority of the park is in intensive cultivation and stripped of parkland trees. There is some post-war development in the vicinity of the main house. Residential development and expansion of a business park affect setting, particularly to north and east.

Contact: Kim Auston 0117 975 0696

WYRE FOREST



© Historic England

SITE NAME:	Severn Bridge including Flanking Arches and Balustrade, Bewdley
DESIGNATION:	Listed Building grade I
CONDITION:	Poor
OCCUPANCY:	N/A
PRIORITY CATEGORY:	C (New entry)
OWNER TYPE:	Local authority
LIST ENTRY NUMBER:	1100000

Bridge over the river Severn, 1798 by Thomas Telford. Mostly sandstone forming three arches over river, two towpath arches on south bank, 14 arches on north bank extending about 50 metres to south-east; balustrades on river part of stone, cast iron on land. The stone balustrade is suffering extensive stone erosion as are the flanking piers. The cast iron is rusting badly.

Contact: Chris Miners 0121 625 6835



© Historic England

SITE NAME:	Churchill Forge, Churchill Lane, Churchill, Churchill and Blakedown
DESIGNATION:	Scheduled Monument and Listed Buildings - 3 grade II, CA
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private, multiple owners
LIST ENTRY NUMBER:	1005274 and 1348320; 1100650; 1100651

Early C19 hand forge building that made spades and shovels, comprising three brick buildings, two water wheels, a dam and large mill pond. The forge is still in working order and is managed by a small local trust. The designation for the site has been reviewed in May 2016 and the buildings are now listed buildings only. The whole of the site is a scheduled monument. An overall management plan addressing the condition of the monument and surviving plant, and identifying priority works to address the principal risks is required and the spillway weir is the component at greatest risk.

Contact: Neil Rimmington 0121 625 6856



© Historic England Archive

SITE NAME:	Ribbesford House, Ribbesford
DESIGNATION:	Listed Building grade II*
CONDITION:	Very bad
OCCUPANCY:	Part occupied/part in use
PRIORITY CATEGORY:	A (A)
OWNER TYPE:	Private
LIST ENTRY NUMBER:	1329928

Mid C16 country house with late C17 and early C19 alterations. The building is largely unoccupied and has been neglected for many years with significant areas open to the elements. Urgent works are required in order to prevent further deterioration.

Contact: Cristina Gardiner 0121 625 6850

SITE NAME:	Gilgal, Stourport-on-Severn, East of Stourport Town Centre		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Peter Bassett (LPA) 01562 732928

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

- CA** Conservation Area
- LB** Listed Building
- LPA** Local Planning Authority
- NP** National Park
- RPG** Registered Park and Garden
- SM** Scheduled Monument
- UA** Unitary Authority
- WHS** World Heritage Site

SITE NAME:	Green Street, Kidderminster, Town centre		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Peter Bassett (LPA) 01562 732928

SITE NAME:	Ribbesford, 2 miles south of Bewdley		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Peter Bassett (LPA) 01562 732928

PRIORITY CATEGORIES

- A** Immediate risk of further rapid deterioration or loss of fabric; no solution agreed.
- B** Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
- C** Slow decay; no solution agreed.
- D** Slow decay; solution agreed but not yet implemented.
- E** Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F** Repair scheme in progress and (where applicable) end use or user identified; or functionally redundant buildings with new use agreed but not yet implemented.

NOTE
Last year's priority category is shown in brackets (otherwise, New Entry is noted).

ABBREVIATIONS

CA	Conservation Area
LB	Listed Building
LPA	Local Planning Authority
NP	National Park
RPG	Registered Park and Garden
SM	Scheduled Monument
UA	Unitary Authority
WHS	World Heritage Site

This document is one in a series of publications produced as part of Historic England's national **Heritage at Risk** programme. More information about **Heritage at Risk** and other titles in the series can be found at HistoricEngland.org.uk/har

Heritage at Risk

Published October 2017

4th Floor, Cannon Bridge House

25 Dowgate Hill

London EC4R 2YA

© Copyright Historic England 2017

Product code: 52078



Historic England

West Midlands Register 2017