





Contents

Heritage at Risk	III
The Register	VII
Content and criteria	VII
Criteria for inclusion on the Register	VIII
Reducing the risks	Х
Key statistics	XIII
Publications and guidance	XIV
Key to the entries	XVI
Entries on the Register by local planning authority	XVIII
Greater London	I
Barking and Dagenham	I
Barnet	2
Bexley	5
Brent	5
Bromley Camden	6
City of London	20
Croydon	20
Ealing	24
Enfield	27
Greenwich	30
Hackney	33
Hammersmith and Fulham	40
Haringey	42
Harrow	46
Havering	50
Hillingdon	52
Hounslow	59 65
Islington Kensington and Chelsea	70
Kingston upon Thames	82
Lambeth	82
Lewisham	92
Merton	96
Newham	99
Redbridge	104
Richmond upon Thames	105
Southwark	107
Sutton Tower Hamlets	115 116
Waltham Forest	118
Wandsworth	125
Westminster, City of	128



HERITAGE AT



2014



Heritage at Risk is our campaign to save listed buildings and important historic sites, places and landmarks from neglect or decay. At its heart is the Heritage at Risk Register, an online database containing details of each site known to be at risk. It is analysed and updated annually and this leaflet summarises the results.

Over the past year we have focused much of our effort on assessing listed Places of Worship, and visiting those considered to be in poor or very bad condition as a result of local reports. We now know that of the 14,775 listed places of worship in

England, 6% (887) are at risk and as such are included on this year's Register. These additions mean the overall number of sites on the Register has increased to 5,753. However, 575 sites have been removed from the 2013 Register, which includes one of our biggest achievements this year, Severndroog Castle, Greenwich.

Nigel Barker, Planning and Conservation Director, London

Our success stories this year reflect the variety of sites we deal with in London. From a K2 telephone box to a grand Georgian house, a total of 41 sites have been removed from the London Heritage at Risk Register. We are particularly pleased that Severndroog Castle has once again opened its doors to the public, ten years after it first appeared in the television series 'Restoration'. The impressive 60 foot tower dates from the late 18th century and has been carefully restored under the guidance of the Severndroog Castle Building Preservation Trust, with support from English Heritage, the Heritage Lottery Fund and the Royal Borough of Greenwich. Another notable achievement is the repair of two monuments in Kensal Green Cemetery, with funding from English Heritage and the cemetery Friends Group, including a monument to French acrobat Emile Blondin.

We have also seen progress on a number of our top ten priority sites. Now in the ownership of English Heritage, repairs to the magnificent Manor Farm Barn at Harmondsworth are well underway. The project has provided opportunities for training in traditional building skills and regular open days have enabled the public to better appreciate this grade I listed medieval barn. We are also delighted that the Heritage Lottery Fund has awarded almost £9m to Ealing and Hounslow Councils to support the restoration of Gunnersbury Park and its many buildings and follies, as well as the museum currently housed in the Large Mansion. Both of these projects demonstrate the collaboration, perseverance and imagination so often needed to find sustainable solutions to heritage at risk.

Despite our successes, there are still considerable challenges. Most notable this year is the addition of 25 places of worship to the Register. This follows an extensive national project which has provided us with an accurate and up to date picture of places of worship at risk in London. With this information we will continue to work closely with congregations and funding bodies in the year ahead.

A further 23 buildings or structures have been added to the Register, as well as 1 archaeological site and 5 conservation areas. Scadbury Manor, a newly designated scheduled monument in Bromley; Reliance Arcade, a 1920s covered market in Brixton; and the Mare Street conservation area in Hackney are just three examples. A number of churchyard and cemetery monuments have also been added and tackling these remains a priority for us in London.


Whilst we recognise that funding and resources are still stretched, we hope to build on our successes to secure the future of vulnerable heritage assets in London. To achieve this, the support and imagination of our partners will be as important as ever.

Karett

Rebecca Barrett, Principal Adviser, Heritage at Risk

SCADBURY MANOR MOATED SITE AND FISHPONDS, CHISLEHURST, BROMLEY

Scadbury Manor is an impressive site with the remains of a medieval moated manor house and well preserved fishponds. Having flourished during the 15th and 16th centuries, the fortunes of Scadbury turned in the early 18th century when the manor house was partially demolished. Today the site is in a deteriorating condition and needs further investigation and repair. Bromley Council is working closely with partners, including the Friends Group and English Heritage, to secure the long-term conservation and interpretation of this scheduled monument.





KENSAL GREEN (ALL SOULS) CEMETERY, KENSINGTON AND CHELSEA

BACKGROUND AND HISTORY:

Kensal Green is a 77 acre cemetery situated in the heart of London. One of the so-called 'Magnificent Seven' Victorian cemeteries, Kensal Green certainly lives up to this name with its impressive Anglican Chapel, Entrance Lodge, Dissenters Chapel, North Colonnade, and many elaborately decorated monuments.

The cemetery opened in 1833 to the designs of John Griffith. It was the first commercial cemetery in London, providing much needed burial space in an ever-expanding city. Kensal Green was also the 'cemetery of choice' for the rich and famous and the impressive monuments and mausolea we see today reflect this status.

Kensal Green is owned and managed by the General Cemetery Company and is still actively used for burials. The Friends Group, set up in 1989, also play an important role in the maintenance and conservation of the cemetery.

IS IT AT RISK?

The fortunes of Kensal Green Cemetery turned

in the latter part of the 20th century, with fewer resources available for its upkeep, a growing number of monuments and structures in need of attention, and the encroachment of self-seeded vegetation on the legibility of the historic landscape.

The cemetery was added to the Heritage at Risk Register in 2009. The Anglican Chapel, the North Colonnade, boundary wall and some 32 monuments are also at risk.

WHAT'S THE CURRENT SITUATION?

Despite the overwhelming size of Kensal Green Cemetery and the variety of issues to be tackled, the General Cemetery Company and the Friends Group have made considerable progress in recent years.

Day-to-day maintenance of the cemetery is now informed by a robust Conservation Management Plan. A newly appointed project manager has also given fresh impetus to the project steering group and condition surveys of the Anglican Chapel and the most vulnerable monuments are helping to prioritise and guide repair works. Some works have already been carried out to the boundary wall, the North Colonnade and four mausolea, partly funded by English Heritage and the Friends Group.

The next challenge is to think imaginatively about the long-term management of the cemetery, as well as the repair and re-use of the Anglican Chapel which sits so prominently within the historic landscape. All partners will continue to work together over the coming year to secure the future of this magnificent cemetery for future generations.

HELP HISTORIC BUILDINGS

Historic buildings are irreplaceable; they give us our sense of place and contribute to our quality of life. These precious buildings need to be looked after for future generations, but how do we know what needs our help the most? English Heritage is encouraging community groups, volunteers, building owners and local authorities across the country to come together to record the condition of grade II listed buildings in their area. Volunteers will visit a selection of grade II buildings local to them and answer questions, in the form of a survey, about the condition of the building. This information will be collected together and shared with local planning authorities to help identify those grade II buildings most at risk. Visit www.english-heritage.org.uk/helphistoricbuildings to find out more.

FOR MORE INFORMATION CONTACT:

Rebecca Barrett English Heritage London I Waterhouse Square I38 – I42 Holborn London ECIN 2ST Telephone: 0207 973 3000

Email: london@ english-heritage.org.uk



SEVERNDROOG CASTLE, GREENWICH

BACKGROUND AND HISTORY:

Severndroog Castle is a hidden gem situated amongst ancient woodland in the Royal Borough of Greenwich. It was commissioned by the grieving widow of Sir William James following the death of her husband in 1783. Sir William James was the Commander-in-Chief of the East India Company's marine forces and achieved great success in 1755 when his fleet defeated pirates on the island fortress of Severndroog, off the west coast of India.

The castle is an impressive triangular tower, some 60 feet in height, with hexagonal turrets and battlements. It was designed in the Gothic style by architect Richard Jupp and included decorative interior rooms.

Throughout the course of its history, Severndroog Castle has changed hands numerous times. Its story has also been shaped by the sheer height of the tower - the rooftop provided a temporary home to the Ramsden Theodolite used by General William Roy and his team in the first Ordnance Survey of southern Britain, and the castle served as a strategic watch tower during the Second World War.

Towards the end of the 20th century Severndroog Castle fell into a state of disrepair. Its decorative plasterwork and joinery were damaged by water penetration and many features were damaged or stolen by vandals.

IS IT AT RISK?

The fortunes of Severndroog Castle have been turned around thanks to the perseverance and hard work of the Severndroog Castle Building Preservation Trust. Set up in 2003, the trust now leases the building from the Royal Borough of Greenwich. It has successfully repaired and restored the castle, with support from the Heritage Lottery Fund, English Heritage and the Royal Borough of Greenwich amongst many others.

The castle was added to the Heritage at Risk Register in 1990, but has been removed this year following its successful restoration.

WHAT'S THE CURRENT SITUATION?

In summer 2014, Severndroog Castle opened its doors to the public for the first time in 25 years. The castle has been carefully restored. The decorative plasterwork has been repaired and re-gilded, the windows painstakingly overhauled and graffiti cleaned from the outer walls.

The castle now provides a tearoom, much needed community space and a small exhibition area which tells the story of the castle and its owners. The building is available for both educational visits and private hire, and the rooftop gallery provides spectacular views of London and the surrounding countryside.

Find out what's at risk by searching or downloading the online Heritage at Risk Register at www.english-heritage.org.uk/har If you would like this document in a different format, please contact our customer services department on telephone: 0870 333 1181 fax: 01793 414926 textphone: 01793 414878 email: customers@english-heritage.org.uk

THE REGISTER Content and criteria

DESIGNATION Definition

All the historic environment matters but there are some elements which warrant extra protection through the planning system. These are included in the National Heritage List for England (NHLE), an online searchable database of designated assets (http://list.english-heritage.org.uk). Since 1882, when the first Act protecting ancient monuments and archaeological remains was passed, government has been developing the designation system. Listing, which is applied to buildings, emerged from the post-Blitz 1940s planning acts. There are now nearly 400,000 designated assets on the NHLE including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites.

English Heritage, as the government's expert adviser, is responsible for making recommendations – but it is still the Secretary of State at the Department for Culture Media and Sport who makes the decisions on whether an asset is designated. Understanding and appreciation develop constantly, which makes keeping the designation base up-to-date a neverending challenge.

While responding to threat-driven cases, we increasingly seek to work strategically through the National Heritage Protection Plan. Recent developments have seen a greater striving for openness and transparency in the process of designating a site, and better communication of what makes something special.

Alongside the nationally designated assets found on the National Heritage List for England are locally designated assets. Best known are conservation areas, but local authorities can also create lists of locally valued assets. Most archaeological sites of significance are not scheduled, but rely on local identification and management for their protection.

LISTED BUILDINGS

Listing is by far the most commonly encountered type of designation. A listed building (or structure) is one that has been designated as being of special architectural or historic interest. The older and rarer a building is, the more likely it is to be listed. Buildings less than 30 years old are listed only if they are of outstanding quality and under threat. Listed buildings are graded I, II* and II. Grade I buildings are of outstanding interest, and II* are particularly important buildings of more than special interest; together they amount to 8% of all listed buildings. The remaining 92% are of special interest and are listed grade II.

There are almost 376,000 listed entries on the statutory list of buildings of special architectural or historic interest. Entries on the statutory list sometimes group together a number of separate buildings: a terrace will be counted as one entry, rather than as separate units. Entries on this Register reflect how buildings are grouped and recorded on the statutory list.

Structures can occasionally be dual designated (both listed as buildings and scheduled as monuments). In such cases, scheduling controls take precedence.

SCHEDULED MONUMENTS

Scheduled monuments include single archaeological sites and complex archaeological landscapes. 19,833 examples have been designated because of their national importance. Scheduled monuments are not graded. They cover human activity from the prehistoric era, such as burial mounds, to 20th century military and industrial remains. For the millennia before written history, archaeology is the only testament to innumerable generations of people of whom there is no other record.

The later 20th century saw unprecedented changes to the landscape. As a result, types of historic site that once were commonplace began to become rare. Those that survive often represent just small islands of what once characterised broad sweeps of our towns and countryside. Although protected by law, scheduled monuments are still at risk from a wide range of processes and intense pressures outside of the planning system. These include damage from cultivation, forestry and – often most seriously of all – wholly natural processes such as scrub growth, animal burrowing and erosion.

REGISTERED PARKS AND GARDENS

There are 1,628 designed landscapes on the current English Heritage *Register of Historic Parks and Gardens of Special Historic Interest.* These registered landscapes are graded I, II* or II, and include private gardens, public parks and cemeteries, rural parkland and other green spaces. They are valued for their design and cultural importance, and are distinct from natural heritage designations.

Inclusion on the English Heritage *Register of Historic Parks and Gardens* brings no additional statutory controls,

but there is a clear presumption in favour of upholding their significance in government planning guidance. Local authorities are required to consult English Heritage on applications affecting sites registered as grade I or II* and the Garden History Society on sites of all grades. The setting of other designated heritage assets can also protect registered landscapes.

REGISTERED BATTLEFIELDS

English Heritage's *Register of Historic Battlefields* was set up in 1995, and is our youngest category of designation. Its aim is to protect and promote those sites where history was made through conflict. They range from the Battle of Maldon (991) to Sedgemoor (1685): almost half date from the period of the civil wars in the mid-17th century. These special places, where thousands were often killed, deserve our recognition and respect. Recently, additions have been made to the *Register of Historic Battlefields* for the first time since its creation. There are now 46 registered battlefields.

Protection is needed to prevent encroachment through inappropriate development, or insensitive (and damaging) metal detecting, which can permanently alter the archaeological record. As with registered parks and gardens, there is a clear presumption in favour of protecting registered battlefields in Government planning policy.

PROTECTED WRECK SITES

England's 49 protected wreck sites represent a tiny proportion of the 33,000 or so pre-1945 wrecks and recorded casualties that are known to lie in the territorial waters. Wreck sites can be of importance for different reasons: the distinctive design or construction of a ship, the story it can tell about its past, its association with notable people or events and its cargo. The Protection of Wrecks Act 1973 empowers the appropriate Secretary of State to designate a restricted area around a vessel to protect it or its contents from unauthorised interference, and English Heritage administers the attendant licensing scheme for divers seeking access.

CONSERVATION AREAS

Conservation areas are designated by local authorities and are areas of particular architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance. For more than 40 years conservation areas have proved a highly effective mechanism for managing change on an area-wide basis. There are currently 9,848 conservation areas in England including town and city centres, suburbs, industrial areas, rural landscapes, cemeteries and residential areas. They form the historic backcloth to national and local life and are a crucial component of local identity and community cohesion.

Criteria for inclusion on the Register

RISK ASSESSMENTS

A risk assessment of a heritage asset is based on the nature of the site. Building or structure assessments, for instance, include listed buildings (but not listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

BUILDINGS AND STRUCTURES

Buildings or structures (not in use as public places of worship) considered for inclusion on this Register must be listed grade I or II*, (or grade II in London) or be a structural scheduled monument with upstanding masonry remains. Buildings or structures are assessed for inclusion on the basis of condition and, where applicable, occupancy (or use) reflecting the fact that a building which is occupied is generally less vulnerable than one that is not.

Occupancy (or use) is noted as 'vacant', 'part occupied', 'occupied', 'not applicable', or occasionally, 'unknown'. Many structures fall into the 'not applicable' category as they can be ruins, walls, gates, headstones or boundary stones.

Condition is noted as 'very bad', 'poor', 'fair' or 'good'. The condition of buildings or structures on the Register typically ranges from very bad to poor, fair and (occasionally) good reflecting the fact that some buildings or structures capable of use are vulnerable to becoming at risk because they are empty, under-used or face redundancy without a new use to secure their future. Assessing vulnerability in the case of buildings in fair condition necessarily involves judgement and discretion. A few buildings on the Register are in good condition, having been repaired or mothballed, but a new use or owner is still to be secured.

Buildings or structures are removed from the Register when they are fully repaired/consolidated, and their future secured through either occupation and use, or through the adoption of appropriate management.

PLACES OF WORSHIP

Places of worship considered for inclusion on this Register must be listed grade I, II* or II and be used as a public place of worship at least six times a year.

Places of worship are assessed on the basis of condition only. If the place of worship is in very bad or poor condition it is added to the Register.

English Heritage has visited and assessed listed places of worship considered to be in poor or very bad condition according to local assessments. Those that are identified as at risk are included on the Register.

Once on the Register, places of worship can move through the condition categories (e.g. from very bad to poor, to fair, even good) as repairs are implemented and the condition improves, until they are fully repaired and can be removed from the Register.

ARCHAEOLOGY

Archaeology assessments cover earthworks and buried archaeology. The archaeological sites on this Register have been identified as being at risk because of their condition and vulnerability, the trend in their condition, and their likely future vulnerability. A site's condition is expressed in terms of the scale and severity of adverse effects on it, ranging from those with 'extensive significant problems' to others that have only 'minor localised problems'.

Archaeological entries are removed from the Register once sufficient progress has been made to address identified issues, demonstrating a significant reduction in the level of risk.

PARKS AND GARDENS

The assessment of parks and gardens starts with an appraisal of the condition and vulnerability of each registered landscape. Steps being taken by owners to address problems are also taken into consideration.

Parks and gardens assessed as being at risk are typically affected by development and neglect. They have frequently been altered by development or are faced with major change. The original function of these landscapes has often changed; and divided ownership often results in the loss of the cohesive conservation of the historic designs.

Park and garden entries are removed from the Register once plans are put in place to address issues and positive progress is being made.

BATTLEFIELDS

Battlefields deemed to be at risk of loss of historic significance are included on this Register.

The identified risks and threats come from development pressure - for example, because they lie on urban fringes or are subject to development pressures within the site; arable cultivation, and unregulated metaldetecting. One major impact or a combination of factors can be enough to raise the risk of a particular site.

Battlefields are removed from the Register when either actual damaging activities are reversed or managed, or threats recede due to effective management planning.

WRECK SITES

English Heritage has audited all designated wreck sites to identify those most at risk based on their current condition, vulnerability and the way they are being managed. Wrecks are vulnerable to both environmental and human impacts. Risks that contribute to inclusion on the Register range from unauthorised access to erosion and fishing damage.

The monitoring process ensures that the significance of the site is identified and maintained.

In spite of the inherent difficulties in caring for this type of site, careful management must be maintained.

Wrecks are removed from the Register once an appropriate management and monitoring regime is operational.

CONSERVATION AREAS

English Heritage has asked every local authority in England to complete (and update as appropriate) a survey of its conservation areas, highlighting current condition, threats and trends. Conservation areas that are deteriorating, or are in very bad or poor condition and are not expected to change significantly in the next three years, are defined as being at risk.

The methodology for assessing conservation areas at risk has been refined since the first survey in 2008/2009. The information collated provides a detailed assessment of each conservation area and an overall category for condition, vulnerability and trend is included for each conservation area on this Register. Conservation areas identified as at risk in 2009, but not reassessed since using the revised methodology, are included on the Register but with limited information.

Conservation areas are removed from the Register once plans have been put in place to address the issues that led to the conservation area being at risk, and once positive progress is being made.

Reducing the risks

English Heritage is working to secure a reduction in the number of heritage sites at risk as part of our contribution to the National Heritage Protection Plan (2011-2015). We have set ourselves a target to remove 25% of entries (1,137) published on the 2010 Register by 2015. Despite the challenge, given the number of entries on the Register and the different kinds of risk they face, excellent progress is being made.

The published Heritage at Risk National Strategy (www.english-heritage.org.uk/publications/eh-harstrategy-2011-15) sets out how this will be delivered through our dedicated Heritage at Risk teams in each local office. Key objectives of the strategy are to understand what factors lead to heritage sites becoming at risk, what most influences their removal from the Register, and to achieve this through partnership, stimulating economic regeneration and growth, and maximising the benefit of our expertise and resources.

Whilst each type of heritage asset and individual site will require its own approach and solution, there are some general approaches that are relevant to all 'at risk' assets. Resolving cases requires working in close partnership with owners, local planning authorities and a wide variety of other relevant organisations. The provision of clear advice and understanding are essential.

Maintenance and where appropriate, occupation are key to preventing heritage assets becoming at risk, whilst maintenance of those already at risk will prevent them from decaying further. Without maintenance, the cost of repair and consolidation escalates, the challenge for owners and occupiers increases, and the scope for affordable solutions declines.

English Heritage provides a wide range of published guidance on reducing the risks, including: new uses for heritage assets, finding partners and funding, and on enforcing urgent works and repairs, on our website: **www.english-heritage.org.uk** or the Historic Environment Local Management (HELM) website: **www.helm.org.uk** Key publications and guidance are listed on pages XIV-XV.

Historic Environment Records and local heritage at risk registers, maintained by local authorities, are repositories of information on local historic assets. They underpin the work of local authority historic environment services and can help improve the protection, conservation and management of heritage assets.

BUILDINGS AND STRUCTURES

Our nine local teams can help existing and potential owners, developers and local authorities with the assessment of risk and the identification of appropriate programmes of repair. They can advise on the benefits of additional survey and assessment, help with feasibility studies and with brokering solutions. In particularly difficult cases they can draw on the additional expertise of our national advisers specialising in structural engineering, quantity surveying, development economics, enforcement and planning law. We can help with access to funding as we work closely with grant providers including the Heritage Lottery Fund and Natural England. Our own principal grant stream for buildings and structures is the Historic Buildings, Monuments and Designed Landscapes (HBMDL) grant but Section 17 Management Agreements can also be used to tackle risk to scheduled monuments. More information on funding can be found at www.english-heritage.org.uk/professional/funding.

We know from our own Register how useful it is in managing risk, prioritising action and engaging partners. We are therefore working with local authorities and voluntary groups to enable them to compile local heritage at risk registers and develop strategies for tackling buildings in poor condition. These strategies should include the use of enforcement powers. Our Heritage at Risk Legal Adviser can support local authorities considering enforcement action and we have published guidance at **www.englishheritage.org.uk/publications/stoppingtherot**. In certain circumstances we can also provide grant aid to underwrite the cost of serving Urgent Works and Repairs Notices.

Building preservation trusts (BPTs) offer a tried and tested way of saving buildings at risk. We have close links with the Architectural Heritage Fund and fund their regional support officers to work across the county. They help BPTs and other not-for-profit organisations access funding, carry out feasibility studies and develop solutions for buildings at risk. For more information on support officers and BPTs visit www.ahfund.org.uk and www.ukapt.org.uk. Guidance and case studies can be found at www.englishheritage.org.uk/publications/pillars-of-the-community.

English Heritage also funds an Industrial Heritage Support Officer to work with groups running industrial heritage sites. For more information please visit www.industrialheritagesupport.wordpress.com.

PLACES OF WORSHIP

Regular maintenance helps to keep all buildings in good condition but those suffering major problems need repairs to minimise the risks to both the structure and the contents. Keeping drains and gutters clear so that water is taken away from the building efficiently is the most important thing congregations can do as this stops small problems developing into unnecessary crises. The overflowing gutter soon soaks the wall beneath, rots the roof timbers behind it and makes the whole building vulnerable.

In some areas congregations group together to engage reputable contractors at competitive rates to clear gutters and rainwater goods. Such co-operation enables them to get good quality work carried out at reasonable prices by firms that understand historic buildings. The Maintenance Co-operatives project run by the Society for the Protection of Ancient Buildings will further help to connect, inform and empower those people who look after places of worship.

The Heritage Lottery Fund runs the new Grants for Places of Worship scheme. The main focus of the scheme is fabric repairs but it also provides funds for modest changes to enhance community use of the building. English Heritage's architects and surveyors, based in our local Heritage at Risk teams, provide technical advice to the Heritage Lottery Fund on fabric repairs to ensure appropriate conservation standards are met.

The Government's Listed Places of Worship scheme, enabling the reclaiming of VAT on eligible repairs, maintenance and authorised alterations, is available to all listed places of worship, whether they have obtained grants or are funding work themselves. Local and national charities also offer grants.

English Heritage supports congregations wanting to keep their places of worship in use and recognises the need for appropriate new facilities such as kitchens and toilets that are sensitive to the building's special character. *New Work in Historic Places of Worship* (published 2012) helps congregations understand how changes can be achieved.

A network of support officers, employed locally but part-funded by English Heritage, offers direct advice and encouragement to congregations. Projects to effect repairs and develop necessary new facilities for both the community and visitors are breathing a new lease of life into these treasured parts of our heritage.

ARCHAEOLOGY

The excellent progress which is being made with reducing the number of scheduled monuments on the Register continues to demonstrate the value which owners and land managers are placing upon the positive management of archaeological sites. The large majority (84%) of the 19,832 scheduled monuments in England (in 2013) are on land classified as agricultural. Effective information sharing with Natural England and Defra is therefore of great importance for prioritising management action and for targeting agrienvironment grant schemes to best effect. This will be especially important with the New Environmental Land Management Scheme (NELMS) which commences in 2015. Natural England now shares our corporate target of removing 25% of the scheduled monuments on the 2010 Register by 2015. We also continue to work closely with the Heritage Lottery Fund to identify the nationally important monuments deserving of grant-aid for enhanced conservation, presentation and access projects.

Loss and damage as a consequence of arable cultivation remains the greatest source of risk to scheduled monuments on the Register. Reporting in late 2013, however, the Conservation of Scheduled Monuments in Cultivation (COSMIC) project has provided updated risk assessments for 1587 sites on the Register, and features bespoke prescriptions for reducing the risks from cultivation damage. In some cases, the COSMIC mitigation recommendations have already been acted upon by our local teams, resulting in a significant number of removals from the 2013 Register.

Analysis of entries on the Register shows that unmanaged woodland, tree, scrub and bracken growth is one of the most widespread causes of long-term damage to both urban and rural archaeological sites even if the effects are not as visible or as immediately destructive as other processes. In most cases simple, low cost but regular maintenance is the key, the delivery of which will always be reliant upon the help and goodwill of landowners.

PARKS AND GARDENS

Although a statutory list, the *Register of Historic Parks Gardens of Special Historic Interest in England* in itself brings no additional statutory powers, it instead works through the development control system to provide a valuable tool for the protection of the sites it includes. The Government's *National Planning Policy Framework* (NPPF) stresses the desirability of sustaining and enhancing the significance of all heritage assets and finding viable uses consistent with their conservation. The NPPF states that great weight must be given to the conservation of sites included on the *Register of Historic Parks and Gardens of Special Historic Interest* and that substantial harm or loss of such features can only be justified in exceptional cases.

A great many historic parks and gardens are either privately owned or in trust. In addition, local authorities are responsible for nearly all the public parks and cemeteries in our towns and cities. Registered parks and gardens are typically large, complex heritage assets, many in multiple ownership, and it can take years to identify and implement solutions to reduce the risks to parks and gardens. To help reduce the risks, English Heritage encourages and works with owners to develop conservation management strategies. Landscape architects working in our Heritage at Risk teams can help tailor conservation management plans and funding packages for individual landscape features or whole sites. We work with partners, such as Natural England and the Heritage Lottery Fund, to help source funding to secure sustainable futures for parks and gardens at risk.

Further information and conservation guidance for parks, gardens and designed landscapes is available at: www.english-heritage.org.uk/professional/advice/adviceby-topic/parks-and-gardens.

BATTLEFIELDS

As with registered parks and gardens, the *Register of Historic Battlefields* brings no additional statutory controls to registered battlefields, but the *National Planning Policy Framework* makes it clear that registered battlefields are of equal significance to scheduled monuments, buildings listed grade I and II* registered parks and gardens and protected wreck sites. Therefore, the positive conservation and management of registered battlefields is a core element of current heritage legislation.

English Heritage continues to work with owners to develop management plans for registered battlefields and, in appropriate cases, contribute towards the cost of management plans. We work to develop positive landscape strategies with owners and partners such as Defra through Environmental Stewardship schemes. In some circumstances, we may encourage the conversion from arable to pasture of especially sensitive locations to protect battlefield archaeology from the effects of ploughing and as part of a wider drive to prevent unauthorised or damaging metal-detecting.

English Heritage also continues to encourage greater access to battlefields and improve their amenity value and visitors' understanding of the impact these historic events had on our development as a nation.

Local authorities can also invite comments from the Battlefields Trust on planning applications affecting the setting of registered battlefield sites.

WRECK SITES

At the strategic level, the major sources of risk to protected wreck sites have been identified. In terms of high-priority sites, practical requirements have also been implemented through conservation management plans and appropriate intervention.

Risks to protected historic wreck sites can often be reduced through education, provision of marker buoys, or planning policies that take full account of their national importance. However, some sites require significant resources to stabilise their condition or to carry out detailed archaeological assessments of their conservation requirements. Although English Heritage has statutory power to allocate funds to promote the preservation and maintenance of protected wreck sites, its financial resources can solve only a small proportion of the problems.

In spite of the inherent difficulties with caring for this type of site, careful management must be maintained if we are to avoid the loss of wreck sites. It is therefore close co-operation between the owners of protected wreck sites (where known), authorised divers and all organisations charged with care for the marine and coastal environment, that will make the real difference to their long-term survival.

Practical advice on the management of historic wreck sites, whether at the coast-edge or under water, is available from English Heritage (maritime@englishheritage.org.uk) and from www.helm.org.uk.

CONSERVATION AREAS

The risks to conservation areas are difficult to address as these designated areas can constitute large areas of land; they include streets, spaces, archaeology and trees as well as buildings and structures and therefore involve many different owners and methods of management. Looking after conservation areas is a responsibility shared by those of us who own homes and businesses within them as well as those of us whose job it is to manage them or make decisions about their future.

The Conservation Areas Survey, completed by local authorities, provides us with an understanding of what is particularly affecting the character and appearance of conservation areas: what is working well or what is putting them at risk. Strong planning policies, guidance and a clear management strategy for individual conservation areas, backed up by effective enforcement, are all critical in managing change in these areas. This is, however, extremely difficult at a time when local authorities across the country are reducing their staff numbers. Armed with the information provided by conservation area surveys, we, local authorities and other partners will have the evidence to direct resources much more accurately towards those conservation areas at greatest risk.

There are opportunities for members of the local community to get involved with protecting and enhancing their conservation area, either individually or through groups. Some local groups have helped to prepare character appraisals and management plans for conservation areas whilst others have carried out their own assessments to identify management issues. Further information on how you can get involved is available at: www.english-heritage.org.uk/caring/getinvolved/improve-your-neighbourhood.

Key statistics

BUILDINGS AND STRUCTURES

- Nationally, 4.0% of grade I and II* listed buildings (excluding places of worship) are on the Register. In London the percentage is 4.2% (69 listed secular buildings).
- 2.6% (430) of London's grade II listed secular buildings are on the Register.
- 30 building or structure entries have been removed from the 2013 London Register because their futures have been secured, and 23 have been added.
- 96% of buildings or structures on the London baseline 1991 Register have been removed because their futures have been secured.

PLACES OF WORSHIP

- Nationally, 6.0% of listed places of worship are on the Register. In London, 9.2% (73) are on the Register.
- 4 places of worship have been removed from the London Register following repair work, and 25 have been added.

ARCHAEOLOGY

- 3,012 (15.2%) of England's 19,833 scheduled monuments are on the Register. 31 (19.9%) of London's 156 scheduled monuments are on the Register.
- 2 archaeology entries have been removed from the 2013 London Register for positive reasons, and 1 has been added.
- 29.7% of archaeology entries (11) on the London baseline 2009 Register have been removed for positive reasons, compared with the national figure of 29.2%.

 Nationally, damage from arable cultivation is the greatest cause of risk affecting 43% of archaeological entries on the Register. In London the proportion is 10%. The greatest risk, to 26% of entries on the London Register is from unrestricted plant, scrub and tree growth. The national figure for plant, scrub and tree growth is also 26%.

PARKS AND GARDENS

 93 (5.7%) of England's 1,628 registered parks and gardens are on the Register. Of the 150 registered parks and gardens in London, 11 (7.3%) are on the Register, the same as last year.

BATTLEFIELDS

• Of the 46 registered battlefields in England, 6 (13.0%) are on the Register. The only registered battlefield in London is not on the Register.

WRECK SITES

• Of the 49 protected wreck sites around England's coast, 4 (8.2%) are on the Register. London has no protected wreck sites.

CONSERVATION AREAS

- 8,206 of England's 9,848 conservation areas have been surveyed by local authorities and 497 (6.1%) are on the Register. Of the 1,014 conservation areas in London, 953 have been surveyed and 60 (6.3%) are on the Register.
- 5 conservation areas have been removed from the 2013 London Register for positive reasons, and 5 have been added.

ENGLISH HERITAGE FUNDING

• £813,000 in grant was spent on 17 entries on the London Register during 2013/14.

Risk assessments of heritage assets are based on the nature of the site. Building and structure assessments include listed buildings (excluding listed places of worship) and structural scheduled monuments; archaeology assessments cover earthworks and buried archaeology.

Publications and guidance

English Heritage has produced the following publications relating to heritage at risk, including:

Assessment of Heritage at Risk from Environmental Threat: Key Message (2013)

Buildings at Risk: a New Strategy (1998)

Caring for Places of Worship 2010(2010) – a report on the condition of England's listed places of worship and the needs of the congregations

COSMIC 3 – Grappling with a 140-Year-Old Conservation Problem (2014) – English Heritage Research News 21, available online

Counting our Heritage: a Heritage at Risk Survey for High Peak Staffordshire Moorlands by Community Volunteers (2013)

English Heritage's Heritage at Risk National Strategy (2011-2015) (2012)

Heritage at Risk 2010 – report (2010)

Heritage at Risk: Conservation Areas (2009)

Heritage at Risk 2014 – national summary leaflet and regional summary leaflets for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

Heritage at Risk Register 2014 – detailed listings for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire can be downloaded from our website or viewed on an interactive database: www.english-heritage.org.uk/risk

Monuments at Risk (2008) – summary of scheduled monuments at risk for: East Midlands, East of England, London, North East, North West, South East, South West, West Midlands, and Yorkshire

The Monuments at Risk initiative 2003-08 (2010)

Protected Wreck Sites at Risk: A Risk Management Handbook (2007)

Saving London: 20 Years of Heritage at Risk in the Capital (2010)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

HERITAGE AT RISK ON THE WEB

To find out more about the Heritage at Risk programme visit **www.english-heritage.org.uk/risk** where you will find an interactive database providing detailed information on all heritage sites at risk nationally.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database: http://list.english-heritage.org.uk.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit the Heritage Protection section of our website www.english-heritage.org.uk/professional/protection.

CONSERVATION POLICIES AND GUIDANCE

The following publications are among the numerous guidance documents available on our website: www.english-heritage.org.uk/publications and www.english-heritage.org.uk/helm

Caring for Historic Graveyard and Cemetery Monuments (2011)

Caring for Our Shipwreck Heritage: Guidelines on the First Aid Treatment and Conservation Management of Finds Recovered from Designated Wreck Sites Resulting from Licensed Investigations (2012)

Caring for Places of Worship (2010) – a practical booklet for everyone involved in caring for England's listed places of worship

Constructive Conservation in Practice (2008)

Constructive Conservation: Sustainable Growth for Historic Places (2013)

Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)

The Conservation, Repair and Management of War Memorials (2014)

Creativity and Care: New Works in English Cathedrals (2009)

The Disposal of Historic Buildings: Guidance Note for Government Departments and Non-Departmental Public Bodies (2010)

Enabling Development and the Conservation of Significant Places (2008)

Farming the Historic Landscape: Caring for Archaeological sites on Arable Land (2004) Farming the Historic Landscape: Caring for Archaeological Sites in Grassland (2004)

Guidance notes and application forms for grants to local authorities:

- Grants to Local Authorities to Underwrite Urgent Works Notices (1998)
- Acquisition Grants to Local Authorities to Underwrite Repairs Notices (1998)
- Grants for Historic Buildings, Monuments and Designed Landscapes (2004)

Heritage Crime Prevention: A guide for Owners, Tenants and Managers of Heritage Assets (2013)

Heritage Crime Risk: Quick Assessment Tool (2013)

Heritage Works: the use of Historic Buildings in Regeneration (2013)

Managing Local Authority Heritage Assets: Some Guiding Principles for Decision Makers (2003)

New Uses for Former Places of Worship (2010)

New Work in Historic Places of Worship (2012)

Options for the Disposal of Redundant Churches and Other Places of Worship (2010) Paradise Preserved: An Introduction to the Assessment, Evaluation, Conservation and Management of Historic Cemeteries (2002)

Pillars of the Community: the transfer of local authority heritage assets (2014)

Practical Building Conservation – revised ten-part series: Glass & Glazing; Metals, Mortars, Renders & Plasters; Stone; Timber; Building Environment; Concrete; Conservation Basics; Earth, Brick & Terracotta; Roofing (2012–2014)

Scheduled Monument Consent: A Guide for Owners and Occupiers (2009)

Shared Interest: Celebrating Investment in the Historic Environment (2006)

Theft of Metal from Church Buildings (2011)

Understanding Place: Conservation Area Designation, Appraisal and Management (2011)

Valuing Places: Good Practice in Conservation Areas (2011)

If you would like further information about any of these publications, please contact:

English Heritage Customer Services Department PO Box 569, Swindon SN2 2YP Telephone: 0870 333 1181 Fax: 01793 414926 Email: customers@english-heritage.org.uk

Key to the entries

This Register includes the following risk assessment types

- Building or structure (grade I, II* and II listed buildings and structural scheduled monuments)
- Place of worship (grade I, II* and II listed buildings)
- Archaeology (scheduled monuments – earthworks and buried archaeology)
- Park and garden
 (Registered parks and gardens)
- Conservation area
 (Conservation areas)

ORDER

Entries are grouped and ordered alphabetically by London borough. Within each borough, entries are grouped by risk assessment type in the following order:

- Buildings or structures
- Places of worship
- Archaeology
- Conservation areas

Within each risk assessment type, entries are ordered alphabetically by street and site name. Conservation areas are ordered by site name only. Parks and gardens are integrated by locality.

DESIGNATION

The principal designation is noted for each entry and includes:

- Listed Building (LB) grade I, II* or II
- Listed Place of Worship grade I, II* or II
- Scheduled Monument (SM)
- Registered Park and Garden (RPG) grade I, II* or II
- Conservation Area (CA)

Other designations that apply to the designated site, including location within a World Heritage Site (WHS), are also noted.

If an entry is dual designated (both listed and scheduled), 'and' rather than a comma is used (eg 'Scheduled Monument and Listed Building grade I'). If a scheduled monument entry is dual designated with a number of listed buildings, each is separated by a semicolon.

The National Heritage List Entry Number is included for all entries (except conservation areas). If a site is dual designated, all relevant List Entry Numbers are noted.

CONDITION

For buildings (including places of worship), condition is graded as: 'very bad', 'poor', 'fair' and 'good'.

For sites that cover areas (scheduled monuments (archaeology assessments) and parks and gardens) one overall condition category is recorded. The category may relate only to the part of the site or monument that is at risk and not the whole site:

- extensive significant problems
- generally unsatisfactory with major localised problems
- generally satisfactory but with significant localised problems
- generally satisfactory but with minor localised problems
- optimal
- unknown (noted for a number of scheduled monuments that are below-ground and where their condition cannot be established).

For conservation areas, condition is categorised as: 'very bad', 'poor', 'fair' and 'optimal'.

If a site has suffered from heritage crime it is noted in the summary. Heritage crime is defined as any offence which harms the heritage asset or its setting and includes arson, graffiti, lead theft and vandalism.

OCCUPANCY/USE

For buildings (excluding places of worship) that can be occupied or have a use, the main vulnerability is vacancy or under-use. Occupancy (or use) is noted as follows:

- vacant
- part occupied
- occupied
- unknown
- not applicable

VULNERABILITY

Principal vulnerability is noted for archaeology assessments and may relate only to the part of the site that is at risk, and include:

- animal burrowing
- arable ploughing
- coastal erosion
- collapse
- deterioration in need of management
- scrub/tree growth
- visitor erosion

For parks and gardens and conservation areas, vulnerability is noted as high, medium or low.

PRIORITY CATEGORY

Priority for action is assessed on a scale of A to F, where 'A' is the highest priority for a site which is deteriorating rapidly with no solution to secure its future, and 'F' is the lowest priority.

For buildings and structures and places of worship the following priority categories are used as an indication of trend and as a means of prioritising action:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- D Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

2013 priority categories are given in brackets, otherwise 'New entry' is noted.

'New entry – re-assessed' indicates an existing site on the Register that has been re-assessed using a different risk assessment methodology and is included on this year's Register under the new assessment type.

TREND

Trend for archaeology entries and parks and gardens may relate only to the part of the site that is at risk and is categorised as:

- declining
- stable
- improving
- unknown

For conservation areas trend is categorised as:

- deteriorating
- deteriorating significantly
- no significant change
- improving
- improving significantly
- unknown

OWNERSHIP

A principal ownership category is given for each entry, and if sites are in divided ownership, a 'multiple' ownership category is noted.

CONTACT

This is the member of the English Heritage local team who acts as a first point of contact for the case, and to whom enquiries should be addressed.

For conservation areas and grade II listed buildings, the contact is the conservation/planning officer at the relevant local planning authority (indicated by 'LPA').

We are not in any sense agents for the owners of the sites included, but we will endeavour to put people in touch with them where appropriate.

- CA Conservation Area
- EH English Heritage
- HLF Heritage Lottery Fund
- LB Listed Building
- LPA Local Planning Authority
- NP National Park
- RPG Registered Park and Garden
- SM Scheduled Monument
- UA Unitary Authority
- WHS World Heritage Site

Entries on the Register by local planning authority

Local planning authority	Building and structure entries	Place of worship entries	Archaeology entries	Park and garden entries	Battlefield entries	Wreck site entries	Conservation area entries
GREATER LONDON							
Barking and Dagenham	5		1	0	0	0	1
Barnet	10		1	0	0	0	1
Bexley	2		0	1	0	0	0
Brent	2	0	0	0	0	0	0
Bromley	20	1	4	1	0	0	1
Camden	32	11	0	0	0	0	0
City of London	1	3	3	0	0	0	0
Croydon	7	5	3	0	0	0	0
Ealing	9		4	0	0	0	5
Enfield	9	2	0	2	0	0	2
Greenwich	15	0	0	0	0	0	0
Hackney	27	6	0	1	0	0	3
Hammersmith and Fulham	8	1	0	0	0	0	1
Haringey	14	4	0	0	0	0	5
Harrow	10	I	5		0	0	0
Havering	12	0	1	0	0	0	1
Hillingdon	29	0	2	0	0	0	10
Hounslow	20	I	2	I	0	0	2
Islington	15	8	0	0	0	0	11
Kensington and Chelsea	42	4	0	2	0	0	I
Kingston upon Thames	3	0	0	0	0	0	0
Lambeth	40	2	0	0	0	0	0
Lewisham	18	2	0	0	0	0	1
Merton	13	0	2	0	0	0	2
Newham	20	I	0	0	0	0	2
Redbridge	2	0	0	I	0	0	3
Richmond upon Thames	12	0	0	0	0	0	1
Southwark	35	2	2	1	0	0	1
Sutton	2	0	0	0	0	0	0
Tower Hamlets	22	6	I	0	0	0	6
Waltham Forest	10	3	0	0	0	0	0
Wandsworth	16	0	0	0	0	0	0
Westminster, City of	17	6	0	0	0	0	0
	400		- 24				
TOTAL	499	73	31	11	0	0	60

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

GREATER LONDON

BARKING AND DAGENHAM

ARKING AND DAGENF			
	SITE NAME:	The Old Vicarage, Crown Street, Dagenham	House, dated 1665, and remodelled in the C19. The building is currently (summer 2014) part occupied and has
	DESIGNATION:	Listed Building grade II, CA	been at risk of vandalism. Planning Permission was granted in March 2013 for residential conversion into flats.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
nglish Heritage	LIST ENTRY NUMBER:	1064411	Contact: Daniel Pope (LPA) 020 8227 3929

The Marks Stones, Whalebone

The Warren Stone, Whalebone Lane North, Chadwell Heath

Listed Building grade II

Lane North, Chadwell Heath

Listed Building grade II

Very bad

N/A

D (D)

Crown

Poor

N/A

D (D)

Crown

1064419

1359307





	SITE NAME:	Magistrates Court, East Street, Barking	Built in 1893 in the manner of the Flemish Renaissance. The building was in use as a magistrates' court but has been
N-T	DESIGNATION:	Listed Building grade II, CA	empty since 2011. Planning Permission has been granted for residential conversion with commercial use on the
	CONDITION:	Good	ground floor and a contemporary extension.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
13	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1359304	Contact: Daniel Pope (LPA) 020 8227 3929

involvement.

involvement.

© London Borough of Barking and Dagenham



© London Borough of Barking and Dagenham



© English Heritage Archive



	SITE NAME:	Chadwell Heath anti-aircraft gun site, Whalebone Lane North (off), Chadwell Heath	The substantial remains of a World War II anti-aircraft battery with pits for eight guns in two groups of four and associated structures. The buildings are subject to	
	DESIGNATION:	Listed Building grade II, CA	vandalism and are in an isolated spot, surrounded by a quarry. The quarry is now being restored, including the	
	CONDITION:	Poor	land levels around the gun site. Its future is being discusse with the Local Authority, the landowners (the Crown	
	OCCUPANCY:	N/A	Estate) and English Heritage. A Heritage Lottery Fund start-	
	PRIORITY CATEGORY:	C (C)	up grant has been awarded to investigate the potential of the site with community involvement.	
P	OWNER TYPE:	Crown	·	
	LIST ENTRY NUMBER:	1079855	Contact: Daniel Pope (LPA) 020 8227 3929	

© London Borough of Barking and Dagenham

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Boundary marker of the Liberty of Havering-atte-Bower, originally set up in 1642. There are two stones; one 12

inches high inscribed 'Marks Stone' and one 30 inches high

inscribed 'Marks Stone Sept 1642'. One stone is broken and in safekeeping, the other remains in its original

operators as part of a planning condition for the adjacent quarry once restoration of the area is complete. A

Heritage Lottery Fund start-up grant has been awarded to investigate the potential of the site with community

Boundary stone erected in 1642. The stone marked the

Warren Farm during ongoing quarrying operations. The stone will be reinstated in its original position by the quarry

finished and land levels have been restored. A Heritage Lottery Fund start-up grant has been awarded to

investigate the potential of the site with community

Contact: Daniel Pope (LPA) 020 8227 3929

operators as part of a planning condition once quarrying is


boundary of Hainault Forest, along with the Marks Stones and the Forest Bounds Stone. The stone is in storage at

position. The stones are to be repaired by quarry

Contact: Daniel Pope (LPA) 020 8227 3929

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ÍΙΑ Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014 / LONDON / BARKING AND DAGENHAM / BARNET



© English Heritage

SITE NAME:	Barking Abbey		
DESIGNATION:	Scheduled Monument, LB grade II, CA	LIST ENTRY NUMBER:	1003581
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Chadwell Heath Anti-Aircraft Gun Site, Marks Gat	e	
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Francesca Cliff (LPA) 020 8227 3910

BARNET



	SITE NAME:	Tomb of John Jones, Church End, St Mary's Churchyard, Hendon NW4	Tall pedestal over base with carved fielded panels, dating from the early C18. Panels have been dismantled exposing damaged brickwork.
	DESIGNATION:	Listed Building grade II, CA	
4.	CONDITION:	Very bad	
14	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
1	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1375647	Contact: Jonathan Hardy (LPA) 020 8359 4655





	LIST EINTRT NUMBER:	1373647	Contact: Jonathan Hardy (LPA) 020 8359 4655
	SITE NAME:	Tomb of Susannah Frye, Church End, St Mary's Churchyard, Hendon NW4	Chest tomb with inset angle balusters, a curved cover with carvings of funerary and heraldic imagery. Collapsed end panel.
1000	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
No.	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1375651	Contact: Jonathan Hardy (LPA) 020 8359 4655

© English Heritage

PRIORITY CATEGORIES А

Immediate risk of further rapid deterioration or loss of fabric: no

D

Е

- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building Local Planning Authority National Park CA LB
- LPA
- NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE A	AT RISK	2014 /	I ONDON /	BARNET
	11100	2011/	LOINDOIN	

	SITE NAME:	The Bothy, East End Road, Finchley N3	Garden compound in the grounds of Avenue House, comprising summer house, living accommodation and
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	storage. Completed in 1882. The building is currently vacant although permission for re-use by a charity has bee granted. Proposals for the restoration of the Bothy are in
	CONDITION:	Fair	progress, with potential funding from the Heritage Lottery Fund.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1387534	Contact: Jonathan Hardy (LPA) 020 8359 4655
	SITE NAME:	The Water Tower, East End Road, Finchley N3	Water tower, circa 1800, built of massed concrete. The structure has been neglected for many years. The
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	overgrown ivy, which may have contributed to the large cracks in the concrete, has been removed. Proposals for the restoration of Avenue House, the water tower, stable
	CONDITION:	Very bad	block and garage are in progress, with funding from the Heritage Lottery Fund.
	OCCUPANCY:	Vacant/not in use	Tertage Lottery Fund.
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Charity (heritage)	

© English Heritage

ARAC



	LIST ENTRY NUMBER:	1387524	Contact: Jonathan Hardy (LPA) 020 8359 4655		
	SITE NAME:	College Farm - main building, Fitzalan Road N3	Stables, teashop and dairy, built in 1883 to the design of Frederick Chancellor in a picturesque style. Model dairy		
	DESIGNATION:	Listed Building grade II, CA	farm of the Express Dairy Company. Acquired by the College Farm Trust.		
	CONDITION:	Fair			
	OCCUPANCY:	Occupied/in use			
	PRIORITY CATEGORY:	C (C)			
and the second second	OWNER TYPE:	Charity (heritage)			
	LIST ENTRY NUMBER:	1359127	Contact: Jonathan Hardy (LPA) 020 8359 4655		

	SITE NAME:	College Farm Dairy, Fitzalan Road N3	Dairy built in 1883 to the design of Frederick Chancellor, with ornate timber lantern roof and decorative tilework to
	DESIGNATION:	Listed Building grade II, CA	the interior. The condition of the building is deteriorating. Acquired by the College Farm Trust. See also entry for
	CONDITION:	Fair	College Farm main building.
NE LOS ADA	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
English Heritage	LIST ENTRY NUMBER:	1064789	Contact: Jonathan Hardy (LPA) 020 8359 4655

© E

© English Heritage



	SITE NAME:	Silo, Fitzalan Road, College Farm N3	Silo built in 1883 to the design of Frederick Chancellor as part of the Express Dairy Company's pioneering model
	DESIGNATION:	Listed Building grade II, CA	farm. The condition of the building is deteriorating. Acquired by the College Farm Trust. See also entry for
	CONDITION:	Fair	College Farm main building.
	OCCUPANCY:	N/A	
and the second	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1359128	Contact: Jonathan Hardy (LPA) 020 8359 4655

© English Heritage

- А
- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / BARNET

	SITE NAME:	Monument to Major John Cartwright, St Mary at Finchley Churchyard, Hendon Lane N3	Monument erected in 1835 to Major John Cartwright by public subscription. Built of yellow oolitic limestone, with square tapering obelisk and armorial and portrait roundels.
	DESIGNATION:	Listed Building grade II, CA	The monument has been dismantled due to its dangerous condition and plans for restoration are under discussion.
	CONDITION:	Poor	
LOFF CALLS	OCCUPANCY:	N/A	
H	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© English Heritage Archive	LIST ENTRY NUMBER:	1246062	Contact: Jonathan Hardy (LPA) 020 8359 4655

	SITE NAME:	Railway Hotel including sign in front and former off-sales building to west, Station Road, Edgware	The Railway Hotel dates from 1931 and was designed by AE Sewell for the brewers, Truman Hanbury Buxton. It is a large, prominent, three storey, half-timbered roadhouse and one of the best examples of its type in the country. It
	DESIGNATION:	Listed Building grade II	has been closed as a public house for over six years. The listing includes the former off-sales building to the west and
	CONDITION:	Fair	the gibbet sign on the frontage. A scheme of restoration and extension for hotel use has been approved although
	OCCUPANCY:	Part occupied/part in use	not implemented.
	PRIORITY CATEGORY:	D (D)	
© English Heritage	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1096066	Contact: Jonathan Hardy (LPA) 020 8359 4655

	SITE NAME:	Physic Well, Well Approach	Timber-framed cruciform cover to well circa 1937.
	DESIGNATION:	Listed Building grade II	Beneath is the original CI7 barrel-vaulted brick well chamber. Once a fashionable rendezvous for Londoners
	CONDITION:	Poor	for the medicinal qualities of the mineral waters. Proposals for refurbishment are being discussed.
	OCCUPANCY:	Vacant/not in use	for real distingent are being discussed.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1064804	Contact: Jonathan Hardy (LPA) 020 8359 4655
© English Heritage Archive			

Acres	SITE NAME:	Church of St Jude, Central Square, Hendon NWI I	Designed by Sir Edwin Lutyens, St Jude's was consecrated in 1911 with the west end finally completed in 1935.
	DESIGNATION:	Listed Place of Worship grade I, CA	Frescoes throughout by Walter Starmer 1919-30. Built in grey and red brick with stone dressings and clay tiled roofs It has a tall open tower and spire. The church has damp
	CONDITION:	Poor	issues, including the crypt which is prone to flooding. Th is cracking evident internally and some areas of the
	PRIORITY CATEGORY:	C (New entry)	frescoes are suffering from salt damage. Localised repairs
	OWNER TYPE:	Religious organisation	are required to the brickwork and the roofs. The heating system requires overhauling.
	LIST ENTRY NUMBER:	1294714	Contact: Tracey Craig 020 7973 3756
English Heritage			

© English Heritage

1

SITE NAME:	Brockley Hill Romano-British pottery and settlement			
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018006	
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown	
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No	
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145	
SITE NAME:	College Farm, Finchley N3			
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No	
CONDITION:	Poor	TREND:	Deteriorating	
VULNERABILITY:	Medium	CONTACT:	Jonathan Hardy (LPA) 020 8359 4655	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / BEXLEY / BRENT

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

D (D)

Part occupied/part in use

Commercial company

BEXLEY

Ô

DEALET			
	SITE NAME:	Crossness Pumping Station, Belvedere Road SE28	Opened 4 April 1865; the engineer was Joseph Bazalgette. The building retains important cast iron interior fittings and
	DESIGNATION:	Listed Building grade I, CA	four colossal beam engines by James Watt and Co. The Crossness Engines Trust is restoring the building, with
The second secon	CONDITION:	Good	funding from the Heritage Lottery Fund. Work is expected to finish in 2015.
THE ADAR AND THE	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (heritage)	
© English Heritage	LIST ENTRY NUMBER:	1064241	Contact: Elizabeth Whitbourn 07889 808145
	SITE NAME:	Chapel House, 497, Blackfen Road, Sidcup	An eye-catcher as part of the layout of Danson Park, circa 1761 and attributed to Lancelot 'Capability' Brown. The
	DESIGNATION:	Listed Building grade II	Chapel House is now separated from the park by the A2 trunk road and modern houses. Some render repairs have
	CONDITION:	Fair	been carried out. The building forms part of a larger extant

©	English	Heritage

© English Heritage



LIST ENTRY NUMBER: 1064248 Contact: Gordon Fraser (LPA) 020 3045 5789 St Paulinus dates from the CII when the church was in the SITE NAME: Parish Church of St Paulinus, form of a simple two-cell building on the footprint of the Perry Street, Bexley current north nave. By 1220, a parallel nave was added on the south side, later arcaded. By the 1430s a western Listed Place of Worship grade DESIGNATION: II*, CA tower had been added, largely in the form we see today. An eastern chapel houses fine C17 monuments, and the CONDITION: Poor marble reredos in the chancel dates from the C19 restoration. Repairs are needed to flint walling, the tower PRIORITY CATEGORY: C (New entry) stonework and the drainage system, which is the cause of OWNER TYPE: Religious organisation much dampness in the lower walls. The church is seeking funding for the repairs. LIST ENTRY NUMBER: 1359434 Contact: Ian Harper 020 7973 3786

	SITE NAME:	Lamorbey Park	A C18 landscape park with early C19 pleasure grounds and
	DESIGNATION:	Registered Park and Garden grade II, 4 LBs, part in CA	C20 gardens. The park was partially converted to a golf course in the early C20 and further subdivided by the construction of three schools. London Borough of Bexley
	CONDITION:	Generally satisfactory but with minor localised problems	manages part as a public park. The gardens and pleasure grounds are in need of repair, and the management of the historic landscape is disjointed due to the separate
The Barrow	VULNERABILITY:	Medium	ownerships.
- 1. Marke	TREND:	Declining	
	NEW ENTRY?:	No	
e	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000289	Contact: Zosia Mellor 020 7973 3473

© English Heritage

BRENT			
	SITE NAME:	Cambridge Hall, Cambridge Avenue, Kilburn NW6	Built in 1863 as St James's Episcopal Chapel. Prefabricated structure of corrugated iron with boarded roof covered in
	DESIGNATION:	Listed Building grade II, CA	corrugated asbestos. The Hall is within the South Kilburn New Deal for Communities area and is the subject of a
	CONDITION:	Poor	conservation study and assessment. A planning applicatio has been submitted for a new residential building alongsic and conservation works to the Hall.
ATT	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Other not for profit group	
© English Heritage	LIST ENTRY NUMBER:	1271962	Contact: Ben Martin (LPA) 020 8937 5231

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

Е

- obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

redevelopment scheme, which if implemented will result in

the building being refurbished and brought back into

sustainable use.

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2014 / LONDON / BRENT / BROMLEY

SITE NAME:	Old Oxgate Farm, Coles Green Road, Cricklewood NW2	C16 and C17 timber-framed building suffering from subsidence to the brick plinth and structural failure of beam
DESIGNATION:	Listed Building grade II*	ends to the ground floor due to damp penetration. The owner is actively exploring possible solutions and carried
CONDITION:	Poor	out urgent works in 2013.
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1078875	Contact: Elizabeth Whitbourn 07889 808145
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Road, Cricklewood NW2DESIGNATION:Listed Building grade II*CONDITION:PoorOCCUPANCY:Occupied/in usePRIORITY CATEGORY:C (C)OWNER TYPE:Private

© English Heritage

BROMLEY

© Lor

© English Heritage

	SITE NAME:	The Studio, 28, Beckenham Road, Beckenham	Technical Institute and later an arts centre. Built in Dutch style in 1898 for Beckenham Urban District Council.
	DESIGNATION:	Listed Building grade II, CA	Planning Permission and Listed Building Consent have been granted for community use. Work is yet to commence.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
ondon Borough of Bromley	LIST ENTRY NUMBER:	1390855	Contact: Kevin Munnelly (LPA) 020 8313 4582

SITE NAME: Crystal Palace Park SE19 C19 pleasure grounds designed by Sir Joseph Paxton as a setting for the Crystal Palace (re-erected here 1852-4 and Registered Park and Garden burnt down in 1936). The park is in variable condition and DESIGNATION: grade II*, 7 LBs, part in CA the grade II listed terraces, pedestrian subway and railings are also at risk. Specialist surveys of the terrace sphinxes Generally satisfactory but with CONDITION: were carried out in 2013 and a condition survey of the significant localised problems subway is underway, grant-aided by English Heritage. The VULNERABILITY: Medium Mayor of London and Bromley Council plan to invest £2.4 million towards improvements to the park. TREND: Declining NEW ENTRY ?: No OWNER TYPE: Local authority LIST ENTRY NUMBER: 1000373 Contact: Zosia Mellor 020 7973 3473



	SITE NAME:	Pedestrian subway under Crystal Palace Parade, Crystal Palace SE19	Pedestrian subway circa 1854. The subway was included in the 2008 masterplan application for the regeneration of the wider park as the site of a proposed new museum. A		
	DESIGNATION:	Listed Building grade II, RPG grade II*	condition survey and investigative works are in progress, grant-aided by English Heritage.		
	CONDITION:	Poor			
a ber	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	C (C)			
ve	OWNER TYPE:	Local authority			
	LIST ENTRY NUMBER:	1385457	Contact: Kevin Munnelly (LPA) 020 8313 4582		

© English Heritage Archive

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building Local Planning Authority National Park CA LB
- LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / BROMLEY

©

	SITE NAME:	Downe Court Manor, Cudham Road, Downe	Modest red brick house of 1690. The building is currently vacant and starting to show the effects of long term
p English Freihage Archive	LIST ENTRY NUMBER:	1064352	Contact: Kevin Munnelly (LPA) 020 8313 4582
© English Heritage Archive	OWNER TYPE:	Local authority	
and the second second	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	N/A	
	CONDITION:	Poor	was undertaken in 2013, grant-aided by English Heritage.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	and burnt down in 1936), on the west of Crystal Palace Park. The terraces are in a ruinous condition and sufferin from erosion. A condition survey of the terrace sphinxes
	SITE NAME:	Upper and Lower Terraces, Crystal Palace Park SE19	Terraces designed by Sir Joseph Paxton and situated to east of the site of Crystal Palace (re-erected here in 185
	LIST ENTRY NUMBER:	1393659	Contact: Kevin Munnelly (LPA) 020 8313 4582
) English Heritage	OWNER TYPE:	Local authority	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	N/A	
I State I	CONDITION:	Poor	
	DESIGNATION:	Listed Building grade II, RPG grade II*	1936) from Crystal Palace Parade. There is damage to some cast iron panels and dwarf wall.
	SITE NAME:	North and south railings, Crystal Palace Parade, Crystal Palace Park SE19	Decorative cast iron railings on gault brick plinths with stone copings, which formed the main pedestrian entrance to the Crystal Palace (demolished following a major fire in



© English Heritage

neglect. Roof and joinery repairs have been undertaken to DESIGNATION: Listed Building grade II arrest the decline of the building. CONDITION: Poor OCCUPANCY. Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1064357 Contact: Kevin Munnelly (LPA) 020 8313 4582

Offices, cutting shop, tool room and storage factory. SITE NAME: Frontage building to Richard Klinger Factory, Edgington Way, Completed in 1937 to the designs of Wallis Gilbert and Partners for Richard Klinger Ltd, founded in Austria in Sidcup 1893. The building has been vacant for many years. The DESIGNATION: Listed Building grade II crittal window frames are intact, but the interior is dilapidated. The current owner is marketing the property CONDITION: Poor and it is understood that there is interest. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company © London Borough of Bromley LIST ENTRY NUMBER: 1387704 Contact: Kevin Munnelly (LPA) 020 8313 4582



SITE NAME:	20-22, Hamlet Road, Crystal Palace SEI9	Pair of mid C19 stuccoed houses suffering from structural problems. Some urgent works have been undertaken,
DESIGNATION:	Listed Building grade II, CA	including the removal of a tree from the front garden and the erection of additional scaffolding. Discussions are
CONDITION:	Poor	ongoing with regards to further remedial works required to stabilise the buildings, as well as a longer-term
OCCUPANCY:	Vacant/not in use	development scheme.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	3593 9	Contact: Kevin Munnelly (LPA) 020 8313 4582

© London Borough of Bromley

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2014 / LONDON / BROMLEY



SITE NAME:	91, High Street, St Mary Cray	C16 dwelling with crown post roof. The building is in a very
DESIGNATION:	Listed Building grade II, CA	poor condition and at risk of collapse. It is currently being recorded by a local archaeological society. Listed Building
CONDITION:	Very bad	Consent has been granted for the restoration of the property for residential use.
OCCUPANCY:	Vacant/not in use	property for residential use.
PRIORITY CATEGORY:	B (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1298993	Contact: Kevin Munnelly (LPA) 020 8313 4582

© London Borough of Bromley

H HT.

	SITE NAME:	The Royal Bell Hotel, 173-177, High Street, Bromley	This range of buildings was rebuilt in 1898 on the site of an earlier hostelry of 1666. The Royal Bell Hotel is vacant and	
	DESIGNATION:	Listed Building grade II, CA	boarded up. Á community use is under discussion.	
	CONDITION:	Fair		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1054095	Contact: Kevin Munnelly (LPA) 020 8313 4582	

© English Heritage

© English Heritage



	SITE NAME:	Former Officers' Mess, RAF Biggin Hill, Main Road, Biggin Hill	Officers' mess, circa 1935. Partially occupied but suffering neglect due to the cost of repairs and maintenance. Some works have been carried out. Planning Permission and
14	DESIGNATION:	Listed Building grade II, CA	Listed Building Consent have been granted for conversion to a hotel.
1	CONDITION: Poor		
	OCCUPANCY:	Part occupied/part in use	
院	PRIORITY CATEGORY:	D (D)	
1	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1186840	Contact: Robert Buckley (LPA) 020 8461 7532



© London Borough of Bromley



No.	SITE NAME:	Building 15, Hawkinge Block, West Camp, Main Road, A233	Barrack block dated 1934. Built by the Air Ministry's Directorate of Works and Buildings, but vacant since the
	LIST ENTRY NUMBER:	1391606	Contact: Kevin Munnelly (LPA) 020 8313 4582
	OWNER TYPE:	Commercial company	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	Vacant/not in use	
	CONDITION:	Poor	
	DESIGNATION:	Listed Building grade II, CA	
物たとう	SITE NAME:	Building 12 (Candidates' Club, Former Sergeants' Mess), West Camp, Main Road, A233 (east side), Biggin Hill	Sergeants' mess, 1932. Built by the Air Ministry's Directorate of Works and Buildings, but vacant since the RAF withdrew from Biggin Hill in 1993. The Council is working with the owners to explore possible new uses.

	and the second s	SITE NAME:	Building I 5, Hawkinge Block, West Camp, Main Road, A233 (east side), Biggin Hill	Barrack block dated 1934. Built by the Air Ministry's Directorate of Works and Buildings, but vacant since the RAF withdrew from Biggin Hill in 1993. The Council is
		DESIGNATION:	Listed Building grade II, CA	working with the owners to explore possible new uses.
		CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use		
		PRIORITY CATEGORY:	C (C)	
© London Borough of Bromley	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1391604	Contact: Kevin Munnelly (LPA) 020 8313 4582	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / BROMLEY

SITE NAME: Building 33 (Station HQ), West Camp, Main Road, A233 (east side), Biggin Hill Office block dated 1931, formerly the station headquarter building. The building has been vacant since the RAF withdrew from Biggin Hill in 1993. The Council is working with the owners to explore possible new uses. DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1391587				
DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company		SITE NAME:	Camp, Main Road, A233 (east	building. The building has been vacant since the RAF withdrew from Biggin Hill in 1993. The Council is workir
© London Borough of Bromley FOOL		DESIGNATION:	Listed Building grade II, CA	
PRIORITY CATEGORY: C (C) OWNER TYPE: Commercial company		CONDITION:	Poor	
© London Borough of Bromley		OCCUPANCY:	Vacant/not in use	
© London Borough of Bromley		PRIORITY CATEGORY:	C (C)	
		OWNER TYPE:	Commercial company	
	© London Borough of Bromley	LIST ENTRY NUMBER:	39 587	Contact: Kevin Munnelly (LPA) 020 8313 4582

	SITE NAME:	Buildings I-5 (Airmens' barrack blocks), West Camp, Main Road, A233 (east side), Biggin Hill	Group of five airmens' barracks blocks, 1930. The buildings have been vacant since the RAF withdrew from Biggin Hill in 1993. The Council is working with the owners to explore possible new uses.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
The second second	PRIORITY CATEGORY:	E (C)	
ndon Borough of Bromley	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1391589	Contact: Kevin Munnelly (LPA) 020 8313 4582

	SITE NAME:	lce house to Sundridge Park, Plaistow Lane, Bromley	Ice house circa 1800, in the south west corner of a late C18 landscape park designed by Humphry Repton, now a golf course. The ice house is subject to continuous vandalism despite strenuous efforts by owners to prevent access. Negotiations about its future have so far failed to
	DESIGNATION:	Listed Building grade II, RPG grade II	
MARCH STR	CONDITION:	Very bad	find a suitable solution.
© English Heritage	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1254001	Contact: Kevin Munnelly (LPA) 020 8313 4582

	SITE NAME:	The Convent of the Holy Trinity, Plaistow Lane, Bromley	House built by John Hulls about 1708 and since 1888 used as a convent and school. The building is currently vacant
	DESIGNATION:	Listed Building grade II	and covered in order to protect it against the elements. Planning Permission and Listed Building Consent have been
	CONDITION:	Very bad	granted to convert the building into flats and works are underway.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (B)	
	OWNER TYPE:	Religious organisation	
© London Borough of Bromley	LIST ENTRY NUMBER:	1186782	Contact: Kevin Munnelly (LPA) 020 8313 4582

© Lond



	SITE NAME:	lce house to Old Palace, Stockwell Close, Bromley Palace Park	Ice house to Bromley Old Palace, located in the gardens of the Palace at the southern end of the ornamental lake near the waterfall. Probably late C18, remodelled in the early
	DESIGNATION:	Listed Building grade II	C19 as a garden shelter, possibly used as a stopping-off point when guests at the Old Palace were taken for a
	CONDITION:	Poor	perambulation of the grounds. The ice house is currently in poor condition and in need of conservation and repair. A
	OCCUPANCY:	N/A	budget has been allocated for repairs and quotes are being
	PRIORITY CATEGORY:	D (C)	sought.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1281268	Contact: Kevin Munnelly (LPA) 020 8313 4582

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Pulhamite fernery, Stockwell Close, Bromley Palace Park	Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace
Mach-	DESIGNATION:	Listed Building grade II	that had been acquired by Coles Child, a wealthy coal merchant. The fernery is at the northern end of the
	CONDITION:	Poor	ornamental lake and is in need of repair.
A REAL OF THE	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1392584	Contact: Kevin Munnelly (LPA) 020 8313 4582

A CARACTER STATE	SITE NAME:	Pulhamite waterfall, Stockwell Close, Bromley Palace Park	Pulhamite rock-work garden feature constructed c1865 as part of the improvements to the gardens of Bromley Palace
	DESIGNATION:	Listed Building grade II	that had been acquired by Coles Child, a wealthy coal merchant. The waterfall is at the southern end, adjacent to
	CONDITION:	Poor	a probably late C18 ice house, and is in need of repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1392583	Contact: Kevin Munnelly (LPA) 020 8313 4582

	SITE NAME:	Old Town Hall, Tweedy Road, Bromley	Former Town Hall building built in 1906 and used as premises for Bromley College until 2006/07. The building
	DESIGNATION: CONDITION:	Listed Building grade II, CA	is partially vacant and awaiting a suitable use. The Council is working with a development partner to bring forward a
A		Fair	proposal to convert the building to a hotel. A planning application is expected mid 2014.
	OCCUPANCY:	Part occupied/part in use	application is expected fille 2014.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1299012	Contact: Kevin Munnelly (LPA) 020 8313 4582
	SITE NAME:	Church of St John the Evangelist, High Street, Penge SE20	Church by John Nash and Edwin Nash of Bermondsey in the Early English style, completed in 1849. Built of ragstone with Bath stone dressings, including spire. The church is
	DESIGNATION:	Listed Place of Worship grade II, CA	suffering from water ingress at roof and lower levels, and dampness at lower levels. High level repairs to the east end were completed in 2013, grant-aided by English Heritage
	CONDITION:	Poor	and the Heritage Lottery Fund. A second phase of repairs is required to the west end.
			is required to the west end.

© English Heritage

Contact: Ian Harper 020 7973 3786

SITE NAME:	High Elms ice house 130m south of Flint Lodge		
DESIGNATION:	Scheduled Monument, LB grade II	LIST ENTRY NUMBER:	1018959
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE:

C (D)

1186832

Religious organisation

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / BROMLEY / CAMDEN

SITE NAME:	Iron Age settlement and Roman villa at Warban	<, Keston	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002024
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Private, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Scadbury Manor moated site and fishponds		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1409786
CONDITION:	Extensive significant problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Collapse	NEW ENTRY?:	Yes
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Romano-British masonry building and Saxon cen	netery, Fordcroft, Orp	pington
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001973
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Biggin Hill RAF		
DESIGNATION:	Conservation Area, 14 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Kevin Munnelly (LPA) 020 8313 4582

CAMDEN

© English Heritage

	SITE NAME:	Cattle trough to south east of the Roundhouse, Chalk Farm Road NWI	Late C19 granite cattle trough. Placed by the Metropolitan Cattle Trough and Drinking Fountain Association in memory of the Christian Socialist Charles Kingsley. Some
	DESIGNATION:	Listed Building grade II, CA	repairs have been carried out but investigation into the security of the trough on the plinth is required. It is vulnerable given its location adjacent to the bus lane and
-6	CONDITION:	Poor	vulnerable given its location adjacent to the bus lane and bus stop.
	OCCUPANCY:	N/A	<i>bus stop.</i>
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1258104	Contact: Caroline Welch (LPA) 020 7974 1944



© English Heritage

	LIST ENTRY NOTIDER.	1236104	Contact: Caroline Weich (LFA) 020 7974 1944
	SITE NAME:	Drinking fountain set in wall next to the Roundhouse, Chalk Farm Road NWI	Late C19 Gothic style drinking fountain presented by the Metropolitan Cattle Trough and Drinking Fountain Association. Cleaning has been carried out, but the drinking
	DESIGNATION:	Listed Building grade II, CA	fountain remains prone to littering and damage. Options for repair are being explored with the relevant partner
	CONDITION:	Poor	organisations.
Carlos and	OCCUPANCY:	N/A	
E I	PRIORITY CATEGORY:	C (C)	
100	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1258105	Contact: Caroline Welch (LPA) 020 7974 1944

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



© London Borough of Camden

© London Borough o

I	SITE NAME:	Stanley Sidings: stables (inc. stables A, B, C, D), Chalk Farm Road NWI	Important complex of industrial stabling built 1883-1895 for the Camden Goods Yard of the London and North Western Railway. The Local Planning Authority is dealing
	DESIGNATION:	Listed Building grade II, CA	with Planning and Listed Building Consent applications for the repair and sensitive adaptation of the Tack Room, with
	CONDITION:	Fair	a view to works commencing on site in summer 2014. Applications for remedial works to the Provender Store
	OCCUPANCY:	Occupied/in use	are also expected in summer 2014. The LPA is hoping to
	PRIORITY CATEGORY:	C (D)	work collaboratively with the building owners to avoid serving repairs and enforcement notices.
Lir I	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1258101	Contact: Caroline Welch (LPA) 020 7974 1944

of Camden	SITE NAME:	Monument to John Hodgson, Church Road, St John's Churchyard, Hampstead NW3	Stone stele from the mid-C19 with flanking angels holding a cross and an inscription. The monument is leaning heavily, but propping has secured it temporarily. Listed Building
	DESIGNATION:	Listed Building grade II, CA	Consent has been granted for structural repairs.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1067360	Contact: Caroline Welch (LPA) 020 7974 1944

	SITE NAME:	Stanley Buildings South, Flats 21-30, Clarence Passage, King's Cross NI	Philanthropic flats built in 1865 to design by Matthew Allen under the guidance of Sydney Waterlow. Consent was granted in 2012 for conversion into offices and work is
ALV A	DESIGNATION:	Listed Building grade II, CA	underway.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1356760	Contact: Caroline Welch (LPA) 020 7974 1944

	SITE NAME:	Former Strand Union Workhouse (Middlesex Hospital Annex), 44, Cleveland Street WI	Former Strand Union workhouse, 1778 austere symmetrical brick building facing Cleveland Street behind later high brick walls. Vacated by University College London Hospital and in temporary occupation by live-in
LE LE E H H	DESIGNATION:	Listed Building grade II, CA	guardians and site staff in the adjoining unlisted buildings. The buildings are weathertight and secure; negotiations for
	CONDITION:	Fair	the redevelopment of the site are ongoing.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	
© English Heritage	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1242917	Contact: Caroline Welch (LPA) 020 7974 1944
IIIIIII	SITE NAME:	26, Denmark Street WC2	Early C18 terraced house; windows altered in C20. Bar on
日日前日	DESIGNATION:	Listed Building grade II, CA	ground floor. Windows, parapets and gutters are still in poor condition. Listed Building Consent and Planning

	SITE NAME:	26, Denmark Street WC2	Early C18 terraced house; windows altered in C20. Bar on
	DESIGNATION:	Listed Building grade II, CA	ground floor. Windows, parapets and gutters are still in poor condition. Listed Building Consent and Planning
	CONDITION:	Poor	Permission have been granted as part of a wider scheme which includes residential use on the upper floors and
	OCCUPANCY:	Part occupied/part in use	repairs to the roof and front parapet.
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1271982	Contact: Caroline Welch (LPA) 020 7974 1944

© English Heritage

PRIORITY CATEGORIES

А	Immediate risk of further rapid
	deterioration or loss of fabric: no
	a a lution a manual

D

Е

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented. C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	The Elms (formerly Elm Lodge), Fitzroy Park N6	Detached house built 1838-40 to the design of George Basevi. A listed building enforcement notice was served in	
	DESIGNATION:	Listed Building grade II, CA	2012 following unauthorised works during refurbishment. The Local Planning Authority is currently in receipt of	
	CONDITION:	Poor	Planning and Listed Building Consent applications for remedial works, but these are not yet determined.	
	OCCUPANCY:	Vacant/not in use	remedial works, but these are not yet determined.	
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Commercial company		
English Heritage	LIST ENTRY NUMBER:	1078355	Contact: Caroline Welch (LPA) 020 7974 1944	
Å	SITE NAME:	43, Fitzroy Street WI	One of a terrace of four houses, dating from the late C18,	
	DESIGNATION:	Listed Building grade II, CA	constructed from darkened multi-coloured stock brick with some stucco dressings. Comprising four storeys and	
	CONDITION:	Poor	basements. The property is partially occupied, and in a	
	OCCUPANCY:	Part occupied/part in use	deteriorating condition.	
	PRIORITY CATEGORY:	A (C)		
	OWNER TYPE:	Private		
English Heritage	LIST ENTRY NUMBER:	1322184	Contact: Caroline Welch (LPA) 020 7974 1944	
English Flentage				
m. Martine	SITE NAME:	Monuments in St Andrews Gardens, Gray's Inn Road WCI	Monuments in St Andrew's Gardens, the former St Andrew's Holborn Burial Ground, which was consecrat in 1754. The public gardens contain a number of C18 tombs, mostly with weathered inscriptions, but includin	
	DESIGNATION:	Listed Building grade II, CA		
	CONDITION:	Poor	one dating from 1753. The tombs are in varying states of poor repair and some are likely to require structural	
and and the second	OCCUPANCY:	N/A	remedial works.	
- Martin Pres	PRIORITY CATEGORY:	C (New entry)		
	OWNER TYPE:	Religious organisation		
English Heritage	LIST ENTRY NUMBER:	3 93	Contact: Caroline Welch (LPA) 020 7974 1944	
Tar	SITE NAME:	39, Great James Street WCI	One of a terrace of 14 houses, dating from 1720-24,	
	DESIGNATION:	Listed Building grade II*, CA	comprising four storeys and basement, constructed from brown brick. The property is currently empty. Listed	
	CONDITION:	Poor	Building Consent and Planning Permission were granted in 2011 for refurbishment and a rear extension. The	
	OCCUPANCY:	Vacant/not in use	consented scheme has not been implemented and no	
	PRIORITY CATEGORY:	B (F)	repairs have been undertaken.	
	OWNER TYPE:	Commercial company		
English Heritage	LIST ENTRY NUMBER:	1113203	Contact: Elizabeth Whitbourn 07889 808145	
Lanna Lagran St.	SITE NAME:	Ladies and gentlemen's public conveniences, Guilford Place WC1	Disused late C19 public lavatory sited on a traffic island. Enriched railings and gates with overthrows and lanterns. No current proposals.	
The state of the second se	DESIGNATION:	Listed Building grade II, CA		
	CONDITION	Poor		

A. C.	SITE NAME:	Ladies and gentlemen's public conveniences, Guilford Place WC1	Disused late C19 public lavatory sited on a traffic island Enriched railings and gates with overthrows and lanter No current proposals.
¢	DESIGNATION:	Listed Building grade II, CA	
10/20 111 700	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1245849	Contact: Caroline Welch (LPA) 020 7974 1944

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.


- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	66, Guilford Street WCI	One of a terrace of six houses built circa 1793-99 by James
	DESIGNATION:	Listed Building grade II, CA	Burton. Planning Permission and Listed Building Consent have been granted for change of use to a backpackers'
	CONDITION:	Fair	hostel. The works are not yet implemented.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1245858	Contact: Caroline Welch (LPA) 020 7974 1944

© English Heritage

	SITE NAME:	67, Guilford Street WCI	Part of a terrace of three houses built circa 1793-99 by
	DESIGNATION:	Listed Building grade II, CA	James Burton. Planning Permission and Listed Building Consent have been granted for change of use to a
	CONDITION:	Fair	backpackers' hostel. The works are not yet implemented.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1245860	Contact: Caroline Welch (LPA) 020 7974 1944

© English Heritage



	SITE NAME:	77-82 (consecutive), Guilford Street WCI	Terrace built circa 1793-99 by James Burton. Various degrees of deterioration. Consent was granted in 2012 for
	DESIGNATION:	Listed Building grade II, CA	change of use to residential and internal works. The consented scheme is currently being implemented.
	CONDITION:	Fair	, , ,
	OCCUPANCY:	Part occupied/part in use	
SRA.	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Private	
_	LIST ENTRY NUMBER:	1271620	Contact: Caroline Welch (LPA) 020 7974 1944

© English Heritage



© London Borough of Camden

	SITE NAME:	Drinking Fountain in St James Gardens, Hampstead Road NWI	Drinking fountain likely to date from the 1880s. Constructed from cast iron, the design closely resembles a pattern illustrated in Macfarlane's catalogue of circa 1880.
	DESIGNATION:	Listed Building grade II	The fountain has been temporarily removed from its plinth due to fire damage, and is being stored by the Local
	CONDITION:	Very bad	Authority with a view to its future repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1378714	Contact: Caroline Welch (LPA) 020 7974 1944

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	I, Hawley Road NWI	Early C19 detached villa. Repairs to render and joinery on
	DESIGNATION:	Listed Building grade II	the front facade are complete. The building is now weathertight. Planning Permission and Listed Building
	CONDITION:	Fair	Consent have been granted for various internal and external works to adapt the building for educational use
	OCCUPANCY:	Vacant/not in use	and to provide level access. These proposed works are in
	PRIORITY CATEGORY:	D (D)	connection with the use of the building as part of a new primary school to be built on an adjacent site.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1378820	Contact: Caroline Welch (LPA) 020 7974 1944

© London Borough of Camden



A Kur	SITE NAME:	Fountain and pond in the Italianate Garden, Witanhurst, Highgate West Hill N6	Fountain set in a circular pond forming a central feature of the Italianate Garden, built circa 1913, probably to the design of Harold Peto for Sir Arthur Crosfield. Repairs to the fountain are underway.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1379027	Contact: Caroline Welch (LPA) 020 7974 1944

© English Heritage

© English Heritage



	SITE NAME:	Four sculptures surrounding pond in Italianate Garden, Witanhurst, Highgate West Hill N6	Four carved figures, circa 1913, probably part of Harold Peto's design for Sir Arthur Crosfield's garden. Two are now missing; the remaining two are in storage. Repairs are underway.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1379028	Contact: Caroline Welch (LPA) 020 7974 1944

	SITE NAME:	Italianate Garden in grounds of Witanhurst, Highgate West Hill N6	Italianate Garden comprising walls, steps, gateway, sunken pond and pergola. Built circa 1913, probably designed by Harold Peto for Sir Arthur Crosfield. Repair works are
	DESIGNATION:	Listed Building grade II, CA	nearly complete.
CALLER THE REAL	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1379032	Contact: Caroline Welch (LPA) 020 7974 1944



	SITE NAME:	I and 2, Lincoln's Inn Fields WC2	Two early C18 terraced houses, converted to one in the C19. The building is protected by occupation. The Local	
	DESIGNATION:	Listed Building grade II, CA	Planning Authority has granted Planning Permission and Listed Building Consent for the conversion and extension	
	CONDITION:	Fair	of the properties to create a single family dwelling. Works have not yet commenced.	
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	D (E)		
-	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	379323	Contact: Caroline Welch (LPA) 020 7974 1944	

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument


	SITE NAME:	25, Mornington Crescent NWI	House forming part of a crescent, built circa 1821-23 by 1
	DESIGNATION:	Listed Building grade II, CA	Bryant for the Southampton Estate. Planning Permission and Listed Building Consent have been granted for
	CONDITION:	Fair	conversion to four flats and works of repair and reinstatement. Works are in progress and should be
	OCCUPANCY:	Part occupied/part in use	completed in 2014.
	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	3 40	Contact: Caroline Welch (LPA) 020 7974 1944


© English Heritage

© English Heritage

	SITE NAME:	Heath House, North End Way NW3	Substantial early C18 double-fronted detached house, with C19 extensions. Much of the house was rebuilt following
	DESIGNATION:	Listed Building grade II*, CA	war damage. The building has suffered prolonged water penetration and most interior fittings and detailings have
	CONDITION:	Poor	been removed. The building is currently protected by a temporary roof and monoflex wrapping. Discussions are
	OCCUPANCY:	Vacant/not in use	ongoing with the Council regarding the long-term use of
	PRIORITY CATEGORY:	C (New entry)	the building.
ne	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	3 83	Contact: Elizabeth Whitbourn 07889 808145

© London Borough of Camden







TIM	PRIORITY CATEGORY:	F (F)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	3 9	Contact: Caroline Welch (LPA) 020 7974 1944	
	SITE NAME: Section of boundary wall to St Stephen's Church, Rosslyn Hill NW3		Brick and stone boundary wall along Hampstead Green, 1869. Repairs are complete to the wall and piers in location of entrances, but other areas on Rosslyn Hill and fronting	
	DESIGNATION:	Listed Building grade II, CA	Hampstead Green need repairs to the stone copings and repointing.	
Tu The	CONDITION:	Poor		
La Partie	OCCUPANCY:	N/A		
- Alexandre	PRIORITY CATEGORY:	C (F)		
	OWNER TYPE:	Charity (non-heritage)		
	LIST ENTRY NUMBER:	1130395	Contact: Caroline Welch (LPA) 020 7974 1944	

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ŬA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Baptist Church House, 2-6 (even), Southampton Row WCI	Former Baptist Chapel, offices and shop built 1901-3 to the design of Arthur Keen, architect for the Baptist Union of
in min	DESIGNATION:	Listed Building grade II*, CA	Great Britain and Ireland. 'Wrenaissance' style with Flemish-inspired shaped gables and eclectic baroque and
	CONDITION:	CONDITION: Eair Arts and Crafts details.	Arts and Crafts details. Planning Permission and Listed Building Consent were granted for restoration and
	OCCUPANCY:	Part occupied/part in use	conversion to a hotel; the commencement of works is
	PRIORITY CATEGORY:	D (D)	anticipated.
	OWNER TYPE:	Commercial company	
ge Archive	Archive LIST ENTRY NUMBER: 1378782		Contact: Elizabeth Whitbourn 07889 808145

© English Heritage

	SITE NAME:	Toll Gate House, Spaniards Road, Highgate NW3	Late C18 toll house, marking the spot where the road entered the Bishop of London's estate. It stands at a traffic
	DESIGNATION:	Listed Building grade II	bottleneck on a busy road and has suffered impact damage from heavy vehicles. A bollard was erected in late 2008 to
	CONDITION:	Good	provide protection from traffic. Roof and guttering repair works have been undertaken and the property is now in good condition, but remains unoccupied.
R. A.	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
© English Heritage Archive	LIST ENTRY NUMBER:	1378793	Contact: Caroline Welch (LPA) 020 7974 1944

	SITE NAME:	108, St Pancras Way, Kentish Town NW1	End of terrace house dating from the mid 1820s, with early C19 shop front. The building has been squatted intermittently and is in poor condition. Temporary roof repairs were carried out in early 2012. A Repairs Notice
E III	DESIGNATION:	Listed Building grade II, CA	
TETLET	CONDITION:	Poor	has been served on the property. Implementation of extant consents and remedial works in accordance with the notice
	OCCUPANCY:	Vacant/not in use	have commenced.
	PRIORITY CATEGORY:	F (A)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1245848	Contact: Caroline Welch (LPA) 020 7974 1944

SITE NAME:	65, Swinton Street WCI	Terraced house circa 1775, with late C19 shop front.
DESIGNATION:	Listed Building grade II, CA	Currently unoccupied and deteriorating. The building is in very poor condition, with much of the interior removed.
CONDITION:	Very bad	Consents were granted in 2012 for conversion to a hotel, but the scheme has not yet been implemented.
OCCUPANCY:	DCCUPANCY: Vacant/not in use	but the scheme has not yet been implemented.
PRIORITY CATEGORY:	B (B)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1378960	Contact: Caroline Welch (LPA) 020 7974 1944

© English Heritage



	SITE NAME:	Eastern coal drops at Kings Cross Goods Yard, York Way NI	Coal drops built in 1851-2, probably to the design of Lewis Cubitt, to carry high level track for the transport of coal into storage bins. Part of a system of distributing coal from the North East and Yorkshire to the London market. Proposals for a mixed use scheme were included in the Kings Cross Central planning application.	
	DESIGNATION:	Listed Building grade II, CA		
	CONDITION:	Fair		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1379214	Contact: Caroline Welch (LPA) 020 7974 1944	

© English Heritage Archive

- А
- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDO	DN / CAMDEN		
	SITE NAME:	St George's Cathedral (formerly Christ Church), Albany Street, Camden Town NW1	Designed by Sir James Pennethorne, built 1837 in neo- Grecian style to serve Nash's development east of Regents Park, with later alterations. Grey stock brick with Roman cement and stone dressings. There is vegetation growth on the spire. The Roman cement mouldings and past repairs in cementitious mortar are failing in places. Cracking is evident, particularly on the principal south elevation.
	DESIGNATION:	Listed Place of Worship grade II*, CA	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1378620	Contact: Tracey Craig 020 7973 3756
			, ,
Paglish Heritage	SITE NAME:	Church of St Michael, Camden Road, Camden Town NWI	The nave and aisles were built in 1881 designed by GF Bodley and T Garner, chancel added in 1894 and vestries in 1908. Bodley's altar, reredos, stone chapel vaulting and screen survive. The church has undergone structural and stonework repair, re-roofing and drainage works. The electrics have been disconnected due to their hazardous condition and there is now only a temporary supply. The church has been awarded a first round pass from the Heritage Lottery Fund for works including a new electrical installation. Repair works are expected to start summer
	DESIGNATION:	Listed Place of Worship grade II*	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	D (New entry)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1244156	
			2015.
			Contact: Tracey Craig 020 7973 3756
	SITE NAME:	Church of the Holy Trinity with St Barnabas, Clarence Way NWI	Built 1849-50 in a C14 Gothic style to the design of Thomas H Wyatt and David Brandon. The church was bomb damaged during World War II and is now suffering from structural movement. The tower roof was re-covered and the roofs re-slated with Heritage Lottery Fund/English Heritage grant aid. The church has been awarded a first round pass from the Heritage Lottery Fund for repairs to the tower stonework, currently in poor condition. The development phase of the project is nearing completion and repair works are expected to start in 2014.
2 CIA	DESIGNATION:	Listed Place of Worship grade II	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1356761	Contact: Tracey Craig 020 7973 3756
© English Heritage			
	SITE NAME:	Church of the Holy Cross, Cromer Street, Camden Town WCI	The church was built in the Early English style in 1885 by Joseph Peacock with additional internal features by Charles Nicholson c1913. Built of yellow stock brick under clay tiled roofs; stone dressings inside and out with red brick banding inside. The church has an unusual two-storey Narthex with bellcote. There is settlement of the foundations at the north-east corner causing structural cracking to the vestry and associated walls of the church itself. The east end roofing and north side guttering are in
	DESIGNATION:	Listed Place of Worship grade II, CA	
	CONDITION:	Very bad	
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE:	Religious organisation	need of repair.
© English Heritage	LIST ENTRY NUMBER:	1067375	Contact: Ian Harper 020 7973 3786
	SITE NAME:	Christ Apostolic Church (formerly Church of St John), Highgate Road, Kentish Town NW5	Church built on the site of the Kentish Town Chapel of 1783 by James Wyatt, of which the nave walls and apse remain. The rest was rebuilt in 1843-45 by JH Hakewill. High level repairs to the west end, grant-aided by English Heritage/Heritage Lottery Fund, are complete. Further works are required to the roofs, high level stonework, boundary wall and gates. The church suffered storm damage in December 2013 and repairs to the affected area are underway.
	DESIGNATION:	Listed Place of Worship grade II	
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
© English Heritage Archive	LIST ENTRY NUMBER:	1379013	Contact: Ian Harper 020 7973 3786

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / CAMDEN

A A III	SITE NAME:	St Andrew's Cathedral (former Church of St Barnabas), Kentish Town Road, Hampstead NWI	This church was constructed in the style of a three-aisled basilica (without a dome) by Ewan Christian in 1884-85. It has been in use by the Greek Orthodox Church since
	DESIGNATION:	Listed Place of Worship grade II, CA	1957, and became their St Andrew's Cathedral in 1970. All internal walls and ceilings have been decorated in the traditional Byzantine style, but large areas of plaster are
	CONDITION:	Poor	detaching due to dampness. Externally the tabled guttering to the aisles and apse needs renewal.
	PRIORITY CATEGORY:	A (New entry)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1379241	Contact: Ian Harper 020 7973 3786

S
C
C
Ρ
C

C.	SITE NAME:	Church of St Mary Magdalene, Munster Square, Camden Town NW1	The church, designed by RC Carpenter and completed in 1852, was described in the Ecclesiologist as the 'most artistically correct new church in London'. Even so, it was
	DESIGNATION:	Listed Place of Worship grade II*, CA	altered in 1866-67, and in 1883-84 the north aisle and crypt were added. Built of ragstone with Welsh slate roofs on Baltic fir collar-braced trusses. The interior is richly
CONDITIO	CONDITION:	Poor	decorated with marbles and frescoes. The condition of the frescos is deteriorating as a result of damp caused by leaks
	PRIORITY CATEGORY:	A (New entry)	in the roof and defective rainwater goods. Externally there
	OWNER TYPE:	Religious organisation	is localised decay to the stonework.
	LIST ENTRY NUMBER:	1113157	Contact: Ian Harper 020 7973 3786

© English Heritage



Dates from the CI3 and enlarged in the CI9, but retains SITE NAME: St Pancras Old Church, Pancras Road, Camden Town NWI CI3 and CI5 fabric and some very fine wall memorials. The church exhibits cracking externally and internally. Listed Place of Worship grade Monitoring is showing movement to be progressive and DESIGNATION: II*, RPG grade II, CA not just seasonal. A contributing cause is considered to be the very deep and narrow C19 gully which runs around the CONDITION: Poor building. The church has been awarded a first round pass PRIORITY CATEGORY: from the Heritage Lottery Fund to undertake further D (New entry) investigations and develop a repair strategy. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: Contact: Tracey Craig 020 7973 3756 1113246

© English Heritage



Designed by Frederick and Horace Francis in 1856 with SITE NAME: Church of St Mary and attached spire added in 1872. Kentish ragstone with Bath stone walls, piers and gates, Priory dressings and slate roofs. Stonework repairs to the north Road, Hampstead NW6 and south transept gables and east end of the nave were Listed Place of Worship grade II, carried out in 2008, grant-aided by English Heritage. A DESIGNATION CA Heritage Lottery Fund/English Heritage Repair Grant for Places of Worship was awarded in 2013 for stone repairs CONDITION: Poor to the west elevation of the nave and north aisle. Work is expected to start during 2014. Repairs are still required to PRIORITY CATEGORY: C (D) the tower and spire stonework. OWNER TYPE-Religious organisation LIST ENTRY NUMBER: 1139083 Contact: Tracey Craig 020 7973 3756

© English Heritage



		Designed by H and HW/ Inwood, built in 1822 and
SITE NAME:	Church of St Pancras, Upper Woburn Place, Camden Town NWI	Designed by H and HW Inwood, built in 1822 and restored in 1953. The earliest Greek Revival church in London. West end Ionic portico to a vestibule with tower
DESIGNATION:	Listed Place of Worship grade I, CA	above. The north and south facades each have a tribune with a portico supported by four caryatids with a sarcophagus behind. The church has been awarded a first
CONDITION:	Poor	round pass from the Heritage Lottery Fund and the development phase is underway. Repair works to the west
PRIORITY CATEGORY:	D (C)	portico roof and surrounding stone parapets, currently in
OWNER TYPE:	Religious organisation	poor condition, are due to commence in 2015. The condition of the tower will also be investigated.
LIST ENTRY NUMBER:	1379062	Contact: Tracey Craig 020 7973 3756

© English Heritage

PRIOR	IT	CAI	EGO	RIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е


Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building Local Planning Authority National Park CA
- LB I PA
- NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

HERITAGE AT RISK 2014 / LONDON / CAMDEN / CITY OF LONDON



© English Heritage

© English Heritage

CITY OF LONDON

	SITE NAME:	St Mary Somerset Tower, Upper Thames Street EC4	Redundant church built between 1686-94 by Wren. Body of church destroyed in 1871. Permission has been granted
1	DESIGNATION:	Listed Building grade I	for renovations and extension in connection with conversion to residential use.
	CONDITION:	Fair	
Ran teleistel	OCCUPANCY:	Vacant/not in use	
HAN MERIE	PRIORITY CATEGORY:	F (F)	
C Equanda	OWNER TYPE:	Local authority	
ge Archive	LIST ENTRY NUMBER:	1358904	Contact: Elizabeth Whitbourn 07889 808145



	SITE NAME:	Church of St Bride, Fleet Street, City of London EC4	Wren church of 1671-8 on the site of an earlier church, the Medieval crypts of which were excavated after World War
	DESIGNATION:	Listed Place of Worship grade I, CA	II. The church has the tallest of all Wren spires which is unique in form. Repairs to the spire were completed in 2014; however, the condition of the nave parapets, the
	CONDITION:	Poor	aisle roofs and the clerestory walls and windows remains
	PRIORITY CATEGORY:	C (F)	poor.
10.0	OWNER TYPE:	Religious organisation	
- Tell	LIST ENTRY NUMBER:	1064657	Contact: Ian Harper 020 7973 3786

Jen-	SITE NAME:	Church of St Andrew, Holborn Viaduct, City of London EC4	encasing CI5 tower. The nave was substantially	
	DESIGNATION:	Listed Place of Worship grade I	reconstructed following World War II bombing. The upper tower dates from the C18. Brick with Portland stone	
	CONDITION:	Poor	dressings and facing to the tower. Iron cramps in the tower are rusting and stone spalling off. Repair works to the	
	PRIORITY CATEGORY:	D (C)	tower are due to start in late 2014, grant-aided by the	
• "	OWNER TYPE:	Religious organisation	Heritage Lottery Fund.	
	LIST ENTRY NUMBER:	1064643	Contact: Ian Harper 020 7973 3786	

© English Heritage

© English Heritage



Designed by Sir Christopher Wren this church was built SITE NAME Church of St Margaret, between 1686 and 1695. The form is a simple rectangle Lothbury, City of London EC2 orientated north-south with a vestry to the east and a Listed Place of Worship grade I, tower to the west end. The south elevation is faced in DESIGNATION: CA Portland stone while the others are rendered with stone dressings. The four-stage tower is topped with a cupola CONDITION: Poor and obelisk. The church has fine contemporary fittings. PRIORITY CATEGORY: A (New entry) There are cracks evident externally between the tower and the body of the church, which are being monitored. The OWNER TYPE: Religious organisation floor of the nave is also undulating as a result of differential settlement. LIST ENTRY NUMBER: 1064634

© English Heritage

Contact: lan Harper 020 7973 3786

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014 / LONDON / CITY OF LONDON / CROYDON

SITE NAME: London Wall: section of Roman and Medieval wall at St Alphage garden, incorporating remains of St Alpha Church EC2 DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1018886 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No OWNER TYPE: Local authority CONTACT: Elizabeth Whitbourn 07889 80814 SITE NAME: Roman wall in basement of 90 Gracechurch Street EC3 I002035 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002035 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No				
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY:NoOWNER TYPE:Local authority, multiple ownersCONTACT:Elizabeth Whitbourn 07889 80814SITE NAME:London Wall: section of Roman and Medieval wall at St Alphage garder, incorporating remains of St AlphaDESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1018886CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY:NoOWNER TYPE:Local authorityCONTACT:Elizabeth Whitbourn 07889 80814STE NAME:Roman wall in basement of 90 Gracechurch Street E/Elizabeth Whitbourn 07889 80814STE NAME:Roman wall in basement of 90 Gracechurch Street E/Io02035DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1002035CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY:No	SITE NAME:		from west end of <i>i</i>	All Hallows Church to 38 Camomile
CONDITION: problems Pro	DESIGNATION:	Scheduled Monument, 2 CAs	LIST ENTRY NUMBER:	1002050
OWNERTTYPE: Local authority, multiple owners CONTACT: Elizabeth Whitbourn 07889 80814 SITE NAME: London Wall: section of Roman and Medieval wall at St Alphage garden, incorporating remains of St Alpha DESIGNATION: Scheduled Monument UST ENTRY NUMBER: 1018886 CONDITION: Generally satisfactory but with significant localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY: No OWNER TYPE: Local authority CONTACT: Elizabeth Whitbourn 07889 80814 SITE NAME: Roman wall in basement of 90 Gracechurch Street EC3 Elizabeth Whitbourn 07889 80814 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002035 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY No	CONDITION:	, , 6	TREND:	Declining
SITE NAME: London Wall: section of Roman and Medieval wall at St Alphage garden, incorporating remains of St Alphage DESIGNATION: Scheduled Monument IIST ENTRY NUMBER: 1018886 CONDITION: Generally satisfactory but with significant localised problems INEW ENTRY: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY: No OWNER TYPE: Local authority CONTACT: Elizabeth Whitbourn 07889 80814 SITE NAME: Roman wall in basement of 90 Gracechurch Street ECJ IST ENTRY NUMBER: 1002035 DESIGNATION: Scheduled Monument, CA IIST ENTRY NUMBER: 1002035 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY: No	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
InternationalChurch EC2DESIGNATION:Scheduled MonumentLIST ENTRY NUMBER:1018886cONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:NoOWNER TYPE:Local authorityCONTACT:Elizabeth Whitbourn 07889 80814SITE NAME:Roman wall in basement of 90 Gracechurch Street E-Image: Scheduled Monument, CALIST ENTRY NUMBER:1002035CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?No	OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
CONDITION:Generally satisfactory but with significant localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:NoOWNER TYPE:Local authorityCONTACT:Elizabeth Whitbourn 07889 80814SITE NAME:Roman wall in basement of 90 Gracechurch Street E/1002035DESIGNATION:Scheduled Monument, CALIST ENTRY NUMBER:1002035CONDITION:Generally unsatisfactory with major localised problemsTREND:DecliningPRINCIPAL VULNERABILITY:Deterioration - in need of managementNEW ENTRY?:No	SITE NAME:		at St Alphage garde	en, incorporating remains of St Alphage's
PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No OWNER TYPE: Local authority CONTACT: Elizabeth Whitbourn 07889 80814. SITE NAME: Roman wall in basement of 90 Gracechurch Street ECJ IO02035 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002035 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining	DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1018886
OWNER TYPE: Local authority CONTACT: Elizabeth Whitbourn 07889 80814. SITE NAME: Roman wall in basement of 90 Gracechurch Street EC3 IO02035 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002035 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	CONDITION:		TREND:	Declining
SITE NAME: Roman wall in basement of 90 Gracechurch Street EC3 DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002035 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
DESIGNATION: Scheduled Monument, CA LIST ENTRY NUMBER: 1002035 CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
CONDITION: Generally unsatisfactory with major localised problems TREND: Declining PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	SITE NAME:	Roman wall in basement of 90 Gracechurch Street	EC3	
PRINCIPAL VULNERABILITY: Deterioration - in need of management NEW ENTRY?: No	DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002035
	CONDITION:		TREND:	Declining
OWNER TYPE: Local authority CONTACT: Elizabeth Whitbourn 07889 80814	PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
	OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145

CROYDON



	SITE NAME:	Former Kennedys Butchers.	Built in 1926 for Kennedys, a chain of South London		
	LIST ENTRY NUMBER:	1031615	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051		
CONDITION: OCCUPANCY: PRIORITY CATEGOR OWNER TYPE:	OWNER TYPE:	Educational (independent)			
	PRIORITY CATEGORY:	C (C)			
	OCCUPANCY:	N/A	appropriate repairs.		
	CONDITION:	Poor	located in Geoffrey Harris House. Discussions with the Local Authority are ongoing and advice is being sought on		
	DESIGNATION:	Listed Building grade II	brickwork and deteriorating pointing. The ice house is under new ownership in the grounds of The Cedars schoo		
SITE	SITE NAME:	lce house, Geoffrey Harris House, Coombe Road	C18 ice house to Coombe House, now Geoffrey Harris House. Disused and partly overgrown, with some loose		

© English Heritage



		62051
SITE NAME:	Former Kennedys Butchers, 18a, High Street, South Norwood SE25	Built in 1926 for Kennedys, a chain of South London butchers, now closed. It is hoped the ground floor shop can be brought back into use. Conversion of the upper
DESIGNATION:	Listed Building grade II, CA	floors was proposed in 2011-2012, however this work does not appear to have been carried out. Unauthorised
CONDITION:	Poor	works to the building's front elevation are being pursued by the Council's Enforcement Team.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1392596	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051

© London Borough of Croydon

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Lesley Arms public house, 62, Lower Addiscombe Road, Addiscombe	Public house circa 1900 in Arts and Crafts style. The building has been vacant for many years and its condition is deteriorating, in particular that of the interiors. The upper
	DESIGNATION:	Listed Building grade II	floors have now been converted to flats. Discussions with the Local Authority on the future use of the ground floor
	CONDITION:	Poor	took place in 2012 but no progress has been made.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
London Borough of Croydon	LIST ENTRY NUMBER:	1272418	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
	SITE NAME:	Segas Offices, 32, Park Lane, Croydon	Gas company showroom and office, built 1939-41 in Moderne style. The building is in sound condition but
	DESIGNATION:	Listed Building grade II, CA	vacant. The Mid Croydon Masterplan and Opportunity Area Planning Framework emphasises the need for a new
	CONDITION:	Fair	use to be found for the building. Discussions are ongoing with the property owner regarding possible new uses.
	OCCUPANCY:	Vacant/not in use	with the property owner regarding possible new uses.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
London Borough of Croydon	LIST ENTRY NUMBER:	1262041	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
	SITE NAME:	Former lodge to Croydon Airport Terminal, Purley Way, Croydon	Single storey lodge to Airport House, built c1928. The building has fallen into a state of disrepair through a lac maintenance and possibly vandalism. There are damag windows and masonry, and overgrown vegetation. Par used for storage and part by the Croydon Airport Soc Discussions with the Local Authority are ongoing and advice is being sought on appropriate repairs, which ar
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	due to be carried out in 2014.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
London Borough of Croydon	LIST ENTRY NUMBER:	1079299	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
	SITE NAME:	Surrey Street Pumping Station, Surrey Street, Croydon	Pumping station, built in four phases from 1851. Some exterior repairs have been carried out, however, the
	DESIGNATION:	Listed Building grade II, CA	building is vacant. Located within the Old Town Masterpla area, its future use has been identified as key to the
	CONDITION:	Fair	regeneration of Croydon's Old Town. Local people, including the Portas Town Team, have expressed a desire
	OCCUPANCY:	Vacant/not in use	for it to be publicly accessible.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
English Heritage	LIST ENTRY NUMBER:	1079248	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051
-	SITE NAME:	2, Woodside Green, South Norwood SE25	Early C18 timber-framed house with brick gable ends and catslide roof to the rear. The building is unoccupied and in
	DESIGNATION:	Listed Building grade II	very poor condition internally and externally following extensive fire damage in 1991 and subsequent neglect. The
	CONDITION:	Very bad	condition of the building is being monitored by the Local
	OCCUPANCY:	Vacant/not in use	Authority and survey work and renovations are due to begin later in 2014.
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Private	
English Heritage	LIST ENTRY NUMBER:	1079280	Contact: Vincent Lacovara (LPA) 020 8726 6000 ext 62051

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / CROYDON

	SITE NAME:	Church of St Mark, Albert Road, Croydon SE25	Designed by GH Lewis of Linden and Lewis, the nave was built in 1852 and the rest completed by 1890. Slate pitched
	DESIGNATION:	Listed Place of Worship grade II, CA	roofs, Kentish ragstone walling. Stonework repairs were recently completed, grant-aided by English Heritage and the Heritage Lottery Fund. Some associated and temporary
	CONDITION:	Poor	roof repairs have been carried out, but the roofs genera need re-slating.
	PRIORITY CATEGORY:	C (C)	need re-slaung.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1323688	Contact: Tracey Craig 020 7973 3756
lish Heritage			

© Englis



SITE NAME:	Church of St Mark, Church Road, Croydon	Built in 1910, designed by Fellowes-Prynne. The clay tiled south aisle mono-pitched roof and the double-pitched roof
DESIGNATION:	Listed Place of Worship grade II	over the adjacent Memorial Chapel are in poor condition, along with associated flashings and valley gutter linings. This
CONDITION:	Poor	is resulting in rainwater ingress. Stonework and pointing are also in need of attention in places. The church has been
PRIORITY CATEGORY:	D (New entry)	awarded a first round pass from the Heritage Lottery Fund
OWNER TYPE:	Religious organisation	for re-roofing and masonry repairs. The development phase of the project is underway.
LIST ENTRY NUMBER:	1079317	Contact: Tracey Craig 020 7973 3756

© English Heritage

-	SITE NAME:	Church of St Andrew, Southbridge Road, Croydon	Church dating from 1857 by Benjamin Ferrey, aisles added in 1879, chancel rebuilt and Lady Chapel added in 1891
	DESIGNATION:	Listed Place of Worship grade II	designed by HB Walton. The church has recently been reordered. Unusual bellcote feature, which has been
	CONDITION:	Fair	dismantled due to its poor structural condition and needs to be reinstated. Works are still required to the rainwater
	PRIORITY CATEGORY:	C (D)	goods and stonework.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1079305	Contact: Tracey Craig 020 7973 3756

© English Heritage

	SITE NAME:	Church of St Augustine, St Augustine's Avenue, Croydon	Designed by John Oldrid Scott, built in 1884. Reordered in 1989 to provide hall accommodation. Clay tiled roofs, flint
	DESIGNATION:	Listed Place of Worship grade II*	walling. À Heritage Lottery Fund/English Heritage Repair Grant for Places of Worship was awarded in 2012 towards
	CONDITION:	Poor	the first phase of roof repairs to the south transept and south chapel along with associated overhauling of rainwater
	PRIORITY CATEGORY:	D (D)	goods and stone and flint repairs. Works are due to
	OWNER TYPE:	Religious organisation	commence in summer 2014.
	LIST ENTRY NUMBER:	1079301	Contact: Tracey Craig 020 7973 3756
	LIST ENTITY INOTIDER.	1077501	Contact. Tracey Craig 020 /9/3 3/36

© English Heritage



SITE NAME:	Church of St John, Upper Norwood, Sylvan Road, Croydon SE19	Built in 1882, designed by John Loughborough Pearson. The church is located on the crest of a hill on shrinkable clay and has been subject to ongoing differential movement
DESIGNATION:	Listed Place of Worship grade II*, CA	for many years. There has been regular monitoring and ground investigations were carried out in 2013. Substantial cracking is occurring mainly to the south side of the building
CONDITION:	Poor	and internally netting has been erected at high level in the south aisle to collect any fragments of masonry. The church
PRIORITY CATEGORY:	A (New entry)	is seeking ways to raise funds for the repairs.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1079275	Contact: Tracey Craig 020 7973 3756

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 23

HERITAGE AT RISK 2014 / LONDON / CROYDON / EALING

SITE NAME:	Group of four World War II fighter pens at the for	mer airfield of RAF	Kenley
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021242
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Group of seven World War II fighter pens at the fo	ormer airfield of RA	\F Kenley
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1021243
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Surrey Iron Railway embankment, approximately 1	0m south west of	Lion Green Road, Coulsdon
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1021441
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145

EALING

© English Heritage



Late C19, yellow stock brick, two storey building. Urgent Stable Block at Brent Lodge SITE NAME: Park, Church Road, Hanwell works to the slate hipped roof and underpinning were undertaken to control water ingress and stabilise the building. A statement of significance and condition survey were completed in 2010. The Council is exploring options W7 DESIGNATION: Listed Building grade II, CA for future use. CONDITION: Good OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1079410 Contact: Rosemarie Wakelin (LPA) 020 8825 6600

	SITE NAME:	Crossways, 134, Church Road, Hanwell W7	C18 or earlier house. In a very bad condition, vacant and has been deteriorating for some time. Now under new
	DESIGNATION:	Listed Building grade II, CA	ownership and some site clearance has been carried out. Further urgent works are now required, following works
	CONDITION:	Very bad	carried out in 2012. The building is shored up with scaffolding supporting a tin roof. A Repairs Notice has been
	OCCUPANCY:	Vacant/not in use	prepared.
	PRIORITY CATEGORY:	A (A)	
The stand of the stand	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1358740	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

T	SITE NAME:	Hanwell Community Centre, Cuckoo Avenue, Hanwell W7	Administration block of former London District Schools, 1856. The Council carried out major repairs in 2010 and
1 miles	DESIGNATION:	Listed Building grade II, CA	the building is now in good condition. A condition survey is being carried out to inform a planned maintenance
	CONDITION:	Good	programme. Management of the building has reverted to the Local Authority and a long-term business plan is being
	OCCUPANCY:	Part occupied/part in use	formulated.
	PRIORITY CATEGORY:	E (E)	
I'm @ @	OWNER TYPE:	Local authority	
h of Ealing	LIST ENTRY NUMBER:	1358760	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

PRIORITY CATEGORIES

© London Borough

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / EALING

	SITE NAME:	Hanwell Station, main up side building and down side island platform, Station Road, Hanwell W7	Circa 1875-77. Important station canopies and ironwork especially on the central platform. It is the least altered example remaining of the general station rebuilding of the 1870s when the track numbers were quadrupled. The
	DESIGNATION:	Listed Building grade II, CA	timber platform structures have been repaired, however, the buildings remain underused. Drainage issues are causin
	CONDITION:	Fair	localised deterioration to the fabric. Discussions are ongoing to secure step-free access to the station before
	OCCUPANCY:	N/A	2017, when the Crossrail line opens.
and the last	PRIORITY CATEGORY:	C (A)	
© English Heritage	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1358787	Contact: Rosemarie Wakelin (LPA) 020 8825 6600
	SITE NAME:	Norwood Hall, Norwood Green Road, Southall	Built 1801-3 by Sir John Soane for the auctioneer and estate agent John Robins. Extended in the late C19 and
			includes substantial grounds, outbuildings and a walled

	A A A	SHE NAME:	Green Road, Southall	estate agent John Robins. Extended in the late C19 and
n - h	The second second	DESIGNATION:	Listed Building grade II, CA	includes substantial grounds, outbuildings and a walled garden. The building was most recently used as a
	HULLAN	CONDITION:	Fair	horticultural college and is now used as a community centre by the present owner. Works are ongoing.
		OCCUPANCY:	Part occupied/part in use	
		PRIORITY CATEGORY:	F (F)	
		OWNER TYPE:	Private	
	© English Heritage	LIST ENTRY NUMBER:	1079330	Contact: Rosemarie Wakelin (LPA) 020 8825 6600



© London Borough of Ea

Cemetery, South Ealing Road W5 and belfry above, designed by Charles 1861. The buildings have fallen into dis	The two chapels are linked by a porte cochere with clock and belfry above, designed by Charles Jones and built in 1861. The buildings have fallen into disrepair and are now
DESIGNATION: Listed Building grade II considered too dangerous to use. Fund repairs is being sought and a long term	
CONDITION: Very bad explored.	explored.
OCCUPANCY: Vacant/not in use	
PRIORITY CATEGORY: A (C)	
OWNER TYPE: Local authority	
LIST ENTRY NUMBER: 1380227 Contact: Rosemarie Wakelin (LPA) 02	0 8825 6600

	SITE NAME:	Southall Manor House, The Green, Southall	Substantial timber-framed manor house of 1587, with later extensions and alterations. Works are ongoing to upgrade
	DESIGNATION:	Listed Building grade II*	the property internally to a minimum standard to accommodate incoming temporary tenants. There are
	CONDITION:	Fair	ongoing negotiations regarding long-term management and a permanent use.
	OCCUPANCY:	Part occupied/part in use	a permanent use.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1079419	Contact: Elizabeth Whitbourn 07889 808145

HI H AL	SITE NAME:	Twyford Abbey, Twyford Abbey Road NW10	Gothick country house built 1807-9 by William Atkinson. Last used as a nursing home. A planning application was
	DESIGNATION:	Listed Building grade II	made in 2012 for the refurbishment of the listed building and conversion into 25 residential flats, and an additional
	CONDITION:	Very bad	65 residential units to be built on surrounding grounds (metropolitan open land) to pay for the refurbishment.
	OCCUPANCY:	Vacant/not in use	Discussions are ongoing.
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
© English Heritage Archive	LIST ENTRY NUMBER:	1079383	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / EALING

	SITE NAME:	St Bernard's Hospital, Uxbridge Road, Southall	Former mental asylum (1829) by William Alderson; extended in 1854-57. Part of the original complex has been
	DESIGNATION:	Listed Building grade II	restored for continuing healthcare use. Applications for the conversion of the listed wards to private residential use
V/N	CONDITION:	Fair	were approved in 2013. The site is now partially refurbished, but the chapel, ballroom and remaining wards
ME	OCCUPANCY:	Part occupied/part in use	are still vacant and awaiting conversion.
	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Health authority	
Archive	LIST ENTRY NUMBER:	1079364	Contact: Rosemarie Wakelin (LPA) 020 8825 6600

SITE NAME:	Church of St Peter, Mount Park Road W5	Church in free Gothic style by JD Sedding and H Wilson dating from 1889 to 1892. Stock brick with stone dressings.
DESIGNATION:	Listed Place of Worship grade II*, CA	Two west end towers with spirelets. Turrets, the extension of the nave piers, extend up through the nave roof and have connecting arches. Recent repairs to the north side
CONDITION:	Poor	included the reroofing of the north slopes, turrets and tower; repair of the timber shingles to the tower spirelet;
PRIORITY CATEGORY:	F (D)	and stonework repairs. A Heritage Lottery Fund/English
OWNER TYPE:	Religious organisation	Heritage Repair Grant for Places of Worship has been awarded for similar repairs to the south side and works are
LIST ENTRY NUMBER:	1079390	underway.
		Contact: Tracey Craig 020 7973 3756
	DESIGNATION: CONDITION: PRIORITY CATEGORY: OWNER TYPE:	Road W5DESIGNATION:Listed Place of Worship grade II*, CACONDITION:PoorPRIORITY CATEGORY:F (D)OWNER TYPE:Religious organisation

© English Heritage

© English Heritage Ar

SITE NAME:	Hanwell flight of locks and brick boundary wall of S	St Bernard's Hospita	al
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1001963
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Improving
PRINCIPAL VULNERABILITY:	Vandalism	NEW ENTRY?:	No
OWNER TYPE:	Mixed, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Moated site at Down Barns Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1005552
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Stable
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Charity (non-heritage)	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Moated site at Sudbury golf course, Wembley		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001971
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Private	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Windmill Bridge		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002020
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Deterioration - in need of management	NEW ENTRY?:	No
OWNER TYPE:	Government or agency	CONTACT:	Elizabeth Whitbourn 07889 808145

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / EALING / ENFIELD

SITE NAME:	Acton Town Centre, Acton W3		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600
SITE NAME:	Cuckoo Estate, Hanwell W7		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600
SITE NAME:	Ealing Town Centre, Ealing W5		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600
SITE NAME:	Hanwell Village Green, Hanwell W7		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY ?:	No
CONDITION:	Optimal	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600
SITE NAME:	Norwood Green, Southall		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Rosemarie Wakelin (LPA) 020 8825 6600

ENFIELD

© English Heritage	SITE NAME:	Broomfield House, Broomfield Park, Broomfield Lane N13	C16 house with late C18 additions, situated in a public park. The building is severely fire damaged, although
	DESIGNATION:	Listed Building grade II*, RPG grade II	significant parts of the interior are in safe storage. A joint Council-Community bid to the Heritage Lottery Fund in October 2012, to rebuild and reopen Broomfield House as
	CONDITION:	Very bad	a heritage, learning and community centre, was unsuccessful. However, discussions are ongoing with
	OCCUPANCY:	Vacant/not in use	regards to the future use of the building and possible
	PRIORITY CATEGORY:	A (C)	sources of funding. A condition survey has been undertaken.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1078934	Contact: Verena McCaig 020 7973 3718



SITE NAME:	Stable block in Broomfield Park, Broomfield Lane N13	Early C18 stable block to Broomfield House. The building is currently empty, although weathertight and secure. A
DESIGNATION:	Listed Building grade II*, RPG grade II	joint Council-Community bid to the Heritage Lottery Fund in 2012, for the refurbishment of the stable yard and the baroque winter gardens, was unsuccessful. However,
CONDITION:	Poor	discussions are ongoing with regards to the future use of the stable block and possible sources of funding.
OCCUPANCY:	Vacant/not in use	the stable block and possible sources of funding.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1188544	Contact: Verena McCaig 020 7973 3718

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / ENFIELD



© London Borough of Enfield

© Lond

N. N. W. W. W.	SITE NAME:	Nonconformist Chapel, Lavender Hill Cemetery, Cedar Road	1870-1 Gothic Revival cemetery chapel. The chapel is in poor condition and in need of an appropriate use. Holding repairs to the external envelope were undertaken by the
	DESIGNATION:	Listed Building grade II	Council in 2012 and 2013. A decision is needed on the future of the building.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079458	Contact: Christine White (LPA) 020 8379 3865

vay to the	
way to the e ding is	
building is to	
sh condition	
iced. Sers.	



C	London	Borough	ot	Enfield	

© English Heritage

	SITE NAME:	Trent Park	Late C18 landscape park further developed in the early
	DESIGNATION:	Registered Park and Garden grade II, 19 LBs, SM, CA	C20 by Sir Philip Sassoon. The central mansion house, gardens and pleasure grounds have been vacated by Middlesex University and discussions are ongoing with
	CONDITION:	Generally satisfactory but with significant localised problems	regards to a future use. The surrounding parkland is managed by the London Borough of Enfield as a country park. The mansion house's terrace is also at risk.
	VULNERABILITY:	High	
	TREND:	Declining	
	NEW ENTRY?:	No	
	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000484	Contact: Zosia Mellor 020 7973 3473

	SITE NAME:	Trent Park House terrace, Cockfosters Road, Trent Park	Brick and stone terrace reconstructed in the 1920s. The terrace is in very poor condition and needs repair and	
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	repaving. Discussions are ongoing with regards to proposals for the wider site.	
	CONDITION:	Very bad		
	OCCUPANCY:	N/A		
100	PRIORITY CATEGORY:	A (C)		
	OWNER TYPE:	Educational (independent)		
	LIST ENTRY NUMBER:	1078931	Contact: Christine White (LPA) 020 8379 3865	

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В
- solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. D Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

Е

obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / ENFIELD

	SITE NAME:	Truro House and stable block, 176, Green Lanes N13	Early to mid C19 detached villa with C19 stable block. The Local Authority has written to the owners with a suggester schedule of repair works and is awaiting a timetable. A residential scheme was agreed in 2009 and the legal
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	agreement remains to be concluded.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
aller -	OWNER TYPE:	Commercial company	
© London Borough of Enfield	LIST ENTRY NUMBER:	1079521	Contact: Christine White (LPA) 020 8379 3865

*	SITE NAME:	Enfield Electricity Works, 20, Ladysmith Road, Enfield	Former Enfield Electricity Works 1906, architect unknown. The building is partially occupied. Future operational
12.	DESIGNATION:	Listed Building grade II	requirements are under consideration and investigative works proposed to explore options for repair and re-use.
EDDDDD	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (C)	
	OWNER TYPE:	Utility	
prough of Enfield	LIST ENTRY NUMBER:	1389537	Contact: Christine White (LPA) 020 8379 3865

	SITE NAME:	Barn at Whitewebbs Farm, Whitewebbs Road	Simple, timber-framed barn probably dating from later C17. Works to support the structure and protect it from
	DESIGNATION:	Listed Building grade II	the elements were undertaken by the owner in 2012, in response to an Urgent Works Notice served by the
	CONDITION:	Very bad	Council. Consents have been granted for residential conversion.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Commercial company	
D London Borough of Enfield	LIST ENTRY NUMBER:	1079480	Contact: Christine White (LPA) 020 8379 3865

T	SITE NAME:	All Saints Church, Church Street N9	C12 in origin, largely rebuilt C15 and clad in brick in 1772. Restored in 1855 and 1871 by Ewan Christian and in 1889
	DESIGNATION:	Listed Place of Worship grade II*, CA	by W Gilbert Scott. Kentish ragstone Medieval tower, 1772 brick-faced east and north sides, and stone south and west sides. The tower stonework is in very poor condition
	CONDITION:	Very bad	and the area below is fenced off due to the risk of falling stone. The nave and aisle roofs need recovering. The
	PRIORITY CATEGORY:	B (A)	church has been awarded a first-round pass from the
	OWNER TYPE:	Religious organisation	Heritage Lottery Fund for repair works to the tower, and the development phase is nearing completion.
	LIST ENTRY NUMBER:	1079548	Contact: Tracey Craig 020 7973 3756
🛛 Colin Kerr (Architect)			

©

© London Bor

©



© Hook Mason Ar

chitect)			
	SITE NAME:	New Covenant Church (formerly The Charles Lamb Halls), Church Street, Edmonton N9	The Charles Lamb Halls were built in a collegiate Tudor style by local philanthropist Charles Lamb in 1908. The buildings are faced in stone under plain tile roofs and now occupied by the New Covenant Church, Edmonton.
	DESIGNATION:	Listed Place of Worship grade II, CA	Repairs to high level stonework and other external fabric are expected to start in early 2015, grant-aided by the Heritage Lottery Fund.
and the second	CONDITION:	Poor	
States and States and States	PRIORITY CATEGORY:	D (C)	
Architects	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1078914	Contact: Ian Harper 020 7973 3786

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / ENFIELD / GREENWICH

and the second se	SITE NAME:	Grovelands Park N14	Late C18 landscape park and lake by Humphry Repton,
Contraction of the local division of the loc	DESIGNATION:	Registered Park and Garden grade II*, 4 LBs	extended in the mid C19, and laid out as a public park in early C20 by Thomas Mawson. The mansion is now a private hospital. The management is fragmented due to the
	CONDITION:	Generally satisfactory but with minor localised problems	separate ownerships. The London Borough of Enfield h produced a historic environment assessment which set out priorities for repair and restoration of the park and
	VULNERABILITY:	Medium	Conservation Management Plan is underway.
	TREND:	Declining	
	NEW ENTRY ?:	No	
) English Heritage	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1000395	Contact: Zosia Mellor 020 7973 3473

SITE NAME:	Church Street, Edmonton N9		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Christine White (LPA) 020 8379 3865
SITE NAME:	Fore Street, Edmonton N18		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Christine White (LPA) 020 8379 3865

GREENWICH

	SITE NAME:	Winter Garden of former Avery Hill Training College, Bexley Road, Eltham SE9	Large conservatory with domed glass roofs, surmounted by a figure of Mercury. Built in 1889 in a classical style. Previously suffering from long-term neglect and major
	DESIGNATION:	Listed Building grade II	deterioration of the fabric. Restoration of the East House has been completed. A Stage 2 Heritage Lottery Fund
	CONDITION:	Fair	application is in development for comprehensive repair and alteration, including new heating to reinstate the main
	OCCUPANCY:	N/A	conservatory to a temperate house.
A CAR	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1079082	Contact: Conservation Team (LPA) 020 8921 5355



合わ	SITE NAME:	Lock and swing bridge, Broadwater Estate SE28	The canal was built 1812-14 to bring supplies into the Arsenal. The swing bridge was built circa 1876 to carry
	DESIGNATION:	Listed Building grade II	railway tracks across the canal. Some work was done to the bridge in the early 1980s but since then the lock and
	CONDITION:	Poor	bridge have both lain derelict.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1213695	Contact: Conservation Team (LPA) 020 8921 5355

© English Heritage

© English Heritage



	SITE NAME:	Garden House to north west of Charlton House, Charlton Road, Charlton SE7	Small red brick garden house with undercroft. High pyramidal swept roof. Mid to late C17 and attributed to Inigo Jones. Previously used as a public lavatory, now
	DESIGNATION:	Listed Building grade I, CA	vacant. In need of repair, maintenance and beneficial use. Discussions have begun to identify a future use in
	CONDITION:	Poor	conjunction with a new borough wide Heritage Trust.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1291892	Contact: Verena McCaig 020 7973 3718

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBR	eviations
CA LB LPA NP RPG SM UA	Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument Unitary Authority
WHS	World Heritage Site

HERITAGE AT RISK 2014 / LONDON / GREENWICH

Provide the second se	SITE NAME:	Enderby House, 100, Christchurch Way, Greenwich SE10	Early-mid C19 wharf-side building of Samuel Enderby, largest whalers and sealers in Britain and pioneers of Atlantic exploration. Unusual octagonal room giving onto a
	DESIGNATION:	Listed Building grade II	projecting bay, allowing views of approaching vessels. Scheme agreed in principle, subject to a Section 106
	CONDITION:	Poor	agreement, but currently unresolved.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1079026	Contact: Conservation Team (LPA) 020 8921 5355

© English Heritage	SITE NAME:	Old brick wall between gardens in front of Nos. 34 and 36, Court Yard, Eltham SE9	Brick wall with sloped coping of C16 appearance. In poor condition with some structural problems caused by overgrowth of vegetation.
	DESIGNATION:	Listed Building grade II*, SM, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1358957	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	95A, Eltham High Street, Eltham SE9	C17 or earlier stable building with three diagonal chimney shafts. Although the building has been made weathertight,
	DESIGNATION:	Listed Building grade II	it is vulnerable to vandalism and pigeons. Previously in use as a joinery workshop, the most appropriate future use
	CONDITION:	Poor	would be commercial/office use. Currently in residential use and subject to enforcement action.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1219821	Contact: Conservation Team (LPA) 020 8921 5355

	SITE NAME:	Royal Military Academy, Academy Road, Woolwich SE18	Military college built in 1805 to the designs of James Wyatt. Planning Permission has been granted for residential
	DESIGNATION:	Listed Building grade II*, CA	conversion. Works began in spring 2008 and are continuing in phases.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1358936	Contact: Verena McCaig 020 7973 3718



			0
	SITE NAME:	Forecourt railings and gates to Red Barracks, and Gate Lodge, Frances Street, Woolwich SE18	Railings and entrance gateway to the former Red Barracks (1858-60 but now demolished). The gate lodges are in particularly poor condition and in need of major repair and
	DESIGNATION:	Listed Building grade II	identification of a new use.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
-	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1358950	Contact: Conservation Team (LPA) 020 8921 5355

PRIORITY CATEGORIES

© English Heritage

Immediate risk of further rapid deterioration or loss of fabric: no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / GREENWICH

HERITAGE AT RISK 2014 / LONDC	N / GREENWICH		
	SITE NAME:	Garrison Church of St George, Grand Depot Road, Royal Artillery Barracks, Woolwich SE18	Former Italianate church of 1863, a roofless ruin after bomb damage in 1944. Valuable mosaics survive in the apse, including one commemorating members of the Royal Artillery awarded the Victoria Cross. The temporary
	DESIGNATION:	Listed Building grade II	protective scaffolding is due to be removed in 2014 to allow for the erection of a new permanent protective roof
	CONDITION:	Poor	funded by the Heritage Lottery Fund. English Heritage has offered a grant towards the conservation of the mosaics
	OCCUPANCY:	N/A	and preliminary works to protect them began in April
	PRIORITY CATEGORY:	F (F)	2014.
© English Heritage	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1078985	Contact: Conservation Team (LPA) 020 8921 5355
	SITE NAME:	The Rotunda, Greenhill, Woolwich Common SE18	24-side polygon, single storey building designed by John Nash. Concave conoid lead covered roof; first erected in
	DESIGNATION:	Listed Building grade II*, CA	the grounds of Carlton House in 1814 for (premature) celebration of Allied victory in the Napoleonic wars. The
Con Alla and	CONDITION:	Poor	Rotunda housed the reserve collection of 'Firepower' museum but is now vacant. The lead sheet roof covering is
	OCCUPANCY:	Vacant/not in use	failing. Listed Building Consent has been granted for
	PRIORITY CATEGORY:	C (C)	investigative works and some repairs. Discussions are ongoing to identify potential new uses.
A CONTRACTOR	OWNER TYPE:	Government or agency	
© English Heritage	LIST ENTRY NUMBER:	1078987	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	I, Greenwich South Street, Woolwich SE10	End terrace to an early C18 group, three storeys and attic with mansard roof. The upper floors have been
	DESIGNATION:	Listed Building grade II, CA	unoccupied for a number of years and the building fabric, especially the windows, is deteriorating.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
142	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Commercial company	
© Royal Borough of Greenwich	LIST ENTRY NUMBER:	1079000	Contact: Conservation Team (LPA) 020 8921 5355
A	SITE NAME:	Riverside Guard Rooms, Royal Arsenal, Plumstead Road, Woolwich SE18	Royal Arsenal's guardrooms, 1814. The Royal Arsenal site is owned by Berkeley Homes who are progressing repairs. Planning Permission has been granted for the Arsenal
	DESIGNATION:	Listed Building grade II, CA	Masterplan. Shell repairs have been carried out.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
© English Heritage Archive	LIST ENTRY NUMBER:	1078955	Contact: Conservation Team (LPA) 020 8921 5355
	SITE NAME:	Royal Laboratory to Royal Arsenal, Plumstead Road, Woolwich SE18	Royal Arsenal's laboratory, two buildings originally built in 1696, reconstructed in 1802 after fire. Both buildings are within the area covered by the Arsenal Masterplan. A
	DESIGNATION:	Listed Building grade II, CA	scheme for restoration and conversion to residential use is well underway.
	CONDITION:	Fair	· · · · ·
A PORTAL A	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
Cathold Shares	OWNER TYPE:	Commercial company	
© Royal Borough of Greenwich	LIST ENTRY NUMBER:	1211082	Contact: Conservation Team (LPA) 020 8921 5355

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / GREENWICH / HACKNEY

	SITE NAME:	24, Royal Hill SE10	Early C18 small urban house of central chimneystack plan,
DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:	Listed Building grade II, CA	the smallest known example of the 1703 Moxón Plan. The building has been vacant for some years and in poor condition. A scheme for restoration and conversion has
	Poor	condition. A scheme for restoration and conversion has been agreed but not yet implemented.	
	OCCUPANCY:	Vacant/not in use	been agreed but not yet implemented.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1391248	Contact: Conservation Team (LPA) 020 8921 5355

© English Heritage Archive	SITE NAME:	Officers' Quarters, Royal Arsenal (building 11), Seymour Street, Woolwich SE18	Officers' block for Royal Military Academy 1717-20. The Royal Arsenal site is owned by Berkeley Homes who are progressing repairs. A masterplan for the whole site has
	DESIGNATION:	Listed Building grade II, CA	been approved by the Local Authority. The building is protected by sheeted scaffold and a temporary roof, bu there is much timber decay to the interior. Proposals a awaited from the developers.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1289024	Contact: Conservation Team (LPA) 020 8921 5355

	1E A

Ô

	SITE NAME:	Cleeve Workshops, Calvert Avenue E2	Row of workshops, built 1895-8 to the design of Reginald Minton Taylor of the London County Council as part of the
	DESIGNATION:	Listed Building grade II	Boundary Éstate. Some are in use but all require repair. The owners have had pre-application discussions with the
	CONDITION:	Poor	Local Authority.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
D English Heritage	LIST ENTRY NUMBER:	1264906	Contact: Peter Ashby (LPA) 020 8356 6408

	SITE NAME:	7, Clapton Square E5	Early C19 terraced house. The Local Authority has taken
	DESIGNATION:	Listed Building grade II, CA	enforcement action against unauthorised works. The property remains in a poor state of repair.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226411	Contact: Peter Ashby (LPA) 020 8356 6408
link I Invitenza Auchiva			

© English Heritage Archive

	SITE NAME:	55 and 59, Clapton Terrace E5	Terraced houses, mid to late C18. Suffering from disrepair
	DESIGNATION:	Listed Building grade II, CA	and under use.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226416	Contact: Peter Ashby (LPA) 020 8356 6408

© English Heritage Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Marlow House, 160, Dalston Lane E8	Early-mid C18 house. Listed Building Consent was granted for conversion to residential use in 2011. Works are yet to
	DESIGNATION:	Listed Building grade II, CA	commence.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© English Heritage Archive	LIST ENTRY NUMBER:	1226591	Contact: Peter Ashby (LPA) 020 8356 6408

© English Heritage Archive	SITE NAME:	St Columba's Vicarage and link to church, Kingsland Road E2	Gothic Revival vicarage built 1873-4 to the design of James Brooks. The lantern joinery and leadwork were repaired in 2011 and localised reslating carried out. Further repair
	DESIGNATION:	Listed Building grade I, CA	2011 and localised restating carried out. Further repair works are still required.
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1265658	Contact: Rebecca Barrett 020 7973 3716

	SITE NAME:	320, Kingsland Road E8	Early C19 terraced house suffering from under use and lack
	DESIGNATION:	Listed Building grade II, CA	of maintenance. An enforcement notice has been served (May 2013).
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
1.	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1226848	Contact: Peter Ashby (LPA) 020 8356 6408

© London Borough of Hackney

	SITE NAME:	592, Kingsland Road E8	C18 terraced house with a shop on the ground floor. The
	DESIGNATION:	Listed Building grade II, CA	upper floors are disused. Listed Building Consent was granted in 2008 for rebuilding the upper parts of the north
	CONDITION:	Poor	and east wall following structural problems.
	OCCUPANCY:	Part occupied/part in use	
H	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1226776	Contact: Peter Ashby (LPA) 020 8356 6408

© English Heritage Archive

	SITE NAME:	The Griffin, Leonard Street EC2	Public house circa 1889. The building is suffering from a
	DESIGNATION:	Listed Building grade II, CA	lack of maintenance. Listed Building Consent was granted for conversion of the upper floors in 2012. Works have not
	CONDITION:	Poor	yet commenced.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1389397	Contact: Peter Ashby (LPA) 020 8356 6408

© English Heritage

ANY ANY ANY

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.


- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

THE	SITE NAME:	Gas House to west of reservoir, Lordship Road, Stoke Newington N16	Single storey, four bay, stock brick building with moulded brick cornice and parapet. The building no longer has an operational use in connection with the reservoir and is in a
	DESIGNATION:	Listed Building grade II, CA	deteriorating condition. A Heritage Lottery Fund bid is currently being prepared for use of the building as a nature
	CONDITION:	Poor	reserve visitor centre. Listed Building Consent was granted in April 2014 for the conversion and repair works.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Utility	
lish Heritage	LIST ENTRY NUMBER:	1265631	Contact: Peter Ashby (LPA) 020 8356 6408

1	Bishop Wood's Almshouses, Lower Clapton Road E5	Late CI7 almshouses restored in the late CI9. The small chapel and almshouses are all vacant and in a deteriorating	
	Listed Building grade II, CA	condition. Discussions are ongoing between the trust and Local Planning Authority to explore options for repair and	
	CONDITION:	Poor	refurbishment.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (New entry)	
+ \	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1226891	Contact: Peter Ashby (LPA) 020 8356 6408

© English Heritage

© Englis



	SITE NAME:	New Lansdowne Club, 195, Mare Street E8	Substantial detached house, 1715. The front elevation was repaired in 2010. The property was bought by new owners
	DESIGNATION:	Listed Building grade II*, CA	in May 2013. Discussions are underway between the Council and the owner to carry out necessary survey work
	CONDITION:	Poor	and to stabilise the building. Detailed proposals and options for future use are under consideration.
© English Heritage Archive	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1265590	Contact: Rebecca Barrett 020 7973 3716
	SITE NAME:	Hackney Borough Disinfecting Station, Millfields Road E5	Disinfecting station, built in 1900. Located within a site used as an animal warden's base and as the Council's
	DESIGNATION	Line d Duildin a sur de U	cleansing depot. Proposals are underway to make the



and the second second	OWNER TYPE:	Commercial company	
ge Archive	LIST ENTRY NUMBER:	1265590	Contact: Rebecca Barrett 020 7973 3716
1.	SITE NAME:	Hackney Borough Disinfecting Station, Millfields Road E5	Disinfecting station, built in 1900. Located within a site used as an animal warden's base and as the Council's
1	DESIGNATION:	Listed Building grade II	cleansing depot. Proposals are underway to make the building watertight pending a feasibility study for new uses.
	CONDITION:	Poor	
STA DATA	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
ow	OWNER TYPE:	Local authority	
ge Archive	LIST ENTRY NUMBER:	1253493	Contact: Peter Ashby (LPA) 020 8356 6408

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Court House and Police Station, Old Street ECI	Former magistrates' court and police station. Listed Building Consent and Planning Permission for conversion
	DESIGNATION:	Listed Building grade II, CA	into hotel use were granted in 2012. Works have commenced on site and the project is due for completion
	CONDITION:	Poor	in late 2014.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1376533	Contact: Peter Ashby (LPA) 020 8356 6408

	SITE NAME:	Air Raid Precaution Centre, Rossendale Street (east side) E5	Air raid shelter built in 1938. The building has suffered from flooding and is in poor condition. It was "adopted" as a
	DESIGNATION:	Listed Building grade II	monument by a local school, Horizon School in Stoke Newington. Planning Permission and Listed Building
	CONDITION:	Poor	Consent were granted in 2004 for the retention of the air raid shelter as a museum and construction of flats above.
	OCCUPANCY:	Vacant/not in use	Works are nearing completion.
PRIORITY CATEGORY:	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
e Archive	LIST ENTRY NUMBER:	1235876	Contact: Peter Ashby (LPA) 020 8356 6408

	SITE NAME:	Walls and gates to Bishopsgate Goods Station, Shoreditch High Street El	Late C19 walls to demolished goods station. The gates were recently repaired and have been re-erected on site. The future use of the structure is currently being discussed
	DESIGNATION:	Listed Building grade II	as part of the wider redevelopment of the Goods Yard.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Utility	
© English Heritage Archive	LIST ENTRY NUMBER:	1235316	Contact: Peter Ashby (LPA) 020 8356 6408

SITE NAME:	187, Shoreditch High Street EI	Early C18 terraced house with altered facade. The building
DESIGNATION:	Listed Building grade II	is vacant and in a deteriorating condition. A temporary metal covering to the roof is providing protection against
CONDITION:	Very bad	water ingress. Listed Building Consent and Planning Permission have been granted for the conversion of the
OCCUPANCY:	Vacant/not in use	ground floor to a retail unit, with residential above. Works
PRIORITY CATEGORY:	B (A)	are expected to commence late 2014.
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1235320	Contact: Peter Ashby (LPA) 020 8356 6408
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION: Listed Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: B (A) OWNER TYPE: Commercial company

© London Borough of Hackney

© English Heritage

	SITE NAME:	196, Shoreditch High Street EI	Early C18 building. Stabilisation and repair works are
	DESIGNATION:	Listed Building grade II	complete and all floors now have existing or prospective occupiers. The owner and the Local Authority have agreed
	CONDITION:	Good	that the temporary wall behind the shopfront should be removed.
FEFFF	OCCUPANCY:	Occupied/in use	removed.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1235410	Contact: Peter Ashby (LPA) 020 8356 6408

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT	RISK 2014 /		HACKNEY
		LONDON	

Phylic 1925-1

©

© English Heritage	SITE NAME:	Walls to St Leonard's Churchyard, Shoreditch High Street and Boundary Street EI	The C19 churchyard walls and stone coped brick piers that occur at intervals along the walls are in poor repair with missing bricks, plant growth, missing or inappropriate
	DESIGNATION:	Listed Building grade II, CA	pointing and damaged stone coping. The railings and gate around the forecourt to St Leonard's Church were repaired in 2010 with grant aid from English Heritage. Propping works have been undertaken and a condition report prepared to inform future repair work. Like-for-li
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (C)	repairs are due to commence in summer 2014.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1235318	Contact: Peter Ashby (LPA) 020 8356 6408

HALL	SITE NAME:	Shrubland Road Evangelical Church, Shrubland Road E8	A rare and complete example of a temporary iron mission church built in 1858. The building is in need of some repair
	DESIGNATION:	Listed Building grade II, CA	and is for sale (spring 2014).
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1245303	Contact: Peter Ashby (LPA) 020 8356 6408



	SITE NAME:	White Lodge, Springfield Park E5	Early/mid C19 villa. There is a café on the ground floor. Listed Building Consent was granted in November 2011 for	
	DESIGNATION:	Listed Building grade II, RPG grade II	the repair and use of the upper floor for community uses. Works are yet to start.	
	CONDITION:	Fair		
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	D (D)		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1235414	Contact: Peter Ashby (LPA) 020 8356 6408	

	SITE NAME:	91, Stoke Newington Church Street N16	Mid C18 house of three storeys with pedimented front. Although at least partially occupied, the building is falling
	DESIGNATION:	Listed Building grade II, CA	into disrepair.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ritage	LIST ENTRY NUMBER:	1265044	Contact: Peter Ashby (LPA) 020 8356 6408

© English Herit



0200	SITE NAME: DESIGNATION:	Abney Park Cemetery N16	Laid out as an arboretum cemetery in 1840 from the gardens of two C17 houses. Abney Park is one of London's most important Nonconformist cemeteries. Features of the historic designed landscape survive but are in poor
STAT N		Registered Park and Garden grade II, 16 LBs, CA	
3	CONDITION:	Extensive significant problems	condition and, in many places, illegible. Two of the monuments and the Mortuary Chapel are also at risk.
	VULNERABILITY: TREND:	High	Discussions are ongoing to agree a future strategy for repairs and improvements.
Ser Ser		Declining	
	NEW ENTRY?:	No	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1000789	Contact: Zosia Mellor 020 7973 3473

PRIORITY CATEGORIES

© English Heritage

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Monument to Joanna Vassa, Stoke Newington High Street, Abney Park Cemetery N16	A four-sided stone pedestal with lotus bud cornice surmounted by an urn commemorating the death of the daughter of black abolitionist, Olaudah Equiano in 1857.
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	Previous repairs have failed and there is widespread erosion. Discussions are ongoing to agree a schedule of repairs and to explore possible sources of funding.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1392851	Contact: Peter Ashby (LPA) 020 8356 6408
	SITE NAME:	Monument to John Swan, Stoke Newington High Street, Abney Park Cemetery N16	A white marble draped urn over pedestal from around 1869. The surface is badly damaged by erosion, dirt and organic growth and the monument is hidden behind
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	overgrown vegetation. The adjacent pedestal, which was leaning against the monument to John Swan, has been moved. Discussions are ongoing to agree a schedule of
	CONDITION:	Poor	repairs and to explore possible sources of funding.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	С (В)	
© English Heritage	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1257265	Contact: Peter Ashby (LPA) 020 8356 6408
*	SITE NAME:	Mortuary Chapel, Stoke Newington High Street, Abney Park Cemetery N16	Gothic Revival cemetery chapel, 1839, now ruinous. The chapel is situated in the centre of the early C19 cemetery and is a feature of views along the main avenues. See entry
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	for Abney Park Cemetery. A condition survey was completed in 2012 and a further structural survey is planned for summer 2014. The chapel is currently fenced
	CONDITION:	Very bad	off and discussions are ongoing to explore future uses and possible sources of funding.
	OCCUPANCY:	Vacant/not in use	P
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1265023	Contact: Peter Ashby (LPA) 020 8356 6408
	SITE NAME:	Premises of Testi and Sons Millwrights, Waterworks Lane E5	Mid C19 Tudor style building, probably originally a school. The building is currently vacant and repairs are required to the roof and stonework. Listed Building Consent has been
	DESIGNATION:	Listed Building grade II, CA	granted for the conversion of the building into two residential units.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
THE PERSON	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Commercial company	
© English Heritage Archive	LIST ENTRY NUMBER:	1264991	Contact: Peter Ashby (LPA) 020 8356 6408
	SITE NAME:	Haggerston Baths, Whiston Road E2	Public baths and swimming pool, 1904. The building is now vacant and in a state of disrepair. The Council is currently
	DESIGNATION:	Listed Building grade II	considering options for future use and funding.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
I TANK	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
		/	

PRIORITY CATEGORIES

- PRIORITY CATEGORIES
 A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Church of St Andrew, Bethune Road, Stoke Newington N16	Church built 1883-4 by Sir Arthur Blomfield in the Early English style. Kentish ragstone with Bath stone dressings.
	DESIGNATION:	Listed Place of Worship grade II*	Although plain externally, the interior is richly decorated. The interior is now deteriorating due to dampness and
	CONDITION:	Poor	water ingress. The church has been awarded a first rour pass from the Heritage Lottery Fund and has started the development phase of the project.
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1264896	Contact: Ian Harper 020 7973 3786

© English Heritage Archive

	SITE NAME:	Church of St Mary of Eton with St Augustine, East Way E9	Late Victorian brick church with stone dressings by Bodley and Garner. A former mission church of Eton College. The
	DESIGNATION:	Listed Place of Worship grade II*	church has suffered damage in the past from water penetration at parapet gutter level. The roof, gutters and
	CONDITION:	Poor	flashings are now under repair as part of a programme du to complete in late 2014.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1226605	Contact: Ian Harper 020 7973 3786

© English Heritage

	SITE NAME:	Church of St John of Jerusalem, Lauriston Road E9	Church by EC Hakewill of 1845-8 in the Early English style. Cruciform with west tower in Kentish ragstone with
	DESIGNATION:	Listed Place of Worship grade II*, CA	limestone dressings and slate roofs. Repair works to the roofs and high level stonework, grant-aided by English Heritage and the Heritage Lottery Fund, are now complete. However, there is still more stonework to be repaired.
	CONDITION:	Fair	
	PRIORITY CATEGORY:	C (F)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1226409	Contact: Ian Harper 020 7973 3786
© English Heritage			

5 5	SITE NAME:	Old Church of St Mary Stoke	The old parish church of Stoke Newington dates from
		Old Church of St Mary, Stoke Newington Church Street, Stoke Newington N16	1563. The church was restored in 1827-29 by Charles Barry who raised new roofs on a clerestory and added the
	DESIGNATION:	Listed Place of Worship grade II*, CA	spire and an outer north aisle, which was not rebuilt after World War II damage. Consequently the soft red bricks, now exposed to the weather on the north side, are
	CONDITION:	Poor	deteriorating badly. Much of the external fabric needs repairs, including the tower, cracked renders and open joints to copings. The churchyard is heavily overgrown,
IT	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	with the monuments suffering accordingly.
© English Heritage	LIST ENTRY NUMBER:	1235419	Contact: Ian Harper 020 7973 3786
© English Heritage	LIST ENTRY NUMBER:	1235419	Contact: Ian Harper 020 7973 3786



SITE NAME:	Church of St Leonard, Shoreditch High Street EI	Church built between 1736 and 1740 to the design of George Dance the Elder. Built in brick with a Portland
DESIGNATION:	Listed Place of Worship grade I, CA	stone front facade and dressings, and slate roofs. The flat roofs either side of the tower have been repaired and the church received a joint Heritage Lottery Fund/English
CONDITION:	Poor	Heritage Repair Grant for Places of Worship for repairs to the nave and north and south aisle roofs. These external
PRIORITY CATEGORY:	C (F)	repairs are now also complete, but further works are
OWNER TYPE:	Religious organisation	required internally.
LIST ENTRY NUMBER:	1235382	Contact: Tracey Craig 020 7973 3756

© English Heritage Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / HACKNEY / HAMMERSMITH AND FULHAM



SITE NAME:	Church of St Matthias, Wordsworth Road, Stoke Newington N16	Completed in 1851 to an innovative design by William Butterfield in free Gothic style. Stock brick with Bath stone dressings. A Heritage Lottery Fund/English Heritage grant
DESIGNATION:	Listed Place of Worship grade I	was offered in December 2012 for the repair of the nave roof and rainwater goods, and repairs are due to start in
CONDITION:	Poor	2014.
PRIORITY CATEGORY:	D (F)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1265031	Contact: Ian Harper 020 7973 3786

© English Heritage

SITE NAME:	Dalston Lane (West), Dalston E8		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Rodney Keg (LPA) 020 8356 7739
SITE NAME:	Mare Street, Hackney Central E8		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY ?:	Yes
CONDITION:	Fair	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rodney Keg (LPA) 020 8356 7739
SITE NAME:	Sun Street, City of London EC2		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Rodney Keg (LPA) 020 8356 7739

HAMMERSMITH AND FULHAM



	SITE NAME:	34, Black Lion Lane, St Peter's Square W6	Cottage, early/mid C19. Stuccoed and painted brick. Listed Building Consent for restoration was approved, and	
	DESIGNATION:	Listed Building grade II, CA	the Local Planning Authority has been proactive in seeking implementation. Works are at an advanced stage.	
	CONDITION:	Fair	· · · · · · · · · · · · · · · · · · ·	
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Private		
h and	LIST ENTRY NUMBER:	1287039	Contact: Adam O'Neill (LPA) 020 8753 3318	

© London Borough of Hammersmith and Fulham



© English Heritage

SITE NAME:	Mortuary Chapel of Conde De Bayona Marques De Misa, Harrow Road, St Mary's Roman Catholic Cemetery NW10	Late C19 Gothic mausoleum with tiled forecourt, railings and gate. The mausoleum is in a deteriorating condition, with broken stained glass, loss of gutters and roof tiles, and corrosion of ironwork with missing finials. There is also
DESIGNATION:	Listed Building grade II, CA	evidence of anti-social activity. Discussions have begun to identify possible funding sources for repair works.
CONDITION:	Very bad	
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1358575	Contact: Adam O'Neill (LPA) 020 8753 3318

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park
- CA LB LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM

- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / HAMMERSMITH AND FULHAM



1 Aller	SITE NAME:	Vault of Campbell Family, Harrow Road, St Mary's Roman Catholic Cemetery NW10	Mausoleum by CHB Quennell in Byzantine style, erected in 1904. There is severe damage to the brickwork bands and internal marble cladding, and vegetation is growing through
	DESIGNATION:	Listed Building grade II, CA	the roof. There is also evidence of anti-social activity. Discussions have begun to identify possible funding sources
	CONDITION:	Very bad	for repair works.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1079822	Contact: Adam O'Neill (LPA) 020 8753 3318

© English Heritage



	SITE NAME:	Hope and Anchor Public House, Macbeth Street, Hammersmith W6	Public house in neo-Georgian style dating from 1936. Built for Truman's as part of a housing estate. The building is an unusual survival with two exceptionally intact 1930s bar
	DESIGNATION:	Listed Building grade II, CA	interiors. The public house business closed in 2012. There is no identified future use for the bar area. The upper floors
	CONDITION:	Fair	are currently occupied and in residential use. Discussions with the new owner are ongoing.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Private	
nith and	LIST ENTRY NUMBER:	1392791	Contact: Adam O'Neill (LPA) 020 8753 3318



© London Borough of Hamm

Fulham

© London Borough of Hammersmi Fulham

mersmith and	SITE NAME:	Tomb of Frederick Harold Young, Margravine Road, Hammersmith Cemetery W6	Mausoleum dating from 1884. Missing coping stone to the west elevation and some broken or missing glass. Lead flashing was stolen in 2012. The interior has not been	
	DESIGNATION:	Listed Building grade II, CA	inspected. Discussions are ongoing to identify funding for repair works.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1072617	Contact: Adam O'Neill (LPA) 020 8753 3318	

Table tomb over brick and stone plinth dating from the end SITE NAME: Tomb of Samuel Jones, Queen Caroline Street, St Paul's of the C18. There is evidence of severe mechanical damage Churchyard W6 and erosion and rusting of the remaining railings. There is also invasive vegetation, which the church was asked to DESIGNATION: Listed Building grade II, CA remove in 2014. A planning application was submitted to relocate the tomb within the churchyard in connection CONDITION: Very bad with its restoration. The tomb is currently behind a protective hoarding. OCCUPANCY: N/A PRIORITY CATEGORY: C (D) OWNER TYPE: Religious organisation © English Heritage LIST ENTRY NUMBER: 1246022 Contact: Adam O'Neill (LPA) 020 8753 3318



Luton	SITE NAME:	Ashlar Court, Former Royal Masonic Hospital Nurses' Home, Ravenscourt Gardens W6	Nurses' home, 1938 by Burnet, Tait and Lorne. The building has been vacant since the cessation of an unauthorised budget hotel use in 2009. Planning Permission and Listed Building Consent have been granted for
	DESIGNATION:	Listed Building grade II, CA	conversion to residential use. Works are at an advanced stage towards completion.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
© London Borough of Hammersmith and Fulham	OWNER TYPE:	Private	
i uniani	LIST ENTRY NUMBER:	1269052	Contact: Adam O'Neill (LPA) 020 8753 3318

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA LB

- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / HAMMERSMITH AND FULHAM / HARINGEY



	SITE NAME:	Former Royal Masonic Hospital, Ravenscourt Park, Hammersmith W6	Hospital, 1933 by Thomas Tait, funded by the Freemasons. The building has been vacant since the closure of the NHS facility in 2006. Listed Building Consent was granted in
	DESIGNATION:	Listed Building grade II*, CA	2008 for refurbishment in connection with a cancer treatment hospital proposal. Some works, including the
	CONDITION:	Fair	dismantling of the garden walls and sundial, have been undertaken, but conversion work has stalled. Parapet
	OCCUPANCY:	Vacant/not in use	repairs were undertaken in 2011/12.
1000	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
nith and	LIST ENTRY NUMBER:	1192740	Contact: Verena McCaig 020 7973 3718

© London Borough of Hammersmit Fulham



A MARK NO	SITE NAME:	Church of St John, North End Road, Walham Green SW6	Church built in 1827 designed by George Ledwell Taylor. Most roof slopes have artificial slates which are in poor
	DESIGNATION:	Listed Place of Worship grade II, CA	condition. Walling is brick with Bath stone dressings. The tower suffers from rusting buried iron, causing damage to the stone. The tower openings have large perforated stone
	CONDITION:	Poor	panels rather than louvres and there are concerns over their structural stability due to spalling. A Heritage Lottery
	PRIORITY CATEGORY:	D (D)	Fund/English Heritage Repair Grant for Places of Worship
	OWNER TYPE:	Religious organisation	has been awarded for re-covering the aisle roofs and tower repairs. Work is due to start during 2014.
	LIST ENTRY NUMBER:	1079751	Contact: Tracey Craig 020 7973 3756

© English Heritage

SITE NAME:	St Mary's, Kensal Green NW10		
DESIGNATION:	Conservation Area, 10 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Adam O'Neill (LPA) 020 8753 3318

HARINGEY

©

	SITE NAME:	Alexandra Palace, Alexandra Palace Way, Wood Green N10	Entertainment complex including exhibition hall, music hall and theatre, built 1868-73. First ever television centre,
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	1935. Urgent repairs to the loggia on the south terrace and south east roofs were completed in 2013, part funded by English Heritage. The Alexandra Palace and Park Trust is
All Annes	CONDITION: OCCUPANCY:	Poor	preparing a Stage 2 Heritage Lottery Fund application for the restoration of the eastern wing for community use.
		Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (heritage)	
D English Heritage	LIST ENTRY NUMBER:	1268256	Contact: Nairita Chakraborty (LPA) 020 8489 2841



	SITE NAME:	Hornsey Town Hall, Broadway N8	Built in 1935 to the design of RH Uren. Modelled on Dudock's seminal town hall at Hilversum and an important
	DESIGNATION:	Listed Building grade II*, CA	influence in subsequent British town hall design. Well preserved interior. Proposals for the repair and conversion
	CONDITION:	Poor	of the building to provide a theatre and drama school, as well as enabling development to the rear of the site, are
	OCCUPANCY:	Vacant/not in use	under consideration. A Stage I Heritage Lottery Fund grant
	PRIORITY CATEGORY:	D (D)	has been approved and the Stage 2 application is expected in Autumn 2014. Temporary uses are being explored in the
	OWNER TYPE:	Local authority	interim.
	LIST ENTRY NUMBER:	1263688	Contact: Rebecca Barrett 020 7973 3716

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Public toilets, Bruce Grove, Tottenham N17	Public toilet circa 1920, with fine external ironwork. Empty and deteriorating. The ironwork has been restored as part
ATAN	DESIGNATION:	Listed Building grade II, CA	of a partnership scheme between the Local Authority and English Heritage and a feasibility study has been
	CONDITION:	Poor	undertaken. Discussions regarding future use are ongoin
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
prough of Haringey	LIST ENTRY NUMBER:	1259316	Contact: Nairita Chakraborty (LPA) 020 8489 2841



© London Borough of Haringey

© London Bor

	SITE NAME:	7, Bruce Grove, Tottenham N17	One of a pair of early C19 houses. The building is vacant and has suffered substantial internal collapse. A scheme of
	DESIGNATION:	Listed Building grade II, CA	refurbishment and conversion to flats has been approved, but not yet implemented. The Local Authority is also
	CONDITION:	Very bad	considering statutory action to ensure that essential repr works are carried out.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	B (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1 188605	Contact: Nairita Chakraborty (LPA) 020 8489 2841

© London Borough of Haringey

	LIST ENTRY NUMBER:	1188605	Contact: Nairita Chakraborty (LPA) 020 8489 2841
	SITE NAME:	South boundary wall to Bruce Castle Park, Lordship Lane, Tottenham N17	Probably early C17 tall red brick wall in Flemish bond. Tall sloped coping and plinth. Wall ramped gently up at intervals towards the west. Now seriously deteriorating
	DESIGNATION:	Listed Building grade II, CA	with open decayed pointing, loose and unstable brickwork, previous re-pointing damage, and extensive ivy/creeper
	CONDITION:	Poor	and frost damage. À programme of urgent repairs has been undertaken, but further repairs are required.
	OCCUPANCY:	N/A	undertaken, but further repairs are required.
-	PRIORITY CATEGORY:	A (A)	
1	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079218	Contact: Nairita Chakraborty (LPA) 020 8489 2841



© London Borough of Haringey



SITE NAME:	Drinking fountain and cattle trough, High Road, Wood	Cattle trough and drinking fountain, 1901. Elaborate Roman baroque style stone fountain head. Grey granite
LIST ENTRY NUMBER:	1294666	Contact: Nairita Chakraborty (LPA) 020 8489 2841
OWNER TYPE:	Local authority	
PRIORITY CATEGORY:	C (B)	
OCCUPANCY:	N/A	
CONDITION:	Poor	
DESIGNATION:	Listed Building grade II, CA	deteriorating. An initial programme of repairs has been undertaken, but further works are needed.
SITE NAME:	West wall, Bruce Castle Park, Church Lane, Tottenham N17	C17 red brick boundary wall to Bruce Castle Park. In urgent need of essential repairs as the brickwork is

nite T Green N22 trough. Some repair works have been carried out, but further works are still required. DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1249717 Contact: Nairita Chakraborty (LPA) 020 8489 2841

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

©

	SITE NAME:	662, High Road, Tottenham N17	Early C18 building of three storeys, in stock brick with stone coped parapet, lower than the neighbouring
• H	DESIGNATION:	Listed Building grade II, CA	properties with which it has group value. Badly fire damaged during the 2011 riots. Owners are seeking to
	CONDITION:	Very bad	restore the building with office use at ground floor level and residential above. Listed Building Consent has been
	OCCUPANCY:	Vacant/not in use	granted for repair and refurbishment, including a mansard
	PRIORITY CATEGORY:	B (B)	extension at roof level. Works are yet to commence.
Mar Maria	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1358832	Contact: Nairita Chakraborty (LPA) 020 8489 2841

	SITE NAME:	Warmington House, 744, High Road, Tottenham N17	Early C19 house last used as offices. Partly in use for storage. The building is to be restored as part of the
	DESIGNATION:	Listed Building grade II, CA	proposed Tottenham Hotspur Football Club stadium redevelopment proposal.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© London Borough of Haringey	LIST ENTRY NUMBER:	1358833	Contact: Nairita Chakraborty (LPA) 020 8489 2841

.1	SITE NAME:	Percy House, 796, High Road, Tottenham N17	Mid C18 house with late C17 forecourt walls and railings. The Council has been liaising with Tottenham Hotspur
	DESIGNATION:	Listed Building grade II*, CA	Football Club to secure the repair and reuse of Percy House for education use as part of the stadium
	CONDITION:	Fair	redevelopment proposals.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
and the second design of the s	OWNER TYPE:	Commercial company	
© London Borough of Haringey	LIST ENTRY NUMBER:	1079242	Contact: Rebecca Barrett 020 7973 3716

	SITE NAME:	810, High Road, Tottenham N17	Fine house built circa 1715 as part of a symmetrical pair. Externally restored by a building preservation trust. The
	DESIGNATION:	Listed Building grade II*, CA	trust has secured agreement to undertake the internal refurbishment and reuse of the building as part of
	CONDITION:	Fair	Tottenham Hotspur Football Club's redevelopment proposals.
in	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
Dondon Borough of Haringey	LIST ENTRY NUMBER:	1358835	Contact: Rebecca Barrett 020 7973 3716



© London Borough of Haringey	LIST ENTRY NUMBER:	1358835	Contact: Rebecca Barrett 020 7973 3716
	SITE NAME:	Retaining wall along Highgate Hill (The Bank), Highgate Hill, Highgate N6	Retaining wall along Highgate Hill between the street pavement and higher paved walk. Early C19 wall in need of repair. Some repairs were carried out in 2010/11 and a
	DESIGNATION:	Listed Building grade II, CA	wider scheme of repair has been agreed for 2014/15. Works are yet to commence.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
	Local authority		
© London Borough of Haringey	LIST ENTRY NUMBER:	1079237	Contact: Nairita Chakraborty (LPA) 020 8489 2841

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

44



	SITE NAME:	62, Monument Way, Tottenham N17	Late C18 three storey detached house, also known as 62 High Cross Road. Seriously affected by water penetration
	DESIGNATION:	Listed Building grade II	into the structure and interior. Consent for conversion into flats was granted in August 2012; scheme awaiting
	CONDITION:	Poor	implementation.
• •	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© London Borough of Haringey	LIST ENTRY NUMBER:	1079226	Contact: Nairita Chakraborty (LPA) 020 8489 2841



© London Borough of Haringey

	SITE NAME:	Porters and Walters Almshouses, St Leonard's Almshouses, Nightingale Road, Wood Green N22	Circa 1904. Four two storey almshouses which form a group with a commemorative stone and front railings. The buildings have suffered from lack of proper maintenance over a number of years and are in a slow state of decay.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
-	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Trust	
	LIST ENTRY NUMBER:	1079222	Contact: Nairita Chakraborty (LPA) 020 8489 2841

	SITE NAME:	Church of St Augustine, Archway Road, Hornsey N6	The Art-Workers-Guild background of the three architects involved in this late C19 church is very apparent. JF Sedding
	DESIGNATION:	Listed Place of Worship grade II, CA	died when the austere Gothic nave was half completed from the east; he was succeeded by his pupil Henry Wilson (west nave and lady chapel) and J Harold Gibbons, who in
	CONDITION:	Poor	1916 completed the Arts and Crafts facade. The church is in ragstone, with Bath stone dressings under a plain tiled roof. It has high quality interior fittings. The roof tiling is
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	original and now failing.
	LIST ENTRY NUMBER:	1358860	Contact: Ian Harper 020 7973 3786
© English Heritage			

and the second	SITE NAME:	Parish Church of All Hallows, Church Lane, Tottenham N17	This is a Medieval church which incorporates a C14 tower with C18 battlements. The north aisle was rebuilt in 1855.
	DESIGNATION:	Listed Place of Worship grade II*, CA	The chancel and east end extensions, raised clerestories and other internal alterations were by William Butterfield in 1875-7. Although altered, the C14 and C15 fabric survives
	CONDITION:	Poor	internally. The poor of the parvis is in poor condition, as well as the valley gutters and wall plates of the roof in places. Internally there is localised decay to the stonework particularly at the west end. There are important monumental tombs in the churchyard, also in poor
	PRIORITY CATEGORY:	C (New entry)	
The second	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1188633	condition.
© English Heritage			Contact: Ian Harper 020 7973 3786
	SITE NAME:	The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17	The former Tottenham Palace was built in 1908 by Wylsor Long as a variety theatre. The building is currently occupied by a church group and is suffering from water ingress,
	DESIGNATION:	Listed Place of Worship grade II,	which is causing significant damage to both the structure and interior plaster work. Repair works have commenced

Settementer -
Ta aga of
And I ARREST TO A DECIDENT OF TAXABLE PARTY.

	LIST ENTRY NUMBER:	1188633	condition.
			Contact: Ian Harper 020 7973 3786
	SITE NAME:	The Palace Cathedral (former Tottenham Palace Theatre), High Road, Tottenham N17	The former Tottenham Palace was built in Long as a variety theatre. The building is cu by a church group and is suffering from wat
	DESIGNATION:	Listed Place of Worship grade II, CA	which is causing significant damage to both and interior plaster work. Repair works hav and are due for completion in 2015.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1249660	Contact: Ian Harper 020 7973 3786

© London Borough of Haringey

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / HARINGEY / HARROW

	SITE NAME:	Greek Orthodox Church of St John the Baptist (formerly St Peter), Wightman Road, Hornsey N8	The church was completed in 1898, designed by Brooks and Son, with later additions. The church has problems with roofing, high level masonry, rainwater goods and glazing. A Heritage Lottery Fund/English Heritage Repair
	DESIGNATION:	Listed Place of Worship grade II*	Grant for Places of Worship was offered in December 2012 and repairs are due to start in summer 2014.
	CONDITION:	Poor	
ATRA-	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1189472	Contact: Ian Harper 020 7973 3786

SITE NAME:	Bruce Grove N17		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	Clyde Circus N15		
DESIGNATION:	Conservation Area	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	Noel Park N22		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	North Tottenham High Road N17		
DESIGNATION:	Conservation Area, 30 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841
SITE NAME:	Scotland Green N17		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Nairita Chakraborty (LPA) 020 8489 2841

HARROW



	SITE NAME:	Brick Kiln to south east of The Kiln, Common Road, Stanmore	Lower part of a C18 bric upper part no longer exis
	DESIGNATION:	Listed Building grade II	stabilisation and repair.
(CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079710	Contact: Lucy Haile (LPA

ck kiln conical chimney of which the ists. In urgent need of structural

A) 020 8736 6101

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / HARROW

	SITE NAME:	Pinner Park Farmhouse, George V Avenue, Pinner	The building dates from circa 1750. It is two storeys wi three bays plus hipped wing. The windows to the main
	DESIGNATION:	Listed Building grade II	house are altered. The building appears in good condition externally but the interior requires attention. There has
	CONDITION:	Poor	been damage from water penetration from the central valley gutter and the building is part vacant.
	OCCUPANCY:	Part occupied/part in use	
m	PRIORITY CATEGORY:	C (C)	
7 Stered	OWNER TYPE:	Local authority	
Borough of Harrow	LIST ENTRY NUMBER:	1079715	Contact: Lucy Haile (LPA) 020 8736 6101

The Hermitage, 776, Kenton

Listed Building grade II

Garden wall to Bernays

Gardens, Old Church Lane,

Listed Building grade II, CA

Vacant/not in use

Lane

Good

E (F)

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

Private

1193722

Stanmore

Poor

N/A

D (D)

1079749

Local authority



© London Borough of Harrow

© London B

	SITE NAME:	Commence Forme Down Lloweford	C17 barn with three bays and narrow central bay. The
-	SHE MAPLE	Cannons Farm Barn, Hereford Gardens, Pinner	Council approved the change of use of the building, as well
	DESIGNATION:	Listed Building grade II	as its repair and restoration. Works have been carried out and the building is now in use. However, unauthorised
	CONDITION:	Good	boundary treatments need addressing.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (E)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1079725	Contact: Lucy Haile (LPA) 020 8736 6101

implemented.

Funding is being sought.

The building is a partially timber-framed, rendered, two

storey range of two bays that probably dates to the CI6.

The building is in a state of disrepair with cracks in walls,

holes in ceilings, broken roof tiles and damp problems. A proposal to secure the repair and future upkeep of the

building has been approved with conditions and is being

C19 wall with buttresses. A high number of bricks are

Listed Building Consent and Planning Permission were

granted in April 2013 for the restoration of the wall.

significantly decayed and the wall is in need of repointing.

Contact: Lucy Haile (LPA) 020 8736 6101



© London Borough of Harrow



© London Borough of Harrow



Contact: Lucy Haile (LPA) 020 8736 6101 Manor House dating from CI4 with CI6, CI7 and CI8 SITE NAME: Headstone Manor, Pinner View, fabric, surrounded by a moat. Believed to be the earliest Harrow surviving timber-framed building in Middlesex, and the DESIGNATION: Listed Building grade I, SM oldest complete water-filled moat in Greater London. The Council has secured Stage I funding from the Heritage CONDITION: Poor lans to restore the building, part rovide Harrow's heritage centre A detailed Conservation Plan is ner 2014) and over £1 million of cured for the project. urn 07889 808145

© London Borough of Harrow

		1001	Lottery Fund to develop pla
	OCCUPANCY:	Part occupied/part in use	of a wider masterplan to pr
I	PRIORITY CATEGORY:	C (C)	and community museum. A out for consultation (summ
	OWNER TYPE:	Local authority	council funds have been s
	LIST ENTRY NUMBER:	1285855	Contact: Elizabeth Whitbou

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ŬA
- Unitary Authority World Heritage Site WHS

HERIT

	SITE NAME:	Harrow Magistrates Court, Rosslyn Crescent, Wealdstone	The Jasper Foundation has acquired the building with the intention of carrying out repairs and finding a new use.
	DESIGNATION:	Listed Building grade II	Unauthorised works have been carried out, including the removal of original fixtures and fittings. A listed building
	CONDITION:	Poor	enforcement case is open and a Listed Building Consent
H H RAAAA	OCCUPANCY:	Occupied/in use	application has been received to address the unauthorised works.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (non-heritage)	
Dondon Borough of Harrow	LIST ENTRY NUMBER:	1390755	Contact: Lucy Haile (LPA) 020 8736 6101
	SITE NAME:	Boundary wall fronting road from Nos 118-128, Stanmore Hill (East Side), Stanmore	C18 brick wall with buttresses with chamfered bases. Many bricks at the base have weathered away and parts require repointing. The Local Authority is discussing repairs with
Children and	DESIGNATION:	Listed Building grade II, CA	the owners.
A A H A A	CONDITION:	Poor	
At a second second	OCCUPANCY:	N/A	
and the for	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
) London Borough of Harrow	LIST ENTRY NUMBER:	1194205	Contact: Lucy Haile (LPA) 020 8736 6101
	SITE NAME:	Boundary wall fronting road (Hill House), 173, Stanmore Hill (West Side), Stanmore	This brick wall originates from the C18 or early C19. It is 10 foot high, built of red brick with chamfered pilaster buttresses. Many sections of the wall have weathered away
18 CAN MONTH	DESIGNATION:	Listed Building grade II, CA	and parts require repointing. The owner is aware of the issue.
N. W. W. W.	CONDITION:	Poor	
A MARTINE	OCCUPANCY:	N/A	
Contraction of the	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Other not for profit group	
Dondon Borough of Harrow	LIST ENTRY NUMBER:	1079648	Contact: Lucy Haile (LPA) 020 8736 6101
- TT	SITE NAME:	The Rayners public house, 23, Village Way East	A virtually unaltered 1930s public house retaining its internal plan form and original fittings. The building has
- Aller	DESIGNATION:	Listed Building grade II	been empty since 2006. Listed Building Consent was granted for the repair, renovation and reuse of the building
	CONDITION:	Good	and outline Planning Permission granted for surrounding development that will help to secure funding for its future.
	OCCUPANCY:	Vacant/not in use	The works of repair have largely been implemented though
	PRIORITY CATEGORY:	E (D)	the curtilage listed wall awaits work and a new occupier for the building is being sought.
	OWNER TYPE:	Private	
Dondon Borough of Harrow	LIST ENTRY NUMBER:	1392310	Contact: Lucy Haile (LPA) 020 8736 6101
	SITE NAME:	Old Stanmore Church, Church Road, Stanmore	The roofless ruined church of St John the Evangelist was built in 1632, attributed to Nicholas Stone. The wall heads
			have exposed brickwork allowing rainwater ingress. This is



	SITE NAME:	Old Stanmore Church, Church Road, Stanmore	The roofless ruined church of St John the Evangelist was built in 1632, attributed to Nicholas Stone. The wall heads
	DESIGNATION:	Listed Place of Worship grade II*, CA	have exposed brickwork allowing rainwater ingress. This is resulting in the erosion of mortar and bricks and supporting deleterious plant growth. There is decayed mortar, brick,
	CONDITION:	Poor	stone and timber elsewhere around the building along w some vertical cracking in the walling. The church is still u
	PRIORITY CATEGORY:	C (New entry)	for worship.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1079747	Contact: Tracey Craig 020 7973 3756

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / HARROW

	SITE NAME:	Bentley Priory	A C16 estate enlarged and improved in the late C18. Sir
and the second fill	DESIGNATION:	Registered Park and Garden grade II, LB grade II*	Uvedale Price and William Gilpin influenced the design in the early C19. Royal Air Force Fighter Command occupied the mansion from 1936 and it played a central role during
	CONDITION:	Generally satisfactory but with significant localised problems	World War II. The mansion has been converted to a museum with residential units and additional housing in the grounds. A Conservation Management Plan has been
1 main	VULNERABILITY:	Medium	prepared to guide landscape restoration, including work
	TREND:	Improving	to the Italian Gardens. Natural England is preparing a Parkland Management Plan for land owned and managed
	NEW ENTRY?:	No	by the LPA, with input from the Friends group.
© English Heritage	OWNER TYPE:	Mixed, multiple owners	
	LIST ENTRY NUMBER:	1001440	Contact: Zosia Mellor 020 7973 3473

SITE NAME:	Grim's Ditch: four linear sections between Uxbridg	ge Road and Oxhey	Lane
DESIGNATION:	Scheduled Monument, part in CA	LIST ENTRY NUMBER:	1003530
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Gardening	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: section extending 1500yds (1370m) r	north east from Ox	khey Lane
DESIGNATION:	Scheduled Monument, part in RPG grade II, part in CA	LIST ENTRY NUMBER:	1002044
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grim's Ditch: section north of Blythwood House		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002007
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Linear earthworks in Pear Wood, west of Watling	Street	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001996
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Pinner deer park, Pinner Park Farm		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1019135
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HAVERING

トレビア

C

	SITE NAME:	K6 Telephone Kiosk, outside the Bell Public House, Broadway, Rainham	K6 telephone box from 1935, designed by Sir Giles Gilbert Scott. Situated within the Rainham conservation area, the telephone box has been decommissioned and is slowly
	DESIGNATION:	Listed Building grade II, CA	deteriorating. BT has agreed to re-install the equipment, carry out repairs, and bring it back into use.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1079853	Contact: Heritage Officer (LPA) 01708 432606

	SITE NAME:	Stable block, Rainham Hall, Broadway, Rainham	Stables and coach house dating to C18. Works are underway to restore the stable block to provide a National
	DESIGNATION:	Listed Building grade II*, CA	Trust cafe and community/learning space, grant-aided by the Heritage Lottery Fund. Works are due to be
	CONDITION:	Poor	completed in early 2015.
	OCCUPANCY:	Vacant/not in use	
FIFE	PRIORITY CATEGORY:	F (C)	
	OWNER TYPE:	Charity (heritage)	
D English Heritage	LIST ENTRY NUMBER:	1183554	Contact: Verena McCaig 020 7973 3718

Garden walls to former North Ockendon Hall, Church Lane,

Listed Building grade II, CA

Bridge in Parklands Park,

Listed Building grade II, CA

Corbets Tey Road, Upminster

North Ockendon

Very bad

N/A

C (C)

Private

Poor

N/A

D (D)

1079928

Local authority

1300500



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© London Borough of Havering



© London Borough of Havering



SITE NAME:	Outbuilding to the rear of The Old Anchor, Harwood Hall Lane	C19 timber framed outbuildings which continue the line of the rear wing of The Old Anchor, a C18 timber-framed house. The building is in need of re-roofing and the
DESIGNATION:	Listed Building grade II, CA	brickwork is seriously decayed and in need of repair, along with the renewal of the timber lintels. The Council and
CONDITION:	Poor	English Heritage are now in discussion with the owners regarding options for repair.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1079891	Contact: Heritage Officer (LPA) 01708 432606

summer 2014.

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

C16 and later garden walls to Ockendon Hall (now

Contact: Heritage Officer (LPA) 01708 432606

Contact: Heritage Officer (LPA) 01708 432606

C18 bridge, attributed to James Paine; in the former

the full repair of the bridge and work is due to start in

landscaped park to Gaynes House (demolished), and now a public park. Listed Building Consent has been granted for

demolished). Slowly deteriorating.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site
- 50

HERITAGE AT RISK 2014 / LONDON / HAVERING


J	SITE NAME:	Mill Cottage, The Dell, High Street, Hornchurch	Single storey timber-framed range, C17. Now one dwelling. The building is in poor condition and continuing
A CONTRACT	DESIGNATION:	Listed Building grade II, CA	to deteriorate.
	CONDITION:	Poor	
1. A. I.	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
of Havering	LIST ENTRY NUMBER:	1079898	Contact: Heritage Officer (LPA) 01708 432606

	SITE NAME:	96-102, North Street, Romford	Late C17 timber-framed building consisting of two paralle
	DESIGNATION:	Listed Building grade II	ranges. The building is occupied and considerable repair works have been undertaken. An assessment for further
- 1	CONDITION:	Poor	repairs is now required.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
Line -	OWNER TYPE:	Commercial company	
and the second	LIST ENTRY NUMBER:	1079909	Contact: Heritage Officer (LPA) 01708 432606
Havering			

© London Borough of Havering


© English Heritage

© London Borough o



	SIT
ML 2 H	DE
	СС
	00
	PR

© London Borough of Havering





*	SITE NAME:	Upminster Windmill, St Mary's Lane, Upminster	Smock mill 1803, retaining original machinery. The building preservation trust (Friends of Upminster Windmill), in
	DESIGNATION:	Listed Building grade II*	conjunction with the Local Authority, has been awarded grant from the Heritage Lottery Fund. Works will include the full restoration of the mill, and the provision of a workshop and visitors' centre on the site. Regular public access will be provided.
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1079878	Contact: Verena McCaig 020 7973 3718

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014 / LONDON / HAVERING / HILLINGDON

Alle	SITE NAME:	Garden walls at Cranham Hall, The Chase, Cranham	C16 walls to earlier house on the site of Cranham Hall. In need of extensive repairs.
- ALLAN	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
Aller Frederick	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
of Havering	LIST ENTRY NUMBER:	1183600	Contact: Heritage Officer (LPA) 01708 432606

	SITE NAME:	Footbridge to rear of Nos. 52 and 54, The Grove, Upminster	Footbridge and eye-catcher, circa 1765, probably by Jame Paine who laid out the estate of Gaynes Park in the 1760s
	DESIGNATION:	Listed Building grade II	for Sir James Esdaile, Lord Mayor of London 1777-78. Some structural repairs have been carried out in the past,
	CONDITION:	Fair	and funding for further repair works is being explored.
and the second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (F)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1323729	Contact: Heritage Officer (LPA) 01708 432606

SITE NAME: Dagnam Park Farm moated site, Noak Hill, Romford DESIGNATION: Scheduled Monument LIST ENTRY NUMBER: 1001988 Generally satisfactory but with significant localised CONDITION: TREND: Declining problems PRINCIPAL VULNERABILITY: NEW ENTRY? Vandalism No OWNER TYPE: Local authority CONTACT: Elizabeth Whitbourn 07889 808145 SITE NAME: Romford DESIGNATION: Conservation Area, 4 LBs NEW ENTRY ?: No CONDITION: TREND: Improving Very bad VULNERABILITY: CONTACT: Katie Dickson (LPA) 01708 432606 Low

HILLINGDON

© London Borough

© London Borough of

	SITE NAME:	Barn to the west of Weekly House, Bath Road, Harmondsworth	Late C17 or early C18 weatherboarded barn with tiled roof. Queen post truss at west end. Weekly House, the boundary wall and the barn form a group. The barn is in a
1	DESIGNATION:	Listed Building grade II, CA	dilapidated state.
A MARINE	CONDITION:	Very bad	
E CONTRACTOR	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
sh of Hillingdon	LIST ENTRY NUMBER:	1286544	Contact: Sarah Harper (LPA) 01895 556000



SITE NAME:	Former King Henry public house and stables, 456, Bath Road, Longford	Converted to a house, the rear of the building is the former "King Henry" public house. The front part of the property has been rebuilt, using old material, after a fire. All
DESIGNATION:	Listed Building grade II	the walls have exposed timber framing with brick filling and tiled roofs. The adjacent stables are also of interest with an
CONDITION:	Poor	early diamond mullioned window. The buildings are in poor condition and have been included in large development
OCCUPANCY:	Vacant/not in use	proposals.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1080296	Contact: Sarah Harper (LPA) 01895 556000

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet
- implemented. C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS			
CA	Conservation Area		
LB	Listed Building		
LPA	Local Planning Authority		
NP	National Park		
RPG	Registered Park and Garden		
SM	Scheduled Monument		

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / HILLINGDON

	SITE NAME:	Enterprise House, Blyth Road, Hayes	1912 factory building by the Trussed Concrete Steel Company for HMV. It has an unusual design with a high level water tank and is an important local landmark. The building is partially occupied and in a deteriorating condition.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
© London Borough of Hillingdon	LIST ENTRY NUMBER:	1244861	Contact: Sarah Harper (LPA) 01895 556000

	SITE NAME:	Breakspear House, Breakspear Road North, Harefield	Early to mid C17 manor house in extensive grounds. Inspected on a regular basis and being maintained in a
	DESIGNATION:	Listed Building grade I, CA	secure and relatively weathertight state, but a long-term use is required. Listed Building Consent and Planning Permission have been granted for conversion to residentia use. The external skin and roof have been repaired and internal works are partially complete.
	CONDITION:	Good	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
© English Heritage Archive	LIST ENTRY NUMBER:	1080262	Contact: Elizabeth Whitbourn 07889 808145



© London Borough of Hillingdon

		• (•)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1080262	Contact: Elizabeth Whitbourn 07889 808145	
	SITE NAME: DESIGNATION:	Langley Farm Barn, Breakspear Road North, Harefield, Northwood	C16 barn in private ownership at Langley Farm. The barn is three bay timber-framed and weatherboarded with a tiled roof. It has lost parts of the brick plinth to the north east	
		Listed Building grade II, CA	elevation. The front area adjacent to the barn appears to have been subject to fly tipping. Applications for	
LL I	CONDITION:	Very bad	redevelopment of the adjacent farm buildings were refused.	
TTTT	OCCUPANCY:	N/A		
The second	PRIORITY CATEGORY:	A (A)		
1	OWNER TYPE: Private			
	LIST ENTRY NUMBER:	1080261	Contact: Sarah Harper (LPA) 01895 556000	

DADHIMAN	SITE NAME:	Garden walls to Church Gardens Nursery, Church Hill, Harefield	C17 red brick garden walls in need of extensive repairs, but some works already undertaken to a good standard.
	DESIGNATION:	Listed Building grade II, RPG grade II, CA	
	CONDITION:	Fair	
and the second	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
© English Heritage Archive	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080272	Contact: Sarah Harper (LPA) 01895 556000



	LIST ENTRY NUMBER:	1080272	Contact: Sarah Harper (LPA) 01895 556000
	SITE NAME:	Wall in front of numbers 30 to 36 (even), Church Road, Hillingdon	CI6 red brick wall of varied height, breached in places to create access for houses behind. Some sections have been repaired but of varied quality and much of the remainder is
	DESIGNATION:	Listed Building grade II, CA	in poor condition.
	CONDITION:	Poor	
1.16	OCCUPANCY:	N/A	
100	PRIORITY CATEGORY:	B (B)	
11.0	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080277	Contact: Sarah Harper (LPA) 01895 556000

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / HILLINGDON


	SITE NAME:	Wall in front of numbers 40 to 50 (even), Church Road, Hillingdon	C16 red brick wall of varied height, breached in places to create access for houses behind. Some sections have bee repaired but of varied quality and much of the remainder
Contraction of the	DESIGNATION:	Listed Building grade II, CA	in poor condition.
2120-00	CONDITION:	Poor	
1242	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Private	
1	LIST ENTRY NUMBER:	1358327	Contact: Sarah Harper (LPA) 01895 556000

(even) and along west end of create access for h	create access for houses behind. Some sections have been repaired but of varied quality and much of the remainder is
DESIGNATION: Listed Building grade II, CA	
CONDITION: Poor	
OCCUPANCY: N/A	
PRIORITY CATEGORY: B (B)	
OWNER TYPE: Private	
LIST ENTRY NUMBER: 1286348 Contact: Sarah Hai	rper (LPA) 01895 556000



© English Heritage

© English Heritage



	SITE NAME:	Cinema, RAF Uxbridge, Grays Road, Uxbridge	Designed in 1918, the building has a large auditorium used historically as a lecture hall/cinema or concert hall and was converted to a gymnasium in the 1960s. The building is vacant and in very poor condition. RAF Uxbridge has been sold by the Ministry of Defence to a private sector consortium on a long lease. Developers and the Local Authority are working together to find a suitable new use. Minor repairs were carried out in February 2010.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Commercial company	
don Borough of Hillingdon	LIST ENTRY NUMBER:	1392376	Contact: Sarah Harper (LPA) 01895 556000

© Londo

	SITE NAME:	Dovecote and garden walls to Eastcote House, High Road, Eastcote, Pinner	Square red brick building of C18 appearance with pyramidal tiled roof and central louvred turret. The wall is to the west of the dovecote. Inside the roof structure is visible and part of the wooden potence remains. Holding repairs have been undertaken by the Council. A Stage 2 bid for funding from the Heritage Lottery Fund has been successful for works to repair and reuse all the listed structures on site. Works are expected to start in 2014.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
1	LIST ENTRY NUMBER:	1285861	Contact: Sarah Harper (LPA) 01895 556000

PRIORITY CATEGORIES

© London Borough of Hillingdon

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

© Lond


© London Bord

© London

	SITE NAME:	Former stables to Eastcote House, High Road, Eastcote, Pinner	Early C17 timber-framed building with alterations. Two storeys, three windows blocked. A Conservation Management Plan, jointly funded by the Council and English
	DESIGNATION:	Listed Building grade II, CA	Heritage, was prepared in 2010 and a Stage 2 bid for funding from the Heritage Lottery Fund has been successful
	CONDITION:	Poor	for works to repair and reuse all the listed structures on site. Holding works to the structure have been completed
	OCCUPANCY:	Part occupied/part in use	and the building is in temporary use. Works are expec
	PRIORITY CATEGORY:	D (D)	to start in 2014.
	OWNER TYPE:	Local authority	
don Borough of Hillingdon	LIST ENTRY NUMBER:	1080226	Contact: Sarah Harper (LPA) 01895 556000

	SITE NAME:	Garden walls to east of the Old Coach House, High Road, Pinner	Extensive Cl7 red brick garden walls. Rebuilt in part and lowered to the south and east. Following partial collapse, the walls were repaired by the Council. A Stage 2 Heritage
	DESIGNATION:	Listed Building grade II, CA	Lottery Fund bid for the repair of all of the historic structures on site has been successful; work is expected to
	CONDITION:	Fair	start in 2014.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
rough of Hillingdon	LIST ENTRY NUMBER:	1080227	Contact: Sarah Harper (LPA) 01895 556000

- The	SITE NAME:	Front garden wall, The Beeches, High Street, Cowley	C18 red brick wall with sloped coping, located to the north of the Beeches. Repairs to the house have been completed
	DESIGNATION:	Listed Building grade II	and it has been removed from the Heritage at Risk Register. Repairs to the wall are still outstanding.
ALC: NO	CONDITION:	Poor	
Par and a start of	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
on Borough of Hillingdon	LIST ENTRY NUMBER:	1194165	Contact: Sarah Harper (LPA) 01895 556000



© English Heritage

SITE
DESI
CON
000
PRIO
OW

NAME: The Cedars, 66, High Street, C18 town house with later additions. Three storeys, central doorway with Doric pilasters, entablature and open Uxbridge pediment. Red brick facade, with bands at first and second IGNATION: Listed Building grade II, CA floors, dentil and cyma recta cornice with plain tiled roof. The building has distinctive Dutch gables to the side NDITION: Fair elevation. Development proposals, including the site to the CUPANCY: rear, have been discussed with the Local Authority. Occupied/in use DRITY CATEGORY: C (C) NER TYPE: Charity (non-heritage) LIST ENTRY NUMBER: 1358372 Contact: Sarah Harper (LPA) 01895 556000

© London Borough of Hillingdon

D

Е

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM UÁ
- UA Unitary Authority WHS World Heritage Site

X	SITE NAME:	The Dower House, 393, High Street, Harlington	Two storey house with C18 brick front to older timber- framed structure, with rebuilt large C16 chimney. The
D	DESIGNATION:	Listed Building grade II	house is four windows wide, built of brown brick with red brick quoins and window dressings. The high pitched roof
	CONDITION:	Very bad	is hipped to the right and renewed in machine tile. The building suffered severe fire damage in May 2011. It is wind
	OCCUPANCY:	Vacant/not in use	and weather tight with a temporary roof and a structural
	PRIORITY CATEGORY:	A (A)	survey is being carried out.
	OWNER TYPE:	Private	
ı	LIST ENTRY NUMBER:	1080196	Contact: Sarah Harper (LPA) 01895 556000




© London Borough of Hillingdon

© London Borough of Hillingdon

1111

SITE NAME:	Harefield Park (annexe to Harefield Hospital), Hill End Road, Harefield	The site comprises the main building and two flanking stable buildings of early C18 date. The house is vacant and in very poor condition, with no use identified. The building
DESIGNATION:	Listed Building grade II*, CA	is propped and a temporary roof is in place. Survey work to inform repairs is underway.
CONDITION:	Very bad	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Health authority	
LIST ENTRY NUMBER:	1080177	Contact: Elizabeth Whitbourn 07889 808145





-	SITE NAME:	The stable block, south east of Harefield Park, (annexe to Harefield Hospital), Hill End Road, Harefield	The site comprises one of two stable buildings of early CI8 date. The hospital may close. In the interim, the stable building will continue to be used for clinical storage. A long-term use needs to be identified.
LPLE	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
© London Borough of Hillingdon	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1358396	Contact: Sarah Harper (LPA) 01895 556000



	SITE NAME:	Nurses Home in grounds of Hillingdon Hospital, Pield Heath Road, Hillingdon	Early C19 house in the grounds of Hillingdon Hospital, currently used as offices, but in generally poor condition.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
teresting a	OWNER TYPE:	Health authority	
gh of Hillingdon	LIST ENTRY NUMBER:	1080153	Contact: Sarah Harper (LPA) 01895 556000

PRIORITY CATEGORIES

© London Borough

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

use).

- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

IV.		Manuat Viana an Illana ital	1902 A by El M/boolor in Edwardian Eron Style, Ruilt as a
© Antonio Cruz, Comer Homes Group	LIST ENTRY NUMBER:	8 48	Contact: Sarah Harper (LPA) 01895 556000
	OWNER TYPE:	Private	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	Vacant/not in use)
	CONDITION:	Fair	use with atrium link. It has been vacant for a number of years and is deteriorating.
FE FINA	DESIGNATION:	Listed Building grade II	concealing a fairly low pitched hipped slate roof. The building has a two storey modern courtyard wing for office
	SITE NAME:	Harefield Grove, Rickmansworth Road, Harefield	Probably early C19 country house of three storeys, five windows. Stucco with stone cornice and parapet



	SITE NAME:	Mount Vernon Hospital, Rickmansworth Road, Northwood	1902-4 by FL Wheeler in Edwardian Free Style. Built as a hospital for the treatment of tuberculosis patients, and a branch hospital of the original Mount Vernon hospital in
18:10	DESIGNATION:	Listed Building grade II	Hampstead (built 1879-80). The building is noted for its advanced plan, including isolation wards and facilities such
	CONDITION:	Poor	as an X-ray room and dental unit. It is still in use by the hospital, but in a poor state of repair and under pressure
THE PARTY AND ADDRESS OF	OCCUPANCY:	Occupied/in use	from the redevelopment of the site.
© London Borough of Hillingdon	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1080083	Contact: Sarah Harper (LPA) 01895 556000



© English Heritage

	SITE NAME:	Cellars of former Cranford House, Roseville Road, Cranford	Brick vaulted cellars to Cranford House circa 1722 (demolished). Of archaeological interest, but the potential for use is limited due to the likely very high costs involved.	
	DESIGNATION:	Listed Building grade II, CA	The cellars are suffering from structural weakening and the condition is deteriorating. The Council is working with local	
	CONDITION:	Fair	groups to consider options for the future of the site.	
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Local authority, multiple owners		
	LIST ENTRY NUMBER:	1285115	Contact: Sarah Harper (LPA) 01895 556000	

	SITE NAME:	Cranford House Stables, Roseville Road, Cranford	Stables to Cranford House circa 1720 (demolished). Managed by the London Borough of Hillingdon. The east
	DESIGNATION:	Listed Building grade II, CA	block is in very poor condition and the site is in need of a long-term use. The Council is working with local groups to
AAAA CI	CONDITION:	Very bad	consider options for the future of the site.
	OCCUPANCY:	Vacant/not in use	
- and the second	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
leritage Archive	LIST ENTRY NUMBER:	1080157	Contact: Sarah Harper (LPA) 01895 556000

© English He

	-	
4	9	al al

Orchestrelle Factory of 1909-11. Reinforced concrete SITE NAME: Benlow Works, Silverdale Road, frame, with brick exterior. Four storeys with a 19 bay Hayes ircular stepped DES mental arched asters slightly set CON nt temporary ner, so that the 000 iscussions have PRIC on is agreed for OW LIST 000

© London Borough of Hillingdon

signation:	, Listed Building grade II	elevation. The entrance bay has a semi-cir brick architrave to the doorway and segm
NDITION:	Very bad	metal casements flanked by rusticated pila forward and breaking the parapet. Recent
CCUPANCY:	Part occupied/part in use	repairs have been undertaken by the own
ORITY CATEGORY:	C (C)	building is in a weather tight condition. Dis been held with the owner, but no solutior
VNER TYPE:	Private	future use as yet.
T ENTRY NUMBER:	1080121	Contact: Sarah Harper (LPA) 01895 5560

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
 - Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site



© London Borough of Hillingdon

SITE NAME:	Gatehouse at Hillingdon- Uxbridge Cemetery, Uxbridge Road	Mid C19 gatehouse by Benjamin Ferry, with adjacent stock brick boundary wall. The gatehouse is constructed of rubble with stone dressings, tiled roof, five bays with wide
DESIGNATION:	Listed Building grade II	central entrance under the arch. It is in deteriorating condition and vacant; wall partially collapsed. A condition
CONDITION:	Poor	survey is currently being undertaken.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Local authority	
LIST ENTRY NUMBER:	1358415	Contact: Sarah Harper (LPA) 01895 556000

SITE NAME: Hubbard's Farm Barn and Two barns dating from C16, both now collapsed; historic timbers salvaged for reuse. Applications are under outbuildings, West Drayton consideration for the rebuilding of both structures. Road, Colham Green, Úxbridge DESIGNATION: Listed Building grade II CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private © London Borough of Hillingdon LIST ENTRY NUMBER: 1284866 Contact: Sarah Harper (LPA) 01895 556000

SITE NAME:	Moated site, west bank of River Pinn, near Ickenha	m (1/2 mile (800m)	north west of church)
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002001
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY ?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Manor Farm moat, Ickenham		
DESIGNATION:	Scheduled Monument, CA	LIST ENTRY NUMBER:	1002006
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Scrub/tree growth	NEW ENTRY?:	No
OWNER TYPE:	Educational (state sector)	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Black Jacks Lock and Copper Mill Lock, Harefield		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	Botwell (Nestles), Hayes		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	Botwell (Thorn/EMI), Hayes		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Harper (LPA) 01895 556000

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA

- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / HILLINGDON / HOUNSLOW

SITE NAME:	Bulls Bridge, Hayes		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Medium	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	Harlington Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Medium	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	Harmondsworth Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 18 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	Hayes Village		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	Longford Village, Heathrow Villages		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	Morford Way, Eastcote, Ruislip		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sarah Harper (LPA) 01895 556000
SITE NAME:	The Greenway, Uxbridge		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Sarah Harper (LPA) 01895 556000

HOUNSLOW



SITE NAME:	The Keep (Armoury) to Hounslow Cavalry Barracks, Beavers Lane, Hounslow	Built in 1875 consisting of three storeys with four storey staircase towers at each end and in the centre of the south west front. Many windows retain heavy cast iron shutters
DESIGNATION:	Listed Building grade II, CA	with firing loops and massive bolts to the interior. The building has been unused for some years and the interior of
CONDITION:	Poor	the top storey in particular displays evidence of deterioration. This is as a result of rainwater penetration
OCCUPANCY:	Vacant/not in use	from the rooftop parapet and blockages in the flat roof
PRIORITY CATEGORY:	C (C)	drainage rainwater pipes. There are currently no plans for repairs.
OWNER TYPE:	Government or agency	
LIST ENTRY NUMBER:	1240633	Contact: Sean Doran (LPA) 020 8583 4943

© London Borough of Hounslow

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

UA Unitary Authority WHS World Heritage Site

A-A-A	SITE NAME:	Boston Manor House, Boston Manor Road, Boston Manor Park	Built in 1623 for Lady Mary Reade. Stabilising action to the south and west elevations has been undertaken. Repairs to the south west corner are complete and reinstatement of
	DESIGNATION:	Listed Building grade I, CA	finishes awaited. An options appraisal has been undertaken grant-aided by English Heritage, and discussions are
	CONDITION:	Fair	ongoing regarding future uses and funding.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	
no state in the state	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1079603	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Brentford Baths, Clifden Road, Brentford	Public baths and swimming pool 1895-96, closed in 1990. The building was sold by the London Borough of
	DESIGNATION:		Hounslow in November 1998. The interiors are in
	CONDITION:	Listed Building grade II, CA	reasonable condition, due to inherent robustness, but there is major rooflight leakage. Planning Permission and
- TITTEL - YOU		Fair	Listed Building Consent were granted on appeal in July
	OCCUPANCY:	Vacant/not in use	2011 for change of use to live-work units. Repair and conversion works are underway and nearing completion.
	PRIORITY CATEGORY:	F (D)	
- Internet	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1334358	Contact: Sean Doran (LPA) 020 8583 4943
	SITE NAME:	Feltham House, Elmwood Avenue, Feltham	Built mid C18 as a compact block in stock brick and modelled on other Palladian villas. Extended in late C18
	DESIGNATION:	Listed Building grade II, CA	with the addition of side wings. The interior has been modernised but retains C18 decorations of interest, which
	CONDITION:	Poor	may partly be attributable to James Wyatt who lived at Hanworth. The building has been unused for some time,
	OCCUPANCY:	Vacant/not in use	there is extensive rot damage in the principal storey and
	PRIORITY CATEGORY:	C (C)	rainwater penetration. Some urgent repair works were carried out in 2013 to stabilise the building, but further
	OWNER TYPE:	Government or agency	work is required. There are no plans for the future use of
© English Heritage	LIST ENTRY NUMBER:	1189466	the building. Contact: Sean Doran (LPA) 020 8583 4943
	SITE NAME:	Gunnersbury Park W5	A landscape park developed in the CI8 by Princess Amelia
	DESIGNATION:	Registered Park and Garden grade II*, 22 LBs, CA	and in the C19 by Baron Lionel de Rothschild. It became a public park in 1925. The landscape is in variable condition. Funding has been secured from the Heritage Lottery Fund
	CONDITION:	Generally satisfactory but with significant localised problems	and Big Lottery Fund. Works will include the restoration of parts of the historic landscape, including repairs to the
	VULNERABILITY:	Medium	Round Pond and the Orangery, and the recreation of the west side of the horseshoe lake.
Ser and the second	TREND:	Improving	
	NEW ENTRY?:	No	
© English Heritage	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1000808	Contact: Zosia Mellor 020 7973 3473
	SITE NAME:	Archway near east entrance lodge, Gunnersbury Avenue, Gunnersbury Park W3	Stucco pedimented archway, circa 1837, situated near to the East Lodge, on the eastern edge of Gunnersbury Park, a public park since 1925. Urgent repairs to secure the
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	structural stability of the arch were undertaken in 2012, grant-aided by English Heritage. Funding has been secured from the Heritage Lottery Fund for the wider park, which
	CONDITION:	Poor	includes repair works to the arch.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
© English Heritage Archive	OWNER TYPE:	Local authority, multiple owners	
		· · ·	

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
 - use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- 60

HERITAGE AT RISK 2014 / LONDON / HOUNSLOW

	SITE NAME:	Boundary wall at Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Part of the boundary wall to the garden of the original Gunnersbury House, built 1658-63 by John Webb for Sir John Maynard. The wall runs north-south from the arch to
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	the south east of Princess Amelia's Bath House. Funding has been secured from the Heritage Lottery Fund for the wider park, which includes repair works to the boundary
	CONDITION:	Poor	wall.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1322060	Contact: Sean Doran (LPA) 020 8583 4943
	SITE NAME:	East lodge to Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Entrance lodge circa 1837. All that remains are small sections of the south and west elevations. English Heritage awarded a grant towards urgent repairs to secure the
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	structural stability of the remaining elements of the lodge, which are now complete. Funding has been secured from the Heritage Lottery Fund for the wider park, which
	CONDITION:	Poor	includes repair works to the East Lodge.
	OCCUPANCY:	N/A	
an entry	PRIORITY CATEGORY:	D (C)	
© English Heritage Archive	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1080334	Contact: Sean Doran (LPA) 020 8583 4943
	SITE NAME:	East stables in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Stable block 1835, on the eastern edge of Gunnersbury Park, to the south of the Small Mansion. Emergency works have been undertaken, partly funded by English Heritage.
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	Works are ongoing to stabilise the building.
A AND	CONDITION:	Very bad	
Receiver -	OCCUPANCY:	Vacant/not in use	
		Vacant/ not in use	
	PRIORITY CATEGORY:	C (D)	
© English Heritage	PRIORITY CATEGORY: OWNER TYPE:		
© English Heritage		C (D)	Contact: Verena McCaig 020 7973 3718
© English Heritage	OWNER TYPE:	C (D) Local authority	Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly
© English Heritage	OWNER TYPE: LIST ENTRY NUMBER:	C (D) Local authority 1358316 Gothic Boathouse, Gunnersbury Avenue,	Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some
© English Heritage	OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	C (D) Local authority 1358316 Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park Listed Building grade II, RPG	Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly funded by English Heritage. Funding has been secured from the Heritage Lottery Fund for the wider park, which
© English Heritage	OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	C (D) Local authority 1358316 Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park Listed Building grade II, RPG grade II*, CA	Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly funded by English Heritage. Funding has been secured from the Heritage Lottery Fund for the wider park, which
© English Heritage	OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	C (D) Local authority 1358316 Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park Listed Building grade II, RPG grade II*, CA	Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly funded by English Heritage. Funding has been secured from the Heritage Lottery Fund for the wider park, which
© English Heritage	OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	C (D) Local authority 1358316 Gothic Boathouse, Gunnersbury Avenue, Gunnersbury Park Listed Building grade II, RPG grade II*, CA Poor N/A	Mid C19 Gothic folly tower, converted from a tile kiln and situated on the southern shore of Potomac Lake. Some repair and emergency works have been undertaken, partly funded by English Heritage. Funding has been secured from the Heritage Lottery Fund for the wider park, which

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / HOUNSLOW

HERITAGE AT RISK 2014 / LONDO	ON / HOUNSLOW		
	SITE NAME:	Gothic ruins in Gunnersbury Park, Gunnersbury Avenue, Gunnersbury Park W3	Sham Gothic ruins, on the east side of Gunnersbury Park. Funding has been secured from the Heritage Lottery Fund for the wider park, which includes repair works to the
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	Gothic ruins.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
A AND	PRIORITY CATEGORY:	B (A)	
© English Heritage Archive	OWNER TYPE:	Local authority, multiple owners	
	LIST ENTRY NUMBER:	1080335	Contact: Sean Doran (LPA) 020 8583 4943
	SITE NAME:	The Large Mansion, Gunnersbury Park House, Gunnersbury Avenue, Gunnersbury Park W3	Country house 1801-28 by and for Alexander Copland; remodelled in 1836 by Sydney Smirke for Nathan Rothschild. The building has good interiors and houses the local history museum and education centre for the
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	Boroughs of Hounslow and Ealing. A major 'Heritage Grant' bid received Stage I approval from the Heritage Lottery Fund in 2012, which includes repair and restoratio
	CONDITION:	Poor	of the building for continued use as a local history museum Repairs to the roof were carried out in 2012; the building
	OCCUPANCY:	Part occupied/part in use	now weathertight. A Stage 2 Heritage Lottery Fund bid ha
© English Heritage	PRIORITY CATEGORY:	D (D)	been submitted.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1358312	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	The Small Mansion, Gunnersbury House, Gunnersbury Avenue, Gunnersbury Park W3	Built circa 1810, the smaller of the two houses on the site of Gunnersbury House demolished circa 1801. Discussion are continuing with local planning authorities in order to secure the repair and reuse of the building. Urgent repairs
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	were carried out in 2012, grant-aided by English Heritage.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
English Heritage	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1080330	Contact: Sean Doran (LPA) 020 8583 4943
	SITE NAME:	West Lodge, Gunnersbury Avenue, Gunnersbury Park	Lodge building dating from 1875 in the manner of a gate house, partly in use for residential purposes. English
	DESIGNATION:	Listed Building grade II, RPG grade II*	Heritage awarded a grant towards urgent repairs to the roofs of the unoccupied part of the lodge and the archway located at the south entrance of the park. Repair works
	CONDITION:	Fair	were completed in 2012.

© English Heritage

OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: E (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1389619 Contact: Sean Doran (LPA) 020 8583 4943

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS


- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

62

HERITAGE AT RISK 2014 / LONDON / HOUNSLOW



Early C19 stables situated within Gunnersbury Park. SITE NAME: West stable block in Discussions are continuing with English Heritage and the Gunnersbury Park, Gunnersbury Avenue, local authorities in order to secure the repair and reuse of Gunnersbury Park W3 the building. Works are also underway to stabilise the building. Listed Building grade II, RPG DESIGNATION: grade II*, CA CONDITION: Very bad OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (A) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1096950 Contact: Sean Doran (LPA) 020 8583 4943



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

PRIORITY CATEGORY:

© English Heritage



LIST ENTRY NUMBER: 1189787 Contact: Verena McCaig 020 7973 3718 SITE NAME: Railway station built 1850 by Sir William Tite for the Kew Bridge Railway Station, London and South Western Railway. The building is largely Kew Bridge Road, Brentford unoccupied and boarded up at low levels. Full repair and DESIGNATION: Listed Building grade II, CA re-roofing was undertaken in 2012 and the building is now weathertight. A nearby development site now under CONDITION: Good construction may act as a catalyst for combined action by English Heritage, the Local Authority and others. OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: E (E) OWNER TYPE: Utility LIST ENTRY NUMBER 1260672 Contact: Sean Doran (LPA) 020 8583 4943

Rose and Crown Inn, 333,

Listed Building grade II

Vacant/not in use

London Road

Poor

F (B)

Private

1293984

Roman Bridge, Jersey Road,

Listed Building grade II*, RPG

Osterley Park

grade II*

Very bad

N/A

A (A)

Private

C18 coaching inn with watching bay at first floor. Following a long period of lack of maintenance and water ingress, Planning Permission and Listed Building Consent have been

Bridge, 1780, by Robert Adam. Rusticated stone-faced with

one segmental arch. Flanking pairs of rusticated Doric half

the M4. It straddles the borough boundary between Ealing

columns. The bridge is severed from the historic park by

and Hounslow. The bridge is in need of repair and consolidation; suffers from sporadic vandalism.

granted for residential conversion. Works are well underway and due for completion in 2014.

© English Heritage

© English Heritage

Contact: Sean Doran (LPA) 020 8583 4943

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

ΪA

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

HERITAGE	AT RISK 2014		HOUNSLOW
TILINITAGE		/ LONDON /	TICOTALOVA

	SITE NAME:	The Hermitage, 17, Upper Sutton Lane, Heston	Late C15 timber-framed house with later additions. Badly damaged by fire in 2003. The building has suffered further
	DESIGNATION:	Listed Building grade II	deterioration following theft of the temporary protective roof. The owner is seeking enabling development, but
	CONDITION:	Very bad	proposals are considered excessive. Discussions are ongoing.
A THE MERINE	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1260544	Contact: Sean Doran (LPA) 020 8583 4943

	SITE NAME:	Hanworth Park House, Uxbridge Road, Hanworth	Country house built after 1828 with extension c1860. Urgent works were carried out in 2002, but the building
	DESIGNATION:	Listed Building grade II	has suffered vandalism and further deterioration. Further works were undertaken to stem dry rot outbreaks and to
	CONDITION:	Poor	secure the building, but further outbreaks have occurred. Planning Permission and Listed Building Consent have been
	OCCUPANCY:	Vacant/not in use	granted and the details of a Section 106 agreement are
	PRIORITY CATEGORY:	B (A)	being negotiated.
	OWNER TYPE:	Commercial company	
© English Heritage Archive	LIST ENTRY NUMBER:	1240343	Contact: Sean Doran (LPA) 020 8583 4943

the laters	SITE NAME:	Church of St Paul, Bath Road, Hounslow	Built in 1873, designed by WG Habershon. The tower and spire have been inspected and a scan carried out to plot
	DESIGNATION:	Listed Place of Worship grade II, CA	buried iron cramps and ties which are causing rust jacking and fracturing of stone. Some elements have been removed due to concerns over their structural integrity,
	CONDITION:	Poor	including one of the tower gargoyles, the weathervane from the spire, one of the gable crosses along with brok fragments of stone. The church is currently exploring
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Religious organisation	funding options.
	LIST ENTRY NUMBER:	1245132	Contact: Tracey Craig 020 7973 3756

© English Heritage

SITE NAME:	Double ditched enclosure beside A30 road 500	yds (460m) west of Eas	st Bedfont parish church
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002043
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Romano-British site 1000yds (910m) west of Ea	st Bedfont parish chur	ch
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002042
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Arable ploughing	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Grand Union Canal and Boston Manor, Brentfo	rd	
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Maeve Faulkner (LPA) 020 8583 494
SITE NAME:	Gunnersbury Park, Brentford W3		
DESIGNATION:	Conservation Area, 21 LBs, RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Unknown
VULNERABILITY:	Low	CONTACT:	Maeve Faulkner (LPA) 020 8583 494

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

ISLINGTON



SITE NAME:	Flying Scotsman public house, 2- 4, Caledonian Road, King's Cross NI	Public house of 1900-01, by Wylson and Long. The ground floor is in use as a public house, but the upper floors are vacant and in poor condition with a leaking roof.
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Poor	
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1195703	Contact: Luciana Grave (LPA) 020 7527 2389

© English Heritage

© English Heritage



	SITE NAME:	Former Milford Haven public house, 214, Caledonian Road NI	Mid-C19 public house. Previously in poor condition, with substantial decay to the original timber pub front. However, works are now being implemented for
delited	DESIGNATION:	Listed Building grade II, CA	conversion to residential use.
A RULE	CONDITION:	Poor	
1	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (C)	
-	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1280781	Contact: Kristian Kaminski (LPA) 020 7527 2524



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

© English Heritage



Block of 130 flats designed by Skinner, Bailey and Lubetkin, SITE NAME: Bevin Court, Cruickshank Street WCI built 1951-4. The entrance hall contains a mural by Peter Yates depicting elements of Finsbury's history, staircase DESIGNATION: Listed Building grade II*, CA considered to be Lubetkin's "most idiosyncratic post-war achievement". Redecoration to the common stairwell has CONDITION: Poor been completed but works to rectify damage to the mural OCCUPANCY: Occupied/in use caused by water ingress are still outstanding. PRIORITY CATEGORY: D (D) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1246687 Contact: Verena McCaig 020 7973 3718

Gates and railings around New Church Hawe and gates on south side of the square,

Charterhouse Square ECI

Listed Building grade II, CA

Poor

N/A

C (A)

Unknown

1195529

© English Heritage

	SITE NAME:	Odeon Cinema, Holloway Road N7	Cinema, built as the Gaumont 1937-8, architect C Howard Crane of Chicago. Poor general condition, with cracking
	DESIGNATION:	Listed Building grade II, CA	and damage to faience. Inappropriate modern shop fronts in poor condition undermine the design aesthetic.
	CONDITION:	Poor	
DDEON	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	C (C)	
The second secon	OWNER TYPE:	Commercial company	
English Heritage	LIST ENTRY NUMBER:	1384986	Contact: Kristian Kaminski (LPA) 020 7527 2524

PRIORITY CATEGORIES

© En

Immediate risk of further rapid deterioration or loss of fabric: no

D

Е

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

C19 cast iron carriage gates, the piers of clustered columns surmounted by quatrefoiled panels with a coat of arms and

scrolled finials carrying globe lanterns. There has been

severe vehicle impact damage to one of the piers.

Contact: Kristian Kaminski (LPA) 020 7527 2524

- Conservation Area Listed Building CA
- LB LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Studio (former Chapel), Lloyd Baker Street, Thornhill WCI	Former Chapel of the House of Retreat (Lloyd Baker Street and Lloyd Square), 1891-2 by Ernest Newton. Stock
	DESIGNATION:	Listed Building grade II, CA	brick with tracery windows in stone, slate roof, late Decorated Gothic style. Permission has been granted to
	CONDITION:	Fair	convert the building to residential use.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
© London Borough of Islington	LIST ENTRY NUMBER:	1 195670	Contact: Andy Rayner (LPA) 020 7527 4087

	SITE NAME:	Islington War Memorial Arch, Manor Gardens N7	Listed war memorial designed by Percy Adams, formerly part of the Royal Northern Hospital. The memorial is the
	DESIGNATION:	Listed Building grade II	archway around which the new building has been constructed. Repairs have been carried out including works
	CONDITION:	Fair	to the lettering and stonework and the arch remains in a fair condition. Investigative works into water ingress to the
	OCCUPANCY:	N/A	stonework are complete and a solution agreed. Grant
	PRIORITY CATEGORY:	D (D)	funding is to be sought.
	OWNER TYPE:	Commercial company	
© London Borough of Islington	LIST ENTRY NUMBER:	1392555	Contact: Luciana Grave (LPA) 020 7527 3000

h Heritage Archive	SITE NAME:	Railings, walls, gate piers and gates to Caledonian Park, Market Road N7	Railings, walls and gates to Caledonian Market built in 18 (market demolished). Some repairs have been carried o part funded by English Heritage, but extensive further
	DESIGNATION:	Listed Building grade II	works are required. Redevelopment of housing on an adjacent site is underway. A section of the railings has been
	CONDITION:	Poor	repaired as part of this but there is no scheme for complete repair as yet.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1208009	Contact: Kristian Kaminski (LPA) 020 7527 2524

	SITE NAME:	The Clock Tower, Caledonian Park, Market Road N7	Built as the clock tower of the Caledonian Market in 1855 by John Bunstone Bunning. It is currently vacant and slowly
6 🏛	DESIGNATION:	Listed Building grade II*	decaying. Stage 1 Heritage Lottery Funding has been secured towards its future restoration.
	CONDITION:	Poor	
-u Real	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
© London Borough of Islington	LIST ENTRY NUMBER:	1298021	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Finsbury Health Centre, Pine Street ECI	Seminal Modern Movement health centre built 1935-8 to the design of Berthold Lubetkin. A conservation plan and
	DESIGNATION:	Listed Building grade I, CA	management guidelines have been produced, grant aided by English Heritage. Some urgent work has been carried
	CONDITION:	Poor	out. Its health use is to remain, but repairs are still required. A Feasibility Study has been commissioned.
	OCCUPANCY:	Occupied/in use	required. Arreasioney study has been commissioned.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
sh Heritage	LIST ENTRY NUMBER:	1297993	Contact: Verena McCaig 020 7973 3718

© English Heritage

© English

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

use).

D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

X	SITE NAME:	Finsbury Town Hall, Rosebery Avenue ECI	Town hall, built in 1895 to the design of C Evans Vaughan in an eclectic 'Free Renaissance' style. Magnificent public
	DESIGNATION:	Listed Building grade II*, CA	hall on the first floor with elaborate plasterwork in Belle Epoque manner. Now in use as dance studios with the
	CONDITION:	Fair	main halls available for public use. The external fabric of the building has still not been fully repaired.
	OCCUPANCY:	Occupied/in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1293112	Contact: Verena McCaig 020 7973 3718




	SITE NAME:	The Vaults to the House of Detention (part of former), Sans Walk ECI	Part of Middlesex House of Detention built 1845-47, previously occupied as a museum. Works for conversion to office space for a part of the structure have been
	DESIGNATION:	Listed Building grade II, CA	approved but not yet implemented. There is a problem with water ingress from the car park above and
	CONDITION:	Fair	management issues due to multiple ownership.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private, multiple owners	
	LIST ENTRY NUMBER:	1297973	Contact: Luciana Grave (LPA) 020 7527 2389



© English Heritage Archive

© English Heritage



TH	SITE NAME:	Railings, Thornhill Square NI	Some repairs to the railings were completed in 2010, part
	DESIGNATION:	Listed Building grade II, CA	funded by English Heritage. The Council is proposing to apply to the Heritage Lottery Fund for a grant towards
TAT	CONDITION:	Poor	further repairs and landscaping. Discussions are ongoing regarding how best to repair or replace damaged railings.
1 State	OCCUPANCY:	N/A	regarding now best to repair of replace damaged railings.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1297982	Contact: Andy Rayner (LPA) 020 7527 4087

© English Heritage



	SITE NAME:	Railings, Wilmington Square WCI	Cast iron railings of 1819-1841, in very poor condition. Urgent works have previously been carried out, but
	DESIGNATION:	Listed Building grade II, CA	currently no funding has been identified for a full repair programme.
1	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
Sec.	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1195789	Contact: Andy Rayner (LPA) 020 7527 4087

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious powy user (coplicable only

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

Â	SITE NAME:	Church of St James and attached railings, Clerkenwell Close, Islington EC1	The church was built by architect James Carr between 1788 and 1792 for a Methodist congregation; this was reordered in 1882 by Reginald Blomfield for an Anglican
	DESIGNATION:	Listed Place of Worship grade II*, CA	congregation when the altar was placed in the east and the galleries cut back. The steeple was rebuilt in 1849, and in 1900 the vaulted crypt was deepened and supported on ar
Terrenter Terrenter	CONDITION:	Poor	iron structure. There are cracks on the west front, the
1000	PRIORITY CATEGORY:	C (New entry)	windows are in need of repair and local repairs are needed to the steeple.
	OWNER TYPE:	Religious organisation	
English Heritage	LIST ENTRY NUMBER:	1207786	Contact: Ian Harper 020 7973 3786
Î.Î	SITE NAME:	Celestial Church of Christ, Cloudesley Square NI	Built 1826-9 to the design of Sir Charles Barry. Urgent repairs to the roof and high level stonework were carried
	DESIGNATION:	Listed Place of Worship grade II*, CA	out with Heritage Lottery Fund/English Heritage funding in 2006-7. However the west turrets are still in bad condition and the finials remain clad in netting. The nave ceiling is still
	CONDITION:	Very bad	netted internally to catch plaster.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1195557	Contact: Ian Harper 020 7973 3786
English Heritage			
	SITE NAME:	Union Chapel, Compton Terrace NI	Congregational chapel and related buildings of 1876-7 by James Cubitt with the upper part of the tower completed in 1889. Repairs to the tower and high level roofs are
	DESIGNATION:	Listed Place of Worship grade I, CA	complete, grant-aided by the Heritage Lottery Fund and English Heritage. There are still concerns about the lower
te 202	CONDITION:	Fair	level masonry of the tower and the structure of the octagon
THE PARTY	PRIORITY CATEGORY:	C (F)	0
	OWNER TYPE:	Religious organisation	
English Heritage	LIST ENTRY NUMBER:	1208365	Contact: Ian Harper 020 7973 3786
	SITE NAME:	Maaaa Binga 171 170 Faaaa	Built as the Carlton Cinema in 1930 by George Coles,
	SHE MARE.	Mecca Bingo, 161-169, Essex Road NI	previously a bingo hall and now in use as a place of
	DESIGNATION:	Listed Place of Worship grade II*	worship. Black, white and coloured faience to the Essex Road front, the rest of yellow brick; slate roof. The façade
	CONDITION:	Poor	to Essex Road is in Egyptian style. The church has temporary consent for their use of the building, including
	PRIORITY CATEGORY:	C (New entry - re-assessed)	the temporary division of the main auditorium. Some
	OWNER TYPE:	Religious organisation	repairs and restoration have been carried out, but there is evidence of damage to the faience tiles. Proposals for re-
- 1	LIST ENTRY NUMBER:	1292870	use are currently being explored.
English Heritage	-		Contact: Verena McCaig 020 7973 3718
421	SITE NAME:	Church of St Joseph, Highgate Hill, Islington N19	The Passionists acquired the site in 1858 and built a monastery and chapel. The monastery remains and is wrapped around the existing church to its eastern and Th



SITE NAME:	Church of St Joseph, Highgate Hill, Islington N19	The Passionists acquired the site in 1858 and built a monastery and chapel. The monastery remains and is
DESIGNATION:	Listed Place of Worship grade II*, CA	wrapped around the existing church to its eastern end. The existing church was built in 1887-9 by Albert Vicars in a Neo-Romanesque style. The roof and rainwater goods are
CONDITION:	Poor	in a poor condition.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1279729	Contact: Ian Harper 020 7973 3786

© Jim Linwood

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user latentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE	AT RISK	(2014 /		/ ISLINGTON
TILKIT/ OL.	/ 1 1 1 1 3 1	2011/	LONDON	

HERITAGE AT RISK 2014 / LONDO	UN / ISLINGTON			
	SITE NAME:	Hope Church (former Church of St Mary Magdalene) and attached railings, Holloway Road, Islington N7	1812-14 by arc Ease to St Mary Portland stone	h re-named Hope Church in 2013; built hitect William Wickings as the Chapel of y's Islington. London yellow stock bricks with dressings. The unusually planned east-end
6-0-0-0	DESIGNATION:	Listed Place of Worship grade II*, CA	north and sout	ed structurally against the aisles, and the h porches have settled and pulled away fron west end and porch have also settled. The
	CONDITION:	Poor	crypt is at risk o	of flooding; underground water levels, olled by permanent pumping, require
	PRIORITY CATEGORY:	C (New entry)	investigation to	achieve a sustainable solution to the
© English Heritage	OWNER TYPE:	Religious organisation	settlement.	
S English Hentage	LIST ENTRY NUMBER:	1195637	Contact: Ian H	arper 020 7973 3786
and the second	SITE NAME:	Church of St Silas, Penton Street, Islington NI	Built in 1860, designed by SS Teulon, completed in 186 EP Loftus Brock and chancel added in 1884 by W Whi	
	DESIGNATION:	Listed Place of Worship grade II, CA	photovoltaic til Priority stone r	e re-slated in 2010, the south slope with es to match the slates in size and colour. repairs have been carried out but more
	CONDITION:	Poor		uired. The church has been awarded a first m the Heritage Lottery Fund for structural
	PRIORITY CATEGORY:	D (New entry)	repairs to the v	vest end, where there is significant cracking.
I and the second second	OWNER TYPE:	Religious organisation	i ne developme	ent phase of the project is underway.
© English Heritage	LIST ENTRY NUMBER:	1208241	Contact: Trace	y Craig 020 7973 3756
9 Eligisti Fieritage				
No Charles	SITE NAME:	Church of St Mary, Upper Street, Islington NI	This is the fourth church on this site, having been rebu 1955-56 by Seely and White to replace the 1751 chur	
1 AL	DESIGNATION:	Listed Place of Worship grade II, CA	destroyed in the Blitz, which had replaced a C14 Medie church built on the site of a Norman church. Construct as with the C18 church, is in brick with stone quoins ar dressings. The neoclassical tower survived, along with t 1902 portico by R Blomfield. The portico has settled ar	the site of a Norman church. Construction
	CONDITION:	Poor		
	PRIORITY CATEGORY:	C (New entry)	the masonry and roof are in need of repair. Possible sources of funding are currently being explored. Contact: Ian Harper 020 7973 3786	
STATE DI MARCO	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1195776		
© English Heritage				
SITE NAME:				
	Bunnill Fields, Fin	SDULY SQUALE LCZ		
DESIGNATION:	Bunhill Fields, Fin Conservation Are	· · ·	NEW ENTRY?:	No
DESIGNATION: CONDITION:		ea, 95 LBs, RPG grade I	NEW ENTRY?: TREND:	
	Conservation Are	· · ·		No Deteriorating Luciana Grave (LPA) 020 7527 3000
CONDITION: VULNERABILITY:	Conservation Are Fair Medium	ea, 95 LBs, RPG grade I	TREND:	Deteriorating
CONDITION: VULNERABILITY: SITE NAME:	Conservation Are Fair Medium Chapel Market N	ea, 95 LBs, RPG grade I	TREND: CONTACT:	Deteriorating Luciana Grave (LPA) 020 7527 3000
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION:	Conservation Are Fair Medium Chapel Market N Conservation Are	ea, 95 LBs, RPG grade I	TREND: CONTACT: NEW ENTRY?:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad	ea, 95 LBs, RPG grade I	TREND: CONTACT: NEW ENTRY?: TREND:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION:	Conservation Are Fair Medium Chapel Market N Conservation Are	ea, 95 LBs, RPG grade I	TREND: CONTACT: NEW ENTRY?:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad	ea, 95 LBs, RPG grade I I ea, 5 LBs	TREND: CONTACT: NEW ENTRY?: TREND:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad Medium	ea, 95 LBs, RPG grade I I ea, 5 LBs C1	TREND: CONTACT: NEW ENTRY?: TREND:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: SITE NAME:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad Medium Chiswell Street E	ea, 95 LBs, RPG grade I I ea, 5 LBs C1	TREND: CONTACT: NEW ENTRY?: TREND: CONTACT:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly Luciana Grave (LPA) 020 7527 3000
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: DESIGNATION:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad Medium Chiswell Street E Conservation Are	ea, 95 LBs, RPG grade I I ea, 5 LBs C1	TREND: CONTACT: NEW ENTRY?: TREND: CONTACT:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly Luciana Grave (LPA) 020 7527 3000 No
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad Medium Chiswell Street E Conservation Are Fair	ea, 95 LBs, RPG grade I I ea, 5 LBs C1	TREND: CONTACT: NEW ENTRY?: TREND: CONTACT: NEW ENTRY?: TREND:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly Luciana Grave (LPA) 020 7527 3000 No Deteriorating
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: VULNERABILITY: CONDITION: CONDITION: CONDITION: VULNERABILITY: CONDITION:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad Medium Chiswell Street E Conservation Are Fair Medium	ea, 95 LBs, RPG grade I I ea, 5 LBs CI ea, 3 LBs	TREND: CONTACT: NEW ENTRY?: TREND: CONTACT: NEW ENTRY?: TREND:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly Luciana Grave (LPA) 020 7527 3000 No Deteriorating
CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: DESIGNATION: CONDITION: VULNERABILITY: SITE NAME: SITE NAME:	Conservation Are Fair Medium Chapel Market N Conservation Are Very bad Medium Chiswell Street E Conservation Are Fair Medium	ea, 95 LBs, RPG grade I I ea, 5 LBs CI ea, 3 LBs	TREND: CONTACT: NEW ENTRY?: TREND: CONTACT: NEW ENTRY?: TREND: CONTACT:	Deteriorating Luciana Grave (LPA) 020 7527 3000 No Improving significantly Luciana Grave (LPA) 020 7527 3000 No Deteriorating Luciana Grave (LPA) 020 7527 3000

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:	Hat and Feathers ECI		
DESIGNATION:	Conservation Area, 4 LBs	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300
SITE NAME:	Mercers Road/Tavistock Terrace N7		
DESIGNATION:	Conservation Area, 3 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300
GITE NAME:	Moorfields ECI		
DESIGNATION:	Conservation Area, LB grade II	NEW ENTRY ?:	No
CONDITION:	Fair	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300
SITE NAME:	St John's Grove N19		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
/ULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300
SITE NAME:	St Mary Magdalene N5		
DESIGNATION:	Conservation Area, 34 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300
SITE NAME:	Stroud Green N4		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300
ITE NAME:	Tollington Park N4		
DESIGNATION:	Conservation Area, 5 LBs	NEW ENTRY ?:	No
CONDITION:	Poor	TREND:	Deteriorating
/ULNERABILITY:	Medium	CONTACT:	Luciana Grave (LPA) 020 7527 300

KENSINGTON AND CHELSEA



	SITE NAME:	Arcade forming circle and avenue, Brompton Cemetery, Old Brompton Road SW10	Arcade, 1839-40, situated in the centre of the southern half of Brompton Cemetery, designed by Benjamin Baud. It is a united composition comprising four quadrants which form
1	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	the circle and the avenue. The structure is suffering gradual decay owing to the later addition of a cast concrete flat roof. A Heritage Lottery Fund grant was awarded in
	CONDITION:	Poor	January 2014 for works to the wider cemetery.
l	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	^{RY:} C (C)	
	OWNER TYPE:	Government or agency	
	LIST ENTRY NUMBER:	1225713	Contact: Rebecca Barrett 020 7973 3716

Contact: Rebecca Barrett 020 /9/3 3/16

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	31, Brompton Square, South Kensington SW3	House dating from 1824-39, part of Brompton Square. A series of Planning Permissions and Listed Building Consents
	DESIGNATION:	Listed Building grade II, CA	have been granted for internal alterations and rear extensions. Works to implement the consents came to a
I I I MANUTA	CONDITION:	Poor	halt in December 2008. An Urgent Works Notice to make the building weathertight was served and complied with in
# - B	OCCUPANCY:	Vacant/not in use	December 2009.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
of Kensington and	LIST ENTRY NUMBER:	1080723	Contact: Mark Butler (LPA) 020 7361 2465

© Royal Borough of Chelsea

E	SITE NAME:	Campden Hill, I, Campden Hill W8	Private house built 1914-15. It represents an Edwardian Arts and Crafts led interpretation of a large C17 country
	DESIGNATION:	Listed Building grade II, CA	house in an urban setting. Permission was granted for internal alterations and extensions in July 2008. Works
	CONDITION:	Fair	have stalled on site and the building is now showing the initial signs of neglect with lack of general maintenance.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	39 38	Contact: Mark Butler (LPA) 020 7361 2465

© English Heritage

© Royal Borough of Kensington and Chelsea

	SITE NAME:	Kensal Green (All Souls) Cemetery W10	London's first metropolitan cemetery, begun 1833, designed by John William Griffith. The cemetery contains a
	DESIGNATION:	Registered Park and Garden grade I, 139 LBs, 2 CAs	large number of listed monuments and structures at risk, including the Anglican Chapel and North Colonnade. A Conservation Management Plan is in place and a project
	CONDITION:	Generally unsatisfactory with major localised problems	manager has been appointed to further develop management and conservation strategies, including a possible application to the Heritage Lottery Fund.
B T	VULNERABILITY:	Medium	Legislative changes in May 2014 will enable the formatic of a Trust to oversee the management of parts of the cemetery.
	TREND:	Declining	
	NEW ENTRY?:	No	,
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1000817	Contact: Zosia Mellor 020 7973 3473

	SITE NAME:	Boundary wall to Kensal Green Cemetery, Harrow Road W10	High brick boundary wall to Harrow Road, a 100 metre section of which collapsed in 2006. Further bays reduced in
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	height subsequently due to safety concerns. English Heritage has awarded a grant towards the first phase of rebuilding the collapsed section which involves piling, casting a ground beam and rebuilding part of the wall as original. Repair works are underway. There are no proposals or funding at present to rebuild the remainder of
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	the wall.
	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1191000	Contact: Mark Butler (LPA) 020 7361 2465

SITE NAME:	Blumberg Mausoleum, Harrow Road, Kensal Green Cemetery W10	Large mausoleum from mid C19 in Carrara marble, grey granite and bronze. In very bad condition with extensive vegetation growth, collapsed in parts and showing	
DESIGNATION:	Listed Building grade II, RPG grade I, CA	widespread delamination. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.	
CONDITION:	Very bad		
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	A (A)		
OWNER TYPE:	Unknown		
LIST ENTRY NUMBER:	1245932	Contact: Mark Butler (LPA) 020 7361 2465	
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Road, Kensal Green Cemetery W10DESIGNATION:Listed Building grade II, RPG grade I, CACONDITION:Very badOCCUPANCY:N/APRIORITY CATEGORY:A (A)OWNER TYPE:Unknown	

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

N/A

A (A)

Unknown

1227650

HENTAGE AT MISK 20147 EONDO		ID CITELSEA	
	SITE NAME:	Mausoleum of Andrew Ducrow, Harrow Road, Kensal Green Cemetery W10	Mausoleum erected in 1837 for Andrew Ducrow's wife from a design by George Danson, with later embellishments following Ducrow's own interment. The
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	mausoleum is in poor condition given the loss of sculptu elements and ironwork, overgrown vegetation and gene erosion. A comprehensive condition survey was produce
	CONDITION:	Poor	in 2013, funded by English Heritage. Works are being prioritised accordingly.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1358179	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Mausoleum of Isabella Gregory, Harrow Road, Kensal Green Cemetery NW10	Mausoleum circa 1830. Overgrown vegetation obscures the condition of much of the mausoleum but spalled stone due to corroding iron cramps is evident. A comprehensive
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Very bad	

© English Heritage

©

10-1

C

	SITE NAME:	Mausoleum of James Morison, Harrow Road, Kensal Green Cemetery W10	Large mausoleum dated 1838 designed by Robert Shout. Several of the stone roof panels are missing, part of a pediment has collapsed and there are cracks in the stone,
Store .	DESIGNATION:	Listed Building grade II, RPG grade I, CA	probably due to corroding iron cramps. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Very bad	
Record and	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
D English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246098	Contact: Mark Butler (LPA) 020 7361 2465



© English Heritage

OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1246098	Contact: Mark Butler (LPA) 020 7361 2465
SITE NAME:	Mausoleum of Ross Martha, Harrow Road, Kensal Green Cemetery W10	Gothic mausoleum in Bath and Portland stone dating from circa 1860. Some stonework has fallen off, the railings have been lost, invasive vegetation is growing from the roof and
DESIGNATION:	Listed Building grade II, RPG grade I, CA	there is damage to some windows which may have been caused by anti-social behaviour. A comprehensive condition survey was produced in 2013, funded by English
CONDITION:	Poor	Heritage. Works are being prioritised accordingly.
OCCUPANCY:	N/A	
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Unknown	
LIST ENTRY NUMBER:	1246097	Contact: Mark Butler (LPA) 020 7361 2465
	LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	LIST ENTRY NUMBER:1246098SITE NAME:Mausoleum of Ross Martha, Harrow Road, Kensal Green Cemetery W10DESIGNATION:Listed Building grade II, RPG grade I, CACONDITION:PoorOCCUPANCY:N/APRIORITY CATEGORY:A (A)OWNER TYPE:Unknown

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Mark Butler (LPA) 020 7361 2465

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Monument to Joseph Allmond	Circa 1870, tall composite monument in Portland stone
		Cropper, Harrow Road, Kensal Green Cemetery W10	and pink Peterhead granite shafts. The monument is leaning significantly and there is damage to the figure, canopy and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	ironwork. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389193	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Monument to Julia Slater, Harrow Road, Kensal Green Cemetery W10	Triangular monument with relief of an allegorical female figure on each side on a circular plinth, circa 1840. The monument is leaning significantly, is very unstable and
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	severely damaged due largely to rusting iron cramps. The is also encroaching mature vegetation. A comprehensive condition survey was produced in 2013, funded by English
The states	CONDITION:	Very bad	Heritage. Works are being prioritised accordingly.
	OCCUPANCY:	N/A	
- China al	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	38920	Contact: Mark Butler (LPA) 020 7361 2465
Factor in	SITE NAME:	The Anglican Chapel, Harrow Road, Kensal Green Cemetery W10	1835-36 by John Griffith for the General Cemetery Company. Portland stone and stucco central chapel of a Greek Doric tetra style, with (now roofless) pavilions
	DESIGNATION:	Listed Building grade I, RPG grade I, CA	containing marble memorial sculpture. Large catacomb below. The building is no longer in use and is suffering from water ingress. A detailed condition survey has been
	CONDITION:	Poor	undertaken, funded by English Heritage. Proposals for repair and future use are being considered.
	OCCUPANCY:	N/A	repair and future use are being considered.
	PRIORITY CATEGORY:	C (C)	
© English Heritage	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	90995	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	The North Colonnade, Harrow	Built by John Griffith in 1833 to display tablets and



	LIST ENTRY NUMBER:	1190995	Contact: Verena McCaig 020 7973 3718
1	SITE NAME:	The North Colonnade, Harrow Road, Kensal Green Cemetery W10	Built by John Griffith in 1833 to display tablets and monuments, with a brick vaulted catacomb underneath. Currently in poor condition. The restoration of a sample
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	bay was recently completed, part funded by English Heritage. Discussions regarding the repair of the remain of the colonnade are ongoing.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080629	Contact: Mark Butler (LPA) 020 7361 2465

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

LIST ENTRY NUMBER:

1389215

TIERTAGE AT RISK 20147 EONDO			
	SITE NAME:	Tomb of Admiral Henry Collins Deacon, Harrow Road, Kensal Green Cemetery W10	Mid C19 sculptural monument in Portland stone with cannon, flag, rope and cannon balls. Cracks and missing elements on the plinth have caused the shifting of the
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	monument on its base and a significant lean. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised
	CONDITION:	Poor	accordingly.
SKIN KOL	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389226	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Admiral Sir John Ross, Harrow Road, Kensal Green Cemetery W10	Marble memorial with sculpture of an anchor and cross a tall pedestal, dating from mid C19. Significant lean to t south. A comprehensive condition survey was produced
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	

	SITE NAME:	Tomb of Alexander Bruce, Harrow Road, Kensal Green Cemetery W10	Two stage monument dating from 1850 consisting of a rectangular pedestal upon a tomb chest with relief of mourning women in a tropical landscape. A deep undercut
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	at its base has led to the exposure and erosion of the vault and foundations and a slight lean of the monument. A comprehensive condition survey was produced in 2013,
	CONDITION:	Very bad	funded by English Heritage. Works are being prioritised accordingly.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
nglish Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389188	Contact: Mark Butler (LPA) 020 7361 2465



	LIST EN TRY NUMBER:	1389188	Contact: Mark Butler (LPA) 020 7361 2465
SITE NAME: DESIGNATION:	SITE NAME:	Tomb of Alfred Cooke, Harrow Road, Kensal Green Cemetery W10	A limestone tomb by Thomas Milnes from the mid-C19 with a statue of a horse and infant on a pedestal. The sculpture is badly damaged and railings are missing. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	
	CONDITION:	Poor	
1	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389167	Contact: Mark Butler (LPA) 020 7361 2465

© English Heritage

© Engl

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Mark Butler (LPA) 020 7361 2465

ABBREVIATIONS

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	Tomb of Colonel Gideon Gorrequer, Harrow Road, Kensal Green Cemetery NW10	Elaborate military monument dating from 1841 to Colonel Gorrequer, ADC (aide-de-camp) to the Governor of St Helena during Napoleon's banishment. There is evidence of erosion at foundation level. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	
And the second	CONDITION:	Fair	61 67
THE PARTY OF	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389244	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Commander Charles Spencer Ricketts, Harrow Road, Kensal Green Cemetery W10	Monument designed by William Burges in 1867. Elaborat Portland stone canopied tomb with sarcophagus decorat with naval imagery. In very poor condition with damage inflicted by anti-social behaviour, invasive vegetation and general weathering. A comprehensive condition survey v produced in 2013, funded by English Heritage. Works an
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	
HITILS	CONDITION:	Very bad	being prioritised accordingly.
E. Terre	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080630	Contact: Verena McCaig 020 7973 3718
	SITE NAME:	Tomb of Daboda Dewanjee, Harrow Road, Kensal Green Cemetery W10	Indian grave marker of red sandstone from the mid-C19. The tomb has a significant lean due to severe erosion of the base. A comprehensive condition survey was produced
		Listed Building grade II RPG	in 2013, funded by English Heritage. Works are being

Listed Building grade II, RPG

grade I, CA

Very bad

N/A

A (A)

-		AV A
	-	THE
and a second		
-		7
		N

DESIGNATION:

CONDITION:

OCCUPANCY:

PRIORITY CATEGORY:

© English Heritage

	A	-
F		-
	J.	

	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246079	Contact: Mark Butler (LPA) 020 7361 2465
1	SITE NAME:	Tomb of Duke of Somerset, Harrow Road, Kensal Green Cemetery W10	Portland stone mausoleum dating from the mid-C19. Erosion at foundation level, spalling stone due to rusting cramps. The interior is in poor condition and there is
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	evidence of anti-social activity. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Poor	
清	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389242	Contact: Mark Butler (LPA) 020 7361 2465

prioritised accordingly.

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

LIST ENTRY NUMBER:

1389182

	SITE NAME:	Tomb of Frederick Tillson, Harrow Road, Kensal Green Cemetery W10	Gothic Revival monument dating from circa 1870, consisting of a canopied tomb of Portland stone, marble and sandstone over a raised, moulded base. The
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	monument is in very poor condition with subsidence on the north elevation, deterioration of stonework, widening of joints, corrosion of iron, and loss of finials. A
	CONDITION:	Very bad	comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised
	OCCUPANCY:	N/A	accordingly.
- James Base	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389192	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Frederick Yates, Harrow Road, Kensal Green Cemetery W10	Portland stone sarcophagus with effigy of a sleeping child Carrara marble from around 1840. Slight lean to north east, erosion of foundations and invasive vegetation
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	growth. The effigy of the child has been removed for safekeeping. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are
	CONDITION:	Poor	being prioritised accordingly.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	

	SITE NAME:	Tomb of General James Perry and Sir Patrick O'Brien, Harrow Road, Kensal Green Cemetery W10	Large chapel-like mausoleum from the end of the C19. In very bad condition with widespread erosion, harmful plant growth and extensive damage to the roof and north west corner. A comprehensive condition survey was produced
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
© English Heritage	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1246096	Contact: Mark Butler (LPA) 020 7361 2465



Tomb of Henry Kendall, Harrow Road, Kensal Green Cemetery W10 SITE NAME: A Gothic monument erected in 1853 by architect Henry E Kendall in memory of his son. A large headstone with Masonic symbols over raised ledger framed by Minton tiles and looked over by an angel sculpture. The tomb is in a Listed Building grade II, RPG deteriorating condition due to the failure of metal supports DESIGNATION: grade I, CA behind the sculpture, the loss of tiles, overgrown vegetation and general erosion. A comprehensive CONDITION: Poor condition survey was produced in 2013, funded by English OCCUPANCY: N/A Heritage. Works are being prioritised accordingly. PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1246092 Contact: Mark Butler (LPA) 020 7361 2465

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Mark Butler (LPA) 020 7361 2465

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Tomb of James Poole, Harrow Road, Kensal Green Cemetery W10	Slate chest tomb from the mid-C18. Structural settlement has led to compression/shearing of some slate elements. This structural movement needs to be arrested. The tomb
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	has also suffered from the loss of decorative features. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised
	CONDITION:	Very bad	accordingly.
	OCCUPANCY:	N/A	
and the second	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1271534	Contact: Mark Butler (LPA) 020 7361 2465

Tomb of James Ward, Harrow Road, Kensal Green Cemetery

Listed Building grade II, RPG

W10

grade I, CA

Very bad

Unknown

1389200

N/A

A (A)



D

©

	SITE NAME:	Tomb of John Thompson, Harrow Road, Kensal Green Cemetery W10	Tomb of John Thompson, died 1843, of Portland stone and Carrara marble. One of the earliest monuments in the cemetery. The surface of the stone is deteriorating and	
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	part of the wall structure is starting to bulge. The roof is in very poor condition with vegetative growth.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	C (New entry)		
	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1246094	Contact: Mark Butler (LPA) 020 7361 2465	



© English Heritage

© English Heritage



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



X	SITE NAME:	Tomb of John Gibson, Harrow Road, Kensal Green Cemetery W10	Gothic style tomb of architect John Gibson d.1859, designed by the architect himself. There is severe erosion of the upper registers and widening of joints. A		
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.		
F.	CONDITION:	Poor			
	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Unknown			
	LIST ENTRY NUMBER:	1080632	Contact: Mark Butler (LPA) 020 7361 2465		

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Tall upright with a relief of the Muse of Painting dating from circa 1859. The stone now lies flat and broken in two

pieces. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being

Contact: Mark Butler (LPA) 020 7361 2465

prioritised accordingly.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

the state	SITE NAME:	Tomb of John Lucas, Harrow Road, Kensal Green Cemetery NW10	Tall grey Cornish granite obelisk with Carrara marble bas- relief dating from the end of the C19. The landing stone is broken and sinking into the vault and the monument is
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	leaning significantly. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389238	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of Major General Sir William Casement, Knight Commander of the Bath, Harrow Road, Kensal Green Cemetery W10	Portland stone base supporting a coffin chest draped with Casement's cloak and topped with his bicorn and sword, all under a stone canopy supported at each corner by an Indian bearer. There has been some disruption of stone due to ivy and the corrosion of cramps has led to part of the corrosion of cramps has led to part of
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	the cornice being removed. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
Red Rooter	CONDITION		
	CONDITION:	Poor	
	OCCUPANCY:	Poor N/A	
© English Heritage			
© English Heritage	OCCUPANCY:	N/A	



	SITE NAME:	Tomb of Mary Gibson, Harrow Road, Kensal Green Cemetery W10	Monumental tomb from 1856 comprising a carved coffin under an open aedicule with twelve Corinthian columns surmounted by four angels each with an arm held aloft to
	DESIGNATION:	Listed Building grade II*, RPG grade I, CA	support a now missing central wreath. The tomb is in poor condition due to the loss of sculptural elements, sinking on the west side, widespread erosion and dirt accretions. A
	CONDITION:	Poor	comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised
	OCCUPANCY:	N/A	accordingly.
Aug.	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1293490	Contact: Verena McCaig 020 7973 3718

© English Heritage



SITE NAME: Tomb of Samuel Griffith, Portland stone altar tomb on a stepped granite base, from Harrow Road, Kensal Green circa 1830. The tomb is in poor condition due to erosion and loss of detailing, corrosion of ironwork and heavy Cemetery WI0 overgrowth which is exacerbating the disruption of stone. Listed Building grade II, RPG Railings are missing and bollards have fallen. A DESIGNATION: grade I, CA comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised CONDITION: Poor accordingly. OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: Contact: Mark Butler (LPA) 020 7361 2465 1389237

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; в solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building Local Planning Authority National Park CA
- LB LPA
- NP RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

	SITE NAME:	Tomb of Sir Charles Newton, Harrow Road, Kensal Green Cemetery W10	Tall Greek grave stele style headstone dating from the end of the C19. Now laid flat and more vulnerable to dirt and organic growth. There is some erosion and cracking. A
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389225	Contact: Mark Butler (LPA) 020 7361 2465
	SITE NAME:	Tomb of the Earl of Galloway, Harrow Road, Kensal Green Cemetery W10	Large neoclassical chest tomb by JB Papworth dating from 1838. There is damage to the kerb stone, widening of joints, invasive plant growth causing extensive disruption
AND A CONTRACTOR OF THE REAL O			and some collapse on the east face. A comprehensive

© English	Heritage

	SITE NAME:	Tomb of the Earl of Galloway, Harrow Road, Kensal Green Cemetery W10	Large neoclassical chest tomb by JB Papworth dating from 1838. There is damage to the kerb stone, widening of joints, invasive plant growth causing extensive disruption
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	and some collapse on the east face. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
nglish Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389178	Contact: Mark Butler (LPA) 020 7361 2465

-	SITE NAME:	Tomb of Thomas Fenwick, Harrow Road, Kensal Green Cemetery NW10	Mausoleum from 1834, one of the earliest monuments in the cemetery. Several elements have collapsed and vegetation is infiltrating through the masonry. The door is rusted and the bollards and chains have been lost. A
		rusted and the bollards and chains have been lost. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised	
	CONDITION:	Very bad	accordingly.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1227649	Contact: Mark Butler (LPA) 020 7361 2465



11	SITE NAME:	Tomb of WH Kent, Harrow Road, Kensal Green Cemetery NW10	Carrara marble pedestal surmounted by a draped urn dating from 1874. Relief of dog at base. The tomb is in poor condition due to erosion of its carving, deterioration
	DESIGNATION:	Listed Building grade II, RPG grade I, CA	of the inscription, the heavy lean of the monument towards the west and encroaching vegetation. A comprehensive condition survey was produced in 2013, funded by English
	CONDITION:	Poor	Heritage. Works are being prioritised accordingly.
ST A	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1389246	Contact: Mark Butler (LPA) 020 7361 2465

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

DESIGNATION:

CONDITION:


OCCUPANCY.

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

	Se de la	SITE NAME:	Commonwealth Institute.	The Commonwealth Institute designed by Robert
Harrow Road, Kensal Green Centerry W10 Listed Building grade II, RPG grade I, CA CONDITION: Listed Building grade II, RPG CONDITION: Perior: N/A PRIOR:TY CATEGORY: OWNER TYPE: Unknown		LIST EINTRT NUMBER:	1246083	Contact: Mark Butler (LPA) 020 7361 2465
Harrow Road, Kensal Green Cemetery W10 For the mid-C19. The corrosion of iron cramps is causin spalling of the stone. The ground is eroded around the tomb resulting in damage to the brickwork below. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly. OCCUPANCY: N/A PRIORITY CATEGORY: C (C)) English Heritage		1246023	Contracts Marily Dutley (LDA) 020 72(L 24/E
Harrow Road, Kensal Green Harrow Road, Kensal Green from the mid-C19. The corrosion of iron cramps is causin spalling of the stone. The ground is eroded around the tomb resulting in damage to the brickwork below. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly. CONDITION: Poor OCCUPANCY: N/A		OWNER TYPE:	Unknown	
Harrow Road, Kensal Green Cemetery W10 From the mid-C19. The corrosion of iron cramps is causin spalling of the stone. The ground is eroded around the tomb resulting in damage to the brickwork below. A comprehensive condition survey was produced in 2013, funded by English Heritage. Works are being prioritised accordingly.		PRIORITY CATEGORY:	C (C)	
Harrow Road, Kensal Green Cemetery W10 DESIGNATION: Listed Building grade II, RPG grade I, CA Listed Building grade II, RPG grade I, CA	Contraction of the local division of the loc	OCCUPANCY:	N/A	
Harrow Road, Kensal Green Cemetery W10 Listed Building grade II, RPG Listed Building grade II, RPG	S. Althe Stand	CONDITION:	Poor	accordingly.
Harrow Road, Kensal Green Cemetery W10 from the mid-C19. The corrosion of iron cramps is causin spalling of the stone. The ground is eroded around the		DESIGNATION:		comprehensive condition survey was produced in 2013,
		SITE NAME:	Harrow Road, Kensal Green	







© English Heritage

© English Heritage



OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1224734 Contact: Mark Butler (LPA) 020 7361 2465 SITE NAME: Two mid C19 stucco houses in florid classical style now 25-26, Pembridge Square W2 joined together to form a hotel. Permission was granted in DESIGNATION: Listed Building grade II, CA June 2009 for change of use back to residential with a rear extension and basement. The elevations have been CONDITION: Fair repaired and redecorated, however other works on site OCCUPANCY: Part occupied/part in use have ceased following the submission of further Planning and Listed Building Consent applications. The buildings are PRIORITY CATEGORY D (D) now showing signs of neglect. OWNER TYPE: Private

Enclosing walls to Moravian

Burial Ground, King's Road

Listed Building grade II, CA

SW10

Poor

N/A

1225869

C (New entry)

Contact: Mark Butler (LPA) 020 7361 2465

Brick walls enclosing the Moravian Burial Ground, mostly

Tudor in origin with later additions. Historic repairs have

brickwork are causing localised damage. A condition survey is required to inform repair works. Discussions are ongoing

between the Local Planning Authority, English Heritage and

resulted in a patchwork of bricks and mortars in places.

Vegetation growth, large tree roots and the loss of

the owners to explore possible sources of funding.

© Royal Borough of Kensington and Chelsez

1 A	SITE NAME: 18, Queen's Gate Place SW7		Mid C19 terrace house with attached mews arch. Planning	
	DESIGNATION:	Listed Building grade II, CA	Permission and Listed Building Consent were granted in June 2008 for internal alterations and rear extensions.	
50	CONDITION:	Good	Works are almost complete to return the building back to a single residential property.	
TEL	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	F (F)		
IIIIIII II	OWNER TYPE:	Private		
	LIST ENTRY NUMBER:	1226193	Contact: Mark Butler (LPA) 020 7361 2465	

© Royal Borough of Kensington and

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric: solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	Church of St John the Baptist, Holland Road, Kensington W14	Church dating from 1874-1911 by J Brooks and JS Atkins architects. Coursed rubble walling with Bath stone
	DESIGNATION:	Listed Place of Worship grade II*, CA	dressings and slate pitched roofs. Early English style with large rose window at the west end and a highly decorated baptistery. Extensive repairs to the roofs, high level
	CONDITION:	Fair	masonry and rainwater goods are underway, grant-aide by English Heritage and the Heritage Lottery Fund.
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1080593	Contact: Tracey Craig 020 7973 3756
English Heritage			

	SITE NAME:	Church of St Michael and All Angels, Ladbroke Grove, Kensington W10	Designed by J and JS Edmeston, built 1871. Rhineland Romanesque style in London stock brick with terracotta, red Mansfield and Forest of Dean stone dressings. Clay
	DESIGNATION:	Listed Place of Worship grade II, CA	roof tiles. The roofs and rainwater disposal system are in poor condition. Some stone and brickwork is also in need of repair.
	CONDITION:	Poor	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
English Heritage	LIST ENTRY NUMBER:	1226579	Contact: Tracey Craig 020 7973 3756

	SITE NAME:	Church of St Augustine, Queen's Gate, Kensington SW7	Large church designed by William Butterfield in the Gothic style completed in 1876. Constructed in Gault brick with
	DESIGNATION:	Listed Place of Worship grade II*, CA	stone and red brick banding with areas of patterned diaper work to parapets and gables and decorative carved stone panels. Rich polychromatic decoration internally also. Re-
	CONDITION:	Poor	slating of the north slope of the nave and the north aisle was completed in 2011, grant-aided by English Heritage and the Heritage Lottery Fund. The south side is in need of
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	similar work along with brick and stone repairs particularly to the west elevation.
	LIST ENTRY NUMBER:	1226161	Contact: Tracey Craig 020 7973 3756
© English Heritage			, _

Designed by JP Aubyn, built in 1867. Fellowes Pryne added SITE NAME: St Clement's Church, Treadgold an east end range of rooms c1905. The interior was Street, Kensington WII reordered in 2007 separating off the chancel to form a DESIGNATION: Listed Place of Worship grade II community education suite. A Heritage Lottery Fund/English Heritage Repair Grant for Places of Worship CONDITION: Poor was offered in 2012 for re-roofing of the chancel, transepts PRIORITY CATEGORY: C (D) and the eastern end of the nave, including the fleche and repair of copings, associated rainwater goods and drainage. OWNER TYPE: Religious organisation Works are expected to start in 2014. The western end roof to the nave and the north and south aisle roofs are LIST ENTRY NUMBER: 1265169 also in poor condition.

© English Heritage

© En

Contact: Tracey Craig 020 7973 3756 SITE NAME: Commonwealth Institute W14 Garden for the Commonwealth Institute (1960-2). Outline design by architects Robert Matthew and Johnson Marshall, Registered Park and Garden refined and detailed by Dame Sylvia Crowe, showing a DESIGNATION: grade II, LB grade II*, CA strong unity between architecture and a designed landscape. The Institute has been vacant since 1995. Future CONDITION: Extensive significant problems use as the Design Museum is under construction. VULNERABILITY: High TREND: Declining NEW ENTRY ?: No OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1001393 Contact: Zosia Mellor 020 7973 3473

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014 / LONDON / KENSINGTON AND CHELSEA / KINGSTON UPON THAMES / LAMBETH

SITE NAME:	Kensal Green Cemetery W10		
DESIGNATION:	Conservation Area, 153 LBs, part in RPG grade I	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Mark Butler (LPA) 020 7361 2465

KINGSTON UPON THAMES			
	SITE NAME:	Kingston Telephone Exchange, Ashdown Road, Kingston upon Thames	Purpose built telephone exchange, built in 1907 and opened in 1908. Arts and Crafts style in asymmetrical plan. The building is located within an area identified for
	DESIGNATION:	Listed Building grade II	comprehensive redevelopment as set out in the K+20 Area Action Plan. Repairs have been undertaken following theft.
	CONDITION:	Fair	Re-cladding of the dormer window was also undertaken An application has been submitted for change of use.
	OCCUPANCY:	Vacant/not in use	
© English Heritage Archive	PRIORITY CATEGORY:	E (C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080059	Contact: Danalee Edmund 020 8547 5376



© English Heritage Archive

	SITE NAME:	Former Head Post Office, 42, Eden Street, Kingston upon Thames	Post office built in 1875. Three storeys in red brick with stone dressings. The reuse of the building has been delayed due to wider considerations relating to the Council's
	DESIGNATION:	Listed Building grade II	aspirations for town centre renewal as set out in the K+20 Area Action Plan. Repairs have been undertaken following
	CONDITION:	Fair	theft. An application has been submitted for change of use.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1080100	Contact: Danalee Edmund 020 8547 5376



© Royal Borough of Kingston upon Thames

	SITE NAME:	Lambeth uncovered coal store including tower and attached tunnels, Portsmouth Road, Surbiton	Uncovered coal store with tower and attached underground tunnels. Built 1851-1852 to the design of James Simpson in a Romanesque style for the Lambeth Waterworks. It has been vacant for many years. The Local
	DESIGNATION:	Listed Building grade II, CA	Authority has been in negotiations with the owner regarding works.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
N.	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1031864	Contact: Danalee Edmund 020 8547 5376

LAMBETH			
TAN IL	SITE NAME:	Beaufoy Institute, 39, Black Prince Road, Vauxhall SEI I	Educational building of 1907 (architect FA Powell). Brick and terracotta facade with free Baroque motifs. 1930
LI THE	DESIGNATION:	Listed Building grade II, CA	laboratory wing to the side and assembly hall at the rear. The building was vacated by the Lilian Baylis Secondary
	CONDITION:	Fair	School in 1999. Some conservation work has been carri- out in the building which has Planning Permission and List
	OCCUPANCY:	Vacant/not in use	Building Consent for community use.
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Religious organisation	
) English Heritage	LIST ENTRY NUMBER:	1358193	Contact: Elizabeth Martin (LPA) 020 7926 1213

© Eng

L

a stand and the

PRIORITY C	

D Е

А

- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented В implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM UA WHS
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- Unitary Authority World Heritage Site



1183436

LIST ENTRY NUMBER:

Granite plinth, wrought iron railings in scalloped pattern and three pairs of wrought iron gates, circa 1907. Currently in poor condition, suffering from deterioration and pigeon damage. Conservation work has been carried out in the building which has Planning Permission and Listed Building Consent for community use.

Contact: Elizabeth Martin (LPA) 020 7926 1213



-	SITE NAME:	136 and 138, Brixton Hill SW2	Early-mid C19. The windows are boarded up and
	DESIGNATION:	Listed Building grade II, CA	scaffolding has been erected. Change of use to residential was granted by the Local Authority in 2013. The building is
2	CONDITION:	Poor	still unoccupied.
	OCCUPANCY:	Vacant/not in use	
F	PRIORITY CATEGORY:	D (D)	
1	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1080539	Contact: Elizabeth Martin (LPA) 020 7926 1213

© London Borough of Lambeth

	SITE NAME:	Shelter, Denmark Hill, Ruskin Park SE5	Late C18 screen and flanking walls of a house that stood on the site. The wisteria has been cut back. Historical research
	DESIGNATION:	Listed Building grade II, RPG grade II	is also being undertaken. A strategy for the conservation and repair of the shelter is being discussed with the Local Authority and English Heritage and funding is being sought.
	CONDITION:	Poor	, , , , , , , , , , , , , , , , , , , ,
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	B (B)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1064982	Contact: Elizabeth Martin (LPA) 020 7926 1213

	SITE NAME:	Raleigh Hall, I and 3, Effra Road SW2	Substantial pair of villas built in 1824. The restoration of the building as a national Black Heritage Centre by the Black Cultural Archives, with a grant from the Heritage Lottery
	DESIGNATION:	Listed Building grade II, CA	Cultural Archives, with a grant from the Heritage Lottery Fund, is nearing completion. The centre is expected to
	CONDITION:	Fair	open in summer 2014.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
n Borough of Lambeth	LIST ENTRY NUMBER:	1358256	Contact: Elizabeth Martin (LPA) 020 7926 1213

© London



SITE NAME:	Dorchester Court, Herne Hill SE24	Eight blocks with 96 flats around a central landscaped courtyard, dating from 1933-4 by Leslie H Kemp and
DESIGNATION:	Listed Building grade II	Frederick E Tasker. There are structural problems with the balconies and general external deterioration. Discussions
CONDITION:	Poor	are ongoing regarding a comprehensive programme of refurbishment.
OCCUPANCY:	Occupied/in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1390780	Contact: Douglas Black (LPA) 020 7926 4065

© London Borough of Lambeth

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- NP
- Conservation Area Listed Building Local Planning Authority National Park RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site

© Lond

FOR SALE E-MIN HERSELEY HISSELEY	SITE NAME:	Off licence attached to the Old Red Lion public house, 44, Kennington Park Road SEI I	Tudorbethan style off-licence, built circa 1929. Damage includes a broken window pane. Planning Permission for redevelopment with facade retention was granted in 2004
	DESIGNATION:	Listed Building grade II	but has expired. Subsequent Planning and Listed Building Consent applications for the erection of a three storey
	CONDITION:	Poor	extension were refused by the Local Planning Authority 2013 and are subject of an appeal.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
ndon Borough of Lambeth	LIST ENTRY NUMBER:	1061361	Contact: Elizabeth Martin (LPA) 020 7926 1213

	SITE NAME:	Walls, railings and gates to Church of St Mary, Lambeth Road SEI	Mid-C19 ragstone walls and ironwork in a partial state of collapse. Urgent action is needed to secure their repair an restoration. A strategy for the site has been agreed, which
	DESIGNATION:	Listed Building grade II, CA	includes repair works to the walls, railings and gates. Funding options are being explored.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (A)	
-	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1358299	Contact: Elizabeth Martin (LPA) 020 7926 1213



	SITE NAME:	Reliance Arcade, Brixton Market, Market Row SW9	Covered market built 1923-5 by Andrews and Peascod, of brick and concrete construction. The market is a straight
	DESIGNATION:	Listed Building grade II, CA	narrow arcade running east-west from Electric Lane to Brixton Road. Fronting Electric Lane is a buff faience facade
	CONDITION:	Poor	with Art Deco Egyptian-style detailing, which has been poorly repaired in the past. The units within the arcade are
	OCCUPANCY:	Occupied/in use	mostly occupied, but the roof and windows are in
	PRIORITY CATEGORY:	C (New entry)	particularly poor condition. The Local Planning Authority is currently considering repair options and exploring possible
	OWNER TYPE:	Private	sources of funding.
	LIST ENTRY NUMBER:	39388	Contact: Ellie Cook (LPA) 020 7527 2801

© English Heritage



Former fire station in use as the South London Theatre for SITE NAME: Old Fire Station (South London many years, leased from the London Borough of Lambeth. Theatre), 2A, Norwood High There has been internal water damage and significant roof Street SE27 repairs are required. Funding has been secured from the DESIGNATION: Listed Building grade II, CA Heritage Lottery Fund and a Conservation Management Plan is being prepared. Planning and Listed Building CONDITION: Poor Consent applications were submitted to the Local Planning Authority in April 2014 for redevelopment of the site OCCUPANCY. Part occupied/part in use including new accessible theatre space, entrance foyer and PRIORITY CATEGORY: B (B) passenger lift. OWNER TYPE: Charity (non-heritage) LIST ENTRY NUMBER: 1263240 Contact: Elizabeth Martin (LPA) 020 7926 1213

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UÁ
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014 / LONDON / LAMBETH				
M	SITE NAME:	Augustus Ralli Mortuary Chapel, Norwood Road, West Norwood Memorial Park SE27	Doric temple mortuary chapel c1872, attributed to J Oldrid Scott, within the Greek Burial Ground and known as St Stephen's Chapel. White and gold coloured fossiliferous	
	DESIGNATION:	Listed Building grade II*, RPG grade II*, CA	limestone. The chapel is in poor condition due to subsidence, collapsed steps and internal water damage.	
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	C (New entry)		
© English Heritage	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1064989	Contact: Elizabeth Whitbourn 07889 808145	
	SITE NAME:	Catacombs beneath the Remembrance Garden, Norwood High Street, West Norwood Memorial Park SE27	Catacombs circa 1837; cemetery laid out circa 1837 by Sir William Tite. A temporary roof has been erected over the entrance to allow the structure to dry out before agreeing repairs. Funding options are being explored. An application to retain the temporary roof was approved in 2011 for five	
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	years. Moisture surveys are ongoing; levels appear to be stabilising/reducing. Discussions are ongoing regarding a	
	CONDITION:	Very bad	cemetery management plan and long-term future.	
ALMS STEP OV	OCCUPANCY:	N/A		
© English Heritage Archive	PRIORITY CATEGORY:	D (D)		
	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1263192	Contact: Elizabeth Martin (LPA) 020 7926 1213	
3				
	SITE NAME:	Letts Family Tomb, West Norwood Memorial Park, Norwood Road SE27	Pedestal monument and slab above a vault circa 1850. The tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal.	
	SITE NAME: DESIGNATION:	Norwood Memorial Park,	tomb began falling over early in 2013. As of May 2013 it	
		Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG	tomb began falling over early in 2013. As of May 2013 it	
	DESIGNATION:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA	tomb began falling over early in 2013. As of May 2013 it	
	DESIGNATION: CONDITION:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad	tomb began falling over early in 2013. As of May 2013 it	
© London Borough of Lambeth	DESIGNATION: CONDITION: OCCUPANCY:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A	tomb began falling over early in 2013. As of May 2013 it	
© London Borough of Lambeth	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A A (A)	tomb began falling over early in 2013. As of May 2013 it	
For the second secon	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A A (A) Unknown	tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. Conservation works, funded by the Berens family and	
Sector A control of Cambra	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A A (A) Unknown 1263199 Tomb of Alexander Berens, Norwood Road, West	tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture.	
Second	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A A (A) Unknown 1263199 Tomb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27 Listed Building grade II*, RPG	tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. Conservation works, funded by the Berens family and English Heritage, are underway and due for completion in	
Second control of the second control of t	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A A (A) Unknown 1263199 Tomb of Alexander Berens, Norwood Road, West Norwood Memorial Park SE27	tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. Conservation works, funded by the Berens family and English Heritage, are underway and due for completion in	
For the second secon	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: DESIGNATION: CONDITION:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A A (A) Unknown 1263199 Tomb of Alexander Berens, Norwood Road, West Norwood Road, West Norwood Memorial Park SE27 Listed Building grade II*, RPG grade II*, CA	tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. Conservation works, funded by the Berens family and English Heritage, are underway and due for completion in	
<image/>	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER: SITE NAME: SITE NAME: CONDITION: CONDITION:	Norwood Memorial Park, Norwood Road SE27 Listed Building grade II, RPG grade II*, CA Very bad N/A A (A) Unknown 1263199 Tomb of Alexander Berens, Norwood Road, West Norwood Road, West Norwood Alexander Berens, Norwood Road, West Norwood Road, West Norwood Road, West Norwood Road, West Norwood Road, West Norwood Road, West	tomb began falling over early in 2013. As of May 2013 it was approximately 15% from horizontal. Contact: Elizabeth Martin (LPA) 020 7926 1213 1858 chest tomb designed by EM Barry. Pink granite plinth, with marble superstructure and Portland stone sculpture. Conservation works, funded by the Berens family and English Heritage, are underway and due for completion in	

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

OWNER TYPE:

LIST ENTRY NUMBER:



Tomb of C Auffrey and E SITE NAME: O'Gorman, Norwood Road, West Norwood Memorial Park SE27 Listed Building grade II, RPG DESIGNATION: grade II*, CA CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: A (A)

Unknown

1250576

Pedestal tomb dating from 1893 with carved wreaths, faces and anchor. The tomb is leaning significantly.

Contact: Elizabeth Martin (LPA) 020 7926 1213

Chest tomb in Portland stone dating from 1873 with

Contact: Elizabeth Martin (LPA) 020 7926 1213

the side of the tomb.

carvings by Kelsey. There is cracking to the stone panels on

© English Heritage



No. No. of Street, Str	SITE NAME:	Tomb of Captain John Wimble, Norwood Road, West Norwood Memorial Park SE27	Chest tomb dating from 1851 with finely carved reliefs showing ships at sea. The stone ship surmounting the tomb is subject to movement.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	
	CONDITION:	Fair	
	OCCUPANCY: N/A		
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1065020	Contact: Elizabeth Martin (LPA) 020 7926 1213

© English Heritage



LIST ENTRY NUMBER:

1064988

© English Heritage



SITE NAME: Tomb of Elizabeth King, Statue of an angel mounted against a rough headstone over rough base, dating from 1922. In the style of the 1878 Oneto Monument by Giulio Monteverge in Genoa. The Norwood Road, West Norwood Memorial Park SE27 statue and headstone are leaning significantly. Listed Building grade II, RPG DESIGNATION: grade II*, CA CONDITION: Fair OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1250589 Contact: Elizabeth Martin (LPA) 020 7926 1213

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

ŬA

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

86

	SITE NAME:	Tomb of Ibbotson Family, Norwood Road, West Norwood Memorial Park SE27	Cross decorated with blue and buff ceramic tiles by Doulton of Lambeth on pedestal with grave slab dating from 1904. Tiles are missing and cementitious repairs are
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	causing further damage.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1250687	Contact: Elizabeth Martin (LPA) 020 7926 1213

	SITE NAME:	Tomb of Israel Thomas, Norwood Road, West Norwood Memorial Park SE27	Pedestal monument above a vault in the Egyptian Revival style, circa 1842. The tomb is overgrown with vegetation. The plinth is also broken and open to the elements.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1263196	Contact: Elizabeth Martin (LPA) 020 7926 1213

	SITE NAME:	Tomb of James Baldwin Brown, Norwood Road, West Norwood Memorial Park SE27	Celtic cross on pedestal faced in terracotta in Romanesque/Gothic style, dating from 1885. The tomb is leaning heavily, with side tablet disengaged and pinnacle tip
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	missing.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
Manus mala	PRIORITY CATEGORY:	A (A)	
© English Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1250584	Contact: Elizabeth Martin (LPA) 020 7926 1213



	OWNER TYPE:	Unknown			
	LIST ENTRY NUMBER:	1250584	Contact: Elizabeth Martin (LPA) 020 7926 1213		
Mar and a second second	SITE NAME:	Tomb of James Kershaw, Norwood Road, West Norwood Memorial Park SE27	Chest tomb dating from 1864 in Gothic style with elaborate carving. Designed by Alfred Waterhouse commemorating the MP James Kershaw. The structural		
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	ironwork is corroding, causing splitting of the stone. The railings are also being affected by movement to the plinth.		
	CONDITION:	Poor			
E.	OCCUPANCY:	N/A			
	PRIORITY CATEGORY:	C (C)			
	OWNER TYPE:	Unknown			
	LIST ENTRY NUMBER:	1263197	Contact: Elizabeth Martin (LPA) 020 7926 1213		

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

OWNER TYPE:



SITE NAME: Tomb of Johann and Annie Sparenborg and family, Norwood Road, West Norwood Memorial Park SE27 Listed Building grade II, RPG DESIGNATION: grade II*, CA CONDITION: Poor N/A OCCUPANCY: PRIORITY CATEGORY: C (C)

Unknown


Tomb in the style of a small Greek temple, dating from 1904. Movement is evident to the columns and base.

© English Heritage

© English Heritage



	LIST ENTRY NUMBER:	1250680	Contact: Elizabeth Martin (LPA) 020 7926 1213	
	SITE NAME:	Tomb of John and Virginia Schilizzi, Norwood Road, West Norwood Memorial Park SE27	Monument dating from 1908 within the Greek Burial Ground. Comprises a stepped granite base with sarcophagus surmounted by white marble female figure	
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	with flowing robes and veiled head. The figure is subject to movement and is now close to the edge of the sarcophagus.	
	CONDITION:	Fair		
	OCCUPANCY:	N/A		
and the second	PRIORITY CATEGORY:	A (A)		
	OWNER TYPE:	Unknown		
	LIST ENTRY NUMBER:	1064995	Contact: Elizabeth Martin (LPA) 020 7926 1213	
	SITE NAME:	Tomb of John Stevens,	Obelisk monument dating from 1861 by Anderson and	





SITE NAME: Tomb of Michael Emmanuel Pink granite table tomb dating from circa 1899 within the Rodocanachi and Family, Greek Burial Ground. Invasive vegetation is causing damage to the stepped base and the pillars surrounding the central Norwood Road, West Norwood Memorial Park SE21 pedestal. Listed Building grade II, RPG DESIGNATION: grade II*, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1064992 Contact: Elizabeth Martin (LPA) 020 7926 1213

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.


NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA LB
- LPA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument SM
- UA WHS
 - Unitary Authority World Heritage Site

© Englisł

	SITE NAME:	Tomb of Mrs Alice Moffatt, Norwood Road, West Norwood Memorial Park SE27	An arcaded chest tomb, circa 1847. The columns and to slab have been lost, leaving the structural rods exposed.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
ish Heritage	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1357922	Contact: Elizabeth Martin (LPA) 020 7926 1213

© English Heritage	SITE NAME:	Tomb of Thomas De La Garde Grissell, Norwood Road, West Norwood Memorial Park SE27	Chest tomb, circa 1847. Cast iron, stucco and pink granite. The plinth is broken and parts are exposed.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1065021	Contact: Elizabeth Martin (LPA) 020 7926 1213





	O MILEI (THTE:	UTIKHUWH	
	LIST ENTRY NUMBER:	1357900	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	Tomb of XE Balli Family, Norwood Road, West Norwood Memorial Park SE27	lonic temple mausoleum dating from the late C19 within the Greek Burial Ground. There is evidence of movement to the entablature and collapse of the steps.
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1120820	Contact: Elizabeth Martin (LPA) 020 7926 1213

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

D

Е

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA
- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site



© London Borough of Lambeth

	SITE NAME:	West Norwood fire station, 445, Norwood Road, Norwood SE27	Fire station with flats above. Built in 1914-15 by the London County Council Architects' Department. Planning Permission was granted for a new station elsewhere in the
	DESIGNATION:	Listed Building grade II	borough. The future use of the building is uncertain.
-11	CONDITION:	Good	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1392336	Contact: Elizabeth Martin (LPA) 020 7926 1213



© London Borough of Lambeth

S.F	SITE NAME:	Dyce Drinking Fountain, Streatham Green SW16	Drinking fountain, 1862 in Portland stone/red sandstone with a marble basin. There is water ingress and structural
1	DESIGNATION:	Listed Building grade II, CA	instability. A condition survey has been undertaken by the Local Authority and funding is being sought for repairs
	CONDITION:	Very bad	through Section 106 money.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	39 393	Contact: Elizabeth Martin (LPA) 020 7926 1213



© London Borough of Lambeth

Art Deco style cinema built in 1938 to the design of WR SITE NAME: ABC Cinema, Streatham High Road, Streatham SW16 Glen. The facade and double height foyer are of notable quality. Repair work is complete, but awaiting a new use. DESIGNATION: Listed Building grade II, CA CONDITION. Good OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: E (E) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1385902 Contact: Douglas Black (LPA) 020 7926 4065

	SITE NAME:	Monument to George Abell, St Leonard's churchyard, Streatham High Road, Streatham SW16	Chest tomb of circa 1826 commemorating George and Elizabeth Abell. The slab of Portland limestone with curved edged top has broken and the plinth is in a bad condition. The owner is being traced by the Local Authority so that a
	DESIGNATION:	Listed Building grade II, CA	scheme of repair and funding sources can be explored.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
© London Borough of Lambeth	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1323730	Contact: Elizabeth Martin (LPA) 020 7926 1213
Lin	SITE NAME:	Monument to Joseph Hay, St Leonards churchyard, Streatham High Road, Streatham SW16	Coade stone chest tomb in railed enclosure, dated 1808 by Coade and Sealy. The railings are broken and in a poor state of repair. The owner is being traced by the Local Authority so that a scheme of repair and funding sources
A TRACK	DESIGNATION:	Listed Building grade II, CA	can be explored.
	CONDITION:	Poor	

© English Heritage

PRIORITY CATEGORY: A (A) OWNER TYPE: Unknown LIST ENTRY NUMBER: 1323732

N/A

Contact: Elizabeth Martin (LPA) 020 7926 1213

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

OCCUPANCY:

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB
- LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA WHS Unitary Authority World Heritage Site
- 90

HERITAGE AT RISK 2014 / LONDON / LAMBETH

	SITE NAME:	Monument to Lt. Col. William Boyce, St Leonards churchyard, Streatham High Road, Streatham SW16	Chest tomb in railed enclosure, circa 1808 by Coade and Sealy. The Coade Stone is in an advanced state of decay. The owner is being traced by the Local Authority so that a scheme of repair and funding sources can be explored.
	DESIGNATION:	Listed Building grade II, CA	
© English Heritage	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	32373	Contact: Elizabeth Martin (LPA) 020 7926 1213
	SITE NAME:	335-337, Wandsworth Road	Pair of Regency houses, formerly undertaker's premises.
		SW8	The buildings are occupied and the freeholders are co-
	DESIGNATION:	Listed Building grade II, CA	operating with the Local Authority on a phased programme of repairs.
	CONDITION:	Fair	
	OCCUPANCY:	Occupied/in use	

© London Borough of Lambeth

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

OWNER TYPE-

D (D)


1081047

Commercial company



© London Borough of Lambeth

SITE NAME: Wall on the south side of St Early C19 stock brick walls, spalled with cracked brickwork. The finials are broken and missing. John with All Saints' churchyard, Waterloo Road SEI DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY. N/A PRIORITY CATEGORY: A (A) Religious organisation OWNER TYPE: LIST ENTRY NUMBER: 1068687 Contact: Elizabeth Martin (LPA) 020 7926 1213



	1 25 0
Contractory B	- North
1	
6.6.	
ALL	U Star
000	and the
· 《四》、 《四》、 《四》、 《四》、 《四》、 《四》、 《四》、 《四》、	

Redemptionist Fathers) problems with the stonework of the spire. The parish has Clapham Park Road, Clapham been awarded a grant under the Heritage Lottery Fund's SW4 Grants for Places of Worship scheme and repair works are Listed Place of Worship grade due to start in late 2014. DESIGNATION: II*, CA CONDITION: Very bad PRIORITY CATEGORY: B (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: Contact: Ian Harper 020 7973 3786 1358240

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but not yet implemented. D Е Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

use).

F

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Elizabeth Martin (LPA) 020 7926 1213

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM UÁ
- Unitary Authority World Heritage Site WHS
- 91

HERITAGE AT RISK 2014 / LONDON / LAMBETH / LEWISHAM

6	St Matthews Road, Brixton SW2 entablature and original pews internally. There are structural problems with the front and side elevation	Classical chapel built in 1828 of stock brick with stucco entablature and original pews internally. There are structural problems with the front and side elevations,	
	DESIGNATION:	Listed Place of Worship grade II	although no further movement has been noted in the past two years. The owners are assessing repair needs and
	CONDITION:	Poor	exploring funding options.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1357942	Contact: Tracey Craig 020 7973 3756
n Borough of Lambeth			

© London E ugh of L

LEWISHAM

	SITE NAME:	Beckenham Place, Foxgrove Road, Beckenham Place Park	Mansion built circa 1773, situated within former park land, now a golf course. Some emergency repairs were carried
DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:	Listed Building grade II*, CA	out in 2012 with a grant from English Heritage. A Heritage Lottery Fund bid is being prepared by the Local Authority
	Fair	for repairs to Beckenham Place and a strategy for its future use.	
	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1359317	Contact: Elizabeth Whitbourn 07889 808145

Stable block and garden walls to Beckenham Place, Beckenham

Listed Building grade II

Vacant/not in use

Local authority

Hill Road

Very bad

B (A)

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

D

Е

PRIORITY CATEGORY:

©	English	n Herit	age
---	---------	---------	-----

© English Heritage

© English Heritage

e	LIST ENTRY NUMBER:	1080027	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Louise House, Dartmouth Road, Lewisham SE23	Former Girls' Industrial Home, built in 1891, and surviving former laundry block to rear. Some essential repairs have
	DESIGNATION:	Listed Building grade II	been carried out. The building has just been passed to a new leaseholder.
	CONDITION:	Fair	
FIT	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
je	LIST ENTRY NUMBER:	1392722	Contact: Regina Jaszinski (LPA) 020 8314 9112



SITE NAME:	Holland and Company's Distillery, 14 and 16, Deptford Bridge SE8	Former offices of the Ho late C18. On the ground door and a carriage entr
DESIGNATION:	Listed Building grade II	stonework with dentil co small pediment over: "Est
CONDITION:	Poor	Distillery and Bonded Sto for a number of years and
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (New entry)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1080000	Contact: Regina Jaszinski

olland and Company's Distillery, floor at the east end is a double rance, framed in late CI9 ornice and an inscription in the stablished 1779. Holland and Co's ore". The building has been empty nd is deteriorating.

Late C18 stable block, which was severely damaged by fire in 2011. An updated survey is being prepared to ensure

that the remaining structure is stabilised and protected.

The Heritage Lottery Fund has awarded development

funding under the Parks for People programme for the wider park, which includes funds towards restoring the

stable block and a strategy for its future use.

i (LPA) 020 8314 9112

PRIORITY CATEGORIES

© London Borough of Lewisham

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no


obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / LEWISHAM



Tomb of Captain Limeburner, Lee Terrace, St Margaret's Old

Listed Building grade II, CA

Churchyard SEI3

Religious organisation

Very bad

N/A

A (A)



	SITE NAME:	Road SE13 pools constructed in 1884. Designed in the	Public baths, consisting of first and second class swimming pools constructed in 1884. Designed in the Gothic style by
	DESIGNATION: Listed Building grade II, CA currently unused, however urgent works to	Wilson and Son and Thomas Aldwinkle. The building is currently unused, however urgent works to the roof and	
171	CONDITION:	Poor	dry-rot are now complete and have stabilised the building. The Local Authority is investigating funding options for the
	OCCUPANCY:	Vacant/not in use	full repair of the building and options for its long term use.
and a	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	39 8	Contact: Regina Jaszinski (LPA) 020 8314 9112

A stone chest tomb from the middle of the CI8

angle balusters are displaced.

commemorates Captain Limeburner of the Royal Navy and

his wife. The south side has lost its central panel and the



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

© London Borough of Lewisham

© English Heritage



© English Heritage



	LIST ENTRY NUMBER:	1392002	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Fludyer, Lee Terrace, St Margaret's Old Churchyard SEI3	An elaborate Rococo tomb from 1769 in Portland stone and marble. Despite previous repairs, the monument is in very bad condition with widespread cracking, open joints
	DESIGNATION:	Listed Building grade II*, CA	from where vegetation grows and some collapse.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1391993	Contact: Elizabeth Whitbourn 07889 808145

	SITE NAME:	Tomb of Jeremiah Crutchley, Lee Terrace, St Margaret's Old Churchyard SE13	Elegant composition formed by a chest tomb over a smaller sarcophagus with lion's feet and elaborate carvin of garlanded cherub's head dating from 1752. The
	DESIGNATION:	Listed Building grade II, CA	monument has lost its railings, back plates and inscription panels and vegetation growth is causing further damage.
	CONDITION:	Poor	
•	OCCUPANCY:	N/A	
and the set of	PRIORITY CATEGORY:	A (A)	
Contractor Sec.	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1391998	Contact: Regina Jaszinski (LPA) 020 8314 9112

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building CA

- LB LPA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

ŬA Unitary Authority World Heritage Site WHS

	2014 /		LEWISHAM
TENI AGE A	. 2014 /	LONDON	LEVVISHAM

	SITE NAME:	Tomb of John Crutchley, Lee	Raised ledger stone from 1727. Ground subsidence has
and the second second		Terrace, St Margaret's Öld Churchyard SEI3	caused some sinking and movement to the ledger which is now set at an angle.
	DESIGNATION:	Listed Building grade II, CA	
TE	CONDITION:	Poor	
Lorde	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
San Martin Martin	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1392012	Contact: Regina Jaszinski (LPA) 020 8314 9112
AT AT	SITE NAME:	Tomb of John Hosier, Lee Terrace, St Margaret's Old Churchyard SEI3	Stone chest tomb erected in 1767. The tomb is badly damaged by vegetation growth through open joints.
C. A. AT	DESIGNATION:	Listed Building grade II, CA	
CONTRACTOR OF	CONDITION:	Poor	
North State	OCCUPANCY:	N/A	
and the second second	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1392013	Contact: Regina Jaszinski (LPA) 020 8314 9112
100 AM	SITE NAME:	Tomb of Lord Dacre, Lee	This composite urn monument to Lord Dacre dates from
		Terrace, St Margaret's Old Churchyard SEI3	1794. All the elements now lie disassembled on the ground. The monument needs urgent attention to avoid
	DESIGNATION:	Listed Building grade II, CA	further damage or loss of its components.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1392008	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Rev. Thomas Negus, Lee Terrace, St Margaret's Old Churchyard SEI3	Chest tomb from 1765, badly damaged from vegetation which has infiltrated through open joints and cracked the ledger slab. One angle baluster has been lost and there is a
	DESIGNATION:	Listed Building grade II, CA	risk of further collapse.
	CONDITION:	Very bad	
New 1 12	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1392011	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of Thomas Butler, Lee	Chest tomb from 1733. The panels on both sides and on
The second second		Terrace, St Margaret's Old Churchyard SEI3	one end have collapsed exposing brickwork and making th monument vulnerable to rapid deterioration.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1392003	Contact: Regina Jaszinski (LPA) 020 8314 9112
PRIORITY CATEGORIES			ABBREVIATIONS

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

94

HERITAGE AT RISK 2014 / LONDON / LEWISHAM



A composite monument formed by a mid/late C18 chest SITE NAME: Tomb of Tredway, Lee Terrace, tomb surmounted by an early CI9 sarcophagus. The end St Margaret's Old Churchyard SEI3 panel of the upper part is broken. DESIGNATION: Listed Building grade II, CA CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Religious organisation

© English Heritage

© English Heritage



	LIST ENTRY NUMBER:	1392010	Contact: Regina Jaszinski (LPA) 020 8314 9112
	SITE NAME:	Tomb of William Chivers, Lee Terrace, St Margaret's Old Churchyard SE13	Coade stone chest tomb from the late C18. The loss of the ledger slab has allowed a tree to take root inside the structure and to grow from its top. The tomb is in need of
	DESIGNATION:	Listed Building grade II, CA	attention to avoid serious structural damage.
	CONDITION:	Poor	
Lef-	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1392001	Contact: Regina Jaszinski (LPA) 020 8314 9112



© London Borough of Lewisham

Rileys (former Temperance SITE NAME: A temperance billiard hall built 1909-10, originally Billiard Hall), 233-241, incorporating a café, lounge and shops facing Lewisham High Street. Listed as a well-surviving example of an uncommon building type. The building has been empty for Lewisham High Street SEI3 DESIGNATION: Listed Building grade II the past two years. It has been gutted internally and is showing signs of neglect. There is water ingress on the CONDITION: Poor upper floor. Planning Permission was granted in 2012 for OCCUPANCY: Vacant/not in use the change of use to a place of worship. Planning and Listed Building Consent applications for associated changes and PRIORITY CATEGORY: C (New entry) extensions have been submitted. OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1392397 Contact: Regina Jaszinski (LPA) 020 8314 9112

	SITE NAME:	Hall attached to the rear of the Fellowship Inn Public House, Randlesdown Road, Bellingham SE6	Two-storey entertainment hall attached to the rear of the public house built in 1923-4 by FG Newnham for the brewery Barclay Perkins and Co. to serve the former London County Council's Bellingham Estate. The hall has
	DESIGNATION:	Listed Building grade II	been unoccupied for some time and many windows have been vandalised and parts of the hall have had fire and
	CONDITION:	Poor	water damage, although the roof structure appears sound. The condition is deteriorating. The Council is liaising with
CET DE	OCCUPANCY:	Vacant/not in use	the new owner.
	PRIORITY CATEGORY:	C (C)	
Ion Borough of Lewisham	OWNER TYPE:	Other not for profit group	
	LIST ENTRY NUMBER:	4 3050	Contact: Regina Jaszinski (LPA) 020 8314 9112

	SITE NAME:	Church of St Swithun, Hither Green Lane, Lewisham SEI3	This church was completed in 1893 to the designs of Ern Newton, with an extension in 1905. A small mission chur of 1884 survives at the east end. Built of red Wrotham brick, Bath stone is used for windows and dressings and
6.91	DESIGNATION:	Listed Place of Worship grade II	
11/	CONDITION:	Poor	Portland stone for copings, all under slated roofs. A programme of repairs to windows and masonry at the
	PRIORITY CATEGORY:	C (D)	west end was completed in early 2014, grant-aided by the
1	OWNER TYPE:	Religious organisation	Heritage Lottery Fund and English Heritage. There are still concerns about the structure of the east window,
	LIST ENTRY NUMBER:	1192516	rainwater goods and drainage to the north side.
			Contact: lan Harper 020 7973 3786

© English Heritage

© Londo

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA LB
- I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM ÍΙΑ
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014 / LONDON / LEWISHAM / MERTON

	SITE NAME:	Church of St Mary the Virgin, Lewisham High Street, Lewisham SE13	This Georgian church, completed to an unusual design in 1774 by George Gibson Jnr, replaced a Medieval church and incorporated the original tower. The chancel was
	DESIGNATION:	Listed Place of Worship grade II*, CA	added in 1882 by William Blomfield and then re-modelled in 1995-96. The whole church is raised over a crypt and the south side entrance protected by a neoclassical
	CONDITION:	Poor	portico. Despite repairs to the aisle parapet gutters, there has been continued leakage on the north and south sides,
	PRIORITY CATEGORY:	A (New entry)	which has put the fine Georgian woodwork at risk and
-4-1	OWNER TYPE:	Religious organisation	caused localised outbreaks of dry rot.
© English Heritage	LIST ENTRY NUMBER:	1193297	Contact: Ian Harper 020 7973 3786

SITE NAME:	Deptford High Street SE8		
DESIGNATION:	Conservation Area, 7 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Medium	CONTACT:	Philip Ashford (LPA) 020 8314 8533

MERTON

© London Borough of

	SITE NAME:	Garden wall enclosing four sides of playing field, Church Lane, Merton Park SW19	vegetation has been removed and a comprehensive survey and specification for repair has been carried out. The Local Authority has carried out rebuilding and repairs to a
	DESIGNATION:	Listed Building grade II	
王 李 伊	CONDITION:	Poor	section around the entrance gateway which had been dismantled for safety reasons.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	С (В)	
	OWNER TYPE:	Local authority	
of Merton	LIST ENTRY NUMBER:	1286387	Contact: Jill Tyndale (LPA) 020 8545 3839



© English Heritage



© English Heritage

M	SITE NAME:	Tomb of Thomas Stanley, Church Road, Mitcham, St Peter and St Paul's Churchyard	Table tomb over large podium erected in the early C18. The podium is severely damaged by vegetation. Discussions are ongoing with the church to progress
	DESIGNATION:	Listed Building grade II	towards repair.
The second	CONDITION:	Poor	
3	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
1 AL	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1080949	Contact: Jill Tyndale (LPA) 020 8545 3839

SITE NAME: Formerly part of the precinct wall to Merton Priory. Portion of wall on the west side Medieval flint and rubblestone. Sections of the wall are in of River Pickle between Merton High Street and Merantun Way, High Street, Wimbledon Village poor condition and have collapsed due to vegetation growth. The National Trust has progressed with significant clearance works and is now working with English Heritage, SW19 the Local Authority and Merton Local History Society to DESIGNATION: Listed Building grade II identify appropriate works to stabilise and repair the wall and create better public access. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1358009

Contact: Jill Tyndale (LPA) 020 8545 3839

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

use).

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- LB
- LPA NP
- Conservation Area Listed Building Local Planning Authority National Park RPG
- Registered Park and Garden Scheduled Monument SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / MERTON

	SITE NAME:	109-111, London Road, Mitcham	Pair of semi-detached lap boarded cottages. Partly boarded up and windows have been damaged. Suffering from severe
	DESIGNATION:	Listed Building grade II	neglect.
33	CONDITION:	Poor	
-2-21	OCCUPANCY:	Part occupied/part in use	
A 18	PRIORITY CATEGORY:	A (A)	
Constant of the	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1193387	Contact: Jill Tyndale (LPA) 020 8545 3839

© English Heritage

	SITE NAME:	Burn Bullock Public House, 315, London Road	Public house, formerly the Kings Head Hotel, with C16 interior and exterior features and C18 front. No longer
CALL DO DA	DESIGNATION:	Listed Building grade II	operating as a public house, but currently illegally occupied as a House in Multiple Occupation (HMO) with associated
Banks - Ext The	CONDITION: OCCUPANCY:	Poor	management problems and deterioration. Its use is subject to ongoing enforcement investigations.
		Part occupied/part in use	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
© London Borough of Merton	LIST ENTRY NUMBER:	9339	Contact: Caroline Kearey (LPA) 020 8545 3055

	SITE NAME:	Dovecote adjacent to pond to south east of The Canons, Madeira Road, Mitcham	The dovecote was built in 1511, being the oldest building in Merton. It is a square structure of chalk blocks and red brick quoins with a hipped tiled roof. There are nesting
	DESIGNATION:	Listed Building grade II	boxes on the inside of the walls. Repairs to the wall and roof were carried out following damage by vandals. It
	CONDITION:	Fair	remains very vulnerable to vandalism.
Care Care	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1080904	Contact: Jill Tyndale (LPA) 020 8545 3839

	SITE NAME:	Ravensbury Mill (North Wing), 245, Morden Road, Morden	C18 and C19 snuff mill powered by water. The North Wing is subject to a Section 106 agreement. There is slow
	DESIGNATION:	Listed Building grade II	progress towards resolving outstanding planning obligations, enabling a lease for the occupation of the North Wing by Wandle Industrial Museum. Discussions are ongoing to resolve these outstanding issues.
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	are ongoing to resolve these outstanding issues.
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Charity (non-heritage)	
© London Borough of Merton	LIST ENTRY NUMBER:	1080857	Contact: Jill Tyndale (LPA) 020 8545 3839
	SITE NAME:	Mausoleum of Sir Joseph William Bazalgette, St Mary's Road, St Mary's Churchyard, Wimbledon SW19	Portland stone mausoleum from the end of the C19. The ironwork is in very poor condition, gates are missing and there is evidence of anti-social activity. Discussions are ongoing with the church to progress towards repair.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	

© English Heritage

1080887	

Religious organisation

Contact: Jill Tyndale (LPA) 020 8545 3839

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

OCCUPANCY:

OWNER TYPE:

D

Е

use).

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

N/A

A (A)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

- UA Unitary Authority WHS World Heritage Site


HERITAGE AT RISK 2014 / LONDON / MERTON

© English Heri

© English Her

eritage	SITE NAME:	Tomb of Bankes, St Mary's Road, Wimbledon, St Mary's Churchyard SW19	Table tomb from the mid-C18 with inset panels and baluster profiled corners. Suffering from continued waste dump activity.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1080888	Contact: Jill Tyndale (LPA) 020 8545 3839

	SITE NAME:	Tomb of Elizabeth Johnson, St Mary's Road, Wimbledon, St Mary's Churchyard SW19	Table tomb, tapered to base, erected around 1800. The side panels have collapsed and vegetation has rooted in the monument and on its pedestal. Discussions are ongoing
	DESIGNATION:	Listed Building grade II	with the church to progress towards repair.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
eritage	LIST ENTRY NUMBER:	1193775	Contact: Jill Tyndale (LPA) 020 8545 3839



	SITE NAME:	Base of windmill at Mill House, Windmill Road	Brick with timber framing comprising base of hollow-post windmill. Located within the car park of the Windmill
	DESIGNATION:	Listed Building grade II	Public House with its timber superstructure exposed to the elements. The owners have undertaken works to preserve
	CONDITION:	Fair	the timbers which have now been reinstated. The structure remains at risk without a protective cover.
	OCCUPANCY:	N/A	remains at this without a protective cover.
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Commercial company	
ondon Borough of Merton	LIST ENTRY NUMBER:	1194005	Contact: Jill Tyndale (LPA) 020 8545 3839



© Lor

	SITE NAME:	Wall to rear of flats, 27-33 (consecutive), Windsor Avenue, Colliers Wood SW19	rubble stone, it is being damaged by vegetation growing o
123	DESIGNATION:	Listed Building grade II	of the wall structure.
	CONDITION:	Very bad	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
LEW & AL	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1080856	Contact: Jill Tyndale (LPA) 020 8545 3839

PRIORITY CATEGORIES

© English Heritage Archive

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

CA

LB LPA

- Conservation Area Listed Building Local Planning Authority National Park
- NP RPG
- Registered Park and Garden Scheduled Monument SM

UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / MERTON / NEWHAM

SITE NAME:	Morden Park Mound		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1002011
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Visitor erosion - extensive	NEW ENTRY?:	No
OWNER TYPE:	Local authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Merton Priory (site of), Merantun Way, Colliers	Wood SW19	
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001976
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Development requiring planning permission	NEW ENTRY?:	No
OWNER TYPE:	Local authority, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Bathgate Road SW19		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Caroline Kearey (LPA) 020 8545 3055
SITE NAME:	Drax Avenue		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	Poor	TREND:	Deteriorating
VULNERABILITY:	High	CONTACT:	Caroline Kearey (LPA) 020 8545 3055

NEWHAM



SITE NAME:	Abbey Mills Pumping Station (Station C) with associated Valve House, Abbey Lane E15	Pumping station 1910-14, white stock brick with terracotta and moulded stone dressings. Internal pumping floor sunk deep below ground level. There are no long term
DESIGNATION:	Listed Building grade II, CA	proposals for the reuse of the building at this stage.
CONDITION:	Poor	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1392550	Contact: Ben Hull (LPA) 020 3373 9574



and the second	SITE NAME:	Bases of pair of chimneystacks at Abbey Mills Pumping Station, Abbey Lane E15	Two chimney bases built in 1865 by Bazalgette. Elaborate pedimented porches to battered brick plinths crowned by stone bases of octagonal stacks (demolished). Thames
			Water is considering options with regards to works to the structures.
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
an	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1357995	Contact: Ben Hull (LPA) 020 3373 9574

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / NEWHAM

	SITE NAME:	Gate lodge at Abbey Mills Pumping Station, Abbey Lane E15	Lodge to pumping station, built circa 1865. There are no long-term proposals for reuse at this stage.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Utility	
© English Heritage	LIST ENTRY NUMBER:	1080982	Contact: Ben Hull (LPA) 020 3373 9574

	SITE NAME:	Offices (former Superintendent's House) at Abbey Mills Pumping Station, Abbey Lane E15	Former Superintendent's House to pumping station, built in 1865 by Bazalgette. Two storeys in yellow brick with stone dressings. Part of the building is used as offices. External repair and restoration works are now complete, however,
	DESIGNATION:	Listed Building grade II, CA	there are no long term proposals for re-use.
	CONDITION:	Fair	
	OCCUPANCY: Part occupied PRIORITY CATEGORY: E (E) OWNER TYPE: Utility	Part occupied/part in use	
		E (E)	
© English Heritage		Utility	
	LIST ENTRY NUMBER:	1080981	Contact: Ben Hull (LPA) 020 3373 9574

	SITE NAME:	Stores Building at Abbey Mills Pumping Station, Abbey Lane E15	Storage building circa 1865 by Sir Joseph Bazalgette. The building is currently vacant. There is significant structural movement and damage due to water ingress. Thames
MA	DESIGNATION:	Listed Building grade II, CA	Water is considering options for repair.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Utility	
© English Heritage	LIST ENTRY NUMBER:	1080980	Contact: Ben Hull (LPA) 020 3373 9574

	SITE NAME:	Ancillary Pump House at Abbey Mills Pumping Station (Station B), Abbey Road E15	Pump house circa 1868, probably by Bazalgette and Cooper, built in a similar style to the main pumping station. The building is being used temporarily as a storage facility.
C C DELENS	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Fair	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Utility	
© English Heritage	LIST ENTRY NUMBER:	1357994	Contact: Ben Hull (LPA) 020 3373 9574

	SITE NAME:	West Ham Pumping Station Engine House, Abbey Road EI5	Engine house, built in 1897. Contains original Lilleshall Company beam engines. The building is currently in use as
	DESIGNATION:	Listed Building grade II	a training facility. There are extensive unauthorised works to the interior. The owner is engaging with the Council and
	CONDITION:	Fair	English Heritage to regularise works and further develop the use of the building as a training facility, as part of an
	OCCUPANCY:	Part occupied/part in use	overall package of improvements to the site.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1357997	Contact: Ben Hull (LPA) 020 3373 9574

PRIORITY CATEGORIES

-

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / NEWHAM

	SITE NAME:	Technical College, Barking Road, East Ham E6	Technical College, 1903-04, by Cheers and Smith. Red brick with terracotta dressings and slated roof. The building
	DESIGNATION:	Listed Building grade II, CA	has good circulation spaces and an impressive main hall with large painted glass roof light. There is damage to the
	CONDITION:	Fair	elaborate plasterwork within the main hall caused by water ingress. Permission was granted for conversion as part of
	OCCUPANCY:	Vacant/not in use	an overall 'Civic Campus' proposal and change of use to Sixth Form Academy. Refurbishment works are nearing completion.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1080989	Contact: Ben Hull (LPA) 020 3373 9574

Coach and Horses public house, 100, High Street, Plaistow E13

Listed Building grade II

SITE NAME: DESIGNATION: CONDITION: Fair OCCUPANCY: PRIORITY CATEGORY F (F) OWNER TYPE:

SITE NAME:

DESIGNATION:

PRIORITY CATEGORY:

OWNER TYPE:

D (D) Utility

Impressive corner public house dating from 1900. The Dukes Head public house, 593, Barking Road, East Ham E6 ground floor and first floor function room are being used as a hall (for weddings and parties). The flats on the second Listed Building grade II floor are vacant. Restoration works were undertaken following fire damage. There is some unauthorised signage. Part occupied/part in use Commercial company LIST ENTRY NUMBER: 1392558 Contact: Ben Hull (LPA) 020 3373 9574

Three storey C18 public house, yellow brick with red brick

arches and reveals. There is extensive damage to the 1930s interior. Urgent repairs have been carried out following the

threat of a Section 54 notice. Pre-application discussions

© English Heritage

© English Heritage



have taken place and an application for reuse and CONDITION: Poor restoration is expected. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1080959 Contact: Ben Hull (LPA) 020 3373 9574 Chimney 1887/89, designed by Joseph Bazalgette, as part SITE NAME: Chimney to Beckton Sewage of the improvements to the northern outfall of the London Works, Jenkins Lane, Beckton drainage network. Listed Building Consent has been E6 granted for works to facilitate the Lee Tunnel and Beckton DESIGNATION: Listed Building grade II extension works. The chimney has been dismantled and is in storage, pending re-erection following completion of the CONDITION: Poor tunnelling works. OCCUPANCY: N/A

© English Heritage



	LIST ENTRY NUMBER:	1393160	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Earl of Derby public house, London Road, West Ham EI 3	Public house, circa 1880, two storeys with stucco dressings and a slate roof. An application for residential use and
2	DESIGNATION:	Listed Building grade II	repair/restoration has been approved. The building is now occupied but the conditions attached to the consent are
-	CONDITION:	Fair	not yet fully discharged.
a de te ca	OCCUPANCY:	Occupied/in use	
H-1	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1380223	Contact: Ben Hull (LPA) 020 3373 9574

© London Borough of Newham

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

D

Е

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG SM
- UÁ
- Unitary Authority World Heritage Site WHS

© English He

	SITE NAME:	Silo D, North Woolwich Road, Canning Town E16	Grain silo, 1920, built of reinforced concrete. The buildi appears neglected. There is vegetation growing from
	DESIGNATION:	Listed Building grade II	various areas of the structure and broken windows in many places. Discussions are taking place regarding possible
	CONDITION:	Fair	development as part of a wider scheme in the area.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	E (C)	
	OWNER TYPE:	Unknown	
© English Heritage	LIST ENTRY NUMBER:	1245030	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	North Woolwich Station including turntable and platform lamp standards, Pier Road,	Former railway station, 1847. There are broken windows at first floor level on the front elevation. Vegetation is growing from the stonework and brickwork and the

		North Woolwich EI6	platform is overgrown. The site is unsecured.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
Heritage	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1376229	Contact: Ben Hull (LPA) 020 3373 9574



© English Heritage	LIST ENTRY NUMBER:	1357990	Contact: Ben Hull (LPA) 020 3373 9574
	SITE NAME:	Central buffet at Custom House, Royal Albert Dock E16	Restaurant, built in 1883 to the design of Vigers and Wagstaff in a free classical style. Now owned by the
	DESIGNATION:	Listed Building grade II	London Development Agency and part of Royals Business Park. Security has been improved and some emergency
	CONDITION:	Good	repairs undertaken. Discussions are taking place regarding the potential refurbishment and re-use of the building as
	OCCUPANCY:	Vacant/not in use	part of wider developments in the area. Listed Building
	PRIORITY CATEGORY:	E (E)	Consent applications have been submitted.
	OWNER TYPE:	Government or agency	
© English Heritage Archive	LIST ENTRY NUMBER:	1380201	Contact: Ben Hull (LPA) 020 3373 9574

withdrawn.

SITE NAME: Central offices at Custom Offices, built in 1883 to the design of Vigers and Wagstaffe in the manner of Norman Shaw. Now owned by the House, Royal Albert Dock E16 London Development Agency and part of Royals Business DESIGNATION: Listed Building grade II Park. Security has been improved and some emergency repairs undertaken. Discussions are taking place regarding CONDITION: Good the potential refurbishment and re-use of the building as part of wider developments in the area. Listed Building OCCUPANCY: Vacant/not in use Consent applications have been submitted. PRIORITY CATEGORY: E (E) OWNER TYPE: Government or agency LIST ENTRY NUMBER: 1376228 Contact: Ben Hull (LPA) 020 3373 9574 © English Heritage Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Impressive Edwardian public house from 1902, on a prominent corner site by Henry Poston and WE Trent.

to a banqueting facility with residential use above was

The building is empty and boarded up, with no future use identified. An application for change of use and conversion

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / NEWHAM

	SITE NAME:	Tide Mill (known as the House Mill), Three Mill Lane E3	Tide Mill dating from 1776 and last used in 1941. Much of the building fabric has been repaired, but work is now
	DESIGNATION:	Listed Building grade I, CA	needed to the undershot water wheels and surviving machinery. A Stage I Heritage Lottery Fund grant was
	CONDITION:	Fair	awarded to the River Lea Tidal Mill Trust and the development work is nearing completion. The scope of Stage 2 bid will be refined before submission to the
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	Heritage Lottery Fund. Works will include the repair of machinery, interpretation throughout the building and
	OWNER TYPE:	Charity (heritage)	improvements to education and community facilities.
© English Heritage	LIST ENTRY NUMBER:	1080970	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Spotted Dog public house, 212, Upton Lane E7	Weatherboarded C16 timber-framed public house. The Local Authority has carried out works to secure the
	DESIGNATION:	Listed Building grade II	property and make it weathertight following non compliance with an Urgent Works Notice, part funded by
THE SPOTTED	CONDITION:	Very bad	English Heritage. A Repairs Notice was subsequently served and urgent repairs carried out. Discussions are
	OCCUPANCY:	Vacant/not in use	taking place to explore acquisition by a charitable trust for
	PRIORITY CATEGORY:	A (A)	development as a community enterprise.
	OWNER TYPE:	Private	
© English Heritage	LIST ENTRY NUMBER:	1191297	Contact: Ben Hull (LPA) 020 3373 9574

XXN	SITE NAME:	Church of St Barnabas, Browning Boad, East Ham EL2	Simple Perpendicular Gothic style church with triple gable
	LIST ENTRY NUMBER:	1080974	Contact: Ben Hull (LPA) 020 3373 9574
	OWNER TYPE:	Local authority	
	PRIORITY CATEGORY:	C (C)	
	OCCUPANCY:	Vacant/not in use	
	CONDITION:	Very bad	early 2014.
	DESIGNATION:	Listed Building grade II, CA	Newham Council has prepared a conservation plan and is considering options. The building was damaged by fire in
and the second s	SITE NAME:	West Ham Court House, West Ham Lane E15	Court house built in 1884 to the design of Lewis Angell. Urgent works were carried out to prevent water ingress.

DESIGNAT CONDITION PRIORITY	SITE NAME:	Church of St Barnabas, Browning Road, East Ham E12	front, without tower or chancel arch, built in 1900-09 to
	DESIGNATION:	Listed Place of Worship grade II	the design of Bucknell and Comper in soft red brick with stone dressings. There are problems with roofing and brick
	CONDITION:	Poor	decay. The second phase of Heritage Lottery Fund/English Heritage grant-aided repairs are due for completion in
	PRIORITY CATEGORY:	C (D)	2014. Funding for a third phase of repairs is currently being
	OWNER TYPE:	Religious organisation	sought.
	LIST ENTRY NUMBER:	1293562	Contact: Ian Harper 020 7973 3786

© English Heritage

SITE NAME:	Sugar House Lane, Stratford E15		
DESIGNATION:	Conservation Area	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Improving
VULNERABILITY:	Low	CONTACT:	Ben Hull (LPA) 020 3373 9574
SITE NAME:	Thurse Mills, Course Coursel/David FLE		
	Three Mills, Stratford/Bow E15		
DESIGNATION:	Conservation Area, 12 LBs	NEW ENTRY?:	No
DESIGNATION: CONDITION:		NEW ENTRY?: TREND:	No Improving significantly
	Conservation Area, 12 LBs		

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В

implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lidentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

REDBRIDGE

SITE NAME:	Dr Johnson public house, Longwood Gardens, Ilford	Moderne-style public house 1937-8 by H Reginald Ross. Built to serve the large new estates in Barkingside. The
DESIGNATION:	Listed Building grade II	building has been vacant and boarded up since 2010. The roof is in a poor state of repair and in 2011 the interior was
CONDITION:	Poor	seriously damaged following flooding. English Heritage and the Local Authority are in discussion with the owners
OCCUPANCY:	Vacant/not in use	regarding acceptable uses and associated alterations.
PRIORITY CATEGORY:	A (A)	
OWNER TYPE:	Commercial company	
LIST ENTRY NUMBER:	1392792	Contact: Mike Brown 020 8708 2747
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:Listed Building grade IICONDITION:PoorOCCUPANCY:Vacant/not in usePRIORITY CATEGORY:A (A)OWNER TYPE:Commercial company



© London Borough of Redbridge

	SITE NAME:	Garden Temple in garden of Temple House, 14, The Avenue, Wanstead E11	Garden temple, 1730-40, with lonic pedimented portico. Roof, wall and column repairs have been completed, grant- aided by English Heritage. However, further repairs are
	DESIGNATION:	Listed Building grade II*, CA	required.
	CONDITION:	Poor	
No. of Lot	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (D)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357974	Contact: Verena McCaig 020 7973 3718

	SITE NAME:	Wanstead Park EI2	Remains of an important landscape dating from the late
See The se	DESIGNATION:	Registered Park and Garden grade II*, 6 LBs, part in CA	C17 to early C19, further developed in the late C19 by the City of London as a public park. The central area was converted to a private golf course in the early C20.
A CONTRACT OF	CONDITION:	Extensive significant problems	Features of the historic designed landscape survive but are in poor condition. The City of London commissioned a
NORE Y	VULNERABILITY:	High	study of the designed cascade lake system in late 2013,
	TREND:	Declining	which identifies options to achieve water balance. A steering group of stakeholders meets regularly to promote
and the second second	NEW ENTRY?:	No	positive conservation management and is currently exploring possible sources of funding.
© English Heritage	OWNER TYPE:	Local authority, multiple owners	exploring possible sources of landing.
	LIST ENTRY NUMBER:	1000194	Contact: Zosia Mellor 020 7973 3473

SITE NAME:	Mayfield, Ilford		
DESIGNATION:	Conservation Area	NEW ENTRY?:	Yes
CONDITION:	NDITION: Very bad		Improving
VULNERABILITY:	Low	CONTACT:	Mike Brown (LPA) 020 8708 2747
SITE NAME:	Wanstead Park EI I		
DESIGNATION:	Conservation Area, 8 LBs, part in RPG grade II*	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Mike Brown (LPA) 020 8708 2747
SITE NAME:	Woodford Bridge, Bridge		
DESIGNATION:	Conservation Area, 8 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating
CONDITION: VULNERABILITY:	Very bad Medium	TREND: CONTACT:	Deteriorating Mike Brown (LPA) 020 8708 2747

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

RICHMOND UPON THAMES Stone loggia of nine Doric columns and shellwork grotto, SITE NAME Loggia and grotto in grounds of Thames Eyot, Cross Deep, probably C18. Situated in the grounds of 1930s flats on the bank of the Thames. The roof has suffered partial collapse Twickenham and structural movement causing distortion to the DESIGNATION: Listed Building grade II*, CA colonnade. An options appraisal was completed in 2011, but no further progress has been made due to a lack of CONDITION: Very bad resources. Monitoring of the loggia and grotto is ongoing. OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Commercial company © English Heritage LIST ENTRY NUMBER: 1080812 Contact: Elizabeth Whitbourn 07889 808145



© English Heritage

	SITE NAME:	Pope's Grotto in grounds of St James Independent School for Boys, Cross Deep (east side), Twickenham	Grotto with rusticated arched entrance facing the river. Long passage with two 'chapels', one on either side of the entrance. The grotto is seen as the 'locus classicus' of English C18 garden history. The basic structural condition
	DESIGNATION:	Listed Building grade II*	appears sound, but much of the decorative lining is loose or missing. The owners are working with the Environment
	CONDITION:	Fair	Trust for Richmond upon Thames, Pope's Grotto Preservation Trust, English Heritage and Radnor House
	OCCUPANCY:	N/A	School to achieve a solution.
AN CONTRACT	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Educational (independent)	
	LIST ENTRY NUMBER:	1192178	Contact: Elizabeth Whitbourn 07889 808145



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:



LIST ENTRY NUMBER: 1193477 Contact: Elizabeth Whitbourn 07889 808145 SITE NAME: Timber-framed boathouse built in 1917 by Augustine Alban Boat house No. 5 (easternmost Hamilton Scott for the Thorneycroft firm to build torpedo 13 bays), Platts Eyot, Hampton boats for the Admiralty. A full measured survey of the DESIGNATION: Listed Building grade II, CA remaining structure has been completed. Monitoring of the boat house is ongoing. CONDITION: Very bad OCCUPANCY: Part occupied/part in use PRIORITY CATEGORY: A (A) OWNER TYPE: Commercial company

Garrick's Villa, Hampton Court

Listed Building grade I, RPG

Road, Hampton

Vacant/not in use

grade II, CA

Fair

F (F)

Private

1254429

© English Heritage Archive



SITE NAME:	Wick House, Richmond Hill, Richmond	Designed by Sir William Chambers c1772 for Sir Joshua Reynolds. Permission was granted in recent years for
DESIGNATION:	Listed Building grade II, CA	conversion from a nurses' home to a single residence once again. However, after internal works were carried out,
CONDITION:	Poor	construction work ceased and the building was sold to a new owner. A large crack has since appeared on the flank
OCCUPANCY:	Vacant/not in use	wall of the building indicating significant structural
PRIORITY CATEGORY:	C (C)	problems. The Local Authority has been in contact with the owner and is pursuing formal enforcement action.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1263475	Contact: Nicolette Duckham (LPA) 020 8891 7335

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

D

Е

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Rachel Shortman (LPA) 020 8891 7941

ABBF	ABBREVIATIONS			
CA LB	Conservation Area Listed Building			
	Local Planning Auth			

Villa by Robert Adam built in 1756 and remodelled in 1773.

Converted into nine apartments in the 1960s and severely damaged by fire in 2008. External works are complete and

the internal fit-out is now progressing.

- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014 / LONDON / RICHMOND UPON THAMES

EE E	
	al.

SITE NAME:	Doughty House, 142, Richmond Hill, Richmond	C18 house with C19 alterations made by the Cook family. Planning Permission and Listed Building Consent have been			
DESIGNATION:	Listed Building grade II, CA	granted to retain the main property as a single dwelling and to convert the gallery to ancillary accommodation, along			
CONDITION:	Poor	with re-instating Doughty Cottage as the link between the house and gallery. No works have taken place and the			
OCCUPANCY:	Vacant/not in use	building is vacant.			
PRIORITY CATEGORY:	C (New entry)				
OWNER TYPE:	Private				
LIST ENTRY NUMBER:	1249955	Contact: Nicolette Duckham (LPA) 020 8891 7335			

© London Borough of Richmond on Thames



-	SITE NAME:	The Gallery at Doughty House, 142, Richmond Hill, Richmond	Gallery built in 1880 for Sir Francis Cook, extended in 1915 by Brewer Smith, comprising eleven bays. Giant Ionic order
	DESIGNATION:	Listed Building grade II, CA	with balustrade, the lower order containing door and window openings between Doric pilasters. Works are
	CONDITION:	Poor	required to the roof, balustrade and rainwater goods. Planning Permission and Listed Building Consent have been
22	OCCUPANCY:	CY: Vacant/not in use	granted to retain the main property as a single dwelling and
177	PRIORITY CATEGORY:	D (D)	to convert the gallery to ancillary accommodation, along with re-instating Doughty Cottage as the link between the
	OWNER TYPE:	Private	house and gallery. No works have taken place and the building is vacant.
	LIST ENTRY NUMBER:	1387232	Contact: Nicolette Duckham (LPA) 020 8891 7335



Thames

Begun in 1860 by Decimus Burton and not completed until Temperate House, Royal SITE NAME: 1897-9. The Temperate House comprises three Botanical Gardens, Kew communicating glasshouses in iron, glass and stucco. Listed Building grade I, RPG grade I, CA, WHS Heritage Lottery Funding has been secured and Planning DESIGNATION: Permission and Listed Building Consent granted for major repair and refurbishment works, along with the former CONDITION: Poor Evolution House. Handover to a contractor is expected in OCCUPANCY: July 2014. Occupied/in use PRIORITY CATEGORY: D (D) OWNER TYPE: Charity (heritage) LIST ENTRY NUMBER: 1262590 Contact: Elizabeth Whitbourn 07889 808145

Sandycombe Lodge, 40,

Listed Building grade II*, CA

Sandycoombe Road,

Vacant/not in use

Twickenham

Fair

C (C)

LIST ENTRY NUMBER:

Unknown

1262429



© London Borough of Richmond on Thames



© London Borough of Richmond on

Thames

Air raid shelter, probably built in 1938 to serve St Air Raid Shelter, St Leonard's SITE NAME: Leonard's Court which was built in 1934-38 by local Court, St Leonard's Road, East builder Mr FG Fox. Designed to hold 48 people; at the Sheen SW14 time there were 83 flats. Richmond Environment Trust has DESIGNATION: Listed Building grade II commissioned a structural survey and funding is being sought for repairs and use as an educational resource. CONDITION: Poor OCCUPANCY. N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Private LIST ENTRY NUMBER: 1395422 Contact: Nicolette Duckham (LPA) 020 8891 7335

building.

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good

D

Е

repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Early C19, built for and to the design of JMW Turner. Main

central bay with gable roof and wide eaves, with lower set

being sought as work progresses towards a new use for the

back flanking wings. The building is vacant but used for

dwelling to a centre dedicated to the life and work of Turner. Heritage Lottery and other sources of funding are

Contact: Elizabeth Whitbourn 07889 808145

tours at present. The intention is to convert the former

- Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

	SITE NAME:	The Kilmorey Mausoleum, including enclosure wall, railings and gate, St Margaret's Road, Isleworth	Mausoleum dating from 1854 by Henry Kendall junior for Francis Needham, 2nd Earl of Kilmorey, brought to its present location in 1868. The surrounding railings are in poor condition. Funding has been confirmed and conservation works are due to start summer 2014.	
	DESIGNATION:	Listed Building grade II*, CA	conservation wo	rks are due to start summer 2014.
	CONDITION:	Poor		
	OCCUPANCY:	N/A		
Addaugt	PRIORITY CATEGORY:	D (C)		
🕽 English Heritage	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1240128	Contact: Elizabet	th Whitbourn 07889 808145
	SITE NAME:	Church of St Michael and St George, Wilcox Road	Perpendicular an	prick with stone dressings on the cusp of Id Gothic Revival styles. Designed by JS
	DESIGNATION:	Listed Building grade II		in 1913. Currently (summer 2014) not in worship and in a poor but stable
	CONDITION:	Poor	condition.	
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	C (New entry)		
	OWNER TYPE:	Religious organisation		
D English Heritage	LIST ENTRY NUMBER:	1393730	Contact: Rachel Shortman (LPA) 020 8891 7941	
SITE NAME:	Platt's Eyot			
	Platt's Eyot Conservation Are	ea, 4 LBs	NEW ENTRY?:	No
DESIGNATION:		ea, 4 LBs	NEW ENTRY?: TREND:	No Deteriorating significantly
SITE NAME: DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are	ea, 4 LBs		
DESIGNATION: CONDITION:	Conservation Are Poor	ea, 4 LBs	TREND:	Deteriorating significantly Nicolette Duckham (LPA) 020 8891
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor	ea, 4 LBs Number 8, Addington Square and attached railings SE5	TREND: CONTACT: One of a pair of Conservation Ar	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squar rea. It has broken windows and widespre
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium	Number 8, Addington Square	TREND: CONTACT: One of a pair of	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squar rea. It has broken windows and widespre
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium	Number 8, Addington Square and attached railings SE5	TREND: CONTACT: One of a pair of Conservation Ar	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium SITE NAME: DESIGNATION:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA	TREND: CONTACT: One of a pair of Conservation Ar	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium SITE NAME: DESIGNATION: CONDITION:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA Poor	TREND: CONTACT: One of a pair of Conservation Ar	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium SITE NAME: DESIGNATION: CONDITION: OCCUPANCY:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA Poor Occupied/in use	TREND: CONTACT: One of a pair of Conservation Ar	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre
DESIGNATION: CONDITION: VULNERABILITY: SOUTHWARK	Conservation Are Poor Medium SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA Poor Occupied/in use C (New entry)	TREND: CONTACT: One of a pair of Conservation Ar external cracking	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre
DESIGNATION: CONDITION: VULNERABILITY: SOUTHVVARK	Conservation Are Poor Medium SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA Poor Occupied/in use C (New entry) Private	TREND: CONTACT: One of a pair of Conservation Ar external cracking Contact: Tracy C	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squar rea. It has broken windows and widespre 3. Chapman (LPA) 020 7525 2289 ne Licensed Victuallers' Almshouse largely to c1830-40. Sections of the
DESIGNATION: CONDITION: VULNERABILITY: SOUTHWARK	Conservation Are Poor Medium SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA Poor Occupied/in use C (New entry) Private 1376521 Railings and Gates to Caroline	TREND: CONTACT: One of a pair of Conservation Ar external cracking Contact: Tracy O Iron railings to th complex, dating ironwork are in a	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre 3. Chapman (LPA) 020 7525 2289 he Licensed Victuallers' Almshouse largely to c1830-40. Sections of the a poor state of repair with some element
DESIGNATION: CONDITION: VULNERABILITY: SOUTHWARK	Conservation Are Poor Medium SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: LIST ENTRY NUMBER:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA Poor Occupied/in use C (New entry) Private 1376521 Railings and Gates to Caroline Gardens, Asylum Road SE15	TREND: CONTACT: One of a pair of Conservation Ar external cracking Contact: Tracy C	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre 3. Chapman (LPA) 020 7525 2289 the Licensed Victuallers' Almshouse largely to c1830-40. Sections of the a poor state of repair with some element
DESIGNATION: CONDITION: VULNERABILITY:	Conservation Are Poor Medium SITE NAME: DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE: UIST ENTRY NUMBER: SITE NAME: DESIGNATION:	Number 8, Addington Square and attached railings SE5 Listed Building grade II, CA Poor Occupied/in use C (New entry) Private 1376521 Railings and Gates to Caroline Gardens, Asylum Road SE15 Listed Building grade II, CA	TREND: CONTACT: One of a pair of Conservation Ar external cracking Contact: Tracy O Iron railings to th complex, dating ironwork are in a	Deteriorating significantly Nicolette Duckham (LPA) 020 8891 7335 early C19 houses in the Addington Squa rea. It has broken windows and widespre 3. Chapman (LPA) 020 7525 2289 the Licensed Victuallers' Almshouse largely to c1830-40. Sections of the a poor state of repair with some element

© English Heritage

-	
CONDITION: Poor	
OCCUPANCY: N/A	
PRIORITY CATEGORY: C (New entry)	
OWNER TYPE: Local authority	
LIST ENTRY NUMBER: 1376543 Contact: Tracy Chapman (LPA) 020 7525 2289	


- PRIORITY CATEGORIES
- A Immediate risk of further rapid deterioration or loss of fabric: no
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no
- obvious new user (applicable only to buildings capable of beneficial use)

D

Е

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA
- Unitary Authority World Heritage Site WHS

108

© English Heritage

	SITE NAME:	Lodge, Camberwell New Cemetery, Brenchley Gardens, Honor Oak SE23	Former cemetery lodge (1928-29) designed by Sir Aston Webb. The building is vacant and its condition deteriorating. Planning Permission has been granted for the
	DESIGNATION:	Listed Building grade II	London Borough of Southwark to bring the building back into use in connection with cemetery management. The
	CONDITION:	Fair	works are imminent.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Local authority	
© London Borough of Southwark	LIST ENTRY NUMBER:	1378387	Contact: Tracy Chapman (LPA) 020 7525 2289

ge	SITE NAME:	Gate piers and railings to the churchyard of the former Church of St John, Fair Street SEI	arly to mid C19 railings, gates and gate piers. Wrought on railings and Portland stone piers and plinth. They are a bod example of late Georgian ironwork but have started o corrode. Proposals for repair have stalled.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1393615	Contact: Tracy Chapman (LPA) 020 7525 2289

	SITE NAME:	Monument to Charles Waters, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1910 to Charles Waters. Marble group of a seated woman with book/bible in her lap embracing a small child on a battered plinth. Due to ground subsidence there is a concern over its structural stability. The
10 2 2 4 m	DESIGNATION:	Listed Building grade II	monument is fenced off pending an assessment by a structural engineer.
	CONDITION:	Poor	-
North Land	OCCUPANCY:	N/A	
mar 2	PRIORITY CATEGORY:	A (A)	
© London Borough of Southwark	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1385530	Contact: Tracy Chapman (LPA) 020 7525 2289



SITE NAME:	Monument to Rebekah Horniman, Camberwell Old Cemetery, Forest Hill Road, Forest Hill SE23	Monument circa 1895 to Rebekah, wife of FS Hornim prominent bronze tablet depicting a figure of an angel missing, presumed stolen.	
DESIGNATION:	Listed Building grade II		
CONDITION:	Poor		
OCCUPANCY:	N/A		
PRIORITY CATEGORY:	C (A)		
OWNER TYPE:	Private		
LIST ENTRY NUMBER:	1385533	Contact: Tracy Chapman (LPA) 020 7525 2289	

© English Heritage



	SITE NAME:	38, Glengall Road, Peckham SE15	Semi-detached house dating from 1843-1845 by the Brighton architect Amon Henry Wilds. The lonic entrance porch is in poor condition. Discussions have been held	
	DESIGNATION:	Listed Building grade II, CA	porch is in poor condition. Discussions have been held regarding the repair of the building.	
	CONDITION:	Poor		
	OCCUPANCY:	Part occupied/part in use		
	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Private		
Ithwark	LIST ENTRY NUMBER:	1385563	Contact: Tracy Chapman (LPA) 020 7525 2289	

PRIORITY CATEGORIES

© London Borough of South

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	55, Great Suffolk Street SEI	Unaltered mid C19 warehouse. The building is in a poor
	DESIGNATION:	Listed Building grade II	condition having been vacant for a number of years.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (New entry)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1393123	Contact: Tracy Chapman (LPA) 020 7525 2289
ritago			

© English Heritage

	SITE NAME:	133 Kennington Park Road SEI I	Late C18 terrace house. Planning Permission and Listed
	DESIGNATION:	Listed Building grade II, CA	Building Consent were granted in May 2008 for conversion to four flats, but not implemented. These consents have
	CONDITION:	Fair	now expired and have not been renewed. The building is partially occupied but no repairs have been undertaken and
	OCCUPANCY:	Part occupied/part in use	the building continues to decline.
~	PRIORITY CATEGORY:	C (D)	
R	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	385634	Contact: Tracy Chapman (LPA) 020 7525 2289

© English Heritage



© English Heritage

	SITE NAME:	Nunhead Cemetery (All Saints) SE15	An important public cemetery designed by J Bunstone Bunning and consecrated in 1840. The layout of the
	DESIGNATION:	Registered Park and Garden grade II*, 13 LBs, CA	cemetery skillfully exploits the undulating topography to create picturesque effects and vistas. Despite the repair of some elements in 1998, grant-aided by the Heritage
	CONDITION:	Generally unsatisfactory with major localised problems	Lottery Fund, the landscape is in need of further management. Many of the tombs are also in poor condition and the East Lodge is a building at risk.
	VULNERABILITY:	High	
	TREND:	Declining	
	NEW ENTRY?:	No	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1000824	Contact: Zosia Mellor 020 7973 3473

A STATIC OF	SITE NAME:	East Lodge to Nunhead Cemetery, Linden Grove SE15	One of a pair of gate lodges, 1840, by James Bunstone Bunning, adjacent to the main entrance gates. The lodge is
	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	in a ruinous condition, but stabilised. English Heritage has previously awarded a development grant towards surveys. The Friends of Nunhead Cemetery are exploring options
(一)(在1995年)	CONDITION:	Very bad	to repair the building.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
© English Heritage	LIST ENTRY NUMBER:	1385647	Contact: Tracy Chapman (LPA) 020 7525 2289

	E.	

	SITE NAME:	Tomb of Maria Proom, Linden Grove, Nunhead Cemetery SE15	Visually prominent monument from 1872 in pink and grey granite and Carrara marble. Inspired by Catholic monuments from the continent, the structure presents a
R	DESIGNATION:	Listed Building grade II, RPG grade II*, CA	praying figure carried on a tall column and plinth and an angel statue at its base. The railings around it are missing. There is concern over the structural stability of the
	CONDITION:	Fair	monument due to ground subsidence nearby.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1385651	Contact: Tracy Chapman (LPA) 020 7525 2289

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).
 - Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument



© London Borough of Southwark

	SITE NAME:	St Peter's Church Hall, 522, Lordship Lane, East Dulwich SE22	Situated adjacent to St Peter's Church, the hall was constructed in 1899. Both buildings are believed to be by Charles Barry Junior. The building is currently vacant and is
	DESIGNATION:	Listed Building grade II, CA	suffering from structural movement and lack of maintenance.
	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
1	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1385671	Contact: Tracy Chapman (LPA) 020 7525 2289




	SITE NAME:	Fire station (former), 306-312 (even), Old Kent Road SEI	Fire station built between 1903-4 by the London County Council Architects Department. Red brick with Portland
	DESIGNATION:	Listed Building grade II	stone dressings. Shop fronts have been installed without appropriate authorisation. A grant has been given by the
	CONDITION:	Poor	Empty Homes Agency towards conversion of the upper floors for which Planning Permission has been granted.
	OCCUPANCY:	Part occupied/part in use	Work has commenced on site.
	PRIORITY CATEGORY:	F(C)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1385738	Contact: Tracy Chapman (LPA) 020 7525 2289

© English Heritage Archive



© London Borough of Southwark



all 1	SITE NAME:	21 and 23, Park Street SEI	Pair of houses dating to circa 1820. Currently vacant and
	DESIGNATION:	Listed Building grade II, CA	suffering from significant structural problems. The northern flank wall to No. 23 is propped with scaffolding. The
1 THUR	CONDITION: OCCUPANCY:	Poor	houses have been sold and the new owners are in pre- application discussions with Southwark Council.
LAND		Vacant/not in use	application discussions with southwark Council.
ANT I	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
And the state of the	LIST ENTRY NUMBER:	1385752	Contact: Tracy Chapman (LPA) 020 7525 2289

© English Heritage



SITE NAME:	38, Peckham Hill Street SEI5	One of a terrace of four houses, built circa 1840. The
DESIGNATION:	Listed Building grade II	building was damaged by fire in 2009 and subsequently sold to a new owner in February 2011. Unauthorised works
CONDITION:	Poor	were carried out to mitigate fire damage. No valid application has as yet been received to regularise these
OCCUPANCY:	Occupied/in use	works.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1385760	Contact: Tracy Chapman (LPA) 020 7525 2289
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY: OWNER TYPE:	DESIGNATION:Listed Building grade IICONDITION:PoorOCCUPANCY:Occupied/in usePRIORITY CATEGORY:C (C)OWNER TYPE:Private

© London Borough of Southwark

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented. obvious new user (applicable only to buildings capable of beneficial

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM UA WHS
 - Unitary Authority World Heritage Site

tion the second se	SITE NAME:	112, Peckham Park Road, Peckham SE15	One of a group of four pairs of early C19 houses. Repairs have been carried out using unsuitable materials. There are currently no proposals for reuse.
IHEE	DESIGNATION:	Listed Building grade II	
	CONDITION:	Poor	
	OCCUPANCY:	Occupied/in use	
COMPANY OF	PRIORITY CATEGORY:	C (C)	
dimension in the second se	OWNER TYPE:	Private	
© London Borough of Southwark	LIST ENTRY NUMBER:	1385765	Contact: Tracy Chapman (LPA) 020 7525 2289

	SITE NAME:	Former Peckham Fire Station, 82, Peckham Road SE5	Former fire station built c1867 by Edward Cresy Junior which later became part of the Kennedy's sausage factory.
	DESIGNATION:	Listed Building grade II	The remainder of the factory has been demolished. The building has been vacant for some time and is in a poor
	CONDITION:	Poor	state of repair, with water ingress and widespread rot.
	OCCUPANCY:	Vacant/not in use	
NAME OF TAXABLE PARTY.	PRIORITY CATEGORY:	C (New entry)	
E THE REAL PROPERTY.	OWNER TYPE:	Unknown	
© London Borough of Southwark	LIST ENTRY NUMBER:	1392995	Contact: Tracy Chapman (LPA) 020 7525 2289

	SITE NAME:	40, Queens Road, Peckham SE15	Early C19 terraced building. The building is in poor condition and has suffered from extensive unauthorised
	DESIGNATION:	Listed Building grade II	works.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Private	
© London Borough of Southwark	LIST ENTRY NUMBER:	1385796	Contact: Tracy Chapman (LPA) 020 7525 2289

	SITE NAME:	Former Clare College Mission Church, Southwark Park SEI6	Former church. The Bermondsey Artists' Group was awarded a Big Lottery grant under the Community Assets
	DESIGNATION: CONDITION: OCCUPANCY: PRIORITY CATEGORY:	Listed Building grade II	Programme (2008) to refurbish the building as an art gallery space. English Heritage and Southwark Council ha
1		Poor	funded roof repairs, which were completed in 2010. Further repairs are required to the walls.
		Occupied/in use	
		C (D)	
	OWNER TYPE:	Local authority	
1	LIST ENTRY NUMBER:	1385919	Contact: Tracy Chapman (LPA) 020 7525 2289



© English Heritage

	SITE NAME:	Southwark Park School, Southwark Park Road, Southwark SE16	London Board School, by ER Robson, of 1873 with extensions of 1899. Works are well underway for full refurbishment towards re-opening as a school in 2014/15.
	DESIGNATION:	Listed Building grade II	
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (D)	
	OWNER TYPE:	Local authority	
© London Borough of Southwark	LIST ENTRY NUMBER:	1385920	Contact: Tracy Chapman (LPA) 020 7525 2289

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

AL PROPERTY OF	SITE NAME:	Number 1 and attached Railings, 1, Stamford Street SE1	Mid-C19 red brick building that occupies a prominent position looking towards Blackfriars Bridge. The building is
	DESIGNATION:	Listed Building grade II	vacant and in a poor and deteriorating condition. Planning Permission is being sought for conversion from offices to a
	CONDITION:	Poor	hotel associated with the adjacent Mad Hatter Hotel.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Commercial company	
on Borough of Southwark	LIST ENTRY NUMBER:	1385933	Contact: Tracy Chapman (LPA) 020 7525 2289

A	SITE NAME:	Peckham Rye Station, Station Way, Peckham SEI5	The station is an H-shaped building, built in 1864-65 by Charles Henry Driver for the London, Brighton and South
The Mar	DESIGNATION:	Listed Building grade II, CA	East Coast Railway. The northern wing has been refurbished and brought back into use. Discussions are
	CONDITION:	Poor	ongoing to bring the vacant areas in the southern wing back into use. An application has been approved to refurbish
AG	OCCUPANCY:	Part occupied/part in use	parts of the south wing, but works have not yet started.
A DESCRIPTION OF	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1392389	Contact: Tracy Chapman (LPA) 020 7525 2289

Early CI8 three-storey house with a shop on the ground SITE NAME: 5, Stoney Street SEI floor, formerly a potato warehouse, in the Borough High Listed Building grade II, CA Street Conservation Area. The upper floors of the property are vacant and in a poor condition, with significant CONDITION: Poor water ingress, and unauthorised works have been carried OCCUPANCY: Part occupied/part in use out. The ground floor of the property is occupied but works have not been carried out in line with planning PRIORITY CATEGORY: A (New entry) consents granted in 2007. OWNER TYPE: Private LIST ENTRY NUMBER: 1385937 Contact: Tracy Chapman (LPA) 020 7525 2289

© English Heritage

© London Bo

© English Heritage

© London

	SITE NAME:	Beltwood House, 41, Sydenham Hill, Camberwell SE26	Large mid-Victorian villa, possibly by Banks and Barry, Dulwich College architects. The house was remodelled in
	DESIGNATION:	Listed Building grade II, CA	the neoclassical style in circa 1895. The building contains fine interiors, but is currently vacant and suffering from the
	CONDITION:	Fair	effects of water ingress. The curtilage buildings (stables, lodge, two cottages and animal store) are in a poor state of
and the second	OCCUPANCY:	Vacant/not in use	repair. An application for Planning Permission has been
	PRIORITY CATEGORY:	C (C)	received for conversion to flats and houses.
	OWNER TYPE:	Commercial company	
orough of Southwark	LIST ENTRY NUMBER:	1385958	Contact: Tracy Chapman (LPA) 020 7525 2289
	SITE NAME:	Drinking fountain, Tanner Street Park, Bermondsey SEI	Originally a turret and the capping to the tower of the former Church of St Olave, Tooley Street. 1738-9, re-site



in 1929. Now a defunct drinking fountain and in poor DESIGNATION: Listed Building grade II, CA condition. A condition survey has been carried out, funded by English Heritage, with a view to works being carried out CONDITION: Poor as part of a new landscaping scheme for the park. OCCUPANCY: N/A PRIORITY CATEGORY: C (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1385959 Contact: Tracy Chapman (LPA) 020 7525 2289

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

ŬA

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- Unitary Authority World Heritage Site WHS

	SITE NAME:	62 and 64, Union Street SEI SEI	Pair of terraced houses built circa 1835. Network Rail has carried out works to make the properties weatherproof
1 12 1	DESIGNATION:	Listed Building grade II, CA	and structurally secure. Planning Permission has now been granted for restoration and conversion for restaurant use.
	CONDITION:	Fair	
and the of the owner way	OCCUPANCY:	Vacant/not in use	
El Harry	PRIORITY CATEGORY:	D (E)	
S.	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1386010	Contact: Tracy Chapman (LPA) 020 7525 2289

© English Heritage


© English Heritage




a sea	SITE NAME:	Southwark Municipal Offices and attached railings, Walworth Road SE17	Built as a vestry hall circa 1863-64, then later used as a town hall and more recently as municipal offices for Southwark Council. The building was severely damaged by
	DESIGNATION:	Listed Building grade II	fire in 2013 and the former council chamber and roof were destroyed. The building has been stabilised and the Council
4	CONDITION:	Very bad	is discussing options for restoration with the local community and English Heritage.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY: C	C (New entry)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1386028	Contact: Tracy Chapman (LPA) 020 7525 2289



© London Borough of Southwar	
	Ŀ





© English Heritage



	SITE NAME:	Celestial Church of Christ and attached wall and railings, Glengall Road, Camberwell SEI 5	Designed by E Bassett Keeling, built in 1865. The spire wa removed c1950. Formerly known as St Andrew's. Mainly clay tiled pitched roofs and Kentish ragstone walling with limestone dressings and red sandstone banding. A Heritag Lottery Fund/English Heritage Repair Grant for Places of Worship was awarded in 2012 to carry out masonry and roofing repairs and to overhaul rainwater goods. Works are due to commence in autumn 2014.
2 al start	DESIGNATION:	Listed Place of Worship grade II	
F1(1)	CONDITION:	Poor	
ing line	PRIORITY CATEGORY:	D (D)	
and the second	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1385564	Contact: Ian Harper 020 7973 3786

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM
- ŬA Unitary Authority World Heritage Site WHS

 SITE NAME:	Church of St Augustine, Honor Oak Park, Camberwell SE23	Constructed between 1872-73 by William Oakley in Kentish ragstone with ashlar details and slate roof. High
DESIGNATION:	Listed Place of Worship grade II	level fabric and some structural defects have been remedied, and some roofs and masonry repaired. The
CONDITION:	Poor	latest phase of stonework and tower re-roofing has recently been completed, grant-aided by the Heritage
PRIORITY CATEGORY:	C (F)	Lottery Fund and English Heritage. Further re-roofing and
OWNER TYPE:	Religious organisation	masonry repairs are required.
LIST ENTRY NUMBER:	1385617	Contact: Ian Harper 020 7973 3786

© English Heritage

SITE NAME:	Roman boat at New Guy's House, Bermondsey SE		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1001979
CONDITION:	Generally satisfactory but with significant localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Health authority	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	The Rose Theatre, Rose Court, Southwark SEI		
DESIGNATION:	Scheduled Monument	LIST ENTRY NUMBER:	1012707
CONDITION:	Extensive significant problems	TREND:	Unknown
PRINCIPAL VULNERABILITY:	Drainage/dewatering	NEW ENTRY?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	Nunhead Cemetery, Nunhead SE15		
DESIGNATION:	Conservation Area, 13 LBs, RPG grade II*	NEW ENTRY?:	Yes
CONDITION:	Very bad	TREND:	Deteriorating
VULNERABILITY:	Low	CONTACT:	Michael Tsoukaris (LPA) 020 8299 6078

SUTTON

	SITE NAME:	Orangery wall to Beddington Place, Church Road, Beddington	Orangery wall of circa 1720. Subject to severe vandalism. The Local Authority has completed a restoration strategy
San Allera.	DESIGNATION:	Listed Building grade II, CA	document.
Contraction of the second	CONDITION:	Poor	
A COLUMN T	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
rchive	LIST ENTRY NUMBER:	1065673	Contact: Dean James (LPA) 0208 770 5000

© English Heritage Arcl



	SITE NAME:	Grotto in Carshalton Park, Ruskin Road, Carshalton	Early C18 grotto in Carshalton Park. The exterior of the grotto has symmetrical curved walls of brick, ramped up	
	DESIGNATION:	Listed Building grade II, CA	gradually to a central peak. The grotto is extremely vulnerable to vandalism and graffiti.	
	CONDITION:	Poor		
115	OCCUPANCY:	N/A		
	PRIORITY CATEGORY:	A (A)		
Call N	OWNER TYPE:	Local authority		
	LIST ENTRY NUMBER:	1065628	Contact: Dean James (LPA) 0208 770 5000	

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

TOWER HAMLETS



Decorative gates and railings forming the front boundary to SITE NAME: Front wall, gate piers and gates at St Clements Hospital, Bow the redundant St Clements Hospital. The freehold has been transferred to the Greater London Authority. Road, Bow E3 Planning Permission and Listed Building Consent have been DESIGNATION: Listed Building grade II, CA granted for the conversion of the former hospital to housing, but works have not yet started. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: D (C) OWNER TYPE: Government or agency

bollard.

Contact: Andrew Hargreaves (LPA) 020 7364 5576

Redundant hospital, formerly City of London infirmary

freehold has been transferred to the Greater London

hospital to housing, but works have not yet started.

Contact: Andrew Hargreaves (LPA) 020 7364 5576

Two C19 bollards which formed a group along with St

Mary's Church, its gates and railings and the statue of WE

Local Authority is considering reinstatement of the missing

Gladstone. One of the bollards has been removed. The

Contact: Andrew Hargreaves (LPA) 020 7364 5576

Impressive Italianate main block fronting Bow Road. The

Authority. Planning Permission and Listed Building Consent have been granted for the conversion of the former

© English Heritage



SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

LIST ENTRY NUMBER:

LIST ENTRY NUMBER:

1065276

2 Bollards (Between statue of

Gladstone and St Mary's

churchyard entrance), Bow Road, Bromley-By-Bow E3

Listed Building grade II, CA

Commercial company

Poor

N/A

C (C)

1262757

© English Heritage



© English Heritage



Underground gentlemen's public convenience, constructed SITE NAME: Gentlemen's public by the Board of Works and opened in 1899. Curved convenience, Bow Road, Bromley-By-Bow E3 entrance steps designed to fit around the statue of WE Gladstone. The decorative interior finish includes russet DESIGNATION: Listed Building grade II, CA marble urinals. The public convenience has been disused for many years and the decorative iron gates have been CONDITION: Very bad damaged. The interior is also subject to vandalism. Tower OCCUPANCY: Hamlets Council is aiming to work with strategic partners Vacant/not in use to find a way forward. PRIORITY CATEGORY: A (A) OWNER TYPE-Local authority LIST ENTRY NUMBER: 1392968 Contact: Andrew Hargreaves (LPA) 020 7364 5576

© English Heritage



	SITE NAME:	Former Bromley Hall School, Bromley Hall Road, London E14	School for physically disabled children, built in 1967-8 by the Greater London Council's Architects' Department and
	DESIGNATION:	Listed Building grade II	extended in 1978-9. The building has a distinctive architectural form which reflects the local industrial
	CONDITION:	Poor	vernacular. It has been vacant for several years following changes in educational requirements. Proposals for reus
	OCCUPANCY:	Vacant/not in use	are being developed and Planning and Listed Building
	PRIORITY CATEGORY:	C (New entry)	Consent applications are anticipated in due course.
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1402561	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

D

Е

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- Slow decay; no solution agreed. С
- Slow decay; solution agreed but F not yet implemented.
- Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)
- Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.
- NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area Listed Building
- LB I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM

ΪA Unitary Authority World Heritage Site ŴĤS

	HERITAGE	AT RISK 2014	/ LONDON /	TOWER HAMLETS
--	----------	--------------	------------	---------------

NG?	SITE NAME:	How Memorial Gateway, Bromley High Street E3	Gabled stone Gothic arch with double buttresses at each side, circa 1893. Formerly an entrance to St Mary's
	DESIGNATION:	Listed Building grade II	Churchyard. The gateway is suffering from stonework decay. The Local Authority is considering options for
	CONDITION:	Poor	repair.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1065281	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© English Heritage

© English Heritage

© English Heritage

-	SITE NAME:	Limehouse District Library, Commercial Road, Limehouse E14	Former Passmore Edwards Library. Built in 1900 by Messrs Clarkson Architects. The library is closed and the building vacant and boarded up. The Local Planning Authority has
	DESIGNATION:	Listed Building grade II, CA	resolved to grant Planning Permission and Listed Building Consent to convert the building to student
	CONDITION:	Fair	accommodation with associated educational and ancillary facilities, subject to a section 106 agreement and detailed
	OCCUPANCY:	Vacant/not in use	conditions.
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357807	Contact: Andrew Hargreaves (LPA) 020 7364 5576

Early C19 terraced house, three storeys and basement. SITE NAME: 689, Commercial Road, Limehouse EI4 The building was severely damaged by fire in 2012. The Local Planning Authority is working towards a solution. DESIGNATION: Listed Building grade II, CA Planning and Listed Building Consent applications have been submitted for works to convert the building into flats. CONDITION: Very bad Temporary propping and protection has been erected. OCCUPANCY: Vacant/not in use PRIORITY CATEGORY: A (A) OWNER TYPE: Private LIST ENTRY NUMBER: 1357810 Contact: Andrew Hargreaves (LPA) 020 7364 5576

	SITE NAME:	Former Caird & Rayner Ltd Warehouse, 777-783, Commercial Road E14	Former sail makers and ship chandler's warehouse, 1869. A rare survival consisting of a brick skin enclosing a timber structure. The building was fire damaged, resulting in the
	DESIGNATION:	Listed Building grade II, CA	loss of its roof covering. Urgent works were completed in April 2010. The Council is continuing to pursue
	CONDITION:	Very bad	enforcement action and discussions regarding the re-use o the building are ongoing. Recently much of the vegetation inside the building and on the front elevation has been
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	removed by the owners to prevent further damage.
	OWNER TYPE:	Commercial company	
© English Heritage	LIST ENTRY NUMBER:	1385372	Contact: Andrew Hargreaves (LPA) 020 7364 5576

	SITE NAME:	Poplar Baths, East India Dock Road E14	Former public baths, with slipper and vapour baths. Built 1932-4 for Poplar Borough Council to the designs of
	DESIGNATION:	Listed Building grade II	Harley Heckford, Borough Engineer, and RW Stanton, Chief Assistant. The building is vacant and in poor
	CONDITION:	Poor	condition. Planning Permission and Listed Building Consent have been granted for works associated with the re-use of
	OCCUPANCY:	Vacant/not in use	the building as a leisure centre and swimming pool and
	PRIORITY CATEGORY:	F(C)	works have started.
	OWNER TYPE:	Local authority	
English Heritage	LIST ENTRY NUMBER:	1334939	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© Er

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid deterioration or loss of fabric; В solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA
- LB LPA
- Conservation Area Listed Building Local Planning Authority National Park NP RPG
- Registered Park and Garden Scheduled Monument
- SM
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT RISK 2014 / LONDON / TOWER HAMLETS

	SITE NAME:	Wiltons Music Hall, Graces Alley El	Former music hall with fine ornamental interior built in 1858. The building is leased to an opera company and is
	DESIGNATION:	Listed Building grade II*, CA	now in regular use. The interior and exterior restoration of the auditorium is now complete. The final stages of
	CONDITION:	Fair	restoration work, implementing Stage 2 of a Heritage Lottery Fund grant, are ongoing following the receipt of
	OCCUPANCY:	Occupied/in use	Planning Permission and Listed Building Consent.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Charity (heritage)	
	LIST ENTRY NUMBER:	1065173	Contact: Elizabeth Whitbourn 07889 808145

© English Heritage



© English Heritage Archive

An inscribed stone tablet, formerly in a glazed case with SITE NAME: Tablet in the North Wall of the Portuguese Jewish Burial side scrolls, moulded cornice and pediment, recording the laying of the first stone in the burial ground in 1684. The Ground, Mile End Road EI top of the wall, including the moulded cornice and pediment, has collapsed, leaving the stone open to the DESIGNATION: Listed Building grade II, CA elements. The Local Authority is investigating its repair. CONDITION: Poor OCCUPANCY: N/A PRIORITY CATEGORY: A (A) OWNER TYPE: Religious organisation LIST ENTRY NUMBER: 1260699 Contact: Andrew Hargreaves (LPA) 020 7364 5576

> Late C19 polished granite drinking fountain, with a short column on a plinth. The drinking fountain has an inscription

commemorating its erection by the Metropolitan Cattle Trough and Drinking Fountain Association. The bowl has

been removed. The council is investigating the

Contact: Andrew Hargreaves (LPA) 020 7364 5576

reinstatement of missing elements.

Drinking fountain (on pavement outside 31-74 Mile End Road),

Mile End Road, Stepney EI



DESIGNATION: Listed Building grade II, CA CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: D (D) OWNER TYPE: Local authority © English Heritage LIST ENTRY NUMBER: 1065113

SITE NAME:

BA A	SITE NAME:	St Saviours Church, Northumbria Street, Poplar E14	Former church dating from 1873-4 to the design of Frederick J and Horace Francis. The building was severely
	DESIGNATION:	Listed Building grade II	damaged by fire in May 2007 and is currently propped by scaffolding. Following detailed negotiations, Planning and
	CONDITION:	Very bad	Listed Building Consent applications are now being considered by the LPA for residential conversion.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1242275	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© English Heritage

The second se
A A A A A A A A A A A A A A A A A A A
and the local data and the second
Example and the second s

SITE NAME:	19, Princelet Street, Spitalfields El	Terraced house of 1719 by Samuel Warrall, builder, with added synagogue of 1869 by a Mr Hudson. The building
DESIGNATION:	Listed Building grade II*, CA	combines a well preserved Spitalfields Huguenot merchant's house with weaving garrets, and a rare surviving
CONDITION:	Poor	small synagogue. Listed Building Consent has been granted for roof repairs.
OCCUPANCY:	Part occupied/part in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1260421	Contact: Elizabeth Whitbourn 07889 808145

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no

D

Е

use)

obvious new user (applicable only to buildings capable of beneficial

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site
- 118

HERITAGE AT RISK 2014 / LONDON / TOWER HAMLETS

	SITE NAME:	113, Redchurch Street, Tower Hamlets E2	Weavers' tenement house, built c1735 by William Farmer, a local builder. The building is of interest as a rare and early
	DESIGNATION:	Listed Building grade II, CA	survival of a building type that once dominated Spitalfields. The building is derelict and has structural problems. The
	CONDITION:	Very bad	facade is braced to prevent further movement. Planning Permission and Listed Building Consent have been granted.
	OCCUPANCY:	Vacant/not in use	The Local Planning Authority is now considering
Estate Agents Ltd.	PRIORITY CATEGORY:	B (B)	enforcement action.
	OWNER TYPE:	Private	
itage	LIST ENTRY NUMBER:	393497	Contact: Andrew Hargreaves (LPA) 020 7364 5576



© English Herit

	SITE NAME:	Tomb of Joseph Wrestwood, Southern Grove, Tower Hamlets Cemetery E3	One of the most prominent monuments within the cemetery given its design and location, this stone cross dates from circa 1883. It is in poor condition due to general
	DESIGNATION:	Listed Building grade II, CA	decay and the loss of parts of its low railings, tiles, finials and other detailing. The Local Authority is considering a
	CONDITION:	Poor	repair scheme.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1378758	Contact: Andrew Hargreaves (LPA) 020 7364 5576

St Pauls Mission Room and Infant Nursery, Wellclose

Listed Building grade II, CA

Vacant/not in use

Religious organisation

Braithwaite Viaduct, Bishopsgate Goods Yard,

Listed Building grade II

Wheler Street / Brick Lane EI

C (New entry)

1242432

Poor

N/A

C (C)

Utility

Square EI

Poor

LIST ENTRY NUMBER:

SITE NAME:

DESIGNATION:

CONDITION:

OCCUPANCY:

OWNER TYPE:

PRIORITY CATEGORY:

Gothic style structure built in 1874 to designs by Reuben

dressings to the doors and windows, a steeply pitched tiled

Greatorex. The building is of stock brick with red brick eaves cornice and red and blue brick bands. It has stone

roof with cresting, and a stone banded chimney. The

Contact: Andrew Hargreaves (LPA) 020 7364 5576

Early railway viaduct built in 1840 by John Braithwaite for

the Eastern Counties Railway, formerly set within extensive

brick vaulted goods yard circa 1880, demolished in 2003. A condition survey and other works to the vaults are

required. Discussions on the future of Bishopsgate Goods

Yard, including the viaduct, are ongoing.

building is empty and boarded up.



© English Heritage

© English Heritage



© English Heritage



	LIST ENTRY NUMBER:	1063895	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	Drinking fountain set in wall of former St Mary's Churchyard, Whitechapel Road E1	Drinking fountain with pink marble basin and plaque set in Norman style arch. Erected in 1860 but moved to its present position in 1879. The Local Authority has cleaned
	DESIGNATION:	Listed Building grade II, CA	the fountain, but repairs are outstanding. The Local Authority and English Heritage are working towards a
	CONDITION:	Poor	repair scheme.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	D (D)	
3	OWNER TYPE:	Local authority	
	LIST ENTRY NUMBER:	1357512	Contact: Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

© English Heritage

- Immediate risk of further rapid deterioration or loss of fabric: no А
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- С Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

Conservation Area Listed Building CA

- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM

ŬA Unitary Authority World Heritage Site WHS

HERITAGE AT RISK 2014	/ LONDON / TOWER HAMLETS

HERITAGE AT RISK 2014 / LOINDO	JN / TOWER HAMLET		
	SITE NAME:	Royal London Hospital - front block, Whitechapel Road, Whitechapel El	Fine C18 yellow brick hospital building fronting Whitechapel Road. The building has become redundant following development of new facilities to the rear, but
	DESIGNATION:	Listed Building grade II, CA	remains the responsibility of the Barts NHS Trust. The Local Authority is seeking re-use as a Civic Centre as part
	CONDITION:	Fair	of a new masterplan for Whitechapel.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (E)	
	OWNER TYPE:	Health authority	
© English Heritage	LIST ENTRY NUMBER:	1065788	Contact: Andrew Hargreaves (LPA) 020 7364 5576
	SITE NAME:	2, Wilkes Street El	Early C18 terraced house. Three storeys with basement
	DESIGNATION:	Listed Building grade II, CA	and attic in painted brick. Some repair works have been undertaken. The Local Authority is considering
	CONDITION	Deen	enforcement action.

DESIGNATION:	Listed Building grade II, CA	and attic in painted brick. Some repair works have been undertaken. The Local Authority is considering
CONDITION:	Poor	enforcement action.
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1242278	Contact: Andrew Hargreaves (LPA) 020 7364 5576

© English Heritage Archive

	SITE NAME:	St Paul's Church, Burdett Road, Stepney E3	Designed by architect Robert Maguire, the church was consecrated on the 30th April 1960. The church is based
and the second	DESIGNATION:	Listed Place of Worship grade II*	on a rectangular plan centred round the altar, with projections to the north west and south east for the porch
	CONDITION:	Very bad	and the baptistery. Currently the central nave is closed due to the continuing risk of falling ceiling panels.
	PRIORITY CATEGORY:	A (New entry)	to the continuing hist of failing coning partons.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1241881	Contact: Ian Harper 020 7973 3786

© English Heritage

	SITE NAME:	St Mary's Church, Cable Street, Stepney El	This church was designed by Frederick and Horace Francis and completed c1850. It was reordered in 1986. The
	DESIGNATION:	Listed Place of Worship grade II	church has slate roofing, Kentish ragstone walling with Bath stone dressings. A Heritage Lottery Fund/English Heritage
	CONDITION:	Poor	Repair Grant for Places of Worship was awarded in 20 for masonry repairs to the tower. Repairs are due to
	PRIORITY CATEGORY:	D (D)	commence late 2014.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1096892	Contact: Ian Harper 020 7973 3786

© English Heritage



SITE NAME:	Church of St John on Bethnal Green, Cambridge Heath Road, Bethnal Green E2	Parish church of 1824 by Sir John Soane. Heavily restored and extended in C19 by William Munday and GF Bodley. Stock brick with artificial stone dressings and western
DESIGNATION:	Listed Place of Worship grade I, CA	portico. A phased programme of repairs to high level stonework and render is underway, funded by an English Heritage/Heritage Lottery Fund Repair Grant for Places of
CONDITION:	Poor	Worship. This third phase of repair is due for completion in 2014.
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1065245	Contact: Ian Harper 020 7973 3786

© English Heritage

PRIORITY CATEGORIES

- А
- Immediate risk of further rapid deterioration or loss of fabric: no solution agreed Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented. В
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / TOWER HAMLETS

	DESIGNATION:	Church (former Trinity Methodist Church), including attached hall and church rooms, East India Dock Road, Poplar E14 Listed Place of Worship grade II,	and D Rogers Stark. Spalling of aggregate-faced concrete is exposing reinforcement which requires repair. The new congregation is actively seeking funding for a programme of repairs.	
	CONDITION:	CA Poor		
© English Heritage	PRIORITY CATEGORY:	C (C)		
	OWNER TYPE:	Religious organisation		
	LIST ENTRY NUMBER:	1376625	Contact: Ian Harper 020 7973 3786	
	SITE NAME:	New Testament Church of God (former Holy Trinity), Morgan Street, Bethnal Green E3	Church constructed of London stock brick with stone dressings designed by G Austin and built 1836-9. Repairs to the roofs and stonework have been undertaken. The Local	

SV.	12-	à.
X	A D	
	會行	
	Antonia !	

A.	SITE NAME:	New Testament Church of God (former Holy Trinity), Morgan Street, Bethnal Green E3	Church constructed of London stock brick with stone dressings designed by G Austin and built 1836-9. Repairs to the roofs and stonework have been undertaken. The Local
F	DESIGNATION:	Listed Place of Worship grade II, CA	Authority's Historic Places of Worship Support Officer will be working with relevant parties to develop a strategy for repair and to explore funding options.
	CONDITION:	Fair	
	PRIORITY CATEGORY:	C (C)	
- Main	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065118	Contact: Ian Harper 020 7973 3786

© English Heritage Archive



	SITE NAME:	Sandy's Row Synagogue, Sandys Row, Bethnal Green El	Former Huguenot chapel which was altered mid-C19 as a synagogue. Slate roof and stock brick walling with red brick
	DESIGNATION:	Listed Place of Worship grade II, CA	dressings. Major re-roofing and high level brick repairs were completed in 2011 with a Heritage Lottery Fund/English Heritage Repair Grant for Places of Worship.
	CONDITION:	Fair	Whilst underway bowing of the narrow brick piers on the front elevation was discovered. Emergency works were
	PRIORITY CATEGORY:	C (D)	carried out to temporarily restrain the piers until
	OWNER TYPE:	Religious organisation	permanent repair and funding can be resolved.
	LIST ENTRY NUMBER:	1260323	Contact: Tracey Craig 020 7973 3756

© English Heritage

SITE NAME:	Priory and Hospital of St Mary Spital, Steward St	reet El	
DESIGNATION:	Scheduled Monument, 11 LBs, part in CA	LIST ENTRY NUMBER:	1001982
CONDITION:	Generally unsatisfactory with major localised problems	TREND:	Declining
PRINCIPAL VULNERABILITY:	Public utilities	NEW ENTRY ?:	No
OWNER TYPE:	Commercial company, multiple owners	CONTACT:	Elizabeth Whitbourn 07889 808145
SITE NAME:	London Hospital, Stepney El		
DESIGNATION:	Conservation Area, 16 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	St Anne's Church EI4		
DESIGNATION:	Conservation Area, 31 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no А

- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В
- implemented. C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / TOWER HAMLETS / WALTHAM FOREST

SITE NAME:	Tower Hamlets Cemetery, Bow E3		
DESIGNATION:	Conservation Area, 19 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	Deteriorating significantly
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Wentworth Street, Bethnal Green El		
DESIGNATION:	Conservation Area, 2 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Low	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Whitechapel High Street, Aldgate El		
DESIGNATION:	Conservation Area, 9 LBs	NEW ENTRY?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576
SITE NAME:	Wilton's Music Hall El		
DESIGNATION:	Conservation Area, 6 LBs	NEW ENTRY ?:	No
CONDITION:	Very bad	TREND:	No significant change
VULNERABILITY:	Medium	CONTACT:	Andrew Hargreaves (LPA) 020 7364 5576

WALTHAM FOREST

	SITE NAME:	Wall to south east of St Mary's Churchyard, Church End E17	C18 walls, formerly belonging to a house, now demolished, on the adjacent site. In need of repair.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357602	Contact: Jacinta Fisher (LPA) 020 8496 6737



© English Heritage

	SITE NAME:	Walnut Tree House, 500, High Road E10	Mid C16 timber-framed property formerly used as the Conservative Club, but currently vacant. Unauthorised and
	DESIGNATION:	Listed Building grade II*	unsympathetic changes have been made to the property, including the removal of original floorboards and the
-	CONDITION: Fair	Fair	installation of modern skirting/architraves. Enforcement action has been initiated. Listed Building Consent and
	OCCUPANCY:	Vacant/not in use	Planning Permission have been granted subject to
	PRIORITY CATEGORY:	E (E)	conditions. The conditions are yet to be discharged.
0	OWNER TYPE:	Other not for profit group	
st	LIST ENTRY NUMBER:	1065586	Contact: Verena McCaig 020 7973 3718

© London Borough of Waltham Forest

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).


Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / WALTHAM FOREST

EL	SITE NAME:	698a, High Road Leytonstone, Leytonstone EI I	One of a surviving terrace of three Georgian houses, probably late C18, for many years the home of the local
	DESIGNATION:	Listed Building grade II	British Legion branch. Planning Permission and Listed Building Consent have been granted, but works are yet to
	CONDITION:	Very bad	commence. There has been a change of ownership.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Private	
n Borough of Waltham Forest	LIST ENTRY NUMBER:	1357632	Contact: Jacinta Fisher (LPA) 020 8496 6737



2.13

© London

© London Borough of Waltham Forest



CONDITION:

OCCUPANCY:

Poor

Vacant/not in use

CI6/CI7 timber-framed dovecote, the last surviving SITE NAME: Pimp Hall dovecote, King's Road, Chingford E4 structure from the historic Chingford Manor of Gowers and Buckerells. The building is in a poor condition as a DESIGNATION: Listed Building grade II result of the deteriorating timber frame and repeated vandalism. CONDITION: Very bad OCCUPANCY: N/A PRIORITY CATEGORY: A (C) OWNER TYPE: Local authority LIST ENTRY NUMBER: 1065591 Contact: Jacinta Fisher (LPA) 020 8496 6737 Closed chapel to hospital (formerly a workhouse), 1840. SITE NAME: Chapel to south of main hospital block, Langthorne Road Roof tiles have slipped and the building is not wind and weathertight. ELI DESIGNATION: Listed Building grade II

© English Heritage



	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1357634	Contact: Jacinta Fisher (LPA) 020 8496 6737
Salar (*	SITE NAME:	Lodge south of main hospital block, Langthorne Road El I	1840 lodge to hospital (formerly a workhouse). Considerable ivy growth is now covering most of the building requiring urgent management. The long term us of the building is to be determined as part of the wider hospital site.
	DESIGNATION:	Listed Building grade II	
A State	CONDITION:	Very bad	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	C (C)	
	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1293493	Contact: Jacinta Fisher (LPA) 020 8496 6737

© English Heritage

PRIORITY CATEGORIES

Immediate risk of further rapid deterioration or loss of fabric: no

D

Е

- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but $\ \ F$ not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

WHS

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG
- Registered Park and Garden Scheduled Monument SM
- ŬA
 - Unitary Authority World Heritage Site

HERITAGE AT RISK 2014 / LONDON / WALTHAM FOREST

IENTAGE AT NISK 20147 EOND			
	SITE NAME:	Chingford Mill Pumping Station, Lower Hall Lane E4	Pumping station built in 1895 for East London Water Works, in a variant of the style popularised by Norman
1000	DESIGNATION:	Listed Building grade II	Shaw. Planning Permission and Listed Building Consent for residential use were granted in 2007 and subsequently
	CONDITION:	Poor	renewed; subject to a Section 106 agreement. Enforcement action for unauthorised works is ongoing.
	OCCUPANCY:	Vacant/not in use	action for unautionsed works is ongoing.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
Dondon Borough of Waltham Forest	LIST ENTRY NUMBER:	1250896	Contact: Jacinta Fisher (LPA) 020 8496 6737
	SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4	Water turbine house to pumping station built in 1895 for East London Water Works. Planning Permission and Listed Building Consent for residential use were granted in 2007
	DESIGNATION:	Listed Building grade II	and subsequently renewed; subject to a Section 106 agreement. Enforcement action for unauthorised works is
	CONDITION:	Very bad	ongoing.

© London Borough of Waltham

©

am Forest	SITE NAME:	Water Turbine House, Chingford Mill Pumping Station, Lower Hall Lane E4	Water turbine house to pumping station built in 189 East London Water Works. Planning Permission ar Building Consent for residential use were granted in
	DESIGNATION:	Listed Building grade II	and subsequently renewed; subject to a Section 10 agreement. Enforcement action for unauthorised w
	CONDITION:	Very bad	ongoing.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1065574	Contact: Jacinta Fisher (LPA) 020 8496 6737



	SITE NAME:	133, Whipps Cross Road, Leytonstone EI I	One of six survivors from an original terrace of 12 'middle- class' three storey houses called Assembly Row. Built in
	DESIGNATION:	Listed Building grade II, CA	1767 on the high ground at the edge of the forest land and within Leytonstone Conservation Area. Planning
	CONDITION:	Poor	Permission and Listed Building Consent for conversion into flats were refused in 2005 and upheld on appeal. A new
	OCCUPANCY:	Occupied/in use	owner has purchased the property and will be looking to
	PRIORITY CATEGORY:	C (C)	undertake repairs soon.
	OWNER TYPE:	Private	
rest	LIST ENTRY NUMBER:	1357621	Contact: Jacinta Fisher (LPA) 020 8496 6737

	SITE NAME:	Church of St Saviour, Markhouse Road, Walthamstow E17	Church built in 1874 of squared coursed Kentish ragstone to the design of TF Dolman, with a 1980s internal enclosure at the west end composed of glass screens and
	DESIGNATION:	Listed Place of Worship grade II	architectural roof. The roofs of the church were renewed after war damage in 1945 to a lower pitch and finished in
	CONDITION:	Poor	artificial slates. There is internal water staining due to failed tabled gutters to the nave and to the aisles. The rainwater
	PRIORITY CATEGORY:	C (New entry)	pipes, gullies and drains are all in need of repair.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065595	Contact: Ian Harper 020 7973 3786

© English Heritage



SITE NAME:	St Peter in the Forest, Woodford New Road, Walthamstow E17	Church of 1840 by John Shaw Jr extended westwards in 1887 and further extended and repaired in 1951 and 1958. Located in a woodland setting, the church is built of yellow
DESIGNATION:	Listed Place of Worship grade II	stock brick with stone dressings and a pitched slate roof; there is a central projecting tower on the south elevation. The 1951 extension is pulling away from the west wall of the church and this wall is settling and cracked.
CONDITION:	Very bad	
PRIORITY CATEGORY:	A (New entry)	are charen and ans wants seeing and chacked.
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1393232	Contact: Ian Harper 020 7973 3786

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

HERITAGE AT RISK 2014 / LONDON / WALTHAM FOREST / WANDSWORTH

	SITE NAME:	Church of St Margaret of Antioch and attached railings, Woodhouse Road, Leyton EI I	A late C19 basilica style church by architect JT Newman commenced in 1892, replacing an earlier iron mission church. The Lady Chapel was added in 1910. There are
ALA BAL	DESIGNATION:	Listed Place of Worship grade II	fine decorations and wall paintings internally. The church has completed projects to repair most of the roofs. Further
	CONDITION:	Poor	repair is needed to the north transept and aisle roofs, rainwater goods and drainage. The railings around the
	PRIORITY CATEGORY:	C (New entry)	church are contemporary but in poor condition and also
	OWNER TYPE:	Religious organisation	need of repair.
	LIST ENTRY NUMBER:	1390581	Contact: Ian Harper 020 7973 3786
oritago			

© English Heritage

WANDSWORTH

	SITE NAME:	Battersea Park Station, Battersea Park Road SW8	Italianate style railway station built circa 1865 for the London, Brighton and South Coast Railway. Repair works
	DESIGNATION:	Listed Building grade II, CA	are now complete. Alterations to the train service mean that the historically and architecturally significant platform I
	CONDITION:	Fair	is now redundant while options for its future are being considered by Network Rail.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	E (F)	
	OWNER TYPE:	Utility	
	LIST ENTRY NUMBER:	1357652	Contact: Barry Sellers (LPA) 020 8871 7564



© London Borough of Wandsworth

	SITE NAME:	Former St Mark's Infant School, Battersea Rise SWII	Church School of 1866-67 designed by Benjamin Ferrey. The building is currently vacant. A report on the structural
	DESIGNATION:	Listed Building grade II, CA	condition, commissioned by the owners, found the building wind and weathertight. Initial proposals for demolition
	CONDITION:	Poor	were discussed in 2012. Further discussions were held in November 2013 concerning the re-use, extension,
	OCCUPANCY:	Vacant/not in use	alteration and repair of the building. Applications are
	PRIORITY CATEGORY:	A (A)	anticipated in 2014.
	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1389136	Contact: Barry Sellers (LPA) 020 8871 7564



© London Borough of Wandsworth



SITE NAME:	Battersea Power Station, Cringle Street SW8	Power station built from 1932 onwards. Closed and vacated in 1983. Planning and Listed Building Consent	
LIST ENTRY NUMBER:	1065554	Contact: Barry Sellers (LPA) 020 8871 7564	
OWNER TYPE:	Educational (state sector)		
PRIORITY CATEGORY:	C (C)		
OCCUPANCY:	N/A		
CONDITION:	Poor		
DESIGNATION:	Listed Building grade II	redevelopment. New funding source to be identified.	
SITE NAME:	Ice house in the grounds of Burntwood Secondary School, Beechcroft Road, Tooting SW17	Circular domical ice house in brown and yellow brick covered by an earth mound with retaining walls to the approach. Probably C18. The ice house is in a poor but stable condition. It was linked with the Springfield Hospi	

SITE	SITE NAME:	Battersea Power Station, Cringle Street SW8	Power station built from 1932 onwards. Closed and vacated in 1983. Planning and Listed Building Consent
	DESIGNATION:	Listed Building grade II*	applications were approved in 2011, subject to legal agreement, for restoration, extension and conversion to
	CONDITION:	Very bad	provide mixed use facilities. The building was sold in July 2012. The new owners are the Malaysian-based companies
	OCCUPANCY:	Vacant/not in use	SP Setia, Sime Darby and the Employees' Pension Fund of
a.	PRIORITY CATEGORY:		Malaysia. A Section 73 application for revised proposals was approved in April 2014, subject to legal agreement.
	OWNER TYPE:	Commercial company	Works of alteration, repair and re-use have commenced.
	LIST ENTRY NUMBER:	1357620	Contact: Elizabeth Whitbourn 07889 808145

© English Heritage Archive

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay: solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

HERITAGE AT	RISK 2014 /	LONDON /	WANDSWORTH

	SITE NAME:	Battersea Pumping Station, Cringle Street SW8	Water pumping station, circa 1846. Linked to the development of Battersea Power Station. Archaeological
	DESIGNATION:	Listed Building grade II	report and building recording has been completed. An application to demolish was approved in August 2011. The
	CONDITION:	Very bad	building was sold in July 2012. The new owners are the
	OCCUPANCY:	Vacant/not in use	Malaysian-based companies SP Setia, Sime Darby and the Employees' Pension Fund of Malaysia. An application for
- A C 19-0-0	PRIORITY CATEGORY:	D (D)	reserved matters concerning demolition was approved in June 2014 with conditions in place to ensure the recording
	OWNER TYPE:	Commercial company	of the building and salvaging of items of historic significance prior to demolition.
	LIST ENTRY NUMBER:	1226087	Contact: Barry Sellers (LPA) 020 8871 7564
	SITE NAME:	Springfield Hospital (main building), Glenburnie Road SW17	Former Psychiatric hospital built in 1840 in Tudor Goth style as the Surrey County Asylum. Planning Permission Listed Building Consent for the redevelopment of the si
ETTE	DESIGNATION:	Listed Building grade II, RPG grade II	and demolition of curtilage listed buildings were granted on appeal in 2012. The Local Authority is awaiting further details.
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
Construction of the second	PRIORITY CATEGORY:	D (D)	
© English Heritage	OWNER TYPE:	Health authority	
	LIST ENTRY NUMBER:	1065553	Contact: Barry Sellers (LPA) 020 8871 7564
	SITE NAME:	Paggen Table Tomb, Huguenot Place, Huguenot Burial Ground SW18	Stone faced table tomb dating from 1769. One of five table tombs. The strategy for its conservation and repair is being discussed with the Local Authority and English Heritage.
	DESIGNATION:	Listed Building grade II, CA	

Con the second		SW18	discussed with the Local Authority and English Herita
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	N/A	
- Anna had	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© London Borough of Wandsworth	LIST ENTRY NUMBER:	1065536	Contact: Trisha Jean-Marie (LPA) 020 8871 6612

	SITE NAME:	Table Tomb to Errington Ward, Huguenot Place, Huguenot Burial Ground SW18	Stone faced table tomb, dating from 1720, with a deep moulded plinth. One of five table tombs. The strategy for its conservation and repair is being discussed with the Local
	DESIGNATION:	Listed Building grade II, CA	Authority and English Heritage.
	CONDITION:	Poor	
and the second second	OCCUPANCY:	N/A	
Se man	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1184219	Contact: Trisha Jean-Marie (LPA) 020 8871 6612



		1101217	
	SITE NAME:	Table Tomb to John Gilham, Huguenot Place, Huguenot Burial Ground SW18	Stone faced table tomb dating from 1728, with a deep moulded plinth. Similar to the Samuel John tomb. One of five table tombs. The strategy for its conservation and
	DESIGNATION:	Listed Building grade II, CA	repair is being discussed with the Local Authority and English Heritage.
CONDITION:	CONDITION:	Poor	
The state	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
the set of	OWNER TYPE:	Religious organisation	
	LIST ENTRY NUMBER:	1065537	Contact: Trisha Jean-Marie (LPA) 020 8871 6612

© English Heritage

PRIORITY CATEGORIES

- A Immediate risk of further rapid deterioration or loss of fabric: no solution agreed
 B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented.
 C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site

HERITAGE A	T RISK 2014	WANDSWORTH

HERITAGE AT RISK 2014 / LONDO	on / wandsworth		
	SITE NAME:	Table Tomb to Samuel John, Huguenot Place, Huguenot Burial Ground SW18	Stone faced table tomb, dating from the early to mid C18, with a deep moulded plinth. One of five table tombs. The strategy for its conservation and repair is being discussed
	DESIGNATION:	Listed Building grade II, CA	with the Local Authority and English Heritage.
ZL-FAL/4	CONDITION:	Poor	
and the first	OCCUPANCY:	N/A	
and the family	PRIORITY CATEGORY:	A (A)	
A AND A A	OWNER TYPE:	Religious organisation	
© English Heritage	LIST ENTRY NUMBER:	1357644	Contact: Trisha Jean-Marie (LPA) 020 8871 6612
	SITE NAME:	Tomb of Cotterell and Allen, Huguenot Place, Huguenot Burial Ground SW18	Table tomb from 1843. The moulded top slab is cracked in the middle and vegetation is growing through it. One of five table tombs. The strategy for its conservation and repair is
	DESIGNATION:	Listed Building grade II, CA	being discussed with the Local Authority and English Heritage.
	CONDITION:	Poor	0
marker 102	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	A (A)	
	OWNER TYPE:	Unknown	
© English Heritage	LIST ENTRY NUMBER:	1184206	Contact: Trisha Jean-Marie (LPA) 020 8871 6612
Alantagut Armis	SITE NAME:	The Montague Arms, 3, Medfield Street, Roehampton Village SW15	C17 house converted into a public house in the 1860s. Applications for change of use from a public house to retail or office uses at ground floor level with residential above
	DESIGNATION:	Listed Building grade II, CA	were approved in June 2010. Works to the flats are complete and they are occupied. Still awaiting tenants for
	CONDITION:	Fair	the ground floor commercial accommodation.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
© London Borough of Wandsworth			

© London Borough of Wandsworth

	SITE NAME: Temple in the grounds of Mount Clare, Minstead Gardens SW15		Temple dating from 1762-69. Some damage was caused by vandalism following unauthorised access. The site has been re-secured and minor works of repair to the roof were
	DESIGNATION:	Listed Building grade II*, CA	undertaken in 2012. The masterplan for the University's campus sites prepared in 2013 is currently being updated.
	CONDITION:	Poor	Pre-application discussions have been held with Roehampton University.
	OCCUPANCY:	N/A	
	PRIORITY CATEGORY:	C (C)	
© London Borough of Wandsworth	OWNER TYPE:	Educational (state sector)	
	LIST ENTRY NUMBER:	1065545	Contact: Elizabeth Whitbourn 07889 808145



SITE NAME:	Queenstown Road Station, Queenstown Road SW8	Station built in 1877. Repairs are needed to the doors, windows and floors of the disused areas of this unattend
DESIGNATION:	Listed Building grade II, CA	station. The former station ticket office has been re-used as a cafe and redecoration of the lobby area was completed in
CONDITION:	Poor	2010. The owners have re-confirmed that funding is in place for repair works in 2014-15. A Listed Building
OCCUPANCY:	Part occupied/part in use	Consent application is now expected in 2014.
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Utility	
LIST ENTRY NUMBER:	1389413	Contact: Barry Sellers (LPA) 020 8871 7564

PRIORITY CATEGORIES

© London Borough of Wandsworth

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

D

Е

LIST ENTRY NUMBER:

1184425

Slow decay: solution agreed but F not yet implemented. Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

Contact: Barry Sellers (LPA) 020 8871 7564

ABBREVIATIONS

- CA LB LPA NP RPG SM
- Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument
- UA Unitary Authority WHS World Heritage Site

127

HERITAGE AT RISK 2014 / LONDON / WANDSWORTH / WESTMINSTER, CITY OF

	SITE NAME:	The Watchers, behind Downshire House, Roehampton Lane, Roehampton SW15	Sculpture of 1960 by Lynn Chadwick and installed in 1963 by the London County Council. The sculpture has been temporarily removed following vandalism and carefully
TRACE.	DESIGNATION: CONDITION: OCCUPANCY:	Listed Building grade II, CA	stored. A planning application was approved in 2013 with a condition requiring the submission of details for the
		Poor	restoration of The Watchers linked to the occupancy of new student accommodation.
		N/A	new student accommodation.
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Educational (state sector)	
ge	LIST ENTRY NUMBER:	1031600	Contact: Barry Sellers (LPA) 020 8871 7564
10	SITE NAME:	100, Tooting Bec Road SW17	Early C19 stucco lodge. The building is vacant and in need

10	SITE NAME:	100, Tooting Bec Road SW17	Early C19 stucco lodge. The building is vacant and in need
	DESIGNATION:	Listed Building grade II	of repair. Planning and Listed Building Consent applications were approved in September 2012 to use the building for
	CONDITION:	Poor	retail (Å1) use and ancillary office space, together with a separate new building for use as a café and storage facilities
	OCCUPANCY:	Vacant/not in use	for cars in conjunction with car sales. Discussions have
	PRIORITY CATEGORY:	D (D)	been held with the owner's representative about implementation.
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1357661	Contact: Barry Sellers (LPA) 020 8871 7564
of Mandawarth			

© London Borough of Wandsworth

© English Heri

WESTMINSTER, CITY OF

	SITE NAME:	Crockers public house, 23-24, Aberdeen Place NW8	Public house circa 1900, formerly known as The Crown. Has been closed since autumn 2004. Planning Permission
	DESIGNATION:	Listed Building grade II*, CA	and Listed Building Consent were granted in November 2011 to allow the use of the upper floors as residential
	CONDITION:	Fair	flats. Work is well advanced on this scheme.
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
© Westminster City Council	LIST ENTRY NUMBER:	1357150	Contact: Rebecca Barrett 020 7973 3716
	SITE NAME:	Bow Street Magistrates Court and Police Station, Bow Street WC2	Court and Police Station, built in 1879-80. Greco Roman style with Vanbrughian details. Planning Permission and Listed Building Consent have been granted for the
	DESIGNATION:	Listed Building grade II, CA	refurbishment of the site and re-use as a hotel, museum and interpretive centre. Works have not yet begun.
		E - tu	. , 3

	DESIGNATION:	Listed Building grade II, CA	and interpretive centre. Works have not yet begun
	CONDITION:	Fair	
	OCCUPANCY:	Vacant/not in use	
r City Council	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1066393	Contact: Kate Green (LPA) 020 7641 2914

The second	SITE NAME:	21, Charles Street WI	Terraced town house circa 1750-53. Some unauthorised
	DESIGNATION:	Listed Building grade II, CA	works have taken place. Planning Permission and Listed Building Consent were granted in July 2008 for various
	CONDITION:	Poor	works including demolition and rebuilding of the mews building to the rear. The street elevation was cleaned and
A H IT H	OCCUPANCY:	Vacant/not in use	repaired in 2011-12.
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Unknown	
	LIST ENTRY NUMBER:	1357294	Contact: Robert Ayton (LPA) 020 7641 2978

© English Heritage

© Westminster

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

	SITE NAME:	39, Charles Street, Mayfair WI	The main house dates from the 1750s and includes mews
	DESIGNATION:	Listed Building grade II*, CA	buildings at the rear. Severe structural problems to the rear of the property are in the process of being rectified and
	CONDITION:	Poor	of the property are in the process of being rectified and works have started to implement permissions for a phased scheme of repair and restoration.
	OCCUPANCY:	Vacant/not in use	scheme of repair and restoration.
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1292197	Contact: Rebecca Barrett 020 7973 3716
ouncil			

© Westminster City Council

	SITE NAME:	76, Dean Street, Soho WI	Terraced town house dating from the 1730s. The property
	DESIGNATION:	Listed Building grade II*, CA	was seriously damaged by fire in 2009. Works have commenced on site to restore and enhance the building,
	CONDITION:	Very bad	including its decorative interior.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (B)	
M	OWNER TYPE:	Charity (non-heritage)	
	LIST ENTRY NUMBER:	1066917	Contact: Rebecca Barrett 020 7973 3716

© Westminster City Council

	SITE NAME:	112, Eaton Square SW1	Grand terraced house, circa 1825. The building is suffering
TEFE	DESIGNATION:	Listed Building grade II*, CA	from neglect, water ingress and a serious outbreak of dry rot. Works to improve the building are underway on site.
	CONDITION:	Poor	
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (F)	
	OWNER TYPE:	Private	
	LIST ENTRY NUMBER:	1066851	Contact: Rebecca Barrett 020 7973 3716
© Westminster City Council			

	SITE NAME:	94 and 100, Gloucester Place WI	Terraced houses built circa 1800 for the Portman Estate. Listed Building Consent was granted in July 2009 for the internal refurbishment and alterations to No. 100. Works have yet to be implemented.
	DESIGNATION:	Listed Building grade II, CA	
	CONDITION:	Poor	
	OCCUPANCY:	Part occupied/part in use	
	PRIORITY CATEGORY:	D (D)	
	OWNER TYPE:	Commercial company	
il	LIST ENTRY NUMBER:	1066788	Contact: Susanna Miller (LPA) 020 7641 2459

SITE NAME:	10-11, Lancaster Gate W2	Grand terrace of houses dating from 1865, attributed to
DESIGNATION:	Listed Building grade II, CA	John Johnson. The building is three bays wide with four storeys plus attic and basement. It has excellent classical
CONDITION:	Poor	detailing. The condition of the existing building is poor, owing to water leakage and poor maintenance. The
OCCUPANCY:	Vacant/not in use	building has since been secured following enforcement
PRIORITY CATEGORY:	D (D)	action, although these works are temporary.
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1221694	Contact: Alistair Taylor (LPA) 020 7641 2979

© Westminster City Council

© Westminster City Council

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.
- D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument


	SITE NAME:	7-12, Leinster Square W2	The site comprises six terraced buildings which form part
	DESIGNATION:	Listed Building grade II, CA	of the group listing of 7–16 Leinster Square. Built in 1857 by George Wyatt, they form an integral part of the planned
	CONDITION:	Poor	layout of Leinster Square. Since ceasing to function as a hotel, the properties, which are laterally converted, have
	OCCUPANCY:	Vacant/not in use	remained empty. Planning Permission and Listed Buildin Consent were granted in July 2013 for various works, including repairs to the external elevations and internal
	PRIORITY CATEGORY:	D (C)	
	OWNER TYPE:	Private	refurbishment. Works have yet to be implemented.
	LIST ENTRY NUMBER:	1221945	Contact: Alistair Taylor (LPA) 020 7641 2979

© Westminster City Council



SITE NAME:	Middlesex Hospital Chapel, Mortimer Street, East Marylebone W1	Hospital built in 1891 by John Loughborough Pearson and completed in 1929 by his son Frank Loughborough Pearson in an Italian Gothic style. A new redevelopment scheme for
DESIGNATION:	Listed Building grade II*, CA	this site has been agreed and is nearing completion, including repair works to the Hospital Chapel.
CONDITION:	Fair	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	F (F)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1223496	Contact: Rebecca Barrett 020 7973 3716

© English Heritage



Town Mansion of 1756-1760 by Matthew Brettingham for SITE NAME: 94, Piccadilly WI Lord Egremont, with 1822 and later alterations. Naval and DESIGNATION: Listed Building grade I, CA Military Club from 1866 until 1999. Planning Permission and Listed Building Consent have been granted for CONDITION: Poor alterations and extensions associated with the use of 94 and 95 Piccadilly as two single dwellings. Works have yet to OCCUPANCY: Vacant/not in use commence on site. PRIORITY CATEGORY: D (B) OWNER TYPE: Commercial company LIST ENTRY NUMBER: 1226748 Contact: Rebecca Barrett 020 7973 3716

© English Heritage

© English Heritage

	SITE NAME:	95, Piccadilly WI	Town house dating from 1886, forming part of a larger site
	DESIGNATION:	Listed Building grade II, CA	with the Former Naval and Military Club. Planning Permission and Listed Building Consent have been granted
	CONDITION:	Poor	for alterations and extensions associated with the use of 94 and 95 Piccadilly as two single dwellings. The condition of
	OCCUPANCY:	Vacant/not in use	95 is deteriorating. Works have yet to commence on site
	PRIORITY CATEGORY:	D (B)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1265696	Contact: Matthew Pendleton (LPA) 020 7641 5971

© Westminster City Council

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric; solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

D

Е

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- Conservation Area Listed Building CA
- LB I PA
- Local Planning Authority National Park NP
- RPG Registered Park and Garden Scheduled Monument
- SM
- UA WHS Unitary Authority World Heritage Site

14	SITE NAME:	26, Portland Place WI	Main house circa 1770s, with some C18 interiors. Works	
Y	DESIGNATION:	Listed Building grade II*, CA	have commenced on site and are nearing completion.	
	CONDITION:	Fair		
	OCCUPANCY:	Vacant/not in use		
	PRIORITY CATEGORY:	E (E)		
	OWNER TYPE:	Commercial company		
	LIST ENTRY NUMBER:	1227024	Contact: Rebecca Barrett 020 7973 3716	

© Westminster City Council

4



SITE NAME:	Wharf side shelter and store to rear of builders' merchants, 22, Praed Street W2	Wharf side shelter and store circa 1840. Brick ground floo with timber first floor with large slated hipped roof. Part of the redevelopment scheme for Paddington Basin. The
DESIGNATION:	Listed Building grade II	shelter is currently being stored off-site and will be re- erected as part of the final landscaping proposals.
CONDITION:	Fair	
OCCUPANCY:	Vacant/not in use	
PRIORITY CATEGORY:	D (D)	
OWNER TYPE:	Charity (heritage)	
LIST ENTRY NUMBER:	1248366	Contact: Tom Burke (LPA) 020 7641 2357



© Westminster City Council

	SITE NAME:	21, Upper Grosvenor Street W1	Terraced town house circa 1732. The building is sufferi from a general lack of maintenance and repair with wat
1	DESIGNATION:	Listed Building grade II, CA	ingress. Planning Permission and Listed Building Consent were granted in 2012 to extensively alter and extend the
1	CONDITION:	Poor	property consistent with its use as a single family dwellir Works are underway to implement this scheme.
	OCCUPANCY:	Vacant/not in use	
	PRIORITY CATEGORY:	F (B)	
	OWNER TYPE:	Commercial company	
	LIST ENTRY NUMBER:	1066191	Contact: Matthew Pendleton (LPA) 020 7641 5971
	OWNER TYPE:	Commercial company	Contact: Matthew Pendleton (LPA) 020 7641 5971

 SITE NAME:	140, Westbourne Terrace W2	Detached villa dating from 1843-8 in an Italianate style. Occupied as a number of bedsits. Planning Permission and Listed Building Consent were refused in November 2011
DESIGNATION:	Listed Building grade II, CA	
CONDITION:	Good	for a scheme seeking to retain the use of the building as seven self-contained flats and associated unauthorised
OCCUPANCY:	Occupied/in use	works. This is being investigated as an enforcement matter.
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Private	
LIST ENTRY NUMBER:	1267518	Contact: John Wilman (LPA) 020 7641 2561

© English Heritage



I	SITE NAME:	Church of St Mark, Hamilton Terrace, Paddington NW8	Gothic church dating from 1846-7 by Thomas Cundy Senior, with spire by Thomas Cundy Junior and chancel in
	DESIGNATION:	Listed Place of Worship grade II*, CA	1878 by EB Ferrey. Slate covered pitched roofs, Kentish ragstone walling with ashlar dressings. A Heritage Lottery Fund/English Heritage Repair Grant for Places of Worship was awarded towards re-slating the nave roof and works are now complete. A further grant has been offered towards masonry repairs to the tower and spire and work
	CONDITION:	Poor	
	PRIORITY CATEGORY:	D (F)	
	OWNER TYPE:	Religious organisation	are due to start in 2014.
	LIST ENTRY NUMBER:	1066681	Contact: Tracey Craig 020 7973 3756

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no А
- Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet В implemented.
- C Slow decay; no solution agreed.

 D Slow decay; solution agreed but F not yet implemented.
 E Under repair or in fair to good repair, but no user lacentified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use) use).

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

- CA Conservation Area LB Listed Building LPA Local Planning Authon NP National Park RPG Registered Park and 0 SM Scheduled Monumen UA Unitary Authority WHS World Heritage Site
 - Conservation Area Listed Building Local Planning Authority National Park Registered Park and Garden Scheduled Monument

SITE NAME:

SITE NAME:

CONDITION:

OWNER TYPE:

D

Е

SITE NAME:	Church of St Augustine, Kilburn Park Road, Paddington NW6	Designed by JL Pearson, built in 1877. Slated pitched root and red brick walling with Bath stone dressings. Internally the walls are covered in wall paintings by Clayton & Bell. , Heritage Lottery Fund/English Heritage Repair Grant for Places of Worship was awarded in 2010 towards repairs which included re-slating the south aisle roof. These work are now complete, however, other roofs are now found be in poor condition.
DESIGNATION:	Listed Place of Worship grade I	
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1221320	Contact: Tracey Craig 020 7973 3756

© English Heritage



SITE NAME:	Buddhist Temple, Margaret Street, Marylebone WI	Former Parish School and Church House dating from 1868-70 by William Butterfield. The building is in full-time
DESIGNATION:	Listed Place of Worship grade II*, CA	occupation and used for worship, library and residential accommodation. Repairs are required to the roofs and external facades.
CONDITION:	Poor	
PRIORITY CATEGORY:	C (C)	
OWNER TYPE:	Religious organisation	
LIST ENTRY NUMBER:	1273611	Contact: Tracey Craig 020 7973 3756

1867-78 by GE Street, with crypt chapel of St Sepulchre of


1895 by Sir Ninian Comper. An exceptional High Victorian

Gothic church with complete internal decorative scheme.

© English Heritage



© English Heritage



Church of St Mary Magdalene,

Rowington Close, Paddington

W)

© English Heritage



Built in 1856, designed by F & H Francis. Apse added in Church of St Stephen, 1900. Externally coursed ragstone with limestone dressings Westbourne Park Road, Westminster W2 and slate roofs. The spire was taken down after World War II. The church became near derelict and underwent Listed Place of Worship grade II, major repair in 1995. Progressive structural instability is DESIGNATION: CA exhibited by extensive cracking and splitting of stone in the nave arcading. Some holding works have been Very bad implemented to pin back split stones and steel plates fixed PRIORITY CATEGORY: A (New entry) to the underside of arches where the stones have slipped. Religious organisation LIST ENTRY NUMBER: 1267651 Contact: Tracey Craig 020 7973 3756

© English Heritage

PRIORITY CATEGORIES

- Immediate risk of further rapid deterioration or loss of fabric: no
- solution agreed Immediate risk of further rapid В deterioration or loss of fabric: solution agreed but not yet implemented.
- C Slow decay; no solution agreed.
- Slow decay; solution agreed but F not yet implemented.

Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (applicable only to buildings capable of beneficial use)

Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.

NOTE Last year's priority category is shown in brackets, otherwise 'New entry' is noted.

ABBREVIATIONS

- Conservation Area Listed Building LB
- I PA
- Local Planning Authority National Park NP
- Registered Park and Garden Scheduled Monument RPG
- SM ΪA

WHS

Unitary Authority World Heritage Site



This document is one in a series of publications produced as part of English Heritage's national Heritage at Risk programme. More information about Heritage at Risk and other titles in the series can be found at www.english-heritage.org.uk/risk

HERITAGE AT RISK

Published October 2014 by English Heritage I Waterhouse Square, 138-142 Holborn, London ECIN 2ST

© Copyright English Heritage 2014